

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2048
SCHOOL NAME: Green School
ADDRESS OF SCHOOL: 1150 W 96th Street
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **10/3/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 11/9/2022 ENROLLMENT 299
IDPH INSPECTOR LICENSE NUMBER: 100-18281
IDPH LICENSED INSPECTOR NAME (Please Print): Christopher Antonopoulos
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

11/28/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Green School

1150 W 96th Street
Chicago, IL, 60643

Unit: 24131
Building ID: 4410

IDPH ID Number: 14-016-2990-2048

REPORT DATE:

Monday, November 28, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

11/28/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24131 Region: 06 IDPH ID: 14-016-2990-2048

School: Green School Building ID: 4410

Address: 1150 W 96th Street
Chicago, IL, 60643

Building Contact: Corabi, Joseph Contact Phone: 7737103266

Current Building Owners: Chicago Public Schools

Reinspection Date: 11/9/2022

Review Date: 11/28/2022

Inspector: Christopher Antonopoulos Inspector IDPH License: 100-18281
Management Planner: Todd Huffer Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 28, 2022

RE: Green School, Unit 24131
1150 W 96th Street
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Green School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Green School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Green School Unit: 24131 Region: 06
Address: 1150 W 96th Street Chicago, IL, 60643
IDPH ID: 14-016-2990-2048 Building ID: 4410
Contact: Corabi, Joseph Phone: 7737103266

2. Description of Facility

Original Construction: 1972 Additional Construction:
Total Square Footage: 40088 No of Floors: 3
Current Occupancy: 299

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880 Fax: 630-790-0882

5. Inspector

Inspector Name: Christopher Antonopoulos



Inspector IDPH license # 100-18281
Reinspection Date: 11/9/2022

Signature:
Date: 11/9/2022

6. Management Planner

Management Planner Name: Todd Huffer



Management Planner IDPH license # 100-09870

Signature:
Date: 11/28/2022

7. Review Date: 11/28/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 11/28/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Green School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4410:

17	2'x2' Smooth Ceiling Tiles
18	12x12 Yellow Floor Tile
19	12x12 Yellow Floor Tile Mastic
20	Sink Undercoating
21	12x12 Green Floor Tile
22	12x12 Green Floor Tile Mastic
23	12x12 Brown Floor Tile
24	12x12 Brown Floor Tile Mastic
25	12x12 Orange Floor Tile

26

12x12 Orange Floor Tile Mastic

NEW

Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 4410:

17	2'x2' Smooth Ceiling Tiles
18	12x12 Yellow Floor Tile
19	12x12 Yellow Floor Tile Mastic
20	Sink Undercoating
21	12x12 Green Floor Tile
22	12x12 Green Floor Tile Mastic
23	12x12 Brown Floor Tile
24	12x12 Brown Floor Tile Mastic
25	12x12 Orange Floor Tile
26	12x12 Orange Floor Tile Mastic
NEW	Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01A	12"x12" Off-White Specked Floor Tile
01B	12"x12" Gray Specked Floor Tile
01E	12"x12" Beige Floor Tile w/ Brown Streaks
01F	12"x12" Brown Specked Floor Tile
03A	Black Mopboard
04A	12"x12" Off-White Specked Floor Tile Mastic
04B	12"x12" Gray Specked Floor Tile Mastic
04C	12"x12" Beige Specked Floor Tile Mastic
04E	12"x12" Beige w/Brown Streaks Floor Tile Mastic
04F	12"x12" Brown Specked Floor Tile Mastic
07E	Mauve Carpet Mastic NOT OBSERVED
09	Mudded Joints
10	2'x4' White Fissured Ceiling Tile
100	2'x2' Floor Tile White w/Blue Streaks NOT OBSERVED
100A	2'x2' Floor Tile White w/Blue Streaks Mastic NOT OBSERVED
101	12"x12" Floor Tile White w/Brown Streaks
101A	12" x 12" Floor Tile White w/Brown Streaks Mastic
11	12"x12" Tan w/Brown Streaks Floor Tile
11M	12"x12" Tan w/Brown Streaks Floor Tile Mastic
12	12"x12" Off-White w/Multicolor Floor Tile
12M	12"x12" Off-White w/Multicolor Floor Tile Mastic
13	12"x12" Off-White w/Beige Streaks Floor Tile NOT OBSERVED
13M	12"x12" Off-White w/Beige Streaks Floor Tile Mastic NOT OBSERVED
14	Yellow Mosaic Ceramic Tile Grout
15	Yellow Mosaic Ceramic Tile Adhesive
16	Tan w/Yellow and Brown Speckles Terrazzo Flooring
17	2'x2' Smooth Ceiling Tiles
18	12x12 Yellow Floor Tile
19	12x12 Yellow Floor Tile Mastic
20	Sink Undercoating
21	12x12 Green Floor Tile
22	12x12 Green Floor Tile Mastic
23	12x12 Brown Floor Tile
24	12x12 Brown Floor Tile Mastic
25	12x12 Orange Floor Tile
26	12x12 Orange Floor Tile Mastic
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

04A	12"x12" Off-White Specked Floor Tile Mastic
04B	12"x12" Gray Specked Floor Tile Mastic
04C	12"x12" Beige Specked Floor Tile Mastic
04D	12"x12" Gray Floor Tile Mastic
04E	12"x12" Beige w/Brown Streaks Floor Tile Mastic
04F	12"x12" Brown Specked Floor Tile Mastic
05B	Brown Mopboard Mastic
07B	Blue & Mauve Carpet Mastic NOT OBSERVED
100A	2'x2' Floor Tile White w/Blue Streaks Mastic NOT OBSERVED
101A	12" x 12" Floor Tile White w/Brown Streaks Mastic
11M	12"x12" Tan w/Brown Streaks Floor Tile Mastic
12M	12"x12" Off-White w/Multicolor Floor Tile Mastic
15	Yellow Mosaic Ceramic Tile Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Christopher Antonopoulos, IDPH License # 100-18281. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Green School Building 4410 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Green School Unit 24131 Building ID 4410

Address 1150 W 96th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01A	12"x12" Off-White Specked Floor Tile	2,765	SF	2nd and 3rd Floor Corridors, Rooms 101, 203, 300, 307 and 310 and the Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01B	12"x12" Gray Specked Floor Tile	2,688	SF	2nd & 3rd Floor Corridors, Rooms 101, 203, 300, 307, 310 & Assistant Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01C	12"x12" Beige Specked Floor Tile	1,470	SF	Rooms 105, 301, & 306 (Counselor's Office) and the SW Corridor on the 1st Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01D	12"x12" Gray Floor Tile	10,270	SF	Gym, Gym Office, Lunchroom, Kitchen, 2nd Floor Engineer's Office, Storeroom, Corridor and Electrician's Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01E	12"x12" Beige Floor Tile w/ Brown Streaks	3,600	SF	1st Floor Corridor (except SW Vestibule), Library, Computer Lab, Rooms 204, 206, 210 & Faculty Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01F	12"x12" Brown Specked Floor Tile	270	SF	Two Stage Entries and Patch in Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03A	Black Mopboard	1,500	LF	1st, 2nd and 3rd Floor Corridors, Rooms 101, 203, 301, 307 and 310 and the Gym	ASSUMED	MISC	N		0		No	ACBM with the potential for damage		LOW
04A	12"x12" Off-White Specked Floor Tile Mastic	2,765	SF	2nd and 3rd Floor Corridors, Rooms 101, 203, 300, 307 and 310 and the Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04B	12"x12" Gray Specked Floor Tile Mastic	2,688	SF	2nd & 3rd Floor Corridors and Rooms 101, 203, 300, 307, 310 &	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Green School Unit 24131 Building ID 4410

Address 1150 W 96th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Assistant Principal's Office										
04C	12"x12" Beige Specked Floor Tile Mastic	2,200	SF	Rooms 105, 301, 306, Counselor's Office, and the 1st Floor SW Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04D	12"x12" Gray Floor Tile Mastic	10,270	SF	Gym, Gym Office, Lunchroom, Kitchen, 2nd Floor Engineer's Office, Storeroom, Corridor and Electrician's Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04E	12"x12" Beige w/Brown Streaks Floor Tile Mastic	2,200	SF	1st Floor Corridor (except SW Vestibule), Library, Computer Lab, Rooms 204, 206, 210 & Faculty Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04F	12"x12" Brown Specked Floor Tile Mastic	270	SF	Two Stage Entries and Patch in Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05A	Black Mopboard Mastic	1,500	LF	1st, 2nd and 3rd Floor Corridors, Rooms 101, 203, 301, 307 and 310 and the Gym	NO_ACBM	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05B	Brown Mopboard Mastic	2,000	LF	Rooms 103, 104, 106, 201, 202, 204, 205-209, 303-306, 308 and 309, Lunch Room, Kitchen, Coach's Office and Storage and Teacher's Lounge	NO_ACBM	MISC	N		0		No	ACBM with the potential for damage		LOW
07B	Blue & Mauve Carpet Mastic NOT OBSERVED	500	SF	Room 103	NO_ACBM	MISC	N	NONE	0		No			LOW
07C	Blue Carpet Mastic NOT OBSERVED			Rooms 303-307		MISC		None						Low
07D	Green Carpet Mastic NOT OBSERVED			Room 202 (Library), Library Closet and the Teacher's Lounge Closet		MISC		None						Low
07E	Mauve Carpet Mastic NOT OBSERVED			Rooms 204, 206, 208 and 209	ASSUMED	MISC			0			ACBM with the potential for damage		LOW
08	Wallboard			Throughout All	NO_ACBM	MISC	N	NONE			No			LOW

Chicago Public Schools

School Green School Unit 24131 Building ID 4410

Address 1150 W 96th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Interior Walls										
09	Mudded Joints	19	EA	Water Meter Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
10	2'x4' White Fissured Ceiling Tile	25,000	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
100	2'x2' Floor Tile White w/Blue Streaks NOT OBSERVED	250	SF	Room 202	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
100A	2'x2' Floor Tile White w/Blue Streaks Mastic NOT OBSERVED	250	SF	Room 202	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	12"x12" Floor Tile White w/Brown Streaks	9,400	SF	Rooms 104, 106, 205 - 209, 303, 305, 308 & 309, Main Office & Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101A	12" x 12" Floor Tile White w/Brown Streaks Mastic	9,400	SF	Rooms 104, 106, 205 - 209, 303, 305, 308 & 309, Main Office & Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	12"x12" Tan w/Brown Streaks Floor Tile	4,000	SF	Rooms 100, 202 and 302, Teacher's Lounge and 1st Floor Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11M	12"x12" Tan w/Brown Streaks Floor Tile Mastic	4,000	SF	Rooms 100, 202 and 302, Teacher's Lounge and 1st Floor Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12"x12" Off-White w/Multicolor Floor Tile	3,600	SF	Rooms 104, 106 & 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12M	12"x12" Off-White w/Multicolor Floor Tile Mastic	3,600	SF	Rooms 104, 106 & 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12"x12" Off-White w/Beige Streaks Floor Tile NOT OBSERVED	4,320	SF	Rooms 205, 207, 209, 303, 305 and 309	ASSUMED	MISC			0			ACBM with the potential for damage		
13M	12"x12" Off-White w/Beige Streaks Floor Tile Mastic NOT OBSERVED	4,320	SF	Rooms 205, 207, 209, 303, 305 and 309	ASSUMED	MISC			0			ACBM with the potential for damage		
14	Yellow Mosaic Ceramic Tile Grout	2,820	SF	All Washrooms, Locker Room, All Vestibules and the 1st Floor Janitor's Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Yellow Mosaic Ceramic Tile Adhesive	2,820	SF	All Washrooms, Locker Room, All Vestibules and the 1st Floor Janitor's	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Green School Unit 24131 Building ID 4410

Address 1150 W 96th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Closet										
16	Tan w/Yellow and Brown Speckles Terrazzo Flooring	800	SF	2nd and 3rd Floor Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	2'x2' Smooth Ceiling Tiles	25,000	SF	Throughout Building	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
18	12x12 Yellow Floor Tile	500	SF	Rooms 105, 203, 205-208, & 301	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
19	12x12 Yellow Floor Tile Mastic	500	SF	Rooms 105, 203, 205-208, & 301	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
20	Sink Undercoating	6	EA	Rooms 101, 103-105, 303 & 308	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
21	12x12 Green Floor Tile	120	SF	Library, Lunchroom & Main Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
22	12x12 Green Floor Tile Mastic	120	SF	Library, Lunchroom & Main Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
23	12x12 Brown Floor Tile	2,000	SF	Lunchroom & Kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
24	12x12 Brown Floor Tile Mastic	2,000	SF	Lunchroom & Kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
25	12x12 Orange Floor Tile	200	SF	Rooms 101, 103, 104 & 106	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
26	12x12 Orange Floor Tile Mastic	200	SF	Rooms 101, 103, 104 & 106	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Brown Carpet Mastic NOT OBSERVED	460	SF	Room 201	NO_ACBM	MISC			0			ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNOWN			Yes	ACBM with the potential for damage		

Chicago Public Schools

School Green School Unit 24131 Building ID 4410

Address 1150 W 96th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 11/9/2022
Inspector Name Christopher Antonopoulos
100-18281 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01A	Not Observed in Kitchen, Rooms 300 & 310
01B	Not Observed in 203, 300 & 310
01C	
01D	Not Observed in Lunchroom or Kitchen
01E	
01F	
03A	
04A	Not Observed in Kitchen and Rooms 300 & 310
04B	Not Observed in Room 203, 300 & 310
04C	
04D	Not Observed in Kitchen, Rooms 300 & 310
04E	
04F	
05A	
05B	
07B	not observed 2022
07C	Not Observed 2019 & 2022
07D	Not Observed 2019 & 2022
07E	Not Observed 2019 & 2022
08	
09	
10	
100	Not Observed 2022
100A	Not Observed 2022

Chicago Public Schools

School Green School Unit 24131 Building ID 4410

Address 1150 W 96th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
101	
101A	
11	
11M	
12	
12M	
13	Not Observed 2019 & 2022
13M	Not Observed 2019 & 2022
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
A	Not Observed 2022
NEW	

Chicago Public Schools

School Green School **Unit** 24131 **Building ID** 4410

Address 1150 W 96th Street **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Green School
Address 1150 W 96th Street

Unit 24131
Chicago, IL, 60643

Building ID 4410
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01A	12"x12" Off-White Specked Floor Tile	2,765	SF	2nd and 3rd Floor Corridors, Rooms 101, 203, 300, 307 and 310 and the Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01B	12"x12" Gray Specked Floor Tile	2,688	SF	2nd & 3rd Floor Corridors, Rooms 101, 203, 300, 307, 310 & Assistant Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01C	12"x12" Beige Specked Floor Tile	1,470	SF	Rooms 105, 301, & 306 (Counselor's Office) and the SW Corridor on the 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01D	12"x12" Gray Floor Tile	10,270	SF	Gym, Gym Office, Lunchroom, Kitchen, 2nd Floor Engineer's Office, Storeroom, Corridor and Electrician's Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01E	12"x12" Beige Floor Tile w/ Brown Streaks	3,600	SF	1st Floor Corridor (except SW Vestibule), Library, Computer Lab, Rooms 204, 206, 210 & Faculty Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01F	12"x12" Brown Specked Floor Tile	270	SF	Two Stage Entries and Patch in Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03A	Black Mopboard	1,500	LF	1st, 2nd and 3rd Floor Corridors, Rooms 101, 203, 301, 307 and 310 and the Gym	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
04A	12"x12" Off-White Specked Floor Tile Mastic	2,765	SF	2nd and 3rd Floor Corridors, Rooms 101, 203, 300, 307 and 310 and the Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04B	12"x12" Gray Specked Floor Tile Mastic	2,688	SF	2nd & 3rd Floor Corridors and Rooms 101, 203, 300, 307, 310 & Assistant Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04C	12"x12" Beige Specked Floor Tile Mastic	2,200	SF	Rooms 105, 301, 306, Counselor's Office, and the 1st Floor SW Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04D	12"x12" Gray Floor Tile Mastic	10,270	SF	Gym, Gym Office, Lunchroom, Kitchen, 2nd Floor Engineer's Office, Storeroom, Corridor and Electrician's Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04E	12"x12" Beige w/Brown Streaks Floor Tile Mastic	2,200	SF	1st Floor Corridor (except SW Vestibule), Library, Computer Lab, Rooms 204, 206, 210 & Faculty Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04F	12"x12" Brown Specked Floor Tile Mastic	270	SF	Two Stage Entries and Patch in Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05A	Black Mopboard Mastic	1,500	LF	1st, 2nd and 3rd Floor Corridors, Rooms 101, 203, 301, 307 and 310 and	No ACBM	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Green School
Address 1150 W 96th Street

Unit 24131
Chicago, IL, 60643

Building ID 4410
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
05B	Brown Mopboard Mastic	2,000	LF	the Gym Rooms 103, 104, 106, 201, 202, 204, 205-209, 303-306, 308 and 309, Lunch Room, Kitchen, Coach's Office and Storage and Teacher's Lounge	No ACBM	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
07B	Blue & Mauve Carpet Mastic NOT OBSERVED	500	SF	Room 103	No ACBM	MISC	No	0	SF		
07C	Blue Carpet Mastic NOT OBSERVED			Rooms 303-307		MISC					
07D	Green Carpet Mastic NOT OBSERVED			Room 202 (Library), Library Closet and the Teacher's Lounge Closet		MISC					
07E	Mauve Carpet Mastic NOT OBSERVED			Rooms 204, 206, 208 and 209	Assumed	MISC		0		6 ACBM with the potential for damage	Follow O&M Plan
08	Wallboard			Throughout All Interior Walls	No ACBM	MISC	No				
09	Mudded Joints	19	EA	Water Meter Room	Assumed	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
10	2'x4' White Fissured Ceiling Tile	25,000	SF	Throughout	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	2'x2' Floor Tile White w/Blue Streaks NOT OBSERVED	250	SF	Room 202	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100A	2'x2' Floor Tile White w/Blue Streaks Mastic NOT OBSERVED	250	SF	Room 202	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12"x12" Floor Tile White w/Brown Streaks	9,400	SF	Rooms 104, 106, 205 - 209, 303, 305, 308 & 309, Main Office & Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101A	12" x 12" Floor Tile White w/Brown Streaks Mastic	9,400	SF	Rooms 104, 106, 205 - 209, 303, 305, 308 & 309, Main Office & Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12"x12" Tan w/Brown Streaks Floor Tile	4,000	SF	Rooms 100, 202 and 302, Teacher's Lounge and 1st Floor Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11M	12"x12" Tan w/Brown Streaks Floor Tile Mastic	4,000	SF	Rooms 100, 202 and 302, Teacher's Lounge and 1st Floor Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12"x12" Off-White w/Multicolor Floor Tile	3,600	SF	Rooms 104, 106 & 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12M	12"x12" Off-White w/Multicolor Floor Tile Mastic	3,600	SF	Rooms 104, 106 & 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" Off-White w/Beige Streaks Floor Tile NOT OBSERVED	4,320	SF	Rooms 205, 207, 209, 303, 305 and 309	Assumed	MISC			SF	6 ACBM with the potential for damage	Follow O&M Plan
13M	12"x12" Off-White w/Beige Streaks Floor Tile Mastic NOT OBSERVED	4,320	SF	Rooms 205, 207, 209, 303, 305 and 309	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Yellow Mosaic Ceramic Tile Grout	2,820	SF	All Washrooms, Locker Room, All Vestibules and the 1st Floor Janitor's Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Yellow Mosaic Ceramic Tile Adhesive	2,820	SF	All Washrooms, Locker Room, All Vestibules and the 1st Floor Janitor's	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Green School
Address 1150 W 96th Street

Unit 24131
Chicago, IL, 60643

Building ID 4410
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Closet							
16	Tan w/Yellow and Brown Speckles Terrazzo Flooring	800	SF	2nd and 3rd Floor Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	2'x2' Smooth Ceiling Tiles	25,000	SF	Throughout Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12x12 Yellow Floor Tile	500	SF	Rooms 105, 203, 205-208, & 301	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12x12 Yellow Floor Tile Mastic	500	SF	Rooms 105, 203, 205-208, & 301	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Sink Undercoating	6	EA	Rooms 101, 103-105, 303 & 308	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
21	12x12 Green Floor Tile	120	SF	Library, Lunchroom & Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12x12 Green Floor Tile Mastic	120	SF	Library, Lunchroom & Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12x12 Brown Floor Tile	2,000	SF	Lunchroom & Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12x12 Brown Floor Tile Mastic	2,000	SF	Lunchroom & Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12x12 Orange Floor Tile	200	SF	Rooms 101, 103, 104 & 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12x12 Orange Floor Tile Mastic	200	SF	Rooms 101, 103, 104 & 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Brown Carpet Mastic NOT OBSERVED	460	SF	Room 201	No ACBM	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Green School
Address 1150 W 96th Street

Unit 24131
 Chicago, IL, 60643

Building ID 4410
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	11/28/2022
Manager Planner Name	Todd Huffer
100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01A	Not Observed in Kitchen, Rooms 300 & 310
01B	Not Observed in Kitchen, Rooms 300 & 310
01C	
01D	
01E	
01F	
03A	
04A	
04B	
04C	
04D	Not Observed in Kitchen, Rooms 300 & 310
04E	
04F	
05A	
05B	
07B	not observed 2022
07C	not observed 2022
07D	not observed 2022
07E	Not Observed 2019 & 2022
08	

Chicago Public Schools

School Green School
Address 1150 W 96th Street

Unit 24131
 Chicago, IL, 60643

Building ID 4410
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
09	
10	
100	
100A	
101	
101A	
11	
11M	
12	
12M	
13	
13M	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
A	
NEW	

Chicago Public Schools

School Green School
Address 1150 W 96th Street

Unit 24131
Chicago, IL, 60643

Building ID 4410
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **12"x12" Off-White Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd and 3rd Floor Corridors, Rooms 101, 203, 300, 307 and 310 and the Kitchen**
MATERIAL QUANTITY: **2765** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not Observed in Kitchen, Rooms 300 & 310**

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **12"x12" Off-White Specked Floor Tile**
MATERIAL LOCATION: **2nd and 3rd Floor Corridors, Rooms 101, 203, 300, 307 and 310 and the Kitchen**
MATERIAL QUANTITY: **2765** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Not Observed in Kitchen, Rooms 300 & 310

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **12"x12" Gray Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd & 3rd Floor Corridors, Rooms 101, 203, 300, 307, 310 & Assistant Principal's Office**

MATERIAL QUANTITY: **2688** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in 203, 300 & 310**

Inspector's Signature: *Christopher Antonopoulos*

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **12"x12" Gray Specked Floor Tile**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors, Rooms 101, 203, 300, 307, 310 & Assistant Principal's Office**
MATERIAL QUANTITY: **2688** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Not Observed in Kitchen, Rooms 300 & 310

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **12"x12" Beige Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 105, 301, & 306 (Counselor's Office) and the SW Corridor on the 1st Floor**
MATERIAL QUANTITY: **1470** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **12"x12" Beige Specked Floor Tile**
MATERIAL LOCATION: **Rooms 105, 301, & 306 (Counselor's Office) and the SW Corridor on the 1st Floor**
MATERIAL QUANTITY: **1470** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01D**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym, Gym Office, Lunchroom, Kitchen, 2nd Floor Engineer's Office, Storeroom, Corridor and Electrician's Room**

MATERIAL QUANTITY: **10270** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Lunchroom or Kitchen**

Inspector's Signature: *Christopher Antonopoulos*

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **01D**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile**
MATERIAL LOCATION: **Gym, Gym Office, Lunchroom, Kitchen, 2nd Floor Engineer's Office, Storeroom, Corridor and Electrician's Room**
MATERIAL QUANTITY: **10270** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01E**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/ Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor (except SW Vestibule), Library, Computer Lab, Rooms 204, 206, 210 & Faculty Room**

MATERIAL QUANTITY: **3600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **01E**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/ Brown Streaks**
MATERIAL LOCATION: **1st Floor Corridor (except SW Vestibule), Library, Computer Lab, Rooms 204, 206, 210 & Faculty Room**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01F**
MATERIAL DESCRIPTION: **12"x12" Brown Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Two Stage Entries and Patch in Gym**
MATERIAL QUANTITY: **270** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **01F**
MATERIAL DESCRIPTION: **12"x12" Brown Specked Floor Tile**
MATERIAL LOCATION: **Two Stage Entries and Patch in Gym**
MATERIAL QUANTITY: **270** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **Black Mopboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors, Rooms 101, 203, 301, 307 and 310 and the Gym**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **Black Mopboard**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors, Rooms 101, 203, 301, 307 and 310 and the Gym**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **12"x12" Off-White Specked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd and 3rd Floor Corridors, Rooms 101, 203, 300, 307 and 310 and the Kitchen**
MATERIAL QUANTITY: **2765** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not Observed in Kitchen and Rooms 300 & 310**

Inspector's Signature: _____

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **12"x12" Off-White Specked Floor Tile Mastic**
MATERIAL LOCATION: **2nd and 3rd Floor Corridors, Rooms 101, 203, 300, 307 and 310 and the Kitchen**
MATERIAL QUANTITY: **2765** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04B**
MATERIAL DESCRIPTION: **12"x12" Gray Specked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd & 3rd Floor Corridors and Rooms 101, 203, 300, 307, 310 & Assistant Principal's Office**

MATERIAL QUANTITY: **2688** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Room 203, 300 & 310**

Inspector's Signature: *Christopher Antonopoulos*

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **04B**
MATERIAL DESCRIPTION: **12"x12" Gray Specked Floor Tile Mastic**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors and Rooms 101, 203, 300, 307, 310 & Assistant Principal's Office**
MATERIAL QUANTITY: **2688** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04C**
MATERIAL DESCRIPTION: **12"x12" Beige Specked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 105, 301, 306, Counselor's Office, and the 1st Floor SW Corridor**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **04C**
MATERIAL DESCRIPTION: **12"x12" Beige Specked Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 105, 301, 306, Counselor's Office, and the 1st Floor SW Corridor**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04D**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym, Gym Office, Lunchroom, Kitchen, 2nd Floor Engineer's Office, Storeroom, Corridor and Electrician's Room**

MATERIAL QUANTITY: **10270** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Kitchen, Rooms 300 & 310**

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **04D**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile Mastic**
MATERIAL LOCATION: **Gym, Gym Office, Lunchroom, Kitchen, 2nd Floor Engineer's Office, Storeroom, Corridor and Electrician's Room**
MATERIAL QUANTITY: **10270** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Not Observed in Kitchen, Rooms 300 & 310

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04E**
MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor (except SW Vestibule), Library, Computer Lab, Rooms 204, 206, 210 & Faculty Room**

MATERIAL QUANTITY: **2200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **04E**
MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Streaks Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor (except SW Vestibule), Library, Computer Lab, Rooms 204, 206, 210 & Faculty Room**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24131 BUIDLING ID: 4410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Green School INSPECTION DATE: 11/9/2022
ADDRESS: 1150 W 96th Street IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04F
MATERIAL DESCRIPTION: 12"x12" Brown Specked Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Two Stage Entries and Patch in Gym
MATERIAL QUANTITY: 270 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **04F**
MATERIAL DESCRIPTION: **12"x12" Brown Specked Floor Tile Mastic**
MATERIAL LOCATION: **Two Stage Entries and Patch in Gym**
MATERIAL QUANTITY: **270** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **Black Mopboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors, Rooms 101, 203, 301, 307 and 310 and the Gym**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **Black Mopboard Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors, Rooms 101, 203, 301, 307 and 310 and the Gym**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **Brown Mopboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 103, 104, 106, 201, 202, 204, 205-209, 303-306, 308 and 309, Lunch Room, Kitchen, Coach's Office and Storage and Teacher's Lounge**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **Brown Mopboard Mastic**
MATERIAL LOCATION: **Rooms 103, 104, 106, 201, 202, 204, 205-209, 303-306, 308 and 309, Lunch Room, Kitchen, Coach's Office and Storage and Teacher's Lounge**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07B**
MATERIAL DESCRIPTION: **Blue & Mauve Carpet Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **not observed 2022**

Inspector's Signature:

Christopher Antonopoulos

Date: **11/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **07B**
MATERIAL DESCRIPTION: **Blue & Mauve Carpet Mastic NOT OBSERVED**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:
not observed 2022

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07C**
MATERIAL DESCRIPTION: **Blue Carpet Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 303-307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

Christopher Antonopoulos

Date: **11/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **07C**
MATERIAL DESCRIPTION: **Blue Carpet Mastic NOT OBSERVED**
MATERIAL LOCATION: **Rooms 303-307**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:
not observed 2022

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **07D**
MATERIAL DESCRIPTION: **Green Carpet Mastic NOT OBSERVED**
MATERIAL LOCATION: **Room 202 (Library), Library Closet and the Teacher's Lounge Closet**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:
not observed 2022

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24131 BUIDLING ID: 4410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Green School INSPECTION DATE: 11/9/2022
ADDRESS: 1150 W 96th Street IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07E
MATERIAL DESCRIPTION: Mauve Carpet Mastic NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Rooms 204, 206, 208 and 209

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2019 & 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **07E**
MATERIAL DESCRIPTION: **Mauve Carpet Mastic NOT OBSERVED**
MATERIAL LOCATION: **Rooms 204, 206, 208 and 209**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Wallboard**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout All Interior Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **Wallboard**

MATERIAL LOCATION: **Throughout All Interior Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Mudded Joints**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Water Meter Room**
MATERIAL QUANTITY: **19** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Mudded Joints**
MATERIAL LOCATION: **Water Meter Room**
MATERIAL QUANTITY: **19** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **2'x4' White Fissured Celing Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **2'x4' White Fissured Celing Tile**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **2'x2' Floor Tile White w/Blue Streaks NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 202**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not Observed 2022**

Inspector's Signature: _____

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **2'x2' Floor Tile White w/Blue Streaks NOT OBSERVED**
MATERIAL LOCATION: **Room 202**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100A**
MATERIAL DESCRIPTION: **2'x2' Floor Tile White w/Blue Streaks Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 202**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not Observed 2022**

Inspector's Signature: _____

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **100A**
MATERIAL DESCRIPTION: **2'x2' Floor Tile White w/Blue Streaks Mastic NOT OBSERVED**
MATERIAL LOCATION: **Room 202**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12"x12" Floor Tile White w/Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 104, 106, 205 - 209, 303, 305, 308 & 309, Main Office & Annex**
MATERIAL QUANTITY: **9400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12"x12" Floor Tile White w/Brown Streaks**
MATERIAL LOCATION: **Rooms 104, 106, 205 - 209, 303, 305, 308 & 309, Main Office & Annex**
MATERIAL QUANTITY: **9400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101A**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile White w/Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 104, 106, 205 - 209, 303, 305, 308 & 309, Main Office & Annex**
MATERIAL QUANTITY: **9400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **101A**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile White w/Brown Streaks Mastic**
MATERIAL LOCATION: **Rooms 104, 106, 205 - 209, 303, 305, 308 & 309, Main Office & Annex**
MATERIAL QUANTITY: **9400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12"x12" Tan w/Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 100, 202 and 302, Teacher's Lounge and 1st Floor Storage**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **11/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12"x12" Tan w/Brown Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 100, 202 and 302, Teacher's Lounge and 1st Floor Storage**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11M**
MATERIAL DESCRIPTION: **12"x12" Tan w/Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 100, 202 and 302, Teacher's Lounge and 1st Floor Storage**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **11M**
MATERIAL DESCRIPTION: **12"x12" Tan w/Brown Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 100, 202 and 302, Teacher's Lounge and 1st Floor Storage**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12"x12" Off-White w/Multicolor Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 104, 106 & 208**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12"x12" Off-White w/Multicolor Floor Tile**
MATERIAL LOCATION: **Rooms 104, 106 & 208**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12M**
MATERIAL DESCRIPTION: **12"x12" Off-White w/Multicolor Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 104, 106 & 208**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **11/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **12M**
MATERIAL DESCRIPTION: **12"x12" Off-White w/Multicolor Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 104, 106 & 208**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24131 BUILDING ID: 4410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Green School INSPECTION DATE: 11/9/2022
ADDRESS: 1150 W 96th Street IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13
MATERIAL DESCRIPTION: 12"x12" Off-White w/Beige Streaks Floor Tile NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 205, 207, 209, 303, 305 and 309

MATERIAL QUANTITY: 4320

MATERIAL UNITS: SF

DAMAGE QUANTITY:

DAMAGE UNITS: SF

COMMENTS: Not Observed 2019 & 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12"x12" Off-White w/Beige Streaks Floor Tile NOT OBSERVED**
MATERIAL LOCATION: **Rooms 205, 207, 209, 303, 305 and 309**
MATERIAL QUANTITY: **4320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24131 BUIDLING ID: 4410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Green School INSPECTION DATE: 11/9/2022
ADDRESS: 1150 W 96th Street IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13M
MATERIAL DESCRIPTION: 12"x12" Off-White w/Beige Streaks Floor Tile Mastic NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 205, 207, 209, 303, 305 and 309

MATERIAL QUANTITY: 4320

MATERIAL UNITS: SF

DAMAGE QUANTITY:

DAMAGE UNITS: SF

COMMENTS: Not Observed 2019 & 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **13M**
MATERIAL DESCRIPTION: **12"x12" Off-White w/Beige Streaks Floor Tile Mastic NOT OBSERVED**
MATERIAL LOCATION: **Rooms 205, 207, 209, 303, 305 and 309**
MATERIAL QUANTITY: **4320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Yellow Mosaic Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Washrooms, Locker Room, All Vestibules and the 1st Floor Janitor's Closet**
MATERIAL QUANTITY: **2820** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Yellow Mosaic Ceramic Tile Grout**
MATERIAL LOCATION: **All Washrooms, Locker Room, All Vestibules and the 1st Floor Janitor's Closet**
MATERIAL QUANTITY: **2820** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24131 BUIDLING ID: 4410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Green School INSPECTION DATE: 11/9/2022
ADDRESS: 1150 W 96th Street IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15
MATERIAL DESCRIPTION: Yellow Mosaic Ceramic Tile Adhesive
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: All Washrooms, Locker Room, All Vestibules and the 1st Floor Janitor's Closet
MATERIAL QUANTITY: 2820 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Yellow Mosaic Ceramic Tile Adhesive**
MATERIAL LOCATION: **All Washrooms, Locker Room, All Vestibules and the 1st Floor Janitor's Closet**
MATERIAL QUANTITY: **2820** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24131 BUILDING ID: 4410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Green School INSPECTION DATE: 11/9/2022
ADDRESS: 1150 W 96th Street IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 16
MATERIAL DESCRIPTION: Tan w/Yellow and Brown Speckles Terrazzo Flooring
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 2nd and 3rd Floor Stairways
MATERIAL QUANTITY: 800 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Tan w/Yellow and Brown Speckles Terrazzo Flooring**
MATERIAL LOCATION: **2nd and 3rd Floor Stairways**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24131 BUIDLING ID: 4410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Green School INSPECTION DATE: 11/9/2022
ADDRESS: 1150 W 96th Street IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A
MATERIAL DESCRIPTION: Brown Carpet Mastic NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Room 201
MATERIAL QUANTITY: 460 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS: Not Observed 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Brown Carpet Mastic NOT OBSERVED**
MATERIAL LOCATION: **Room 201**
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**
MATERIAL LOCATION: **Rooms 105, 203, 205-208, & 301**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**


HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**
MATERIAL LOCATION: **Rooms 105, 203, 205-208, & 301**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24131 BUILDING ID: 4410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Green School INSPECTION DATE: 11/9/2022
ADDRESS: 1150 W 96th Street IDPH LICENSE NO: 100-18281

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: 21
MATERIAL DESCRIPTION: 12x12 Green Floor Tile
MATERIAL LOCATION: Library, Lunchroom & Main Office
MATERIAL QUANTITY: 120 MATERIAL UNITS: SF
MATERIAL CATEGORY: MISC FRIABLE: No
ASBESTOS TYPE: Assumed
DISTURBANCE POTENTIAL: LOW CONDITION:
AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
ACCESSIBILITY: Within Reach DAMAGE REASON:
DAMAGE QUANTITY: 0 DAMAGE REASON:
DAMAGE UNITS: SF
COMMENTS:

Inspector's Signature: Christopher Antonopoulos Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**


HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**
MATERIAL LOCATION: **Library, Lunchroom & Main Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

**TEM Environmental, Inc.
2022 AHERA REINSPECTION**

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 105, 203, 205-208, & 301**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: *Christopher Antonopoulos* Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 105, 203, 205-208, & 301**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**
MATERIAL LOCATION: **Lunchroom & Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**
MATERIAL LOCATION: **Lunchroom & Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUIDLING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile**
MATERIAL LOCATION: **Rooms 101, 103, 104 & 106**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile**
MATERIAL LOCATION: **Rooms 101, 103, 104 & 106**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  _____ Date: **11/28/2022** _____

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **2'x2' Smooth Ceiling Tiles**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: *Christopher Antonopoulos* Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **2'x2' Smooth Ceiling Tiles**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 101, 103, 104 & 106**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 101, 103, 104 & 106**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Sink Undercoating**
MATERIAL LOCATION: **Rooms 101, 103-105, 303 & 308**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **EA**
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Sink Undercoating**
MATERIAL LOCATION: **Rooms 101, 103-105, 303 & 308**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**
MATERIAL LOCATION: **Lunchroom & Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**
MATERIAL LOCATION: **Lunchroom & Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Green School** INSPECTION DATE: **11/9/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS:
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **11/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/28/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24131 BUIDLING ID: 4410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Green School INSPECTION DATE: 11/9/2022
ADDRESS: 1150 W 96th Street IDPH LICENSE NO: 100-18281

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: 22
MATERIAL DESCRIPTION: 12x12 Green Floor Tile Mastic
MATERIAL LOCATION: Library, Lunchroom & Main Office
MATERIAL QUANTITY: 120 MATERIAL UNITS: SF
MATERIAL CATEGORY: MISC FRIABLE: No
ASBESTOS TYPE: Assumed
DISTURBANCE POTENTIAL: LOW CONDITION:
AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
ACCESSIBILITY: Within Reach DAMAGE REASON:
DAMAGE QUANTITY: 0 DAMAGE REASON:
DAMAGE UNITS: SF
COMMENTS:

Inspector's Signature: Christopher Antonopoulos Date: 11/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24131** BUILDING ID: **4410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Green School** REVIEW DATE: **11/28/2022**
ADDRESS: **1150 W 96th Street** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**
MATERIAL LOCATION: **Library, Lunchroom & Main Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/28/2022

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER ANTONOPOULOS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 06/01/2021 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II; Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

06/01/2021

Course Dates:

06/01/2022

Expires:

2106BIR11

Certificate Number:

A handwritten signature in black ink, appearing to read "N Penneff".

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER J. ANTONOPOULOS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 06/03/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

06/03/2022

Course Dates:

06/03/2023

Expires:

2206BIR01

Certificate Number:




37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in black ink, appearing to read "N. Peneff", is written over a light gray rectangular background.

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081


FORM # A-010B

 **ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 18281	2/10/2022	05/15/2023

CHRISTOPHER J ANTONOPO
1736 W 102nd ST
CHICAGO, IL 60643

Environmental Health



ENDORSEMENT	TC EXPIRES
INSPECTOR	6/1/2022

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

TODD T HUFFER
315 HATLEN COURT
MT. PROSPECT, IL 60056

2/18/2022


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	ASBESTOS PROFESSIONAL LICENSE		INSPECTOR	11/1/2022
ID NUMBER 100 - 09870	ISSUED 2/18/2022	EXPIRES 05/15/2023	MANAGEMENT PLANNER	11/19/2022
TODD T HUFFER 315 HATLEN COURT MT. PROSPECT, IL 60056 Environmental Health			PROJECT MANAGER	10/20/2022
			AIR SAMPLING PROFESSIONAL	
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265


Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed