

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2317
SCHOOL NAME: Locke School
ADDRESS OF SCHOOL: 2845 N. Newcastle Avenue
CITY: Chicago, IL, 60634

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **10/3/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/17/2022 ENROLLMENT 1168
IDPH INSPECTOR LICENSE NUMBER: 100-19036
IDPH LICENSED INSPECTOR NAME (Please Print): Ismael Hernandez
IDPH MP LICENSE NUMBER: 100-04019
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 4/13/2022
Signature of Designated Person Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Locke School

2845 N. Newcastle Avenue
Chicago, IL, 60634

Unit: 24231
Building ID: 4510

IDPH ID Number: 14-016-2990-2317

REPORT DATE:

Wednesday, April 13, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Specialty Consulting, Inc.

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 13, 2022

RE: Locke School, Unit 24231
2845 N. Newcastle Avenue
Chicago, IL, 60634

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Locke School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Locke School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Locke School Unit: 24231 Region: 02
Address: 2845 N. Newcastle Avenue Chicago, IL, 60634
IDPH ID: 14-016-2990-2317 Building ID: 4510
Contact: Wrenn, Charles Phone: 7737367937

2. Description of Facility

Original Construction: 1998 Additional Construction:
Total Square Footage: 40248 No of Floors: 3
Current Occupancy: 1168

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: Ismael Hernandez


Inspector IDPH license # 100-19036
Reinspection Date: 3/17/2022


Signature:
Date: 3/17/2022

6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019



Signature:
Date: 04/13/2022

7. Review Date: 04/13/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 4/13/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Locke School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4510:

B. The following new homogenous areas have been identified for Building 4510:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	Hard Coat Plaster
02	12"x12" White Vinyl Floor Tile
09	12"x12" White Vinyl Floor Tile Mastic
33	Red Linoleum (Not Observed)
35	2'x2' White Ceiling Tile
36	Hard Coat Plaster
41	2'x4' Ceiling Tile
50	12"x12" Green w/ Specks Floor Tile
51	12"x12" Green w/ Specks Floor Tile Mastic
52	12"x12" Blue Floor Tile
53	12"x12" Blue Floor Tile Mastic
65	Terrazzo
66	Carpet Mastic
67	2' x 4' Dot Ceiling Tile (with 2' x 2' Layout)
68	Terrazzo
69	12"x12" Gold Mottled Floor Tile
70	12"x12" Gold Mottled Floor Tile Mastic
71	12"x12" Gold Floor Tile
72	12"x12" Gold Floor Tile Mastic
73	12" x 12" Blue Floor Tile
73M	12" x 12" Blue Floor Tile Adhesive
74	12" x 12" Tan Multicolored Floor Tile
74M	12" x 12" Tan Multicolored Floor Tile Adhesive
75	2'x4' Grooved Ceiling Tile
76	CMU Wall Mortar
77	Brown ceramic tile
77A	Brown ceramic tile Mastic
78	12" x 12" Cream speckled VFT
78A	12" x 12" Cream speckled VFT Mastic
79	Textured plaster
80	12" x 12" Gray speckled VFT
80A	12" x 12" Gray speckled VFT Mastic
81	12" x 12" Blue speckled VFT
81A	12" x 12" Blue speckled VFT Mastic

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not

conducted to avoid damage.

This reinspection was conducted by Ismael Hernandez, IDPH License # 100-19036. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Locke School Building 4510 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Hard Coat Plaster	80,000	SF	Throughout - 1926	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02	12"x12" White Vinyl Floor Tile	900	SF	Main Office - 1926	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
03	9"x9" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
05	Textured Plaster			Throughout - 1926	NO_ACBM						No			
09	12"x12" White Vinyl Floor Tile Mastic	900	SF	Main Office - 1926	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9"x9" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	ABATED	MISC					No	Any remaining friable ACBM or friable suspect ACBM		
11	9"x9" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC					No	Any remaining friable ACBM or friable suspect ACBM		
12	9"x9" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC					No	Any remaining friable ACBM or friable suspect ACBM		
13	9"x9" Maroon Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	ABATED	MISC					No	Any remaining friable ACBM or friable suspect ACBM		
14	9"x9" Maroon Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	ABATED	MISC					No	Any remaining friable ACBM or friable suspect ACBM		
15	9"x9" Brown w/ White Streaks Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
16	9"x9" Brown w/ White Streaks Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
17	9"x9" Black w/ White Streaks Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
18	9"x9" Black w/ White Streaks Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
19	9"x9" Maroon Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		

Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
20	9"x9" Maroon Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
21	6"x18" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
22	6"x18" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
23	9"x9" Brown w/ Red & White Streaks Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
24	9"x9" Brown w/ Red & White Streaks Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
25	12"x12" Purple Vinyl Floor Tile - ABATED			1st Floor Corridor - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
26	12"x12" Purple Vinyl Floor Tile Mastic - ABATED			1st Floor Corridor - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
27	12"x12" Black w/ White Streaks Vinyl Floor Tile - ABATED			1st Floor Corridor - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
28	12"x12" Black w/ White Streaks Floor Tile Mastic - ABATED			1st Floor Corridor - 1926	ABATED	MISC								
29	12"x12" White w/ Tan Streaks Floor Tile	2,400	SF	Rooms 119, 122, & 124 - 1926	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
30	12"x12" White w/ Tan Streaks Floor Tile Mastic	2,400	SF	Rooms 119, 122, & 124 - 1926	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Red Linoleum (Not Observed)	1,200	SF	Auditorium - 1926	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
34	Red Linoleum Mastic (Not Observed)	1,200	SF	Auditorium - 1926	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	2'x2' White Ceiling Tile	600	SF	Room 225 - 1926	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
36	Hard Coat Plaster	60,000	SF	Throughout - 1936	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12"x12" Black Vinyl Floor Tile - ABATED			Engineer's Office - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
38	12"x12" Black Vinyl Floor Tile Mastic - ABATED			Engineer's Office - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		

Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
39	12"x12" Maroon Vinyl Floor Tile - ABATED			Engineer's Office - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
40	12"x12" Maroon Vinyl Floor Tile Mastic - ABATED			Engineer's Office - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
41	2'x4' Ceiling Tile	500	SF	Engineer's Office - 1926	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
50	12"x12" Green w/ Specks Floor Tile	8,000	SF	Throughout - 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51	12"x12" Green w/ Specks Floor Tile Mastic	8,000	SF	Throughout - 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12"x12" Blue Floor Tile	3,000	SF	Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
53	12"x12" Blue Floor Tile Mastic	3,000	SF	Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	2'x4' White w/ Grooves Ceiling Tile			Throughout - 1998	NO_ACBM	MISC								LOW
55	Green Linoleum			Cafeteria, Kitchen - 1998	NO_ACBM	MISC								
56	Green Linoleum Mastic			Cafeteria, Kitchen - 1998	NO_ACBM	MISC								
57	Blue Linoleum			Cafeteria, Kitchen - 1998	NO_ACBM	MISC								
57A	Blue Linoleum Mastic			Cafeteria, Kitchen - 1998	NO_ACBM	MISC								
58	Drywall			Throughout - 1998	NO_ACBM	MISC								
59	Drywall Compound			Throughout - 1998	NO_ACBM	MISC								
60	Vinyl Baseboards			Throughout - 1998	NO_ACBM	MISC								
61	Vinyl Baseboard Mastic			Throughout - 1998	NO_ACBM	MISC								
62	Spray-On Insulation			Above Ceiling 1st Floor - 1998	NO_ACBM	SURFACE								
63	Carpet Mastic			Main Office Area, Library - 1998	NO_ACBM	MISC								
64	2'x4' White Smooth Ceiling Tile			Kitchen & Storage - 1998	NO_ACBM	MISC								
65	Terrazzo	4,000	SF	Stair Wells and Stairs Throughout 1st and 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	Carpet Mastic	500	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
67	2' x 4' Dot Ceiling Tile (with 2' x 2' Layout)	4,000	SF	Rooms 108, 119, 121, and Old 2nd Floor Girl's Locker Room.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
68	Terrazzo	5,000	SF	Corridors and Toilets (1998)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	12"x12" Gold Mottled Floor Tile	750	SF	Old 2nd Floor Girl's Locker Room.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
70	12"x12" Gold Mottled Floor Tile Mastic	750	SF	Old 2nd Floor Girl's Locker Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	12"x12" Gold Floor Tile	2,000	SF	Throughout Classrooms in 1998 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
72	12"x12" Gold Floor Tile Mastic	2,000	SF	Throughout Classrooms in 1998 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	12" x 12" Blue Floor Tile	4,000	SF	1st and 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
73M	12" x 12" Blue Floor Tile Adhesive	4,000	SF	1st and 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	12" x 12" Tan Multicolored Floor Tile	1,200	SF	Engineer's Office, Rooms 117 and 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
74M	12" x 12" Tan Multicolored Floor Tile Adhesive	1,200	SF	Engineer's Office, Rooms 117 and 122	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	2'x4' Grooved Ceiling Tile	600	SF	Room 222	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		
76	CMU Wall Mortar			1998 Addition Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	Brown ceramic tile	2,400	SF	1st + 2nd Floor boys and girls toilets -1926 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
77A	Brown ceramic tile Mastic	2,400	SF	1st + 2nd Floor boys and girls toilets -1926 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12" x 12" Cream speckled VFT	1,400	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
78A	12" x 12" Cream speckled VFT Mastic	14,000	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	Textured plaster	45,000	SF	Auditorium & Balcony	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
80	12" x 12" Gray speckled VFT	500	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
80A	12" x 12" Gray speckled VFT Mastic	500	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
81	12" x 12" Blue speckled VFT	900	SF	Room 115, 122	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
81A	12" x 12" Blue speckled VFT Mastic	900	SF	Room 115, 122	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
L	Spray-on Insulation			Throughout Above Ceilings in Attic - 1926	NO_ACBM						No			

Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>3/17/2022</u>
Inspector Name <u>Ismael Hernandez</u>
<u>100-19036</u> <u>5/15/2023</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
05	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	

Chicago Public Schools

School Locke School **Unit** 24231 **Building ID** 4510

Address 2845 N. Newcastle Avenue **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
29	
30	
33	
34	
35	
36	
37	
38	
39	
40	
41	
50	
51	
52	
53	
54	
55	
56	
57	
57A	
58	
59	
60	
61	
62	
63	
64	
65	
66	

Chicago Public Schools

School Locke School **Unit** 24231 **Building ID** 4510

Address 2845 N. Newcastle Avenue **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
67	
68	
69	
70	
71	
72	
73	
73M	
74	
74M	
75	
76	
77	
77A	
78	
78A	
79	
80	
80A	
81	
81A	
L	

Table II

Management Planner's Review

Chicago Public Schools

School Locke School
Address 2845 N. Newcastle Avenue

Unit 24231
 Chicago, IL, 60634

Building ID 4510
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Hard Coat Plaster	80,000	SF	Throughout - 1926	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	12"x12" White Vinyl Floor Tile	900	SF	Main Office - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	9"x9" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
05	Textured Plaster			Throughout - 1926	No ACBM						
09	12"x12" White Vinyl Floor Tile Mastic	900	SF	Main Office - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9"x9" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
11	9"x9" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
12	9"x9" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
13	9"x9" Maroon Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
14	9"x9" Maroon Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
15	9"x9" Brown w/ White Streaks Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
16	9"x9" Brown w/ White Streaks Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
17	9"x9" Black w/ White Streaks Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
18	9"x9" Black w/ White Streaks Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
19	9"x9" Maroon Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
20	9"x9" Maroon Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
21	6"x18" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
22	6"x18" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
23	9"x9" Brown w/ Red & White Streaks Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
24	9"x9" Brown w/ Red & White Streaks Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	

Chicago Public Schools

School Locke School
Address 2845 N. Newcastle Avenue

Unit 24231
 Chicago, IL, 60634

Building ID 4510
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
25	12"x12" Purple Vinyl Floor Tile - ABATED			1st Floor Corridor - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
26	12"x12" Purple Vinyl Floor Tile Mastic - ABATED			1st Floor Corridor - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
27	12"x12" Black w/ White Streaks Vinyl Floor Tile - ABATED			1st Floor Corridor - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
28	12"x12" Black w/ White Streaks Floor Tile Mastic - ABATED			1st Floor Corridor - 1926	Abated	MISC					
29	12"x12" White w/ Tan Streaks Floor Tile	2,400	SF	Rooms 119, 122, & 124 - 1926	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12"x12" White w/ Tan Streaks Floor Tile Mastic	2,400	SF	Rooms 119, 122, & 124 - 1926	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Red Linoleum (Not Observed)	1,200	SF	Auditorium - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Red Linoleum Mastic (Not Observed)	1,200	SF	Auditorium - 1926	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	2'x2' White Ceiling Tile	600	SF	Room 225 - 1926	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Hard Coat Plaster	60,000	SF	Throughout - 1936	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12"x12" Black Vinyl Floor Tile - ABATED			Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
38	12"x12" Black Vinyl Floor Tile Mastic - ABATED			Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
39	12"x12" Maroon Vinyl Floor Tile - ABATED			Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
40	12"x12" Maroon Vinyl Floor Tile Mastic - ABATED			Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
41	2'x4' Ceiling Tile	500	SF	Engineer's Office - 1926	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12"x12" Green w/ Specks Floor Tile	8,000	SF	Throughout - 1998	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12"x12" Green w/ Specks Floor Tile Mastic	8,000	SF	Throughout - 1998	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12"x12" Blue Floor Tile	3,000	SF	Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12"x12" Blue Floor Tile Mastic	3,000	SF	Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	2'x4' White w/ Grooves Ceiling Tile			Throughout - 1998	No ACBM	MISC					
55	Green Linoleum			Cafeteria, Kitchen - 1998	No ACBM	MISC					
56	Green Linoleum Mastic			Cafeteria, Kitchen - 1998	No ACBM	MISC					
57	Blue Linoleum			Cafeteria, Kitchen - 1998	No ACBM	MISC					
57A	Blue Linoleum Mastic			Cafeteria, Kitchen - 1998	No ACBM	MISC					

Chicago Public Schools

School Locke School

Unit 24231

Building ID 4510

Address 2845 N. Newcastle Avenue

Chicago, IL, 60634

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
58	Drywall			Throughout - 1998	No ACBM	MISC					
59	Drywall Compound			Throughout - 1998	No ACBM	MISC					
60	Vinyl Baseboards			Throughout - 1998	No ACBM	MISC					
61	Vinyl Baseboard Mastic			Throughout - 1998	No ACBM	MISC					
62	Spray-On Insulation			Above Ceiling 1st Floor - 1998	No ACBM	SURFACE					
63	Carpet Mastic			Main Office Area, Library - 1998	No ACBM	MISC					
64	2'x4' White Smooth Ceiling Tile			Kitchen & Storage - 1998	No ACBM	MISC					
65	Terrazzo	4,000	SF	Stair Wells and Stairs Throughout 1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	Carpet Mastic	500	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	2' x 4' Dot Ceiling Tile (with 2' x 2' Layout)	4,000	SF	Rooms 108, 119, 121, and Old 2nd Floor Girl's Locker Room.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Terrazzo	5,000	SF	Corridors and Toilets (1998)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12"x12" Gold Mottled Floor Tile	750	SF	Old 2nd Floor Girl's Locker Room.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12"x12" Gold Mottled Floor Tile Mastic	750	SF	Old 2nd Floor Girl's Locker Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12"x12" Gold Floor Tile	2,000	SF	Throughout Classrooms in 1998 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12"x12" Gold Floor Tile Mastic	2,000	SF	Throughout Classrooms in 1998 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12" x 12" Blue Floor Tile	4,000	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73M	12" x 12" Blue Floor Tile Adhesive	4,000	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12" x 12" Tan Multicolored Floor Tile	1,200	SF	Engineer's Office, Rooms 117 and 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74M	12" x 12" Tan Multicolored Floor Tile Adhesive	1,200	SF	Engineer's Office, Rooms 117 and 122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	2'x4' Grooved Ceiling Tile	600	SF	Room 222	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	CMU Wall Mortar			1998 Addition Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Brown ceramic tile	2,400	SF	1st + 2nd Floor boys and girls toilets -1926 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77A	Brown ceramic tile Mastic	2,400	SF	1st + 2nd Floor boys and girls toilets -1926 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" Cream speckled VFT	1,400	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78A	12" x 12" Cream speckled VFT Mastic	14,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	Textured plaster	45,000	SF	Auditorium & Balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	12" x 12" Gray speckled VFT	500	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80A	12" x 12" Gray speckled VFT Mastic	500	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12" x 12" Blue speckled VFT	900	SF	Room 115, 122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Locke School
Address 2845 N. Newcastle Avenue

Unit 24231
 Chicago, IL, 60634

Building ID 4510
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
81A	12" x 12" Blue speckled VFT Mastic	900	SF	Room 115, 122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	Spray-on Insulation			Throughout Above Ceilings in Attic - 1926	No ACBM						

Review Date	4/13/2022
Manager Planner Name	Arturo Saenz

HA Number	Management Comments
01	

Chicago Public Schools

School Locke School
Address 2845 N. Newcastle Avenue

Unit 24231
 Chicago, IL, 60634

Building ID 4510
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

100-04019	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
03	
05	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
33	
34	

Chicago Public Schools

School Locke School
Address 2845 N. Newcastle Avenue

Unit 24231
Chicago, IL, 60634

Building ID 4510
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
35	
36	
37	
38	
39	
40	
41	
50	
51	
52	
53	
54	
55	
56	
57	
57A	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	

Chicago Public Schools

School Locke School
Address 2845 N. Newcastle Avenue

Unit 24231
Chicago, IL, 60634

Building ID 4510
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
69	
70	
71	
72	
73	
73M	
74	
74M	
75	
76	
77	
77A	
78	
78A	
79	
80	
80A	
81	
81A	
L	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout - 1926**

MATERIAL QUANTITY: **80000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout - 1926**
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Office - 1926**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile**
MATERIAL LOCATION: **Main Office - 1926**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Textured Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Textured Plaster**
MATERIAL LOCATION: **Throughout - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office - 1926**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Main Office - 1926**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Vinyl Floor Tile - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks Vinyl Floor Tile - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **6"x18" Black Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **6"x18" Black Vinyl Floor Tile - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **6"x18" Black Vinyl Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **6"x18" Black Vinyl Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Red & White Streaks Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Red & White Streaks Floor Tile - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Red & White Streaks Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Red & White Streaks Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12"x12" Purple Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12"x12" Purple Vinyl Floor Tile - ABATED**
MATERIAL LOCATION: **1st Floor Corridor - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12"x12" Purple Vinyl Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12"x12" Purple Vinyl Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **1st Floor Corridor - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks Vinyl Floor Tile - ABATED**
MATERIAL LOCATION: **1st Floor Corridor - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **1st Floor Corridor - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 119, 122, & 124 - 1926**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 119, 122, & 124 - 1926**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 119, 122, & 124 - 1926**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 119, 122, & 124 - 1926**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Red Linoleum (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auditorium - 1926**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Red Linoleum (Not Observed)**
MATERIAL LOCATION: **Auditorium - 1926**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Red Linoleum Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium - 1926**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Red Linoleum Mastic (Not Observed)**
MATERIAL LOCATION: **Auditorium - 1926**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 225 - 1926**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**
MATERIAL LOCATION: **Room 225 - 1926**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1936**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout - 1936**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile - ABATED**
MATERIAL LOCATION: **Engineer's Office - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **Engineer's Office - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"x12" Maroon Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"x12" Maroon Vinyl Floor Tile - ABATED**
MATERIAL LOCATION: **Engineer's Office - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12"x12" Maroon Vinyl Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12"x12" Maroon Vinyl Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **Engineer's Office - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office - 1926**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **Engineer's Office - 1926**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12"x12" Green w/ Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout - 1998**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12"x12" Green w/ Specks Floor Tile**
MATERIAL LOCATION: **Throughout - 1998**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12"x12" Green w/ Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1998**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12"x12" Green w/ Specks Floor Tile Mastic**
MATERIAL LOCATION: **Throughout - 1998**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**
MATERIAL LOCATION: **Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **2'x4' White w/ Grooves Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **2'x4' White w/ Grooves Ceiling Tile**
MATERIAL LOCATION: **Throughout - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Green Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Green Linoleum**
MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Green Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Green Linoleum Mastic**
MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Blue Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Blue Linoleum**
MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57A**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **57A**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Throughout - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Vinyl Baseboards**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Vinyl Baseboards**
MATERIAL LOCATION: **Throughout - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Throughout - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Spray-On Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Above Ceiling 1st Floor - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Spray-On Insulation**
MATERIAL LOCATION: **Above Ceiling 1st Floor - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office Area, Library - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUILDING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Main Office Area, Library - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **2'x4' White Smooth Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Kitchen & Storage - 1998**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **2'x4' White Smooth Ceiling Tile**
MATERIAL LOCATION: **Kitchen & Storage - 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stair Wells and Stairs Throughout 1st and 2nd Floor Corridors**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Stair Wells and Stairs Throughout 1st and 2nd Floor Corridors**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **2' x 4' Dot Ceiling Tile (with 2' x 2' Layout)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 108, 119, 121, and Old 2nd Floor Girl's Locker Room.**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **2' x 4' Dot Ceiling Tile (with 2' x 2' Layout)**
MATERIAL LOCATION: **Rooms 108, 119, 121, and Old 2nd Floor Girl's Locker Room.**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridors and Toilets (1998)**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUILDING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Corridors and Toilets (1998)**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12"x12" Gold Mottled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Old 2nd Floor Girl's Locker Room.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12"x12" Gold Mottled Floor Tile**
MATERIAL LOCATION: **Old 2nd Floor Girl's Locker Room.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **12"x12" Gold Mottled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Old 2nd Floor Girl's Locker Room**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **12"x12" Gold Mottled Floor Tile Mastic**
MATERIAL LOCATION: **Old 2nd Floor Girl's Locker Room**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12"x12" Gold Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout Classrooms in 1998 Building**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12"x12" Gold Floor Tile**
MATERIAL LOCATION: **Throughout Classrooms in 1998 Building**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **12"x12" Gold Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Classrooms in 1998 Building**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **12"x12" Gold Floor Tile Mastic**
MATERIAL LOCATION: **Throughout Classrooms in 1998 Building**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st and 2nd Floor Corridors**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **1st and 2nd Floor Corridors**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73M**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Corridors**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **73M**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Adhesive**
MATERIAL LOCATION: **1st and 2nd Floor Corridors**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12" x 12" Tan Multicolored Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Engineer's Office, Rooms 117 and 112**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12" x 12" Tan Multicolored Floor Tile**
MATERIAL LOCATION: **Engineer's Office, Rooms 117 and 112**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74M**
MATERIAL DESCRIPTION: **12" x 12" Tan Multicolored Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office, Rooms 117 and 122**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **74M**
MATERIAL DESCRIPTION: **12" x 12" Tan Multicolored Floor Tile Adhesive**
MATERIAL LOCATION: **Engineer's Office, Rooms 117 and 122**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **2'x4' Grooved Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 222**

MATERIAL QUANTITY: **600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **2'x4' Grooved Ceiling Tile**
MATERIAL LOCATION: **Room 222**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **CMU Wall Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1998 Addition Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **CMU Wall Mortar**
MATERIAL LOCATION: **1998 Addition Throughout**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Brown ceramic tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st + 2nd Floor boys and girls toilets -1926 bldg**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Brown ceramic tile**
MATERIAL LOCATION: **1st + 2nd Floor boys and girls toilets -1926 bldg**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77A**
MATERIAL DESCRIPTION: **Brown ceramic tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st + 2nd Floor boys and girls toilets -1926 bldg**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **77A**
MATERIAL DESCRIPTION: **Brown ceramic tile Mastic**
MATERIAL LOCATION: **1st + 2nd Floor boys and girls toilets -1926 bldg**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12" x 12" Cream speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12" x 12" Cream speckled VFT**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78A**
MATERIAL DESCRIPTION: **12" x 12" Cream speckled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **78A**
MATERIAL DESCRIPTION: **12" x 12" Cream speckled VFT Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **Textured plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium & Balcony**

MATERIAL QUANTITY: **45000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **Textured plaster**
MATERIAL LOCATION: **Auditorium & Balcony**
MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12" x 12" Gray speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12" x 12" Gray speckled VFT**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80A**
MATERIAL DESCRIPTION: **12" x 12" Gray speckled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **80A**
MATERIAL DESCRIPTION: **12" x 12" Gray speckled VFT Mastic**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12" x 12" Blue speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 115, 122**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12" x 12" Blue speckled VFT**
MATERIAL LOCATION: **Room 115, 122**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81A**
MATERIAL DESCRIPTION: **12" x 12" Blue speckled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 115, 122**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/17/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **81A**
MATERIAL DESCRIPTION: **12" x 12" Blue speckled VFT Mastic**
MATERIAL LOCATION: **Room 115, 122**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Locke School** INSPECTION DATE: **3/17/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Spray-on Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Above Ceilings in Attic - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/17/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Locke School** REVIEW DATE: **4/13/2022**
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Spray-on Insulation**
MATERIAL LOCATION: **Throughout Above Ceilings in Attic - 1926**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ISMAEL HERNANDEZ
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/15/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/15/2022

Course Dates:

01/15/2023

Expires:

2201BIR12

Certificate Number:



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in blue ink, appearing to read "N Peneff". The signature is written over a light-colored rectangular background.

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 19036

ISSUED
2/28/2022

EXPIRES
05/15/2023

ISMAEL HERNANDEZ
2942 W VAN BUREN ST, STE 2
CHICAGO, IL 60612
Environmental Health



ISMAEL HERNANDEZ
2942 W VAN BUREN ST, STE 200
CHICAGO, IL 60612

2/28/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 19036

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p>		<p>TC EXPIRES</p>
<p>ID NUMBER 100 - 19036</p>	<p>ISSUED 2/28/2022</p>	<p>EXPIRES 05/15/2023</p>	<p>INSPECTOR</p>		<p>1/15/2023</p>
<p>ISMAEL HERNANDEZ 2942 W VAN BUREN ST, STE 2 CHICAGO, IL 60612 Environmental Health</p> 			<p>PROJECT MANAGER</p>		<p>2/6/2022</p>
			<p>AIR SAMPLING PROFESSIONAL</p>		
<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>					

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562


Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

2/28/2022



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 04019

ISSUED
2/28/2022

EXPIRES
05/15/2023

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612



Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 04019	ISSUED 2/28/2022	EXPIRES 05/15/2023	INSPECTOR	11/1/2022
ARTURO SAENZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	11/1/2022
			AIR SAMPLING PROFESSIONAL	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES

Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed