

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-3508  
SCHOOL NAME: Mount Vernon School Annex  
ADDRESS OF SCHOOL: 10540 Morgan  
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 1/10/2023 ENROLLMENT 242  
IDPH INSPECTOR LICENSE NUMBER: 100-05730  
IDPH LICENSED INSPECTOR NAME (Please Print): Prins Sales  
IDPH MP LICENSE NUMBER: 100-03613  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 1/11/2023  
*Signature of Designated Person* *Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Mount Vernon School Annex**

10540 Morgan  
Chicago, IL, 60643

Unit: 24601  
Building ID: 4980 Annex

IDPH ID Number: 14-016-2990-3508

**REPORT DATE:**

Wednesday, January 11, 2023

**Prepared for:**

**Chicago Public Schools  
42 W. Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

01/11/2023

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 24601                      Region: 06                      IDPH ID: 14-016-2990-3508

School: Mount Vernon School Annex                      Building ID: 4980 Annex

Address: 10540 Morgan

Chicago, IL, 60643

Building Contact:                      Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 1/10/2023

Review Date: 01/11/2023

Inspector: Prins Sales

Inspector IDPH License: 100-05730

Management Planner: Daniel Juneau

Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Daniel Juneau  
100-03613

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: January 11, 2023

RE: Mount Vernon School Annex , Unit 24601  
10540 Morgan  
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Mount Vernon School Annex , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Mount Vernon School Annex , there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Mount Vernon School Annex  
Address: 10540 Morgan  
IDPH ID: 14-016-2990-3508  
Contact:

Unit: 24601  
Chicago, IL, 60643  
Building ID: 4980 Annex  
Phone:

Region: 06

### 2. Description of Facility

Original Construction: 1970  
Total Square Footage: 10080  
Current Occupancy: 242

Additional Construction:  
No of Floors: 1

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant


MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Prins Sales


Inspector IDPH license # 100-05730  
Reinspection Date: 1/10/2023

Signature:   
Date: 1/10/2023

### 6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613

Signature:   
Date: 01/11/2023

### 7. Review Date: 01/11/2023

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 1/11/2023

Name: Richard J.Schleyer



## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Mount Vernon School Annex. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4980 Annex:

NEW

Newly Installed Suspect ACM



B. The following new homogenous areas have been identified for Building 4980 Annex:

NEW

Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

08X	Vinyl Baseboard
09X	Vinyl Baseboard Mastic
11X	Window Caulking Compound
30X	12x12 Light Brown w/Specks Floor Tile Checkerboard Pattern
31X	12x12 Cream w/Brown Specks Floor Tile Checkerboard Pattern
32X	Annex Hallway Floor Tile Mastic
33	2'x4' White Wormed Ceiling Tile
38	12x12 Crème with Beige Specks Floor Tile
38M	12x12 Crème with Beige Specks Floor Tile Mastic
AX	MJP E/F/V on Fiberglass Pipe Insulation
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

09X	Vinyl Baseboard Mastic
38M	12x12 Crème with Beige Specks Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Prins Sales, IDPH License # 100-05730. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Mount Vernon School Annex Building 4980 Annex Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Mount Vernon School Annex Unit 24601 Building ID 4980 Annex  
 Address 10540 Morgan Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01X	2'x4' Fissured Ceiling Tiles NOT OBSERVED			Throughout Annex		MISC								
02X	2'x4' Pebbled Ceiling Tile NOT OBSERVED			Throughout Annex		MISC								
08X	Vinyl Baseboard	300	SF	Annex- Classrooms 501, 503, 505 & 507	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09X	Vinyl Baseboard Mastic	300	SF	Annex- Classrooms 501, 503, 505 & 507	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10X	Window Glazing Compound	4,500	LF	Facility Interior	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11X	Window Caulking Compound	4,500	LF	Facility Interior	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29X	Red Carpet Mastic NOT OBSERVED			Annex- All Classrooms		MISC								
30X	12x12 Light Brown w/Specks Floor Tile Checkerboard Pattern	600	SF	Annex- Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31X	12x12 Cream w/Brown Specks Floor Tile Checkerboard Pattern	600	SF	Annex- Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32X	Annex Hallway Floor Tile Mastic	1,200	SF	Annex- Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	2'x4' White Wormed Ceiling Tile	7,000	SF	Annex Building- All Classrooms and Corridor	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
33X	Green/Blue Carpet Mastic NOT OBSERVED			Teachers' Lounge, Annex Storeroom		MISC								
38	12x12 Crème with Beige Specks Floor Tile	4,300	SF	Annex Building- All Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38M	12x12 Crème with Beige Specks Floor Tile Mastic	4,300	SF	Annex Building- All Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AX	MJP E/F/V on Fiberglass Pipe Insulation	80	LF	Annex - Janitor's Closet Watermain	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

# Chicago Public Schools

School Mount Vernon School Annex Unit 24601 Building ID 4980 Annex  
Address 10540 Morgan Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>1/10/2023</b>
Inspector Name <b>Prins Sales</b>
<b>100-05730</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01X	Not Observed 2022
02X	Not Observed 2022
08X	
09X	
10X	
11X	
29X	All Carpet Removed
30X	
31X	
32X	
33	
33X	All Carpet Removed
38	
38M	
AX	
NEW	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Mount Vernon School  
Annex

**Unit** 24601

**Building ID** 4980 Annex

**Address** 10540 Morgan

Chicago, IL, 60643

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01X	2'x4' Fissured Ceiling Tiles NOT OBSERVED			Throughout Annex		MISC					
02X	2'x4' Pebbled Ceiling Tile NOT OBSERVED			Throughout Annex		MISC					
08X	Vinyl Baseboard	300	SF	Annex- Classrooms 501, 503, 505 & 507	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09X	Vinyl Baseboard Mastic	300	SF	Annex- Classrooms 501, 503, 505 & 507	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10X	Window Glazing Compound	4,500	LF	Facility Interior	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
11X	Window Caulking Compound	4,500	LF	Facility Interior	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
29X	Red Carpet Mastic NOT OBSERVED			Annex- All Classrooms		MISC					
30X	12x12 Light Brown w/Specks Floor Tile Checkerboard Pattern	600	SF	Annex- Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31X	12x12 Cream w/Brown Specks Floor Tile Checkerboard Pattern	600	SF	Annex- Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32X	Annex Hallway Floor Tile Mastic	1,200	SF	Annex- Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	2'x4' White Wormed Ceiling Tile	7,000	SF	Annex Building- All Classrooms and Corridor	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33X	Green/Blue Carpet Mastic NOT OBSERVED			Teachers' Lounge, Annex Storeroom		MISC					
38	12x12 Crème with Beige Specks Floor Tile	4,300	SF	Annex Building- All Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38M	12x12 Crème with Beige Specks Floor Tile Mastic	4,300	SF	Annex Building- All Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AX	MJP E/F/V on Fiberglass Pipe Insulation	80	LF	Annex - Janitor's Closet Watermain	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan



# Chicago Public Schools

**School** Mount Vernon School  
Annex

**Unit** 24601

**Building ID** 4980 Annex

**Address** 10540 Morgan

Chicago, IL, 60643

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	1/11/2023
Manager Planner Name	Daniel Juneau
100-03613	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01X	
02X	
08X	
09X	
10X	
11X	
29X	
30X	
31X	
32X	
33	
33X	
38	
38M	
AX	

# Chicago Public Schools

**School** Mount Vernon School  
Annex

**Unit** 24601

**Building ID** 4980 Annex

**Address** 10540 Morgan

Chicago, IL, 60643

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
NEW	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01X**  
MATERIAL DESCRIPTION: **2'x4' Fissured Ceiling Tiles NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **01/10/2023**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **01X**  
MATERIAL DESCRIPTION: **2'x4' Fissured Ceiling Tiles NOT OBSERVED**  
MATERIAL LOCATION: **Throughout Annex**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24601    BUILDING ID: 4980 Annex  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Prins Sales  
SCHOOL NAME: Mount Vernon School Annex    INSPECTION DATE: 1/10/2023  
ADDRESS: 10540 Morgan    IDPH LICENSE NO: 100-05730

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 02X  
MATERIAL DESCRIPTION: 2'x4' Pebbled Ceiling Tile NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE:    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Annex

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **02X**  
MATERIAL DESCRIPTION: **2'x4' Pebbled Ceiling Tile NOT OBSERVED**  
MATERIAL LOCATION: **Throughout Annex**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08X**  
MATERIAL DESCRIPTION: **Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex- Classrooms 501, 503, 505 & 507**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUILDING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **08X**  
MATERIAL DESCRIPTION: **Vinyl Baseboard**  
MATERIAL LOCATION: **Annex- Classrooms 501, 503, 505 & 507**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09X**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex- Classrooms 501, 503, 505 & 507**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUILDING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **09X**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Annex- Classrooms 501, 503, 505 & 507**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10X**  
MATERIAL DESCRIPTION: **Window Glazing Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Facility Interior**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUILDING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **10X**  
MATERIAL DESCRIPTION: **Window Glazing Compound**  
MATERIAL LOCATION: **Facility Interior**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11X**  
MATERIAL DESCRIPTION: **Window Caulking Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Facility Interior**

MATERIAL QUANTITY: **4500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUILDING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **11X**  
MATERIAL DESCRIPTION: **Window Caulking Compound**  
MATERIAL LOCATION: **Facility Interior**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29X**  
MATERIAL DESCRIPTION: **Red Carpet Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex- All Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **All Carpet Removed**

Inspector's Signature:



Date: **01/10/2023**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **29X**  
MATERIAL DESCRIPTION: **Red Carpet Mastic NOT OBSERVED**  
MATERIAL LOCATION: **Annex- All Classrooms**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **01/11/2023**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30X**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Specks Floor Tile Checkerboard Pattern**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex- Hallway**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUILDING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **30X**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Specks Floor Tile Checkerboard Pattern**  
MATERIAL LOCATION: **Annex- Hallway**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31X**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Floor Tile Checkerboard Pattern**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex- Hallway**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **31X**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Floor Tile Checkerboard Pattern**  
MATERIAL LOCATION: **Annex- Hallway**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32X**  
MATERIAL DESCRIPTION: **Annex Hallway Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex- Hallway**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **32X**  
MATERIAL DESCRIPTION: **Annex Hallway Floor Tile Mastic**  
MATERIAL LOCATION: **Annex- Hallway**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **2'x4' White Wormed Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex Building- All Classrooms and Corridor**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **2'x4' White Wormed Ceiling Tile**  
MATERIAL LOCATION: **Annex Building- All Classrooms and Corridor**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUILDING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33X**  
MATERIAL DESCRIPTION: **Green/Blue Carpet Mastic NOT OBERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teachers' Lounge, Annex Storeroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **All Carpet Removed**

Inspector's Signature:



Date: **01/10/2023**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **33X**  
MATERIAL DESCRIPTION: **Green/Blue Carpet Mastic NOT OBERVED**  
MATERIAL LOCATION: **Teachers' Lounge, Annex Storeroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUILDING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12x12 Crème with Beige Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex Building- All Classrooms**

MATERIAL QUANTITY: **4300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12x12 Crème with Beige Specks Floor Tile**  
MATERIAL LOCATION: **Annex Building- All Classrooms**  
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **01/11/2023**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUILDING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38M**  
MATERIAL DESCRIPTION: **12x12 Crème with Beige Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex Building- All Classrooms**

MATERIAL QUANTITY: **4300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **38M**  
MATERIAL DESCRIPTION: **12x12 Crème with Beige Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Annex Building- All Classrooms**  
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 01/11/2023



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex** INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AX**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex - Janitor's Closet Watermain**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24601** BUIDLING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex** REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan** IDPH LICENSE NO: **100-05730**

---

HOMOGENEOUS AREA: **AX**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Annex - Janitor's Closet Watermain**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **01/11/2023**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24601**      BUILDING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Prins Sales**  
SCHOOL NAME: **Mount Vernon School Annex**      INSPECTION DATE: **1/10/2023**  
ADDRESS: **10540 Morgan**      IDPH LICENSE NO: **100-05730**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 01/10/2023

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24601**      BUILDING ID: **4980 Annex**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Mount Vernon School Annex**      REVIEW DATE: **1/11/2023**  
ADDRESS: **10540 Morgan**      IDPH LICENSE NO: **100-05730**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  \_\_\_\_\_ Date: **01/11/2023** \_\_\_\_\_

# APPENDIX B

## Inspector and Management Planner Licenses

---



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**PRINS SALES**  
5638 W. 63RD PLACE, APT. #1  
CHICAGO, IL 60638

3/1/2022




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05730

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	<b>ID NUMBER</b> 100 - 05730	<b>ISSUED</b> 3/1/2022	INSPECTOR	12/2/2021
<b>PRINS SALES</b> 5638 W. 63RD PLACE, APT. #1 CHICAGO, IL 60638 Environmental Health		<b>EXPIRES</b> 05/15/2023	PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/1/2021
	<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that*

**Prins Sales**

*has on 12/08/21, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: December 8, 2021

**COURSE LENGTH: 4 HOURS**

Examination Date: December 8, 2021

Expiration Date: December 8, 2022

Certificate Number: BIR/1005

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)





**EarthTech, Inc.**

435 Shadow Wood Drive, Yorkville, IL 60560

## Asbestos Building Inspector Refresher

THIS CERTIFIES THAT

**Prins Sales**

Has successfully completed the IL and IN Approved Asbestos Training Course and passed the Examination for purposes of accreditation under section 206 of Title II, 15 USC 2646 of the Toxic Substances Control Act (TSCA) and 326 IAC 18-2. Conducted by EarthTech, Inc  
630-417-6951

CLASS DATES: 11/16/2022


EXAMINATION: 11/16/2022

LOCATION: Amerisafe

EXPIRATION: 11/16/2023

CERTIFICATE NUMBER: 110176X22S104031





ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/19/2022
MANAGEMENT PLANNER	11/19/2022
PROJECT MANAGER	11/1/2022
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
 This license issued under authority of the State of Illinois  
 Department of Public Health  
 This license is valid only when accompanied by a valid  
 training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: BIR2111192805

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192816

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/12/2022

Exam Date: 12/12/2022

Expiration Date: 12/12/2023

Certificate Number: MPR2212123967

Kathy DeSalvo, Director





OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113645

Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed