

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2401  
SCHOOL NAME: Washington School, Harold  
ADDRESS OF SCHOOL: 9130 S University Avenue  
CITY: Chicago, IL, 60619

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **9/6/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 6/21/2022 ENROLLMENT 244  
IDPH INSPECTOR LICENSE NUMBER: 100-09786  
IDPH LICENSED INSPECTOR NAME (Please Print): John Fenn  
IDPH MP LICENSE NUMBER: 100-01784  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Geneser  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer*

7/21/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Washington School, Harold**

9130 S University Avenue  
Chicago, IL, 60619

Unit: 24921  
Building ID: 5380

IDPH ID Number: 14-016-2990-2401

**REPORT DATE:**

Thursday, July 21, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

07/21/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 24921                      Region: 06                      IDPH ID: 14-016-2990-2401

School: Washington School, Harold                      Building ID: 5380

Address: 9130 S University Avenue

Chicago, IL, 60619

Building Contact:                      Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 6/21/2022

Review Date: 07/21/2022

Inspector: John Fenn


Inspector IDPH License: 100-09786

Management Planner: Steven Geneser

Management Planner IDPH License: 100-01784

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Steven Geneser  
100-01784

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: July 21, 2022

RE: Washington School, Harold, Unit 24921  
9130 S University Avenue  
Chicago, IL, 60619

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Washington School, Harold , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Washington School, Harold, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Washington School, Harold Unit: 24921 Region: 06  
Address: 9130 S University Avenue Chicago, IL, 60619  
IDPH ID: 14-016-2990-2401 Building ID: 5380  
Contact: Phone:

### 2. Description of Facility

Original Construction: 1999 Additional Construction:  
Total Square Footage: 2100 No of Floors:  
Current Occupancy: 244

### 3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602


### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880 Fax: 630-790-0882

### 5. Inspector

Inspector Name: John Fenn


Inspector IDPH license # 100-09786  
Reinspection Date: 6/21/2022

Signature:   
Date: 6/21/2022

### 6. Management Planner

Management Planner Name: Steven Geneser

Management Planner IDPH license # 100-01784

Signature:   
Date: 07/21/2022

### 7. Review Date: 07/21/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 7/21/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Washington School, Harold. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5380:

NEW

Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 5380:

NEW

Newly Installed Suspect ACM



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

08	Black Carpet Mastic NOT OBSERVED
09	Insulation in Fire Rated Door
12	9x9 Green Floor Tile Mastic- NOT OBSERVED
18	9x9 Brown & Tan Floor Tile Mastic
25	12x12 Light Blue Floor Tile NOT OBSERVED
26	12x12 Light Blue Floor Tile Mastic NOT OBSERVED
33	12x12 Black w/White Specks Floor Tile
34	12x12 Black w/White Specks Floor Tile Mastic
35	Brown Carpet Mastic
36	12x12 Cream w/Brown Floor Tile
37	12x12 Cream w/Brown Floor Tile Mastic
38	Cream Baseboard
39	Cream Baseboard Mastic
40	4x8 Lay-In Ceiling Panels
41	12x12 White Floor Tile
42	12x12 White Floor Tile Mastic
43	Red Carpet Mastic
44	Green Carpet Mastic NOT OBSERVED
45	12x12 Gray Floor Tile
46	12x12 Gray Floor Tile Mastic
47	Grey and White Ceramic Tile Grout
48	Grey and White Ceramic Tile Adhesive
49	Tan Ceramic Tile Grout
50	Tan Ceramic Tile Adhesive
51	Blue, Tan and Pink Ceramic Tile Grout
52	Blue, Tan and Pink Ceramic Tile Adhesive
53	Grey Carpet Mastic
54	12x12 Beige & Tan Specks Vinyl Floor Tile
55	12x12 Beige & Tan Specks Vinyl Floor Tile Mastic
G	Boiler Gasket
H	Tank Insulation Cloth Wrapping
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

07	Transite Panels (Fireproofing) NOT OBSERVED
09	Insulation in Fire Rated Door
34	12x12 Black w/White Specks Floor Tile Mastic
35	Brown Carpet Mastic

39	Cream Baseboard Mastic
46	12x12 Gray Floor Tile Mastic
48	Grey and White Ceramic Tile Adhesive
50	Tan Ceramic Tile Adhesive
53	Grey Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by John Fenn, IDPH License # 100-09786. The Management Plan was updated by Steven Geneser, IDPH License # 100-01784. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Washington School, Harold Building 5380 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---



# Chicago Public Schools

School Washington School, Harold Unit 24921 Building ID 5380

Address 9130 S University Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
25	12x12 Light Blue Floor Tile NOT OBSERVED			Room 304	ASSUMED	MISC								
26	12x12 Light Blue Floor Tile Mastic NOT OBSERVED			Room 304	ASSUMED	MISC								
27	Red Multi-Color Carpet Mastic- NO ACBM			Kindergarten	NO_ACBM	MISC								
28	Purple Carpet Mastic- NO ACBM			Conference Room and Main Office	NO_ACBM	MISC								
29	Maroon Carpet Mastic- NO ACBM			Assembly Hall	NO_ACBM	MISC								
30	Green Carpet Mastic NOT OBSERVED			Room 111		MISC								
31	Blue Carpet Mastic- NO ACBM			Library	NO_ACBM	MISC								
32	Panel Mastic- NO ACBM			Throughout Building	NO_ACBM	MISC								
33	12x12 Black w/White Specks Floor Tile	5,952	SF	Engineer's Office, 1st, 2nd and 3rd Floor North Corridors, Rooms 302, 303, 304, 305, 306, 307	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12x12 Black w/White Specks Floor Tile Mastic	2,000	SF	Engineer's Office, 1st, 2nd and 3rd Floor North Corridors, Rooms 302, 303, 304, 305, 306, 307	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Brown Carpet Mastic	300	SF	Room 213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12x12 Cream w/Brown Floor Tile	2,400	SF	Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12x12 Cream w/Brown Floor Tile Mastic	2,400	SF	Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Cream Baseboard	1,000	LF	Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Cream Baseboard Mastic	1,000	LF	Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	4x8 Lay-In Ceiling Panels	1,200	SF	Modular Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
41	12x12 White Floor Tile	600	SF	Computer Room /MDF Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12x12 White Floor Tile Mastic	600	SF	Computer Room /MDF Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Red Carpet Mastic	200	SF	Computer Room and Room 201A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Washington School, Harold Unit 24921 Building ID 5380

Address 9130 S University Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
44	Green Carpet Mastic NOT OBSERVED	400	SF	Room 111 (Classroom for the Blind)	ASSUMED	MISC		NONE	0					
45	12x12 Gray Floor Tile	400	SF	Room 205 (207)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12x12 Gray Floor Tile Mastic	400	SF	Room 205 (207)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	Grey and White Ceramic Tile Grout	3,550	SF	1st, 2nd & 3rd Floor Girls' and Boys' Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Grey and White Ceramic Tile Adhesive	3,550	SF	1st, 2nd & 3rd Floor Girls' and Boys' Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Tan Ceramic Tile Grout	72	SF	Principal's Office Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Tan Ceramic Tile Adhesive	72	SF	Principal's Office Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	Blue, Tan and Pink Ceramic Tile Grout	792	SF	Main Entrance Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	Blue, Tan and Pink Ceramic Tile Adhesive	792	SF	Main Entrance Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Grey Carpet Mastic	4,747	SF	Assembly Hall and Assembly Hall Balcony, Projection Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12x12 Beige & Tan Specks Vinyl Floor Tile	700	SF	Room 205	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
55	12x12 Beige & Tan Specks Vinyl Floor Tile Mastic	700	SF	Room 205	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
F	MJP E/F/V on Fiberglass Pipe Insulation - NO ACBM		Fittings	Throughout Building	NO_ACBM	TSI								
G	Boiler Gasket	201	LF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
H	Tank Insulation Cloth Wrapping	70	SF	Boiler Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

# Chicago Public Schools

School Washington School, Harold Unit 24921 Building ID 5380  
Address 9130 S University Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>6/21/2022</b>
Inspector Name <b>John Fenn</b>
<b>100-09786</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
07	Information Not Updated in 2022
08	Not Observed
09	
11	
12	Not Observed
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	Not Observed



# Chicago Public Schools

**School** Washington School, Harold **Unit** 24921 **Building ID** 5380  
**Address** 9130 S University Avenue **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
26	Not Observed
27	
28	
29	
30	Not Observed. Carpet Removed in Room 111
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	Not Observed. Carpet Removed from Room 111
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	

# Chicago Public Schools

**School** Washington School, Harold **Unit** 24921 **Building ID** 5380

**Address** 9130 S University Avenue **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
55	
F	
G	
H	
NEW	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Washington School, Harold

Unit 24921

Building ID 5380

Address 9130 S University Avenue

Chicago, IL, 60619

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Plaster - NO ACBM			Throughout Building	No ACBM	SURFACE					
02	2x4 Ceiling Tile - NO ACBM			Throughout Building	No ACBM	MISC					
03	12x12 White w/Gray Floor Tile - NO ACBM			Room 201	No ACBM	MISC					
04	9x9 Green Floor Tile	50	SF	Kitchen/Food Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12x12 Ceiling Tile - NO ACBM			Lunchroom	No ACBM	MISC					
06	Tectum Wall Covering - NO ACBM			Assembly Hall	No ACBM	MISC					
07	Transite Panels (Fireproofing) NOT OBSERVED	10	SF	3rd Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
08	Black Carpet Mastic NOT OBSERVED			1st Floor Corridor	Assumed	MISC					
09	Insulation in Fire Rated Door	4	EA	Tank Room Entrance (Sealed Doors-Interior Inaccessible)	Assumed	TSI	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
11	12x12 White w/Gray Floor Tile Mastic - NO ACBM			Lunchroom and Room 201	No ACBM	MISC					
12	9x9 Green Floor Tile Mastic- NOT OBSERVED			Kitchen	Assumed	MISC					
13	Green Multi-Colored Carpet Mastic - NO ACBM			1st Floor Corridor	No ACBM	MISC					
14	Tectum Wall Covering Mastic - NO ACBM			Assembly Hall	No ACBM	MISC					
15	Textured Wall Plaster - NO ACBM			Throughout Building	No ACBM	SURFACE					
16	12x12 Ceiling Tile Mastic - NO ACBM			Lunchroom	No ACBM	MISC					
17	9x9 Brown & Tan Floor Tile	30	SF	1st Floor Store Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	9x9 Brown & Tan Floor Tile Mastic	30	SF	1st Floor Store Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12x12 Tan Floor Tile- No ACBM	320	SF	School Store	No ACBM	MISC		0	SF		
20	12x12 Tan Floor Tile Mastic	320	SF	School Store	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12x12 Brown Floor Tile- NO ACBM			Rooms 103, 105, 110, 200, 202 - 204, 206 - 208, 211, 212, 214, 308 - 313	No ACBM	MISC					
22	12x12 Black Floor Tile Mastic- NO ACBM			Rooms 103, 105, 110, 200, 202 - 204, 206 - 208, 211, 212, 214, 308 - 313	No ACBM	MISC					
23	12x12 Beige Floor Tile ABATED			3rd Floor	Abated	MISC					
24	12x12 Beige Floor Tile Mastic ABATED			3rd Floor	Abated	MISC					
25	12x12 Light Blue Floor Tile NOT OBSERVED			Room 304	Assumed	MISC					
26	12x12 Light Blue Floor Tile Mastic NOT OBSERVED			Room 304	Assumed	MISC					
27	Red Multi-Color Carpet Mastic- NO ACBM			Kindergarten	No ACBM	MISC					
28	Purple Carpet Mastic- NO ACBM			Conference Room and Main Office	No ACBM	MISC					
29	Maroon Carpet Mastic- NO ACBM			Assembly Hall	No ACBM	MISC					
30	Green Carpet Mastic NOT OBSERVED			Room 111		MISC					
31	Blue Carpet Mastic- NO ACBM			Library	No ACBM	MISC					
32	Panel Mastic- NO ACBM			Throughout Building	No ACBM	MISC					

# Chicago Public Schools

School Washington School, Harold

Unit 24921

Building ID 5380

Address 9130 S University Avenue

Chicago, IL, 60619

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
33	12x12 Black w/White Specks Floor Tile	5,952	SF	Engineer's Office, 1st, 2nd and 3rd Floor North Corridors, Rooms 302, 303, 304, 305, 306, 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12x12 Black w/White Specks Floor Tile Mastic	2,000	SF	Engineer's Office, 1st, 2nd and 3rd Floor North Corridors, Rooms 302, 303, 304, 305, 306, 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Brown Carpet Mastic	300	SF	Room 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12x12 Cream w/Brown Floor Tile	2,400	SF	Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12x12 Cream w/Brown Floor Tile Mastic	2,400	SF	Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Cream Baseboard	1,000	LF	Modular Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
39	Cream Baseboard Mastic	1,000	LF	Modular Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
40	4x8 Lay-In Ceiling Panels	1,200	SF	Modular Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
41	12x12 White Floor Tile	600	SF	Computer Room /MDF Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12x12 White Floor Tile Mastic	600	SF	Computer Room /MDF Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Red Carpet Mastic	200	SF	Computer Room and Room 201A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Green Carpet Mastic NOT OBSERVED	400	SF	Room 111 (Classroom for the Blind)	Assumed	MISC		0	SF		
45	12x12 Gray Floor Tile	400	SF	Room 205 (207)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12x12 Gray Floor Tile Mastic	400	SF	Room 205 (207)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Grey and White Ceramic Tile Grout	3,550	SF	1st, 2nd & 3rd Floor Girls' and Boys' Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Grey and White Ceramic Tile Adhesive	3,550	SF	1st, 2nd & 3rd Floor Girls' and Boys' Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Tan Ceramic Tile Grout	72	SF	Principal's Office Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Tan Ceramic Tile Adhesive	72	SF	Principal's Office Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Blue, Tan and Pink Ceramic Tile Grout	792	SF	Main Entrance Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Blue, Tan and Pink Ceramic Tile Adhesive	792	SF	Main Entrance Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Grey Carpet Mastic	4,747	SF	Assembly Hall and Assembly Hall Balcony, Projection Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12x12 Beige & Tan Specks Vinyl Floor Tile	700	SF	Room 205	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12x12 Beige & Tan Specks Vinyl Floor Tile Mastic	700	SF	Room 205	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP E/F/V on Fiberglass Pipe Insulation - NO ACBM		Fittings	Throughout Building	No ACBM	TSI			Fittings		
G	Boiler Gasket	201	LF	Boiler Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	Tank Insulation Cloth Wrapping	70	SF	Boiler Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Washington School, Harold  
**Address** 9130 S University Avenue

**Unit** 24921  
 Chicago, IL, 60619

**Building ID** 5380  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

Review Date	7/21/2022
Manager Planner Name	Steven Geneser

HA Number	Management Comments
01	

# Chicago Public Schools

**School** Washington School, Harold  
**Address** 9130 S University Avenue

**Unit** 24921  
 Chicago, IL, 60619

**Building ID** 5380  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

100-01784	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
03	
04	
05	
06	
07	
08	
09	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	

# Chicago Public Schools

**School** Washington School, Harold  
**Address** 9130 S University Avenue

**Unit** 24921  
Chicago, IL, 60619

**Building ID** 5380  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
F	



# Chicago Public Schools

**School** Washington School, Harold  
**Address** 9130 S University Avenue

**Unit** 24921  
Chicago, IL, 60619

**Building ID** 5380  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
G	
H	
NEW	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Plaster - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---


HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Plaster - NO ACBM**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **2x4 Ceiling Tile - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **2x4 Ceiling Tile - NO ACBM**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12x12 White w/Gray Floor Tile - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---


HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12x12 White w/Gray Floor Tile - NO ACBM**  
MATERIAL LOCATION: **Room 201**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen/Food Storage**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile**  
MATERIAL LOCATION: **Kitchen/Food Storage**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **12x12 Ceiling Tile - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **12x12 Ceiling Tile - NO ACBM**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Tectum Wall Covering - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---


HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Tectum Wall Covering - NO ACBM**  
MATERIAL LOCATION: **Assembly Hall**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Transite Panels (Fireproofing) NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Information Not Updated in 2022**

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Transite Panels (Fireproofing) NOT OBSERVED**  
MATERIAL LOCATION: **3rd Floor**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Black Carpet Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS: **Not Observed**

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---


HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Black Carpet Mastic NOT OBSERVED**  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Door**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Tank Room Entrance (Sealed Doors- Interior Inaccessible)**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Door**  
MATERIAL LOCATION: **Tank Room Entrance (Sealed Doors- Interior Inaccessible)**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12x12 White w/Gray Floor Tile Mastic - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom and Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---


HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12x12 White w/Gray Floor Tile Mastic - NO ACBM**  
MATERIAL LOCATION: **Lunchroom and Room 201**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature:



Date: **06/21/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---


HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Green Multi-Colored Carpet Mastic - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Green Multi-Colored Carpet Mastic - NO ACBM**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Tectum Wall Covering Mastic - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Tectum Wall Covering Mastic - NO ACBM**  
MATERIAL LOCATION: **Assembly Hall**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Textured Wall Plaster - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---


HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Textured Wall Plaster - NO ACBM**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12x12 Ceiling Tile Mastic - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12x12 Ceiling Tile Mastic - NO ACBM**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **9x9 Brown & Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Store Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **9x9 Brown & Tan Floor Tile**  
MATERIAL LOCATION: **1st Floor Store Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **9x9 Brown & Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Store Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **9x9 Brown & Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Store Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **School Store**

MATERIAL QUANTITY: **320**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile- No ACBM**  
MATERIAL LOCATION: **School Store**  
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **School Store**  
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **School Store**  
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile- NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 103, 105, 110, 200, 202 - 204, 206 - 208, 211, 212, 214, 308 - 313**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---


HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile- NO ACBM**  
MATERIAL LOCATION: **Rooms 103, 105, 110, 200, 202 - 204, 206 - 208, 211, 212, 214, 308 - 313**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12x12 Black Floor Tile Mastic- NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 103, 105, 110, 200, 202 - 204, 206 - 208, 211, 212, 214, 308 - 313**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---


HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12x12 Black Floor Tile Mastic- NO ACBM**  
MATERIAL LOCATION: **Rooms 103, 105, 110, 200, 202 - 204, 206 - 208, 211, 212, 214, 308 - 313**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile ABATED**  
MATERIAL LOCATION: **3rd Floor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/21/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **3rd Floor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24921 BUIDLING ID: 5380  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: John Fenn  
SCHOOL NAME: Washington School, Harold INSPECTION DATE: 6/21/2022  
ADDRESS: 9130 S University Avenue IDPH LICENSE NO: 100-09786

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 25  
MATERIAL DESCRIPTION: 12x12 Light Blue Floor Tile NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 304

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **Room 304**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24921 BUIDLING ID: 5380  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: John Fenn  
SCHOOL NAME: Washington School, Harold INSPECTION DATE: 6/21/2022  
ADDRESS: 9130 S University Avenue IDPH LICENSE NO: 100-09786

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 26  
MATERIAL DESCRIPTION: 12x12 Light Blue Floor Tile Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 304

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---


HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile Mastic NOT OBSERVED**  
MATERIAL LOCATION: **Room 304**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Red Multi-Color Carpet Mastic- NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kindergarten**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Red Multi-Color Carpet Mastic- NO ACBM**  
MATERIAL LOCATION: **Kindergarten**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24921**    BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold**    INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue**    IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Purple Carpet Mastic- NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Conference Room and Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Purple Carpet Mastic- NO ACBM**  
MATERIAL LOCATION: **Conference Room and Main Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Maroon Carpet Mastic- NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Maroon Carpet Mastic- NO ACBM**  
MATERIAL LOCATION: **Assembly Hall**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Green Carpet Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed. Carpet Removed in Room 111**

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Green Carpet Mastic NOT OBSERVED**  
MATERIAL LOCATION: **Room 111**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic- NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic- NO ACBM**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Panel Mastic- NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---


HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Panel Mastic- NO ACBM**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12x12 Black w/White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, 1st, 2nd and 3rd Floor North Corridors, Rooms 302, 303, 304, 305, 306, 307**

MATERIAL QUANTITY: **5952** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12x12 Black w/White Specks Floor Tile**  
MATERIAL LOCATION: **Engineer's Office, 1st, 2nd and 3rd Floor North Corridors, Rooms 302, 303, 304, 305, 306, 307**  
MATERIAL QUANTITY: **5952** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12x12 Black w/White Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, 1st, 2nd and 3rd Floor North Corridors, Rooms 302, 303, 304, 305, 306, 307**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12x12 Black w/White Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Engineer's Office, 1st, 2nd and 3rd Floor North Corridors, Rooms 302, 303, 304, 305, 306, 307**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 213**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **Room 213**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Modular Building**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Floor Tile**  
MATERIAL LOCATION: **Modular Building**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Modular Building**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Modular Building**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Cream Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Modular Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Cream Baseboard**  
MATERIAL LOCATION: **Modular Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Cream Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Modular Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Cream Baseboard Mastic**  
MATERIAL LOCATION: **Modular Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **4x8 Lay-In Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Modular Building**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **4x8 Lay-In Ceiling Panels**  
MATERIAL LOCATION: **Modular Building**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12x12 White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Computer Room /MDF Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12x12 White Floor Tile**  
MATERIAL LOCATION: **Computer Room /MDF Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Computer Room /MDF Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**  
MATERIAL LOCATION: **Computer Room /MDF Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Red Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Computer Room and Room 201A**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Red Carpet Mastic**  
MATERIAL LOCATION: **Computer Room and Room 201A**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Green Carpet Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111 (Classroom for the Blind)**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed. Carpet Removed from Room 111**

Inspector's Signature:



Date: **06/21/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Green Carpet Mastic NOT OBSERVED**  
MATERIAL LOCATION: **Room 111 (Classroom for the Blind)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 205 (207)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**  
MATERIAL LOCATION: **Room 205 (207)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 205 (207)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**  
MATERIAL LOCATION: **Room 205 (207)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Grey and White Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Girls' and Boys' Restrooms**  
MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Grey and White Ceramic Tile Grout**  
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Girls' and Boys' Restrooms**  
MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Grey and White Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Girls' and Boys' Restrooms**  
MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Grey and White Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Girls' and Boys' Restrooms**  
MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Tan Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office Toilet**  
MATERIAL QUANTITY: **72** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Tan Ceramic Tile Grout**  
MATERIAL LOCATION: **Principal's Office Toilet**  
MATERIAL QUANTITY: **72** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Tan Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office Toilet**  
MATERIAL QUANTITY: **72** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Tan Ceramic Tile Adhesive**  
MATERIAL LOCATION: **Principal's Office Toilet**  
MATERIAL QUANTITY: **72** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Blue, Tan and Pink Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Entrance Foyer**  
MATERIAL QUANTITY: **792** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Blue, Tan and Pink Ceramic Tile Grout**  
MATERIAL LOCATION: **Main Entrance Foyer**  
MATERIAL QUANTITY: **792** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Blue, Tan and Pink Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Entrance Foyer**  
MATERIAL QUANTITY: **792** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Blue, Tan and Pink Ceramic Tile Adhesive**  
MATERIAL LOCATION: **Main Entrance Foyer**  
MATERIAL QUANTITY: **792** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Grey Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall and Assembly Hall Balcony, Projection Room**  
MATERIAL QUANTITY: **4747** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Grey Carpet Mastic**  
MATERIAL LOCATION: **Assembly Hall and Assembly Hall Balcony, Projection Room**  
MATERIAL QUANTITY: **4747** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12x12 Beige & Tan Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 205**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12x12 Beige & Tan Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 205**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12x12 Beige & Tan Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 205**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12x12 Beige & Tan Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 205**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation - NO ACBM**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**  
DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **201** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University  
Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **201** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/21/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUIDLING ID: **5380**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School, Harold** INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Tank Insulation Cloth Wrapping**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School, Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Tank Insulation Cloth Wrapping**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/21/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24921**      BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Washington School,  
Harold**      INSPECTION DATE: **6/21/2022**  
ADDRESS: **9130 S University  
Avenue**      IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/21/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24921** BUILDING ID: **5380**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Washington School,  
Harold** REVIEW DATE: **7/21/2022**  
ADDRESS: **9130 S University Avenue** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 07/21/2022

# APPENDIX B

## Inspector and Management Planner Licenses

---





525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JOHN H FENN**  
2829 N TROY ST  
CHICAGO, IL 60618

4/7/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09786

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

IDPH ILLINOIS DEPARTMENT OF PUBLIC HEALTH PROTECTING HEALTH. IMPROVING LIVES.		<b>ASBESTOS PROFESSIONAL LICENSE</b>		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 09786	ISSUED 4/7/2022	EXPIRES 05/15/2023		INSPECTOR	3/9/2023
<b>JOHN H FENN</b> 2829 N TROY ST CHICAGO, IL 60618 Environmental Health				MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/9/2023 4/2/2023
				<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH. IMPROVING LIVES**  
Nationally Accredited by PHAB

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOHN FENN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/09/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/09/2022

Course Dates:

03/09/2023

Expires:

2203BIR04

Certificate Number:



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

A handwritten signature in black ink, appearing to read "N. Peneff".

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOHN FENN  
has completed the Asbestos Management Planner Refresher course and passed the examination  
on 03/09/2022 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C. Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

03/09/2022

Course Dates:

03/09/2023

Expires:

2203MPR02

Certificate Number:

A handwritten signature in blue ink that reads "N Peneff".

Director of Training  
**Nicholas J. Peneff**  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-011

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that*

**Steve Geneser**

*has on 4/6/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: April 6, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: April 6, 2022

Expiration Date: April 6, 2023

Certificate Number: BIR/1044

*William S. Williams*

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois ☐ 217.787.9800 ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that*

**Steve Geneser**

*has on 4/06/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: April 6, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: April 6, 2022

Expiration Date: April 6, 2023

Certificate Number: MPR/0470

*William S. Williams*

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois ☐ 217.787.9800 ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)



**ASBESTOS  
 PROFESSIONAL  
 LICENSE**

**ID NUMBER**  
**100 - 01784**

**ISSUED**  
**3/1/2022**

**EXPIRES**  
**05/15/2023**

**STEVEN B GENESER**  
 210 BARNSIDE CIRCLE  
 GENEVA, IL 60134

Environmental Health



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

5/5/2022

MANAGEMENT PLANNER

5/5/2022

PROJECT MANAGER

8/4/2022

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
 This license issued under authority of the State of Illinois  
 Department of Public Health

This license is valid only when accompanied by a valid  
 training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed