

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2405  
SCHOOL NAME: Pirie School  
ADDRESS OF SCHOOL: 650 E 85th Street  
CITY: Chicago, IL, 60619

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **9/17/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 7/27/2022 ENROLLMENT 196  
IDPH INSPECTOR LICENSE NUMBER: 100-18281  
IDPH LICENSED INSPECTOR NAME (Please Print): Christopher Antonopoulos  
IDPH MP LICENSE NUMBER: 100-09870  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



8/25/2022

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Pirie School**

650 E 85th Street  
Chicago, IL, 60619

Unit: 24971  
Building ID: 5440

IDPH ID Number: 14-016-2990-2405

**REPORT DATE:**

Thursday, August 25, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 25, 2022

RE: Pirie School, Unit 24971  
650 E 85th Street  
Chicago, IL, 60619

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Pirie School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Pirie School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Pirie School  
Address: 650 E 85th Street  
IDPH ID: 14-016-2990-2405  
Contact: Rupert, Maurice

Unit: 24971  
Chicago, IL, 60619  
Building ID: 5440  
Phone: 7737102608

Region: 06

### 2. Description of Facility

Original Construction: 2003  
Total Square Footage: 4947  
Current Occupancy: 196

Additional Construction:  
No of Floors: 1

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Christopher Antonopoulos



Inspector IDPH license # 100-18281  
Reinspection Date: 7/27/2022

Signature:  
Date: 7/27/2022

### 6. Management Planner

Management Planner Name: Todd Huffer



Management Planner IDPH license # 100-09870

Signature:  
Date: 08/25/2022

### 7. Review Date: 08/25/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 8/25/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Pirie School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5440:

01F	9x9 Tan w/Beige Streaks Floor Tile
07F	9x9 Tan w/Beige Streaks Floor Tile Mastic
40	Carpet Mastic
41	Terrazzo with White & Grey Specks
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 5440:

40	Carpet Mastic
41	Terrazzo with White & Grey Specks
NEW	Newly Installed Suspect ACM



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05	Duct Sleeve (Vibration Dampener)
10	Carpet Mastic
11	1'x1' Ceiling Tile
12	Brown, Tan and White Ceramic Tile Grout
13	Brown, Tan and White Ceramic Tile Adhesive
14	Insulation Inside Vault Door
15	Peach, Blue, Yellow & White Ceramic Tile Grout
16	Peach, Blue, Yellow and White Ceramic Tile Adhesive
17	Grey, Yellow and White Ceramic Tile Grout
18	Grey, Yellow and White Ceramic Tile Adhesive
19	Blue Ceramic Tile Grout
22	12x12 Tan Floor Tile
22M	12x12 Tan Floor Tile Mastic
23	Yellow Ceramic Tile Grout
24	Yellow Ceramic Tile Adhesive
25	Blue and White Ceramic Tile Grout
26	Blue and White Ceramic Tile Adhesive
27	5'x3' Ceiling Tile
28	12x12 Aqua/Design Floor Tile
28M	12x12 Aqua/Design Floor Tile Mastic
29	2'x2' Ceiling Tile
30	12x12 Tan Floor Tile
30M	12x12 Tan Floor Tile Mastic
31	Tan Baseboard
32	Blue Vinyl Flooring
33	Blue Vinyl Floor Adhesive
34	Pink Vinyl Floor
35	Pink Vinyl Floor Mastic
36	Tan Baseboard Mastic
37	12x12 Beige Streaked Vinyl Floor Tile
37A	12x12 Beige Streaked Vinyl Floor Tile Mastic
38	12x12 Gray w/Blue Streaked Vinyl Floor Tile
38A	12x12 Gray w/Blue Streaked Vinyl Floor Tile Mastic
39	12x12 White/Gray/Blue Mottled Vinyl Floor Tile
39A	12x12 White/Gray/Blue Mottled Vinyl Floor Tile Mastic
40	Carpet Mastic
41	Terrazzo with White & Grey Specks
J	Roofing Panels
K	Various Kinds of 1'x1' Ceiling Tile

L	2'x4' Ceiling Tile
M	Plaster Ceiling
N	Fiberglass Pipe Insulation Paper Wrap
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

10	Carpet Mastic
13	Brown, Tan and White Ceramic Tile Adhesive
16	Peach, Blue, Yellow and White Ceramic Tile Adhesive
18	Grey, Yellow and White Ceramic Tile Adhesive
22M	12x12 Tan Floor Tile Mastic
24	Yellow Ceramic Tile Adhesive
26	Blue and White Ceramic Tile Adhesive
28M	12x12 Aqua/Design Floor Tile Mastic
30M	12x12 Tan Floor Tile Mastic
33	Blue Vinyl Floor Adhesive
35	Pink Vinyl Floor Mastic
36	Tan Baseboard Mastic
39A	12x12 White/Gray/Blue Mottled Vinyl Floor Tile Mastic
I	Fire Brick Incinerator Insulation ABATED

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Christopher Antonopoulos, IDPH License # 100-18281. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 8/5/2021

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Pirie School Building 5440 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01A	9x9 Salmon Floor Tile ABATED			N.E. Corridor	ABATED	MISC								Moderate
01B	9x9 White w/Black Streaks Floor Tile ABATED			All Corridors Except N.E. Corridor	ABATED	MISC								Moderate
01C	9x9 Light Blue w/Blue & White Streaks Floor Tile	4,200	SF	Rooms 111, 112 Lunchroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01D	9x9 Gray Floor Tile ABATED			Kitchen	ABATED	MISC		None						Low
01E	9x9 Light Green w/Black & White Streaks Floor Tile ABATED			Room 101	ABATED	MISC								
01F	9x9 Tan w/Beige Streaks Floor Tile	11,500	SF	All Classrooms, Offices, Stage	CHR	MISC	N	LOC	240		Yes	ACBM with potential for significant damage	5	MODERATE
05	Duct Sleeve (Vibration Dampener)	25	SF	Boiler Room	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
07A	9x9 Salmon Floor Tile Mastic ABATED			Northeast Corridor	ABATED	MISC								
07B	9x9 White w/Black Streaks Floor Tile Mastic ABATED			All Corridors Except Northeast Corridor	ABATED	MISC								
07C	9x9 Light Blue w/Blue & White Streaks Floor Tile	4,200	SF	Rooms 111 & 116	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07D	9x9 Gray Floor Tile Mastic ABATED			Kitchen	ABATED	MISC		None						Low
07E	9x9 Light Green w/Black & White Streaks Floor Tile Mastic ABATED			Main Office & Principal's Office	ABATED	MISC								
07F	9x9 Tan w/Beige Streaks Floor Tile Mastic	11,500	SF	All Classrooms (Except 111 & 112), Offices, Stage & Engineer's Office	CHR	MISC	N	LOC	240		Yes	ACBM with potential for significant damage	3	LOW
08A	12x12 Aqua Floor Tile ABATED			South Entrance	ABATED	MISC								
08B	12x12 Beige w/Tan Streaks Floor Tile ABATED			NE and NW Entrances & Patches in Corridors	ABATED	MISC								
09A	12x12 Aqua Floor Tile Mastic ABATED			South Entrance	ABATED	MISC		None						Low
09B	12x12 Beige w/Tan Streaks Floor Tile Mastic ABATED			NE and NW Entrances & Patches in Corridors	ABATED	MISC		None						Low
10	Carpet Mastic	3,740	SF	Room 111 and Book Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	1'x1' Ceiling Tile	33,536	SF	Throughout Classrooms except Gym, Kitchen, Boys and Girls Restrooms	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
12	Brown, Tan and White Ceramic Tile Grout	79	SF	Principal's Office Toilet, Library Toilet and Room 126 Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Brown, Tan and White Ceramic Tile	79	SF	Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Adhesive			Toilet, Library Toilet and Room 126 Toilet								potential for damage		
14	Insulation Inside Vault Door	1	EA	Main Office	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
15	Peach, Blue, Yellow & White Ceramic Tile Grout	49	SF	Counselor's Toilet and Room 116 Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	Peach, Blue, Yellow and White Ceramic Tile Adhesive	49	SF	Counselor's Toilet & Room 116 Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Grey, Yellow and White Ceramic Tile Grout	308	SF	South Boys Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Grey, Yellow and White Ceramic Tile Adhesive	308	SF	South Boys Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Blue Ceramic Tile Grout	616	SF	South Girls Restroom and North Boys Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12x12 White w/Blue Streaks Floor Tile ABATED			SW Entrance	ABATED	MISC		None						Low
20M	12x12 White w/Blue Streaks Floor Tile Mastic ABATED			SW Entrance	ABATED	MISC		None						Low
22	12x12 Tan Floor Tile	1,232	SF	Room 115 (Library)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22M	12x12 Tan Floor Tile Mastic	1,232	SF	Room 115 (Library)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Yellow Ceramic Tile Grout	332	SF	North Girls' Restroom and Room 126 Women's Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Yellow Ceramic Tile Adhesive	332	SF	North Girls' Restroom and Room 126 Women's Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Blue and White Ceramic Tile Grout	252	SF	Lunchroom Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Blue and White Ceramic Tile Adhesive	252	SF	Lunchroom Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	5'x3' Ceiling Tile	6,000	SF	Gym, Boiler Room, Electrical Room	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
28	12x12 Aqua/Design Floor Tile	160	SF	Table in Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28M	12x12 Aqua/Design Floor Tile Mastic	160	SF	Table in Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	2'x2' Ceiling Tile	4,280	SF	Throughout Modular Building, except	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable		LOW

# Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Restrooms								suspect ACBM		
30	12x12 Tan Floor Tile	4,280	SF	Throughout Modular Building, except Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30M	12x12 Tan Floor Tile Mastic	4,280	SF	Throughout Modular Building, except Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Tan Baseboard	600	LF	Throughout Modular Building, except Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Blue Vinyl Flooring	192	SF	Boys' Restrooms in Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Blue Vinyl Floor Adhesive	192	SF	Boys' Restrooms in Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Pink Vinyl Floor	192	SF	Girls' Restroom in Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Pink Vinyl Floor Mastic	192	SF	Girls' Restroom in Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Tan Baseboard Mastic	600	SF	Throughout Modular Building, except Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12x12 Beige Streaked Vinyl Floor Tile	3,000	SF	Corridors and Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37A	12x12 Beige Streaked Vinyl Floor Tile Mastic	3,000	SF	Corridors and Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12x12 Gray w/Blue Streaked Vinyl Floor Tile	3,500	SF	Lunchroom, Kitchen, Main Office and Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38A	12x12 Gray w/Blue Streaked Vinyl Floor Tile Mastic	3,500	SF	Lunchroom, Kitchen, Main Office and Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	12x12 White/Gray/Blue Mottled Vinyl Floor Tile	1,400	SF	Rooms 103 & 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39A	12x12 White/Gray/Blue Mottled Vinyl Floor Tile Mastic	1,400	SF	Rooms 103 & 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Carpet Mastic	200	SF	Nurse's Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
41	Terrazzo with White & Grey Specks	1,000	SF	Rooms 107 & 107A	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
B	MJP E/F/V on Fiberglass Pipe Insulation	350	EA	In Corridors - Above 2x4 Drop-In Ceiling Panels, 1st Floor	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bathroom Chases										
C	Aircell Pipe Insulation	1,500	LF	Throughout Corridors, Lunchroom Storage, Copy Room, & Book Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	MJP E/F/V on Aircell Pipe Insulation	175	EA	Throughout Corridors	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Cardboard Pipe Insulation	2,500	LF	In Corridors - Above 2x4 Drop-In Ceiling Panels and at Classroom Induction Units	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
F	MJP E/F/V on Cardboard Pipe Insulation	150	EA	In Corridors - Above 2x4 Drop-In Ceiling Panels	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Boiler Gaskets-No ACBM			Boiler Room	NO_ACBM	TSI								
I	Fire Brick Incinerator Insulation ABATED			Inaccessible- Door Welded Shut	ABATED	MISC								
J	Roofing Panels	1,000	SF	Boiler Room and Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
K	Various Kinds of 1'x1' Ceiling Tile	26,000	SF	Throughout Classrooms, Including Pre-Kindergarten & Classroom in Core of Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
L	2'x4' Ceiling Tile	5,000	SF	Throughout Corridors	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
M	Plaster Ceiling	3,000	SF	Rooms 110, 111, 112, 113, 114, 115, 116, 107, 108 and 109	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
N	Fiberglass Pipe Insulation Paper Wrap	400	LF	Boiler Room, Slop Sink Room and Lunch Room	ASSUMED	TSI	Y		0		No	ACBM with potential for significant damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	ASSUMED	MISC		UNKNO WN	0		Yes	ACBM with the potential for damage		



# Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>7/27/2022</b>
Inspector Name <b>Christopher Antonopoulos</b>
<b>100-18281</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01A	
01B	
01C	
01D	
01E	
01F	Damage in Room 106 & MDL Room
05	
07A	
07B	
07C	
07D	
07E	
07F	Damage Tiles in Room 106 & MDL Room
08A	
08B	
09A	
09B	
10	
11	
12	
13	
14	
15	
16	

# Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
17	
18	
19	
20	
20M	
22	
22M	
23	
24	
25	
26	
27	
28	
28M	
29	
30	
30M	
31	
32	
33	
34	
35	
36	
37	
37A	
38	
38A	
39	
39A	

# Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
40	
41	
B	
C	
D	
E	
F	
H	
I	Removed/Abated
J	Not Observed 2022
K	
L	
M	
N	
NEW	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Pirie School  
**Address** 650 E 85th Street

**Unit** 24971  
Chicago, IL, 60619

**Building ID** 5440  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01A	9x9 Salmon Floor Tile ABATED			N.E. Corridor	Abated	MISC					
01B	9x9 White w/Black Streaks FloorTile ABATED			All Corridors Except N.E. Corridor	Abated	MISC					
01C	9x9 Light Blue w/Blue & White Streaks Floor Tile	4,200	SF	Rooms 111, 112 Lunchroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01D	9x9 Gray Floor Tile ABATED			Kitchen	Abated	MISC					
01E	9x9 Light Green w/Black & White Streaks Floor Tile ABATED			Room 101	Abated	MISC					
01F	9x9 Tan w/Beige Streaks Floor Tile	11,500	SF	All Classrooms, Offices, Stage	Chrysotile	MISC	No	240	SF	5 ACBM with potential for significant damage	Repair
05	Duct Sleeve (Vibration Dampener)	25	SF	Boiler Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
07A	9x9 Salmon Floor Tile Mastic ABATED			Northeast Corridor	Abated	MISC					
07B	9x9 White w/Black Streaks FloorTile Mastic ABATED			All Corridors Except Northeast Corridor	Abated	MISC					
07C	9x9 Light Blue w/Blue & White Streaks Floor Tile	4,200	SF	Rooms 111 & 116	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07D	9x9 Gray Floor Tile Mastic ABATED			Kitchen	Abated	MISC					
07E	9x9 Light Green w/Black & White Streaks Floor Tile Mastic ABATED			Main Office & Principal's Office	Abated	MISC					
07F	9x9 Tan w/Beige Streaks Floor Tile Mastic	11,500	SF	All Classrooms (Except 111 & 112), Offices, Stage & Engineer's Office	Chrysotile	MISC	No	240	SF	5 ACBM with potential for significant damage	Repair
08A	12x12 Aqua Floor Tile ABATED			South Entrance	Abated	MISC					
08B	12x12 Beige w/Tan Streaks Floor Tile ABATED			NE and NW Entrances & Patches in Corridors	Abated	MISC					
09A	12x12 Aqua Floor Tile Mastic ABATED			South Entrance	Abated	MISC					
09B	12x12 Beige w/Tan Streaks Floor Tile Mastic ABATED			NE and NW Entrances & Patches in Corridors	Abated	MISC					
10	Carpet Mastic	3,740	SF	Room 111 and Book Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	1'x1' Ceiling Tile	33,536	SF	Throughout Classrooms except Gym, Kitchen, Boys and Girls Restrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Brown, Tan and White Ceramic Tile Grout	79	SF	Principal's Office Toilet, Library Toilet and Room 126 Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Brown, Tan and White Ceramic Tile Adhesive	79	SF	Principal's Office Toilet, Library Toilet and Room 126 Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Insulation Inside Vault Door	1	EA	Main Office	Assumed	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
15	Peach, Blue, Yellow & White Ceramic Tile Grout	49	SF	Counselor's Toilet and Room 116 Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Peach, Blue, Yellow and White Ceramic Tile Adhesive	49	SF	Counselor's Toilet & Room 116 Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Pirie School  
**Address** 650 E 85th Street

**Unit** 24971  
Chicago, IL, 60619

**Building ID** 5440  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
17	Grey, Yellow and White Ceramic Tile Grout	308	SF	South Boys Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Grey, Yellow and White Ceramic Tile Adhesive	308	SF	South Boys Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Blue Ceramic Tile Grout	616	SF	South Girls Restroom and North Boys Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12x12 White w/Blue Streaks Floor Tile ABATED			SW Entrance	Abated	MISC					
20M	12x12 White w/Blue Streaks Floor Tile Mastic ABATED			SW Entrance	Abated	MISC					
22	12x12 Tan Floor Tile	1,232	SF	Room 115 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22M	12x12 Tan Floor Tile Mastic	1,232	SF	Room 115 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Yellow Ceramic Tile Grout	332	SF	North Girls' Restroom and Room 126 Women's Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Yellow Ceramic Tile Adhesive	332	SF	North Girls' Restroom and Room 126 Women's Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Blue and White Ceramic Tile Grout	252	SF	Lunchroom Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Blue and White Ceramic Tile Adhesive	252	SF	Lunchroom Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	5'x3' Ceiling Tile	6,000	SF	Gym, Boiler Room, Electrical Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
28	12x12 Aqua/Design Floor Tile	160	SF	Table in Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28M	12x12 Aqua/Design Floor Tile Mastic	160	SF	Table in Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	2'x2' Ceiling Tile	4,280	SF	Throughout Modular Building, except Restrooms	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
30	12x12 Tan Floor Tile	4,280	SF	Throughout Modular Building, except Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30M	12x12 Tan Floor Tile Mastic	4,280	SF	Throughout Modular Building, except Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Tan Baseboard	600	LF	Throughout Modular Building, except Restrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
32	Blue Vinyl Flooring	192	SF	Boys' Restrooms in Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Blue Vinyl Floor Adhesive	192	SF	Boys' Restrooms in Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Pink Vinyl Floor	192	SF	Girls' Restroom in Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Pink Vinyl Floor Mastic	192	SF	Girls' Restroom in Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Tan Baseboard Mastic	600	SF	Throughout Modular Building, except Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12x12 Beige Streaked Vinyl Floor Tile	3,000	SF	Corridors and Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37A	12x12 Beige Streaked Vinyl Floor Tile Mastic	3,000	SF	Corridors and Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Pirie School  
**Address** 650 E 85th Street

**Unit** 24971  
Chicago, IL, 60619

**Building ID** 5440  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
38	12x12 Gray w/Blue Streaked Vinyl Floor Tile	3,500	SF	Lunchroom, Kitchen, Main Office and Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38A	12x12 Gray w/Blue Streaked Vinyl Floor Tile Mastic	3,500	SF	Lunchroom, Kitchen, Main Office and Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12x12 White/Gray/Blue Mottled Vinyl Floor Tile	1,400	SF	Rooms 103 & 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39A	12x12 White/Gray/Blue Mottled Vinyl Floor Tile Mastic	1,400	SF	Rooms 103 & 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Carpet Mastic	200	SF	Nurse's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Terrazzo with White & Grey Specks	1,000	SF	Rooms 107 & 107A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	MJP E/F/V on Fiberglass Pipe Insulation	350	EA	In Corridors - Above 2x4 Drop-In Ceiling Panels, 1st Floor Bathroom Chases	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
C	Aircell Pipe Insulation	1,500	LF	Throughout Corridors, Lunchroom Storage, Copy Room, & Book Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP E/F/V on Aircell Pipe Insulation	175	EA	Throughout Corridors	Chrysotile	TSI	Yes	0	EA	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Cardboard Pipe Insulation	2,500	LF	In Corridors - Above 2x4 Drop-In Ceiling Panels and at Classroom Induction Units	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP E/F/V on Cardboard Pipe Insulation	150	EA	In Corridors - Above 2x4 Drop-In Ceiling Panels	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
H	Boiler Gaskets-No ACBM			Boiler Room	No ACBM	TSI					
I	Fire Brick Incinerator Insulation ABATED			Inaccessible- Door Welded Shut	Abated	MISC					
J	Roofing Panels	1,000	SF	Boiler Room and Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	Various Kinds of 1'x1' Ceiling Tile	26,000	SF	Throughout Classrooms, Including Pre-Kindergarten & Classroom in Core of Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	2'x4' Ceiling Tile	5,000	SF	Throughout Corridors	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M	Plaster Ceiling	3,000	SF	Rooms 110, 111, 112, 113, 114, 115, 116, 107, 108 and 109	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
N	Fiberglass Pipe Insulation Paper Wrap	400	LF	Boiler Room, Slop Sink Room and Lunch Room	Assumed	TSI	Yes	0	LF	5 ACBM with potential for significant damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	Assumed	MISC		0		6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Pirie School  
**Address** 650 E 85th Street

**Unit** 24971  
Chicago, IL, 60619

**Building ID** 5440  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	8/25/2022
Manager Planner Name	Todd Huffer
100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01A	
01B	
01C	
01D	
01E	
01F	Damage in Room 106 & MDL Room. Patch and Repair
05	



# Chicago Public Schools

**School** Pirie School  
**Address** 650 E 85th Street

**Unit** 24971  
 Chicago, IL, 60619

**Building ID** 5440  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
07A	
07B	
07C	
07D	
07E	
07F	Damage Tiles in Room 106 & MDL Room. Patch and Repair
08A	
08B	
09A	
09B	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
20M	
22	
22M	
23	
24	
25	

# Chicago Public Schools

**School** Pirie School  
**Address** 650 E 85th Street

**Unit** 24971  
 Chicago, IL, 60619

**Building ID** 5440  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
26	
27	
28	
28M	
29	
30	
30M	
31	
32	
33	
34	
35	
36	
37	
37A	
38	
38A	
39	
39A	
40	
41	
B	
C	
D	
E	
F	
H	

# Chicago Public Schools

**School** Pirie School  
**Address** 650 E 85th Street

**Unit** 24971  
Chicago, IL, 60619

**Building ID** 5440  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
I	
J	
K	
L	
M	
N	
NEW	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**  
MATERIAL DESCRIPTION: **9x9 Salmon Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **N.E. Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **01A**  
MATERIAL DESCRIPTION: **9x9 Salmon Floor Tile ABATED**  
MATERIAL LOCATION: **N.E. Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01B**  
MATERIAL DESCRIPTION: **9x9 White w/Black Streaks FloorTile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **All Corridors Except N.E. Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **01B**  
MATERIAL DESCRIPTION: **9x9 White w/Black Streaks FloorTile ABATED**  
MATERIAL LOCATION: **All Corridors Except N.E. Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01C**  
MATERIAL DESCRIPTION: **9x9 Light Blue w/Blue & White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 111, 112 Lunchroom**  
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **01C**  
MATERIAL DESCRIPTION: **9x9 Light Blue w/Blue & White Streaks Floor Tile**  
MATERIAL LOCATION: **Rooms 111, 112 Lunchroom**  
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01D**  
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **01D**  
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile ABATED**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 01E  
MATERIAL DESCRIPTION: 9x9 Light Green w/Black & White Streaks Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 101

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **01E**  
MATERIAL DESCRIPTION: **9x9 Light Green w/Black & White Streaks Floor Tile ABATED**  
MATERIAL LOCATION: **Room 101**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 01F  
MATERIAL DESCRIPTION: 9x9 Tan w/Beige Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 5 ACBM with potential for significant damage  
HISTORICAL DAMAGE REASON: Physical Damage  
Other  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: Physical Damage  
Other  
DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: All Classrooms, Offices, Stage  
MATERIAL QUANTITY: 11500 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Damage in Room 106 & MDL Room

Inspector's Signature: Christopher Antonopoulos

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **01F**  
MATERIAL DESCRIPTION: **9x9 Tan w/Beige Streaks Floor Tile**  
MATERIAL LOCATION: **All Classrooms, Offices, Stage**  
MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **240** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Damage in Room 106 & MDL Room. Patch and Repair

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Duct Sleeve (Vibration Dampener)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Duct Sleeve (Vibration Dampener)**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**  
MATERIAL DESCRIPTION: **9x9 Salmon Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Northeast Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **07A**  
MATERIAL DESCRIPTION: **9x9 Salmon Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **Northeast Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07B**  
MATERIAL DESCRIPTION: **9x9 White w/Black Streaks FloorTile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Corridors Except Northeast Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **07B**  
MATERIAL DESCRIPTION: **9x9 White w/Black Streaks FloorTile Mastic ABATED**  
MATERIAL LOCATION: **All Corridors Except Northeast Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07C**  
MATERIAL DESCRIPTION: **9x9 Light Blue w/Blue & White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 111 & 116**  
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **07C**  
MATERIAL DESCRIPTION: **9x9 Light Blue w/Blue & White Streaks Floor Tile**  
MATERIAL LOCATION: **Rooms 111 & 116**  
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07D**  
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **07D**  
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07E  
MATERIAL DESCRIPTION: 9x9 Light Green w/Black & White Streaks Floor Tile Mastic ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office & Principal's Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **07E**  
MATERIAL DESCRIPTION: **9x9 Light Green w/Black & White Streaks Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **Main Office & Principal's Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07F**  
MATERIAL DESCRIPTION: **9x9 Tan w/Beige Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Classrooms (Except 111 & 112), Offices, Stage & Engineer's Office**  
MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **11500** DAMAGE UNITS: **SF**  
COMMENTS: **Damage Tiles in Room 106 & MDL Room**

Inspector's Signature: *Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **07F**  
MATERIAL DESCRIPTION: **9x9 Tan w/Beige Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **All Classrooms (Except 111 & 112), Offices, Stage & Engineer's Office**  
MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **240** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Damage Tiles in Room 106 & MDL Room. Patch and Repair

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 08A  
MATERIAL DESCRIPTION: 12x12 Aqua Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: South Entrance

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **12x12 Aqua Floor Tile ABATED**  
MATERIAL LOCATION: **South Entrance**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 08B  
MATERIAL DESCRIPTION: 12x12 Beige w/Tan Streaks Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: NE and NW Entrances & Patches in Corridors

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **08B**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile ABATED**  
MATERIAL LOCATION: **NE and NW Entrances & Patches in Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **12x12 Aqua Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **South Entrance**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **12x12 Aqua Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **South Entrance**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022** \_\_\_\_\_

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09B**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **NE and NW Entrances & Patches in Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **09B**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **NE and NW Entrances & Patches in Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 111 and Book Room**  
MATERIAL QUANTITY: **3740** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Room 111 and Book Room**  
MATERIAL QUANTITY: **3740** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Classrooms except Gym, Kitchen, Boys and Girls Restrooms**  
MATERIAL QUANTITY: **33536** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**  
MATERIAL LOCATION: **Throughout Classrooms except Gym, Kitchen, Boys and Girls Restrooms**  
MATERIAL QUANTITY: **33536** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12  
MATERIAL DESCRIPTION: Brown, Tan and White Ceramic Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Principal's Office Toilet, Library Toilet and Room 126 Toilet  
MATERIAL QUANTITY: 79 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Brown, Tan and White Ceramic Tile Grout**  
MATERIAL LOCATION: **Principal's Office Toilet, Library Toilet and Room 126 Toilet**  
MATERIAL QUANTITY: **79** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13  
MATERIAL DESCRIPTION: Brown, Tan and White Ceramic Tile Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Principal's Office Toilet, Library Toilet and Room 126 Toilet  
MATERIAL QUANTITY: 79 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Brown, Tan and White Ceramic Tile Adhesive**  
MATERIAL LOCATION: **Principal's Office Toilet, Library Toilet and Room 126 Toilet**  
MATERIAL QUANTITY: **79** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14  
MATERIAL DESCRIPTION: Insulation Inside Vault Door  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Main Office  
MATERIAL QUANTITY: 1    MATERIAL UNITS: EA  
DAMAGE QUANTITY:    DAMAGE UNITS: EA

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Insulation Inside Vault Door**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15  
MATERIAL DESCRIPTION: Peach, Blue, Yellow & White Ceramic Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Counselor's Toilet and Room 116 Toilet  
MATERIAL QUANTITY: 49    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Peach, Blue, Yellow & White Ceramic Tile Grout**  
MATERIAL LOCATION: **Counselor's Toilet and Room 116 Toilet**  
MATERIAL QUANTITY: **49** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Peach, Blue, Yellow and White Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Counselor's Toilet & Room 116 Toilet**  
MATERIAL QUANTITY: **49** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Peach, Blue, Yellow and White Ceramic Tile Adhesive**  
MATERIAL LOCATION: **Counselor's Toilet & Room 116 Toilet**  
MATERIAL QUANTITY: **49** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17  
MATERIAL DESCRIPTION: Grey, Yellow and White Ceramic Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: South Boys Restroom  
MATERIAL QUANTITY: 308    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Grey, Yellow and White Ceramic Tile Grout**  
MATERIAL LOCATION: **South Boys Restroom**  
MATERIAL QUANTITY: **308** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18  
MATERIAL DESCRIPTION: Grey, Yellow and White Ceramic Tile Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: South Boys Restroom  
MATERIAL QUANTITY: 308    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Grey, Yellow and White Ceramic Tile Adhesive**  
MATERIAL LOCATION: **South Boys Restroom**  
MATERIAL QUANTITY: **308** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **South Girls Restroom and North Boys Restroom**  
MATERIAL QUANTITY: **616** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**  
MATERIAL LOCATION: **South Girls Restroom and North Boys Restroom**  
MATERIAL QUANTITY: **616** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **SW Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12x12 White w/Blue Streaks Floor Tile ABATED**

MATERIAL LOCATION: **SW Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20M**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Streaks Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **SW Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **20M**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Streaks Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **SW Entrance**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22  
MATERIAL DESCRIPTION: 12x12 Tan Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 115 (Library)  
MATERIAL QUANTITY: 1232    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
MATERIAL LOCATION: **Room 115 (Library)**  
MATERIAL QUANTITY: **1232** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22M  
MATERIAL DESCRIPTION: 12x12 Tan Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 115 (Library)  
MATERIAL QUANTITY: 1232 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **22M**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Room 115 (Library)**  
MATERIAL QUANTITY: **1232** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23  
MATERIAL DESCRIPTION: Yellow Ceramic Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: North Girls' Restroom and Room 126 Women's Toilet  
MATERIAL QUANTITY: 332    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Yellow Ceramic Tile Grout**  
MATERIAL LOCATION: **North Girls' Restroom and Room 126 Women's Toilet**  
MATERIAL QUANTITY: **332** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24  
MATERIAL DESCRIPTION: Yellow Ceramic Tile Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: North Girls' Restroom and Room 126 Women's Toilet  
MATERIAL QUANTITY: 332 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Yellow Ceramic Tile Adhesive**  
MATERIAL LOCATION: **North Girls' Restroom and Room 126 Women's Toilet**  
MATERIAL QUANTITY: **332** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 25  
MATERIAL DESCRIPTION: Blue and White Ceramic Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Lunchroom Restroom  
MATERIAL QUANTITY: 252 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Blue and White Ceramic Tile Grout**  
MATERIAL LOCATION: **Lunchroom Restroom**  
MATERIAL QUANTITY: **252** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 26  
MATERIAL DESCRIPTION: Blue and White Ceramic Tile Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Lunchroom Restroom  
MATERIAL QUANTITY: 252    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Blue and White Ceramic Tile Adhesive**  
MATERIAL LOCATION: **Lunchroom Restroom**  
MATERIAL QUANTITY: **252** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **5'x3' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym, Boiler Room, Electrical Room**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **5'x3' Ceiling Tile**  
MATERIAL LOCATION: **Gym, Boiler Room, Electrical Room**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28  
MATERIAL DESCRIPTION: 12x12 Aqua/Design Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Table in Storage Room  
MATERIAL QUANTITY: 160    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12x12 Aqua/Design Floor Tile**  
MATERIAL LOCATION: **Table in Storage Room**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28M  
MATERIAL DESCRIPTION: 12x12 Aqua/Design Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Table in Storage Room  
MATERIAL QUANTITY: 160    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28M**  
MATERIAL DESCRIPTION: **12x12 Aqua/Design Floor Tile Mastic**  
MATERIAL LOCATION: **Table in Storage Room**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29  
MATERIAL DESCRIPTION: 2'x2' Ceiling Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 7 Any remaining friable ACBM or friable suspect ACBM  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Throughout Modular Building, except Restrooms  
MATERIAL QUANTITY: 4280    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**  
MATERIAL LOCATION: **Throughout Modular Building, except Restrooms**  
MATERIAL QUANTITY: **4280** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Modular Building, except Restrooms**  
MATERIAL QUANTITY: **4280** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
MATERIAL LOCATION: **Throughout Modular Building, except Restrooms**  
MATERIAL QUANTITY: **4280** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30M**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Modular Building, except Restrooms**  
MATERIAL QUANTITY: **4280** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30M**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout Modular Building, except Restrooms**  
MATERIAL QUANTITY: **4280** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Tan Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Modular Building, except Restrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Tan Baseboard**  
MATERIAL LOCATION: **Throughout Modular Building, except Restrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Blue Vinyl Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boys' Restrooms in Modular Building**  
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Blue Vinyl Flooring**  
MATERIAL LOCATION: **Boys' Restrooms in Modular Building**  
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Blue Vinyl Floor Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boys' Restrooms in Modular Building**  
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Blue Vinyl Floor Adhesive**  
MATERIAL LOCATION: **Boys' Restrooms in Modular Building**  
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Pink Vinyl Floor**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Girls' Restroom in Modular Building**  
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Pink Vinyl Floor**  
MATERIAL LOCATION: **Girls' Restroom in Modular Building**  
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35  
MATERIAL DESCRIPTION: Pink Vinyl Floor Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Girls' Restroom in Modular Building  
MATERIAL QUANTITY: 192 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Pink Vinyl Floor Mastic**  
MATERIAL LOCATION: **Girls' Restroom in Modular Building**  
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 36  
MATERIAL DESCRIPTION: Tan Baseboard Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Throughout Modular Building, except Restrooms  
MATERIAL QUANTITY: 600 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Tan Baseboard Mastic**  
MATERIAL LOCATION: **Throughout Modular Building, except Restrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Beige Streaked Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridors and Vestibules**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Beige Streaked Vinyl Floor Tile**  
MATERIAL LOCATION: **Corridors and Vestibules**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37A**  
MATERIAL DESCRIPTION: **12x12 Beige Streaked Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridors and Vestibules**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **37A**  
MATERIAL DESCRIPTION: **12x12 Beige Streaked Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Corridors and Vestibules**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12x12 Gray w/Blue Streaked Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom, Kitchen, Main Office and Principal's Office**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12x12 Gray w/Blue Streaked Vinyl Floor Tile**  
MATERIAL LOCATION: **Lunchroom, Kitchen, Main Office and Principal's Office**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38A**  
MATERIAL DESCRIPTION: **12x12 Gray w/Blue Streaked Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom, Kitchen, Main Office and Principal's Office**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **38A**  
MATERIAL DESCRIPTION: **12x12 Gray w/Blue Streaked Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Lunchroom, Kitchen, Main Office and Principal's Office**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12x12 White/Gray/Blue Mottled Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 103 & 104**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12x12 White/Gray/Blue Mottled Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 103 & 104**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39A  
MATERIAL DESCRIPTION: 12x12 White/Gray/Blue Mottled Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 103 & 104  
MATERIAL QUANTITY: 1400 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **39A**  
MATERIAL DESCRIPTION: **12x12 White/Gray/Blue Mottled Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 103 & 104**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **In Corridors - Above 2x4 Drop-In Ceiling Panels, 1st Floor Bathroom Chases**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **In Corridors - Above 2x4 Drop-In Ceiling Panels, 1st Floor Bathroom Chases**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Corridors, Lunchroom Storage, Copy Room, & Book Room**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Throughout Corridors, Lunchroom Storage, Copy Room, & Book Room**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: D  
MATERIAL DESCRIPTION: MJP E/F/V on Aircell Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 7 Any remaining friable ACBM or friable suspect ACBM  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Throughout Corridors  
MATERIAL QUANTITY: 175    MATERIAL UNITS: EA  
DAMAGE QUANTITY:    DAMAGE UNITS: EA

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Throughout Corridors**  
MATERIAL QUANTITY: **175** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **In Corridors - Above 2x4 Drop-In Ceiling Panels and at Classroom Induction Units**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **In Corridors - Above 2x4 Drop-In Ceiling Panels and at Classroom Induction Units**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: F  
MATERIAL DESCRIPTION: MJP E/F/V on Cardboard Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: In Corridors - Above 2x4 Drop-In Ceiling Panels  
MATERIAL QUANTITY: 150    MATERIAL UNITS: EA  
DAMAGE QUANTITY:    DAMAGE UNITS: EA

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **In Corridors - Above 2x4 Drop-In Ceiling Panels**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Boiler Gaskets-No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Boiler Gaskets-No ACBM**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24971 BUIDLING ID: 5440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: I  
MATERIAL DESCRIPTION: Fire Brick Incinerator Insulation ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Inaccessible- Door Welded Shut

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Removed/Abated

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Fire Brick Incinerator Insulation ABATED**

MATERIAL LOCATION: **Inaccessible- Door Welded Shut**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Roofing Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room and Gym**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed 2022**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Roofing Panels**  
MATERIAL LOCATION: **Boiler Room and Gym**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 24971    BUILDING ID: 5440  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Pirie School    INSPECTION DATE: 7/27/2022  
ADDRESS: 650 E 85th Street    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: K  
MATERIAL DESCRIPTION: Various Kinds of 1'x1' Ceiling Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Throughout Classrooms, Including Pre-Kindergarten & Classroom in Core of Building  
MATERIAL QUANTITY: 26000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Various Kinds of 1'x1' Ceiling Tile**  
MATERIAL LOCATION: **Throughout Classrooms, Including Pre-Kindergarten & Classroom in Core of Building**  
MATERIAL QUANTITY: **26000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Corridors**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
MATERIAL LOCATION: **Throughout Corridors**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Plaster Ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 110, 111, 112, 113, 114, 115, 116, 107, 108 and 109**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Plaster Ceiling**  
MATERIAL LOCATION: **Rooms 110, 111, 112, 113, 114, 115, 116, 107, 108 and 109**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School** INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation Paper Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room, Slop Sink Room and Lunch Room**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/27/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School** REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation Paper Wrap**  
MATERIAL LOCATION: **Boiler Room, Slop Sink Room and Lunch Room**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24971**    BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School**    INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street**    IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Terrazzo with White & Grey Specks**  
MATERIAL LOCATION: **Rooms 107 & 107A**  
MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/27/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24971**      BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School**      REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Terrazzo with White & Grey Specks**  
MATERIAL LOCATION: **Rooms 107 & 107A**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24971**      BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School**      INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Nurse's Office**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24971**      BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School**      REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Nurse's Office**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24971**      BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Pirie School**      INSPECTION DATE: **7/27/2022**  
ADDRESS: **650 E 85th Street**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/27/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24971**      BUILDING ID: **5440**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Pirie School**      REVIEW DATE: **8/25/2022**  
ADDRESS: **650 E 85th Street**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY: **0**      DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 08/25/2022

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER ANTONOPOULOS  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 06/01/2021 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II; Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

06/01/2021

Course Dates:

06/01/2022

Expires:

2106BIR11

Certificate Number:

A handwritten signature in black ink, appearing to read "N Penneff", written over a rectangular stamp area.

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER J. ANTONOPOULOS  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 06/03/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

06/03/2022

Course Dates:

06/03/2023

Expires:

2206BIR01

Certificate Number:



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com


A handwritten signature in black ink, appearing to read "N. Peneff", is written over a light-colored rectangular background.

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B




 **ASBESTOS  
PROFESSIONAL  
LICENSE**

<b>ID NUMBER</b>	<b>ISSUED</b>	<b>EXPIRES</b>
100 - 18281	2/10/2022	05/15/2023

**CHRISTOPHER J ANTONOPO**  
1736 W 102nd ST  
CHICAGO, IL 60643

Environmental Health



<b>ENDORSEMENT</b>	<b>TC EXPIRES</b>
INSPECTOR	6/1/2022

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**TODD T HUFFER**  
315 HATLEN COURT  
MT. PROSPECT, IL 60056

2/18/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	<b>ASBESTOS PROFESSIONAL LICENSE</b>		INSPECTOR	11/1/2022
<b>ID NUMBER</b> 100 - 09870	<b>ISSUED</b> 2/18/2022	<b>EXPIRES</b> 05/15/2023	MANAGEMENT PLANNER	11/19/2022
<b>TODD T HUFFER</b> 315 HATLEN COURT MT. PROSPECT, IL 60056 Environmental Health			PROJECT MANAGER	10/20/2022
			AIR SAMPLING PROFESSIONAL	
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815

  
Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255

  
Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265

  
Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed