

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2414
SCHOOL NAME: Pullman School
ADDRESS OF SCHOOL: 11311 Forrestville
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/20/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 8/9/2022 ENROLLMENT 302
IDPH INSPECTOR LICENSE NUMBER: 100-18281
IDPH LICENSED INSPECTOR NAME (Please Print): Christopher Antonopoulos
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

9/5/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Pullman School

11311 Forrestville
Chicago, IL, 60628

Unit: 25041
Building ID: 5530

IDPH ID Number: 14-016-2990-2414

REPORT DATE:

Monday, September 05, 2022

Prepared for:

**Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

09/05/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25041 Region: 06 IDPH ID: 14-016-2990-2414

School: Pullman School Building ID: 5530

Address: 11311 Forrestville
Chicago, IL, 60628

Building Contact: Palmer, Chris Contact Phone: 7736306543

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/9/2022

Review Date: 09/05/2022

Inspector: Christopher Antonopoulos Inspector IDPH License: 100-18281
Management Planner: Todd Huffer Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 05, 2022

RE: Pullman School, Unit 25041
11311 Forrestville
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Pullman School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Pullman School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Pullman School
Address: 11311 Forrestville
IDPH ID: 14-016-2990-2414
Contact: Palmer, Chris

Unit: 25041
Chicago, IL, 60628
Building ID: 5530
Phone: 7736306543

Region: 06

2. Description of Facility

Original Construction: 1907
Total Square Footage: 80075
Current Occupancy: 302

Additional Construction:
No of Floors: 3

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Christopher Antonopoulos



Inspector IDPH license # 100-18281
Reinspection Date: 8/9/2022

Signature:
Date: 8/9/2022

6. Management Planner

Management Planner Name: Todd Huffer



Management Planner IDPH license # 100-09870

Signature:
Date: 09/05/2022

7. Review Date: 09/05/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 9/5/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Pullman School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5530:

03C	12x12 Blue Floor Tile
14	Blue Carpet Mastic ABATED
18	12x12 Orange w/White Streaks Floor Tile ABATED
19	12x12 Orange w/White Streaks Floor Tile Mastic ABATED
27	Brown Carpet Adhesive ABATED
37	12"x12" Yellow/Cream/Light Grey Mix Floor Tile
37A	12"x12" Yellow/Cream/Light Grey Mix Floor Tile Mastic
38	1'x1' Ceiling Tiles

39	12"x12" Light Brown & Red Mix Floor Tile
40	12"x12" Light Brown & Red Mix Floor Tile Mastic
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 5530:

37	12"x12" Yellow/Cream/Light Grey Mix Floor Tile
37A	12"x12" Yellow/Cream/Light Grey Mix Floor Tile Mastic
38	1'x1' Ceiling Tiles
39	12"x12" Light Brown & Red Mix Floor Tile
40	12"x12" Light Brown & Red Mix Floor Tile Mastic
NEW	Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	2x4 Acoustical Ceiling Tile
03B	12x12 Beige w/White Streaks Floor Tile
03C	12x12 Blue Floor Tile
03D	12x12 Dark Gray w/White Specks Floor Tile
03E	12x12 Dark Gray Floor Tile
05B	12x12 Beige w/White Stripes Floor Tile Mastic
05C	12x12 Blue Floor Tile Mastic
05D	12x12 Dark Grey w/White Specks Floor Tile Mastic
05E	12x12 Dark Gray Floor Tile Mastic
07	Black Mopboard
07A	Brown Mopboard
08	Black Mopboard Mastic
08A	Brown Mopboard Mastic
10	Boiler Gaskets
12	Fire Brick
15	Gray Carpet Mastic
16	12x12 Red and White Streaks Floor Tile
17	12x12 Red and White Streaks Floor Tile Mastic
20	12x12 Blue w/White Streaks Floor Tile
21	12x12 Blue w/White Streaks Floor Tile Mastic
22	12x12 Light Blue w/Blue Streaks Floor Tile
23	12x12 Light Blue w/Blue Streaks Floor Tile Mastic
24	12x12 Tan w/Brown Streaks Floor Tile
26	2'x4' Ceiling Tile
28	Brown Mosaic Ceramic Tile Grout
29	Brown Mosaic Ceramic Tile Adhesive
30	Hardcoat Plaster - Walls and Ceilings
31	12"x12" Peach Vinyl Floor Tile
32	12"x12" Peach Vinyl Floor Tile Mastic
33	12"x12" Cream w/Tan Streaks Floor Tile
34	12"x12" Cream w/Tan Streaks Floor Tile Mastic
35	Red Carpet Mastic
36	Wood finish Laminate Flooring
37	12"x12" Yellow/Cream/Light Grey Mix Floor Tile
37A	12"x12" Yellow/Cream/Light Grey Mix Floor Tile Mastic
38	1'x1' Ceiling Tiles
39	12"x12" Light Brown & Red Mix Floor Tile
40	12"x12" Light Brown & Red Mix Floor Tile Mastic
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

05B	12x12 Beige w/White Stripes Floor Tile Mastic
05C	12x12 Blue Floor Tile Mastic
05D	12x12 Dark Grey w/White Specks Floor Tile Mastic
05E	12x12 Dark Gray Floor Tile Mastic
08	Black Mopboard Mastic
10	Boiler Gaskets
12	Fire Brick
15	Gray Carpet Mastic
23	12x12 Light Blue w/Blue Streaks Floor Tile Mastic
26	2'x4' Ceiling Tile
29	Brown Mosaic Ceramic Tile Adhesive
32	12"x12" Peach Vinyl Floor Tile Mastic
D	MAG Block Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Christopher Antonopoulos, IDPH License # 100-18281. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 7/21/2021

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Pullman School Building 5530 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Pullman School Unit 25041 Building ID 5530

Address 11311 Forrestville Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
07	Black Mopboard	90	LF	Lunchrooms 1 and 2	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07A	Brown Mopboard	124	LF	Ground Floor East Exit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Black Mopboard Mastic	90	LF	Lunchrooms 1 and 2	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08A	Brown Mopboard Mastic	124	LF	Ground Floor East Exit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	Boiler Gaskets	10	LF	Boiler Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Fire Brick	80	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Blue Carpet Mastic ABATED			Room 102	ABATED	MISC					Yes			
15	Gray Carpet Mastic	1,600	SF	Athletic Storage Room and Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12x12 Red and White Streaks Floor Tile	1,500	SF	Room 305, 3rd Floor Lounge, and Athletic Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12x12 Red and White Streaks Floor Tile Mastic	1,500	SF	Room 305, 3rd Floor Lounge, and Athletic Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12x12 Orange w/White Streaks Floor Tile ABATED			2nd Floor Lounge, Rooms 101 and 108	ABATED	MISC					Yes			
19	12x12 Orange w/White Streaks Floor Tile Mastic ABATED			2nd Floor Lounge, Rooms 101 and 108	ABATED	MISC					Yes			
20	12x12 Blue w/White Streaks Floor Tile	30	SF	Principal's Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
21	12x12 Blue w/White Streaks Floor Tile Mastic	30	SF	Principal's Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12x12 Light Blue w/Blue Streaks Floor Tile	1,500	SF	Room 001, Room 001 Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
23	12x12 Light Blue w/Blue Streaks Floor Tile Mastic	1,500	SF	Room 001, Room 001 Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12x12 Tan w/Brown Streaks Floor Tile	3,100	SF	Auditorium, Girls' Play Room, Speech Room, NW Corner-Room, and MDF Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12x12 Tan w/Brown Streaks Floor Tile Mastic	3,100	SF	Play Room, Speech Room, NW Corner-Room, and MDF Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	2'x4' Ceiling Tile	15,000	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Pullman School Unit 25041 Building ID 5530

Address 11311 Forrestville Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
F	Fiber Glass Hard Joints ABATED			Basement Fan Room, Corridors on 1st, 2nd and 3rd Floors, 1st Floor Bathrooms	ABATED	TSI								
G	Cardboard Hard Fittings ABATED			Basement, Fan Room, Boiler Room	ABATED	TSI								
H	Boiler Blanket Insulation - Not Observed			Boiler Room	ABATED	TSI								
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

Chicago Public Schools

School Pullman School Unit 25041 Building ID 5530

Address 11311 Forrestville Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/9/2022
Inspector Name Christopher Antonopoulos
100-18281 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
02	Ceiling Tiles replaced in Rooms 101, 102, 204, 208 & 209
03	
03A	
03B	
03C	
03D	
03E	
03G	Hardwood Floor
04	
04A	
05	
05A	
05B	
05C	
05D	
05E	
05G	
06	
06A	
06H	
07	
07A	
08	
08A	

Chicago Public Schools

School Pullman School Unit 25041 Building ID 5530

Address 11311 Forrestville Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
10	
12	
14	Abated
15	
16	
17	
18	Abated. Oak Flooring in Room 108
19	Abated. Oak Flooring in Room 108
20	
21	
22	
23	
24	
25	
26	
27	Not Observed 2019. Abated
28	
29	
30	
31	Covered with New Tile
32	Covered with New Tile
33	
34	
35	
36	
37	
37A	
38	
39	

Chicago Public Schools

School Pullman School Unit 25041 Building ID 5530

Address 11311 Forrestville Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
40	
A	
B	
C	
D	
E	
F	
G	
H	Not Observed Since 2016,
NEW	

Table II

Management Planner's Review

Chicago Public Schools

School Pullman School

Unit 25041

Building ID 5530

Address 11311 Forrestville

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	2x4 Acoustical Ceiling Tile	45,500	SF	Hallways, Classrooms & Lunchrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	12x12 Tan w/Brown Speckled Floor Tile ABATED			1st and 2nd Floor Teachers' Lounge	Abated	MISC					
03A	12x12 Off-White w/Green Specks Floor Tile ABATED			Principal's Office- Washroom	Abated	MISC					
03B	12x12 Beige w/White Streaks Floor Tile	2,400	SF	Lunchroom 1 and 2, and Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03C	12x12 Blue Floor Tile	84	SF	3rd Floor Athletic Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03D	12x12 Dark Gray w/White Specks Floor Tile	950	SF	Room 206 & 206 W. Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03E	12x12 Dark Gray Floor Tile	570	SF	Kitchen, Kitchen Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03G	12x12 White w/Orange Specks Floor Tile ABATED			Room 001	Abated	MISC					
04	9x9 Gray w/White Specks Floor Tile ABATED			Room 101	Abated	MISC					
04A	9X9 Tan w/White Streaks Floor Tile ABATED			Room 108	Abated	MISC					
05	12x12 Tan w/Brown Specks Floor Tile Mastic ABATED			2nd Floor Teachers' Lounge, 1st Floor Teachers' Lounge	Abated	MISC					
05A	12x12 Off-White w/Green Floor Tile Mastic ABATED			Principal's Office- Washroom	Abated	MISC					
05B	12x12 Beige w/White Stripes Floor Tile Mastic	2,400	SF	Lunchrooms 1 and 2, and Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05C	12x12 Blue Floor Tile Mastic	84	SF	3rd Floor Athletic Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05D	12x12 Dark Grey w/White Specks Floor Tile Mastic	950	SF	Room 206 & 206 W. Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05E	12x12 Dark Gray Floor Tile Mastic	570	SF	Kitchen, Kitchen Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05G	12x12 White w/Orange Specks Floor Tile Mastic ABATED			Room 001	Abated	MISC					
06	9x9 Gray w/White Specks Floor Tile Mastic ABATED			Room 101	Abated	MISC					
06A	9x9 Tan w/White Streaks Floor Tile Mastic ABATED			Room 108	Abated	MISC					
06H	9x9 Gray w/White Specks Floor Tile Mastic ABATED			Room 101	Abated	MISC					
07	Black Mopboard	90	LF	Lunchrooms 1 and 2	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
07A	Brown Mopboard	124	LF	Ground Floor East Exit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
08	Black Mopboard Mastic	90	LF	Lunchrooms 1 and 2	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
08A	Brown Mopboard Mastic	124	LF	Ground Floor East Exit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
10	Boiler Gaskets	10	LF	Boiler Room	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	Fire Brick	80	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Pullman School
Address 11311 Forrestville

Unit 25041
Chicago, IL, 60628

Building ID 5530
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
14	Blue Carpet Mastic ABATED			Room 102	Abated	MISC					
15	Gray Carpet Mastic	1,600	SF	Athletic Storage Room and Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12x12 Red and White Streaks Floor Tile	1,500	SF	Room 305, 3rd Floor Lounge, and Athletic Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12x12 Red and White Streaks Floor Tile Mastic	1,500	SF	Room 305, 3rd Floor Lounge, and Athletic Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12x12 Orange w/White Streaks Floor Tile ABATED			2nd Floor Lounge, Rooms 101 and 108	Abated	MISC					
19	12x12 Orange w/White Streaks Floor Tile Mastic ABATED			2nd Floor Lounge, Rooms 101 and 108	Abated	MISC					
20	12x12 Blue w/White Streaks Floor Tile	30	SF	Principal's Office Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12x12 Blue w/White Streaks Floor Tile Mastic	30	SF	Principal's Office Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12x12 Light Blue w/Blue Streaks Floor Tile	1,500	SF	Room 001, Room 001 Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12x12 Light Blue w/Blue Streaks Floor Tile Mastic	1,500	SF	Room 001, Room 001 Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12x12 Tan w/Brown Streaks Floor Tile	3,100	SF	Auditorium, Girls' Play Room, Speech Room, NW Corner-Room, and MDF Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12x12 Tan w/Brown Streaks Floor Tile Mastic	3,100	SF	Play Room, Speech Room, NW Corner-Room, and MDF Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	2'x4' Ceiling Tile	15,000	SF	Throughout Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Brown Carpet Adhesive ABATED			Room 102	Abated	MISC					
28	Brown Mosaic Ceramic Tile Grout	1,000	SF	1st, 2nd and 3rd Floor Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Brown Mosaic Ceramic Tile Adhesive	1,000	SF	1st, 2nd and 3rd Floor Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Hardcoat Plaster - Walls and Ceilings	225,000	SF	Throughout School	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x12" Peach Vinyl Floor Tile	500	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12"x12" Peach Vinyl Floor Tile Mastic	500	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12"x12" Cream w/Tan Streaks Floor Tile	250	SF	Custodian's Break Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12"x12" Cream w/Tan Streaks Floor Tile Mastic	250	SF	Custodian's Break Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Red Carpet Mastic	600	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Wood finish Laminate Flooring	250	SF	1st Floor Teachers' Lounge and Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12"x12" Yellow/Cream/Light Grey Mix Floor Tile	1,025	SF	Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37A	12"x12" Yellow/Cream/Light Grey Mix Floor Tile Mastic	1,025	SF	Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Pullman School

Unit 25041

Building ID 5530

Address 11311 Forrestville

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
38	1'x1' Ceiling Tiles	4,000	SF	Rooms 101, 102, 204, 208 & 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12"x12" Light Brown & Red Mix Floor Tile	500	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12"x12" Light Brown & Red Mix Floor Tile Mastic	500	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Air Cell Duct Wrap ABATED			Basement	Abated	TSI					
B	Air Cell Pipe Lagging ABATED			Basement, Boiler Room, Mechanical Room, Room 001, 002, 005, 1st & 2nd Floor Corridors	Abated	TSI					
C	Cardboard Pipe Insulation ABATED			Basement, Boiler Room	Abated	TSI					
D	MAG Block Pipe Insulation	15	LF	Basement	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
E	Aircell Hard Joints ABATED			Basement, 1st and 2nd Floor	Abated	TSI					
F	Fiber Glass Hard Joints ABATED			Basement Fan Room, Corridors on 1st, 2nd and 3rd Floors, 1st Floor Bathrooms	Abated	TSI					
G	Cardboard Hard Fittings ABATED			Basement, Fan Room, Boiler Room	Abated	TSI					
H	Boiler Blanket Insulation - Not Observed			Boiler Room	Abated	TSI					
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Pullman School
Address 11311 Forrestville

Unit 25041
 Chicago, IL, 60628

Building ID 5530
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	9/5/2022
Manager Planner Name	Todd Huffer
100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	Ceiling Tiles replaced in Rooms 101, 102, 204, 208 & 209
03	
03A	
03B	
03C	
03D	
03E	
03G	
04	
04A	
05	
05A	
05B	
05C	
05D	
05E	
05G	
06	
06A	
06H	

Chicago Public Schools

School Pullman School
Address 11311 Forrestville

Unit 25041
Chicago, IL, 60628

Building ID 5530
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
07	
07A	
08	
08A	
10	
12	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	Covered with New Tile
32	Covered with New Tile
33	
34	

Chicago Public Schools

School Pullman School
Address 11311 Forrestville

Unit 25041
Chicago, IL, 60628

Building ID 5530
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
35	
36	
37	
37A	
38	
39	
40	
A	
B	
C	
D	
E	
F	
G	
H	
NEW	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **2x4 Acoustical Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hallways, Classrooms & Lunchrooms**
MATERIAL QUANTITY: **45500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Ceiling Tiles replaced in Rooms 101, 102, 204, 208 & 209**

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **2x4 Acoustical Ceiling Tile**
MATERIAL LOCATION: **Hallways, Classrooms & Lunchrooms**
MATERIAL QUANTITY: **45500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Ceiling Tiles replaced in Rooms 101, 102, 204, 208 & 209

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 03
MATERIAL DESCRIPTION: 12x12 Tan w/Brown Speckled Floor Tile ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st and 2nd Floor Teachers' Lounge

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **12x12 Tan w/Brown Speckled Floor Tile ABATED**

MATERIAL LOCATION: **1st and 2nd Floor Teachers' Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022** _____

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **12x12 Off-White w/Green Specks Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Principal's Office- Washroom**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **12x12 Off-White w/Green Specks Floor Tile ABATED**
MATERIAL LOCATION: **Principal's Office- Washroom**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022** _____

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 03B
MATERIAL DESCRIPTION: 12x12 Beige w/White Streaks Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Lunchroom 1 and 2, and Teachers' Lounge
MATERIAL QUANTITY: 2400 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **03B**
MATERIAL DESCRIPTION: **12x12 Beige w/White Streaks Floor Tile**
MATERIAL LOCATION: **Lunchroom 1 and 2, and Teachers' Lounge**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 03C
MATERIAL DESCRIPTION: 12x12 Blue Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 3rd Floor Athletic Storage
MATERIAL QUANTITY: 84 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **03C**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**
MATERIAL LOCATION: **3rd Floor Athletic Storage**
MATERIAL QUANTITY: **84** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 03D
MATERIAL DESCRIPTION: 12x12 Dark Gray w/White Specks Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Room 206 & 206 W. Room
MATERIAL QUANTITY: 950 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **03D**
MATERIAL DESCRIPTION: **12x12 Dark Gray w/White Specks Floor Tile**
MATERIAL LOCATION: **Room 206 & 206 W. Room**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 03E
MATERIAL DESCRIPTION: 12x12 Dark Gray Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Kitchen, Kitchen Storage Room
MATERIAL QUANTITY: 570 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **03E**
MATERIAL DESCRIPTION: **12x12 Dark Gray Floor Tile**
MATERIAL LOCATION: **Kitchen, Kitchen Storage Room**
MATERIAL QUANTITY: **570** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03G**
MATERIAL DESCRIPTION: **12x12 White w/Orange Specks Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 001**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Hardwood Floor**

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **03G**

MATERIAL DESCRIPTION: **12x12 White w/Orange Specks Floor Tile ABATED**

MATERIAL LOCATION: **Room 001**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022** _____

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04
MATERIAL DESCRIPTION: 9x9 Gray w/White Specks Floor Tile ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 101

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **9x9 Gray w/White Specks Floor Tile ABATED**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022** _____

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04A
MATERIAL DESCRIPTION: 9X9 Tan w/White Streaks Floor Tile ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 108

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **9X9 Tan w/White Streaks Floor Tile ABATED**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05
MATERIAL DESCRIPTION: 12x12 Tan w/Brown Specks Floor Tile Mastic ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd Floor Teachers' Lounge, 1st Floor Teachers' Lounge

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Specks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **2nd Floor Teachers' Lounge, 1st Floor Teachers' Lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05A
MATERIAL DESCRIPTION: 12x12 Off-White w/Green Floor Tile Mastic ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Principal's Office- Washroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **12x12 Off-White w/Green Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Principal's Office- Washroom**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05B
MATERIAL DESCRIPTION: 12x12 Beige w/White Stripes Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Lunchrooms 1 and 2, and Teachers' Lounge
MATERIAL QUANTITY: 2400 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **12x12 Beige w/White Stripes Floor Tile Mastic**
MATERIAL LOCATION: **Lunchrooms 1 and 2, and Teachers' Lounge**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05C
MATERIAL DESCRIPTION: 12x12 Blue Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 3rd Floor Athletic Storage
MATERIAL QUANTITY: 84 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05C**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile Mastic**
MATERIAL LOCATION: **3rd Floor Athletic Storage**
MATERIAL QUANTITY: **84** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05D
MATERIAL DESCRIPTION: 12x12 Dark Grey w/White Specks Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Room 206 & 206 W. Room
MATERIAL QUANTITY: 950 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05D**
MATERIAL DESCRIPTION: **12x12 Dark Grey w/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Room 206 & 206 W. Room**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05E
MATERIAL DESCRIPTION: 12x12 Dark Gray Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Kitchen, Kitchen Storage Room
MATERIAL QUANTITY: 570 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05E**
MATERIAL DESCRIPTION: **12x12 Dark Gray Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen, Kitchen Storage Room**
MATERIAL QUANTITY: **570** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05G
MATERIAL DESCRIPTION: 12x12 White w/Orange Specks Floor Tile Mastic ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 001

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05G**
MATERIAL DESCRIPTION: **12x12 White w/Orange Specks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Room 001**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 06
MATERIAL DESCRIPTION: 9x9 Gray w/White Specks Floor Tile Mastic ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 101

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **9x9 Gray w/White Specks Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **9x9 Tan w/White Streaks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **9x9 Tan w/White Streaks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06H**
MATERIAL DESCRIPTION: **9x9 Gray w/White Specks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **06H**
MATERIAL DESCRIPTION: **9x9 Gray w/White Specks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Room 101**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07
MATERIAL DESCRIPTION: Black Mopboard
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Lunchrooms 1 and 2
MATERIAL QUANTITY: 90 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Black Mopboard**
MATERIAL LOCATION: **Lunchrooms 1 and 2**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **Brown Mopboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Ground Floor East Exit**
MATERIAL QUANTITY: **124** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **Brown Mopboard**
MATERIAL LOCATION: **Ground Floor East Exit**
MATERIAL QUANTITY: **124** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Black Mopboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchrooms 1 and 2**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Black Mopboard Mastic**
MATERIAL LOCATION: **Lunchrooms 1 and 2**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **Brown Mopboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Ground Floor East Exit**
MATERIAL QUANTITY: **124** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **Brown Mopboard Mastic**
MATERIAL LOCATION: **Ground Floor East Exit**
MATERIAL QUANTITY: **124** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Boiler Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12
MATERIAL DESCRIPTION: Fire Brick
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Boiler Room
MATERIAL QUANTITY: 80 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Fire Brick**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Blue Carpet Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated**

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Blue Carpet Mastic ABATED**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Athletic Storage Room and Principal's Office**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
MATERIAL LOCATION: **Athletic Storage Room and Principal's Office**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 16
MATERIAL DESCRIPTION: 12x12 Red and White Streaks Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Room 305, 3rd Floor Lounge, and Athletic Storage
MATERIAL QUANTITY: 1500 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Red and White Streaks Floor Tile**
MATERIAL LOCATION: **Room 305, 3rd Floor Lounge, and Athletic Storage**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12x12 Red and White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 305, 3rd Floor Lounge, and Athletic Storage**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12x12 Red and White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 305, 3rd Floor Lounge, and Athletic Storage**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12x12 Orange w/White Streaks Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Lounge, Rooms 101 and 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated. Oak Flooring in Room 108**

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12x12 Orange w/White Streaks Floor Tile ABATED**

MATERIAL LOCATION: **2nd Floor Lounge, Rooms 101 and 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12x12 Orange w/White Streaks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Lounge, Rooms 101 and 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated. Oak Flooring in Room 108**

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12x12 Orange w/White Streaks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **2nd Floor Lounge, Rooms 101 and 108**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12x12 Blue w/White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Principal's Office Washroom**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12x12 Blue w/White Streaks Floor Tile**
MATERIAL LOCATION: **Principal's Office Washroom**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21
MATERIAL DESCRIPTION: 12x12 Blue w/White Streaks Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Principal's Office Washroom
MATERIAL QUANTITY: 30 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12x12 Blue w/White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Principal's Office Washroom**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22
MATERIAL DESCRIPTION: 12x12 Light Blue w/Blue Streaks Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE
MATERIAL LOCATION: Room 001, Room 001 Storage
MATERIAL QUANTITY: 1500 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12x12 Light Blue w/Blue Streaks Floor Tile**
MATERIAL LOCATION: **Room 001, Room 001 Storage**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 Light Blue w/Blue Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 001, Room 001 Storage**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 Light Blue w/Blue Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 001, Room 001 Storage**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24
MATERIAL DESCRIPTION: 12x12 Tan w/Brown Streaks Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Auditorium, Girls' Play Room, Speech Room, NW Corner-Room, and MDF Room
MATERIAL QUANTITY: 3100 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Streaks Floor Tile**
MATERIAL LOCATION: **Auditorium, Girls' Play Room, Speech Room, NW Corner-Room, and MDF Room**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Play Room, Speech Room, NW Corner-Room, and MDF Room**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Play Room, Speech Room, NW Corner-Room, and MDF Room**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 26
MATERIAL DESCRIPTION: 2'x4' Ceiling Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Throughout Building
MATERIAL QUANTITY: 15000 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27
MATERIAL DESCRIPTION: Brown Carpet Adhesive ABATED
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 102

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2019. Abated

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Brown Carpet Adhesive ABATED**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28
MATERIAL DESCRIPTION: Brown Mosaic Ceramic Tile Grout
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 1st, 2nd and 3rd Floor Girls' Washrooms
MATERIAL QUANTITY: 1000 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Girls' Washrooms**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Girls' Washrooms**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Girls' Washrooms**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30
MATERIAL DESCRIPTION: Hardcoat Plaster - Walls and Ceilings
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Throughout School
MATERIAL QUANTITY: 225000 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Hardcoat Plaster - Walls and Ceilings**
MATERIAL LOCATION: **Throughout School**
MATERIAL QUANTITY: **225000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x12" Peach Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Covered with New Tile**

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x12" Peach Vinyl Floor Tile**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Covered with New Tile

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12"x12" Peach Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Covered with New Tile**

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12"x12" Peach Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Covered with New Tile

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33
MATERIAL DESCRIPTION: 12"x12" Cream w/Tan Streaks Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE
MATERIAL LOCATION: Custodian's Break Room
MATERIAL QUANTITY: 250 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Streaks Floor Tile**
MATERIAL LOCATION: **Custodian's Break Room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34
MATERIAL DESCRIPTION: 12"x12" Cream w/Tan Streaks Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Custodian's Break Room
MATERIAL QUANTITY: 250 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Custodian's Break Room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35
MATERIAL DESCRIPTION: Red Carpet Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Library
MATERIAL QUANTITY: 600 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Red Carpet Mastic**
MATERIAL LOCATION: **Library**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUILDING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 36
MATERIAL DESCRIPTION: Wood finish Laminate Flooring
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 1st Floor Teachers' Lounge and Toilet
MATERIAL QUANTITY: 250 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Wood finish Laminate Flooring**
MATERIAL LOCATION: **1st Floor Teachers' Lounge and Toilet**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Air Cell Duct Wrap ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Air Cell Duct Wrap ABATED**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Air Cell Pipe Lagging ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement, Boiler Room, Mechanical Room, Room 001, 002, 005, 1st & 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Air Cell Pipe Lagging ABATED**
MATERIAL LOCATION: **Basement, Boiler Room, Mechanical Room, Room 001, 002, 005, 1st & 2nd Floor Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement, Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation ABATED**

MATERIAL LOCATION: **Basement, Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022** _____

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **MAG Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **MAG Block Pipe Insulation**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Hard Joints ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Basement, 1st and 2nd Floor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Aircell Hard Joints ABATED**

MATERIAL LOCATION: **Basement, 1st and 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: F
MATERIAL DESCRIPTION: Fiber Glass Hard Joints ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement Fan Room, Corridors on 1st, 2nd and 3rd Floors, 1st Floor Bathrooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Fiber Glass Hard Joints ABATED**
MATERIAL LOCATION: **Basement Fan Room, Corridors on 1st, 2nd and 3rd Floors, 1st Floor Bathrooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022** _____

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Cardboard Hard Fittings ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement, Fan Room, Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Cardboard Hard Fittings ABATED**
MATERIAL LOCATION: **Basement, Fan Room, Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022** _____

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25041 BUIDLING ID: 5530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Pullman School INSPECTION DATE: 8/9/2022
ADDRESS: 11311 Forrestville IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: H
MATERIAL DESCRIPTION: Boiler Blanket Insulation - Not Observed
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Since 2016,

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUIDLING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Blanket Insulation - Not Observed**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022** _____

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12"x12" Yellow/Cream/Light Grey Mix Floor Tile**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **1025** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**


HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12"x12" Yellow/Cream/Light Grey Mix Floor Tile**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **1025** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/05/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **37A**
MATERIAL DESCRIPTION: **12"x12" Yellow/Cream/Light Grey Mix Floor Tile Mastic**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **1025** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **37A**

MATERIAL DESCRIPTION: **12"x12" Yellow/Cream/Light Grey Mix Floor Tile Mastic**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: **1025** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/05/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"x12" Light Brown & Red Mix Floor Tile**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/09/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12"x12" Light Brown & Red Mix Floor Tile**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/05/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tiles**
MATERIAL LOCATION: **Rooms 101, 102, 204, 208 & 209**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tiles**
MATERIAL LOCATION: **Rooms 101, 102, 204, 208 & 209**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/05/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Pullman School** INSPECTION DATE: **8/9/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12"x12" Light Brown & Red Mix Floor Tile Mastic**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/09/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25041** BUILDING ID: **5530**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Pullman School** REVIEW DATE: **9/5/2022**
ADDRESS: **11311 Forrestville** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12"x12" Light Brown & Red Mix Floor Tile Mastic**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/05/2022

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER ANTONOPOULOS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 06/01/2021 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II; Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

06/01/2021

Course Dates:

06/01/2022

Expires:

2106BIR11

Certificate Number:

A handwritten signature in black ink, appearing to read "N. Penneff".

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER J. ANTONOPOULOS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 06/03/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

06/03/2022

Course Dates:

06/03/2023

Expires:

2206BIR01

Certificate Number:




37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in black ink, appearing to read "N. Peneff", is written over a light gray rectangular background.

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081


FORM # A-010B

 **ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 18281	2/10/2022	05/15/2023

CHRISTOPHER J ANTONOPO
1736 W 102nd ST
CHICAGO, IL 60643

Environmental Health



ENDORSEMENT	TC EXPIRES
INSPECTOR	6/1/2022

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

TODD T HUFFER
315 HATLEN COURT
MT. PROSPECT, IL 60056

2/18/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
			INSPECTOR	11/1/2022
ID NUMBER	ISSUED	EXPIRES	MANAGEMENT PLANNER	11/19/2022
100 - 09870	2/18/2022	05/15/2023	PROJECT MANAGER	10/20/2022
TODD T HUFFER			AIR SAMPLING PROFESSIONAL	
315 HATLEN COURT			Alteration of this license shall result in legal action	
MT. PROSPECT, IL 60056			This license issued under authority of the State of Illinois	
Environmental Health			Department of Public Health	
			This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265


Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed