

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2417
SCHOOL NAME: Ray School
ADDRESS OF SCHOOL: 5631 S. Kimbark
CITY: Chicago, IL, 60637

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/16/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 11/4/2022 ENROLLMENT 503
IDPH INSPECTOR LICENSE NUMBER: 100-05020
IDPH LICENSED INSPECTOR NAME (Please Print): Devon Jackson
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

11/17/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Ray School

5631 S. Kimbark
Chicago, IL, 60637

Unit: 25071
Building ID: 5560

IDPH ID Number: 14-016-2990-2417

REPORT DATE:

Thursday, November 17, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 17, 2022

RE: Ray School, Unit 25071
5631 S. Kimbark
Chicago, IL, 60637

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Ray School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Ray School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Ray School Unit: 25071 Region: 04
Address: 5631 S. Kimbark Chicago, IL, 60637
IDPH ID: 14-016-2990-2417 Building ID: 5560
Contact: Mayo, Tom Phone: 7737102359

2. Description of Facility

Original Construction: 1893 Additional Construction: 1915,1996
Total Square Footage: 84500 No of Floors: 4
Current Occupancy: 503

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Devon Jackson


Inspector IDPH license # 100-05020
Reinspection Date: 11/4/2022

Signature: 
Date: 11/4/2022

6. Management Planner

Management Planner Name: Evan Christian


Management Planner IDPH license # 100-19466

Signature: 
Date: 11/17/2022

7. Review Date: 11/17/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 11/17/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Ray School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5560:

02E	12" x 12" Orange Floor Tile
11D	12" x 12" Beige streaked Floor Tile Mastic
11E	12" x 12" Orange Floor Tile Mastic
32	Tongue and groove wooden floor
33	12" x 12" Light Brown w/ White Specks Floor Tile
34	12" x 12" Light Brown w/ White Specks Floor Tile Mastic
35	12" x 12" White w/ Light Green/ gray Specks Floor Tile
36	12" x 12" White w/ Light Green/ gray Specks Floor Tile Mastic

E	Cardboard pipe covering
F	Cardboard pipe fittings
S	Cementious pipe fittings
T	Pipe insulation
W	Pipe insulation

B. The following new homogenous areas have been identified for Building 5560:

- 32 Tongue and groove wooden floor
- 33 12" x 12" Light Brown w/ White Specks Floor Tile
- 34 12" x 12" Light Brown w/ White Specks Floor Tile
Mastic
- 35 12" x 12" White w/ Light Green/ gray Specks Floor
Tile
- 36 12" x 12" White w/ Light Green/ gray Specks Floor
Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	Hard plaster
02A	12" x 12" Beige w/tan Streaks Floor Tile
02B	12" x 12" black Floor Tile
02C	12" x 12" White Floor Tile
02D	12" x 12" Beige streaked Floor Tile
02E	12" x 12" Orange Floor Tile
10	Wallboard
11B	12" x 12" black Floor Tile Mastic
16	Brown vinyl baseboard
17	Brown vinyl baseboard Mastic
18	Drywall compound
19A	12" x 12" Green Floor Tile
19B	12" x 12" Green Floor Tile Mastic
21	Ceiling plaster
22	12" x 12" Light Blue Vinyl Floor Tile
23	12" x 12" Light Blue Vinyl Floor Tile Mastic
24	12" x 12" Dark Blue Vinyl Floor Tile
25	12" x 12" Dark Blue Vinyl Floor Tile Mastic
26	Lab table tops
27	12" x 12" Light Green Vinyl Floor Tile
28	12" x 12" Light Green Vinyl Floor Tile Mastic
29	12" x 12" Dark Green Vinyl Floor Tile
30	12" x 12" Dark Green Vinyl Floor Tile Mastic
32	Tongue and groove wooden floor
33	12" x 12" Light Brown w/ White Specks Floor Tile
34	12" x 12" Light Brown w/ White Specks Floor Tile Mastic
35	12" x 12" White w/ Light Green/ gray Specks Floor Tile
36	12" x 12" White w/ Light Green/ gray Specks Floor Tile Mastic
S	Cementitious pipe fittings
T	Pipe insulation
V	Cementitious pipe fittings
W	Pipe insulation
X	Material behind metal ceiling and walls

The following areas were deemed to be inaccessible:

11A	12" x 12" Beige w/tan Streaks Floor Tile Mastic
-----	---

11B	12" x 12" black Floor Tile Mastic
11E	12" x 12" Orange Floor Tile Mastic
11F	12" x 12" tan Floor Tile Mastic
17	Brown vinyl baseboard Mastic
18	Drywall compound
19B	12" x 12" Green Floor Tile Mastic
23	12" x 12" Light Blue Vinyl Floor Tile Mastic
25	12" x 12" Dark Blue Vinyl Floor Tile Mastic
28	12" x 12" Light Green Vinyl Floor Tile Mastic
30	12" x 12" Dark Green Vinyl Floor Tile Mastic
E	Cardboard pipe covering
F	Cardboard pipe fittings
H	Aircell pipe joints
K	Water meter packing
S	Cementious pipe fittings
T	Pipe insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Devon Jackson, IDPH License # 100-05020. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Ray School Building 5560 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Hard plaster	40,000	SF	Throughout 1893 Construction	ASSUMED	SURFACE	N	LOC	2	SF	No	ACBM with the potential for damage	3	LOW
02A	12" x 12" Beige w/tan Streaks Floor Tile	1,550	SF	basement art room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
02B	12" x 12" black Floor Tile	300	SF	room 306	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
02C	12" x 12" White Floor Tile	300	SF	room 306	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
02D	12" x 12" Beige streaked Floor Tile	430	SF	1st, 2nd, 3rd floor corridors (patches), 310 (patches)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
02E	12" x 12" Orange Floor Tile	75	SF	1st floor corridor - outside boys toilet, as patches in room 313, 311, 310, 303, 211	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
02F	12" x 12" tan Floor Tile	4,770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, eng office 211	CHR	MISC	N	LOC	10	SF	No	ACBM with the potential for damage	3	LOW
03A	9" x 9" black Floor Tile			main office - principal's office, bathroom, vault	CHR	MISC								
03B	9" x 9" White Floor Tile			main office - principal's office, bathroom & vault	CHR	MISC								
03C	9" x 9" Green Floor Tile			Engineer's Bathroom	CHR	MISC								
05	Linoleum			basement ladie's room	NO_ACBM	MISC								
08	12" x 12" Floor Tile- ABATED			1955 building (demolished)	ABATED	MISC								
09	9" x 9" Floor Tile- ABATED			1955 building (demolished)	ABATED	MISC								
10	Wallboard	450	SF	basement art room, fire pump room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
11A	12" x 12" Beige w/tan Streaks Floor Tile Mastic	1,550	SF	basement - art room	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
11B	12" x 12" black Floor Tile Mastic	1,000	SF	room 306	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
11C	12" x 12" White Floor Tile Mastic			room 306	NO_ACBM	MISC								
11D	12" x 12" Beige streaked Floor Tile Mastic	150	SF	1st, 2nd, 3rd floor corridors (patches), 310 (patches)	CHR	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
11E	12" x 12" Orange Floor Tile Mastic	75	SF	1st floor corridor - outside boys toilet, Room 313, 311, 310 (patches), 303	CHR	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
11F	12" x 12" tan Floor Tile Mastic	4,770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, engineer'sn office, 211	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
12A	9" x 9" black Floor Tile Mastic (Abated)			main office - principal's office, washroom, vault	ABATED	MISC								
12B	9" x 9" White Floor Tile Mastic (Abated)			main office - principal's office, bathroom & vault	ABATED	MISC								
12C	9" x 9" Green Floor Tile Mastic			engineer's toilet	ABATED	MISC								
13	Linoleum mastic			basement ladie's room	NO_ACBM	MISC								
14	12" x 12" Floor Tile Mastic- ABATED			1955 building- (building demolished)	ABATED	MISC								
15	9" x 9" Floor Tile Mastic- ABATED			1955 building- (building demolished)	ABATED	MISC								
16	Brown vinyl baseboard	200	LF	basement art room	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
17	Brown vinyl baseboard Mastic	200	LF	basement art room	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
18	Drywall compound	200	SF	basement art room	ASSUMED	SURFACE	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
19A	12" x 12" Green Floor Tile	800	SF	Staff lounge - kitchen	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
19B	12" x 12" Green Floor Tile Mastic	800	SF	Staff lounge - kitchen	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
20	Hard plaster			Auditorium	NO_ACBM	SURFACE								
21	Ceiling plaster	10,160	SF	Throughout basement and classrooms	ASSUMED	MISC	N	DIST	40	SF	No	ACBM with the potential for damage	3	LOW
22	12" x 12" Light Blue Vinyl Floor Tile	6,700	SF	Basement Storage, Boys Bathroom, Lunchroom, Corridor, Girls Playroom, Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				material abated and boiler removed in 1994										
E	Cardboard pipe covering	40	SF	attic - tank	CHR	TSI	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Cardboard pipe fittings	3	LF	attic - tank	CHR	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Aircell pipe insulation			original (1893) building air chamber	ABATED	TSI								
H	Aircell pipe joints	6	FITTING	basement teachers lounge	CHR	TSI	Y	NONE	0	FITTING	No	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
I	Preform pipe covering- ABATED			1893 building	ABATED	MISC								
K	Water meter packing	5	FITTING	basement fire pump room, Basement Teacher's Lounge	AMO	TSI	Y	NONE	0	FITTING	No	Any remaining friable ACBM or friable suspect ACBM		LOW
O	Cardboard pipe covering- ABATED			1955 addition- (building demolished)	ABATED	MISC								
P	Cardboard pipe joint- ABATED			1955 addition- (building demolished)	ABATED	MISC								
Q	Aircell pipe insulation- ABATED			1955 building addition- (building demolished)	ABATED	MISC								
R	Aircell pipe joints- ABATED			1955 addition- (building demolished)	ABATED	MISC								
S	Cementitious pipe fittings	10	LF	Girls and Boys bathrooms - pipe chases	ASSUMED	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
T	Pipe insulation	30	LF	Girls and Boys bathrooms - pipe chases	ASSUMED	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
U	Incinerator brick			boiler room	NO ACBM	TSI								
V	Cementitious pipe fittings			Engineer's Storage and Fire Pump Room	ASSUMED	TSI								
W	Pipe insulation	100	LF	Engineer's Storage and Fire Pump Room	ASSUMED	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE

Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 11/4/2022
Inspector Name Devon Jackson
100-05020 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	Damage in 1st floor teacher's storage room
02A	
02B	
02C	
02D	
02E	
02F	Damage in Room 311
03A	Not observed 2022
03B	Not observed 2022
03C	Not Observed 2022
05	
08	
09	
10	
11A	
11B	
11C	
11D	
11E	
11F	
12A	
12B	
12C	
13	

Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
14	
15	
16	
17	
18	
19A	
19B	
20	
21	Ceiling damage in Room 307, 305, 214
22	
23	
24	
25	
26	
27	Damage in 1st floor corridor
28	
29	
30	
32	
33	Damage in Room 311
34	
35	Damage in 1st floor teacher's storage room
36	Damage in 1st floor teacher's storage room
A	
E	
F	
G	
H	
I	

Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
K	
O	
P	
Q	
R	
S	
T	
U	
V	Not Observed 2022
W	
X	Not Observed 2022

Table II

Management Planner's Review

Chicago Public Schools

School Ray School
Address 5631 S. Kimbark

Unit 25071
Chicago, IL, 60637

Building ID 5560
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Hard plaster	40,000	SF	Throughout 1893 Construction	Assumed	SURFACE	No	2	SF	6 ACBM with the potential for damage	Repair
02A	12" x 12" Beige w/tan Streaks Floor Tile	1,550	SF	basement art room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02B	12" x 12" black Floor Tile	300	SF	room 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02C	12" x 12" White Floor Tile	300	SF	room 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02D	12" x 12" Beige streaked Floor Tile	430	SF	1st, 2nd, 3rd floor corridors (patches), 310 (patches)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02E	12" x 12" Orange Floor Tile	75	SF	1st floor corridor - outside boys toilet, as patches in room 313, 311, 310, 303, 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02F	12" x 12" tan Floor Tile	4,770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, eng office 211	Chrysotile	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
03A	9" x 9" black Floor Tile			main office - principal's office, bathroom, vault	Chrysotile	MISC					Follow O&M Plan
03B	9" x 9" White Floor Tile			main office - principal's office, bathroom & vault	Chrysotile	MISC					Follow O&M Plan
03C	9" x 9" Green Floor Tile			Engineer's Bathroom	Chrysotile	MISC					Follow O&M Plan
05	Linoleum			basement ladie's room	No ACBM	MISC					
08	12" x 12" Floor Tile- ABATED			1955 building (demolished)	Abated	MISC					
09	9" x 9" Floor Tile- ABATED			1955 building (demolished)	Abated	MISC					
10	Wallboard	450	SF	basement art room, fire pump room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	12" x 12" Beige w/tan Streaks Floor Tile Mastic	1,550	SF	basement - art room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11B	12" x 12" black Floor Tile Mastic	1,000	SF	room 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11C	12" x 12" White Floor Tile Mastic			room 306	No ACBM	MISC					
11D	12" x 12" Beige streaked Floor Tile Mastic	150	SF	1st, 2nd, 3rd floor corridors (patches), 310 (patches)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11E	12" x 12" Orange Floor Tile Mastic	75	SF	1st floor corridor - outside boys toilet, Room 313, 311, 310 (patches), 303	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11F	12" x 12" tan Floor Tile Mastic	4,770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102,105,107, engineer'sn office, 211	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12A	9" x 9" black Floor Tile Mastic (Abated)			main office - principal's office, washroom, vault	Abated	MISC					
12B	9" x 9" White Floor Tile Mastic (Abated)			main office - principal's office, bathroom & vault	Abated	MISC					
12C	9" x 9" Green Floor Tile Mastic			engineer's toilet	Abated	MISC					

Chicago Public Schools

School Ray School
Address 5631 S. Kimbark

Unit 25071
Chicago, IL, 60637

Building ID 5560
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
13	Linoleum mastic			basement ladie's room	No ACBM	MISC					
14	12" x 12" Floor Tile Mastic- ABATED			1955 building- (building demolished)	Abated	MISC					
15	9" x 9" Floor Tile Mastic- ABATED			1955 building- (building demolished)	Abated	MISC					
16	Brown vinyl baseboard	200	LF	basement art room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
17	Brown vinyl baseboard Mastic	200	LF	basement art room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
18	Drywall compound	200	SF	basement art room	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19A	12" x 12" Green Floor Tile	800	SF	Staff lounge - kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19B	12" x 12" Green Floor Tile Mastic	800	SF	Staff lounge - kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Hard plaster			Auditorium	No ACBM	SURFACE					
21	Ceiling plaster	10,160	SF	Throughout basement and classrooms	Assumed	MISC	No	40	SF	6 ACBM with the potential for damage	Remove
22	12" x 12" Light Blue Vinyl Floor Tile	6,700	SF	Basement Storage, Boys Bathroom, Lunchroom, Corridor, Girls Playroom, Room 312,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12" x 12" Light Blue Vinyl Floor Tile Mastic	6,700	SF	Basement Storage, Boys Bathroom, Lunchroom, Corridor, Girls Playroom, Room 312,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12" x 12" Dark Blue Vinyl Floor Tile	2,400	SF	Basement, 1st, 2nd, 3rd Floor Corridors, Adjust. Office,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12" x 12" Dark Blue Vinyl Floor Tile Mastic	2,400	SF	Basement, 1st, 2nd, 3rd Floor Corridors, Adjust. Office,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Lab table tops	432	SF	Room 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12" x 12" Light Green Vinyl Floor Tile	3,200	SF	1st Floor Corridor, Storage Room, Principles Office.	Assumed	MISC	No	2	SF	6 ACBM with the potential for damage	Repair
28	12" x 12" Light Green Vinyl Floor Tile Mastic	3,200	SF	1st Floor Corridor, Storage Room, Principles Office.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12" x 12" Dark Green Vinyl Floor Tile	3,200	SF	1st Floor Corridor and Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12" x 12" Dark Green Vinyl Floor Tile Mastic	3,200	SF	1st Floor Corridor and Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Tongue and groove wooden floor	600	SF	Rooms 315, 314, 309, 307, 304, 302, 301, 215, 214, 213, 212, 210, 209, 207, 204, 202, 201, 104, gym track, gym, 106, 112, 113, 114, 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" x 12" Light Brown w/ White Specks Floor Tile	20	SF	Patches in Room 308, 305	Assumed	MISC	No	4	SF	6 ACBM with the potential for damage	Repair
34	12" x 12" Light Brown w/ White Specks Floor Tile Mastic	20	SF	Patches in Room 308, 305	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12" x 12" White w/ Light Green/ gray Specks Floor Tile	3,500	SF	1st FI Corridor, main Office, 1st floor teacher's storage	Assumed	MISC	No	4	SF	6 ACBM with the potential for damage	Repair

Chicago Public Schools

School Ray School
Address 5631 S. Kimbark

Unit 25071
Chicago, IL, 60637

Building ID 5560
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
36	12" x 12" White w/ Light Green/ gray Specks Floor Tile Mastic	3,500	SF	1st Fl Corridor, main Office, 1st floor teacher's storage	Assumed	MISC	No	4	SF	6 ACBM with the potential for damage	Repair
A	Mag block boiler insulation- ABATED			boiler room- material abated and boiler removed in 1994	Abated	MISC					
E	Cardboard pipe covering	40	SF	attic - tank	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Cardboard pipe fittings	3	LF	attic - tank	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Aircell pipe insulation			original (1893) building air chamber	Abated	TSI					
H	Aircell pipe joints	6	FITTING	basement teachers lounge	Chrysotile	TSI	Yes	0	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
I	Preform pipe covering- ABATED			1893 building	Abated	MISC					
K	Water meter packing	5	FITTING	basement fire pump room, Basement Teacher's Lounge	Amosite	TSI	Yes	0	FITTING	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
O	Cardboard pipe covering- ABATED			1955 addition- (building demolished)	Abated	MISC					
P	Cardboard pipe joint- ABATED			1955 addition- (building demolished)	Abated	MISC					
Q	Aircell pipe insulation- ABATED			1955 building addition- (building demolished)	Abated	MISC					
R	Aircell pipe joints- ABATED			1955 addition- (building demolished)	Abated	MISC					
S	Cementitious pipe fittings	10	LF	Girls and Boys bathrooms - pipe chases	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
T	Pipe insulation	30	LF	Girls and Boys bathrooms - pipe chases	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
U	Incinerator brick			boiler room	No ACBM	TSI					
V	Cementitious pipe fittings			Engineer's Storage and Fire Pump Room	Assumed	TSI					Follow O&M Plan
W	Pipe insulation	100	LF	Engineer's Storage and Fire Pump Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
X	Material behind metal ceiling and walls			Auditorium Fan Room	Assumed	SURFACE					Follow O&M Plan

Chicago Public Schools

School Ray School
Address 5631 S. Kimbark

Unit 25071
 Chicago, IL, 60637

Building ID 5560
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	11/17/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02A	
02B	
02C	
02D	
02E	
02F	
03A	
03B	
03C	
05	

Chicago Public Schools

School Ray School
Address 5631 S. Kimbark

Unit 25071
 Chicago, IL, 60637

Building ID 5560
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
08	
09	
10	
11A	
11B	
11C	
11D	
11E	
11F	
12A	
12B	
12C	
13	
14	
15	
16	
17	
18	
19A	
19B	
20	
21	Sample to Determine ACM Content
22	
23	
24	
25	
26	

Chicago Public Schools

School Ray School
Address 5631 S. Kimbark

Unit 25071
 Chicago, IL, 60637

Building ID 5560
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
27	
28	
29	
30	
32	
33	
34	
35	
36	
A	
E	
F	
G	
H	
I	
K	
O	
P	
Q	
R	
S	
T	
U	
V	
W	
X	Sample to determine ACM content

Chicago Public Schools

School Ray School
Address 5631 S. Kimbark

Unit 25071
Chicago, IL, 60637

Building ID 5560
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Hard plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1893 Construction**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in 1st floor teacher's storage room**

Inspector's Signature: _____



Date: 11/04/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Hard plaster**
MATERIAL LOCATION: **Throughout 1893 Construction**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02A**
MATERIAL DESCRIPTION: **12" x 12" Beige w/tan Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **basement art room**
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **02A**
MATERIAL DESCRIPTION: **12" x 12" Beige w/tan Streaks Floor Tile**
MATERIAL LOCATION: **basement art room**
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02B**
MATERIAL DESCRIPTION: **12" x 12" black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **room 306**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **02B**
MATERIAL DESCRIPTION: **12" x 12" black Floor Tile**
MATERIAL LOCATION: **room 306**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02C**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **room 306**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **02C**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **room 306**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02D**
MATERIAL DESCRIPTION: **12" x 12" Beige streaked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors (patches), 310 (patches)**
MATERIAL QUANTITY: **430** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **02D**
MATERIAL DESCRIPTION: **12" x 12" Beige streaked Floor Tile**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors (patches), 310 (patches)**
MATERIAL QUANTITY: **430** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25071 BUIDLING ID: 5560
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Devon Jackson
SCHOOL NAME: Ray School INSPECTION DATE: 11/4/2022
ADDRESS: 5631 S. Kimbark IDPH LICENSE NO: 100-05020

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 02E
MATERIAL DESCRIPTION: 12" x 12" Orange Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st floor corridor - outside boys toilet, as patches in room 313, 311, 310, 303, 211**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **02E**
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile**
MATERIAL LOCATION: **1st floor corridor - outside boys toilet, as patches in room 313, 311, 310, 303, 211**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02F**
MATERIAL DESCRIPTION: **12" x 12" tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, eng office 211**
MATERIAL QUANTITY: **4770** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 311**

Inspector's Signature: _____



Date: 11/04/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **02F**
MATERIAL DESCRIPTION: **12" x 12" tan Floor Tile**
MATERIAL LOCATION: **Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, eng office 211**
MATERIAL QUANTITY: **4770** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **9" x 9" black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **main office - principal's office, bathroom, vault**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **03A**

MATERIAL DESCRIPTION: **9" x 9" black Floor Tile**

MATERIAL LOCATION: **main office - principal's office, bathroom, vault**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03B**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **main office - principal's office, bathroom & vault**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **03B**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile**

MATERIAL LOCATION: **main office - principal's office, bathroom & vault**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03C**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **03C**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**

MATERIAL LOCATION: **Engineer's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **basement ladie's room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Linoleum**

MATERIAL LOCATION: **basement ladie's room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 building (demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile- ABATED**

MATERIAL LOCATION: **1955 building (demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **9" x 9" Floor Tile- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 building (demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile- ABATED**

MATERIAL LOCATION: **1955 building (demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Wallboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **basement art room, fire pump room**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Wallboard**
MATERIAL LOCATION: **basement art room, fire pump room**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **12" x 12" Beige w/tan Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **basement - art room**

MATERIAL QUANTITY: **1550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **12" x 12" Beige w/tan Streaks Floor Tile Mastic**
MATERIAL LOCATION: **basement - art room**
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11B**
MATERIAL DESCRIPTION: **12" x 12" black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **room 306**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **11B**
MATERIAL DESCRIPTION: **12" x 12" black Floor Tile Mastic**
MATERIAL LOCATION: **room 306**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11C**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **11C**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **room 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11D**
MATERIAL DESCRIPTION: **12" x 12" Beige streaked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors (patches), 310 (patches)**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 11/04/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **11D**
MATERIAL DESCRIPTION: **12" x 12" Beige streaked Floor Tile Mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors (patches), 310 (patches)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11E**
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st floor corridor - outside boys toilet, Room 313, 311, 310 (patches), 303**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 11/04/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **11E**
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile Mastic**
MATERIAL LOCATION: **1st floor corridor - outside boys toilet, Room 313, 311, 310 (patches), 303**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11F**
MATERIAL DESCRIPTION: **12" x 12" tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102,105,107, engineer'sn office, 211**

MATERIAL QUANTITY: **4770**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **11F**
MATERIAL DESCRIPTION: **12" x 12" tan Floor Tile Mastic**
MATERIAL LOCATION: **Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102,105,107, engineer'sn office, 211**
MATERIAL QUANTITY: **4770** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **9" x 9" black Floor Tile Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **main office - principal's office, washroom, vault**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **9" x 9" black Floor Tile Mastic (Abated)**
MATERIAL LOCATION: **main office - principal's office, washroom, vault**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12B**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **main office - principal's office, bathroom & vault**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **12B**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile Mastic (Abated)**
MATERIAL LOCATION: **main office - principal's office, bathroom & vault**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12C**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **engineer's toilet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **12C**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**

MATERIAL LOCATION: **engineer's toilet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **basement ladie's room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Linoleum mastic**

MATERIAL LOCATION: **basement ladie's room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 building- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic- ABATED**

MATERIAL LOCATION: **1955 building- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9" x 9" Floor Tile Mastic- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 building- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile Mastic- ABATED**

MATERIAL LOCATION: **1955 building- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **basement art room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Brown vinyl baseboard**

MATERIAL LOCATION: **basement art room**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Brown vinyl baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **basement art room**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Brown vinyl baseboard Mastic**
MATERIAL LOCATION: **basement art room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Drywall compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **basement art room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Drywall compound**
MATERIAL LOCATION: **basement art room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Staff lounge - kitchen**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 11/04/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**
MATERIAL LOCATION: **Staff lounge - kitchen**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19B**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Staff lounge - kitchen**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **19B**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**
MATERIAL LOCATION: **Staff lounge - kitchen**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Hard plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Hard plaster**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Ceiling plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout basement and classrooms**
MATERIAL QUANTITY: **10160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Ceiling damage in Room 307, 305, 214**

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Ceiling plaster**
MATERIAL LOCATION: **Throughout basement and classrooms**
MATERIAL QUANTITY: **10160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to Determine ACM Content

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12" x 12" Light Blue Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Storage, Boys Bathroom, Lunchroom, Corridor, Girls Playroom, Room 312,**

MATERIAL QUANTITY: **6700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Vinyl Floor Tile**

MATERIAL LOCATION: **Basement Storage, Boys Bathroom, Lunchroom, Corridor, Girls Playroom, Room 312,**

MATERIAL QUANTITY: **6700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" Light Blue Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Storage, Boys Bathroom, Lunchroom, Corridor, Girls Playroom, Room 312,**

MATERIAL QUANTITY: **6700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Basement Storage, Boys Bathroom, Lunchroom, Corridor, Girls Playroom, Room 312,**

MATERIAL QUANTITY: **6700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Vinyl Floor Tile**
MATERIAL LOCATION: **Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,**

MATERIAL QUANTITY: **2400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Lab table tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 309**
MATERIAL QUANTITY: **432** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Lab table tops**

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY: **432**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12" x 12" Light Green Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor, Storage Room, Principles Office.**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in 1st floor corridor**

Inspector's Signature: _____



Date: 11/04/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12" x 12" Light Green Vinyl Floor Tile**

MATERIAL LOCATION: **1st Floor Corridor, Storage Room, Principles Office.**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" Light Green Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor, Storage Room, Principles Office.**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" Light Green Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor, Storage Room, Principles Office.**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12" x 12" Dark Green Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor and Office**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12" x 12" Dark Green Vinyl Floor Tile**
MATERIAL LOCATION: **1st Floor Corridor and Office**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12" x 12" Dark Green Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor and Office**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12" x 12" Dark Green Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor and Office**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Mag block boiler insulation- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **boiler room- material abated and boiler removed in 1994**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Mag block boiler insulation- ABATED**

MATERIAL LOCATION: **boiler room- material abated and boiler removed in 1994**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard pipe covering**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **attic - tank**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard pipe covering**
MATERIAL LOCATION: **attic - tank**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Cardboard pipe fittings**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **attic - tank**
MATERIAL QUANTITY: **3** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Cardboard pipe fittings**

MATERIAL LOCATION: **attic - tank**

MATERIAL QUANTITY: **3**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **original (1893) building air chamber**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Aircell pipe insulation**

MATERIAL LOCATION: **original (1893) building air chamber**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell pipe joints**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **basement teachers lounge**

MATERIAL QUANTITY: **6**

MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY:

DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell pipe joints**
MATERIAL LOCATION: **basement teachers lounge**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Preform pipe covering- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1893 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Preform pipe covering- ABATED**

MATERIAL LOCATION: **1893 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Water meter packing**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **basement fire pump room, Basement Teacher's Lounge**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Water meter packing**
MATERIAL LOCATION: **basement fire pump room, Basement Teacher's Lounge**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Cardboard pipe covering- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **Cardboard pipe covering- ABATED**

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Cardboard pipe joint- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Cardboard pipe joint- ABATED**

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **Aircell pipe insulation- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 building addition- (building demolished)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Aircell pipe insulation- ABATED**

MATERIAL LOCATION: **1955 building addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **Aircell pipe joints- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Aircell pipe joints- ABATED**

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Cementious pipe fittings**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Girls and Boys bathrooms - pipe chases**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Cementious pipe fittings**
MATERIAL LOCATION: **Girls and Boys bathrooms - pipe chases**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **Pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Girls and Boys bathrooms - pipe chases**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 11/04/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **Pipe insulation**
MATERIAL LOCATION: **Girls and Boys bathrooms - pipe chases**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**
MATERIAL DESCRIPTION: **Incinerator brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **U**

MATERIAL DESCRIPTION: **Incinerator brick**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**
MATERIAL DESCRIPTION: **Cementitious pipe fittings**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Storage and Fire Pump Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **V**

MATERIAL DESCRIPTION: **Cementitious pipe fittings**

MATERIAL LOCATION: **Engineer's Storage and Fire Pump Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**
MATERIAL DESCRIPTION: **Pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Engineer's Storage and Fire Pump Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **W**
MATERIAL DESCRIPTION: **Pipe insulation**
MATERIAL LOCATION: **Engineer's Storage and Fire Pump Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**
MATERIAL DESCRIPTION: **Material behind metal ceiling and walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Auditorium Fan Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **11/04/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **X**

MATERIAL DESCRIPTION: **Material behind metal ceiling and walls**

MATERIAL LOCATION: **Auditorium Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Sample to determine ACM content

Management Planner's Signature: _____



Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**

ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Tongue and groove wooden floor**

MATERIAL LOCATION: **Rooms 315, 314, 309, 307, 304, 302, 301, 215, 214, 213, 212, 210, 209, 207, 204, 202, 201, 104, gym track, gym, 106, 112, 113, 114, 115**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Patches in Room 308, 305**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/17/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Green/ gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **1st Fl Corridor, main Office, 1st floor teacher's storage**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Ray School** INSPECTION DATE: **11/4/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Green/ gray Specks Floor Tile**
MATERIAL LOCATION: **1st FI Corridor, main Office, 1st floor teacher's storage**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **4** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in 1st floor teacher's storage room

Inspector's Signature: _____



Date: 11/04/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Green/ gray Specks Floor Tile**
MATERIAL LOCATION: **1st Fl Corridor, main Office, 1st floor teacher's storage**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/17/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Ray School** REVIEW DATE: **11/17/2022**
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Specks Floor Tile**
MATERIAL LOCATION: **Patches in Room 308, 305**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/17/2022**

APPENDIX B

Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

Devon Jackson

has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/1/2022 - 3/3/2022

Exam Date: 3/3/2022




Expiration Date: 3/3/2023

Certificate Number: ABI2203030658

Kathy DeSalvo, Director

Devon Jackson

Illinois Licensed Building Inspector, Air Sampling Professional

 ILLINOIS DEPARTMENT OF PUBLIC HEALTH IDPH PROTECTING HEALTH. IMPROVING LIVES.	ASBESTOS PROFESSIONAL LICENSE	
ID NUMBER 100 - 05020	ISSUED 5/13/2022	EXPIRES 05/15/2023
DEVON A JACKSON 10657 SOUTH AVENUE D CHICAGO, IL 60617 Environmental Health		

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/3/2023
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	11/18/2022

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER

3/28/2023

AIR SAMPLING PROFESSIONAL


Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid

training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed