

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2435
SCHOOL NAME: Sawyer School
ADDRESS OF SCHOOL: 5248 S. Sawyer Ave
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/17/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/27/2022 ENROLLMENT 1041
IDPH INSPECTOR LICENSE NUMBER: 100-07134
IDPH LICENSED INSPECTOR NAME (Please Print): Ron Brock
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



11/18/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Sawyer School

5248 S. Sawyer Ave
Chicago, IL, 60632

Unit: 25231
Building ID: 5710

IDPH ID Number: 14-016-2990-2435

REPORT DATE:

Friday, November 18, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

11/18/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25231 Region: 04 IDPH ID: 14-016-2990-2435

School: Sawyer School Building ID: 5710

Address: 5248 S. Sawyer Ave

Chicago, IL, 60632

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 10/27/2022

Review Date: 11/18/2022

Inspector: Ron Brock

Inspector IDPH License: 100-07134

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 18, 2022

RE: Sawyer School, Unit 25231
5248 S. Sawyer Ave
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Sawyer School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Sawyer School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Sawyer School Unit: 25231 Region: 04
Address: 5248 S. Sawyer Ave Chicago, IL, 60632
IDPH ID: 14-016-2990-2435 Building ID: 5710
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 1041

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Ron Brock


Inspector IDPH license # 100-07134
Reinspection Date: 10/27/2022

Signature: 
Date: 10/27/2022

6. Management Planner

Management Planner Name: Evan Christian


Management Planner IDPH license # 100-19466

Signature: 
Date: 11/18/2022

7. Review Date: 11/18/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 11/18/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Sawyer School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5710:

14	9" x 9" Beige Floor Tile Mastic
2	9" x 9" Beige Floor Tile
23	12" x 12" Beige Floor Tile
24	12" x 12" Brown Floor Tile Mastic
25	Wood flooring
26	12" x 12" Off-White w/Beige Streaks Floor Tile
27	Mastic for 12" x 12" Off-White w/Beige Floor Tile
28	Chalkboard/whiteboard adhesive
29	Blue speckled laminate sheet flooring

- 30 Mastic for Blue Speckled Laminate Sheet Flooring
- 31 2'x4' fissured ceiling tile
- 32 Mastic for Blue/Gray Carpet
- 33 12" x 12" Off-White w/White Streaks Floor Tile
- 34 Mastic for 12" x 12" Off-White w/White Streaks Floor Tile
- 35 2'x2' fissured ceiling tile
- 36 12" x 12" Beige w/Brown Streaks Floor Tile
- 37 Mastic for 12" x 12" Beige w/Brown Streaks Floor Tile
- 38 12" x 12" Gray and Brown Streaks w/White Floor Tile
- 39 Mastic for 12" x 12" Gray and Brown Streaks w/White Floor Tile
- 40 Blue carpet adhesive
- 41 Gray laminate sheet flooring
- 42 Mastic for Gray Laminate Sheet Flooring
- 43 12" x 12" Beige w/Gray Streaks Floor Tile
- 44 Mastic for 12" x 12" Beige w/Gray Streaks Floor Tile
- 45 2' x 4' Fissured Ceiling Tile (2x2 Look)
- 46 12" x 12" White w/Gray Streaks Floor Tile
- 47 Mastic for 12" x 12" White w/Gray Streaks Floor Tile
- 48 12" x 12" Dark Green w/White Specks Floor Tile
- 49 Mastic for 12" x 12" Dark Green w/White Specks Floor Tile

- 50 12" x 12" Dark Blue w/White Specks Floor Tile
- 51 Mastic for 12" x 12" Dark Blue w/White Specks Floor Tile
- 52 12" x 12" Yellow w/White Streaks Floor Tile
- 53 Mastic for 12" x 12" Yellow w/White Streaks Floor Tile
- 54 Mastic for Dark Multi-Coloured Carpet
- A Aircell pipe insulation
- J Tank covering

B. The following new homogenous areas have been identified for Building 5710:

25	Wood flooring
26	12" x 12" Off-White w/Beige Streaks Floor Tile
27	Mastic for 12" x 12" Off-White w/Beige Floor Tile
28	Chalkboard/whiteboard adhesive
29	Blue speckled laminate sheet flooring
30	Mastic for Blue Speckled Laminate Sheet Flooring
31	2'x4' fissured ceiling tile
32	Mastic for Blue/Gray Carpet
33	12" x 12" Off-White w/White Streaks Floor Tile
34	Mastic for 12" x 12" Off-White w/White Streaks Floor Tile
35	2'x2' fissured ceiling tile
36	12" x 12" Beige w/Brown Streaks Floor Tile
37	Mastic for 12" x 12" Beige w/Brown Streaks Floor Tile
38	12" x 12" Gray and Brown Streaks w/White Floor Tile
39	Mastic for 12" x 12" Gray and Brown Streaks w/White Floor Tile
40	Blue carpet adhesive
41	Gray laminate sheet flooring
42	Mastic for Gray Laminate Sheet Flooring
43	12" x 12" Beige w/Gray Streaks Floor Tile
44	Mastic for 12" x 12" Beige w/Gray Streaks Floor Tile

- 45 2' x 4' Fissured Ceiling Tile (2x2 Look)
- 46 12" x 12" White w/Gray Streaks Floor Tile
- 47 Mastic for 12" x 12" White w/Gray Streaks Floor Tile
- 48 12" x 12" Dark Green w/White Specks Floor Tile
- 49 Mastic for 12" x 12" Dark Green w/White Specks Floor Tile
- 50 12" x 12" Dark Blue w/White Specks Floor Tile
- 51 Mastic for 12" x 12" Dark Blue w/White Specks Floor Tile
- 52 12" x 12" Yellow w/White Streaks Floor Tile
- 53 Mastic for 12" x 12" Yellow w/White Streaks Floor Tile
- 54 Mastic for Dark Multi-Coloured Carpet

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10	9" x 9" Green Floor Tile Mastic
11	12" x 12" Beige Floor Tile Mastic
12	9" x 9" Green Floor Tile
13	12" x 12" Beige Floor Tile
14	9" x 9" Beige Floor Tile Mastic
15	9" x 9" Multi-Color Floor Tile
16	9" x 9" Multi-Color Floor Tile Mastic
17	12" x 12" Light Gray and Beige Floor Tile
18	12" x 12" Light Gray and Beige Floor Tile Mastic
19	Blue carpet adhesive - removed
2	9" x 9" Beige Floor Tile
20	12" x 12" Light Beige w/ Dark Beige & White Specks Floor Tile
21	12" x 12" Beige w/ Dark Beige & White Specks Floor Tile
22	Mastic Associated w/ 12" x 12" Beige and Light Beige Floor Tile (HA's 20 & 21)
23	12" x 12" Beige Floor Tile
24	12" x 12" Brown Floor Tile Mastic
25	Wood flooring
26	12" x 12" Off-White w/Beige Streaks Floor Tile
27	Mastic for 12" x 12" Off-White w/Beige Floor Tile
28	Chalkboard/whiteboard adhesive
29	Blue speckled laminate sheet flooring
3	12" x 12" Brown Floor Tile
30	Mastic for Blue Speckled Laminate Sheet Flooring
31	2'x4' fissured ceiling tile
32	Mastic for Blue/Gray Carpet
33	12" x 12" Off-White w/White Streaks Floor Tile
34	Mastic for 12" x 12" Off-White w/White Streaks Floor Tile
35	2'x2' fissured ceiling tile
36	12" x 12" Beige w/Brown Streaks Floor Tile
37	Mastic for 12" x 12" Beige w/Brown Streaks Floor Tile
38	12" x 12" Gray and Brown Streaks w/White Floor Tile
39	Mastic for 12" x 12" Gray and Brown Streaks w/White Floor Tile
40	Blue carpet adhesive
41	Gray laminate sheet flooring
42	Mastic for Gray Laminate Sheet Flooring

43	12" x 12" Beige w/Gray Streaks Floor Tile
44	Mastic for 12" x 12" Beige w/Gray Streaks Floor Tile
45	2' x 4' Fissured Ceiling Tile (2x2 Look)
46	12" x 12" White w/Gray Streaks Floor Tile
47	Mastic for 12" x 12" White w/Gray Streaks Floor Tile
48	12" x 12" Dark Green w/White Specks Floor Tile
49	Mastic for 12" x 12" Dark Green w/White Specks Floor Tile
5	Linoleum
50	12" x 12" Dark Blue w/White Specks Floor Tile
51	Mastic for 12" x 12" Dark Blue w/White Specks Floor Tile
52	12" x 12" Yellow w/White Streaks Floor Tile
53	Mastic for 12" x 12" Yellow w/White Streaks Floor Tile
54	Mastic for Dark Multi-Coloured Carpet
6	Fire doors
8	12" x 12" Floor Tile Mastic
9	Linoleum adhesive
A	Aircell pipe insulation
B	Aircell pipe insulation joints
C	Cardboard pipe insulation
E	Aircell duct wrap
H	Boiler gaskets
I	Boiler covering
J	Tank covering
K	Aircell pipe insulation
L	Aircell pipe insulation joints
M	Cardboard pipe insulation
N	Cardboard joints
O	Fiberglass joints
P	Incinerator insulation - removed
Q	12" x 12" Blue Mix Floor Tile
R	12" x 12" Blue Mix Floor Tile Mastic
S	12" x 12" Yellow Mix Floor Tile
T	12" x 12" Yellow Mix Floor Tile Mastic
U	12" x 12" Beige Mix Floor Tile
V	12" x 12" Beige Mix Floor Tile Mastic
W	12" x 12" Brown Mix Floor Tile
X	12" x 12" Brown Mix Floor Tile Mastic
Y	9" x 9" Dark Brown w/Beige Streaks Floor Tile
Z	9" x 9" Dark Brown w/Beige Streaks Floor Tile Mastic

The following areas were deemed to be inaccessible:

11	12" x 12" Beige Floor Tile Mastic
14	9" x 9" Beige Floor Tile Mastic
2	9" x 9" Beige Floor Tile
22	Mastic Associated w/ 12" x 12" Beige and Light Beige Floor Tile (HA's 20 & 21)
24	12" x 12" Brown Floor Tile Mastic
27	Mastic for 12" x 12" Off-White w/Beige Floor Tile
28	Chalkboard/whiteboard adhesive
30	Mastic for Blue Speckled Laminate Sheet Flooring
32	Mastic for Blue/Gray Carpet
34	Mastic for 12" x 12" Off-White w/White Streaks Floor Tile
35	2'x2' fissured ceiling tile
37	Mastic for 12" x 12" Beige w/Brown Streaks Floor Tile
39	Mastic for 12" x 12" Gray and Brown Streaks w/White Floor Tile
40	Blue carpet adhesive
44	Mastic for 12" x 12" Beige w/Gray Streaks Floor Tile
47	Mastic for 12" x 12" White w/Gray Streaks Floor Tile
49	Mastic for 12" x 12" Dark Green w/White Specks Floor Tile
51	Mastic for 12" x 12" Dark Blue w/White Specks Floor Tile
53	Mastic for 12" x 12" Yellow w/White Streaks Floor Tile
54	Mastic for Dark Multi-Coloured Carpet
6	Fire doors
8	12" x 12" Floor Tile Mastic
C	Cardboard pipe insulation
R	12" x 12" Blue Mix Floor Tile Mastic
T	12" x 12" Yellow Mix Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Ron Brock, IDPH License # 100-07134. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Sawyer School Building 5710 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Hard coat			1918 Building	NO_ACBM	MISC								
10	9" x 9" Green Floor Tile Mastic			Throughout 1918 Building, Room 102	ASSUMED	MISC								
11	12" x 12" Beige Floor Tile Mastic	10,000	SF	Throughout 1918 Building	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
12	9" x 9" Green Floor Tile		SF	Throughout 1918 Building, Room 102	ASSUMED	MISC				SF				
13	12" x 12" Beige Floor Tile	10,000	SF	Throughout 1918 Building	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
14	9" x 9" Beige Floor Tile Mastic	1,700	SF	Throughout 1900 Building - Classrooms	ASSUMED	MISC	N	LOC	600	SF	Yes	ACBM with the potential for damage	3	LOW
15	9" x 9" Multi-Color Floor Tile			Room 207	ASSUMED	MISC								
16	9" x 9" Multi-Color Floor Tile Mastic			Room 207	ASSUMED	MISC								
17	12" x 12" Light Gray and Beige Floor Tile		SF	Room 202	ASSUMED	MISC				SF				
18	12" x 12" Light Gray and Beige Floor Tile Mastic			Room 202	ASSUMED	MISC								
19	Blue carpet adhesive - removed			Library (Basement)	ASSUMED	MISC								
2	9" x 9" Beige Floor Tile	1,700	SF	Throughout 1900 Building - Classrooms	ASSUMED	MISC	N	LOC	600	SF	Yes	ACBM with the potential for damage	3	LOW
20	12" x 12" Light Beige w/ Dark Beige & White Specks Floor Tile	800	SF	Room 207, 208,	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
21	12" x 12" Beige w/ Dark Beige & White Specks Floor Tile	800	SF	Room 207, 208	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22	Mastic Associated w/ 12" x 12" Beige and Light Beige Floor Tile (HA's 20 & 21)	800	SF	Room 207, 208	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23	12" x 12" Beige Floor Tile	500	SF	Room 110	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		HIGH
24	12" x 12" Brown Floor Tile Mastic	500	SF	Room 110	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
25	Wood flooring	13,200	SF	301, 005, 303, 304, 311, 310, 305, 209, 206, 204, 203, Gym (1900 Building), 202, 201, Auditorium Balcony, Stage, 101, 103, 112, 111, 109, 108, Teacher's Lounge, Teacher's Lounge Storage Room, 004	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
26	12" x 12" Off-White w/Beige Streaks Floor	500	SF	Rooms 302, 210	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the		LOW

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Tile											potential for damage		
27	Mastic for 12" x 12" Off-White w/Beige Floor Tile	500	SF	Rooms 302, 210	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
28	Chalkboard/whiteboard adhesive	3,100	SF	Rooms 301, 302, 303, 304, 311, 310, 207, 208, 206, 210, 211, 204, 203, 202, 201, 103, 104, 111, 109, 108, 107	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
29	Blue speckled laminate sheet flooring	950	SF	Rooms 311, 211	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
3	12" x 12" Brown Floor Tile		SF	Throughout 1900 Building - Classrooms 301, 302, 303, 304, 306, 203	ASSUMED	MISC				SF				
30	Mastic for Blue Speckled Laminate Sheet Flooring	950	SF	Rooms 311, 211	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
31	2'x4' fissured ceiling tile	450	SF	Room 209	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
32	Mastic for Blue/Gray Carpet	400	SF	Room 205	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
33	12" x 12" Off-White w/White Streaks Floor Tile	500	SF	Room 102	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with the potential for damage	5	LOW
34	Mastic for 12" x 12" Off-White w/White Streaks Floor Tile	500	SF	Room 102	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with the potential for damage	5	LOW
35	2'x2' fissured ceiling tile	300	SF	Rooms 112, 002	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
36	12" x 12" Beige w/Brown Streaks Floor Tile	400	SF	Rooms 104, 110	ASSUMED	MISC	N	DIST	13	SF	Yes	ACBM with the potential for damage	5	LOW
37	Mastic for 12" x 12" Beige w/Brown Streaks Floor Tile	400	SF	Rooms 104, 110	ASSUMED	MISC	N	LOC	8	SF	Yes	ACBM with the potential for damage	5	LOW
38	12" x 12" Gray and Brown Streaks w/White Floor Tile	250	SF	Room 110	ASSUMED	MISC	N	LOC	5	SF	Yes	ACBM with the potential for damage	5	LOW
39	Mastic for 12" x 12" Gray and Brown Streaks w/White Floor Tile	250	SF	Room 110	ASSUMED	MISC	N	LOC	5	SF	Yes	ACBM with the potential for damage	5	LOW
4	2' x 4' Drop Ceiling			Main Office (106) and Library (004)	NO_ACBM	MISC								
40	Blue carpet adhesive	200	SF	Room 106	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
41	Gray laminate sheet flooring	150	SF	Room 106	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
42	Mastic for Gray Laminate Sheet Flooring	150	SF	Room 106	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
43	12" x 12" Beige w/Gray Streaks Floor Tile	400	SF	Room 107	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with the potential for damage	5	LOW
44	Mastic for 12" x 12" Beige w/Gray Streaks Floor Tile	400	SF	Room 107	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with the potential for damage	5	LOW
45	2' x 4' Fissured Ceiling Tile (2x2 Look)	25,000	SF	Teacher's Lounge (1900s Building), 333, 332, 334, 335, 330, 331, 328, 326, 324, 329, 327, 322, 325, 320, 225, 220, 227, 229, 223, 222, 231, 224, 226, 233, 228, 235, 140, 136, 141, 134, 137, 135, 133, Main Office (New Building), Assistant Principal's Office (New Building), Principal's Office (New Building), Main Office Workroom (New Building), Main Office Restroom (New Building), 132, 131, 130, 133, 129, 128	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
46	12" x 12" White w/Gray Streaks Floor Tile	7,800	SF	Rooms 334, 335, 332, 333, 330, 331, 328, 326, 324, 327, 322, 325, 320, 225, 222, 222 Storage Room, 227, 229, 231, 224, 226, 233, 228, 235, 140, 138, 136, 141, 134, Main Office Workroom, 133, 132, 131, 130, 128	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
47	Mastic for 12" x 12" White w/Gray Streaks Floor Tile	7,800	SF	Rooms 334, 335, 332, 333, 330, 331, 328, 326, 324, 327, 322, 325, 320, 225, 222, 222 Storage	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room, 227, 229, 231, 224, 226, 233, 228, 235, 140, 138, 136, 141, 134, Main Office Workroom, 133, 131, 132, 130, 128										
48	12" x 12" Dark Green w/White Specks Floor Tile	2,500	SF	Rooms 334, 331, 326, 325, 320, 225, 231, 228, 138, 132	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
49	Mastic for 12" x 12" Dark Green w/White Specks Floor Tile	2,500	SF	Rooms 334, 331, 326, 325, 320, 225, 231, 228, 138, 132	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
5	Linoleum		SF	Office and Room 211, 311	ASSUMED	MISC				SF				
50	12" x 12" Dark Blue w/White Specks Floor Tile	2,500	SF	Rooms 335, 330, 329, 322, 229, 224, 235, 140, 141, 134, 128	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
51	Mastic for 12" x 12" Dark Blue w/White Specks Floor Tile	2,500	SF	Rooms 335, 330, 329, 322, 229, 224, 235, 140, 141, 134, 128	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
52	12" x 12" Yellow w/White Streaks Floor Tile	2,500	SF	Rooms 332, 333, 324, 327, 227, 226, 233, 136, 130	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
53	Mastic for 12" x 12" Yellow w/White Streaks Floor Tile	2,500	SF	Rooms 332, 333, 324, 327, 227, 226, 233, 136, 130	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
54	Mastic for Dark Multi-Coloured Carpet	3,000	SF	Rooms 220, 222, 223, 135, 137, Main Office, Assistant Principal's Office, Principal's Office, 129	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
6	Fire doors	21	SF	1900 Building-Basement (across from room B3)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
8	12" x 12" Floor Tile Mastic	10,000	SF	Throughout 1900 Building - Classrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
9	Linoleum adhesive		SF	Office and room 211, 311	ASSUMED	MISC				SF				
A	Aircell pipe insulation	750	LF	Throughout 1918 Building	ASSUMED	TSI	Y	LOC	1	LF	Yes	Damaged or significantly damaged	3	MODERATE

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												friable thermal system insulating ACBM		
B	Aircell pipe insulation joints	75	LF	Throughout 1918 Building	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
C	Cardboard pipe insulation	150	LF	Throughout 1900 Building	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Cardboard pipe insulation joints	15	LF	Throughout 1900 Building	CHR	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Aircell duct wrap			Boy's Play Room 1900 Building	ASSUMED	TSI								
G	Fiberglass joints			Throughout 1918 Building	CHR	TSI								
H	Boiler gaskets	15	SF	Boiler Room	ASSUMED	MISC	Y	NONE	0	SF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
I	Boiler covering	750	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0	SF	No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
J	Tank covering	600	SF	Engine and Tank Room	ASSUMED	TSI	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE
K	Aircell pipe insulation	750	LF	Throughout 1900 Building	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Aircell pipe insulation joints	75	LF	Throughout 1900 Building	ASSUMED	TSI	Y	NONE	0	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM		MODERATE
M	Cardboard pipe insulation			Throughout 1918 Building	ASSUMED	TSI								
N	Cardboard joints			Throughout 1918 Building	ASSUMED	TSI								
O	Fiberglass joints	30	LF	Throughout 1900 Building	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
P	Incinerator insulation - removed			Boiler Room	ASSUMED	TSI								
Q	12" x 12" Blue Mix Floor Tile	1,000	SF	1900 BLDG- Room B-1, Room 305, 306, 001, 001 Storage Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
R	12" x 12" Blue Mix Floor Tile Mastic	1,000	SF	1900 BLDG-Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the		LOW

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date **10/27/2022**
Inspector Name **Ron Brock**
100-07134 **5/15/2023**
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	Not observed 2022
11	
12	Not observed 2022
13	
14	All of Rm. 104 damaged
15	Not observed 2022
16	Not observed 2022
17	Not observed 2022
18	Not observed 2022
19	Not observed 2022
2	All of Rm. 104 damaged
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	Not observed 2022
30	

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
31	
32	
33	Damage in 102
34	Damage in 102
35	
36	Damage in 104, 110
37	Damage in 104
38	Damage in 110
39	Damage in 110
4	
40	
41	
42	
43	Damage in 107
44	Damage in 107
45	
46	
47	
48	
49	
5	Not observed 2022
50	
51	
52	
53	
54	
6	
8	
9	Not observed 2022

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
A	Damage in mechanical room
B	
C	
D	
E	Not observed 2022
G	Not observed 2022
H	
I	
J	New water tank and boiler with no cover
K	
L	
M	Not observed 2022
N	Not observed 2022
O	
P	Not observed 2022
Q	
R	
S	
T	
U	Not observed 2022
V	Not observed 2022
W	Not observed 2022
X	Not observed 2022
Y	Not observed 2022
Z	Not observed 2022

Chicago Public Schools

School Sawyer School **Unit** 25231 **Building ID** 5710

Address 5248 S. Sawyer Ave **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Hard coat			1918 Building	No ACBM	MISC					
10	9" x 9" Green Floor Tile Mastic			Throughout 1918 Building, Room 102	Assumed	MISC					Follow O&M Plan
11	12" x 12" Beige Floor Tile Mastic	10,000	SF	Throughout 1918 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9" x 9" Green Floor Tile		SF	Throughout 1918 Building, Room 102	Assumed	MISC			SF		Follow O&M Plan
13	12" x 12" Beige Floor Tile	10,000	SF	Throughout 1918 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	9" x 9" Beige Floor Tile Mastic	1,700	SF	Throughout 1900 Building - Classrooms	Assumed	MISC	No	600	SF	6 ACBM with the potential for damage	Repair
15	9" x 9" Multi-Color Floor Tile			Room 207	Assumed	MISC					Follow O&M Plan
16	9" x 9" Multi-Color Floor Tile Mastic			Room 207	Assumed	MISC					Follow O&M Plan
17	12" x 12" Light Gray and Beige Floor Tile		SF	Room 202	Assumed	MISC			SF		Follow O&M Plan
18	12" x 12" Light Gray and Beige Floor Tile Mastic			Room 202	Assumed	MISC					Follow O&M Plan
19	Blue carpet adhesive - removed			Library (Basement)	Assumed	MISC					Follow O&M Plan
2	9" x 9" Beige Floor Tile	1,700	SF	Throughout 1900 Building - Classrooms	Assumed	MISC	No	600	SF	6 ACBM with the potential for damage	Repair
20	12" x 12" Light Beige w/ Dark Beige & White Specks Floor Tile	800	SF	Room 207, 208,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12" x 12" Beige w/ Dark Beige & White Specks Floor Tile	800	SF	Room 207, 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Mastic Associated w/ 12" x 12" Beige and Light Beige Floor Tile (HA's 20 & 21)	800	SF	Room 207, 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12" x 12" Beige Floor Tile	500	SF	Room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12" x 12" Brown Floor Tile Mastic	500	SF	Room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Wood flooring	13,200	SF	301, 005, 303, 304, 311, 310, 305, 209, 206, 204, 203, Gym (1900 Building), 202, 201, Auditorium Balcony, Stage, 101, 103, 112, 111, 109, 108, Teacher's Lounge, Teacher's Lounge Storage Room, 004	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12" x 12" Off-White w/Beige Streaks Floor Tile	500	SF	Rooms 302, 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Mastic for 12" x 12" Off-White w/Beige Floor Tile	500	SF	Rooms 302, 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Chalkboard/whiteboard adhesive	3,100	SF	Rooms 301, 302, 303, 304, 311, 310, 207, 208, 206, 210, 211, 204, 203, 202, 201, 103, 104, 111, 109, 108, 107	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Blue speckled laminate sheet flooring	950	SF	Rooms 311, 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3	12" x 12" Brown Floor Tile		SF	Throughout 1900 Building - Classrooms 301, 302, 303, 304, 306, 203	Assumed	MISC			SF		Follow O&M Plan
30	Mastic for Blue Speckled Laminate Sheet Flooring	950	SF	Rooms 311, 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	2'x4' fissured ceiling tile	450	SF	Room 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
 Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
32	Mastic for Blue/Gray Carpet	400	SF	Room 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" x 12" Off-White w/White Streaks Floor Tile	500	SF	Room 102	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Repair
34	Mastic for 12" x 12" Off-White w/White Streaks Floor Tile	500	SF	Room 102	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Repair
35	2'x2' fissured ceiling tile	300	SF	Rooms 112, 002	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" x 12" Beige w/Brown Streaks Floor Tile	400	SF	Rooms 104, 110	Assumed	MISC	No	13	SF	6 ACBM with the potential for damage	Repair
37	Mastic for 12" x 12" Beige w/Brown Streaks Floor Tile	400	SF	Rooms 104, 110	Assumed	MISC	No	8	SF	6 ACBM with the potential for damage	Repair
38	12" x 12" Gray and Brown Streaks w/White Floor Tile	250	SF	Room 110	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Repair
39	Mastic for 12" x 12" Gray and Brown Streaks w/White Floor Tile	250	SF	Room 110	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Repair
4	2' x 4' Drop Ceiling			Main Office (106) and Library (004)	No ACBM	MISC					
40	Blue carpet adhesive	200	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Gray laminate sheet flooring	150	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Mastic for Gray Laminate Sheet Flooring	150	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12" x 12" Beige w/Gray Streaks Floor Tile	400	SF	Room 107	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Repair
44	Mastic for 12" x 12" Beige w/Gray Streaks Floor Tile	400	SF	Room 107	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Repair
45	2' x 4' Fissured Ceiling Tile (2x2 Look)	25,000	SF	Teacher's Lounge (1900s Building), 333, 332, 334, 335, 330, 331, 328, 326, 324, 329, 327, 322, 325, 320, 225, 220, 227, 229, 223, 222, 231, 224, 226, 233, 228, 235, 140, 136, 141, 134, 137, 135, 133, Main Office (New Building), Assistant Principal's Office (New Building), Principal's Office (New Building), Main Office Workroom (New Building), Main Office Restroom (New Building), 132, 131, 130, 133, 129, 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12" x 12" White w/Gray Streaks Floor Tile	7,800	SF	Rooms 334, 335, 332, 333, 330, 331, 328, 326, 324, 327, 322, 325, 320, 225, 222, 222 Storage Room, 227, 229, 231, 224, 226, 233, 228, 235, 140, 138, 136, 141, 134, Main Office Workroom, 133, 132, 131, 130, 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
47	Mastic for 12" x 12" White w/Gray Streaks Floor Tile	7,800	SF	Rooms 334, 335, 332, 333, 330, 331, 328, 326, 324, 327, 322, 325, 320, 225, 222, 222 Storage Room, 227, 229, 231, 224, 226, 233, 228, 235, 140, 138, 136, 141, 134, Main Office Workroom, 133, 131, 132, 130, 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12" x 12" Dark Green w/White Specks Floor Tile	2,500	SF	Rooms 334, 331, 326, 325, 320, 225, 231, 228, 138, 132	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Mastic for 12" x 12" Dark Green w/White Specks Floor Tile	2,500	SF	Rooms 334, 331, 326, 325, 320, 225, 231, 228, 138, 132	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5	Linoleum		SF	Office and Room 211, 311	Assumed	MISC			SF		Follow O&M Plan
50	12" x 12" Dark Blue w/White Specks Floor Tile	2,500	SF	Rooms 335, 330, 329, 322, 229, 224, 235, 140, 141, 134, 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Mastic for 12" x 12" Dark Blue w/White Specks Floor Tile	2,500	SF	Rooms 335, 330, 329, 322, 229, 224, 235, 140, 141, 134, 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12" x 12" Yellow w/White Streaks Floor Tile	2,500	SF	Rooms 332, 333, 324, 327, 227, 226, 233, 136, 130	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Mastic for 12" x 12" Yellow w/White Streaks Floor Tile	2,500	SF	Rooms 332, 333, 324, 327, 227, 226, 233, 136, 130	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Mastic for Dark Multi-Coloured Carpet	3,000	SF	Rooms 220, 222, 223, 135, 137, Main Office, Assistant Principal's Office, Principal's Office, 129	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	Fire doors	21	SF	1900 Building- Basement (across from room B3)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	12" x 12" Floor Tile Mastic	10,000	SF	Throughout 1900 Building - Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9	Linoleum adhesive		SF	Office and room 211, 311	Assumed	MISC			SF		Follow O&M Plan
A	Aircell pipe insulation	750	LF	Throughout 1918 Building	Assumed	TSI	Yes	1	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Encapsulate
B	Aircell pipe insulation joints	75	LF	Throughout 1918 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Cardboard pipe insulation	150	LF	Throughout 1900 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Cardboard pipe insulation joints	15	LF	Throughout 1900 Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Aircell duct wrap			Boy's Play Room 1900 Building	Assumed	TSI					Follow O&M Plan
G	Fiberglass joints			Throughout 1918 Building	Chrysotile	TSI					Follow O&M Plan

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
H	Boiler gaskets	15	SF	Boiler Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Boiler covering	750	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	Tank covering	600	SF	Engine and Tank Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	Aircell pipe insulation	750	LF	Throughout 1900 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Aircell pipe insulation joints	75	LF	Throughout 1900 Building	Assumed	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
M	Cardboard pipe insulation			Throughout 1918 Building	Assumed	TSI					Follow O&M Plan
N	Cardboard joints			Throughout 1918 Building	Assumed	TSI					Follow O&M Plan
O	Fiberglass joints	30	LF	Throughout 1900 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
P	Incinerator insulation - removed			Boiler Room	Assumed	TSI					Follow O&M Plan
Q	12" x 12" Blue Mix Floor Tile	1,000	SF	1900 BLDG- Room B-1, Room 305, 306, 001, 001 Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
R	12" x 12" Blue Mix Floor Tile Mastic	1,000	SF	1900 BLDG-Room B-1, Room 305, 306, 001, 001 Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
S	12" x 12" Yellow Mix Floor Tile	1,000	SF	1900 BLDG- Room B-1, Room 305, 306, 001	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
T	12" x 12" Yellow Mix Floor Tile Mastic	1,000	SF	1900 BLDG-Room B-1, Room 305, 306, 001	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
U	12" x 12" Beige Mix Floor Tile		SF	1918 BLDG Room 206, 208	Assumed	MISC			SF		Follow O&M Plan
V	12" x 12" Beige Mix Floor Tile Mastic		SF	1918 BLDG Room 206, 208	Assumed	MISC			SF		Follow O&M Plan
W	12" x 12" Brown Mix Floor Tile		SF	1918 BLDG- Room 206, 208	Assumed	MISC			SF		Follow O&M Plan
X	12" x 12" Brown Mix Floor Tile Mastic		SF	1918 BLDG- Room 206, 208	Assumed	MISC			SF		Follow O&M Plan
Y	9" x 9" Dark Brown w/Beige Streaks Floor Tile			1900 BLDG - Room 007 by Lunchroom	Assumed	MISC					Follow O&M Plan
Z	9" x 9" Dark Brown w/Beige Streaks Floor Tile Mastic			1900 BLDG Room 007 by Lunchroom	Assumed	MISC					Follow O&M Plan

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
 Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	11/18/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
 Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	
6	
8	
9	
A	
B	
C	
D	
E	
G	
H	
I	
J	
K	
L	
M	

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
N	
O	
P	
Q	
R	
S	
T	
U	
V	
W	
X	
Y	
Z	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Hard coat**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1918 Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Hard coat**

MATERIAL LOCATION: **1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1918 Building, Room 102**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**

MATERIAL LOCATION: **Throughout 1918 Building, Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY: **10000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Throughout 1918 Building, Room 102**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**

MATERIAL LOCATION: **Throughout 1918 Building, Room 102**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Delamination
Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **All of Rm. 104 damaged**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9" x 9" Multi-Color Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9" x 9" Multi-Color Floor Tile**

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9" x 9" Multi-Color Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9" x 9" Multi-Color Floor Tile Mastic**

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12" x 12" Light Gray and Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12" x 12" Light Gray and Beige Floor Tile**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12" x 12" Light Gray and Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Light Gray and Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Blue carpet adhesive - removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library (Basement)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Blue carpet adhesive - removed**

MATERIAL LOCATION: **Library (Basement)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**


RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **All of Rm. 104 damaged**

Inspector's Signature: _____



Date: 10/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Dark Beige & White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 207, 208,**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Dark Beige & White Specks Floor Tile**
MATERIAL LOCATION: **Room 207, 208,**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Beige & White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 207, 208**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Beige & White Specks Floor Tile**
MATERIAL LOCATION: **Room 207, 208**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige and Light Beige Floor Tile (HA's 20 & 21)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 207, 208**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige and Light Beige Floor Tile (HA's 20 & 21)**
MATERIAL LOCATION: **Room 207, 208**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
MATERIAL LOCATION: **Room 110**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 110**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1900 Building - Classrooms 301, 302, 303, 304, 306, 203**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Throughout 1900 Building - Classrooms 301, 302, 303, 304, 306, 203**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **2' x 4' Drop Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office (106) and Library (004)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **2' x 4' Drop Ceiling**

MATERIAL LOCATION: **Main Office (106) and Library (004)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office and Room 211, 311**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **Office and Room 211, 311**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Fire doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1900 Building- Basement (across from room B3)**
MATERIAL QUANTITY: **21** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Fire doors**
MATERIAL LOCATION: **1900 Building- Basement (across from room B3)**
MATERIAL QUANTITY: **21** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Linoleum adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office and room 211, 311**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Linoleum adhesive**

MATERIAL LOCATION: **Office and room 211, 311**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**


RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **750** DAMAGE UNITS: **LF**
COMMENTS: **Damage in mechanical room**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell pipe insulation joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell pipe insulation joints**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard pipe insulation joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1900 Building**

MATERIAL QUANTITY: **15**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard pipe insulation joints**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell duct wrap**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boy's Play Room 1900 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Aircell duct wrap**

MATERIAL LOCATION: **Boy's Play Room 1900 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Fiberglass joints**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Fiberglass joints**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler gaskets**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Boiler covering**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Boiler covering**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Tank covering**
HISTORICAL AHERA DAMAGE CATEGORY **7 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Engine and Tank Room**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **New water tank and boiler with no cover**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Tank covering**
MATERIAL LOCATION: **Engine and Tank Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Aircell pipe insulation joints**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout 1900 Building**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Aircell pipe insulation joints**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Cardboard pipe insulation**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Cardboard joints**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cardboard joints**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Fiberglass joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **Fiberglass joints**

MATERIAL LOCATION: **Throughout 1900 Building**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Incinerator insulation - removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Incinerator insulation - removed**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1900 BLDG- Room B-1, Room 305, 306, 001, 001 Storage Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile**
MATERIAL LOCATION: **1900 BLDG- Room B-1, Room 305, 306, 001, 001 Storage Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1900 BLDG-Room B-1, Room 305, 306, 001, 001 Storage Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile Mastic**
MATERIAL LOCATION: **1900 BLDG-Room B-1, Room 305, 306, 001, 001 Storage Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **12" x 12" Yellow Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1900 BLDG- Room B-1, Room 305, 306, 001**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **12" x 12" Yellow Mix Floor Tile**
MATERIAL LOCATION: **1900 BLDG- Room B-1, Room 305, 306, 001**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **12" x 12" Yellow Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1900 BLDG-Room B-1, Room 305, 306, 001**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **12" x 12" Yellow Mix Floor Tile Mastic**
MATERIAL LOCATION: **1900 BLDG-Room B-1, Room 305, 306, 001**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **1918 BLDG Room 206, 208**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **U**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**

MATERIAL LOCATION: **1918 BLDG Room 206, 208**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1918 BLDG Room 206, 208**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **V**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**

MATERIAL LOCATION: **1918 BLDG Room 206, 208**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1918 BLDG- Room 206, 208**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **W**

MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile**

MATERIAL LOCATION: **1918 BLDG- Room 206, 208**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1918 BLDG- Room 206, 208**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **X**

MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile Mastic**

MATERIAL LOCATION: **1918 BLDG- Room 206, 208**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/Beige Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1900 BLDG - Room 007 by Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **Y**

MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/Beige Streaks Floor Tile**

MATERIAL LOCATION: **1900 BLDG - Room 007 by Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/Beige Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1900 BLDG Room 007 by Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **Z**

MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/Beige Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1900 BLDG Room 007 by Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray Streaks Floor Tile**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Off-White w/White Streaks Floor Tile**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **3** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in 102

Inspector's Signature: _____



Date: 10/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" Off-White w/White Streaks Floor Tile**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Mastic for Gray Laminate Sheet Flooring**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Mastic for Gray Laminate Sheet Flooring**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Blue carpet adhesive**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 10/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Blue carpet adhesive**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **2'x2' fissured ceiling tile**

MATERIAL LOCATION: **Rooms 112, 002**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**

DAMAGE QUANTITY: **0**

COMMENTS:

Inspector's Signature: _____



Date: 10/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **2'x2' fissured ceiling tile**
MATERIAL LOCATION: **Rooms 112, 002**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/White Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 332, 333, 324, 327, 227, 226, 233, 136, 130**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/White Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 332, 333, 324, 327, 227, 226, 233, 136, 130**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue w/White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 335, 330, 329, 322, 229, 224, 235, 140, 141, 134, 128**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue w/White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 335, 330, 329, 322, 229, 224, 235, 140, 141, 134, 128**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" White w/Gray Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 334, 335, 332, 333, 330, 331, 328, 326, 324, 327, 322, 325, 320, 225, 222, 222 Storage Room, 227, 229, 231, 224, 226, 233, 228, 235, 140, 138, 136, 141, 134, Main Office Workroom, 133, 131, 132, 130, 128**

MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" White w/Gray Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 334, 335, 332, 333, 330, 331, 328, 326, 324, 327, 322, 325, 320, 225, 222, 222 Storage Room, 227, 229, 231, 224, 226, 233, 228, 235, 140, 138, 136, 141, 134, Main Office Workroom, 133, 131, 132, 130, 128**

MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" Beige w/Brown Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 104, 110**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Dark Blue w/White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 335, 330, 329, 322, 229, 224, 235, 140, 141, 134, 128**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Dark Blue w/White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 335, 330, 329, 322, 229, 224, 235, 140, 141, 134, 128**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12" x 12" Gray and Brown Streaks w/White Floor Tile**
MATERIAL LOCATION: **Room 110**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **2'x4' fissured ceiling tile**
MATERIAL LOCATION: **Room 209**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **2'x4' fissured ceiling tile**
MATERIAL LOCATION: **Room 209**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/White Streaks Floor Tile**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **3** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in 102

Inspector's Signature:



Date: 10/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/White Streaks Floor Tile**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Beige Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 302, 210**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Chalkboard/whiteboard adhesive**

MATERIAL LOCATION: **Rooms 301, 302, 303, 304, 311, 310, 207, 208, 206, 210, 211, 204, 203, 202, 201, 103, 104, 111, 109, 108, 107**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Yellow w/White Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 332, 333, 324, 327, 227, 226, 233, 136, 130**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Yellow w/White Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 332, 333, 324, 327, 227, 226, 233, 136, 130**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" Beige w/Gray Streaks Floor Tile**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Blue speckled laminate sheet flooring**
MATERIAL LOCATION: **Rooms 311, 211**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Mastic for Blue Speckled Laminate Sheet Flooring**

MATERIAL LOCATION: **Rooms 311, 211**

MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Dark Green w/White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 334, 331, 326, 325, 320, 225, 231, 228, 138, 132**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12" x 12" Dark Green w/White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 334, 331, 326, 325, 320, 225, 231, 228, 138, 132**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12" x 12" Dark Green w/White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 334, 331, 326, 325, 320, 225, 231, 228, 138, 132**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12" x 12" White w/Gray Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 334, 335, 332, 333, 330, 331, 328, 326, 324, 327, 322, 325, 320, 225, 222, 222 Storage Room, 227, 229, 231, 224, 226, 233, 228, 235, 140, 138, 136, 141, 134, Main Office Workroom, 133, 132, 131, 130, 128**

MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**

ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12" x 12" White w/Gray Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 334, 335, 332, 333, 330, 331, 328, 326, 324, 327, 322, 325, 320, 225, 222, 222 Storage Room, 227, 229, 231, 224, 226, 233, 228, 235, 140, 138, 136, 141, 134, Main Office Workroom, 133, 132, 131, 130, 128**

MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Gray and Brown Streaks w/White Floor Tile**
MATERIAL LOCATION: **Room 110**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **5** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in 110

Inspector's Signature: _____



Date: 10/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" Gray and Brown Streaks w/White Floor Tile**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 104, 110**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **13** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in 104, 110

Inspector's Signature: _____



Date: 10/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 104, 110**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **13** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Mastic for Blue/Gray Carpet**
MATERIAL LOCATION: **Room 205**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Mastic for Blue/Gray Carpet**

MATERIAL LOCATION: **Room 205**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Mastic for Dark Multi-Coloured Carpet**

MATERIAL LOCATION: **Rooms 220, 222, 223, 135, 137, Main Office, Assistant Principal's Office, Principal's Office, 129**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Not Reachable** DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE REASON:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Mastic for Dark Multi-Coloured Carpet**

MATERIAL LOCATION: **Rooms 220, 222, 223, 135, 137, Main Office, Assistant Principal's Office, Principal's Office, 129**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" Off-White w/Beige Floor Tile**

MATERIAL LOCATION: **Rooms 302, 210**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Wood flooring**

MATERIAL LOCATION: **301, 005, 303, 304, 311, 310, 305, 209, 206, 204, 203, Gym (1900 Building), 202, 201, Auditorium Balcony, Stage, 101, 103, 112, 111, 109, 108, Teacher's Lounge, Teacher's Lounge Storage Room, 004**

MATERIAL QUANTITY: **13200** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**

ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Wood flooring**

MATERIAL LOCATION: **301, 005, 303, 304, 311, 310, 305, 209, 206, 204, 203, Gym (1900 Building), 202, 201, Auditorium Balcony, Stage, 101, 103, 112, 111, 109, 108, Teacher's Lounge, Teacher's Lounge Storage Room, 004**

MATERIAL QUANTITY: **13200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **10/27/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **2' x 4' Fissured Ceiling Tile (2x2 Look)**

MATERIAL LOCATION: **Teacher's Lounge (1900s Building), 333, 332, 334, 335, 330, 331, 328, 326, 324, 329, 327, 322, 325, 320, 225, 220, 227, 229, 223, 222, 231, 224, 226, 233, 228, 235, 140, 136, 141, 134, 137, 135, 133, Main Office (New Building), Assistant Principal's Office (New Building), Principal's Office (New Building), Main Office Workroom (New Building), Main Office Restroom (New Building), 132, 131, 130, 133, 129, 128**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**

ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **2' x 4' Fissured Ceiling Tile (2x2 Look)**

MATERIAL LOCATION: **Teacher's Lounge (1900s Building), 333, 332, 334, 335, 330, 331, 328, 326, 324, 329, 327, 322, 325, 320, 225, 220, 227, 229, 223, 222, 231, 224, 226, 233, 228, 235, 140, 136, 141, 134, 137, 135, 133, Main Office (New Building), Assistant Principal's Office (New Building), Principal's Office (New Building), Main Office Workroom (New Building), Main Office Restroom (New Building), 132, 131, 130, 133, 129, 128**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **11/18/2022**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Gray laminate sheet flooring**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:


Management Planner's Signature: _____



Date: **11/18/2022**

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Ron Brock

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/19/2022

Exam Date: 1/19/2022



Expiration Date: 1/19/2023

Certificate Number: BIR2201190225

Kathy DeSalvo, Director

Ronald Brock

Illinois Licensed Building Inspector, Air Sampling Professional, Asbestos Project Manager





OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER

3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid

training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed