

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2455
SCHOOL NAME: Shields School
ADDRESS OF SCHOOL: 4250 S. Rockwell
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/8/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 12/9/2022 ENROLLMENT 471
IDPH INSPECTOR LICENSE NUMBER: 100-07134
IDPH LICENSED INSPECTOR NAME (Please Print): Ron Brock
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

12/10/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Shields School

4250 S. Rockwell
Chicago, IL, 60632

Unit: 25361
Building ID: 5910

IDPH ID Number: 14-016-2990-2455

REPORT DATE:

Saturday, December 10, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

12/10/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25361 Region: 04 IDPH ID: 14-016-2990-2455

School: Shields School Building ID: 5910

Address: 4250 S. Rockwell

Chicago, IL, 60632

Building Contact: Lara, Toni

Contact Phone: 7737106925

Current Building Owners: Chicago Public Schools

Reinspection Date: 12/9/2022

Review Date: 12/10/2022

Inspector: Ron Brock

Inspector IDPH License: 100-07134

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: December 10, 2022

RE: Shields School, Unit 25361
4250 S. Rockwell
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Shields School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Shields School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Shields School Unit: 25361 Region: 04
Address: 4250 S. Rockwell Chicago, IL, 60632
IDPH ID: 14-016-2990-2455 Building ID: 5910
Contact: Lara, Toni Phone: 7737106925

2. Description of Facility

Original Construction: 1911 Additional Construction: 1902
Total Square Footage: 41300 No of Floors: 3
Current Occupancy: 471

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Ron Brock


Inspector IDPH license # 100-07134
Reinspection Date: 12/9/2022


Signature:
Date: 12/9/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


Signature:
Date: 12/10/2022

7. Review Date: 12/10/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature:

Date: 12/10/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Shields School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5910:

42	2' x 4' Lay In Ceiling Panels
58	2' x 4' Lay In Ceiling Tile
66	Spray-on fireproofing
78	Tan w/Streaks Laminate Sheet Flooring
79	Mastic for Tan w/Streaks Laminate Sheet Flooring
80	Wood flooring
81	12" x 12" Light Blue Grayish Floor Tile
82	Mastic for 12" x 12" Light Blue Grayish Floor Tile
83	12" x 12" Dark Blue w/Blue Streaks Floor Tile

- 84 Mastic for 12" x 12" Dark Blue w/Blue Streaks Floor Tile
- 85 Mastic for Dark Multicolored Carpet
- 86 12" x 12" Blue Speckled Floor Tile
- 87 12" x 12" Blue Speckled Floor Tile Mastic
- L Cementitious Pipe Fittings off FG Pipe Insulation
- S Cementitious Fittings off Cardboard Pipe Runs

B. The following new homogenous areas have been identified for Building 5910:

78	Tan w/Streaks Laminate Sheet Flooring
79	Mastic for Tan w/Streaks Laminate Sheet Flooring
80	Wood flooring
81	12" x 12" Light Blue Grayish Floor Tile
82	Mastic for 12" x 12" Light Blue Grayish Floor Tile
83	12" x 12" Dark Blue w/Blue Streaks Floor Tile
84	Mastic for 12" x 12" Dark Blue w/Blue Streaks Floor Tile
85	Mastic for Dark Multicolored Carpet
86	12" x 12" Blue Speckled Floor Tile
87	12" x 12" Blue Speckled Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10	12" x 12" Off-White Floor Tile w/Brown Specks
12	12" x 12" Brown Speckled Floor Tile
13	12" x 12" Blue Floor Tile w/White Specks
14	12" x 12" White Floor Tile w/Brown Streaks
15	12" x 12" Off-White Floor Tile w/Gray Streaks
18	12" x 12" Mauve Floor Tile
21	12" x 12" Off-White Floor Tile w/Gray Specks
34	Vibration Collars on Duct (2)
35	Blue carpet mastic
36	Blue Carpet Mastic - Replaced w/ HA 76/77
37	Ceiling material
38	Adhesive Behind Chalk Boards and Bulletin Boards
39	Coating on Bottoms of Sinks
4	9" x 9" Brown Speckled Floor Tile
40	Coating on Bottoms of Sinks
41	Drywall
42	2' x 4' Lay In Ceiling Panels
43	4" Brown vinyl baseboard
44	4" Brown vinyl baseboard adhesive
45	Drywall
46	Drywall, Tape and Joint Compound
47	Adhesive Behind Chalk Boards and Bulletin Boards
48	Adhesive Behind Chalk Boards and Bulletin Boards
49	12" x 12" White Floor Tile w/Gray Streaks
5	9" x 9" Brown Speckled Floor Tile Mastic
50	12" x 12" White Floor Tile w/Gray Streaks Mastic
51	12" x 12" Dark Gray Mix Floor Tile
52	12" x 12" Dark Gray Mix Floor Tile Mastic
53	4" Gray vinyl baseboard
54	4" Gray vinyl baseboard adhesive
55	Drywall
56	Drywall joint compound
57	Brown carpet mastic
58	2' x 4' Lay In Ceiling Tile
59	Interior brick
60	Interior brick mortar
61	Elevator brake shoes
62	Chalk Board and Bulletin Board Adhesive
63	Interior window caulk
64	Coating on Bottoms of Sinks
65	Interior door caulk
66	Spray-on fireproofing

67	Duct caulk
68	Stair treads
69	Stair tread adhesive
70	Cinderblock
71	Cinderblock mortar
72	Blue glazed brick
73	Blue glazed brick mortar
74	Green glazed brick
75	Green glazed brick mortar
76	12" x 12" White w/ Brown Streaks Floor Tile
77	12" x 12" White w/ Brown Streaks Floor Tile Mastic
78	Tan w/Streaks Laminate Sheet Flooring
79	Mastic for Tan w/Streaks Laminate Sheet Flooring
80	Wood flooring
81	12" x 12" Light Blue Grayish Floor Tile
82	Mastic for 12" x 12" Light Blue Grayish Floor Tile
83	12" x 12" Dark Blue w/Blue Streaks Floor Tile
84	Mastic for 12" x 12" Dark Blue w/Blue Streaks Floor Tile
85	Mastic for Dark Multicolored Carpet
86	12" x 12" Blue Speckled Floor Tile
87	12" x 12" Blue Speckled Floor Tile Mastic
9	12" x 12" White Floor Tile w/Brown Streaks
9 A	12" x 12" White Floor Tile w/Brown Streaks Mastic

The following areas were deemed to be inaccessible:

35	Blue carpet mastic
38	Adhesive Behind Chalk Boards and Bulletin Boards
44	4" Brown vinyl baseboard adhesive
47	Adhesive Behind Chalk Boards and Bulletin Boards
48	Adhesive Behind Chalk Boards and Bulletin Boards
50	12" x 12" White Floor Tile w/Gray Streaks Mastic
54	4" Gray vinyl baseboard adhesive
55	Drywall
57	Brown carpet mastic
62	Chalk Board and Bulletin Board Adhesive
69	Stair tread adhesive
7 A	12" x 12" Beige Floor Tile w/Brown Specks Mastic
77	12" x 12" White w/ Brown Streaks Floor Tile Mastic
78	Tan w/Streaks Laminate Sheet Flooring
79	Mastic for Tan w/Streaks Laminate Sheet Flooring
82	Mastic for 12" x 12" Light Blue Grayish Floor Tile
84	Mastic for 12" x 12" Dark Blue w/Blue Streaks Floor Tile
85	Mastic for Dark Multicolored Carpet

9 A

12" x 12" White Floor Tile w/Brown Streaks Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Ron Brock, IDPH License # 100-07134. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Shields School Building 5910 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Shields School Unit 25361 Building ID 5910

Address 4250 S. Rockwell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
20	Drywall tape/mud			East Mobile Unit	NO_ACBM	MISC								
21	12" x 12" Off-White Floor Tile w/Gray Specks	1,600	SF	West Mobile Unit	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
21 A	12" x 12" Off-White Floor Tile w/Gray Specks Mastic			West Mobile Unit	NO_ACBM	MISC								
22	Brown linoleum			Room 307	NO_ACBM	MISC								
23	Brown linoleum (beneath carpet)			Room 207	NO_ACBM	MISC								
24	Red attic paper			Attic	NO_ACBM	MISC								
25	Brown floor tile (beneath carpet)		SF	Room 108	CHR	MISC				SF				
25 A	Brown floor tile mastic (beneath carpet)		SF	Room 108	CHR	MISC				SF				
26	Brown floor tile (beneath carpet)		SF	Room 107	CHR	MISC				SF				
26 A	Brown floor tile mastic (beneath carpet)		SF	Room 107	CHR	MISC				SF				
27	Black baseboard			Basement	NO_ACBM	MISC								
27 A	Black baseboard mastic			Basement	NO_ACBM	MISC								
28	Building brick mortar - removed			Exterior of Building	ABATED	MISC								
29	Miscellaneous white round sheet goods			Boiler Room - REMOVED	ABATED	MISC								
3	Wall plaster			Throughout Facility	NO_ACBM	SURFACE								
30	Roof flashing - Non-AHERA			Roof	CHR	MISC								
31	Roof fields - Non-AHERA			Roof	NO_ACBM	MISC								
32	4" Brown vinyl baseboard			Basement Corridors	NO_ACBM	MISC								
33	4" Brown vinyl baseboard adhesive			Basement Corridors	NO_ACBM	MISC								
34	Vibration Collars on Duct (2)	16	LF	Corridor Outside Room 214	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
35	Blue carpet mastic	500	SF	Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
36	Blue Carpet Mastic - Replaced w/ HA 76/77			Library	ASSUMED	MISC								
37	Ceiling material		SF	Electric Room	ASSUMED	MISC				SF				
38	Adhesive Behind Chalk Boards and Bulletin Boards	2,000	SF	Throughout Facility	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
39	Coating on Bottoms of Sinks	6	SF	East Mobile Unit	ASSUMED	SURFACE	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
4	9" x 9" Brown Speckled Floor Tile		SF	212 (Beneath 12" x 12" Floor Tile)	ASSUMED	MISC				SF				
40	Coating on Bottoms of Sinks	6	SF	West Mobile Unit	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
41	Drywall	1,200	SF	East Mobile Unit	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
42	2' x 4' Lay In Ceiling Panels	2,250	SF	East Mobile Unit	ASSUMED	MISC	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
43	4" Brown vinyl baseboard	200	LF	West Mobile Unit	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the		LOW

Chicago Public Schools

School Shields School Unit 25361 Building ID 5910

Address 4250 S. Rockwell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
44	4" Brown vinyl baseboard adhesive	200	LF	West Mobile Unit	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
45	Drywall	1,800	SF	West Mobile Unit	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
46	Drywall, Tape and Joint Compound	1,800	SF	West Mobile Unit	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
47	Adhesive Behind Chalk Boards and Bulletin Boards	250	SF	East Mobile Unit	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
48	Adhesive Behind Chalk Boards and Bulletin Boards	250	SF	West Mobile Unit	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
49	12" x 12" White Floor Tile w/Gray Streaks	32,000	SF	Throughout 1996 Addition, 320, 321, 322, 325, 324, 2nd Fl Hallway, 226, 225, 224, 227, 222, 221, 220, 121, 122, Lunchroom (125), 123, 124	ASSUMED	MISC	N	DIST	15	SF	No	ACBM with the potential for damage	5	LOW
5	9" x 9" Brown Speckled Floor Tile Mastic		SF	Room 212 (Beneath 12" x 12" Floor Tile)	ASSUMED	MISC				SF				
50	12" x 12" White Floor Tile w/Gray Streaks Mastic	32,000	SF	Throughout 1996 Addition, 320, 321, 322, 325, 324, 2nd Fl Hallway, 226, 225, 224, 227, 222, 221, 220, 121, 122, Lunchroom (125), 123, 124	ASSUMED	MISC	N	DIST	15	SF	No	ACBM with the potential for damage	5	LOW
51	12" x 12" Dark Gray Mix Floor Tile		SF	3rd Fl Hallways (Annex), 2nd Fl Hallway (Annex), 1st Fl Hallway (Annex)	ASSUMED	MISC				SF				
52	12" x 12" Dark Gray Mix Floor Tile Mastic		SF	3rd Fl Hallway (Annex), 2nd Fl Hallway (Annex), 1st Fl Hallway (Annex)	ASSUMED	MISC				SF				
53	4" Gray vinyl baseboard	4,000	LF	Throughout 1996 Addition	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
54	4" Gray vinyl baseboard adhesive	4,000	LF	Throughout 1996 Addition	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Shields School Unit 25361 Building ID 5910

Address 4250 S. Rockwell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
55	Drywall	10,000	SF	Office and Walls Between Classrooms, throughout basement areas	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
56	Drywall joint compound	3,000	SF	Office and Walls Between Classrooms, throughout basement areas	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
57	Brown carpet mastic	500	SF	Main Office, (Annex)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
58	2' x 4' Lay In Ceiling Tile	30,000	SF	Throughout 1996 Addition	ASSUMED	MISC	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
59	Interior brick	10,000	SF	Throughout 1996 Addition Corridors	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
6	12" x 12" Brown Floor Tile w/White & Black Specks			3rd Floor Corridor	ABATED	MISC								
6 A	12" x 12" Brown Floor Tile w/White & Blk Spks Mastic			3rd Floor Corridor	ABATED	MISC								
60	Interior brick mortar	10,000	SF	Throughout 1996 Addition Corridors	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
61	Elevator brake shoes		SF	1st Floor Corridor of 1996 Addition	ASSUMED	MISC				SF				
62	Chalk Board and Bulletin Board Adhesive	3,000	SF	Classrooms in 1996 Addition	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
63	Interior window caulk	30,000	LF	Throughout 1996 Addition	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
64	Coating on Bottoms of Sinks	80	SF	Throughout 1996 Addition Classrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
65	Interior door caulk	300	LF	Throughout 1996 Addition	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
66	Spray-on fireproofing	12,000	SF	Basement: Mechanical Areas	ASSUMED	SURFACE	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
67	Duct caulk	200	LF	3rd Floor Mechanical Room of 1996 Addition	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
68	Stair treads	1,500	SF	Throughout 1996 Addition Stairways	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
69	Stair tread adhesive	1,500	SF	Throughout 1996 Addition Stairways	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Shields School Unit 25361 Building ID 5910

Address 4250 S. Rockwell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
7	12" x 12" Beige Floor Tile w/Brown Specks	600	SF	3rd Floor Corridor	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
7 A	12" x 12" Beige Floor Tile w/Brown Specks Mastic	600	SF	3rd Floor Corridor	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
70	Cinderblock	10,000	SF	Throughout 1996 Addition	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
71	Cinderblock mortar	10,000	SF	Throughout 1996 Addition	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
72	Blue glazed brick	1,300	SF	Throughout 1996 Addition Men's & Boy's Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
73	Blue glazed brick mortar	1,300	SF	Throughout 1996 Addition Men's & Boy's Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
74	Green glazed brick	1,300	SF	Throughout 1996 Addition Women's & Girl's Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
75	Green glazed brick mortar	1,000	SF	Throughout 1996 Addition Women's & Girl's Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
76	12" x 12" White w/ Brown Streaks Floor Tile	1,350	SF	Library	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
77	12" x 12" White w/ Brown Streaks Floor Tile Mastic	1,350	SF	Library	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
78	Tan w/Streaks Laminate Sheet Flooring	4,000	SF	Gymnasium	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
79	Mastic for Tan w/Streaks Laminate Sheet Flooring	4,000	SF	Gymnasium	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
8	12" x 12" Yellow Floor Tile w/Brown Specks			Assembly Hall	ABATED	MISC								
8 A	12" x 12" Yellow Floor Tile w/Brown Specks Mastic			Assembly Hall	ABATED	MISC								
80	Wood flooring	15,000	SF	3rd Fl Hallway, 309, 310, 307, 305, 306, 304, 303, 302, 301, 201, 202, 204, 203, 206, 205, IDF Room (208), 209, 211, 213, 214, 102, 104, 103, 106, 110, B13, Auditorium	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
81	12" x 12" Light Blue Grayish Floor Tile	800	SF	Basement, 101, 102	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
82	Mastic for 12" x 12" Light Blue Grayish	800	SF	Basement, 101, 102	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the		LOW

Chicago Public Schools

School Shields School Unit 25361 Building ID 5910

Address 4250 S. Rockwell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 12/9/2022
Inspector Name Ron Brock
100-07134 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	Damage in 310 Storage
10	Damage in 212, Outside 215, Outside 104
10 A	Damage outside 215, 212, outside 104
11	
11 A	
12	
12 A	
13	Damage in Main Office, Main Office Restroom
13 A	Damage in Main Office, Main Office Restroom
14	
14 A	
15	Not observed 2022
15 A	
16	
17	
18	
18 A	
2	Damage in Gymnasium
20	
21	
21 A	
22	
23	
24	

Chicago Public Schools

School Shields School Unit 25361 Building ID 5910

Address 4250 S. Rockwell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
25	Not observed 2022
25 A	Not observed 2022
26	Not observed 2022
26 A	Not observed 2022
27	
27 A	
28	
29	
3	Damage in Gymnasium
30	
31	
32	
33	
34	
35	
36	Not observed 2022
37	Not observed 2022
38	
39	
4	Not observed 2022
40	
41	
42	
43	
44	
45	
46	
47	
48	

Chicago Public Schools

School Shields School Unit 25361 Building ID 5910

Address 4250 S. Rockwell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
49	Damage in 224, 124
5	Not observed 2022
50	Damage in 224, 124
51	Not observed 2022
52	Not observed 2022
53	
54	
55	
56	
57	
58	
59	
6	
6 A	
60	
61	Not observed 2022
62	
63	
64	
65	
66	
67	
68	
69	
7	
7 A	
70	
71	
72	

Chicago Public Schools

School Shields School Unit 25361 Building ID 5910

Address 4250 S. Rockwell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
73	
74	
75	
76	
77	
78	
79	
8	
8 A	
80	
81	
82	
83	
84	
85	
86	
87	
9	Damage located on 2nd floor
9 A	Damage located on 2nd floor
A	
B	
I	
J	
K	
L	
N	Not observed 2022
O	Not observed 2022
R	Not observed 2022
S	

Chicago Public Schools

School Shields School Unit 25361 Building ID 5910

Address 4250 S. Rockwell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
T	

Table II

Management Planner's Review

Chicago Public Schools

School Shields School

Unit 25361

Building ID 5910

Address 4250 S. Rockwell

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	2' x 4' Lay In Ceiling Panels			Throughout Facility, 309, 310, 307, 305, 306, 205, 206, 207, 210, 209, 212, 208, 107, 108, 110, 106, B15, Lunchroom	No ACBM	MISC					
10	12" x 12" Off-White Floor Tile w/Brown Specks	5,500	SF	Lunchroom, 3rd Fl Hallway, 2nd Fl Hallway, 210, 212, 1st Fl Hallway, Basement, B12	Assumed	MISC	No	38	SF	6 ACBM with the potential for damage	Repair
10 A	12" x 12" Off-White Floor Tile w/Brown Specks Mastic			Lunchroom, 3rd Fl Hallway, 2nd Fl Hallway, 210, 212, 1st Fl Hallway, Basement, B12	No ACBM	MISC					
11	Rubber stair covering			West Basement Stairs	No ACBM	MISC					
11 A	Rubber stair covering mastic			West Basement Stairs	No ACBM	MISC					
12	12" x 12" Brown Speckled Floor Tile	1,600	SF	Rooms 210, 101, and 109, B15	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12 A	12" x 12" Brown Speckled Floor Tile Mastic			Rooms 210, 101, and 109, B15	No ACBM	MISC					
13	12" x 12" Blue Floor Tile w/White Specks	700	SF	Office	Assumed	MISC	No	46	SF	6 ACBM with the potential for damage	Repair
13 A	12" x 12" Blue Floor Tile w/White Specks Mastic			Office	No ACBM	MISC					
14	12" x 12" White Floor Tile w/Brown Streaks	600	SF	3rd Fl Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14 A	12" x 12" White Floor Tile w/Brown Streaks Mastic			Room 212	No ACBM	MISC					
15	12" x 12" Off-White Floor Tile w/Gray Streaks		SF	Gym	Assumed	MISC			SF		Follow O&M Plan
15 A	12" x 12" Off-White Floor Tile w/Gray Streaks Mastic			Gym	No ACBM	MISC					
16	Purple carpet mastic			Rooms 307, 207, 107, and 108, 207, 215, 107, 108	No ACBM	MISC					
17	Miscellaneous blue board- removed			Basement	Abated	MISC					
18	12" x 12" Mauve Floor Tile	1,600	SF	East Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18 A	12" x 12" Mauve Floor Tile Mastic			East Mobile Unit	No ACBM	MISC					
2	Ceiling plaster			Throughout Facility	No ACBM	SURFACE					
20	Drywall tape/mud			East Mobile Unit	No ACBM	MISC					
21	12" x 12" Off-White Floor Tile w/Gray Specks	1,600	SF	West Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21 A	12" x 12" Off-White Floor Tile w/Gray Specks Mastic			West Mobile Unit	No ACBM	MISC					
22	Brown linoleum			Room 307	No ACBM	MISC					
23	Brown linoleum (beneath carpet)			Room 207	No ACBM	MISC					
24	Red attic paper			Attic	No ACBM	MISC					
25	Brown floor tile (beneath carpet)		SF	Room 108	Chrysotile	MISC			SF		Follow O&M Plan

Chicago Public Schools

School Shields School
Address 4250 S. Rockwell

Unit 25361
Chicago, IL, 60632

Building ID 5910
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
25 A	Brown floor tile mastic (beneath carpet)		SF	Room 108	Chrysotile	MISC			SF		Follow O&M Plan
26	Brown floor tile (beneath carpet)		SF	Room 107	Chrysotile	MISC			SF		Follow O&M Plan
26 A	Brown floor tile mastic (beneath carpet)		SF	Room 107	Chrysotile	MISC			SF		Follow O&M Plan
27	Black baseboard			Basement	No ACBM	MISC					
27 A	Black baseboard mastic			Basement	No ACBM	MISC					
28	Building brick mortar - removed			Exterior of Building	Abated	MISC					
29	Miscellaneous white round sheet goods			Boiler Room - REMOVED	Abated	MISC					
3	Wall plaster			Throughout Facility	No ACBM	SURFACE					
30	Roof flashing - Non-AHERA			Roof	Chrysotile	MISC					Follow O&M Plan
31	Roof fields - Non-AHERA			Roof	No ACBM	MISC					
32	4" Brown vinyl baseboard			Basement Corridors	No ACBM	MISC					
33	4" Brown vinyl baseboard adhesive			Basement Corridors	No ACBM	MISC					
34	Vibration Collars on Duct (2)	16	LF	Corridor Outside Room 214	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
35	Blue carpet mastic	500	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Blue Carpet Mastic - Replaced w/ HA 76/77			Library	Assumed	MISC					Follow O&M Plan
37	Ceiling material		SF	Electric Room	Assumed	MISC			SF		Follow O&M Plan
38	Adhesive Behind Chalk Boards and Bulletin Boards	2,000	SF	Throughout Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Coating on Bottoms of Sinks	6	SF	East Mobile Unit	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4	9" x 9" Brown Speckled Floor Tile		SF	212 (Beneath 12"x12" Floor Tile)	Assumed	MISC			SF		Follow O&M Plan
40	Coating on Bottoms of Sinks	6	SF	West Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Drywall	1,200	SF	East Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	2' x 4' Lay In Ceiling Panels	2,250	SF	East Mobile Unit	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
43	4" Brown vinyl baseboard	200	LF	West Mobile Unit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
44	4" Brown vinyl baseboard adhesive	200	LF	West Mobile Unit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
45	Drywall	1,800	SF	West Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Drywall, Tape and Joint Compound	1,800	SF	West Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Adhesive Behind Chalk Boards and Bulletin Boards	250	SF	East Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Adhesive Behind Chalk Boards and Bulletin Boards	250	SF	West Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12" x 12" White Floor Tile w/Gray Streaks	32,000	SF	Throughout 1996 Addition, 320, 321, 322, 325, 324, 2nd Fl Hallway, 226, 225, 224, 227, 222, 221, 220, 121, 122, Lunchroom (125), 123, 124	Assumed	MISC	No	15	SF	6 ACBM with the potential for damage	Repair
5	9" x 9" Brown Speckled Floor Tile Mastic		SF	Room 212 (Beneath 12"x12" Floor Tile)	Assumed	MISC			SF		Follow O&M Plan

Chicago Public Schools

School Shields School
Address 4250 S. Rockwell

Unit 25361
Chicago, IL, 60632

Building ID 5910
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
50	12" x 12" White Floor Tile w/Gray Streaks Mastic	32,000	SF	Throughout 1996 Addition, 320, 321, 322, 325, 324, 2nd Fl Hallway, 226, 225, 224, 227, 222, 221, 220, 121 122, Lunchroom (125), 123, 124	Assumed	MISC	No	15	SF	6 ACBM with the potential for damage	Repair
51	12" x 12" Dark Gray Mix Floor Tile		SF	3rd Fl Hallways (Annex), 2nd Fl Hallway (Annex), 1st Fl Hallway (Annex)	Assumed	MISC			SF		Follow O&M Plan
52	12" x 12" Dark Gray Mix Floor Tile Mastic		SF	3rd Fl Hallway (Annex), 2nd Fl Hallway (Annex), 1st Fl Hallway (Annex)	Assumed	MISC			SF		Follow O&M Plan
53	4" Gray vinyl baseboard	4,000	LF	Throughout 1996 Addition	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
54	4" Gray vinyl baseboard adhesive	4,000	LF	Throughout 1996 Addition	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
55	Drywall	10,000	SF	Office and Walls Between Classrooms, throughout basement areas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Drywall joint compound	3,000	SF	Office and Walls Between Classrooms, throughout basement areas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Brown carpet mastic	500	SF	Main Office, (Annex)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	2' x 4' Lay In Ceiling Tile	30,000	SF	Throughout 1996 Addition	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
59	Interior brick	10,000	SF	Throughout 1996 Addition Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	12" x 12" Brown Floor Tile w/White & Black Specks			3rd Floor Corridor	Abated	MISC					
6 A	12" x 12" Brown Floor Tile w/White & Blk Spks Mastic			3rd Floor Corridor	Abated	MISC					
60	Interior brick mortar	10,000	SF	Throughout 1996 Addition Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Elevator brake shoes		SF	1st Floor Corridor of 1996 Addition	Assumed	MISC			SF		Follow O&M Plan
62	Chalk Board and Bulletin Board Adhesive	3,000	SF	Classrooms in 1996 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Interior window caulk	30,000	LF	Throughout 1996 Addition	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
64	Coating on Bottoms of Sinks	80	SF	Throughout 1996 Addition Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Interior door caulk	300	LF	Throughout 1996 Addition	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
66	Spray-on fireproofing	12,000	SF	Basement: Mechanical Areas	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
67	Duct caulk	200	LF	3rd Floor Mechanical Room of 1996 Addition	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
68	Stair treads	1,500	SF	Throughout 1996 Addition Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	Stair tread adhesive	1,500	SF	Throughout 1996 Addition Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7	12" x 12" Beige Floor Tile w/Brown Specks	600	SF	3rd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7 A	12" x 12" Beige Floor Tile w/Brown Specks Mastic	600	SF	3rd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Shields School
Address 4250 S. Rockwell

Unit 25361
Chicago, IL, 60632

Building ID 5910
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
70	Cinderblock	10,000	SF	Throughout 1996 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Cinderblock mortar	10,000	SF	Throughout 1996 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Blue glazed brick	1,300	SF	Throughout 1996 Addition Men's & Boy's Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Blue glazed brick mortar	1,300	SF	Throughout 1996 Addition Men's & Boy's Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	Green glazed brick	1,300	SF	Throughout 1996 Addition Women's & Girl's Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	Green glazed brick mortar	1,000	SF	Throughout 1996 Addition Women's & Girl's Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12" x 12" White w/ Brown Streaks Floor Tile	1,350	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	12" x 12" White w/ Brown Streaks Floor Tile Mastic	1,350	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	Tan w/Streaks Laminate Sheet Flooring	4,000	SF	Gymnasium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	Mastic for Tan w/Streaks Laminate Sheet Flooring	4,000	SF	Gymnasium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	12" x 12" Yellow Floor Tile w/Brown Specks			Assembly Hall	Abated	MISC					
8 A	12" x 12" Yellow Floor Tile/Brown Specks Mastic			Assembly Hall	Abated	MISC					
80	Wood flooring	15,000	SF	3rd Fl Hallway, 309, 310, 307, 305, 306, 304, 303, 302, 301, 201, 202, 204, 203, 206, 205, IDF Room (208), 209, 211, 213, 214, 102, 104, 103, 106, 110, B13, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12" x 12" Light Blue Grayish Floor Tile	800	SF	Basement, 101, 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	Mastic for 12" x 12" Light Blue Grayish Floor Tile	800	SF	Basement, 101, 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12" x 12" Dark Blue w/Blue Streaks Floor Tile	650	SF	Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Mastic for 12" x 12" Dark Blue w/Blue Streaks Floor Tile	500	SF	Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	Mastic for Dark Multicolored Carpet	800	SF	Library (323), 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" Blue Speckled Floor Tile	50	SF	Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12" x 12" Blue Speckled Floor Tile Mastic	50	SF	Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9	12" x 12" White Floor Tile w/Brown Streaks	2,280	SF	Basement, 2nd Floor Stairs, 3rd Floor Corridor	Assumed	MISC	No	80	SF	6 ACBM with the potential for damage	Repair
9 A	12" x 12" White Floor Tile w/Brown Streaks Mastic	2,280	SF	Basement, 2nd Floor Stairs, 3rd Floor Corridor	Assumed	MISC	No	80	SF	6 ACBM with the potential for damage	Repair
A	Boiler insulation			Boiler Room	Abated	MISC					
B	Suspended mag tank (hot water)			Boiler Room	Abated	MISC					
I	Mag Block Pipe Insulation on Steam Supply			Boiler Room	Abated	TSI					

Chicago Public Schools

School Shields School
Address 4250 S. Rockwell

Unit 25361
 Chicago, IL, 60632

Building ID 5910
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
J	Cementitious Pipe Fittings off Steam Line			Boiler Room	Abated	TSI					
K	Plenum Caulking in Air Chamber			WaRoom Air Chamber in Basement	Abated	MISC					
L	Cementitious Pipe Fittings off FG Pipe Insulation	60	LF	Tank Room, Boiler Room, Hall by Tank Room, Lunchroom, Boys and Girls Bathroom.	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
N	Aircell pipe insulation			Basement	Chrysotile	TSI					Follow O&M Plan
O	Cementitious Pipe Fittings off Aircell Pipe Runs			Basement, 1st Floor Corridor	Chrysotile	TSI					Follow O&M Plan
R	Cardboard pipe insulation			Basement	Chrysotile	TSI					Follow O&M Plan
S	Cementitious Fittings off Cardboard Pipe Runs	60	LF	Basement	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
T	Cementitious valve headers - abated 1998			Basement Tank Headers	Abated	MISC					

Chicago Public Schools

School Shields School
Address 4250 S. Rockwell

Unit 25361
 Chicago, IL, 60632

Building ID 5910
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	12/10/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
10 A	
11	
11 A	
12	
12 A	
13	
13 A	
14	
14 A	
15	
15 A	
16	
17	
18	
18 A	
2	
20	
21	
21 A	
22	
23	
24	

Chicago Public Schools

School Shields School
Address 4250 S. Rockwell

Unit 25361
 Chicago, IL, 60632

Building ID 5910
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
25	
25 A	
26	
26 A	
27	
27 A	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	

Chicago Public Schools

School Shields School
Address 4250 S. Rockwell

Unit 25361
Chicago, IL, 60632

Building ID 5910
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
47	
48	
49	
5	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
6	
6 A	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	

Chicago Public Schools

School Shields School
Address 4250 S. Rockwell

Unit 25361
 Chicago, IL, 60632

Building ID 5910
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
7 A	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
8	
8 A	
80	
81	
82	
83	
84	
85	
86	
87	
9	
9 A	
A	
B	
I	
J	

Chicago Public Schools

School Shields School
Address 4250 S. Rockwell

Unit 25361
Chicago, IL, 60632

Building ID 5910
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
K	
L	
N	
O	
R	
S	
T	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility, 309, 310, 307, 305, 306, 205, 206, 207, 210, 209, 212, 208, 107, 108, 110, 106, B15, Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Damage in 310 Storage**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
MATERIAL LOCATION: **Throughout Facility, 309, 310, 307, 305, 306, 205, 206, 207, 210, 209, 212, 208, 107, 108, 110, 106, B15, Lunchroom**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brown Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, 3rd FI Hallway, 2nd FI Hallway, 210, 212, 1st FI Hallway, Basement, B12**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in 212, Outside 215, Outside 104**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brown Specks**
MATERIAL LOCATION: **Lunchroom, 3rd FI Hallway, 2nd FI Hallway, 210, 212, 1st FI Hallway, Basement, B12**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **38** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10 A**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brown Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, 3rd FI Hallway, 2nd FI Hallway, 210, 212, 1st FI Hallway, Basement, B12**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Damage outside 215, 212, outside 104**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **10 A**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brown Specks Mastic**
MATERIAL LOCATION: **Lunchroom, 3rd FI Hallway, 2nd FI Hallway, 210, 212, 1st FI Hallway, Basement, B12**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Rubber stair covering**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Basement Stairs**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Rubber stair covering**

MATERIAL LOCATION: **West Basement Stairs**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11 A**
MATERIAL DESCRIPTION: **Rubber stair covering mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Basement Stairs**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **11 A**

MATERIAL DESCRIPTION: **Rubber stair covering mastic**

MATERIAL LOCATION: **West Basement Stairs**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 210, 101, and 109, B15**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**
MATERIAL LOCATION: **Rooms 210, 101, and 109, B15**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12 A**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 210, 101, and 109, B15**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **12 A**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 210, 101, and 109, B15**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile w/White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Main Office, Main Office Restroom**

Inspector's Signature: _____



Date: 12/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile w/White Specks**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **46**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 A**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile w/White Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Damage in Main Office, Main Office Restroom**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **13 A**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile w/White Specks Mastic**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd FI Hallway**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Brown Streaks**
MATERIAL LOCATION: **3rd FI Hallway**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 A**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **14 A**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Brown Streaks Mastic**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Gray Streaks**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15 A**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **15 A**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Gray Streaks Mastic**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Purple carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 307, 207, 107, and 108, 207, 215, 107, 108**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Purple carpet mastic**

MATERIAL LOCATION: **Rooms 307, 207, 107, and 108, 207, 215, 107, 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Miscellaneous blue board- removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Miscellaneous blue board- removed**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12" x 12" Mauve Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **East Mobile Unit**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Mauve Floor Tile**

MATERIAL LOCATION: **East Mobile Unit**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 A**
MATERIAL DESCRIPTION: **12" x 12" Mauve Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East Mobile Unit**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **18 A**

MATERIAL DESCRIPTION: **12" x 12" Mauve Floor Tile Mastic**

MATERIAL LOCATION: **East Mobile Unit**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **Ceiling plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Damage in Gymnasium**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **Ceiling plaster**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Drywall tape/mud**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East Mobile Unit**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Drywall tape/mud**

MATERIAL LOCATION: **East Mobile Unit**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Gray Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West Mobile Unit**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Gray Specks**

MATERIAL LOCATION: **West Mobile Unit**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21 A**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Gray Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Mobile Unit**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **21 A**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Gray Specks Mastic**

MATERIAL LOCATION: **West Mobile Unit**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Brown linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Brown linoleum**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Brown linoleum (beneath carpet)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Brown linoleum (beneath carpet)**

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Red attic paper**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Red attic paper**

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Brown floor tile (beneath carpet)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Brown floor tile (beneath carpet)**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25 A**
MATERIAL DESCRIPTION: **Brown floor tile mastic (beneath carpet)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **25 A**

MATERIAL DESCRIPTION: **Brown floor tile mastic (beneath carpet)**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Brown floor tile (beneath carpet)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Brown floor tile (beneath carpet)**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26 A**
MATERIAL DESCRIPTION: **Brown floor tile mastic (beneath carpet)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **26 A**

MATERIAL DESCRIPTION: **Brown floor tile mastic (beneath carpet)**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Black baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Black baseboard**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27 A**
MATERIAL DESCRIPTION: **Black baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **27 A**

MATERIAL DESCRIPTION: **Black baseboard mastic**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Building brick mortar - removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Building brick mortar - removed**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Miscellaneous white round sheet goods**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - REMOVED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Miscellaneous white round sheet goods**

MATERIAL LOCATION: **Boiler Room - REMOVED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **Wall plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Damage in Gymnasium**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Wall plaster**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Roof fields - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Roof fields - Non-AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**

MATERIAL LOCATION: **Basement Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**

MATERIAL LOCATION: **Basement Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Vibration Collars on Duct (2)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor Outside Room 214**

MATERIAL QUANTITY: **16**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Vibration Collars on Duct (2)**

MATERIAL LOCATION: **Corridor Outside Room 214**

MATERIAL QUANTITY: **16**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Blue carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Blue carpet mastic**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Blue Carpet Mastic - Replaced w/ HA 76/77**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Blue Carpet Mastic - Replaced w/ HA 76/77**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Ceiling material**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Electric Room**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Ceiling material**

MATERIAL LOCATION: **Electric Room**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Adhesive Behind Chalk Boards and Bulletin Boards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Adhesive Behind Chalk Boards and Bulletin Boards**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Coating on Bottoms of Sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **East Mobile Unit**

MATERIAL QUANTITY: **6**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Coating on Bottoms of Sinks**

MATERIAL LOCATION: **East Mobile Unit**

MATERIAL QUANTITY: **6**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **9" x 9" Brown Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **212 (Beneath 12"x12" Floor Tile)**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **9" x 9" Brown Speckled Floor Tile**

MATERIAL LOCATION: **212 (Beneath 12"x12" Floor Tile)**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Coating on Bottoms of Sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West Mobile Unit**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Coating on Bottoms of Sinks**

MATERIAL LOCATION: **West Mobile Unit**

MATERIAL QUANTITY: **6**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **East Mobile Unit**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **East Mobile Unit**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **East Mobile Unit**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
MATERIAL LOCATION: **East Mobile Unit**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West Mobile Unit**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
MATERIAL LOCATION: **West Mobile Unit**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West Mobile Unit**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**

MATERIAL LOCATION: **West Mobile Unit**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West Mobile Unit**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **West Mobile Unit**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Drywall, Tape and Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West Mobile Unit**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Drywall, Tape and Joint Compound**

MATERIAL LOCATION: **West Mobile Unit**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Adhesive Behind Chalk Boards and Bulletin Boards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **East Mobile Unit**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Adhesive Behind Chalk Boards and Bulletin Boards**

MATERIAL LOCATION: **East Mobile Unit**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Adhesive Behind Chalk Boards and Bulletin Boards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **West Mobile Unit**

MATERIAL QUANTITY: **250**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Adhesive Behind Chalk Boards and Bulletin Boards**

MATERIAL LOCATION: **West Mobile Unit**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Addition, 320, 321, 322, 325, 324, 2nd FI Hallway, 226, 225, 224, 227, 222, 221, 220, 121, 122, Lunchroom (125), 123, 124**
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in 224, 124**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks**
MATERIAL LOCATION: **Throughout 1996 Addition, 320, 321, 322, 325, 324, 2nd FI Hallway, 226, 225, 224, 227, 222, 221, 220, 121, 122, Lunchroom (125), 123, 124**
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **9" x 9" Brown Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 212 (Beneath 12"x12" Floor Tile)**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **9" x 9" Brown Speckled Floor Tile Mastic**
MATERIAL LOCATION: **Room 212 (Beneath 12"x12" Floor Tile)**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Addition, 320, 321, 322, 325, 324, 2nd FI Hallway, 226, 225, 224, 227, 222, 221, 220, 121 122, Lunchroom (125), 123, 124**
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in 224, 124**

Inspector's Signature:



Date: 12/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks Mastic**

MATERIAL LOCATION: **Throughout 1996 Addition, 320, 321, 322, 325, 324, 2nd FI Hallway, 226, 225, 224, 227, 222, 221, 220, 121 122, Lunchroom (125), 123, 124**

MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd FI Hallways (Annex), 2nd FI Hallway (Annex), 1st FI Hallway (Annex)**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mix Floor Tile**

MATERIAL LOCATION: **3rd FI Hallways (Annex), 2nd FI Hallway (Annex), 1st FI Hallway (Annex)**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd FI Hallway (Annex), 2nd FI Hallway (Annex), 1st FI Hallway (Annex)**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mix Floor Tile Mastic**
MATERIAL LOCATION: **3rd FI Hallway (Annex), 2nd FI Hallway (Annex), 1st FI Hallway (Annex)**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1996 Addition**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
MATERIAL LOCATION: **Throughout 1996 Addition**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1996 Addition**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**

MATERIAL LOCATION: **Throughout 1996 Addition**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office and Walls Between Classrooms,throughout basement areas**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Office and Walls Between Classrooms,throughout basement areas**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Drywall joint compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office and Walls Between Classrooms, throughout basement areas**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Drywall joint compound**
MATERIAL LOCATION: **Office and Walls Between Classrooms, throughout basement areas**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Brown carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office, (Annex)**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Brown carpet mastic**

MATERIAL LOCATION: **Main Office, (Annex)**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1996 Addition**

MATERIAL QUANTITY: **30000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Tile**
MATERIAL LOCATION: **Throughout 1996 Addition**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Interior brick**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1996 Addition Corridors**

MATERIAL QUANTITY: **10000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Interior brick**

MATERIAL LOCATION: **Throughout 1996 Addition Corridors**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/White & Black Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/White & Black Specks**

MATERIAL LOCATION: **3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6 A**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/White & Blk Spks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **6 A**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/White & Blk Spks Mastic**

MATERIAL LOCATION: **3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Interior brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Addition Corridors**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Interior brick mortar**

MATERIAL LOCATION: **Throughout 1996 Addition Corridors**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Elevator brake shoes**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor of 1996 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Elevator brake shoes**

MATERIAL LOCATION: **1st Floor Corridor of 1996 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Chalk Board and Bulletin Board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms in 1996 Addition**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Chalk Board and Bulletin Board Adhesive**
MATERIAL LOCATION: **Classrooms in 1996 Addition**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Interior window caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Addition**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Interior window caulk**
MATERIAL LOCATION: **Throughout 1996 Addition**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Coating on Bottoms of Sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Addition Classrooms**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Coating on Bottoms of Sinks**

MATERIAL LOCATION: **Throughout 1996 Addition Classrooms**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Interior door caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1996 Addition**

MATERIAL QUANTITY: **300**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Interior door caulk**

MATERIAL LOCATION: **Throughout 1996 Addition**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Spray-on fireproofing**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement: Mechanical Areas**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Spray-on fireproofing**

MATERIAL LOCATION: **Basement: Mechanical Areas**

MATERIAL QUANTITY: **12000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Duct caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Mechanical Room of 1996 Addition**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Duct caulk**
MATERIAL LOCATION: **3rd Floor Mechanical Room of 1996 Addition**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Stair treads**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1996 Addition Stairways**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Stair treads**
MATERIAL LOCATION: **Throughout 1996 Addition Stairways**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Stair tread adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1996 Addition Stairways**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Stair tread adhesive**
MATERIAL LOCATION: **Throughout 1996 Addition Stairways**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Brown Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Brown Specks**
MATERIAL LOCATION: **3rd Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7 A**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Brown Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **7 A**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Brown Specks Mastic**
MATERIAL LOCATION: **3rd Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Cinderblock**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Addition**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Cinderblock**
MATERIAL LOCATION: **Throughout 1996 Addition**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Cinderblock mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Addition**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Cinderblock mortar**
MATERIAL LOCATION: **Throughout 1996 Addition**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Blue glazed brick**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Addition Men's & Boy's Bathrooms**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Blue glazed brick**
MATERIAL LOCATION: **Throughout 1996 Addition Men's & Boy's Bathrooms**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Blue glazed brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Addition Men's & Boy's Bathrooms**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Blue glazed brick mortar**
MATERIAL LOCATION: **Throughout 1996 Addition Men's & Boy's Bathrooms**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **Green glazed brick**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1996 Addition Women's & Girl's Bathrooms**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **Green glazed brick**
MATERIAL LOCATION: **Throughout 1996 Addition Women's & Girl's Bathrooms**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Green glazed brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Addition Women's & Girl's Bathrooms**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Green glazed brick mortar**
MATERIAL LOCATION: **Throughout 1996 Addition Women's & Girl's Bathrooms**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **1350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Streaks Floor Tile**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **1350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **1350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **1350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile w/Brown Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile w/Brown Specks**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8 A**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tilew/Brown Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **8 A**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tilew/Brown Specks Mastic**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**


RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement, 2nd Floor Stairs, 3rd Floor Corridor**
MATERIAL QUANTITY: **2280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2280** DAMAGE UNITS: **SF**
COMMENTS: **Damage located on 2nd floor**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Brown Streaks**
MATERIAL LOCATION: **Basement, 2nd Floor Stairs, 3rd Floor Corridor**
MATERIAL QUANTITY: **2280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **80** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9 A**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement, 2nd Floor Stairs, 3rd Floor Corridor**
MATERIAL QUANTITY: **2280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2280** DAMAGE UNITS: **SF**
COMMENTS: **Damage located on 2nd floor**

Inspector's Signature: _____



Date: 12/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **9 A**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Brown Streaks Mastic**
MATERIAL LOCATION: **Basement, 2nd Floor Stairs, 3rd Floor Corridor**
MATERIAL QUANTITY: **2280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **80** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Boiler insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Suspended mag tank (hot water)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Suspended mag tank (hot water)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation on Steam Supply**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation on Steam Supply**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings off Steam Line**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Cementitious Pipe Fittings off Steam Line**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Plenum Caulking in Air Chamber**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **WaRoom Air Chamber in Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Plenum Caulking in Air Chamber**

MATERIAL LOCATION: **WaRoom Air Chamber in Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings off FG Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Tank Room, Boiler Room, Hall by Tank Room, Lunchroom, Boys and Girls Bathroom.**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings off FG Pipe Insulation**
MATERIAL LOCATION: **Tank Room, Boiler Room, Hall by Tank Room, Lunchroom, Boys and Girls Bathroom.**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Aircell pipe insulation**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings off Aircell Pipe Runs**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement, 1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Cementitious Pipe Fittings off Aircell Pipe Runs**

MATERIAL LOCATION: **Basement, 1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Cardboard pipe insulation**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Cementitious Fittings off Cardboard Pipe Runs**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Cementitious Fittings off Cardboard Pipe Runs**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **Cementitious valve headers - abated 1998**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Tank Headers**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUIDLING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **T**

MATERIAL DESCRIPTION: **Cementitious valve headers - abated 1998**

MATERIAL LOCATION: **Basement Tank Headers**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Wood flooring**

MATERIAL LOCATION: **3rd Fl Hallway, 309, 310, 307, 305, 306, 304, 303, 302, 301, 201, 202, 204, 203, 206, 205, IDF Room (208), 209, 211, 213, 214, 102, 104, 103, 106, 110, B13, Auditorium**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Light Blue Grayish Floor Tile**
MATERIAL LOCATION: **Basement, 101, 102**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **Tan w/Streaks Laminate Sheet Flooring**
MATERIAL LOCATION: **Gymnasium**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **Tan w/Streaks Laminate Sheet Flooring**
MATERIAL LOCATION: **Gymnasium**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **Mastic for Dark Multicolored Carpet**

MATERIAL LOCATION: **Library (323), 223**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Shields School** INSPECTION DATE: **12/9/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **Mastic for Tan w/Streaks Laminate Sheet Flooring**
MATERIAL LOCATION: **Gymnasium**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **12/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Mastic for Tan w/Streaks Laminate Sheet Flooring**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled Floor Tile**
MATERIAL LOCATION: **Modular**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled Floor Tile Mastic**
MATERIAL LOCATION: **Modular**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" Dark Blue w/Blue Streaks Floor Tile**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12" x 12" Dark Blue w/Blue Streaks Floor Tile**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25361** BUILDING ID: **5910**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Shields School** REVIEW DATE: **12/10/2022**
ADDRESS: **4250 S. Rockwell** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12" x 12" Light Blue Grayish Floor Tile**
MATERIAL LOCATION: **Basement, 101, 102**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:


Management Planner's Signature: _____



Date: 12/10/2022

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Ron Brock

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/19/2022

Exam Date: 1/19/2022



Expiration Date: 1/19/2023

Certificate Number: BIR2201190225

Kathy DeSalvo, Director

Ronald Brock

Illinois Licensed Building Inspector, Air Sampling Professional, Asbestos Project Manager





OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed