

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2442
SCHOOL NAME: Schmid School
ADDRESS OF SCHOOL: 9755 S Greenwood
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/22/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 8/11/2022 ENROLLMENT 179
IDPH INSPECTOR LICENSE NUMBER: 100-20327
IDPH LICENSED INSPECTOR NAME (Please Print): Drake Ottley
IDPH MP LICENSE NUMBER: 100-03613
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



8/22/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Schmid School

9755 S Greenwood
Chicago, IL, 60628

Unit: 25391
Building ID: 5950

IDPH ID Number: 14-016-2990-2442

REPORT DATE:

Monday, August 22, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

08/22/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25391 Region: 06 IDPH ID: 14-016-2990-2442

School: Schmid School Building ID: 5950

Address: 9755 S Greenwood
Chicago, IL, 60628

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/11/2022

Review Date: 08/22/2022

Inspector: Drake Ottley Inspector IDPH License: 100-20327
Management Planner: Daniel Juneau Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Daniel Juneau
100-03613

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 22, 2022

RE: Schmid School, Unit 25391
9755 S Greenwood
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Schmid School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Schmid School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Schmid School
Address: 9755 S Greenwood
IDPH ID: 14-016-2990-2442
Contact:

Unit: 25391
Chicago, IL, 60628
Building ID: 5950
Phone:

Region: 06

2. Description of Facility

Original Construction:
Total Square Footage:
Current Occupancy: 179

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant


MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Drake Ottley


Inspector IDPH license # 100-20327
Reinspection Date: 8/11/2022

Signature: 
Date: 8/11/2022

6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613


Signature: 
Date: 08/22/2022

7. Review Date: 08/22/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 8/22/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Schmid School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5950:

NEW

Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 5950:

NEW

Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

03	12"x12" Rust w/White Specks Floor Tile
03A	12"x12" Brown w/White Specks Floor Tile
03B	12"x12" Cream Floor Tile
05	12"x12" Rust w/White Specks Floor Tile Mastic
07	Drywall
08	Dark Brown Vinyl Baseboard
08A	Beige Vinyl Baseboard
09	Dark Brown Vinyl Baseboard Mastic
09A	Beige Vinyl Baseboard Mastic
10	2'x4' Ceiling Tile
11	Purple Carpet Mastic
12	Carpet Mastic
15	9"x9" Dark Brown Floor Tile
16	9"x9" Dark Floor Tile Mastic
17	12"x12" Beige w/Gray Specks Floor Tile
18	12"x12" Beige w/Gray Specks Floor Tile Mastic
19	Beige Flooring Mastic
20	Gray Flooring Mastic
21	Yellow, Brown & Beige Ceramic Tile Grout
22	Yellow, Brown and Beige Ceramic Tile Adhesive
23	Grey and Black Speckled Terrazzo
24	12"x12" Blue Floor Tile
24M	12"x12" Blue Floor Tile Mastic
25	Beige and Tan Ceramic Tile Grout
26	Beige and Tan Ceramic Tile Grout
27	Gray Baseboard
27A	Gray Baseboard Adhesive
28	Red Ceramic Tile Grout
29	Red Ceramic Tile Adhesive
30	12"x12" White w/Blue and Red Speckles Floor Tile
30M	12"x12" White w/Blue and Red Speckles Floor Tile Mastic
31	Beige Flooring
32	Gray Flooring
33	12"x12" White w/Blue Specks Vinyl Floor Tile
34	12"x12" White w/Blue Specks Mastic
35	12"x12" Cream w/Tan Specks Vinyl Floor Tile
36	12"x12" Cream w/Tan Specks Mastic
37	Fire Doors
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

05	12"x12" Rust w/White Specks Floor Tile Mastic
05A	12"x12" Brown w/White Specks Floor Tile Mastic
05B	12"x12" Cream Floor Tile Mastic
06	9"x9" Light Brown w/Specks Floor Tile Mastic
09	Dark Brown Vinyl Baseboard Mastic
09A	Beige Vinyl Baseboard Mastic
11	Purple Carpet Mastic
12	Carpet Mastic
13	Orange/Brown Carpet Mastic NOT OBSERVED
15	9"x9" Dark Brown Floor Tile
16	9"x9" Dark Floor Tile Mastic
17	12"x12" Beige w/Gray Specks Floor Tile
18	12"x12" Beige w/Gray Specks Floor Tile Mastic
19	Beige Flooring Mastic
20	Gray Flooring Mastic
22	Yellow, Brown and Beige Ceramic Tile Adhesive
24M	12"x12" Blue Floor Tile Mastic
26	Beige and Tan Ceramic Tile Grout
27A	Gray Baseboard Adhesive
29	Red Ceramic Tile Adhesive
30M	12"x12" White w/Blue and Red Speckles Floor Tile Mastic
32	Gray Flooring
37	Fire Doors

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Drake Ottley, IDPH License # 100-20327. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Schmid School Building 5950 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Schmid School Unit 25391 Building ID 5950

Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03	12"x12" Rust w/White Specks Floor Tile	2,804	SF	Annex Building- 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03A	12"x12" Brown w/White Specks Floor Tile	5,198	SF	Annex Building- All Classrooms (except 404 & 406) and 1/2 Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03B	12"x12" Cream Floor Tile	5,198	SF	All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	9"x9" Light Brown w/Specks Floor Tile	4,000	SF	Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	12"x12" Rust w/White Specks Floor Tile Mastic	2,804	SF	Annex Building- 1st Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05A	12"x12" Brown w/White Specks Floor Tile Mastic	5,198	SF	Annex Building- All Classrooms (except 406, 404) and 1/2 Main Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05B	12"x12" Cream Floor Tile Mastic	5,198	SF	All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	9"x9" Light Brown w/Specks Floor Tile Mastic	4,000	SF	Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	Drywall	36,000	SF	Annex Building- Throughout (Covered with Metal)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
08	Dark Brown Vinyl Baseboard	145	LF	Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08A	Beige Vinyl Baseboard	86	LF	Annex Building- Principal's Office,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Schmid School Unit 25391 Building ID 5950

Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Store Room in Main Office										
09	Dark Brown Vinyl Baseboard Mastic	145	LF	Annex Building-Engineer's Office/Washroom, Store Room, Main Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09A	Beige Vinyl Baseboard Mastic	86	LF	Annex Building-Principal's Office, Store Rooms in Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	2'x4' Ceiling Tile	18,000	SF	Throughout Buildings; Annex Building-Engineer's Office/Washroom	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
11	Purple Carpet Mastic	2,222	SF	Annex Building-Room 411, Library, Detention Room 404, Room 403	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Carpet Mastic	395	SF	Annex Building-Main Office, Principal's Office, Main Office Store Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Orange/Brown Carpet Mastic NOT OBSERVED			Annex Building-Room 403		MISC								
14	Red Carpet Mastic NOT OBSERVED			Annex Building-Main Office		MISC					No			
15	9"x9" Dark Brown Floor Tile	100	SF	Main Building-Engineer's Office Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	9"x9" Dark Floor Tile Mastic	100	SF	Main Building-Engineer's Office Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12"x12" Beige w/Gray Specks Floor Tile	300	SF	Main Building-Engineer's Office & Toilet, 1st Floor Wardrobe Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12"x12" Beige w/Gray Specks Floor Tile Mastic	300	SF	Engineer's Office & Toilet, 1st Floor Wardrobe Room (Main Building)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Beige Flooring Mastic	1,100	SF	Main Building- 1st Floor Corridor, Assistant Principal's	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Schmid School Unit 25391 Building ID 5950

Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Office (Room 101)										
20	Gray Flooring Mastic	1,100	SF	Main Building- 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Yellow, Brown & Beige Ceramic Tile Grout	1,684	SF	Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Yellow, Brown and Beige Ceramic Tile Adhesive	1,684	SF	Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Grey and Black Speckled Terrazzo	2,176	SF	1st and 2nd Floor Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12"x12" Blue Floor Tile	2,936	SF	2nd Floor Corridor, Teachers Lounge (Main Building) and Main Office, Kitchen (Annex Building)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
24M	12"x12" Blue Floor Tile Mastic	2,936	SF	Main Building- 2nd Floor Corridor, Teachers' Lounge; Annex Building- Main Office, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Beige and Tan Ceramic Tile Grout	960	SF	Annex Building- Boys' and Girls' Restrooms, Teachers' Toilets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Beige and Tan Ceramic Tile Grout	960	SF	Annex Building- Boys' and Girls' Restrooms, Teachers' Toilets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Gray Baseboard	136	LF	Annex Building- East West Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27A	Gray Baseboard Adhesive	136	LF	Annex Building- East West Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Red Ceramic Tile Grout	120	SF	Annex Building- North and South	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Schmid School Unit 25391 Building ID 5950

Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Entrances										
29	Red Ceramic Tile Adhesive	120	SF	Annex Building- North and South Entrances	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12"x12" White w/Blue and Red Speckles Floor Tile	416	SF	Annex Building- Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30M	12"x12" White w/Blue and Red Speckles Floor Tile Mastic	416	SF	Annex Building- Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Beige Flooring	1,100	SF	1st Floor Corridor, Assistant Principal's Office (Room 101)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
32	Gray Flooring	1,100	SF	1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
33	12"x12" White w/Blue Specks Vinyl Floor Tile	530	SF	Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
34	12"x12" White w/Blue Specks Mastic	530	SF	Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12"x12" Cream w/Tan Specks Vinyl Floor Tile	100	SF	Room 102/ Principal's Office, Stage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12"x12" Cream w/Tan Specks Mastic	100	SF	Room 102/ Principal's Office, Stage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Fire Doors	80	SF	2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

Chicago Public Schools

School Schmid School Unit 25391 Building ID 5950

Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/11/2022
Inspector Name Drake Ottley
100-20327 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
03	
03A	
03B	
04	
05	
05A	
05B	
06	
07	
08	
08A	
09	
09A	
10	
11	
12	
13	Not Observed
14	Not Observed
15	
16	
17	
18	
19	
20	

Chicago Public Schools

School Schmid School Unit 25391 Building ID 5950

Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
21	
22	
23	
24	
24M	
25	
26	
27	
27A	
28	
29	
30	
30M	
31	
32	
33	
34	
35	
36	
37	
NEW	

Table II

Management Planner's Review

Chicago Public Schools

School Schmid School
Address 9755 S Greenwood

Unit 25391
Chicago, IL, 60628

Building ID 5950
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03	12"x12" Rust w/White Specks Floor Tile	2,804	SF	Annex Building- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03A	12"x12" Brown w/White Specks Floor Tile	5,198	SF	Annex Building- All Classrooms (except 404 & 406) and 1/2 Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03B	12"x12" Cream Floor Tile	5,198	SF	All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	9"x9" Light Brown w/Specks Floor Tile	4,000	SF	Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12"x12" Rust w/White Specks Floor Tile Mastic	2,804	SF	Annex Building- 1st Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05A	12"x12" Brown w/White Specks Floor Tile Mastic	5,198	SF	Annex Building- All Classrooms (except 406, 404) and 1/2 Main Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05B	12"x12" Cream Floor Tile Mastic	5,198	SF	All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9"x9" Light Brown w/Specks Floor Tile Mastic	4,000	SF	Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	Drywall	36,000	SF	Annex Building- Throughout (Covered with Metal)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Dark Brown Vinyl Baseboard	145	LF	Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
08A	Beige Vinyl Baseboard	86	LF	Annex Building- Principal's Office, Store Room in Main Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
09	Dark Brown Vinyl Baseboard Mastic	145	LF	Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
09A	Beige Vinyl Baseboard Mastic	86	LF	Annex Building- Principal's Office, Store Rooms in Main Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
10	2'x4' Ceiling Tile	18,000	SF	Throughout Buildings; Annex Building- Engineer's Office/Washroom	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Purple Carpet Mastic	2,222	SF	Annex Building- Room 411, Library, Detention Room 404, Room 403	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Carpet Mastic	395	SF	Annex Building- Main Office, Principal's Office, Main Office Store Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Schmid School
Address 9755 S Greenwood

Unit 25391
Chicago, IL, 60628

Building ID 5950
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
13	Orange/Brown Carpet Mastic NOT OBSERVED			Annex Building- Room 403		MISC					
14	Red Carpet Mastic NOT OBSERVED			Annex Building- Main Office		MISC					
15	9"x9" Dark Brown Floor Tile	100	SF	Main Building- Engineer's Office Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9"x9" Dark Floor Tile Mastic	100	SF	Main Building- Engineer's Office Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"x12" Beige w/Gray Specks Floor Tile	300	SF	Main Building- Engineer's Office & Toilet, 1st Floor Wardrobe Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" Beige w/Gray Specks Floor Tile Mastic	300	SF	Engineer's Office & Toilet, 1st Floor Wardrobe Room (Main Building)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Beige Flooring Mastic	1,100	SF	Main Building- 1st Floor Corridor, Assistant Principal's Office (Room 101)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Gray Flooring Mastic	1,100	SF	Main Building- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Yellow, Brown & Beige Ceramic Tile Grout	1,684	SF	Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Yellow, Brown and Beige Ceramic Tile Adhesive	1,684	SF	Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Grey and Black Speckled Terrazzo	2,176	SF	1st and 2nd Floor Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12"x12" Blue Floor Tile	2,936	SF	2nd Floor Corridor, Teachers Lounge (Main Building) and Main Office, Kitchen (Annex Building)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24M	12"x12" Blue Floor Tile Mastic	2,936	SF	Main Building- 2nd Floor Corridor, Teachers' Lounge; Annex Building- Main Office, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Beige and Tan Ceramic Tile Grout	960	SF	Annex Building- Boys' and Girls' Restrooms, Teachers' Toilets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Beige and Tan Ceramic Tile Grout	960	SF	Annex Building- Boys' and Girls' Restrooms, Teachers' Toilets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Gray Baseboard	136	LF	Annex Building- East West Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
27A	Gray Baseboard Adhesive	136	LF	Annex Building- East West Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
28	Red Ceramic Tile Grout	120	SF	Annex Building- North and South Entrances	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Red Ceramic Tile Adhesive	120	SF	Annex Building- North and South Entrances	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Schmid School
Address 9755 S Greenwood

Unit 25391
 Chicago, IL, 60628

Building ID 5950
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
30	12"x12" White w/Blue and Red Speckles Floor Tile	416	SF	Annex Building- Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30M	12"x12" White w/Blue and Red Speckles Floor Tile Mastic	416	SF	Annex Building- Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Beige Flooring	1,100	SF	1st Floor Corridor, Assistant Principal's Office (Room 101)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Gray Flooring	1,100	SF	1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12"x12" White w/Blue Specks Vinyl Floor Tile	530	SF	Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12"x12" White w/Blue Specks Mastic	530	SF	Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12"x12" Cream w/Tan Specks Vinyl Floor Tile	100	SF	Room 102/ Principal's Office, Stage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"x12" Cream w/Tan Specks Mastic	100	SF	Room 102/ Principal's Office, Stage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Fire Doors	80	SF	2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Schmid School
Address 9755 S Greenwood

Unit 25391
 Chicago, IL, 60628

Building ID 5950
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	8/22/2022
Manager Planner Name	Daniel Juneau
100-03613	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
03	
03A	
03B	
04	
05	
05A	
05B	
06	
07	
08	
08A	
09	
09A	
10	
11	
12	
13	
14	
15	
16	

Chicago Public Schools

School Schmid School
Address 9755 S Greenwood

Unit 25391
 Chicago, IL, 60628

Building ID 5950
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
17	
18	
19	
20	
21	
22	
23	
24	
24M	
25	
26	
27	
27A	
28	
29	
30	
30M	
31	
32	
33	
34	
35	
36	
37	
NEW	

Chicago Public Schools

School Schmid School
Address 9755 S Greenwood

Unit 25391
Chicago, IL, 60628

Building ID 5950
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **12"x12" Rust w/White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex Building- 1st Floor Corridor**

MATERIAL QUANTITY: **2804**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **12"x12" Rust w/White Specks Floor Tile**
MATERIAL LOCATION: **Annex Building- 1st Floor Corridor**
MATERIAL QUANTITY: **2804** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **12"x12" Brown w/White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- All Classrooms (except 404 & 406) and 1/2 Main Office**
MATERIAL QUANTITY: **5198** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **12"x12" Brown w/White Specks Floor Tile**
MATERIAL LOCATION: **Annex Building- All Classrooms (except 404 & 406) and 1/2 Main Office**
MATERIAL QUANTITY: **5198** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03B**
MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)**

MATERIAL QUANTITY: **5198** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **03B**
MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile**
MATERIAL LOCATION: **All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)**
MATERIAL QUANTITY: **5198** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9"x9" Light Brown w/Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9"x9" Light Brown w/Specks Floor Tile**
MATERIAL LOCATION: **Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12"x12" Rust w/White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- 1st Floor Corridors**
MATERIAL QUANTITY: **2804** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12"x12" Rust w/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Annex Building- 1st Floor Corridors**
MATERIAL QUANTITY: **2804** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **12"x12" Brown w/White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- All Classrooms (except 406, 404) and 1/2 Main Office**
MATERIAL QUANTITY: **5198** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **12"x12" Brown w/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Annex Building- All Classrooms (except 406, 404) and 1/2 Main Office**
MATERIAL QUANTITY: **5198** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)**

MATERIAL QUANTITY: **5198**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile Mastic**
MATERIAL LOCATION: **All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)**
MATERIAL QUANTITY: **5198** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x9" Light Brown w/Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x9" Light Brown w/Specks Floor Tile Mastic**
MATERIAL LOCATION: **Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Throughout (Covered with Metal)**
MATERIAL QUANTITY: **36000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Annex Building- Throughout (Covered with Metal)**
MATERIAL QUANTITY: **36000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Dark Brown Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom**

MATERIAL QUANTITY: **145** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Dark Brown Vinyl Baseboard**
MATERIAL LOCATION: **Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom**
MATERIAL QUANTITY: **145** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **Beige Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Principal's Office, Store Room in Main Office**
MATERIAL QUANTITY: **86** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **Beige Vinyl Baseboard**
MATERIAL LOCATION: **Annex Building- Principal's Office, Store Room in Main Office**
MATERIAL QUANTITY: **86** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Dark Brown Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom**
MATERIAL QUANTITY: **145** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Dark Brown Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom**
MATERIAL QUANTITY: **145** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **Beige Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Principal's Office, Store Rooms in Main Office**
MATERIAL QUANTITY: **86** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **Beige Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Annex Building- Principal's Office, Store Rooms in Main Office**
MATERIAL QUANTITY: **86** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Buildings; Annex Building- Engineer's Office/Washroom**
MATERIAL QUANTITY: **18000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **Throughout Buildings; Annex Building- Engineer's Office/Washroom**
MATERIAL QUANTITY: **18000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Room 411, Library, Detention Room 404, Room 403**
MATERIAL QUANTITY: **2222** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
MATERIAL LOCATION: **Annex Building- Room 411, Library, Detention Room 404, Room 403**
MATERIAL QUANTITY: **2222** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Main Office, Principal's Office, Main Office Store Rooms**
MATERIAL QUANTITY: **395** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Annex Building- Main Office, Principal's Office, Main Office Store Rooms**
MATERIAL QUANTITY: **395** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Orange/Brown Carpet Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex Building- Room 403**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Orange/Brown Carpet Mastic NOT OBSERVED**

MATERIAL LOCATION: **Annex Building- Room 403**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Red Carpet Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex Building- Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Red Carpet Mastic NOT OBSERVED**

MATERIAL LOCATION: **Annex Building- Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Engineer's Office Storage Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile**
MATERIAL LOCATION: **Main Building- Engineer's Office Storage Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9"x9" Dark Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Engineer's Office Storage Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9"x9" Dark Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Engineer's Office Storage Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" Beige w/Gray Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Engineer's Office & Toilet, 1st Floor Wardrobe Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" Beige w/Gray Specks Floor Tile**
MATERIAL LOCATION: **Main Building- Engineer's Office & Toilet, 1st Floor Wardrobe Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Beige w/Gray Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office & Toilet, 1st Floor Wardrobe Room (Main Building)**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Beige w/Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office & Toilet, 1st Floor Wardrobe Room (Main Building)**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Beige Flooring Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- 1st Floor Corridor, Assistant Principal's Office (Room 101)**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Beige Flooring Mastic**
MATERIAL LOCATION: **Main Building- 1st Floor Corridor, Assistant Principal's Office (Room 101)**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Gray Flooring Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- 1st Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Gray Flooring Mastic**
MATERIAL LOCATION: **Main Building- 1st Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Yellow, Brown & Beige Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules**

MATERIAL QUANTITY: **1684**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Yellow, Brown & Beige Ceramic Tile Grout**
MATERIAL LOCATION: **Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules**
MATERIAL QUANTITY: **1684** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Yellow, Brown and Beige Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules**

MATERIAL QUANTITY: **1684**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Yellow, Brown and Beige Ceramic Tile Adhesive**
MATERIAL LOCATION: **Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules**
MATERIAL QUANTITY: **1684** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Grey and Black Speckled Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Stairwells**
MATERIAL QUANTITY: **2176** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Grey and Black Speckled Terrazzo**
MATERIAL LOCATION: **1st and 2nd Floor Stairwells**
MATERIAL QUANTITY: **2176** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **2nd Floor Corridor, Teachers Lounge (Main Building) and Main Office, Kitchen (Annex Building)**

MATERIAL QUANTITY: **2936** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**
MATERIAL LOCATION: **2nd Floor Corridor, Teachers Lounge (Main Building) and Main Office, Kitchen (Annex Building)**
MATERIAL QUANTITY: **2936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24M**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Building- 2nd Floor Corridor, Teachers' Lounge; Annex Building- Main Office, Kitchen**

MATERIAL QUANTITY: **2936**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **24M**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- 2nd Floor Corridor, Teachers' Lounge; Annex Building- Main Office, Kitchen**
MATERIAL QUANTITY: **2936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Beige and Tan Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Boys' and Girls' Restrooms, Teachers' Toilets**
MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Beige and Tan Ceramic Tile Grout**
MATERIAL LOCATION: **Annex Building- Boys' and Girls' Restrooms, Teachers' Toilets**
MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Beige and Tan Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Boys' and Girls' Restrooms, Teachers' Toilets**
MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Beige and Tan Ceramic Tile Grout**
MATERIAL LOCATION: **Annex Building- Boys' and Girls' Restrooms, Teachers' Toilets**
MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Gray Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- East West Corridor**
MATERIAL QUANTITY: **136** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Gray Baseboard**
MATERIAL LOCATION: **Annex Building- East West Corridor**
MATERIAL QUANTITY: **136** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27A**
MATERIAL DESCRIPTION: **Gray Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- East West Corridor**
MATERIAL QUANTITY: **136** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **27A**
MATERIAL DESCRIPTION: **Gray Baseboard Adhesive**
MATERIAL LOCATION: **Annex Building- East West Corridor**
MATERIAL QUANTITY: **136** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Red Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- North and South Entrances**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Red Ceramic Tile Grout**
MATERIAL LOCATION: **Annex Building- North and South Entrances**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Red Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- North and South Entrances**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Red Ceramic Tile Adhesive**
MATERIAL LOCATION: **Annex Building- North and South Entrances**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12"x12" White w/Blue and Red Speckles Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Main Office**
MATERIAL QUANTITY: **416** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12"x12" White w/Blue and Red Speckles Floor Tile**
MATERIAL LOCATION: **Annex Building- Main Office**
MATERIAL QUANTITY: **416** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30M**
MATERIAL DESCRIPTION: **12"x12" White w/Blue and Red Speckles Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building- Main Office**
MATERIAL QUANTITY: **416** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **30M**
MATERIAL DESCRIPTION: **12"x12" White w/Blue and Red Speckles Floor Tile Mastic**
MATERIAL LOCATION: **Annex Building- Main Office**
MATERIAL QUANTITY: **416** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Beige Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Corridor, Assistant Principal's Office (Room 101)**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Beige Flooring**
MATERIAL LOCATION: **1st Floor Corridor, Assistant Principal's Office (Room 101)**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Gray Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Gray Flooring**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12"x12" White w/Blue Specks Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge**
MATERIAL QUANTITY: **530** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12"x12" White w/Blue Specks Vinyl Floor Tile**
MATERIAL LOCATION: **Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge**
MATERIAL QUANTITY: **530** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12"x12" White w/Blue Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge**
MATERIAL QUANTITY: **530** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12"x12" White w/Blue Specks Mastic**
MATERIAL LOCATION: **Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge**
MATERIAL QUANTITY: **530** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Specks Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102/ Principal's Office, Stage Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Specks Vinyl Floor Tile**
MATERIAL LOCATION: **Room 102/ Principal's Office, Stage Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102/ Principal's Office, Stage Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/11/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Specks Mastic**
MATERIAL LOCATION: **Room 102/ Principal's Office, Stage Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Drake Ottley**
SCHOOL NAME: **Schmid School** INSPECTION DATE: **8/11/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/11/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUIDLING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Fire Doors**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/22/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25391** BUILDING ID: **5950**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Schmid School** REVIEW DATE: **8/22/2022**
ADDRESS: **9755 S Greenwood** IDPH LICENSE NO: **100-20327**

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  _____ Date: 08/22/2022

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Drake Ottley

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/1/2021

Exam Date: 12/1/2021

Expiration Date: 12/1/2022

Certificate Number: BIR2112012887


Kathy DeSalvo, Director

IDPH ASBESTOS PROFESSIONAL LICENSE

ID NUMBER	ISSUED	EXPIRES
100 - 20327	3/1/2022	05/15/2023

DRAKE E OTTLEY
 693 LEXINGTON DR
 GENEVA, IL 60134

Environmental Health



ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/1/2022
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/2/2022

Alteration of this license shall result in legal action
 This license issued under authority of the State of Illinois
 Department of Public Health
 This license is valid only when accompanied by a valid
 training course certificate.



EarthTech, Inc.

435 Shadow Wood Drive, Yorkville, IL 60560

Asbestos Building Inspector Refresher

THIS CERTIFIES THAT

Drake Ottley


Has successfully completed the IL and IN Approved Asbestos Training Course and passed the Examination for purposes of accreditation under section 206 of Title II, 15 USC 2646 of the Toxic Substances Control Act (TSCA) and 326 IAC 18-2. Conducted by EarthTech, Inc
630-417-6951

CLASS DATES: 11/16/2022


EXAMINATION: 11/16/2022

LOCATION: Amerisafe

EXPIRATION: 11/16/2023




CERTIFICATE NUMBER: 110173X19S103885

 **ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 03613	3/1/2022	05/15/2023

DANIEL J JUNEAU
 1408 OAKWOOD AVENUE
 DES PLAINES, IL 60016
 Environmental Health



ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/19/2022
MANAGEMENT PLANNER	11/19/2022
PROJECT MANAGER	11/1/2022
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
 This license issued under authority of the State of Illinois
 Department of Public Health
 This license is valid only when accompanied by a valid
 training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: BIR2111192805

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192816

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/12/2022

Exam Date: 12/12/2022

Expiration Date: 12/12/2023

Certificate Number: MPR2212123967

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113645

Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed