

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2460  
SCHOOL NAME: Smyth School  
ADDRESS OF SCHOOL: 1059 W. 13th St.  
CITY: Chicago, IL, 60608

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/17/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 9/22/2022 ENROLLMENT 395  
IDPH INSPECTOR LICENSE NUMBER: 100-05020  
IDPH LICENSED INSPECTOR NAME (Please Print): Devon Jackson  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer*

10/12/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Smyth School**

1059 W. 13th St.  
Chicago, IL, 60608

Unit: 25411  
Building ID: 5970

IDPH ID Number: 14-016-2990-2460

**REPORT DATE:**

Wednesday, October 12, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

10/12/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 25411      Region: 03      IDPH ID: 14-016-2990-2460

School: Smyth School      Building ID: 5970

Address: 1059 W. 13th St.

Chicago, IL, 60608

Building Contact: Greene, Joseph

Contact Phone: 3124972644

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/22/2022

Review Date: 10/12/2022

Inspector: Devon Jackson

Inspector IDPH License: 100-05020

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: October 12, 2022

RE: Smyth School, Unit 25411  
1059 W. 13th St.  
Chicago, IL, 60608

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Smyth School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Smyth School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Smyth School Unit: 25411 Region: 03  
Address: 1059 W. 13th St. Chicago, IL, 60608  
IDPH ID: 14-016-2990-2460 Building ID: 5970  
Contact: Greene, Joseph Phone: 3124972644

### 2. Description of Facility

Original Construction: 1961 Additional Construction: 1897,1905  
Total Square Footage: 28381 No of Floors: 2  
Current Occupancy: 395

### 3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602


### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Devon Jackson


Inspector IDPH license # 100-05020  
Reinspection Date: 9/22/2022

Signature:   
Date: 9/22/2022

### 6. Management Planner

Management Planner Name: Evan Christian


Management Planner IDPH license # 100-19466

Signature:   
Date: 10/12/2022

### 7. Review Date: 10/12/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/12/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Smyth School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5970:

31	Boiler breeching sealant
32	12" x 12" mint Green w/ Brown Specks Floor Tile
33	Mastic assoc w/ 12" x 12" mint Green with Brown Specks Floor Tile
3BM	9" x 9" Dark Brown Floor Tile w/White and Blk Streaks Mastic
3GM	9" x 9" Tan Floor Tile w/Brown and Blue Dots Mastic
4	1' x 1' Acoustical Ceiling Tile
5	Acoustical plaster
54A	12" x 12" Red Floor Tile Mastic

55	Gray spray-on fireproofing
56	12" x 12" Light Green w/ Streaks Floor Tile Mastic
57	12" x 12" Light Green w/ Streaks Floor Tile
58	12" x 12" Dark Red Floor Tile w/ Black Specks
59	12" x 12" Dark Red Floor Tile w/ Black Specks Mastic
60	Tongue and Groove Wood Floor
61	12" x 12" Light Blue Floor Tile w/ White Streaks
62	12" x 12" Light Blue Floor Tile w/ White Streaks Mastic
63	12" x 12" Off-White Floor Tile w/ black Streaks
64	12" x 12" Off-White Floor Tile w/ black Streaks Mastic
65	12" x 12" Gray Floor Tile w/ White and Brown Streaks
66	12" x 12" Gray Floor Tile w/ White and Brown Streaks Mastic
67	12" x 12" Pink Floor Tile
68	12" x 12" Pink Floor Tile Mastic
69	12" x 12" Light Brown Floor Tile w/ White Streaks
70	12" x 12" Light Brown Floor Tile w/ White Streaks Mastic
71	9" x 9" Cream Floor Tile w/ Black Specks
72	9" x 9" Cream Floor Tile w/ Black Specks Mastic
73	12" x 12" Gold Floor Tile
74	12" x 12" Light Brown Floor Tile
75	12" x 12" Brown Floor Tile w/ White Specks



- 76 12" x 12" Gold, Light Brown and Brown w/ White Specks Floor Tile Mastic
- 1 Joint Insulation on WoolfeLight Pipe Insulation

B. The following new homogenous areas have been identified for Building 5970:

56	12" x 12" Light Green w/ Streaks Floor Tile Mastic
57	12" x 12" Light Green w/ Streaks Floor Tile
58	12" x 12" Dark Red Floor Tile w/ Black Specks
59	12" x 12" Dark Red Floor Tile w/ Black Specks Mastic
60	Tongue and Groove Wood Floor
61	12" x 12" Light Blue Floor Tile w/ White Streaks
62	12" x 12" Light Blue Floor Tile w/ White Streaks Mastic
63	12" x 12" Off-White Floor Tile w/ black Streaks
64	12" x 12" Off-White Floor Tile w/ black Streaks Mastic
65	12" x 12" Gray Floor Tile w/ White and Brown Streaks
66	12" x 12" Gray Floor Tile w/ White and Brown Streaks Mastic
67	12" x 12" Pink Floor Tile
68	12" x 12" Pink Floor Tile Mastic
69	12" x 12" Light Brown Floor Tile w/ White Streaks
70	12" x 12" Light Brown Floor Tile w/ White Streaks Mastic
71	9" x 9" Cream Floor Tile w/ Black Specks
72	9" x 9" Cream Floor Tile w/ Black Specks Mastic
73	12" x 12" Gold Floor Tile
74	12" x 12" Light Brown Floor Tile
75	12" x 12" Brown Floor Tile w/ White Specks

76

12" x 12" Gold, Light Brown and Brown w/ White  
Specks Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10	Ceramic tile grout
12	Boiler gasket
13	Boiler gasket
17	Refractory Cement in Doors of Boiler #1
18	Refractory Cement in Doors of Boiler #2
19	Fire Brick in Boiler #1
2 F	12" x 12" Beige Floor Tile
2 G	12" x 12" Brown Floor Tile
2 H	12" x 12" Med. Brown Floor Tile w/ Dark & Light Brown
20	Fire Brick in Boiler #2
22	Fire Brick in Incinerator
26	Insulation Beneath Metal Shell of Incinerator
27	12" x 12" Light Blue mix Floor Tile (checkerboard pat)
28	12" x 12" off-White mix Floor Tile (check pattern)
29	12" x 12" Light Blue Floor Tile and Off-White Mastic
2D	12" x 12" Gray Floor Tile w/Brown Streaks
30	Black sink undercoating
31	Boiler breeching sealant
32	12" x 12" mint Green w/ Brown Specks Floor Tile
33	Mastic assoc w/ 12" x 12" mint Green with Brown Specks Floor Tile
34	Brown & tan ceramic flooring & grout
35	Brown & tan ceramic floor tile mastic
36	12" x 12" Orange Floor Tile
37	12" x 12" Orange Floor Tile Mastic
38	Ceramic Flooring Yellow and White
39	Ceramic flooring yellow & white mastic
3A	9" x 9" Gray Floor Tile w/Pink and White Streaks
4	1' x 1' Acoustical Ceiling Tile
40	Ceramic Flooring Blue/Green and Grout
41	Ceramic flooring blue green mastic
42	12" x 12" Blue w/ Specks Floor Tile
42A	12" x 12" Blue w/ Specks Floor Tile Mastic
43	12" x 12" White w/ Specks Floor Tile
43A	12" x 12" White w/ Specks Floor Tile Mastic
44	12" x 12" Beige w/ Specks Floor Tile
44A	12" x 12" Beige w/ Specks Floor Tile Mastic
45	12" x 12" Beige w/ Specks Floor Tile
45A	12" x 12" Beige w/ Specks Floor Tile Mastic

46	Black mastic
47	12" x 12" Beige Floor Tile
47A	12" x 12" Beige Floor Tile Mastic
48	12" x 12" Brown Floor Tile
48A	12" x 12" Brown Floor Tile Mastic
49	Roof drain insulation
50	12" x 12" Light Brown Floor Tile
50A	12" x 12" Light Brown Floor Tile Mastic
51	Plaster board
52	Yellowish Linoleum and Backing
53	12" x 12" Mint Green w/ Specks Floor Tile
53A	12" x 12" Mint Green w/ Specks Floor Tile Mastic
54	12" x 12" Red Floor Tile
54A	12" x 12" Red Floor Tile Mastic
55	Gray spray-on fireproofing
56	12" x 12" Light Green w/ Streaks Floor Tile Mastic
57	12" x 12" Light Green w/ Streaks Floor Tile
58	12" x 12" Dark Red Floor Tile w/ Black Specks
59	12" x 12" Dark Red Floor Tile w/ Black Specks Mastic
6	Hard plaster
60	Tongue and Groove Wood Floor
61	12" x 12" Light Blue Floor Tile w/ White Streaks
62	12" x 12" Light Blue Floor Tile w/ White Streaks Mastic
63	12" x 12" Off-White Floor Tile w/ black Streaks
64	12" x 12" Off-White Floor Tile w/ black Streaks Mastic
65	12" x 12" Gray Floor Tile w/ White and Brown Streaks
66	12" x 12" Gray Floor Tile w/ White and Brown Streaks Mastic
67	12" x 12" Pink Floor Tile
68	12" x 12" Pink Floor Tile Mastic
69	12" x 12" Light Brown Floor Tile w/ White Streaks
7	9" x 9" Floor Tile
70	12" x 12" Light Brown Floor Tile w/ White Streaks Mastic
71	9" x 9" Cream Floor Tile w/ Black Specks
72	9" x 9" Cream Floor Tile w/ Black Specks Mastic
73	12" x 12" Gold Floor Tile
74	12" x 12" Light Brown Floor Tile
75	12" x 12" Brown Floor Tile w/ White Specks
76	12" x 12" Gold, Light Brown and Brown w/ White Specks Floor Tile Mastic
9	Chimney duct packing
E.1	Joint Insulation on Fiberglass Pipe Insulation
E.2	Joint Compound on Fiberglass Pipe Insulation

J 1	Purple carpet mastic
J 2	Blue carpet mastic
J 3	Multi-colored carpet mastic
J 4	Brown carpet mastic
J 5	Aqua carpet mastic
K	Pink terrazzo
L	Exterior brick - Non-AHERA
M	Exterior brick mortar - Non-AHERA
N	Replacement exterior brick - Non-AHERA
O	Replacement exterior brick mortar - Non-AHERA
P	Exterior brick - Non-AHERA
Q	Exterior brick mortar - Non-AHERA

The following areas were deemed to be inaccessible:

2 FM	12" x 12" Beige Floor Tile Mastic
2 GM	12" x 12" Brown Floor Tile Mastic
2 HM	12" x 12" Med Brown Floor Tile w/ Dark & Light Brown Mastic
21	Flange Gaskets on Well Pumps Beneath Tank
29	12" x 12" Light Blue Floor Tile and Off-White Mastic
2AM	12" x 12" Green Floor Tile w/White Streaks Mastic
2BM	12" x 12" Tan w/Brown Specks Floor Tile Mastic
2CM	12" x 12" Burnt Orange w/ Specks Floor Tile Mastic
2DM	12" x 12" Gray Floor Tile w/Brown Streaks Mastic
2EM	12" x 12" Brown Floor Tile w/Brown and Red Specks Mastic
33	Mastic assoc w/ 12" x 12" mint Green with Brown Specks Floor Tile
35	Brown & tan ceramic floor tile mastic
37	12" x 12" Orange Floor Tile Mastic
39	Ceramic flooring yellow & white mastic
3BM	9" x 9" Dark Brown Floor Tile w/White and Blk Streaks Mastic
3CM	9" x 9" Tan Floor Tile w/Brown Streaks Mastic
3DM	9" x 9" Tan Floor Tile w/Brown and White Streaks Mastic
3EM	9" x 9" Cream Floor Tile w/Brown and White Streaks ma
3FM	9" x 9" Pale Cream Floor Tile w/ White Streaks Mastic
3GM	9" x 9" Tan Floor Tile w/Brown and Blue Dots Mastic
41	Ceramic flooring blue green mastic
42A	12" x 12" Blue w/ Specks Floor Tile Mastic

43A	12" x 12" White w/ Specks Floor Tile Mastic
44A	12" x 12" Beige w/ Specks Floor Tile Mastic
45A	12" x 12" Beige w/ Specks Floor Tile Mastic
47A	12" x 12" Beige Floor Tile Mastic
48A	12" x 12" Brown Floor Tile Mastic
50A	12" x 12" Light Brown Floor Tile Mastic
53A	12" x 12" Mint Green w/ Specks Floor Tile Mastic
54A	12" x 12" Red Floor Tile Mastic
J 2	Blue carpet mastic
J 3	Multi-colored carpet mastic
J 4	Brown carpet mastic
J 5	Aqua carpet mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Devon Jackson, IDPH License # 100-05020. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Smyth School Building 5970 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.



**Table I**  
**Inspector's Reinspection Findings**

---



# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
25	Refractory Cement in Incinerator			1967 Building - Boiler Room	NO_ACBM	MISC								
26	Insulation Beneath Metal Shell of Incinerator	100	SF	1967 Building - Boiler Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
27	12" x 12" Light Blue mix Floor Tile (checkerboard pat)	1,500	SF	1967 Building-2nd floor corridor and room 201	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
28	12" x 12" off-White mix Floor Tile (check pattern)	1,500	SF	1967 Building-2nd floor corridor, Room 201	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
29	12" x 12" Light Blue Floor Tile and Off-White Mastic	3,000	SF	1967 building 2nd floor corridor, Room 201, 100	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
2A	12" x 12" Green w/White Streaks Floor Tile	18,160	SF	1892 Building-113, 117, 119, 123, 213, 215, 217, 219, 313, 315, 317, 319, 321, 323, Computer Lab, Basement Teacher's Lounge, and Basement Storage	CHR	MISC	N	LOC	2	SF	No	ACBM with the potential for damage	5	LOW
2AM	12" x 12" Green Floor Tile w/White Streaks Mastic	18,160	SF	1892 Building-113, 117, 119, 123, 213, 215, 217, 219, 313, 315, 317, 319, 321, 323, Computer Lab, Basement Teacher's Lounge, and Basement Storage	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
2B	12" x 12" Tan w/Brown Specks Floor Tile	400	SF	1892 Building- as Patches in the 2nd & 3rd Floor Hallways, storeroom	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
2BM	12" x 12" Tan w/Brown Specks Floor Tile Mastic	400	SF	1892 Building-as Patches in the 2nd & 3rd Floor Hallways	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
2C	12" x 12" Burnt Orange w/ Specks Floor Tile	8,000	SF	1892 Building- Eng.'s Office, 114, 116, 118, 120, 214, 215, 216, 218, 220, 314, 318, 320	CHR	MISC	N	LOC	130	SF	No	ACBM with the potential for damage	5	LOW
2CM	12" x 12" Burnt Orange w/ Specks Floor Tile Mastic	8,000	SF	1892 Building- Eng.'s Office, 114, 116, 118, 120, 214, 215, 216, 218, 220,	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Streaks Mastic			Auditorium										
3B	9" x 9" Dark Brown Floor Tile w/White and Black Streaks	1,250	SF	1967 1st floor Corridor	CHR	MISC	N	LOC	75	SF	No	ACBM with the potential for damage	5	LOW
3BM	9" x 9" Dark Brown Floor Tile w/White and Blk Streaks Mastic	1,250	SF	1967 1st floor Corridor	CHR	MISC	N	LOC	10	SF	Yes	ACBM with potential for significant damage	2	HIGH
3C	9" x 9" Tan Floor Tile w/Brown Streaks	1,000	SF	1967 Building - 1st floor Corridor	CHR	MISC	N	LOC	25	SF	No	ACBM with the potential for damage	3	LOW
3CM	9" x 9" Tan Floor Tile w/Brown Streaks Mastic	1,000	SF	1967 Building - 1st floor Corridor	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
3D	9" x 9" Tan Floor Tile w/Brown and White Streaks	9,000	SF	1967 Building - 102, 104, 106, 107, 109, 111, 200, 202-207, 209, 211, Teachers Lounge, First Floor Men's Bathroom, and Second Floor Women's Bathroom.	CHR	MISC	N	LOC	50	SF	No	ACBM with the potential for damage	5	LOW
3DM	9" x 9" Tan Floor Tile w/Brown and White Streaks Mastic	9,000	SF	1967 Building - 102, 104, 106, 107, 109, 111, 202-207, 209, 211, Teachers Lounge, First Floor Men's Bathroom, and Second Floor Women's Bathroom.	CHR	MISC	N	LOC	5	SF	No	ACBM with the potential for damage	5	LOW
3E	9" x 9" Cream Floor Tile w/Brown and White Streaks	65	SF	1967 Construction - 1st Floor Landing	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
3EM	9" x 9" Cream Floor Tile w/Brown and White Streaks ma	65	SF	1967 Construction - 1st Floor Landing	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
3F	9" x 9" Pale Cream Floor Tile w/ White Streaks	45	SF	1967 Construction - 1st Floor Landing	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
3FM	9" x 9" Pale Cream Floor Tile w/ White Streaks Mastic	45	SF	1967 Construction - 1st Floor Landing	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
3G	9" x 9" Tan Floor Tile w/Brown and Blue Dots	2,300	SF	1967 Building - Rooms 101 and 103	CHR	MISC	N	DIST	100	SF	No	ACBM with the potential for damage	3	LOW
3GM	9" x 9" Tan Floor Tile w/Brown and Blue Dots Mastic	2,300	SF	1967 Building - Rooms 101 and 103	CHR	MISC	N	DIST	100	SF	Yes	ACBM with the potential for damage	3	MODERATE
4	1' x 1' Acoustical Ceiling Tile	750	SF	1892 Building - Room 115	ASSUMED	MISC	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
40	Ceramic Flooring Blue/Green and Grout	900	SF	1892 Boys & Girls Bathrooms 1,2,3, Floors	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
41	Ceramic flooring blue green mastic	900	SF	1892 Boys & Girls	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the		LOW

# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bathrooms 1,2,3 Floors								potential for damage		
42	12" x 12" Blue w/ Specks Floor Tile	350	SF	Room 100	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
42A	12" x 12" Blue w/ Specks Floor Tile Mastic	350	SF	Room 100	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
43	12" x 12" White w/ Specks Floor Tile	350	SF	Room 100, 116, Patch in 204	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
43A	12" x 12" White w/ Specks Floor Tile Mastic	350	SF	Room 100	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
44	12" x 12" Beige w/ Specks Floor Tile	2,250	SF	Rooms 221 and 223	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
44A	12" x 12" Beige w/ Specks Floor Tile Mastic	2,250	SF	Rooms 221 and 223	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
45	12" x 12" Beige w/ Specks Floor Tile	70	SF	Second Floor Faculty Lounge	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
45A	12" x 12" Beige w/ Specks Floor Tile Mastic	70	SF	Second Floor faculty Lounge	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
46	Black mastic			Basement Storage areas south side of Lunchroom	ASSUMED	MISC								
47	12" x 12" Beige Floor Tile	60	SF	1892 Basement Bathrooms for Engineer Break Room (South Side of Lunchroom)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
47A	12" x 12" Beige Floor Tile Mastic	60	SF	1892 Basement Bathrooms for Engineer Break Room (South Side of Lunchroom)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
48	12" x 12" Brown Floor Tile	600	SF	1892 Basement Engineer's Break Room and Room 114a	ASSUMED	MISC	N	LOC	40	SF	No	ACBM with potential for significant damage	3	LOW
48A	12" x 12" Brown Floor Tile Mastic	600	SF	1892 Basement Engineer's Break Room and Room 114a	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
49	Roof drain insulation		SF	1967 Building	ASSUMED	TSI				SF				
5	Acoustical plaster	5,100	SF	1967 Building - Corridors and Room 101	CHR	SURFACE	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
50	12" x 12" Light Brown Floor Tile	3,300	SF	1892 Building - Fist	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the		LOW

# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor Corridor (East) and Room 118A, 2nd floor hallway patches								potential for damage		
50A	12" x 12" Light Brown Floor Tile Mastic	3,300	SF	1892 Building - First Floor Corridor (East) and Room 118A	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
51	Plaster board			Room 120 Greenhouse	ASSUMED	MISC								
52	Yellowish Linoleum and Backing	50	SF	Room 218 Sink Counter Tops	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
53	12" x 12" Mint Green w/ Specks Floor Tile	100	SF	Second Floor Teachers Lounge (Bathrooms), Room 213, 213 closet	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
53A	12" x 12" Mint Green w/ Specks Floor Tile Mastic	100	SF	Second Floor Teachers Lounge (Bathrooms)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
54	12" x 12" Red Floor Tile	1,800	SF	Basement Book Room and Old Engineer's Office (Laundry)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
54A	12" x 12" Red Floor Tile Mastic	1,800	SF	Basement Book Room and Old Engineer's Office (Laundry)	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
55	Gray spray-on fireproofing	1,800	SF	Old Boiler Room - 1892 (Above metal panels)	ASSUMED	SURFACE	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
56	12" x 12" Light Green w/ Streaks Floor Tile Mastic	160	SF	Rooms 321, 217, 123, 119, 113	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
57	12" x 12" Light Green w/ Streaks Floor Tile	160	SF	Rooms 321, 217, 123, 119, 113	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
58	12" x 12" Dark Red Floor Tile w/ Black Specks	150	SF	Rooms 320, 318, 314, 313 closet, 216, 218, 120, 118, 116, 114, patches in Kitchen	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with the potential for damage	5	LOW
59	12" x 12" Dark Red Floor Tile w/ Black Specks Mastic	150	SF	Rooms 320, 318, 314, 313 closet, 216, 218, 120, 118, 116, 114, patches in Kitchen	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with the potential for damage	5	LOW

# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
6	Hard plaster	8,000	SF	Throughout 1967 Construction	ASSUMED	SURFACE	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
60	Tongue and Groove Wood Floor	2,000	SF	Gym, Auditorium Balcony, Stage, and Seating	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
61	12" x 12" Light Blue Floor Tile w/ White Streaks	10	SF	Rooms 313 closet, patch in kitchen	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
62	12" x 12" Light Blue Floor Tile w/ White Streaks Mastic	10	SF	Rooms 313 closet, patch in kitchen	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
63	12" x 12" Off-White Floor Tile w/ black Streaks	50	SF	2nd Floor Teachers Lounge Bathrooms, 2nd floor hallway patches	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
64	12" x 12" Off-White Floor Tile w/ black Streaks Mastic	50	SF	2nd Floor Teachers Lounge Bathrooms, 2nd floor hallway patches	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
65	12" x 12" Gray Floor Tile w/ White and Brown Streaks	253	SF	Rooms 221, 223, 118, patch in kitchen	ASSUMED	MISC	N	LOC	2	SF	Yes	ACBM with the potential for damage	5	LOW
66	12" x 12" Gray Floor Tile w/ White and Brown Streaks Mastic	253	SF	Rooms 221, 223, 118, patch in kitchen	ASSUMED	MISC	N	LOC	2	SF	Yes	ACBM with the potential for damage	5	LOW
67	12" x 12" Pink Floor Tile	15	SF	Room 116	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
68	12" x 12" Pink Floor Tile Mastic	15	SF	Room 116	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
69	12" x 12" Light Brown Floor Tile w/ White Streaks	100	SF	Patches throughout Annex	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
7	9" x 9" Floor Tile			See HA's 3A- 3G	ASSUMED	MISC								
70	12" x 12" Light Brown Floor Tile w/ White Streaks Mastic	100	SF	Patches throughout Annex	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
71	9" x 9" Cream Floor Tile w/ Black Specks	3	SF	Patch in 203	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
72	9" x 9" Cream Floor Tile w/ Black Specks Mastic	3	SF	Patch in 203	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
73	12" x 12" Gold Floor Tile	80	SF	Rooms 101, 103, 107, 109	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
74	12" x 12" Light Brown Floor Tile	80	SF	Rooms 101, 103, 107, 109	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
75	12" x 12" Brown Floor Tile w/ White Specks	160	SF	Rooms 101, 103, 107, 109	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
76	12" x 12" Gold, Light Brown and Brown w/ White Specks Floor Tile Mastic	320	SF	Rooms 101, 103, 107, 109	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
8	Pipe insulation debris			Crawlspace - Abated	ABATED	MISC								
9	Chimney duct packing		SF	1892 Building -	ASSUMED	TSI				SF				



# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Boiler Room										
A1	Mag-Block Insulation on Boiler #1			1967 Building - Boiler Room	CHR	TSI								
A2	Mag-Block Insulation on Boiler #2			1967 Building - Boiler Room	CHR	TSI								
B	Tank insulation			Abated in 1994	ABATED	TSI								
C	Fiberglass tank insulation			1892 Building - Boiler Room	NOT_TESTED	TSI								
D	Fiberglass pipe insulation			Throughout Facility	NOT_TESTED	TSI								
E.1	Joint Insulation on Fiberglass Pipe Insulation		LF	1967 Building various areas. & Boiler Room	ASSUMED	TSI				LF				
E.2	Joint Compound on Fiberglass Pipe Insulation	120	JOINTS	1892 Building-washroom pipe chases and basement	ASSUMED	TSI	Y	NONE	0	JOINTS	No	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
F	Aircell pipe insulation	2,000	LF	Pipe Chases, 1892 basement, 1967 boiler room, and beneath sink in room 218 (suspected within univent in room 201)	CHR	TSI	Y	NONE	0	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM		MODERATE
G	Joint Insulation on Aircell Pipe Insulation	100	LF	Crawl Spaces, Pipe Chases, 1892 basement, 1967 boiler room, and beneath sink in room 218 (suspected within univent in room 201)	CHR	TSI	Y	NONE	0	LF	No	ACBM with the potential for damage		HIGH
H	Woolfelight pipe insulation	50	LF	1892 Building - Boiler Room and beneath sink in room 218	CHR	TSI	Y	NONE	0	LF	No	ACBM with the potential for damage		LOW
I	Joint Insulation on WoolfeLight Pipe Insulation	50	LF	1892 Building - Boiler Room and beneath sink in room 218	CHR	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE
J 1	Purple carpet mastic		SF	Office	ASSUMED	MISC				SF				
J 2	Blue carpet mastic	1,040	SF	Room 115	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
J 3	Multi-colored carpet mastic	600	SF	Room 104	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the		LOW



# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date	<b><u>9/22/2022</u></b>
Inspector Name	<b><u>Devon Jackson</u></b>
<b><u>100-05020</u></b>	<b><u>5/15/2023</u></b>
Inspector's IDPH License Number / Expiration Date	

### Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	
12	
13	
14	
15	
16	
17	Not observed 2022
18	Not observed 2022
19	Not observed 2022
2 F	
2 FM	
2 G	
2 GM	
2 H	
2 HM	
20	Not observed 2022
21	
22	Not observed 2022
23	
25	
26	
27	

# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
28	
29	
2A	Not observed in lounge, damage in 113
2AM	Not observed in lounge
2B	
2BM	
2C	Damage in rooms 114, 116, 218, and 219
2CM	
2D	
2DM	
2E	Damage observed in 2nd and 3rd floor corridors
2EM	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
3A	Damage in Auditorium
3AM	
3B	Damage located on 1st floor corridor
3BM	Damage in 1st floor corridor
3C	Damage located on 1st floor corridor
3CM	
3D	Damage located in 1967 building

# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
3DM	Damage in 106
3E	
3EM	
3F	
3FM	
3G	Damage located in 1967 Building, Rooms 101 and 103
3GM	Damage located in 1967 Building, Rooms 101 and 103
4	
40	
41	
42	
42A	
43	
43A	
44	
44A	
45	
45A	
46	Not observed 2022
47	
47A	
48	Physical damage was observed in room 114. however, areas of deterioration were observed throughout room where tile appeared to maybe buckle
48A	
49	Not observed 2022
5	
50	
50A	
51	Not observed 2022

# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
52	
53	
53A	
54	Not observed in engineer's office
54A	
55	
56	
57	
58	Damage in 218
59	Damage in 218
6	
60	
61	
62	
63	
64	
65	Damage in 223
66	Damage in 223
67	
68	
69	
7	Not observed 2022
70	
71	
72	
73	
74	
75	
76	

# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
8	
9	Not observed 2022
A1	Not observed 2022
A2	Not observed 2022
B	
C	Not observed 2022
D	Not observed 2022
E.1	Not observed 2022
E.2	
F	
G	
H	
I	Room 218 inaccessible - 2022
J 1	Not observed 2022
J 2	
J 3	
J 4	
J 5	
K	
L	
M	
N	
O	
P	
Q	
R	
S	
T	
TM	

# Chicago Public Schools

School Smyth School Unit 25411 Building ID 5970

Address 1059 W. 13th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
V	
VG	



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Smyth School  
Address 1059 W. 13th St.

Unit 25411  
Chicago, IL, 60608

Building ID 5970  
Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Hard plaster			Throughout 1892 Construction	No ACBM	SURFACE					
10	Ceramic tile grout	600	SF	Bathrooms of 1967 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Drywall			Basement of Both Additions	No ACBM	MISC					
12	Boiler gasket	5	LF	1892 Building - Boiler #1 in Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
13	Boiler gasket	5	LF	1892 Building - Boiler #2 in Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
14	Wall molding			Gym	No ACBM	MISC					
15	4" Black vinyl baseboard			1892 Building - Boy's 1st Floor Bathroom by 118	No ACBM	MISC					
16	4" Black vinyl baseboard mastic			1892 Building - Boy's 1st Floor Bathroom by 118	No ACBM	MISC					
17	Refractory Cement in Doors of Boiler #1			1892 Building - Boiler Room	Assumed	MISC					Follow O&M Plan
18	Refractory Cement in Doors of Boiler #2			1892 Building - Boiler Room	Assumed	MISC					Follow O&M Plan
19	Fire Brick in Boiler #1			1892 Building - Boiler Room	Assumed	MISC					Follow O&M Plan
2 F	12" x 12" Beige Floor Tile	700	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2 FM	12" x 12" Beige Floor Tile Mastic	700	SF	Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2 G	12" x 12" Brown Floor Tile	700	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2 GM	12" x 12" Brown Floor Tile Mastic	700	SF	Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2 H	12" x 12" Med. Brown Floor Tile w/ Dark & Light Brown	470	SF	2nd Floor Teacher's Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2 HM	12" x 12" Med Brown Floor Tile w/ Dark & Light Brown Mastic	470	SF	2nd Floor Teacher's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Fire Brick in Boiler #2			1892 Building - Boiler Room	Assumed	MISC					Follow O&M Plan
21	Flange Gaskets on Well Pumps Beneath Tank	3	SF	1967 Building - Boiler Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Fire Brick in Incinerator			1892 Building - Boiler Room	Assumed	MISC					Follow O&M Plan
23	Ceramic Tile Grout in Bathrooms and Exits			1962 Construction	No ACBM	MISC					
25	Refractory Cement in Incinerator			1967 Building - Boiler Room	No ACBM	MISC					
26	Insulation Beneath Metal Shell of Incinerator	100	SF	1967 Building - Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12" x 12" Light Blue mix Floor Tile (checkerboard pat)	1,500	SF	1967 Building-2nd floor corridor and room 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12" x 12" off-White mix Floor Tile (check pattern)	1,500	SF	1967 Building-2nd floor corridor, Room 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12" x 12" Light Blue Floor Tile and Off-White Mastic	3,000	SF	1967 building 2nd floor cooridor, Room 201, 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Smyth School  
Address 1059 W. 13th St.

Unit 25411  
Chicago, IL, 60608

Building ID 5970  
Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
2A	12" x 12" Green w/White Streaks Floor Tile	18,160	SF	1892 Building-113, 117, 119, 123, 213, 215, 217, 219, 313, 315, 317, 319, 321, 323, Computer Lab, Basement Teacher's Lounge, and Basement Storage	Chrysotile	MISC	No	2	SF	6 ACBM with the potential for damage	Follow O&M Plan
2AM	12" x 12" Green Floor Tile w/White Streaks Mastic	18,160	SF	1892 Building-113, 117, 119, 123, 213, 215, 217, 219, 313, 315, 317, 319, 321, 323, Computer Lab, Basement Teacher's Lounge, and Basement Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2B	12" x 12" Tan w/Brown Specks Floor Tile	400	SF	1892 Building- as Patches in the 2nd & 3rd Floor Hallways, storeroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2BM	12" x 12" Tan w/Brown Specks Floor Tile Mastic	400	SF	1892 Building-as Patches in the 2nd & 3rd Floor Hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2C	12" x 12" Burnt Orange w/ Specks Floor Tile	8,000	SF	1892 Building-Eng.'s Office, 114, 116, 118, 120, 214, 215, 216, 218, 220, 314, 318, 320	Chrysotile	MISC	No	130	SF	6 ACBM with the potential for damage	Repair
2CM	12" x 12" Burnt Orange w/ Specks Floor Tile Mastic	8,000	SF	1892 Building-Eng.'s Office, 114, 116, 118, 120, 214, 215, 216, 218, 220, 314, 318, 320	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2D	12" x 12" Gray Floor Tile w/Brown Streaks	1,500	SF	1892 Building-Principal's Office, Main Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2DM	12" x 12" Gray Floor Tile w/Brown Streaks Mastic	1,500	SF	1892 Building-Principal's Office, Main Offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2E	12" x 12" Brown Floor Tile w/Brown and Red Specks	4,000	SF	1892 Construction - 2nd and 3rd Floor Corridors	Chrysotile	MISC	No	1,200	SF	5 ACBM with potential for significant damage	Repair
2EM	12" x 12" Brown Floor Tile w/Brown and Red Specks Mastic	4,000	SF	1892 Construction - 2nd and 3rd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Black sink undercoating	24	SF	1967-103,104,106,107,109,201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Boiler breaching sealant	6	LF	1967-boiler room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
32	12" x 12" mint Green w/ Brown Specks Floor Tile	50	SF	1892 Building 2nd floor faculty washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Mastic assoc w/ 12" x 12" mint Green with Brown Specks Floor Tile	50	SF	1892 bldg 2nd floor faculty washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Brown & tan ceramic flooring & grout	1,600	SF	1967 Building Boys & Giros Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Smyth School  
Address 1059 W. 13th St.

Unit 25411  
Chicago, IL, 60608

Building ID 5970  
Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				1st and 2nd Floor							
35	Brown & tan ceramic floor tile mastic	1,600	SF	1967 Building Boys & Girls Bathrooms 1st & 2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" x 12" Orange Floor Tile	920	SF	1882 Building Room 312, 118, 116, Kitchen (patch)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12" x 12" Orange Floor Tile Mastic	900	SF	1892 Building Room 312	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Ceramic Flooring Yellow and White	900	SF	1892 Building Boys & Girls Bathrooms 1,2,3 Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Ceramic flooring yellow & white mastic	900	SF	1892 Boys & Girls Bathroom 1,2,3 Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3A	9" x 9" Gray Floor Tile w/Pink and White Streaks	1,400	SF	1892 Building - Auditorium	Assumed	MISC	No	50	SF	6 ACBM with the potential for damage	Repair
3AM	9" x 9" Gray Floor Tile w/Pink and White Streaks Mastic			1892 Building - Auditorium	No ACBM	MISC					
3B	9" x 9" Dark Brown Floor Tile w/White and Black Streaks	1,250	SF	1967 1st floor Corridor	Chrysotile	MISC	No	75	SF	6 ACBM with the potential for damage	Repair
3BM	9" x 9" Dark Brown Floor Tile w/White and Blk Streaks Mastic	1,250	SF	1967 1st floor Corridor	Chrysotile	MISC	No	10	SF	5 ACBM with potential for significant damage	Remove
3C	9" x 9" Tan Floor Tile w/Brown Streaks	1,000	SF	1967 Building - 1st floor Corridor	Chrysotile	MISC	No	25	SF	6 ACBM with the potential for damage	Repair
3CM	9" x 9" Tan Floor Tile w/Brown Streaks Mastic	1,000	SF	1967 Building - 1st floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3D	9" x 9" Tan Floor Tile w/Brown and White Streaks	9,000	SF	1967 Building - 102, 104, 106, 107, 109, 111, 200, 202-207, 209, 211, Teachers Lounge, First Floor Men's Bathroom, and Second Floor Women's Bathroom.	Chrysotile	MISC	No	50	SF	6 ACBM with the potential for damage	Repair
3DM	9" x 9" Tan Floor Tile w/Brown and White Streaks Mastic	9,000	SF	1967 Building - 102, 104, 106, 107, 109, 111, 202-207, 209, 211, Teachers Lounge, First Floor Men's Bathroom, and Second Floor Women's Bathroom.	Chrysotile	MISC	No	5	SF	6 ACBM with the potential for damage	Repair
3E	9" x 9" Cream Floor Tile w/Brown and White Streaks	65	SF	1967 Construction - 1st Floor Landing	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3EM	9" x 9" Cream Floor Tile w/Brown and White Streaks ma	65	SF	1967 Construction - 1st Floor Landing	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3F	9" x 9" Pale Cream Floor Tile w/ White Streaks	45	SF	1967 Construction - 1st Floor Landing	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3FM	9" x 9" Pale Cream Floor Tile w/ White Streaks Mastic	45	SF	1967 Construction - 1st Floor Landing	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3G	9" x 9" Tan Floor Tile w/Brown and Blue Dots	2,300	SF	1967 Building - Rooms 101 and 103	Chrysotile	MISC	No	100	SF	6 ACBM with the potential for damage	Repair

# Chicago Public Schools

School Smyth School  
Address 1059 W. 13th St.

Unit 25411  
Chicago, IL, 60608

Building ID 5970  
Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
3GM	9" x 9" Tan Floor Tile w/Brown and Blue Dots Mastic	2,300	SF	1967 Building - Rooms 101 and 103	Chrysotile	MISC	No	100	SF	6 ACBM with the potential for damage	Repair
4	1' x 1' Acoustical Ceiling Tile	750	SF	1892 Building - Room 115	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
40	Ceramic Flooring Blue/Green and Grout	900	SF	1892 Boys & Girls Bathrooms 1,2,3, Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Ceramic flooring blue green mastic	900	SF	1892 Boys & Girls Bathrooms 1,2,3 Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" x 12" Blue w/ Specks Floor Tile	350	SF	Room 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42A	12" x 12" Blue w/ Specks Floor Tile Mastic	350	SF	Room 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12" x 12" White w/ Specks Floor Tile	350	SF	Room 100, 116, Patch in 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43A	12" x 12" White w/ Specks Floor Tile Mastic	350	SF	Room 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12" x 12" Beige w/ Specks Floor Tile	2,250	SF	Rooms 221 and 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44A	12" x 12" Beige w/ Specks Floor Tile Mastic	2,250	SF	Rooms 221 and 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12" x 12" Beige w/ Specks Floor Tile	70	SF	Second Floor Faculty Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45A	12" x 12" Beige w/ Specks Floor Tile Mastic	70	SF	Second Floor faculty Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Black mastic			Basement Storage areas south side of Lunchroom	Assumed	MISC					Follow O&M Plan
47	12" x 12" Beige Floor Tile	60	SF	1892 Basement Bathrooms for Engineer Break Room (South Side of Lunchroom)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47A	12" x 12" Beige Floor Tile Mastic	60	SF	1892 Basement Bathrooms for Engineer Break Room (South Side of Lunchroom)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12" x 12" Brown Floor Tile	600	SF	1892 Basement Engineer's Break Room and Room 114a	Assumed	MISC	No	40	SF	5 ACBM with potential for significant damage	Repair
48A	12" x 12" Brown Floor Tile Mastic	600	SF	1892 Basement Engineer's Break Room and Room 114a	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Roof drain insulation		SF	1967 Building	Assumed	TSI			SF		Follow O&M Plan
5	Acoustical plaster	5,100	SF	1967 Building - Corridors and Room 101	Chrysotile	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
50	12" x 12" Light Brown Floor Tile	3,300	SF	1892 Building - First Floor Corridor (East) and Room 118A, 2nd floor hallway patches	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50A	12" x 12" Light Brown Floor Tile Mastic	3,300	SF	1892 Building - First Floor Corridor (East) and Room 118A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Smyth School  
Address 1059 W. 13th St.

Unit 25411  
Chicago, IL, 60608

Building ID 5970  
Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
51	Plaster board			Room 120 Greenhouse	Assumed	MISC					Follow O&M Plan
52	Yellowish Linoleum and Backing	50	SF	Room 218 Sink Counter Tops	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12" x 12" Mint Green w/ Specks Floor Tile	100	SF	Second Floor Teachers Lounge (Bathrooms), Room 213, 213 closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53A	12" x 12" Mint Green w/ Specks Floor Tile Mastic	100	SF	Second Floor Teachers Lounge (Bathrooms)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" Red Floor Tile	1,800	SF	Basement Book Room and Old Engineer's Office (Laundry)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54A	12" x 12" Red Floor Tile Mastic	1,800	SF	Basement Book Room and Old Engineer's Office (Laundry)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Gray spray-on fireproofing	1,800	SF	Old Boiler Room - 1892 (Above metal panels)	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
56	12" x 12" Light Green w/ Streaks Floor Tile Mastic	160	SF	Rooms 321, 217, 123, 119, 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12" x 12" Light Green w/ Streaks Floor Tile	160	SF	Rooms 321, 217, 123, 119, 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12" x 12" Dark Red Floor Tile w/ Black Specks	150	SF	Rooms 320, 318, 314, 313 closet, 216, 218, 120, 118, 116, 114, patches in Kitchen	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Repair
59	12" x 12" Dark Red Floor Tile w/ Black Specks Mastic	150	SF	Rooms 320, 318, 314, 313 closet, 216, 218, 120, 118, 116, 114, patches in Kitchen	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Repair
6	Hard plaster	8,000	SF	Throughout 1967 Construction	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Tongue and Groove Wood Floor	2,000	SF	Gym, Auditorium Balcony, Stage, and Seating	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12" x 12" Light Blue Floor Tile w/ White Streaks	10	SF	Rooms 313 closet, patch in kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12" x 12" Light Blue Floor Tile w/ White Streaks Mastic	10	SF	Rooms 313 closet, patch in kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12" x 12" Off-White Floor Tile w/ black Streaks	50	SF	2nd Floor Teachers Lounge Bathrooms, 2nd floor hallway patches	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12" x 12" Off-White Floor Tile w/ black Streaks Mastic	50	SF	2nd Floor Teachers Lounge Bathrooms, 2nd floor hallway patches	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12" x 12" Gray Floor Tile w/ White and Brown Streaks	253	SF	Rooms 221, 223, 118, patch in kitchen	Assumed	MISC	No	2	SF	6 ACBM with the potential for damage	Repair
66	12" x 12" Gray Floor Tile w/ White and Brown Streaks Mastic	253	SF	Rooms 221, 223, 118, patch in kitchen	Assumed	MISC	No	2	SF	6 ACBM with the potential for damage	Repair
67	12" x 12" Pink Floor Tile	15	SF	Room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Pink Floor Tile Mastic	15	SF	Room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Smyth School  
Address 1059 W. 13th St.

Unit 25411  
Chicago, IL, 60608

Building ID 5970  
Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
69	12" x 12" Light Brown Floor Tile w/ White Streaks	100	SF	Patches throughout Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7	9" x 9" Floor Tile			See HA's 3A- 3G	Assumed	MISC					Follow O&M Plan
70	12" x 12" Light Brown Floor Tile w/ White Streaks Mastic	100	SF	Patches throughout Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	9" x 9" Cream Floor Tile w/ Black Specks	3	SF	Patch in 203	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	9" x 9" Cream Floor Tile w/ Black Specks Mastic	3	SF	Patch in 203	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12" x 12" Gold Floor Tile	80	SF	Rooms 101, 103, 107, 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12" x 12" Light Brown Floor Tile	80	SF	Rooms 101, 103, 107, 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12" x 12" Brown Floor Tile w/ White Specks	160	SF	Rooms 101, 103, 107, 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12" x 12" Gold, Light Brown and Brown w/ White Specks Floor Tile Mastic	320	SF	Rooms 101, 103, 107, 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	Pipe insulation debris			Crawlspace - Abated	Abated	MISC					
9	Chimney duct packing		SF	1892 Building - Boiler Room	Assumed	TSI			SF		Follow O&M Plan
A1	Mag-Block Insulation on Boiler #1			1967 Building - Boiler Room	Chrysotile	TSI					Follow O&M Plan
A2	Mag-Block Insulation on Boiler #2			1967 Building - Boiler Room	Chrysotile	TSI					Follow O&M Plan
B	Tank insulation			Abated in 1994	Abated	TSI					
C	Fiberglass tank insulation			1892 Building - Boiler Room	Not Tested	TSI					Follow O&M Plan
D	Fiberglass pipe insulation			Throughout Facility	Not Tested	TSI					Follow O&M Plan
E.1	Joint Insulation on Fiberglass Pipe Insulation		LF	1967 Building various areas. & Boiler Room	Assumed	TSI			LF		Follow O&M Plan
E.2	Joint Compound on Fiberglass Pipe Insulation	120	JOINTS	1892 Building- washroom pipe chases and basement	Assumed	TSI	Yes	0	JOINTS	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
F	Aircell pipe insulation	2,000	LF	Pipe Chases, 1892 basement, 1967 boiler room, and beneath sink in room 218 (suspected within univent in room 201)	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
G	Joint Insulation on Aircell Pipe Insulation	100	LF	Crawl Spaces, Pipe Chases, 1892 basement, 1967 boiler room, and beneath sink in room 218 (suspected within univent in room 201)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	Woolfelight pipe insulation	50	LF	1892 Building - Boiler Room and beneath sink in room 218	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I	Joint Insulation on WoolfeLight Pipe Insulation	50	LF	1892 Building - Boiler Room and beneath sink in room 218	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J 1	Purple carpet mastic		SF	Office	Assumed	MISC			SF		Follow O&M Plan
J 2	Blue carpet mastic	1,040	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Smyth School  
**Address** 1059 W. 13th St.

**Unit** 25411  
Chicago, IL, 60608

**Building ID** 5970  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
J 3	Multi-colored carpet mastic	600	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J 4	Brown carpet mastic	600	SF	Basement Band Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J 5	Aqua carpet mastic	1,380	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	Pink terrazzo	1,200	SF	1967 Building - Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	Exterior brick - Non-AHERA			1892 Building Exterior	Assumed	MISC					Follow O&M Plan
M	Exterior brick mortar - Non-AHERA			1892 Building - Exterior	Assumed	MISC					Follow O&M Plan
N	Replacement exterior brick - Non-AHERA			1892 Building Exterior	Assumed	MISC					Follow O&M Plan
O	Replacement exterior brick mortar - Non-AHERA			1892 Building - Exterior	Assumed	MISC					Follow O&M Plan
P	Exterior brick - Non-AHERA			1967 Building Exterior	Assumed	MISC					Follow O&M Plan
Q	Exterior brick mortar - Non-AHERA			1967 Building - Exterior	Assumed	MISC					Follow O&M Plan
R	Boiler #1 gasket #1	600	LF	1967 Building - Boiler Room	Chrysotile	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
S	Boiler #2 gasket #2	600	LF	1967 Building - Boiler Room	Chrysotile	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
T	Linoleum flooring			Basement Cafeteria	No ACBM	MISC					
TM	Linoleum flooring mastic			Basement Cafeteria	No ACBM	MISC					
V	Ceramic tile			1892 Building - Bathrooms	No ACBM	MISC					
VG	Ceramic tile grout			Bathrooms of 1892 Construction	No ACBM	MISC					



# Chicago Public Schools

**School** Smyth School  
**Address** 1059 W. 13th St.

**Unit** 25411  
 Chicago, IL, 60608

**Building ID** 5970  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	10/12/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
2 F	
2 FM	
2 G	
2 GM	
2 H	
2 HM	
20	
21	
22	
23	
25	

# Chicago Public Schools

**School** Smyth School  
**Address** 1059 W. 13th St.

**Unit** 25411  
 Chicago, IL, 60608

**Building ID** 5970  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
26	
27	
28	
29	
2A	
2AM	
2B	
2BM	
2C	
2CM	
2D	
2DM	
2E	
2EM	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
3A	
3AM	
3B	

# Chicago Public Schools

**School** Smyth School  
**Address** 1059 W. 13th St.

**Unit** 25411  
Chicago, IL, 60608

**Building ID** 5970  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
3BM	
3C	
3CM	
3D	
3DM	
3E	
3EM	
3F	
3FM	
3G	
3GM	
4	
40	
41	
42	
42A	
43	
43A	
44	
44A	
45	
45A	
46	
47	
47A	
48	
48A	

# Chicago Public Schools

**School** Smyth School  
**Address** 1059 W. 13th St.

**Unit** 25411  
 Chicago, IL, 60608

**Building ID** 5970  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
49	
5	
50	
50A	
51	
52	
53	
53A	
54	
54A	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	

# Chicago Public Schools

**School** Smyth School  
**Address** 1059 W. 13th St.

**Unit** 25411  
 Chicago, IL, 60608

**Building ID** 5970  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
70	
71	
72	
73	
74	
75	
76	
8	
9	
A1	
A2	
B	
C	
D	
E.1	
E.2	
F	
G	
H	
I	
J 1	
J 2	
J 3	
J 4	
J 5	
K	
L	

# Chicago Public Schools

**School** Smyth School  
**Address** 1059 W. 13th St.

**Unit** 25411  
Chicago, IL, 60608

**Building ID** 5970  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
M	
N	
O	
P	
Q	
R	
S	
T	
TM	
V	
VG	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2022 AHERA REINSPECTION***



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Hard plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1892 Construction**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Hard plaster**

MATERIAL LOCATION: **Throughout 1892 Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Ceramic tile grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Bathrooms of 1967 Building**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Ceramic tile grout**  
MATERIAL LOCATION: **Bathrooms of 1967 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement of Both Additions**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Basement of Both Additions**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Boiler gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building - Boiler #1 in Boiler Room**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Boiler gasket**  
MATERIAL LOCATION: **1892 Building - Boiler #1 in Boiler Room**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Boiler gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building - Boiler #2 in Boiler Room**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Boiler gasket**

MATERIAL LOCATION: **1892 Building - Boiler #2 in Boiler Room**

MATERIAL QUANTITY: **5**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Wall molding**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Wall molding**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **4" Black vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Boy's 1st Floor Bathroom by 118**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **4" Black vinyl baseboard**

MATERIAL LOCATION: **1892 Building - Boy's 1st Floor Bathroom by 118**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **4" Black vinyl baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Boy's 1st Floor Bathroom by 118**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **4" Black vinyl baseboard mastic**

MATERIAL LOCATION: **1892 Building - Boy's 1st Floor Bathroom by 118**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Refractory Cement in Doors of Boiler #1**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Refractory Cement in Doors of Boiler #1**

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Refractory Cement in Doors of Boiler #2**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Refractory Cement in Doors of Boiler #2**

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Fire Brick in Boiler #1**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Fire Brick in Boiler #1**

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 F**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2 F**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 FM**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2 FM**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 G**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2 G**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 GM**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2 GM**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 H**  
MATERIAL DESCRIPTION: **12" x 12" Med. Brown Floor Tile w/ Dark & Light Brown**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Teacher's Lounge**

MATERIAL QUANTITY: **470**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2 H**  
MATERIAL DESCRIPTION: **12" x 12" Med. Brown Floor Tile w/ Dark & Light Brown**  
MATERIAL LOCATION: **2nd Floor Teacher's Lounge**  
MATERIAL QUANTITY: **470** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 HM**  
MATERIAL DESCRIPTION: **12" x 12" Med Brown Floor Tile w/ Dark & Light Brown Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Teacher's Lounge**

MATERIAL QUANTITY: **470**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2 HM**  
MATERIAL DESCRIPTION: **12" x 12" Med Brown Floor Tile w/ Dark & Light Brown Mastic**  
MATERIAL LOCATION: **2nd Floor Teacher's Lounge**  
MATERIAL QUANTITY: **470** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Fire Brick in Boiler #2**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Fire Brick in Boiler #2**

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Flange Gaskets on Well Pumps Beneath Tank**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building - Boiler Room**

MATERIAL QUANTITY: **3**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Flange Gaskets on Well Pumps Beneath Tank**

MATERIAL LOCATION: **1967 Building - Boiler Room**

MATERIAL QUANTITY: **3**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Fire Brick in Incinerator**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Fire Brick in Incinerator**

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Ceramic Tile Grout in Bathrooms and Exits**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1962 Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Ceramic Tile Grout in Bathrooms and Exits**

MATERIAL LOCATION: **1962 Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Refractory Cement in Incinerator**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Refractory Cement in Incinerator**

MATERIAL LOCATION: **1967 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Insulation Beneath Metal Shell of Incinerator**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building - Boiler Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Insulation Beneath Metal Shell of Incinerator**

MATERIAL LOCATION: **1967 Building - Boiler Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue mix Floor Tile (checkerboard pat)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building-2nd floor corridor and room 201**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue mix Floor Tile (checkerboard pat)**  
MATERIAL LOCATION: **1967 Building-2nd floor corridor and room 201**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" x 12" off-White mix Floor Tile (check pattern)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building-2nd floor corridor, Room 201**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" x 12" off-White mix Floor Tile (check pattern)**  
MATERIAL LOCATION: **1967 Building-2nd floor corridor, Room 201**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile and Off-White Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 building 2nd floor cooridor, Room 201, 100**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile and Off-White Mastic**

MATERIAL LOCATION: **1967 building 2nd floor cooridor, Room 201, 100**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2A**  
MATERIAL DESCRIPTION: **12" x 12" Green w/White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building-113, 117, 119, 123, 213, 215, 217, 219, 313, 315, 317, 319, 321, 323, Computer Lab, Basement Teacher's Lounge, and Basement Storage**  
MATERIAL QUANTITY: **18160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not observed in lounge, damage in 113**

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2A**  
MATERIAL DESCRIPTION: **12" x 12" Green w/White Streaks Floor Tile**  
MATERIAL LOCATION: **1892 Building-113, 117, 119, 123, 213, 215, 217, 219, 313, 315, 317, 319, 321, 323, Computer Lab, Basement Teacher's Lounge, and Basement Storage**  
MATERIAL QUANTITY: **18160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2AM**  
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile w/White Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1892 Building-113, 117, 119, 123, 213, 215, 217, 219, 313, 315, 317, 319, 321, 323, Computer Lab, Basement Teacher's Lounge, and Basement Storage**

MATERIAL QUANTITY: **18160** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in lounge**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2AM**  
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile w/White Streaks Mastic**  
MATERIAL LOCATION: **1892 Building-113, 117, 119, 123, 213, 215, 217, 219, 313, 315, 317, 319, 321, 323, Computer Lab, Basement Teacher's Lounge, and Basement Storage**  
MATERIAL QUANTITY: **18160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2B**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building- as Patches in the 2nd & 3rd Floor Hallways, storeroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2B**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/Brown Specks Floor Tile**  
MATERIAL LOCATION: **1892 Building- as Patches in the 2nd & 3rd Floor Hallways, storeroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2BM**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/Brown Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building-as Patches in the 2nd & 3rd Floor Hallways**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2BM**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **1892 Building-as Patches in the 2nd & 3rd Floor Hallways**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2C**  
MATERIAL DESCRIPTION: **12" x 12" Burnt Orange w/ Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage  
Delamination**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building-Eng.'s Office, 114, 116, 118, 120, 214, 215, 216, 218, 220, 314, 318, 320**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **8000** DAMAGE UNITS: **SF**  
COMMENTS: **Damage in rooms 114, 116, 218, and 219**

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2C**  
MATERIAL DESCRIPTION: **12" x 12" Burnt Orange w/ Specks Floor Tile**  
MATERIAL LOCATION: **1892 Building-Eng.'s Office, 114, 116, 118, 120, 214, 215, 216, 218, 220, 314, 318, 320**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **130** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2CM**  
MATERIAL DESCRIPTION: **12" x 12" Burnt Orange w/ Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1892 Building-Eng.'s Office, 114, 116, 118, 120, 214, 215, 216, 218, 220, 314, 318, 320**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2CM**  
MATERIAL DESCRIPTION: **12" x 12" Burnt Orange w/ Specks Floor Tile Mastic**  
MATERIAL LOCATION: **1892 Building-Eng.'s Office, 114, 116, 118, 120, 214, 215, 216, 218, 220, 314, 318, 320**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2D**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Brown Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building-Principal's Office, Main Offices**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2D**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Brown Streaks**  
MATERIAL LOCATION: **1892 Building-Principal's Office, Main Offices**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2DM**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Brown Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building-Principal's Office, Main Offices**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2DM**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Brown Streaks Mastic**  
MATERIAL LOCATION: **1892 Building-Principal's Office, Main Offices**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2E**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Brown and Red Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Construction - 2nd and 3rd Floor Corridors**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **4000** DAMAGE UNITS: **SF**  
COMMENTS: **Damage observed in 2nd and 3rd floor corridors**

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2E**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Brown and Red Specks**  
MATERIAL LOCATION: **1892 Construction - 2nd and 3rd Floor Corridors**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1200** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2EM**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Brown and Red Specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Construction - 2nd and 3rd Floor Corridors**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **2EM**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Brown and Red Specks Mastic**  
MATERIAL LOCATION: **1892 Construction - 2nd and 3rd Floor Corridors**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Black sink undercoating**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967-103,104,106,107,109,201**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Black sink undercoating**  
MATERIAL LOCATION: **1967-103,104,106,107,109,201**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Boiler breeching sealant**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967-boiler room**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Boiler breaching sealant**

MATERIAL LOCATION: **1967-boiler room**

MATERIAL QUANTITY: **6**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12" x 12" mint Green w/ Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building 2nd floor faculty washrooms**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12" x 12" mint Green w/ Brown Specks Floor Tile**  
MATERIAL LOCATION: **1892 Building 2nd floor faculty washrooms**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Mastic assoc w/ 12" x 12" mint Green with Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 bldg 2nd floor faculty washrooms**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Mastic assoc w/ 12" x 12" mint Green with Brown Specks Floor Tile**  
MATERIAL LOCATION: **1892 bldg 2nd floor faculty washrooms**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Brown & tan ceramic flooring & grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building Boys & Giros Bathrooms 1st and 2nd Floor**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Brown & tan ceramic flooring & grout**  
MATERIAL LOCATION: **1967 Building Boys & Giros Bathrooms 1st and 2nd Floor**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Brown & tan ceramic floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building Boys & Girls Bathrooms 1st & 2nd Floor**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Brown & tan ceramic floor tile mastic**  
MATERIAL LOCATION: **1967 Building Boys & Girls Bathrooms 1st & 2nd Floor**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1982 Building Room 312, 118, 116, Kitchen (patch)**  
MATERIAL QUANTITY: **920** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile**  
MATERIAL LOCATION: **1982 Building Room 312, 118, 116, Kitchen (patch)**  
MATERIAL QUANTITY: **920** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building Room 312**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile Mastic**

MATERIAL LOCATION: **1892 Building Room 312**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Ceramic Flooring Yellow and White**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building Boys & Gilrs Bathrooms 1,2,3 Floors**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Ceramic Flooring Yellow and White**  
MATERIAL LOCATION: **1892 Building Boys & Gilrs Bathrooms 1,2,3 Floors**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Ceramic flooring yellow & white mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Boys & Girls Bathroom 1,2,3 Floors**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Ceramic flooring yellow & white mastic**  
MATERIAL LOCATION: **1892 Boys & Girls Bathroom 1,2,3 Floors**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3A**  
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/Pink and White Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage  
Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage  
Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building - Auditorium**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage in Auditorium**

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3A**  
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/Pink and White Streaks**  
MATERIAL LOCATION: **1892 Building - Auditorium**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3AM**  
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/Pink and White Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3AM**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/Pink and White Streaks Mastic**

MATERIAL LOCATION: **1892 Building - Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3B**  
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile w/White and Black Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 1st floor Corridor**  
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1250** DAMAGE UNITS: **SF**  
COMMENTS: **Damage located on 1st floor corridor**

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3B**  
MATERIAL DESCRIPTION: **9" x 9"Dark Brown Floor Tile w/White and Black Streaks**  
MATERIAL LOCATION: **1967 1st floor Corridor**  
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3BM**  
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile w/White and Blk Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Delamination**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **1967 1st floor Corridor**  
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1250** DAMAGE UNITS: **SF**  
COMMENTS: **Damage in 1st floor corridor**

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3BM**  
MATERIAL DESCRIPTION: **9" x 9"Dark Brown Floor Tile w/White and Blk Streaks Mastic**  
MATERIAL LOCATION: **1967 1st floor Corridor**  
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3C**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration  
Delamination**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building - 1st floor Corridor**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS: **Damage located on 1st floor corridor**

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3C**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown Streaks**  
MATERIAL LOCATION: **1967 Building - 1st floor Corridor**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3CM**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building - 1st floor Corridor**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3CM**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown Streaks Mastic**  
MATERIAL LOCATION: **1967 Building - 1st floor Corridor**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3D**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown and White Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building - 102, 104, 106, 107, 109, 111, 200, 202-207, 209, 211, Teachers Lounge, First Floor Men's Bathroom, and Second Floor Women's Bathroom.**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **9000** DAMAGE UNITS: **SF**  
COMMENTS: **Damage located in 1967 building**

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3D**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown and White Streaks**  
MATERIAL LOCATION: **1967 Building - 102, 104, 106, 107, 109, 111, 200, 202-207, 209, 211, Teachers Lounge, First Floor Men's Bathroom, and Second Floor Women's Bathroom.**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3DM**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown and White Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building - 102, 104, 106, 107, 109, 111, 202-207, 209, 211, Teachers Lounge, First Floor Men's Bathroom, and Second Floor Women's Bathroom.**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage in 106**

Inspector's Signature:



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3DM**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown and White Streaks Mastic**  
MATERIAL LOCATION: **1967 Building - 102, 104, 106, 107, 109, 111, 202-207, 209, 211, Teachers Lounge, First Floor Men's Bathroom, and Second Floor Women's Bathroom.**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3E**  
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/Brown and White Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Construction - 1st Floor Landing**  
MATERIAL QUANTITY: **65** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3E**  
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/Brown and White Streaks**  
MATERIAL LOCATION: **1967 Construction - 1st Floor Landing**  
MATERIAL QUANTITY: **65** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3EM**  
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/Brown and White Streaks ma**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Construction - 1st Floor Landing**  
MATERIAL QUANTITY: **65** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3EM**  
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/Brown and White Streaks ma**  
MATERIAL LOCATION: **1967 Construction - 1st Floor Landing**  
MATERIAL QUANTITY: **65** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3F**  
MATERIAL DESCRIPTION: **9" x 9" Pale Cream Floor Tile w/ White Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Construction - 1st Floor Landing**

MATERIAL QUANTITY: **45**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3F**  
MATERIAL DESCRIPTION: **9" x 9" Pale Cream Floor Tile w/ White Streaks**  
MATERIAL LOCATION: **1967 Construction - 1st Floor Landing**  
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3FM**  
MATERIAL DESCRIPTION: **9" x 9" Pale Cream Floor Tile w/ White Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Construction - 1st Floor Landing**

MATERIAL QUANTITY: **45**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3FM**  
MATERIAL DESCRIPTION: **9" x 9" Pale Cream Floor Tile w/ White Streaks Mastic**  
MATERIAL LOCATION: **1967 Construction - 1st Floor Landing**  
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3G**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown and Blue Dots**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building - Rooms 101 and 103**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2300** DAMAGE UNITS: **SF**  
COMMENTS: **Damage located in 1967 Building, Rooms 101 and 103**

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3G**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown and Blue Dots**  
MATERIAL LOCATION: **1967 Building - Rooms 101 and 103**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3GM**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown and Blue Dots Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1967 Building - Rooms 101 and 103**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2300** DAMAGE UNITS: **SF**  
COMMENTS: **Damage located in 1967 Building, Rooms 101 and 103**

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **3GM**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown and Blue Dots Mastic**  
MATERIAL LOCATION: **1967 Building - Rooms 101 and 103**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**  
MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building - Room 115**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile**

MATERIAL LOCATION: **1892 Building - Room 115**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Ceramic Flooring Blue/Green and Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Boys & Girls Bathrooms 1,2,3, Floors**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Ceramic Flooring Blue/Green and Grout**  
MATERIAL LOCATION: **1892 Boys & Girls Bathrooms 1,2,3, Floors**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Ceramic flooring blue green mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Boys & Girls Bathrooms 1,2,3 Floors**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Ceramic flooring blue green mastic**

MATERIAL LOCATION: **1892 Boys & Girls Bathrooms 1,2,3 Floors**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Specks Floor Tile**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42A**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **42A**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 100, 116, Patch in 204**

MATERIAL QUANTITY: **350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Specks Floor Tile**  
MATERIAL LOCATION: **Room 100, 116, Patch in 204**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 221 and 223**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Specks Floor Tile**

MATERIAL LOCATION: **Rooms 221 and 223**

MATERIAL QUANTITY: **2250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44A**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 221 and 223**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **44A**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 221 and 223**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Second Floor Faculty Lounge**

MATERIAL QUANTITY: **70**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Specks Floor Tile**  
MATERIAL LOCATION: **Second Floor Faculty Lounge**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45A**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Second Floor faculty Lounge**

MATERIAL QUANTITY: **70**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **45A**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Second Floor faculty Lounge**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Black mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Storage areas south side of Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Black mastic**

MATERIAL LOCATION: **Basement Storage areas south side of Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Basement Bathrooms for Engineer Break Room (South Side of Lunchroom)**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**  
MATERIAL LOCATION: **1892 Basement Bathrooms for Engineer Break Room (South Side of Lunchroom)**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Basement Bathrooms for Engineer Break Room (South Side of Lunchroom)**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1892 Basement Bathrooms for Engineer Break Room (South Side of Lunchroom)**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration  
Physical Damage**

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1892 Basement Engineer's Break Room and Room 114a**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**

COMMENTS: **Physical damage was observed in room 114. however, areas of deterioration were observed throughout room where tile appeared to maybe buckle**

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**  
MATERIAL LOCATION: **1892 Basement Engineer's Break Room and Room 114a**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Basement Engineer's Break Room and Room 114a**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1892 Basement Engineer's Break Room and Room 114a**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Roof drain insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Roof drain insulation**

MATERIAL LOCATION: **1967 Building**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **Acoustical plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building - Corridors and Room 101**  
MATERIAL QUANTITY: **5100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **Acoustical plaster**  
MATERIAL LOCATION: **1967 Building - Corridors and Room 101**  
MATERIAL QUANTITY: **5100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1892 Building - Fist Floor Corridor (East) and Room 118A, 2nd floor hallway patches**

MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**  
MATERIAL LOCATION: **1892 Building - Fist Floor Corridor (East) and Room 118A, 2nd floor hallway patches**  
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50A**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building - First Floor Corridor (East) and Room 118A**  
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **50A**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1892 Building - First Floor Corridor (East) and Room 118A**  
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Plaster board**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 120 Greenhouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Plaster board**

MATERIAL LOCATION: **Room 120 Greenhouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Yellowish Linoleum and Backing**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 218 Sink Counter Tops**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Yellowish Linoleum and Backing**  
MATERIAL LOCATION: **Room 218 Sink Counter Tops**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25411 BUIDLING ID: 5970  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Devon Jackson  
SCHOOL NAME: Smyth School INSPECTION DATE: 9/22/2022  
ADDRESS: 1059 W. 13th St. IDPH LICENSE NO: 100-05020

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 53  
MATERIAL DESCRIPTION: 12" x 12" Mint Green w/ Specks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Second Floor Teachers Lounge (Bathrooms), Room 213, 213 closet**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12" x 12" Mint Green w/ Specks Floor Tile**  
MATERIAL LOCATION: **Second Floor Teachers Lounge (Bathrooms), Room 213, 213 closet**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25411    BUILDING ID: 5970  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Devon Jackson  
SCHOOL NAME: Smyth School    INSPECTION DATE: 9/22/2022  
ADDRESS: 1059 W. 13th St.    IDPH LICENSE NO: 100-05020

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 53A  
MATERIAL DESCRIPTION: 12" x 12" Mint Green w/ Specks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Second Floor Teachers Lounge (Bathrooms)**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **53A**  
MATERIAL DESCRIPTION: **12" x 12" Mint Green w/ Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Second Floor Teachers Lounge (Bathrooms)**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Book Room and Old Engineer's Office (Laundry)**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in engineer's office**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**  
MATERIAL LOCATION: **Basement Book Room and Old Engineer's Office (Laundry)**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54A**  
MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Book Room and Old Engineer's Office (Laundry)**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **54A**  
MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**  
MATERIAL LOCATION: **Basement Book Room and Old Engineer's Office (Laundry)**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Gray spray-on fireproofing**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Old Boiler Room - 1892 (Above metal panels)**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Gray spray-on fireproofing**  
MATERIAL LOCATION: **Old Boiler Room - 1892 (Above metal panels)**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**  
MATERIAL DESCRIPTION: **Hard plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1967 Construction**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **6**  
MATERIAL DESCRIPTION: **Hard plaster**  
MATERIAL LOCATION: **Throughout 1967 Construction**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **9" x 9" Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **See HA's 3A- 3G**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile**

MATERIAL LOCATION: **See HA's 3A- 3G**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **Pipe insulation debris**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Crawlspace - Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Pipe insulation debris**

MATERIAL LOCATION: **Crawlspace - Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **Chimney duct packing**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Chimney duct packing**

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A1**  
MATERIAL DESCRIPTION: **Mag-Block Insulation on Boiler #1**  
HISTORICAL AHERA DAMAGE CATEGORY **Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **A1**

MATERIAL DESCRIPTION: **Mag-Block Insulation on Boiler #1**

MATERIAL LOCATION: **1967 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A2**  
MATERIAL DESCRIPTION: **Mag-Block Insulation on Boiler #2**  
HISTORICAL AHERA DAMAGE CATEGORY **Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **A2**

MATERIAL DESCRIPTION: **Mag-Block Insulation on Boiler #2**

MATERIAL LOCATION: **1967 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Tank insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Abated in 1994**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Tank insulation**

MATERIAL LOCATION: **Abated in 1994**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Fiberglass tank insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Fiberglass tank insulation**

MATERIAL LOCATION: **1892 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Fiberglass pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Fiberglass pipe insulation**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E.1**  
MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building various areas. & Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **E.1**

MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **1967 Building various areas. & Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E.2**  
MATERIAL DESCRIPTION: **Joint Compound on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1892 Building- washroom pipe chases and basement**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **JOINTS**

DAMAGE QUANTITY: DAMAGE UNITS: **JOINTS**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **E.2**  
MATERIAL DESCRIPTION: **Joint Compound on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **1892 Building- washroom pipe chases and basement**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **JOINTS**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **JOINTS**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25411    BUILDING ID: 5970  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Devon Jackson  
SCHOOL NAME: Smyth School    INSPECTION DATE: 9/22/2022  
ADDRESS: 1059 W. 13th St.    IDPH LICENSE NO: 100-05020

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: F  
MATERIAL DESCRIPTION: Aircell pipe insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 1 Damaged or significantly damaged friable thermal system insulating ACBM  
HISTORICAL DAMAGE REASON: Deterioration  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 1. **Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: Pipe Chases, 1892 basement, 1967 boiler room, and beneath sink in room 218 (suspected within univent in room 201)

MATERIAL QUANTITY: 2000    MATERIAL UNITS: LF

DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
MATERIAL LOCATION: **Pipe Chases, 1892 basement, 1967 boiler room, and beneath sink in room 218 (suspected within univent in room 201)**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Joint Insulation on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Crawl Spaces, Pipe Chases, 1892 basement, 1967 boiler room, and beneath sink in room 218 (suspected within univent in room 201)**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Joint Insulation on Aircell Pipe Insulation**

MATERIAL LOCATION: **Crawl Spaces, Pipe Chases, 1892 basement, 1967 boiler room, and beneath sink in room 218 (suspected within univent in room 201)**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Woolfelight pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1892 Building - Boiler Room and beneath sink in room 218**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Woolfelight pipe insulation**

MATERIAL LOCATION: **1892 Building - Boiler Room and beneath sink in room 218**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Joint Insulation on WoolfeLight Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1892 Building - Boiler Room and beneath sink in room 218**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **LF**  
COMMENTS: **Room 218 inaccessible - 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Joint Insulation on WoolfeLight Pipe Insulation**

MATERIAL LOCATION: **1892 Building - Boiler Room and beneath sink in room 218**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J 1**  
MATERIAL DESCRIPTION: **Purple carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **J 1**

MATERIAL DESCRIPTION: **Purple carpet mastic**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J 2**  
MATERIAL DESCRIPTION: **Blue carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **J 2**  
MATERIAL DESCRIPTION: **Blue carpet mastic**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J 3**  
MATERIAL DESCRIPTION: **Multi-colored carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **J 3**

MATERIAL DESCRIPTION: **Multi-colored carpet mastic**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J 4**  
MATERIAL DESCRIPTION: **Brown carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Band Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **J 4**  
MATERIAL DESCRIPTION: **Brown carpet mastic**  
MATERIAL LOCATION: **Basement Band Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J 5**  
MATERIAL DESCRIPTION: **Aqua carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **1380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **J 5**  
MATERIAL DESCRIPTION: **Aqua carpet mastic**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **1380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Pink terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building - Stairwells**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Pink terrazzo**  
MATERIAL LOCATION: **1967 Building - Stairwells**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**

MATERIAL LOCATION: **1892 Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**

MATERIAL LOCATION: **1892 Building - Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Replacement exterior brick - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Replacement exterior brick - Non-AHERA**

MATERIAL LOCATION: **1892 Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Replacement exterior brick mortar - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Replacement exterior brick mortar - Non-AHERA**

MATERIAL LOCATION: **1892 Building - Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**

MATERIAL LOCATION: **1967 Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25411**    BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**    INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**    IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building - Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**

MATERIAL LOCATION: **1967 Building - Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Boiler #1 gasket #1**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building - Boiler Room**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Boiler #1 gasket #1**  
MATERIAL LOCATION: **1967 Building - Boiler Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Boiler #2 gasket #2**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building - Boiler Room**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Boiler #2 gasket #2**  
MATERIAL LOCATION: **1967 Building - Boiler Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Linoleum flooring**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **T**

MATERIAL DESCRIPTION: **Linoleum flooring**

MATERIAL LOCATION: **Basement Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TM**  
MATERIAL DESCRIPTION: **Linoleum flooring mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **TM**

MATERIAL DESCRIPTION: **Linoleum flooring mastic**

MATERIAL LOCATION: **Basement Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Ceramic tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1892 Building - Bathrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **V**

MATERIAL DESCRIPTION: **Ceramic tile**

MATERIAL LOCATION: **1892 Building - Bathrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School** INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VG**  
MATERIAL DESCRIPTION: **Ceramic tile grout**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Bathrooms of 1892 Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

---

HOMOGENEOUS AREA: **VG**

MATERIAL DESCRIPTION: **Ceramic tile grout**

MATERIAL LOCATION: **Bathrooms of 1892 Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile Mastic**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **15**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile Mastic**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **15**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/ White Streaks**  
MATERIAL LOCATION: **Patches throughout Annex**  
MATERIAL QUANTITY: **100**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/ White Streaks**  
MATERIAL LOCATION: **Patches throughout Annex**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

**Carnow, Conibear and Associates**  
**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**  
MATERIAL LOCATION: **Rooms 101, 103, 107, 109**  
MATERIAL QUANTITY: **80**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**  
MATERIAL LOCATION: **Rooms 101, 103, 107, 109**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/12/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25411**    BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**    INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**    IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **12" x 12" Dark Red Floor Tile w/ Black Specks Mastic**  
MATERIAL LOCATION: **Rooms 320, 318, 314, 313 closet, 216, 218,120, 118, 116, 114, patches in Kitchen**  
MATERIAL QUANTITY: **150**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **Damaged**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **3**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Damage in 218

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**

ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12" x 12" Dark Red Floor Tile w/ Black Specks Mastic**

MATERIAL LOCATION: **Rooms 320, 318, 314, 313 closet, 216, 218, 120, 118, 116, 114, patches in Kitchen**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25411**    BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**    INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**    IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ White and Brown Streaks**  
MATERIAL LOCATION: **Rooms 221, 223, 118, patch in kitchen**  
MATERIAL QUANTITY: **253**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **Damaged**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **2**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Damage in 223

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ White and Brown Streaks**  
MATERIAL LOCATION: **Rooms 221, 223, 118, patch in kitchen**  
MATERIAL QUANTITY: **253** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25411</b>	BUILDING ID:	<b>5970</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Devon Jackson</b>		
SCHOOL NAME:	<b>Smyth School</b>	INSPECTION DATE:	<b>9/22/2022</b>		
ADDRESS:	<b>1059 W. 13th St.</b>	IDPH LICENSE NO:	<b>100-05020</b>		

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	<b>73</b>			
MATERIAL DESCRIPTION:	<b>12" x 12" Gold Floor Tile</b>			
MATERIAL LOCATION:	<b>Rooms 101, 103, 107, 109</b>			
MATERIAL QUANTITY:	<b>80</b>	MATERIAL UNITS:	<b>SF</b>	
MATERIAL CATEGORY:	<b>MISC</b>	FRIABLE:	<b>No</b>	
ASBESTOS TYPE:	<b>Assumed</b>			
DISTURBANCE POTENTIAL:	<b>LOW</b>	CONDITION:	<b>No Damage</b>	
AHERA DAMAGE CATEGORY:	<b>6 ACBM with the potential for damage</b>			
ACCESSIBILITY:	<b>Within Reach</b>	DAMAGE REASON:		
		DAMAGE REASON:		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE REASON:		
		DAMAGE UNITS:	<b>SF</b>	
COMMENTS:				

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12" x 12" Gold Floor Tile**  
MATERIAL LOCATION: **Rooms 101, 103, 107, 109**  
MATERIAL QUANTITY: **80**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12" x 12" Gold, Light Brown and Brown w/ White Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 101, 103, 107, 109**  
MATERIAL QUANTITY: **320**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12" x 12" Gold, Light Brown and Brown w/ White Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 101, 103, 107, 109**  
MATERIAL QUANTITY: **320**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25411**    BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**    INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**    IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/ black Streaks**  
MATERIAL LOCATION: **2nd Floor Teachers Lounge Bathrooms, 2nd floor hallway patches**  
MATERIAL QUANTITY: **50**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**

ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/ black Streaks**

MATERIAL LOCATION: **2nd Floor Teachers Lounge Bathrooms, 2nd floor hallway patches**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25411**    BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**    INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**    IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ White and Brown Streaks Mastic**  
MATERIAL LOCATION: **Rooms 221, 223, 118, patch in kitchen**  
MATERIAL QUANTITY: **253**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **Damaged**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **2**    DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Damage in 223

Inspector's Signature:



Date: **09/22/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ White and Brown Streaks Mastic**  
MATERIAL LOCATION: **Rooms 221, 223, 118, patch in kitchen**  
MATERIAL QUANTITY: **253**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/12/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/ Black Specks**  
MATERIAL LOCATION: **Patch in 203**  
MATERIAL QUANTITY: **3**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/ Black Specks**

MATERIAL LOCATION: **Patch in 203**

MATERIAL QUANTITY: **3**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

**Carnow, Conibear and Associates**

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 321, 217, 123, 119, 113**

MATERIAL QUANTITY: **160**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 321, 217, 123, 119, 113**  
MATERIAL QUANTITY: **160**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/12/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" x 12" Dark Red Floor Tile w/ Black Specks**  
MATERIAL LOCATION: **Rooms 320, 318, 314, 313 closet, 216, 218,120, 118, 116, 114, patches in Kitchen**  
MATERIAL QUANTITY: **150**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **Damaged**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **3**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Damage in 218

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" x 12" Dark Red Floor Tile w/ Black Specks**  
MATERIAL LOCATION: **Rooms 320, 318, 314, 313 closet, 216, 218,120, 118, 116, 114, patches in Kitchen**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25411**    BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**    INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**    IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/ black Streaks Mastic**  
MATERIAL LOCATION: **2nd Floor Teachers Lounge Bathrooms, 2nd floor hallway patches**  
MATERIAL QUANTITY: **50**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/ black Streaks Mastic**  
MATERIAL LOCATION: **2nd Floor Teachers Lounge Bathrooms, 2nd floor hallway patches**  
MATERIAL QUANTITY: **50**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/ White Streaks Mastic**  
MATERIAL LOCATION: **Patches throughout Annex**  
MATERIAL QUANTITY: **100**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: Chicago Public Schools      UNIT NUMBER: 25411      BUILDING ID: 5970  
CITY/STATE: Chicago, Illinois      AHERA INSPECTOR: Devon Jackson  
SCHOOL NAME: Smyth School      INSPECTION DATE: 9/22/2022  
ADDRESS: 1059 W. 13th St.      IDPH LICENSE NO: 100-05020

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: 72  
MATERIAL DESCRIPTION: 9" x 9" Cream Floor Tile w/ Black Specks Mastic  
MATERIAL LOCATION: Patch in 203  
MATERIAL QUANTITY: 3      MATERIAL UNITS: SF  
MATERIAL CATEGORY: MISC      FRIABLE: No  
ASBESTOS TYPE: Assumed  
DISTURBANCE POTENTIAL: LOW      CONDITION: No Damage  
AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
ACCESSIBILITY: Within Reach      DAMAGE REASON:  
DAMAGE QUANTITY: 0      DAMAGE REASON:  
DAMAGE UNITS: SF  
COMMENTS:

Inspector's Signature:



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/ Black Specks Mastic**  
MATERIAL LOCATION: **Patch in 203**  
MATERIAL QUANTITY: **3**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25411**    BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**    INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**    IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Tongue and Groove Wood Floor**  
MATERIAL LOCATION: **Gym, Auditorium Balcony, Stage, and Seating**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Tongue and Groove Wood Floor**  
MATERIAL LOCATION: **Gym, Auditorium Balcony, Stage, and Seating**  
MATERIAL QUANTITY: **2000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ White Specks**  
MATERIAL LOCATION: **Rooms 101, 103, 107, 109**  
MATERIAL QUANTITY: **160**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ White Specks**  
MATERIAL LOCATION: **Rooms 101, 103, 107, 109**  
MATERIAL QUANTITY: **160**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile w/ White Streaks**  
MATERIAL LOCATION: **Rooms 313 closet, patch in kitchen**  
MATERIAL QUANTITY: **10**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile w/ White Streaks**  
MATERIAL LOCATION: **Rooms 313 closet, patch in kitchen**  
MATERIAL QUANTITY: **10**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/12/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile w/ White Streaks Mastic**  
MATERIAL LOCATION: **Rooms 313 closet, patch in kitchen**  
MATERIAL QUANTITY: **10**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile w/ White Streaks Mastic**

MATERIAL LOCATION: **Rooms 313 closet, patch in kitchen**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **15**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/22/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUILDING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Smyth School**      REVIEW DATE: **10/12/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**


HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **15**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **10/12/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25411**      BUIDLING ID: **5970**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Devon Jackson**  
SCHOOL NAME: **Smyth School**      INSPECTION DATE: **9/22/2022**  
ADDRESS: **1059 W. 13th St.**      IDPH LICENSE NO: **100-05020**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Streaks Floor Tile**  
MATERIAL LOCATION: **Rooms 321, 217, 123, 119, 113**  
MATERIAL QUANTITY: **160**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **09/22/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25411** BUILDING ID: **5970**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Smyth School** REVIEW DATE: **10/12/2022**

ADDRESS: **1059 W. 13th St.** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 321, 217, 123, 119, 113**

MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/12/2022**


# APPENDIX B

## Inspector and Management Planner Licenses

---

7233 S. Adams Street | Willowbrook, IL 60527  
(630) 655-3900 | www.otssafety.com

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

**Devon Jackson**

has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/1/2022 - 3/3/2022

Exam Date: 3/3/2022




Expiration Date: 3/3/2023

Certificate Number: ABI2203030658

Kathy DeSalvo, Director

# Devon Jackson

Illinois Licensed Building Inspector, Air Sampling Professional

 ILLINOIS DEPARTMENT OF PUBLIC HEALTH <b>IDPH</b> PROTECTING HEALTH. IMPROVING LIVES.	<b>ASBESTOS PROFESSIONAL LICENSE</b>	
ID NUMBER 100 - 05020	ISSUED 5/13/2022	EXPIRES 05/15/2023
<b>DEVON A JACKSON</b> 10657 SOUTH AVENUE D CHICAGO, IL 60617 Environmental Health		

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/3/2023
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	11/18/2022

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519

  
Kathy DeSalvo, Director



# ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

**100 - 19466**

ISSUED

**4/22/2022**

EXPIRES

**05/15/2023**

**EVAN I CHRISTIAN**  
**1119 N HOYNE AVE, APT 1**  
**CHICAGO, IL 60622**

Environmental Health



## ENDORSEMENTS

## TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER

3/28/2023

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**


This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid

training course certificate.





OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed