

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2480
SCHOOL NAME: Taylor School
ADDRESS OF SCHOOL: 9912 S Avenue H
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **9/20/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/16/2022 ENROLLMENT 349
IDPH INSPECTOR LICENSE NUMBER: 100-09786
IDPH LICENSED INSPECTOR NAME (Please Print): John Fenn
IDPH MP LICENSE NUMBER: 100-03613
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

6/28/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Taylor School

9912 S Avenue H
Chicago, IL, 60617

Unit: 25591
Building ID: 6150

IDPH ID Number: 14-016-2990-2480

REPORT DATE:

Tuesday, June 28, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 28, 2022

RE: Taylor School, Unit 25591
9912 S Avenue H
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Taylor School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Taylor School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Taylor School
Address: 9912 S Avenue H
IDPH ID: 14-016-2990-2480
Contact: Mehalek, Michael

Unit: 25591
Chicago, IL, 60617
Building ID: 6150
Phone: 7737096399

Region: 06

2. Description of Facility

Original Construction: 1996
Total Square Footage: 12310
Current Occupancy: 349

Additional Construction:
No of Floors: 1

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant


MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: John Fenn


Inspector IDPH license # 100-09786
Reinspection Date: 6/16/2022

Signature: 
Date: 6/16/2022

6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613


Signature: 
Date: 06/28/2022

7. Review Date: 06/28/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/28/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Taylor School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6150:

21	Smooth Plaster
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 6150:

NEW

Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05	Drywall
08	12x12 Brown Floor Tile
09	12x12 White Floor Tile
10	12x12 Brown & 12x12 White Floor Tile Mastic
11	Black Baseboard
12	Black Baseboard Mastic
13	12x12 Gray w/Black Streaks Floor Tile
14	12x12 Green w/Black Streaks Floor Tile
15	12x12 Blue w/Black Sreaks Floor Tile
16	12x12 Pink w/Black Streaks Floor Tile
17	12x12 Floor Tile Mastic
18	Gray Baseboard
19	Gray Baseboard Mastic
20	2'x4' Ceiling Tile
22	Gray and Black Terrazzo
23	Green and Black Floor Tile
25	Beige Speckled Mosaic Ceramic Tile Grout
25M	Beige Speckled Mosaic Ceramic Tile Mastic
26	Beige and White Checkered Ceramic Tile Grout
26M	Beige and White Checkered Ceramic Tile Adhesive
27	Grey and Light Grey Checkey Weave Carpet Mastic
28	4x4 Beige and Blue Ceramic Tile Grout
28M	4x4 Beige and Blue Ceramic Tile Mastic
29A	12x12 Brown w/White & Gray Streaks Floor Tile Mastic
30	12x12 Light Gray w/Gray & White Speckles Vinyl Floor Tile
30A	12x12 Light Gray w/Gray & White Speckles Vinyl Floor Tile Mastic
C	Fiberglass Joint Compound
D	Goiler Gasket
H	Cardboard Pipe Insulation
I	Cardboard Joints
J	Incinerator
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

04C	12x12 Beige w/Tan Specks Floor Tile Mastic
25M	Beige Speckled Mosaic Ceramic Tile Mastic

26M	Beige and White Checkered Ceramic Tile Adhesive
27	Grey and Light Grey Checkey Weave Carpet Mastic
28M	4x4 Beige and Blue Ceramic Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by John Fenn, IDPH License # 100-09786. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Taylor School Building 6150 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Taylor School Unit 25591 Building ID 6150

Address 9912 S Avenue H Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01A	12x12 Cream Floor Tile - No ACBM			Main Building-Room 114	NO_ACBM	MISC								
01B	12x12 Light Gray w/Cream Speck Floor Tile - No ACBM			Main Building-Room 114	NO_ACBM	MISC								
01C	12x12 Beige w/Tan Specks Floor Tile	3,500	SF	Kitchen Storage (Cage Area) within Teachers' Lounge next to Room 114, Main Office Public Space & Copy Room, Main Offices, Clerk's Area and Principal's Office (Under the Carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01D	12x12 Multicolor Beige Floor Tile ABATED			Kids' Lunchroom, Balcony of Auditorium	ABATED	MISC								
01E	12x12 Cream w/Brown Specks Floor Tile - No ACBM			Main Building- 2nd Floor Old Teachers' Lounge Room (Next to Room 203), 1st Floor Teachers Lounge and Lunchroom Manager's Office (Next to Room 114)	NO_ACBM	MISC								
01F	12x12 Cream w/Tan Specks Floor Tile ABATED			Assistant Principal's Office	ABATED	MISC								
01G	12x12 Brown w/Cream Specks Floor Tile		SF	Janitor's Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	Brown Carpet Mastic - No ACBM			Engineer's Storage Room, 306, 308, Offices Next To 209	NO_ACBM	MISC								
03	Gray Carpet Mastic - No ACBM			Room 109 & 111	NO_ACBM	MISC								
04A	12x12 Cream Floor Tile Mastic - No ACBM			Main Building-Room 114	NO_ACBM	MISC								
04B	12x12 Light Grey w/Cream Specks Floor Tile Mastic - No ACBM			Main Building-Room 114	NO_ACBM	MISC								
04C	12x12 Beige w/Tan Specks Floor Tile Mastic	3,500	SF	Kitchen Storage (Cage Area) within Teachers' Lounge next to Room 114, Main Office Public Space & Copy	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Taylor School Unit 25591 Building ID 6150

Address 9912 S Avenue H Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room, Main Offices, Clerk's Area and Principal's Office (under the carpet)										
04D	12x12 Multicolor Floor Tile Mastic ABATED			Kids' Lunchroom, Balcony of Auditorium, Room 311	ABATED	MISC								
04E	12x12 Cream w/Brown Specks Floor Tile Mastic - No ACBM			Main Building- 2nd Floor Old Teachers' Lounge Room (Next to Room 203), 1st Floor Teachers' Lounge & Lunchroom Manager's Office (next to Room 114)	NO_ACBM	MISC								
04F	12x12 Cream w/Tan Specks Floor Tile Mastic ABATED			Assistant Principal's Office	ABATED	MISC								
04G	12x12 Brown w/Cream Specks Floor Tile Mastic - No ACBM			Janitor's Lounge C	NO_ACBM	MISC								
05	Drywall	500	SF	Balcony of Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	Brown Baseboard - No ACBM			Main Building- Lunchroom, 114	NO_ACBM	MISC								
07	Brown Baseboard Mastic - No ACBM			Main Building- Lunchroom, 114	NO_ACBM	MISC								
08	12x12 Brown Floor Tile	750	SF	Main Building- Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	12x12 White Floor Tile	750	SF	Main Building- Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	12x12 Brown & 12x12 White Floor Tile Mastic	1,500	SF	Main Building- Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Black Baseboard	340	LF	Hallway of 1997 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Black Baseboard Mastic	340	LF	Hallway of 1997 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12x12 Gray w/Black Streaks Floor Tile	11,100	SF	Throughout Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12x12 Green w/Black Streaks Floor Tile	25	SF	Patches in Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12x12 Blue w/Black Streaks Floor Tile	25	SF	Patches in Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Taylor School Unit 25591 Building ID 6150

Address 9912 S Avenue H Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
16	12x12 Pink w/Black Streaks Floor Tile	25	SF	Patches in Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12x12 Floor Tile Mastic	11,200	SF	Throughout Annex-In Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Gray Baseboard	1,000	LF	Classrooms in Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Gray Baseboard Mastic	1,000	LF	Classrooms in Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	2'x4' Ceiling Tile	11,180	SF	Throughout Annex	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
21	Smooth Plaster			Throughout Main Building & Balcony	NO_ACBM	SURFACE	N				Yes			MODERATE
22	Gray and Black Terrazzo	17,500	SF	3rd Floor NW & SW Toilets, 1st-3rd Floor corridors, 2nd Floor NW & SW toilets, All Stairwells, JC 1st-3rd Floor, Stage Stairs & Dressing Room- Main Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Green and Black Floor Tile	1,200	SF	Border in Corridors and Stair Landings - 1st and 3rd Floor, stage dressing room -Main Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Beige and Black Floor Tile ABATED			Stairs and 1st & 3rd Floors on Steps	ABATED	MISC								
25	Beige Speckled Mosaic Ceramic Tile Grout	936	SF	1st - 3rd Floors Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25M	Beige Speckled Mosaic Ceramic Tile Mastic	936	SF	1st - 3rd Floors Boys and Girls Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Beige and White Checkered Ceramic Tile Grout	1,200	SF	East Main Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26M	Beige and White Checkered Ceramic Tile Adhesive	1,200	SF	East Main Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Grey and Light Grey Checkey Weave Carpet Mastic	800	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	4x4 Beige and Blue Ceramic Tile Grout	125	SF	Annex Building Entrances	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
28M	4x4 Beige and Blue Ceramic Tile Mastic	125	SF	Annex Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Taylor School Unit 25591 Building ID 6150

Address 9912 S Avenue H Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Entrances								potential for damage		
29	12x12 Brown w/White & Gray Streaks Floor Tile	225	SF	Janitor's Break Room- Basement	CHR	MISC	N	LOC	135		No	ACBM with the potential for damage		LOW
29A	12x12 Brown w/White & Gray Streaks Floor Tile Mastic	135	SF	Janitor's Break Room- Basement	ASSUMED	MISC	N	LOC	135		No	ACBM with the potential for damage		LOW
30	12x12 Light Gray w/Gray & White Speckles Vinyl Floor Tile	2,500	SF	Main Building- Rooms 303, 309, 311, Auditorium Balcony Top Level	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30A	12x12 Light Gray w/Gray & White Speckles Vinyl Floor Tile Mastic	2,500	SF	Main Building- Rooms 303, 309, 311, Auditorium Balcony Top Level	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Mag Block Tanking ABATED			Boiler Room	ABATED	TSI								
B	Mag Block Duct Insulation	440	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
C	Fiberglass Joint Compound	314	FITTING	Education & Mechanical Area & Tunnel	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	Goiler Gasket	10	SF	Boiler Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
F	Aircell Pipe Insulation	500	LF	Throughout Air Tunnel, Education & Boiler Room, Under Assembly Hall, Fan Room Tunnel & Crawlspace, 1st, 2nd & 3rd Floor Boys/Girls Toilet Chases, Lunchroom Manager's Office- Main Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Aircell Joints	80	LF	Throughout Air Tunnel, Education & Boiler Room, Under Assembly Hall, Fan Room Tunnel & Crawlspace, 1st, 2nd & 3rd Floor Boys/Girls Toilet Chases, Lunchroom Manager's Office- Main Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Cardboard Pipe Insulation	80	LF	Tunnel & Pipe Room, Boiler	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Taylor School Unit 25591 Building ID 6150

Address 9912 S Avenue H Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
I	Cardboard Joints	10	LF	Pump Room, Wind Tunnel & Boiler Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	Incinerator	1	EA	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	Any remaining friable ACBM or friable suspect ACBM		

Chicago Public Schools

School Taylor School Unit 25591 Building ID 6150

Address 9912 S Avenue H Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 6/16/2022
Inspector Name John Fenn
100-09786 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01A	
01B	
01C	
01D	
01E	
01F	
01G	Duplicate HA. Same as 29/29A
02	
03	
04A	
04B	
04C	
04D	
04E	
04F	
04G	Duplicate HA. Same as 29/29A
05	Not Observed. Balcony of Auditorium is Plaster
06	
07	
08	
09	
10	
11	
12	

Chicago Public Schools

School Taylor School Unit 25591 Building ID 6150

Address 9912 S Avenue H Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
25M	
26	
26M	
27	
28	
28M	
29	135 SF of Damaged Floor Tile
29A	135 SF of Damaged Floor Tile Mastic
30	
30A	
A	
B	
C	
D	
F	
G	

Chicago Public Schools

School Taylor School Unit 25591 Building ID 6150

Address 9912 S Avenue H Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
H	
I	
J	
NEW	

Table II

Management Planner's Review

Chicago Public Schools

School Taylor School
Address 9912 S Avenue H

Unit 25591
Chicago, IL, 60617

Building ID 6150
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01A	12x12 Cream Floor Tile - No ACBM			Main Building- Room 114	No ACBM	MISC					
01B	12x12 Light Gray w/Cream Speck Floor Tile - No ACBM			Main Building- Room 114	No ACBM	MISC					
01C	12x12 Beige w/Tan Specks Floor Tile	3,500	SF	Kitchen Storage (Cage Area) within Teachers' Lounge next to Room 114, Main Office Public Space & Copy Room, Main Offices, Clerk's Area and Principal's Office (Under the Carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01D	12x12 Multicolor Beige Floor Tile ABATED			Kids' Lunchroom, Balcony of Auditorium	Abated	MISC					
01E	12x12 Cream w/Brown Specks Floor Tile - No ACBM			Main Building- 2nd Floor Old Teachers' Lounge Room (Next to Room 203), 1st Floor Teachers Lounge and Lunchroom Manager's Office (Next to Room 114)	No ACBM	MISC					
01F	12x12 Cream w/Tan Specks Floor Tile ABATED			Assistant Principal's Office	Abated	MISC					
01G	12x12 Brown w/Cream Specks Floor Tile		SF	Janitor's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	Brown Carpet Mastic - No ACBM			Engineer's Storage Room, 306, 308, Offices Next To 209	No ACBM	MISC					
03	Gray Carpet Mastic - No ACBM			Room 109 & 111	No ACBM	MISC					
04A	12x12 Cream Floor Tile Mastic - No ACBM			Main Building- Room 114	No ACBM	MISC					
04B	12x12 Light Grey w/Cream Specks Floor Tile Mastic - No ACBM			Main Building- Room 114	No ACBM	MISC					
04C	12x12 Beige w/Tan Specks Floor Tile Mastic	3,500	SF	Kitchen Storage (Cage Area) within Teachers' Lounge next to Room 114, Main Office Public Space & Copy Room, Main Offices, Clerk's Area and Principal's Office (under the carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04D	12x12 Multicolor Floor Tile Mastic ABATED			Kids' Lunchroom, Balcony of Auditorium, Room 311	Abated	MISC					
04E	12x12 Cream w/Brown Specks Floor Tile Mastic - No ACBM			Main Building- 2nd Floor Old Teachers' Lounge Room (Next to Room 203), 1st Floor Teachers' Lounge & Lunchroom Manager's Office (next to Room 114)	No ACBM	MISC					
04F	12x12 Cream w/Tan Specks Floor Tile Mastic ABATED			Assistant Principal's Office	Abated	MISC					
04G	12x12 Brown w/Cream Specks Floor Tile Mastic -			Janitor's Lounge C	No ACBM	MISC					

Chicago Public Schools

School Taylor School
Address 9912 S Avenue H

Unit 25591
Chicago, IL, 60617

Building ID 6150
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	No ACBM										
05	Drywall	500	SF	Balcony of Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	Brown Baseboard - No ACBM			Main Building- Lunchroom, 114	No ACBM	MISC					
07	Brown Baseboard Mastic - No ACBM			Main Building- Lunchroom, 114	No ACBM	MISC					
08	12x12 Brown Floor Tile	750	SF	Main Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12x12 White Floor Tile	750	SF	Main Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12x12 Brown & 12x12 White Floor Tile Mastic	1,500	SF	Main Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Black Baseboard	340	LF	Hallway of 1997 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	Black Baseboard Mastic	340	LF	Hallway of 1997 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
13	12x12 Gray w/Black Streaks Floor Tile	11,100	SF	Throughout Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12x12 Green w/Black Streaks Floor Tile	25	SF	Patches in Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12x12 Blue w/Black Streaks Floor Tile	25	SF	Patches in Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12x12 Pink w/Black Streaks Floor Tile	25	SF	Patches in Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12x12 Floor Tile Mastic	11,200	SF	Throughout Annex- In Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Gray Baseboard	1,000	LF	Classrooms in Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
19	Gray Baseboard Mastic	1,000	LF	Classrooms in Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
20	2'x4' Ceiling Tile	11,180	SF	Throughout Annex	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Smooth Plaster			Throughout Main Building & Balcony	No ACBM	SURFACE	No				
22	Gray and Black Terrazzo	17,500	SF	3rd Floor NW & SW Toilets, 1st-3rd Floor corridors, 2nd Floor NW & SW toilets, All Stairwells, JC 1st-3rd Floor, Stage Stairs & Dressing Room- Main Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Green and Black Floor Tile	1,200	SF	Border in Corridors and Stair Landings - 1st and 3rd Floor, stage dressing room -Main Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Beige and Black Floor Tile ABATED			Stairs and 1st & 3rd Floors on Steps	Abated	MISC					
25	Beige Speckled Mosaic Ceramic Tile Grout	936	SF	1st - 3rd Floors Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25M	Beige Speckled Mosaic Ceramic Tile Mastic	936	SF	1st - 3rd Floors Boys and Girls Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Beige and White Checkered Ceramic Tile Grout	1,200	SF	East Main Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26M	Beige and White Checkered Ceramic Tile Adhesive	1,200	SF	East Main Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Grey and Light Grey Checkey Weave Carpet Mastic	800	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Taylor School
Address 9912 S Avenue H

Unit 25591
 Chicago, IL, 60617

Building ID 6150
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
28	4x4 Beige and Blue Ceramic Tile Grout	125	SF	Annex Building Entrances	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28M	4x4 Beige and Blue Ceramic Tile Mastic	125	SF	Annex Building Entrances	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12x12 Brown w/White & Gray Streaks Floor Tile	225	SF	Janitor's Break Room- Basement	Chrysotile	MISC	No	135	SF	6 ACBM with the potential for damage	Repair
29A	12x12 Brown w/White & Gray Streaks Floor Tile Mastic	135	SF	Janitor's Break Room- Basement	Assumed	MISC	No	135	SF	6 ACBM with the potential for damage	Repair
30	12x12 Light Gray w/Gray & White Speckles Vinyl Floor Tile	2,500	SF	Main Building- Rooms 303, 309, 311, Auditorium Balcony Top Level	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30A	12x12 Light Gray w/Gray & White Speckles Vinyl Floor Tile Mastic	2,500	SF	Main Building- Rooms 303, 309, 311, Auditorium Balcony Top Level	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Mag Block Tanking ABATED			Boiler Room	Abated	TSI					
B	Mag Block Duct Insulation	440	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Fiberglass Joint Compound	314	FITTING	Education & Mechanical Area & Tunnel	Assumed	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
D	Goiler Gasket	10	SF	Boiler Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
F	Aircell Pipe Insulation	500	LF	Throughout Air Tunnel, Education & Boiler Room, Under Assembly Hall, Fan Room Tunnel & Crawlspace, 1st, 2nd & 3rd Floor Boys/Girls Toilet Chases, Lunchroom Manager's Office-Main Building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
G	Aircell Joints	80	LF	Throughout Air Tunnel, Education & Boiler Room, Under Assembly Hall, Fan Room Tunnel & Crawlspace, 1st, 2nd & 3rd Floor Boys/Girls Toilet Chases, Lunchroom Manager's Office-Main Building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	Cardboard Pipe Insulation	80	LF	Tunnel & Pipe Room, Boiler	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I	Cardboard Joints	10	LF	Pump Room, Wind Tunnel & Boiler Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
J	Incinerator	1	EA	Boiler Room	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Taylor School
Address 9912 S Avenue H

Unit 25591
Chicago, IL, 60617

Building ID 6150
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	6/28/2022
Manager Planner Name	Daniel Juneau
100-03613	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01A	
01B	
01C	
01D	
01E	
01F	
01G	
02	
03	

Chicago Public Schools

School Taylor School
Address 9912 S Avenue H

Unit 25591
Chicago, IL, 60617

Building ID 6150
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
04A	
04B	
04C	
04D	
04E	
04F	
04G	
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	

Chicago Public Schools

School Taylor School
Address 9912 S Avenue H

Unit 25591
 Chicago, IL, 60617

Building ID 6150
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
25	
25M	
26	
26M	
27	
28	
28M	
29	Remove or Repair Floor Tile
29A	
30	
30A	
A	
B	
C	
D	
F	
G	
H	
I	
J	
NEW	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Room 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile - No ACBM**
MATERIAL LOCATION: **Main Building- Room 114**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Cream Speck Floor Tile - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Room 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Cream Speck Floor Tile - No ACBM**
MATERIAL LOCATION: **Main Building- Room 114**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen Storage (Cage Area) within Teachers' Lounge next to Room 114, Main Office Public Space & Copy Room, Main Offices, Clerk's Area and Principal's Office (Under the Carpet)**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Specks Floor Tile**
MATERIAL LOCATION: **Kitchen Storage (Cage Area) within Teachers' Lounge next to Room 114, Main Office Public Space & Copy Room, Main Offices, Clerk's Area and Principal's Office (Under the Carpet)**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01D**
MATERIAL DESCRIPTION: **12x12 Multicolor Beige Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kids' Lunchroom, Balcony of Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **01D**
MATERIAL DESCRIPTION: **12x12 Multicolor Beige Floor Tile ABATED**
MATERIAL LOCATION: **Kids' Lunchroom, Balcony of Auditorium**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01E**
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Floor Tile - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- 2nd Floor Old Teachers' Lounge Room (Next to Room 203), 1st Floor Teachers Lounge and Lunchroom Manager's Office (Next to Room 114)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **01E**
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Floor Tile - No ACBM**
MATERIAL LOCATION: **Main Building- 2nd Floor Old Teachers' Lounge Room (Next to Room 203), 1st Floor Teachers Lounge and Lunchroom Manager's Office (Next to Room 114)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01F**
MATERIAL DESCRIPTION: **12x12 Cream w/Tan Specks Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assistant Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **01F**
MATERIAL DESCRIPTION: **12x12 Cream w/Tan Specks Floor Tile ABATED**
MATERIAL LOCATION: **Assistant Principal's Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01G**
MATERIAL DESCRIPTION: **12x12 Brown w/Cream Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Janitor's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Duplicate HA. Same as 29/29A**

Inspector's Signature: _____



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **01G**
MATERIAL DESCRIPTION: **12x12 Brown w/Cream Specks Floor Tile**
MATERIAL LOCATION: **Janitor's Lounge**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Brown Carpet Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Storage Room, 306, 308, Offices Next To 209**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Brown Carpet Mastic - No ACBM**
MATERIAL LOCATION: **Engineer's Storage Room, 306, 308, Offices Next To 209**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **Gray Carpet Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 109 & 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **Gray Carpet Mastic - No ACBM**

MATERIAL LOCATION: **Room 109 & 111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Room 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic - No ACBM**
MATERIAL LOCATION: **Main Building- Room 114**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04B**
MATERIAL DESCRIPTION: **12x12 Light Grey w/Cream Specks Floor Tile Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Room 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **04B**
MATERIAL DESCRIPTION: **12x12 Light Grey w/Cream Specks Floor Tile Mastic - No ACBM**
MATERIAL LOCATION: **Main Building- Room 114**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04C**
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen Storage (Cage Area) within Teachers' Lounge next to Room 114, Main Office Public Space & Copy Room, Main Offices, Clerk's Area and Principal's Office (under the carpet)**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **04C**
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Specks Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen Storage (Cage Area) within Teachers' Lounge next to Room 114, Main Office Public Space & Copy Room, Main Offices, Clerk's Area and Principal's Office (under the carpet)**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04D**
MATERIAL DESCRIPTION: **12x12 Multicolor Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kids' Lunchroom, Balcony of Auditorium, Room 311**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **04D**
MATERIAL DESCRIPTION: **12x12 Multicolor Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Kids' Lunchroom, Balcony of Auditorium, Room 311**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04E**
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Foor Tile Mstic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- 2nd Floor Old Teachers' Lounge Room (Next to Room 203), 1st Floor Teachers' Lounge & Lunchroom Manager's Office (next to Room 114)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **04E**
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Floor Tile Mstic - No ACBM**
MATERIAL LOCATION: **Main Building- 2nd Floor Old Teachers' Lounge Room (Next to Room 203), 1st Floor Teachers' Lounge & Lunchroom Manager's Office (next to Room 114)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04F**
MATERIAL DESCRIPTION: **12x12 Cream w/Tan Specks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assistant Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **04F**
MATERIAL DESCRIPTION: **12x12 Cream w/Tan Specks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Assistant Principal's Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04G**
MATERIAL DESCRIPTION: **12x12 Brown w/Cream Specks Floor Tile Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Janitor's Lounge C**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Duplicate HA. Same as 29/29A**

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **04G**
MATERIAL DESCRIPTION: **12x12 Brown w/Cream Specks Floor Tile Mastic - No ACBM**
MATERIAL LOCATION: **Janitor's Lounge C**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Balcony of Auditorium**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not Observed. Balcony of Auditorium is Plaster**

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Balcony of Auditorium**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Brown Baseboard - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Lunchroom, 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Brown Baseboard - No ACBM**

MATERIAL LOCATION: **Main Building- Lunchroom, 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Lunchroom, 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **Brown Baseboard Mastic - No ACBM**

MATERIAL LOCATION: **Main Building- Lunchroom, 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Lunchroom**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**
MATERIAL LOCATION: **Main Building- Lunchroom**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12x12 White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Lunchroom**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12x12 White Floor Tile**
MATERIAL LOCATION: **Main Building- Lunchroom**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12x12 Brown & 12x12 White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Lunchroom**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12x12 Brown & 12x12 White Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Lunchroom**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hallway of 1997 Annex**
MATERIAL QUANTITY: **340** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Black Baseboard**
MATERIAL LOCATION: **Hallway of 1997 Annex**
MATERIAL QUANTITY: **340** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hallway of 1997 Annex**
MATERIAL QUANTITY: **340** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **Hallway of 1997 Annex**
MATERIAL QUANTITY: **340** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12x12 Gray w/Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Annex**
MATERIAL QUANTITY: **11100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12x12 Gray w/Black Streaks Floor Tile**
MATERIAL LOCATION: **Throughout Annex**
MATERIAL QUANTITY: **11100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12x12 Green w/Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Patches in Annex**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12x12 Green w/Black Streaks Floor Tile**
MATERIAL LOCATION: **Patches in Annex**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12x12 Blue w/Black Sreaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Patches in Annex**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12x12 Blue w/Black Sreaks Floor Tile**
MATERIAL LOCATION: **Patches in Annex**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Pink w/Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Patches in Annex**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Pink w/Black Streaks Floor Tile**
MATERIAL LOCATION: **Patches in Annex**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12x12 Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Annex- In Addition**
MATERIAL QUANTITY: **11200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12x12 Floor Tile Mastic**
MATERIAL LOCATION: **Throughout Annex- In Addition**
MATERIAL QUANTITY: **11200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Gray Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms in Annex**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Gray Baseboard**
MATERIAL LOCATION: **Classrooms in Annex**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms in Annex**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**
MATERIAL LOCATION: **Classrooms in Annex**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Annex**
MATERIAL QUANTITY: **11180** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **Throughout Annex**
MATERIAL QUANTITY: **11180** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Smooth Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Main Building & Balcony**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Smooth Plaster**

MATERIAL LOCATION: **Throughout Main Building & Balcony**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Gray and Black Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor NW & SW Toilets, 1st-3rd Floor corridors, 2nd Floor NW & SW toilets, All Stairwells, JC 1st-3rd Floor, Stage Stairs & Dressing Room- Main Building**

MATERIAL QUANTITY: **17500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Gray and Black Terrazzo**
MATERIAL LOCATION: **3rd Floor NW & SW Toilets, 1st-3rd Floor corridors, 2nd Floor NW & SW toilets, All Stairwells, JC 1st-3rd Floor, Stage Stairs & Dressing Room- Main Building**
MATERIAL QUANTITY: **17500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Green and Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Border in Corridors and Stair Landings - 1st and 3rd Floor, stage dressing room - Main Bldg**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Green and Black Floor Tile**
MATERIAL LOCATION: **Border in Corridors and Stair Landings - 1st and 3rd Floor, stage dressing room -Main Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Beige and Black Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Stairs and 1st & 3rd Floors on Steps**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Beige and Black Floor Tile ABATED**
MATERIAL LOCATION: **Stairs and 1st & 3rd Floors on Steps**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Beige Speckled Mosaic Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st - 3rd Floors Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Beige Speckled Mosaic Ceramic Tile Grout**
MATERIAL LOCATION: **1st - 3rd Floors Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25M**
MATERIAL DESCRIPTION: **Beige Speckled Mosaic Ceramic Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st - 3rd Floors Boys and Girls Washrooms**
MATERIAL QUANTITY: **936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **25M**
MATERIAL DESCRIPTION: **Beige Speckled Mosaic Ceramic Tile Mastic**
MATERIAL LOCATION: **1st - 3rd Floors Boys and Girls Washrooms**
MATERIAL QUANTITY: **936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Beige and White Checkered Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **East Main Entrance**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Beige and White Checkered Ceramic Tile Grout**
MATERIAL LOCATION: **East Main Entrance**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26M**
MATERIAL DESCRIPTION: **Beige and White Checkered Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **East Main Entrance**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **26M**
MATERIAL DESCRIPTION: **Beige and White Checkered Ceramic Tile Adhesive**
MATERIAL LOCATION: **East Main Entrance**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Grey and Light Grey Checkey Weave Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Grey and Light Grey Checky Weave Carpet Mastic**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **4x4 Beige and Blue Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building Entrances**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **4x4 Beige and Blue Ceramic Tile Grout**
MATERIAL LOCATION: **Annex Building Entrances**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28M**
MATERIAL DESCRIPTION: **4x4 Beige and Blue Ceramic Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Building Entrances**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **28M**
MATERIAL DESCRIPTION: **4x4 Beige and Blue Ceramic Tile Mastic**
MATERIAL LOCATION: **Annex Building Entrances**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12x12 Brown w/White & Gray Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Janitor's Break Room- Basement**

MATERIAL QUANTITY: **225**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **135 SF of Damaged Floor Tile**

Inspector's Signature: _____



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12x12 Brown w/White & Gray Streaks Floor Tile**
MATERIAL LOCATION: **Janitor's Break Room- Basement**
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **135** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or Repair Floor Tile

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29A**
MATERIAL DESCRIPTION: **12x12 Brown w/White & Gray Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Janitor's Break Room- Basement**
MATERIAL QUANTITY: **135** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **135 SF of Damaged Floor Tile Mastic**

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **29A**
MATERIAL DESCRIPTION: **12x12 Brown w/White & Gray Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Janitor's Break Room- Basement**
MATERIAL QUANTITY: **135** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **135** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Gray & White Speckles Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Rooms 303, 309, 311, Auditorium Balcony Top Level**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Gray & White Speckles Vinyl Floor Tile**
MATERIAL LOCATION: **Main Building- Rooms 303, 309, 311, Auditorium Balcony Top Level**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30A**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Gray & White Speckles Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Rooms 303, 309, 311, Auditorium Balcony Top Level**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **30A**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Gray & White Speckles Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Rooms 303, 309, 311, Auditorium Balcony Top Level**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Mag Block Tanking ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Mag Block Tanking ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Mag Block Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Mag Block Duct Insulation**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Fiberglass Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Education & Mechanical Area & Tunnel**
MATERIAL QUANTITY: **314** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Fiberglass Joint Compound**
MATERIAL LOCATION: **Education & Mechanical Area & Tunnel**
MATERIAL QUANTITY: **314** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Goiler Gasket**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Goiler Gasket**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Aircell Pipe Imsulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Air Tunnel, Education & Boiler Room, Under Assembly Hall, Fan Room Tunnel & Crawlspace, 1st, 2nd & 3rd Floor Boys/Girls Toilet Chases, Lunchroom Manager's Office- Main Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout Air Tunnel, Education & Boiler Room, Under Assembly Hall, Fan Room Tunnel & Crawlspace, 1st, 2nd & 3rd Floor Boys/Girls Toilet Chases, Lunchroom Manager's Office- Main Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Aircell Joints**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Air Tunnel, Education & Boiler Room, Under Assembly Hall, Fan Room Tunnel & Crawlspace, 1st, 2nd & 3rd Floor Boys/Girls Toilet Chases, Lunchroom Manager's Office- Main Building**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Aircell Joints**
MATERIAL LOCATION: **Throughout Air Tunnel, Education & Boiler Room, Under Assembly Hall, Fan Room Tunnel & Crawlspace, 1st, 2nd & 3rd Floor Boys/Girls Toilet Chases, Lunchroom Manager's Office- Main Building**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Tunnel & Pipe Room, Boiler**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Tunnel & Pipe Room, Boiler**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Cardboard Joints**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pump Room, Wind Tunnel & Boiler Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Cardboard Joints**
MATERIAL LOCATION: **Pump Room, Wind Tunnel & Boiler Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Incinerator**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 06/16/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUIDLING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Incinerator**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/28/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**
SCHOOL NAME: **Taylor School** INSPECTION DATE: **6/16/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS:
COMMENTS:

Inspector's Signature:  Date: **06/16/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25591** BUILDING ID: **6150**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Taylor School** REVIEW DATE: **6/28/2022**
ADDRESS: **9912 S Avenue H** IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **06/28/2022**

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JOHN H FENN
2829 N TROY ST
CHICAGO, IL 60618

4/7/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09786

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

FRONT OF LICENSE		BACK OF LICENSE	
 ILLINOIS DEPARTMENT OF PUBLIC HEALTH IDPH <small>PROTECTING HEALTH. IMPROVING LIVES.</small>	ASBESTOS PROFESSIONAL LICENSE	ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 09786	ISSUED 4/7/2022	INSPECTOR	3/9/2023
JOHN H FENN 2829 N TROY ST CHICAGO, IL 60618 Environmental Health	EXPIRES 05/15/2023 	MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/9/2023 4/2/2023
		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES
Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOHN FENN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/09/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/09/2022

Course Dates:

03/09/2023

Expires:

2203BIR04

Certificate Number:



Environmental &
Occupational Services

37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in blue ink, appearing to read "N. Peneff", is written over a light blue rectangular background.

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOHN FENN
has completed the Asbestos Management Planner Refresher course and passed the examination
on 03/09/2022 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C. Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

03/09/2022

Course Dates:

03/09/2023

Expires:

2203MPR02


Certificate Number:

A handwritten signature in blue ink that reads "N Peneff".

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-011



ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/19/2022
MANAGEMENT PLANNER	11/19/2022
PROJECT MANAGER	11/1/2022
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
 This license issued under authority of the State of Illinois
 Department of Public Health
 This license is valid only when accompanied by a valid
 training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: BIR2111192805

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192816

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/12/2022

Exam Date: 12/12/2022

Expiration Date: 12/12/2023

Certificate Number: MPR2212123967

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113645

Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed