

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2484  
SCHOOL NAME: Thorp School  
ADDRESS OF SCHOOL: 8914 S Buffalo Avenue  
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **9/17/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 12/7/2022 ENROLLMENT 292  
IDPH INSPECTOR LICENSE NUMBER: 100-18281  
IDPH LICENSED INSPECTOR NAME (Please Print): Christopher Antonopoulos  
IDPH MP LICENSE NUMBER: 100-09870  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer*

12/12/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Thorp School**

8914 S Buffalo Avenue  
Chicago, IL, 60617

Unit: 25601  
Building ID: 6180

IDPH ID Number: 14-016-2990-2484

**REPORT DATE:**

Monday, December 12, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

12/12/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 25601            Region: 06            IDPH ID: 14-016-2990-2484

School: Thorp School            Building ID: 6180

Address: 8914 S Buffalo Avenue

Chicago, IL, 60617

Building Contact: Gonzalez, Cecilia

Contact Phone: 7737097028

Current Building Owners: Chicago Public Schools

Reinspection Date: 12/7/2022

Review Date: 12/12/2022

Inspector: Christopher Antonopoulos

Inspector IDPH License: 100-18281

Management Planner: Todd Huffer

Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Todd Huffer  
100-09870

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: December 12, 2022

RE: Thorp School, Unit 25601  
8914 S Buffalo Avenue  
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Thorp School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Thorp School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Thorp School  
Address: 8914 S Buffalo Avenue  
IDPH ID: 14-016-2990-2484  
Contact: Gonzalez, Cecilia

Unit: 25601  
Chicago, IL, 60617  
Building ID: 6180  
Phone: 7737097028

Region: 06

### 2. Description of Facility

Original Construction: 1893  
Total Square Footage: 44587  
Current Occupancy: 292

Additional Construction: 1925,1975  
No of Floors: 3

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Christopher Antonopoulos



Signature:  
Date: 12/7/2022

Inspector IDPH license # 100-18281  
Reinspection Date: 12/7/2022

### 6. Management Planner

Management Planner Name: Todd Huffer



Signature:  
Date: 12/12/2022

Management Planner IDPH license # 100-09870

### 7. Review Date: 12/12/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 12/12/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Thorp School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6180:

80	Spray-On Insulation
81	12x12 Red Floor Tile
81M	12x12 Red Floor Tile Mastic
82	12x12 Purple Floor Tile
82M	12x12 Purple Floor Tile Mastic
83	12x12 Light Grey Floor Tile
83M	12x12 Light Grey Floor Tile Mastic
84	12x12 Grey Speckled Floor Tile
84M	12x12 Grey Speckled Floor Tile Mastic

NEW

Newly Installed Suspect ACM



B. The following new homogenous areas have been identified for Building 6180:

80	Spray-On Insulation
81	12x12 Red Floor Tile
81M	12x12 Red Floor Tile Mastic
82	12x12 Purple Floor Tile
82M	12x12 Purple Floor Tile Mastic
83	12x12 Light Grey Floor Tile
83M	12x12 Light Grey Floor Tile Mastic
84	12x12 Grey Speckled Floor Tile
84M	12x12 Grey Speckled Floor Tile Mastic
NEW	Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04	Accoustical Stucco Plaster
11	12x12 Grey Floor Tile
13	Transite
14	Accoustic Plaster
1500	Green Carpet Adhesive
25	Transite
26	12x12 Beige Floor Tile
28	12x12 Brown Floor Tile
30	12x12 Yellow Floor Tile
31	12x12 Yellow Floor Tile Mastic
32	Brown Carpet Mastic
33	Green Carpet Mastic
34	Insulation in Firedoors
35	Drywall
36	Drywall Joint Compound
41	12x12 Tan Floor Tile
42	12x12 Tan Floor Tile Mastic
43	12x12 Beige Floor Tile
44	12x12 Beige Floor Tile Mastic
49	Light Brown Carpet Mastic
50	Insulation in Fire Doors
56	12x12 Tan Floor Tile Mastic
57	Insulation in Fire Doors
61	12x12 Cream w/Brown Specks Floor Tile
62	12x12 Cream w/Brown Specks Floor Tile Mastic
63	12x12 Brown and Grey Floor Tile
64	12x12 Brown and Grey Floor Tile Mastic
67	Mint Colored Terrazzo Flooring
68	Multicolored Mosaic Ceramic Tile Grout
69	Multicolored Mosaic Ceramic Tile Adhesive
70	1'x1' White Fissured Ceiling Tile
70M	1'x1' White Fissured Ceiling Tile Adhesive
71	Green Terrazzo Flooring
73	White Ceramic Tile Grout
74	White Ceramic Tile Adhesive
75	12x12 Brown w/Streaks Floor Tile
75M	12x12 Brown w/Streaks Floor Tile Mastic
76	12x12 Off-White w/Streaks Floor Tile
76M	12x12 Off-White w/Streaks Floor Tile Mastic
77	Hard Coat Plaster
78	12x12 Grey w/Black Streaks Vinyl Floor Tile
78M	12x12 Grey w/Black Streaks Vinyl Floor Tile

	Mastic
79	12x12 Beige & Tan Specks Vinyl Floor Tile
79M	12x12 Beige & Tan Specks Vinyl Floor Tile Mastic
80	Spray-On Insulation
81	12x12 Red Floor Tile
81M	12x12 Red Floor Tile Mastic
82	12x12 Purple Floor Tile
82M	12x12 Purple Floor Tile Mastic
83	12x12 Light Grey Floor Tile
83M	12x12 Light Grey Floor Tile Mastic
84	12x12 Grey Speckled Floor Tile
84M	12x12 Grey Speckled Floor Tile Mastic
F	Fiberglass Ductwrap
J	Cardboard Pipe Insulation
NEW	Newly Installed Suspect ACM
T	Cardboard Pipe Insulation

The following areas were deemed to be inaccessible:

1500	Green Carpet Adhesive
27	12x12 Beige Floor Tile Mastic
29	12x12 Brown Floor Tile Mastic
31	12x12 Yellow Floor Tile Mastic
34	Insulation in Firedoors
42	12x12 Tan Floor Tile Mastic
49	Light Brown Carpet Mastic
50	Insulation in Fire Doors
57	Insulation in Fire Doors
62	12x12 Cream w/Brown Specks Floor Tile Mastic
64	12x12 Brown and Grey Floor Tile Mastic
69	Multicolored Mosaic Ceramic Tile Adhesive
70M	1'x1' White Fissured Ceiling Tile Adhesive
74	White Ceramic Tile Adhesive
75M	12x12 Brown w/Streaks Floor Tile Mastic
76M	12x12 Off-White w/Streaks Floor Tile Mastic
78M	12x12 Grey w/Black Streaks Vinyl Floor Tile Mastic
79M	12x12 Beige & Tan Specks Vinyl Floor Tile Mastic
K	Pre-Form Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Christopher Antonopoulos, IDPH License # 100-18281. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector

and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:           7/5/2019  
                                     8/22/2019  
                                     4/17/2020

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Thorp School Building 6180 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
04	Accoustical Stucco Plaster	7,050	SF	1961 Building- Lunchroom, 1st Floor Corridor	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9x9 Pinkish Tan Floor Tile	11,750	SF	1961 Building- 1st & 2nd Floor Classrooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	12x12 Grey Floor Tile	11,400	SF	1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 200, 200R, 209, 211, 212, 224 & 225	ASSUMED	MISC	N	DIST	0		No	ACBM with potential for significant damage	5	MODERATE
13	Transite	10	SF	1925 Building- 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Acoustic Plaster	1,400	SF	1925 Building- 1st & 2nd Floor Corridor	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
15	9x9 Tan Floor Tile	2,100	SF	1925 Building- 1st & 2nd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1500	Green Carpet Adhesive	1,500	SF	1925 Building- Rooms 120 & 288	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	9x9 Brown Floor Tile NOT OBSERVED			1888 Building- 2nd Floor Classroom		MISC								
17	12x12 Beige Floor Tile NOT OBSERVED			1925 Building- Rooms 124, 126, 129 & Main Office		MISC								
18	12x12 Brown Floor Tile ABATED			1888 Building- 1st Floor Classrooms & Corridor	ABATED	MISC								
19	9x9 Brown Floor Tile Mastic NOT OBSERVED			1925 Building- 1st Floor Classrooms & Corridor		MISC								
20	9x9 Tan Floor Tile Mastic NOT OBSERVED			1925 Building- 1st & 2nd Floor Corridor		MISC								
21	9x9 Brown Floor Tile Mastic ABATED			1888 Building- 2nd Floor Classrooms Building	ABATED	MISC								
22	12x12 Grey Floor Tile Mastic	11,400	SF	1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 200, 200R, 209, 211,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				212, 224 & 225										
23	12x12 Beige Floor Tile Mastic NOT OBSERVED			1925 Building-Rooms 124, 126, 129, and Main Office		MISC								
24	12x12 Brown Floor Tile Mastic ABATED			1888 Building- 1st Floor Corridor	ABATED	MISC								
25	Transite	800	SF	1888 Building- 1st, 2nd & 3rd Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12x12 Beige Floor Tile	6,350	SF	1961 Building-Basement, Kitchen/Cafeteria & Room 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12x12 Beige Floor Tile Mastic	6,350	SF	1961 Building-Basement, Kitchen/Cafeteria & Room 223	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12x12 Brown Floor Tile	5,500	SF	1961 Building-Basement, 1st & 2nd Floor Corridor Borders, Room 223 & Kitchen/Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12x12 Brown Floor Tile Mastic	5,500	SF	1961 Building-Basement, 1st & 2nd Floor Corridor Borders, Room 223 & Kitchen/Cafeteria	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12x12 Yellow Floor Tile	5,000	SF	1961 Building- 1st & 2nd Floor Corridor	ASSUMED	MISC	N	DIST	0		No	ACBM with potential for significant damage		
31	12x12 Yellow Floor Tile Mastic	5,000	SF	1961 Building- 1st & 2nd Floor Corridors	ASSUMED	MISC	N		0		No	ACBM with potential for significant damage		LOW
32	Brown Carpet Mastic	1,800	SF	1925 Building-Rooms 127 & 227 (Library)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Green Carpet Mastic	750	SF	1961 Building-Rooms 120A & 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Insulation in Firedoors	3	EA	1961 Building-Boiler Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Drywall	400	SF	1925 Building-Rooms 120 and 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Drywall Joint Compound	200	SF	1925 Building-	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW





# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridor										
56	12x12 Tan Floor Tile Mastic	3,470	SF	1888 Building- 1st Floor Classrooms & Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	Insulation in Fire Doors	2	EA	Adjoining Corridor to 1925 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	Blue Carpet Mastic NOT OBSERVED			1960 Building-Room 200		MISC						ACBM with the potential for damage		
59	12x12 Cream Floor Tile NOT OBSERVED			1925 Building-Room 122		MISC								
60	12x12 Cream Floor Tile Mastic NOT OBSERVED			1925 Building-Room 122		MISC								
61	12x12 Cream w/Brown Specks Floor Tile	500	SF	1925 Building-Room 120	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	12x12 Cream w/Brown Specks Floor Tile Mastic	500	SF	1925 Building-Room 120	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	12x12 Brown and Grey Floor Tile	2,000	SF	1925 Building-Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12x12 Brown and Grey Floor Tile Mastic	2,000	SF	1925 Building-Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	Blue Carpet Adhesive NOT OBSERVED			1960 Building-Room 212, 211, 209		MISC								
66	Light Blue Carpet Adhesive NOT OBSERVED			1960 Building-Room 200		MISC								
67	Mint Colored Terrazzo Flooring	1,260	SF	1960 Building-Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	Multicolored Mosaic Ceramic Tile Grout	1,335	SF	1960 Building-Vestibules, 1st & 2nd Floor Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	Multicolored Mosaic Ceramic Tile Adhesive	1,335	SF	1960 Building-Vestibules, 1st & 2nd Floor Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	1'x1' White Fissured Ceiling Tile	1,560	SF	1960 Building-Rooms 209 & 211	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
70M	1'x1' White Fissured Ceiling Tile Adhesive	1,560	SF	1960 Building-Rooms 209 & 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	Green Terrazzo Flooring	1,600	SF	1925 Building- 1st & 2nd Floor Corridors, Stairways, and adjoining Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
73	White Ceramic Tile Grout	1,570	SF	1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
74	White Ceramic Tile Adhesive	1,570	SF	1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	12x12 Brown w/Streaks Floor Tile	360	SF	1925 Building-Room 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75M	12x12 Brown w/Streaks Floor Tile Mastic	360	SF	1925 Building-Room 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	12x12 Off-White w/Streaks Floor Tile	360	SF	1925 Building-Room 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76M	12x12 Off-White w/Streaks Floor Tile Mastic	360	SF	1925 Building-Room 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	Hard Coat Plaster	114,000	SF	1898 Building- 1st, 2nd & 3rd Floors	ASSUMED	SURFACE	N	DIST	50		No	ACBM with the potential for damage		LOW
78	12x12 Grey w/Black Streaks Vinyl Floor Tile	6,600	SF	1961 Building- Main Office, Rooms 103, 105, 109, 110, 113, 200, 202, 205 & 212	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78M	12x12 Grey w/Black Streaks Vinyl Floor Tile Mastic	8,500	SF	1961 Building- Main Office, Rooms 103, 105, 109, 110, 113, 200, 202, 205 & 212	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12x12 Beige & Tan Specks Vinyl Floor Tile	800	SF	Kitchen Office, Rooms 107, 112 & 287 (Teachers' Lounge)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79M	12x12 Beige & Tan Specks Vinyl Floor Tile Mastic	800	SF	Kitchen Office, Rooms 107, 112 & 287 (Teachers' Lounge)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	Spray-On Insulation	20	SF	Fan Room	ASSUMED	TSI	N	NONE	0		Yes	ACBM with the potential for damage		LOW
81	12x12 Red Floor Tile	300	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
81M	12x12 Red Floor Tile Mastic	300	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
82	12x12 Purple Floor Tile	800	SF	Room 215	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
82M	12x12 Purple Floor Tile Mastic	800	SF	Room 215	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
83	12x12 Light Grey Floor Tile	48	SF	Room 112	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
83M	12x12 Light Grey Floor Tile Mastic	48	SF	Room 112	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
84	12x12 Grey Speckled Floor Tile	200	SF	Kitchen Staff Breakroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
84M	12x12 Grey Speckled Floor Tile Mastic	200	SF	Kitchen Staff Breakroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Fiberglass Joint Insulation	45	LF	1960 Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Aircell Joint Insulation ABATED			1888 Building-Boiler Area	ABATED	TSI								
C	Hand Packing ABATED			1888 Building-Boiler Room	ABATED	TSI								
D	Boiler Insulation ABATED			1888 Building-Boiler Room	ABATED	TSI								
E	Tank Insulation ABATED			1888 Building-Boiler & Tank Room	ABATED	TSI								
F	Fiberglass Ductwrap	160	SF	1888 Building-Boiler Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Aircell Ductwrap ABATED			1888 Building-Boiler Room	ABATED	TSI								
I	Aircell Pipe Insulation	400	LF	1888 Building-Boiler Room/Basement Area	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	Cardboard Pipe Insulation	300	LF	1888 Building-Basement Area	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	Pre-Form Pipe Insulation	100	LF	1888 Building-Basement Area	AMO	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
N	Fiberglass Joint Insulation	200	LF	Basement/Tunnel & Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		
O	Fiberglass Joint Insulation	40	LF	1961 Building-Boiler Room, Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
P	Aircell Pipe Joint Insulation	80	LF	1888 Building-Boiler Room/Tunnel	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				& Unexcavated Areas										
Q	Aircell Pipe Joint Insulation	30	LF	1961 Building-Boiler Room/Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
R	Aircell Pipe Insulation	400	LF	1926 Building-Boiler Room/Tunnel	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
S	Aircell Pipe Insulation	300	LF	1961 Building-Boiler Room/Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
T	Cardboard Pipe Insulation	100	LF	Tunnels Unexcavated Areas	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
U	Pre-form Pipe Insulation	100	LF	1898 Building-Boiler Room, Unexcavated Areas	AMO	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
V	Cardboard Pipe Joint Insulation	10	LF	1925 Building-Tunnels/Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
W	Cardboard Pipe Joint Insulation	15	LF	1888 Building-Basement/Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
X	Pre-Form Pipe Joint Insulation	10	LF	1888 Building-Boiler Room/Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
Y	Pre-form Pipe Joint Insulation	10	LF	1888 Building-Boiler Room/Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>12/7/2022</b>
Inspector Name <b>Christopher Antonopoulos</b>
<b>100-18281</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
04	
10	
11	Damage Not Observed 2022
13	
14	
15	Not Observed on 1st Floor Corridor 2022
1500	Room 288 Not Observed
16	Not Observed 2022
17	Not Observed 2022
18	
19	Not Observed 2022
20	Not Observed 2022
21	
22	
23	Not Observed 2022
24	
25	
26	
27	
28	
29	
30	Damage Not Observed 2022
31	Damage Not Observed 2022
32	Not Observed in Room 127. Room 227 is the Library

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
33	Not Observed in Room 209- 2022
34	
35	
36	
37	Not Observed 2022
38	Not Observed 2022
39	Not Observed 2022
40	Not Observed 2022
41	See HAs 26, 27, 28 & 29
42	See HAs 26, 27, 28 & 29
43	Not Observed in Rooms 224 & 225. No Damage Observed
44	Not Observed in Rooms 224 & 225. No Damage Observed
45	There is no Room 216
46	There is no Room 216
47	Not Observed 2022
48	Not Observed 2022
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	Not Observed 2022
59	Not Observed 2022
60	Not Observed 2022
61	

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
62	
63	Black Wax Covering Material
64	Black Wax Covering Material
65	Not Observed 2022
66	Not Observed 2022
67	
68	
69	
70	
70M	
71	
73	
74	
75	
75M	
76	
76M	
77	Damage Observed in Auditorium and Classrooms
78	
78M	
79	
79M	
80	
81	
81M	
82	
82M	
83	
83M	



# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
84	
84M	
A	
B	
C	
D	
E	
F	
H	
I	
J	
K	
N	
NEW	
O	
P	
Q	
R	
S	
T	
U	
V	
W	
X	
Y	

# Chicago Public Schools

**School** Thorp School **Unit** 25601 **Building ID** 6180

**Address** 8914 S Buffalo Avenue **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
04	Accoustical Stucco Plaster	7,050	SF	1961 Building- Lunchroom, 1st Floor Corridor	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9x9 Pinkish Tan Floor Tile	11,750	SF	1961 Building- 1st & 2nd Floor Classrooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12x12 Grey Floor Tile	11,400	SF	1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 200, 200R, 209, 211, 212, 224 & 225	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
13	Transite	10	SF	1925 Building- 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Accoustic Plaster	1,400	SF	1925 Building- 1st & 2nd Floor Corridor	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
15	9x9 Tan Floor Tile	2,100	SF	1925 Building- 1st & 2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1500	Green Carpet Adhesive	1,500	SF	1925 Building- Rooms 120 & 288	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9x9 Brown Floor Tile NOT OBSERVED			1888 Building- 2nd Floor Classroom		MISC					
17	12x12 Beige Floor Tile NOT OBSERVED			1925 Building- Rooms 124, 126, 129 & Main Office		MISC					
18	12x12 Brown Floor Tile ABATED			1888 Building- 1st Floor Classrooms & Corridor	Abated	MISC					
19	9x9 Brown Floor Tile Mastic NOT OBSERVED			1925 Building- 1st Floor Classrooms & Corridor		MISC					
20	9x9 Tan Floor Tile Mastic NOT OBSERVED			1925 Building- 1st & 2nd Floor Corridor		MISC					
21	9x9 Brown Floor Tile Mastic ABATED			1888 Building- 2nd Floor Classrooms Building	Abated	MISC					
22	12x12 Grey Floor Tile Mastic	11,400	SF	1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 200, 200R, 209, 211, 212, 224 & 225	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12x12 Beige Floor Tile Mastic NOT OBSERVED			1925 Building- Rooms 124, 126, 129, and Main Office		MISC					
24	12x12 Brown Floor Tile Mastic ABATED			1888 Building- 1st Floor Corridor	Abated	MISC					
25	Transite	800	SF	1888 Building- 1st, 2nd & 3rd Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12x12 Beige Floor Tile	6,350	SF	1961 Building- Basement, Kitchen/Cafeteria & Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x12 Beige Floor Tile Mastic	6,350	SF	1961 Building- Basement, Kitchen/Cafeteria & Room 223	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12x12 Brown Floor Tile	5,500	SF	1961 Building- Basement, 1st & 2nd Floor Corridor Borders, Room 223 &	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
29	12x12 Brown Floor Tile Mastic	5,500	SF	Kitchen/Cafeteria 1961 Building- Basement, 1st & 2nd Floor Corridor Borders, Room 223 & Kitchen/Cafeteria	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12x12 Yellow Floor Tile	5,000	SF	1961 Building- 1st & 2nd Floor Corridor	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
31	12x12 Yellow Floor Tile Mastic	5,000	SF	1961 Building- 1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
32	Brown Carpet Mastic	1,800	SF	1925 Building- Rooms 127 & 227 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Green Carpet Mastic	750	SF	1961 Building- Rooms 120A & 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Insulation in Firedoors	3	EA	1961 Building- Boiler Room	Assumed	TSI	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
35	Drywall	400	SF	1925 Building- Rooms 120 and 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Drywall Joint Compound	200	SF	1925 Building- Rooms 120 and 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	9x9 Brown Floor Tile NOT OBSERVED			1925 Building- 1st & 2nd Floor Corridor		MISC				6 ACBM with the potential for damage	
38	9x9 Brown Floor Tile Mastic NOT OBSERVED			1925 Building- 1st & 2nd Floor Corridor		MISC					
39	12x12 Brown Floor Tile NOT OBSERVED			1925 Building- Room 217		MISC					
40	12x12 Brown Floor Tile Mastic NOT OBSERVED			1925 Building- Room 217		MISC					
41	12x12 Tan Floor Tile	750	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12x12 Tan Floor Tile Mastic	750	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12x12 Beige Floor Tile	5,000	SF	1925 Building- Rooms 224, 225, 226R, 228 & 229	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
44	12x12 Beige Floor Tile Mastic	6,750	SF	1925 Building- Rooms 224, 225, 226R, 228 & 229	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
45	12x12 Light Brown Floor Tile NOT OBSERVED			1925 Building- Room 216		MISC		0		6 ACBM with the potential for damage	
46	12x12 Light Brown Floor Tile Mastic NOT OBSERVED			1926 Building- Room 216		MISC				6 ACBM with the potential for damage	
47	Black Carpet Mastic NOT OBSERVED			1925 Building- Rooms 117 & 223		MISC				6 ACBM with the potential for damage	
48	Brown Carpet Mastic NOT OBSERVED			1961 Building- Rooms 209 & 211		MISC					
49	Light Brown Carpet Mastic	780	SF	1925 Building- Room 125, Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Insulation in Fire Doors	2	Each	Adjoining Corridor to 1888 building	Assumed	MISC	No	0	Each	6 ACBM with the potential for damage	Follow O&M Plan
51	9x9 Black Floor Tile ABATED 2009			1888 Building- Room 145 Closet	Abated	MISC					
52	9x9 Black Floor Tile Mastic ABATED 2009			1888 Building- Room 145 Closet	Abated	MISC					
53	9x9 Red Floor Tile ABATED 2009			1888 Building- Room 132 Closet	Abated	MISC					

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
54	9x9 Red Floor Tile Mastic ABATED 2009			1888 Building- Room 132 Closet	Abated	MISC					
55	12x12 Tan Floor Tile ABATED 2009			1888 Building- 1st Floor Classrooms & Corridor	Abated	MISC					
56	12x12 Tan Floor Tile Mastic	3,470	SF	1888 Building- 1st Floor Classrooms & Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Insulation in Fire Doors	2	EA	Adjoining Corridor to 1925 Building	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
58	Blue Carpet Mastic NOT OBSERVED			1960 Building- Room 200		MISC				6 ACBM with the potential for damage	
59	12x12 Cream Floor Tile NOT OBSERVED			1925 Building- Room 122		MISC					
60	12x12 Cream Floor Tile Mastic NOT OBSERVED			1925 Building- Room 122		MISC					
61	12x12 Cream w/Brown Specks Floor Tile	500	SF	1925 Building- Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12x12 Cream w/Brown Specks Floor Tile Mastic	500	SF	1925 Building- Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12x12 Brown and Grey Floor Tile	2,000	SF	1925 Building- Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12x12 Brown and Grey Floor Tile Mastic	2,000	SF	1925 Building- Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
65	Blue Carpet Adhesive NOT OBSERVED			1960 Building- Room 212, 211, 209		MISC					
66	Light Blue Carpet Adhesive NOT OBSERVED			1960 Building- Room 200		MISC					
67	Mint Colored Terrazzo Flooring	1,260	SF	1960 Building- Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Multicolored Mosaic Ceramic Tile Grout	1,335	SF	1960 Building- Vestibules, 1st & 2nd Floor Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	Multicolored Mosaic Ceramic Tile Adhesive	1,335	SF	1960 Building- Vestibules, 1st & 2nd Floor Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	1'x1' White Fissured Ceiling Tile	1,560	SF	1960 Building- Rooms 209 & 211	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
70M	1'x1' White Fissured Ceiling Tile Adhesive	1,560	SF	1960 Building- Rooms 209 & 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Green Terrazzo Flooring	1,600	SF	1925 Building- 1st & 2nd Floor Corridors, Stairways, and adjoining Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	White Ceramic Tile Grout	1,570	SF	1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
74	White Ceramic Tile Adhesive	1,570	SF	1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12x12 Brown w/Streaks Floor Tile	360	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75M	12x12 Brown w/Streaks Floor Tile Mastic	360	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12x12 Off-White w/Streaks Floor Tile	360	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76M	12x12 Off-White w/Streaks Floor Tile Mastic	360	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Hard Coat Plaster	114,000	SF	1898 Building- 1st, 2nd & 3rd Floors	Assumed	SURFACE	No	50	SF	6 ACBM with the potential for damage	Repair

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
 Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
78	12x12Grey w/Black Streaks Vinyl Floor Tile	6,600	SF	1961 Building- Main Office, Rooms 103, 105, 109, 110, 113, 200, 202, 205 & 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78M	12x12 Grey w/Black Streaks Vinyl Floor Tile Mastic	8,500	SF	1961 Building- Main Office, Rooms 103, 105, 109, 110, 113, 200, 202, 205 & 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12x12 Beige & Tan Specks Vinyl Floor Tile	800	SF	Kitchen Office, Rooms 107, 112 & 287 (Teachers' Lounge)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79M	12x12 Beige & Tan Specks Vinyl Floor Tile Mastic	800	SF	Kitchen Office, Rooms 107, 112 & 287 (Teachers' Lounge)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Spray-On Insulation	20	SF	Fan Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12x12 Red Floor Tile	300	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81M	12x12 Red Floor Tile Mastic	300	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12x12 Purple Floor Tile	800	SF	Room 215	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82M	12x12 Purple Floor Tile Mastic	800	SF	Room 215	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12x12 Light Grey Floor Tile	48	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83M	12x12 Light Grey Floor Tile Mastic	48	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12x12 Grey Speckled Floor Tile	200	SF	Kitchen Staff Breakroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84M	12x12 Grey Speckled Floor Tile Mastic	200	SF	Kitchen Staff Breakroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Fiberglass Joint Insulation	45	LF	1960 Boiler Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Aircell Joint Insulation ABATED			1888 Building- Boiler Area	Abated	TSI					
C	Hand Packing ABATED			1888 Building- Boiler Room	Abated	TSI					
D	Boiler Insulation ABATED			1888 Building- Boiler Room	Abated	TSI					
E	Tank Insulation ABATED			1888 Building- Boiler & Tank Room	Abated	TSI					
F	Fiberglass Ductwrap	160	SF	1888 Building- Boiler Room	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
H	Aircell Ductwrap ABATED			1888 Building- Boiler Room	Abated	TSI					
I	Aircell Pipe Insulation	400	LF	1888 Building- Boiler Room/Basement Area	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
J	Cardboard Pipe Insulation	300	LF	1888 Building- Basement Area	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	Pre-Form Pipe Insulation	100	LF	1888 Building- Basement Area	Amosite	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
N	Fiberglass Joint Insulation	200	LF	Basement/Tunnel & Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
 Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
O	Fiberglass Joint Insulation	40	LF	1961 Building- Boiler Room, Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
P	Aircell Pipe Joint Insulation	80	LF	1888 Building- Boiler Room/Tunnel & Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Q	Aircell Pipe Joint Insulation	30	LF	1961 Building- Boiler Room/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
R	Aircell Pipe Insulation	400	LF	1926 Building- Boiler Room/Tunnel	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
S	Aircell Pipe Insulation	300	LF	1961 Building- Boiler Room/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
T	Cardboard Pipe Insulation	100	LF	Tunnels Unexcavated Areas	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
U	Pre-form Pipe Insulation	100	LF	1898 Building- Boiler Room, Unexcavated Areas	Amosite	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
V	Cardboard Pipe Joint Insulation	10	LF	1925 Building- Tunnels/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
W	Cardboard Pipe Joint Insulation	15	LF	1888 Building- Basement/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
X	Pre-Form Pipe Joint Insulation	10	LF	1888 Building- Boiler Room/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Y	Pre-form Pipe Joint Insulation	10	LF	1888 Building- Boiler Room/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan



# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
 Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	12/12/2022
Manager Planner Name	Todd Huffer
100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
04	
10	
11	
13	
14	
15	
1500	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
70M	
71	
73	
74	
75	
75M	
76	
76M	
77	
78	

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
 Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
78M	
79	
79M	
80	
81	
81M	
82	
82M	
83	
83M	
84	
84M	
A	
B	
C	
D	
E	
F	
H	
I	
J	
K	
N	
NEW	
O	
P	
Q	

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
R	
S	
T	
U	
V	
W	
X	
Y	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Accoustical Stucco Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Lunchroom, 1st Floor Corridor**  
MATERIAL QUANTITY: **7050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Accoustical Stucco Plaster**  
MATERIAL LOCATION: **1961 Building- Lunchroom, 1st Floor Corridor**  
MATERIAL QUANTITY: **7050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 10  
MATERIAL DESCRIPTION: 9x9 Pinkish Tan Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1961 Building- 1st & 2nd Floor Classrooms  
MATERIAL QUANTITY: 11750 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9x9 Pinkish Tan Floor Tile**  
MATERIAL LOCATION: **1961 Building- 1st & 2nd Floor Classrooms**  
MATERIAL QUANTITY: **11750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 200, 200R, 209, 211, 212, 224 & 225**  
MATERIAL QUANTITY: **11400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS: **Damage Not Observed 2022**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 200, 200R, 209, 211, 212, 224 & 225**  
MATERIAL QUANTITY: **11400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13  
MATERIAL DESCRIPTION: Transite  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- 2nd Floor Corridor  
MATERIAL QUANTITY: 10    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Transite**  
MATERIAL LOCATION: **1925 Building- 2nd Floor Corridor**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Accoustic Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Accoustic Plaster**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed on 1st Floor Corridor 2022**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1500**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Rooms 120 & 288**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Room 288 Not Observed**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **1500**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
MATERIAL LOCATION: **1925 Building- Rooms 120 & 288**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- 2nd Floor Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9x9 Brown Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1888 Building- 2nd Floor Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17  
MATERIAL DESCRIPTION: 12x12 Beige Floor Tile NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Rooms 124, 126, 129 & Main Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **1925 Building- Rooms 124, 126, 129 & Main Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18  
MATERIAL DESCRIPTION: 12x12 Brown Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1888 Building- 1st Floor Classrooms & Corridor

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile ABATED**  
MATERIAL LOCATION: **1888 Building- 1st Floor Classrooms & Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 19  
MATERIAL DESCRIPTION: 9x9 Brown Floor Tile Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- 1st Floor Classrooms & Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- 1st Floor Classrooms & Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20  
MATERIAL DESCRIPTION: 9x9 Tan Floor Tile Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- 1st & 2nd Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9x9 Tan Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- 2nd Floor Classrooms Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **12/07/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1888 Building- 2nd Floor Classrooms Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22  
MATERIAL DESCRIPTION: 12x12 Grey Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 200, 200R, 209, 211, 212, 224 & 225**

MATERIAL QUANTITY: **11400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 200, 200R, 209, 211, 212, 224 & 225**  
MATERIAL QUANTITY: **11400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23  
MATERIAL DESCRIPTION: 12x12 Beige Floor Tile Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Rooms 124, 126, 129, and Main Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Rooms 124, 126, 129, and Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24  
MATERIAL DESCRIPTION: 12x12 Brown Floor Tile Mastic ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1888 Building- 1st Floor Corridor

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1888 Building- 1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Transite**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- 1st, 2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Transite**  
MATERIAL LOCATION: **1888 Building- 1st, 2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Basement, Kitchen/Cafeteria & Room 223**  
MATERIAL QUANTITY: **6350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **1961 Building- Basement, Kitchen/Cafeteria & Room 223**  
MATERIAL QUANTITY: **6350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27  
MATERIAL DESCRIPTION: 12x12 Beige Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1961 Building- Basement, Kitchen/Cafeteria & Room 223  
MATERIAL QUANTITY: 6350    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1961 Building- Basement, Kitchen/Cafeteria & Room 223**  
MATERIAL QUANTITY: **6350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1961 Building- Basement, 1st & 2nd Floor Corridor Borders, Room 223 & Kitchen/Cafeteria**

MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
MATERIAL LOCATION: **1961 Building- Basement, 1st & 2nd Floor Corridor Borders, Room 223 & Kitchen/Cafeteria**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1961 Building- Basement, 1st & 2nd Floor Corridor Borders, Room 223 & Kitchen/Cafeteria**

MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1961 Building- Basement, 1st & 2nd Floor Corridor Borders, Room 223 & Kitchen/Cafeteria**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Building- 1st & 2nd Floor Corridor**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Damage Not Observed 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**  
MATERIAL LOCATION: **1961 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31  
MATERIAL DESCRIPTION: 12x12 Yellow Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 5 ACBM with potential for significant damage  
HISTORICAL DAMAGE REASON: Physical Damage  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1961 Building- 1st & 2nd Floor Corridors**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Damage Not Observed 2022**

Inspector's Signature: *Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**  
MATERIAL LOCATION: **1961 Building- 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32  
MATERIAL DESCRIPTION: Brown Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Rooms 127 & 227 (Library)  
MATERIAL QUANTITY: 1800    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Room 127. Room 227 is the Library

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **1925 Building- Rooms 127 & 227 (Library)**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33  
MATERIAL DESCRIPTION: Green Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1961 Building- Rooms 120A & 209  
MATERIAL QUANTITY: 750 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Not Observed in Room 209- 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
MATERIAL LOCATION: **1961 Building- Rooms 120A & 209**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34  
MATERIAL DESCRIPTION: Insulation in Firedoors  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1961 Building- Boiler Room  
MATERIAL QUANTITY: 3    MATERIAL UNITS: EA  
DAMAGE QUANTITY:    DAMAGE UNITS: EA

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Insulation in Firedoors**  
MATERIAL LOCATION: **1961 Building- Boiler Room**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35  
MATERIAL DESCRIPTION: Drywall  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Rooms 120 and 225  
MATERIAL QUANTITY: 400    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **1925 Building- Rooms 120 and 225**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 36  
MATERIAL DESCRIPTION: Drywall Joint Compound  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Rooms 120 and 225  
MATERIAL QUANTITY: 200    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **1925 Building- Rooms 120 and 225**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 37  
MATERIAL DESCRIPTION: 9x9 Brown Floor Tile NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- 1st & 2nd Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 38  
MATERIAL DESCRIPTION: 9x9 Brown Floor Tile Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- 1st & 2nd Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39  
MATERIAL DESCRIPTION: 12x12 Brown Floor Tile NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE:    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Room 217

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Room 217**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 40  
MATERIAL DESCRIPTION: 12x12 Brown Floor Tile Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Room 217

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Room 217**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 41  
MATERIAL DESCRIPTION: 12x12 Tan Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Room 223  
MATERIAL QUANTITY: 750    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: See HAs 26, 27, 28 & 29

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 42  
MATERIAL DESCRIPTION: 12x12 Tan Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Room 223  
MATERIAL QUANTITY: 750    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: See HAs 26, 27, 28 & 29

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 43  
MATERIAL DESCRIPTION: 12x12 Beige Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 5 ACBM with potential for significant damage  
HISTORICAL DAMAGE REASON: Physical Damage  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: Physical Damage  
DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: 1925 Building- Rooms 224, 225, 226R, 228 & 229  
MATERIAL QUANTITY: 5000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Rooms 224 & 225. No Damage Observed

Inspector's Signature: Christopher Antonopoulos

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **1925 Building- Rooms 224, 225, 226R, 228 & 229**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Rooms 224, 225, 226R, 228 & 229**  
MATERIAL QUANTITY: **6750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **6750** DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Rooms 224 & 225. No Damage Observed**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Rooms 224, 225, 226R, 228 & 229**  
MATERIAL QUANTITY: **6750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 45  
MATERIAL DESCRIPTION: 12x12 Light Brown Floor Tile NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Room 216

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: There is no Room 216

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **1925 Building- Room 216**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 46  
MATERIAL DESCRIPTION: 12x12 Light Brown Floor Tile Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE:    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1926 Building- Room 216

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: There is no Room 216

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1926 Building- Room 216**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 47  
MATERIAL DESCRIPTION: Black Carpet Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE:    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Rooms 117 & 223

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Black Carpet Mastic NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Rooms 117 & 223**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Building- Rooms 209 & 211**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Brown Carpet Mastic NOT OBSERVED**

MATERIAL LOCATION: **1961 Building- Rooms 209 & 211**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 49  
MATERIAL DESCRIPTION: Light Brown Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Room 125, Principal's Office  
MATERIAL QUANTITY: 780 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Light Brown Carpet Mastic**  
MATERIAL LOCATION: **1925 Building- Room 125, Principal's Office**  
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 50  
MATERIAL DESCRIPTION: Insulation in Fire Doors  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Adjoining Corridor to 1888 building  
MATERIAL QUANTITY: 2    MATERIAL UNITS: Each  
DAMAGE QUANTITY:    DAMAGE UNITS: Each

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Insulation in Fire Doors**  
MATERIAL LOCATION: **Adjoining Corridor to 1888 building**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **Each**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **Each**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 51  
MATERIAL DESCRIPTION: 9x9 Black Floor Tile ABATED 2009  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1888 Building- Room 145 Closet

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **9x9 Black Floor Tile ABATED 2009**

MATERIAL LOCATION: **1888 Building- Room 145 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 52  
MATERIAL DESCRIPTION: 9x9 Black Floor Tile Mastic ABATED 2009  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1888 Building- Room 145 Closet

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **9x9 Black Floor Tile Mastic ABATED 2009**

MATERIAL LOCATION: **1888 Building- Room 145 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 53  
MATERIAL DESCRIPTION: 9x9 Red Floor Tile ABATED 2009  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: 1888 Building- Room 132 Closet  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **9x9 Red Floor Tile ABATED 2009**

MATERIAL LOCATION: **1888 Building- Room 132 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 54  
MATERIAL DESCRIPTION: 9x9 Red Floor Tile Mastic ABATED 2009  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1888 Building- Room 132 Closet

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **9x9 Red Floor Tile Mastic ABATED 2009**

MATERIAL LOCATION: **1888 Building- Room 132 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 55  
MATERIAL DESCRIPTION: 12x12 Tan Floor Tile ABATED 2009  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1888 Building- 1st Floor Classrooms & Corridor

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12x12 Tan Floor Tile ABATED 2009**

MATERIAL LOCATION: **1888 Building- 1st Floor Classrooms & Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 56  
MATERIAL DESCRIPTION: 12x12 Tan Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1888 Building- 1st Floor Classrooms & Corridor  
MATERIAL QUANTITY: 3470    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1888 Building- 1st Floor Classrooms & Corridor**  
MATERIAL QUANTITY: **3470** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 57  
MATERIAL DESCRIPTION: Insulation in Fire Doors  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Adjoining Corridor to 1925 Building  
MATERIAL QUANTITY: 2    MATERIAL UNITS: EA  
DAMAGE QUANTITY:    DAMAGE UNITS: EA

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Insulation in Fire Doors**  
MATERIAL LOCATION: **Adjoining Corridor to 1925 Building**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 58  
MATERIAL DESCRIPTION: Blue Carpet Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building- Room 200

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Blue Carpet Mastic NOT OBSERVED**

MATERIAL LOCATION: **1960 Building- Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 59  
MATERIAL DESCRIPTION: 12x12 Cream Floor Tile NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Room 122

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12x12 Cream Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Room 122**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 60  
MATERIAL DESCRIPTION: 12x12 Cream Floor Tile Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE:    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Room 122

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Room 122**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 61  
MATERIAL DESCRIPTION: 12x12 Cream w/Brown Specks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Room 120  
MATERIAL QUANTITY: 500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 120**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 62  
MATERIAL DESCRIPTION: 12x12 Cream w/Brown Specks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Room 120  
MATERIAL QUANTITY: 500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 120**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 63  
MATERIAL DESCRIPTION: 12x12 Brown and Grey Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Auditorium  
MATERIAL QUANTITY: 2000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Black Wax Covering Material

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12x12 Brown and Grey Floor Tile**  
MATERIAL LOCATION: **1925 Building- Auditorium**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 64  
MATERIAL DESCRIPTION: 12x12 Brown and Grey Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Auditorium  
MATERIAL QUANTITY: 2000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Black Wax Covering Material

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12x12 Brown and Grey Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Auditorium**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **Blue Carpet Adhesive NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 Building- Room 212, 211, 209**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **Blue Carpet Adhesive NOT OBSERVED**  
MATERIAL LOCATION: **1960 Building- Room 212, 211, 209**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 66  
MATERIAL DESCRIPTION: Light Blue Carpet Adhesive NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building- Room 200

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Light Blue Carpet Adhesive NOT OBSERVED**

MATERIAL LOCATION: **1960 Building- Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Mint Colored Terrazzo Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Building- Stairways**  
MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Mint Colored Terrazzo Flooring**  
MATERIAL LOCATION: **1960 Building- Stairways**  
MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 68  
MATERIAL DESCRIPTION: Multicolored Mosaic Ceramic Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1960 Building- Vestibules, 1st & 2nd Floor Boys' and Girls' Washrooms  
MATERIAL QUANTITY: 1335    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **Multicolored Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **1960 Building- Vestibules, 1st & 2nd Floor Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **1335** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 69  
MATERIAL DESCRIPTION: Multicolored Mosaic Ceramic Tile Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Building- Vestibules, 1st & 2nd Floor Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **1335**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **Multicolored Mosaic Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1960 Building- Vestibules, 1st & 2nd Floor Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **1335** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 70  
MATERIAL DESCRIPTION: 1'x1' White Fissured Ceiling Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 7 Any remaining friable ACBM or friable suspect ACBM  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Building- Rooms 209 & 211**  
MATERIAL QUANTITY: **1560**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **1'x1' White Fissured Ceiling Tile**  
MATERIAL LOCATION: **1960 Building- Rooms 209 & 211**  
MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 70M  
MATERIAL DESCRIPTION: 1'x1' White Fissured Ceiling Tile Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1960 Building- Rooms 209 & 211  
MATERIAL QUANTITY: 1560    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **70M**  
MATERIAL DESCRIPTION: **1'x1' White Fissured Ceiling Tile Adhesive**  
MATERIAL LOCATION: **1960 Building- Rooms 209 & 211**  
MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 71  
MATERIAL DESCRIPTION: Green Terrazzo Flooring  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- 1st & 2nd Floor Corridors, Stairways, and adjoining Corridor  
MATERIAL QUANTITY: 1600    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **Green Terrazzo Flooring**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridors, Stairways, and adjoining Corridor**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 73  
MATERIAL DESCRIPTION: White Ceramic Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY: 7 Any remaining friable ACBM or friable suspect ACBM  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms  
MATERIAL QUANTITY: 1570    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **White Ceramic Tile Grout**  
MATERIAL LOCATION: **1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **1570** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 74  
MATERIAL DESCRIPTION: White Ceramic Tile Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms  
MATERIAL QUANTITY: 1570    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **1570** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 75  
MATERIAL DESCRIPTION: 12x12 Brown w/Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Room 223  
MATERIAL QUANTITY: 360    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 75M  
MATERIAL DESCRIPTION: 12x12 Brown w/Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Room 223  
MATERIAL QUANTITY: 360    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **75M**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Streaks Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76M**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **76M**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1898 Building- 1st, 2nd & 3rd Floors**  
MATERIAL QUANTITY: **114000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage Observed in Auditorium and Classrooms**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **1898 Building- 1st, 2nd & 3rd Floors**  
MATERIAL QUANTITY: **114000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12x12Grey w/Black Streaks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Main Office, Rooms 103, 105, 109, 110, 113, 200, 202, 205 & 212**  
MATERIAL QUANTITY: **6600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12x12Grey w/Black Streaks Vinyl Floor Tile**  
MATERIAL LOCATION: **1961 Building- Main Office, Rooms 103, 105, 109, 110, 113, 200, 202, 205 & 212**  
MATERIAL QUANTITY: **6600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78M**  
MATERIAL DESCRIPTION: **12x12 Grey w/Black Streaks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Main Office, Rooms 103, 105, 109, 110, 113, 200, 202, 205 & 212**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **78M**  
MATERIAL DESCRIPTION: **12x12 Grey w/Black Streaks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **1961 Building- Main Office, Rooms 103, 105, 109, 110, 113, 200, 202, 205 & 212**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 79  
MATERIAL DESCRIPTION: 12x12 Beige & Tan Specks Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Kitchen Office, Rooms 107, 112 & 287 (Teachers' Lounge)  
MATERIAL QUANTITY: 800    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **12x12 Beige & Tan Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Kitchen Office, Rooms 107, 112 & 287 (Teachers' Lounge)**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 79M  
MATERIAL DESCRIPTION: 12x12 Beige & Tan Specks Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Kitchen Office, Rooms 107, 112 & 287 (Teachers' Lounge)  
MATERIAL QUANTITY: 800    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **79M**  
MATERIAL DESCRIPTION: **12x12 Beige & Tan Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Kitchen Office, Rooms 107, 112 & 287 (Teachers' Lounge)**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A  
MATERIAL DESCRIPTION: Fiberglass Joint Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 7 Any remaining friable ACBM or friable suspect ACBM  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1960 Boiler Room  
MATERIAL QUANTITY: 45    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**  
MATERIAL LOCATION: **1960 Boiler Room**  
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Aircell Joint Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- Boiler Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **12/07/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Aircell Joint Insulation ABATED**

MATERIAL LOCATION: **1888 Building- Boiler Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: C  
MATERIAL DESCRIPTION: Hand Packing ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1888 Building- Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Hand Packing ABATED**

MATERIAL LOCATION: **1888 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Boiler Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **12/07/2022**

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Boiler Insulation ABATED**  
MATERIAL LOCATION: **1888 Building- Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: E  
MATERIAL DESCRIPTION: Tank Insulation ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1888 Building- Boiler & Tank Room

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Tank Insulation ABATED**

MATERIAL LOCATION: **1888 Building- Boiler & Tank Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: F  
MATERIAL DESCRIPTION: Fiberglass Ductwrap  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1888 Building- Boiler Room  
MATERIAL QUANTITY: 160    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Fiberglass Ductwrap**  
MATERIAL LOCATION: **1888 Building- Boiler Room**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: H  
MATERIAL DESCRIPTION: Aircell Ductwrap ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1888 Building- Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Aircell Ductwrap ABATED**  
MATERIAL LOCATION: **1888 Building- Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: I  
MATERIAL DESCRIPTION: Aircell Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1888 Building- Boiler Room/Basement Area  
MATERIAL QUANTITY: 400 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Basement Area**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: J  
MATERIAL DESCRIPTION: Cardboard Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1888 Building- Basement Area  
MATERIAL QUANTITY: 300    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **1888 Building- Basement Area**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: K  
MATERIAL DESCRIPTION: Pre-Form Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Amosite FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1888 Building- Basement Area  
MATERIAL QUANTITY: 100 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Pre-Form Pipe Insulation**  
MATERIAL LOCATION: **1888 Building- Basement Area**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: N  
MATERIAL DESCRIPTION: Fiberglass Joint Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Basement/Tunnel & Unexcavated Areas  
MATERIAL QUANTITY: 200    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**  
MATERIAL LOCATION: **Basement/Tunnel & Unexcavated Areas**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **O**  
MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Boiler Room, Unexcavated Areas**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**  
MATERIAL LOCATION: **1961 Building- Boiler Room, Unexcavated Areas**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: P  
MATERIAL DESCRIPTION: Aircell Pipe Joint Insulation  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1888 Building- Boiler Room/Tunnel & Unexcavated Areas  
MATERIAL QUANTITY: 80 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Aircell Pipe Joint Insulation**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Tunnel & Unexcavated Areas**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Q  
MATERIAL DESCRIPTION: Aircell Pipe Joint Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1961 Building- Boiler Room/Unexcavated Areas  
MATERIAL QUANTITY: 30    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Aircell Pipe Joint Insulation**  
MATERIAL LOCATION: **1961 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: R  
MATERIAL DESCRIPTION: Aircell Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1926 Building- Boiler Room/Tunnel  
MATERIAL QUANTITY: 400    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1926 Building- Boiler Room/Tunnel**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25601 BUIDLING ID: 6180  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: S  
MATERIAL DESCRIPTION: Aircell Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1961 Building- Boiler Room/Unexcavated Areas  
MATERIAL QUANTITY: 300 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1961 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: T  
MATERIAL DESCRIPTION: Cardboard Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Tunnels Unexcavated Areas  
MATERIAL QUANTITY: 100    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Tunnels Unexcavated Areas**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: U  
MATERIAL DESCRIPTION: Pre-form Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Amosite    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1898 Building- Boiler Room, Unexcavated Areas  
MATERIAL QUANTITY: 100    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Pre-form Pipe Insulation**  
MATERIAL LOCATION: **1898 Building- Boiler Room, Unexcavated Areas**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 25601    BUILDING ID: 6180  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Thorp School    INSPECTION DATE: 12/7/2022  
ADDRESS: 8914 S Buffalo Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: V  
MATERIAL DESCRIPTION: Cardboard Pipe Joint Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1925 Building- Tunnels/Unexcavated Areas  
MATERIAL QUANTITY: 10    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Cardboard Pipe Joint Insulation**  
MATERIAL LOCATION: **1925 Building- Tunnels/Unexcavated Areas**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Cardboard Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- Basement/Unexcavated Areas**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Cardboard Pipe Joint Insulation**  
MATERIAL LOCATION: **1888 Building- Basement/Unexcavated Areas**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **Pre-Form Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **Pre-Form Pipe Joint Insulation**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **Pre-form Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **Pre-form Pipe Joint Insulation**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/12/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25601**      BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School**      REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **12x12 Light Grey Floor Tile**  
MATERIAL LOCATION: **Room 112**  
MATERIAL QUANTITY: **48**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25601**      BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School**      REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **300**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **81M**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **300**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25601**      BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School**      REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **81M**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **300**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **83M**  
MATERIAL DESCRIPTION: **12x12 Light Grey Floor Tile Mastic**  
MATERIAL LOCATION: **Room 112**  
MATERIAL QUANTITY: **48**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **83M**  
MATERIAL DESCRIPTION: **12x12 Light Grey Floor Tile Mastic**  
MATERIAL LOCATION: **Room 112**  
MATERIAL QUANTITY: **48** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25601**      BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School**      REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **Spray-On Insulation**  
MATERIAL LOCATION: **Fan Room**  
MATERIAL QUANTITY: **20**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **12x12 Grey Speckled Floor Tile**  
MATERIAL LOCATION: **Kitchen Staff Breakroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **84M**  
MATERIAL DESCRIPTION: **12x12 Grey Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Kitchen Staff Breakroom**  
MATERIAL QUANTITY: **200**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 12/07/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **84M**  
MATERIAL DESCRIPTION: **12x12 Grey Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Kitchen Staff Breakroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **12/7/2022**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **82M**  
MATERIAL DESCRIPTION: **12x12 Purple Floor Tile Mastic**  
MATERIAL LOCATION: **Room 215**  
MATERIAL QUANTITY: **800**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 12/07/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25601**      BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School**      REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **82M**  
MATERIAL DESCRIPTION: **12x12 Purple Floor Tile Mastic**  
MATERIAL LOCATION: **Room 215**  
MATERIAL QUANTITY: **800**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25601**      BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School**      REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25601**      BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Thorp School**      REVIEW DATE: **12/12/2022**  
ADDRESS: **8914 S Buffalo Avenue**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **12x12 Purple Floor Tile**  
MATERIAL LOCATION: **Room 215**  
MATERIAL QUANTITY: **800**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/12/2022

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER ANTONOPOULOS  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 06/01/2021 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II; Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

06/01/2021

Course Dates:

06/01/2022

Expires:

2106BIR11

Certificate Number:

A handwritten signature in black ink, appearing to read "N Penneff".

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER J. ANTONOPOULOS  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 06/03/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

06/03/2022

Course Dates:

06/03/2023

Expires:

2206BIR01

Certificate Number:



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com


A handwritten signature in black ink, appearing to read "N. Peneff", is written over a light gray rectangular background.

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B




 **ASBESTOS  
PROFESSIONAL  
LICENSE**

<b>ID NUMBER</b>	<b>ISSUED</b>	<b>EXPIRES</b>
100 - 18281	2/10/2022	05/15/2023

**CHRISTOPHER J ANTONOPO**  
1736 W 102nd ST  
CHICAGO, IL 60643

Environmental Health



<b>ENDORSEMENT</b>	<b>TC EXPIRES</b>
INSPECTOR	6/1/2022

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**TODD T HUFFER**  
315 HATLEN COURT  
MT. PROSPECT, IL 60056

2/18/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

			<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 09870	<b>ISSUED</b> 2/18/2022	<b>EXPIRES</b> 05/15/2023			INSPECTOR	11/1/2022
<b>TODD T HUFFER</b> 315 HATLEN COURT MT. PROSPECT, IL 60056 Environmental Health					MANAGEMENT PLANNER	11/19/2022
					PROJECT MANAGER	10/20/2022
					AIR SAMPLING PROFESSIONAL	
					<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815

  
Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255

  
Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265

  
Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed