

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2502  
SCHOOL NAME: Warren School  
ADDRESS OF SCHOOL: 9239 S Jeffrey  
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/20/2019**


**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** (Please type or print)

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 6/13/2022 ENROLLMENT 263  
IDPH INSPECTOR LICENSE NUMBER: 100-09786  
IDPH LICENSED INSPECTOR NAME (Please Print): John Fenn  
IDPH MP LICENSE NUMBER: 100-03613  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



7/10/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Warren School**

9239 S Jeffrey  
Chicago, IL, 60617

Unit: 25761  
Building ID: 6350

IDPH ID Number: 14-016-2990-2502

**REPORT DATE:**

Sunday, July 10, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

07/10/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 25761                      Region: 06                      IDPH ID: 14-016-2990-2502

School: Warren School                      Building ID: 6350

Address: 9239 S Jeffrey

Chicago, IL, 60617

Building Contact: Gonzalez, Cecilia

Contact Phone: 7737097028

Current Building Owners: Chicago Public Schools

Reinspection Date: 6/13/2022

Review Date: 07/10/2022

Inspector: John Fenn

Inspector IDPH License: 100-09786

Management Planner: Daniel Juneau

Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Daniel Juneau  
100-03613

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: July 10, 2022

RE: Warren School, Unit 25761  
9239 S Jeffrey  
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Warren School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Warren School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Warren School Unit: 25761 Region: 06  
Address: 9239 S Jeffrey Chicago, IL, 60617  
IDPH ID: 14-016-2990-2502 Building ID: 6350  
Contact: Gonzalez, Cecilia Phone: 7737097028

### 2. Description of Facility

Original Construction: 1971 Additional Construction:  
Total Square Footage: 27715 No of Floors: 2  
Current Occupancy: 263

### 3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602


### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880 Fax: 630-790-0882

### 5. Inspector

Inspector Name: John Fenn


Inspector IDPH license # 100-09786  
Reinspection Date: 6/13/2022

  
Signature:  
Date: 6/13/2022

### 6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613


  
Signature:  
Date: 07/10/2022

### 7. Review Date: 07/10/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 7/10/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Warren School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6350:

NEW

Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 6350:

NEW

Newly Installed Suspect ACM



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02B	12x12 Off-White Floor Tile
02C	12x12 Brown Speckled Floor Tile
02D	12x12 Off-White Speckled Floor Tile
02E	12x12 Beige w/Streaks Floor Tile
02F	12x12 Light Brown w/Streaks Floor Tile
02G	12x12 Brown Floor Tile
02H	12x12 Beige Mottled Floor Tile
05A	12x12 Brown Speckled Floor Tile
05B	12x12 Off-White Speckled Floor Tile
07F	12x12 Light Brown Streaked Floor Tile Mastic
07G	12x12 Brown Floor Tile Mastic
07H	12x12 Beige Mottled Floor Tile Mastic
40	Beige Carpet Mastic
41	12x12 Red Floor Tile
42	12x12 Red Floor Tile Mastic
43	12x12 Dark Blue Floor Tile
44	12x12 Dark Blue Floor Tile Mastic
45	12x12 Light Blue Floor Tile
46	12x12 Light Blue Floor Tile Mastic
47	12x12 Bright Blue Floor Tile
48	12x12 Bright Blue Floor Tile Mastic
49	Green and Blue Carpet Mastic- NOT OBSERVED
50	Brown and Black Mosaic Ceramic Tile Grout
51	Brown and Black Mosaic Ceramic Tile Adhesive
52	White Ceramic Tile Grout
53	White Ceramic Tile Adhesive
54	Black Ceramic Tile Grout
55	Multi-Colored Ceramic Tile Adhesive
56	Yellow Mosaic Ceramic Tile Grout
57	Yellow Mosaic Ceramic Tile Adhesive
58	Gray and Green Carpet Adhesive
59	Beige w/Red Specks Terrazzo Floor
60	Brown Carpet Adhesive
61	Blue Mosaic Ceramic Tile Grout
62	Blue Mosaic Ceramic Tile Adhesive
63	Brown Mosaic Ceramic Tile Grout
64	Brown Mosaic Ceramic Tile Adhesive
65	2'x4' White Fissured Ceiling Tile
66	2'x4' Smooth Ceiling Tile
67	Dark Grey Mosaic Ceramic Tile Grout
68	Dark Grey Mosaic Ceramic Tile Adhesive
69	Drywall Ceilings

70	Soft Plaster Ceiling
71	12x12 Beige Streaked Vinyl Floor Tile
71A	12x12 Beige Streaked Vinyl Floor Tile Mastic
L	MJP on Fiberglass Pipes
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

07A	12x12 Beige Speckled Floor Tile Mastic
07B	12x12 Off-White Floor Tile Mastic
07C	12x12 Brown Speckled Floor Tile Mastic
07D	12x12 Off-White Speckled Floor Tile Mastic
07E	12x12 Beige Streaked Floor Tile Mastic
07F	12x12 Light Brown Streaked Floor Tile Mastic
07G	12x12 Brown Floor Tile Mastic
07H	12x12 Beige Mottled Floor Tile Mastic
07I	12x12 Gray Floor Tile Mastic
08A	12x12 Brown Speckled Floor Tile Mastic
08B	12x12 Off White Speckled Floor Tile Mastic
09A	9x9 Tan Speckled Floor Tile Mastic
09B	9x9 Brown Speckled Floor Tile Mastic
40	Beige Carpet Mastic
42	12x12 Red Floor Tile Mastic
44	12x12 Dark Blue Floor Tile Mastic
46	12x12 Light Blue Floor Tile Mastic
48	12x12 Bright Blue Floor Tile Mastic
51	Brown and Black Mosaic Ceramic Tile Adhesive
53	White Ceramic Tile Adhesive
55	Multi-Colored Ceramic Tile Adhesive
57	Yellow Mosaic Ceramic Tile Adhesive
58	Gray and Green Carpet Adhesive
60	Brown Carpet Adhesive
62	Blue Mosaic Ceramic Tile Adhesive
64	Brown Mosaic Ceramic Tile Adhesive
68	Dark Grey Mosaic Ceramic Tile Adhesive
71A	12x12 Beige Streaked Vinyl Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by John Fenn, IDPH License # 100-09786. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	12/27/2019
	11/1/2020
	6/29/2022
	7/12/2022

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Warren School Building 6350 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Warren School Unit 25761 Building ID 6350

Address 9239 S Jeffrey Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02A	12x12 Light Beige Speckled Floor Tile/Mastic	6,315	SF	1971 Building- Kitchen Office & Storage, Gym, Cafeteria, Janitor's Closets, Teacher's Lunchroom, Office Storage, Vault, Library Work Room & Engineer's Office	CHR	MISC	N	LOC	100		No	ACBM with the potential for damage		MODERATE
02B	12x12 Off-White Floor Tile	120	SF	1971 Building- Kitchen Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02C	12x12 Brown Speckled Floor Tile	1,350	SF	1971 Building- 1st & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02D	12x12 Off-White Speckled Floor Tile	1,350	SF	1971 Building- 1st and 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02E	12x12 Beige w/Streaks Floor Tile	1,125	SF	1971 Building- Rooms 120, 121, 124	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02F	12x12 Light Brown w/Streaks Floor Tile	1,125	SF	1971 Building- Rooms 120, 121, and 124	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02G	12x12 Brown Floor Tile	375	SF	1971 Building- Room 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02H	12x12 Beige Mottled Floor Tile	375	SF	1971 Building- Room 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02I	12x12 Gray Floor Tile	450	SF	1971 Building- Lunchroom Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05A	12x12 Brown Speckled Floor Tile	1,490	SF	1959 Building- Teachers' Lounge, Corridor, and Room 113	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05B	12x12 Off-White Speckled Floor Tile	1,490	SF	1959 Building- Teachers' Lounge, Corridor, and Room 113	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05C	12x12 Tan Speckled Floor Tile	1,300	SF	1959 Building- Room 112	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
06A	9x9 Tan Speckled Floor Tile	5,650	SF	1959 Building- Rooms 105, 106, 107, 108, 109, 110, and 111	CHR	MISC	N	DIST	235		No	ACBM with the potential for damage	5	MODERATE
06B	9x9 Light Brown Speckled Floor Tile	200	SF	1959 Building-	CHR	MISC	N	NONE	0		No	ACBM with the		MODERATE

# Chicago Public Schools

School Warren School Unit 25761 Building ID 6350

Address 9239 S Jeffrey Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room 112								potential for damage		
07A	12x12 Beige Speckled Floor Tile Mastic	6,315	SF	1971 Building-Kitchen Office & Storage, Gym, Cafeteria, Janitor's Closets, Engineer's Office, Teacher's Lunchroom, Office Storage, Vault, Library Work Room	CHR	MISC	N	LOC	100		No	ACBM with the potential for damage		MODERATE
07B	12x12 Off-White Floor Tile Mastic	120	SF	1971 Building-Kitchen Hallway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07C	12x12 Brown Speckled Floor Tile Mastic	1,350	SF	1971 Building- 1st & 2nd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07D	12x12 Off-White Speckled Floor Tile Mastic	1,350	SF	1971 Building- 1st & 2nd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07E	12x12 Beige Streaked Floor Tile Mastic	1,125	SF	1971 Building-Rooms 120, 121, & 124	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07F	12x12 Light Brown Streaked Floor Tile Mastic	1,125	SF	1971 Building-Rooms 120, 121, & 124	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07G	12x12 Brown Floor Tile Mastic	375	SF	1971 Building-Room 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07H	12x12 Beige Mottled Floor Tile Mastic	375	SF	1971 Building-Room 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07I	12x12 Gray Floor Tile Mastic	450	SF	1971 Building-Lunchroom Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08A	12x12 Brown Speckled Floor Tile Mastic	1,490	SF	1959 Building-Teachers Lounge, Corridors, Room 113	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08B	12x12 Off White Speckled Floor Tile Mastic	1,490	SF	1959 Building-Teachers' Lounge, Corridor, Room 113	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08C	12x12 Tan Speckled Floor Tile	1,300	SF	1959 Building-Room 112	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
09A	9x9 Tan Speckled Floor Tile Mastic	5,650	SF	1959 Building-Rooms 105, 106, 107, 108, 109, 110 & 111	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09B	9x9 Brown Speckled Floor Tile Mastic	200	SF	1959 Building-	CHR	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Warren School Unit 25761 Building ID 6350

Address 9239 S Jeffrey Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	OBSERVED													
50	Brown and Black Mosaic Ceramic Tile Grout	1,400	SF	1971 Building-Kitchen, Kitchen Locker Room and All Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	Brown and Black Mosaic Ceramic Tile Adhesive	1,400	SF	1971 Building-Kitchen, Kitchen Locker Room and All Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	White Ceramic Tile Grout	20	SF	1971 Building-Patches in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	White Ceramic Tile Adhesive	20	SF	1971 Building-Patches in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Black Ceramic Tile Grout	20	SF	1971 Building-Patches in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	Multi-Colored Ceramic Tile Adhesive	20	SF	1971 Building-Patches in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Yellow Mosaic Ceramic Tile Grout	10	SF	1971 Building-Patches in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	Yellow Mosaic Ceramic Tile Adhesive	10	SF	1971 Building-Patches in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	Gray and Green Carpet Adhesive	2,650	SF	1971 Building-Library, 121, Main Office and Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Beige w/Red Specks Terrazzo Floor	400	SF	1971 Building-Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	Brown Carpet Adhesive	675	SF	1971 Building-Room 226	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Blue Mosaic Ceramic Tile Grout	560	SF	1971 Building-Men's and Boy's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	Blue Mosaic Ceramic Tile Adhesive	560	SF	1971 Building-Men's and Boy's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	Brown Mosaic Ceramic Tile Grout	600	SF	1971 Building-Women's and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	Brown Mosaic Ceramic Tile Adhesive	600	SF	1971 Building-Women's and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	2'x4' White Fissured Ceiling Tile	28,000	SF	1971 Building-Throughout	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW



# Chicago Public Schools

School Warren School Unit 25761 Building ID 6350

Address 9239 S Jeffrey Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
66	2'x4' Smooth Ceiling Tile	1,800	SF	1971 Building- Kitchen, Washrooms and Patched Areas	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
67	Dark Grey Mosaic Ceramic Tile Grout	800	SF	1959 Building- Vestibules, and Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	Dark Grey Mosaic Ceramic Tile Adhesive	800	SF	1959 Building- Vestibules, and Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	Drywall Ceilings	250	SF	1959 Building- Boys' & Girls' Toilets and Janitor's Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	Soft Plaster Ceiling	50,000	SF	1959 Building- Throughout Corridor & Classrooms	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
71	12x12 Beige Streaked Vinyl Floor Tile	1,840	SF	1959 Building- 107, 109 and Underneath all Univents	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71A	12x12 Beige Streaked Vinyl Floor Tile Mastic	1,840	SF	1959 Building- 107, 109 and Underneath all Uni-vents	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
F	Aircell Pipe Insulation	30	LF	1959 Building- Bathroom Pipe Chase	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Cardboard Pipe Insulation	30	LF	1959 Building- Bathroom Pipe Chase	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
H	MJP E/F/V on Aircell Pipe Insulation	10	LF	1959 Building- Bathroom Pipe Chase	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
K	MJP E/F/V on Cardboard Pipe Insulation	10	LF	1959 Building- Bathroom Pipe Chase	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	MJP on Fiberglass Pipes	120	LF	1971 Building- Main Office Closet, Janitor's Closet, Teacher's Closet, Kitchen, Corridor and Former Toilet Rooms	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of	ASSUMED	MISC		UNKNOWN			Yes	ACBM with the potential for damage		



# Chicago Public Schools

School Warren School Unit 25761 Building ID 6350

Address 9239 S Jeffrey Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>6/13/2022</b>
Inspector Name <b>John Fenn</b>
<b>100-09786</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
02A	Damage in Engineer's Office
02B	
02C	
02D	
02E	
02F	
02G	
02H	
02I	
05A	
05B	
05C	
06A	Damage is in Rooms 106, 108, 110 & 111. Room 105 is Storage, and not entirely observable & SD
06B	
07A	Damaged Tile in Engineer's Office
07B	
07C	
07D	
07E	
07F	
07G	
07H	
07I	

# Chicago Public Schools

School Warren School Unit 25761 Building ID 6350

Address 9239 S Jeffrey Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
08A	
08B	
08C	
09A	
09B	
10A	
10B	
11A	
11B	
12	
13	
14	
40	
41	No Damaged Observed 2022
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	

# Chicago Public Schools

School Warren School Unit 25761 Building ID 6350

Address 9239 S Jeffrey Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
71A	
F	
G	
H	
K	
L	
NEW	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Warren School  
**Address** 9239 S Jeffrey

**Unit** 25761  
Chicago, IL, 60617

**Building ID** 6350  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02A	12x12 Light Beige Speckled Floor Tile/Mastic	6,315	SF	1971 Building- Kitchen Office & Storage, Gym, Cafeteria, Janitor's Closets, Teacher's Lunchroom, Office Storage, Vault, Library Work Room & Engineer's Office	Chrysotile	MISC	No	100	SF	6 ACBM with the potential for damage	Repair
02B	12x12 Off-White Floor Tile	120	SF	1971 Building- Kitchen Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02C	12x12 Brown Speckled Floor Tile	1,350	SF	1971 Building- 1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02D	12x12 Off-White Speckled Floor Tile	1,350	SF	1971 Building- 1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02E	12x12 Beige w/Streaks Floor Tile	1,125	SF	1971 Building- Rooms 120, 121, 124	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02F	12x12 Light Brown w/Streaks Floor Tile	1,125	SF	1971 Building- Rooms 120, 121, and 124	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02G	12x12 Brown Floor Tile	375	SF	1971 Building- Room 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02H	12x12 Beige Mottled Floor Tile	375	SF	1971 Building- Room 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02I	12x12 Gray Floor Tile	450	SF	1971 Building- Lunchroom Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05A	12x12 Brown Speckled Floor Tile	1,490	SF	1959 Building- Teachers' Lounge, Corridor, and Room 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05B	12x12 Off-White Speckled Floor Tile	1,490	SF	1959 Building- Teachers' Lounge, Corridor, and Room 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05C	12x12 Tan Speckled Floor Tile	1,300	SF	1959 Building- Room 112	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	9x9 Tan Speckled Floor Tile	5,650	SF	1959 Building- Rooms 105, 106, 107, 108, 109, 110, and 111	Chrysotile	MISC	No	235	SF	6 ACBM with the potential for damage	Repair
06B	9x9 Light Brown Speckled Floor Tile	200	SF	1959 Building- Room 112	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07A	12x12 Beige Speckled Floor Tile Mastic	6,315	SF	1971 Building- Kitchen Office & Storage, Gym, Cafeteria, Janitor's Closets, Engineer's Office, Teacher's Lunchroom, Office Storage, Vault, Library Work Room	Chrysotile	MISC	No	100	SF	6 ACBM with the potential for damage	Repair
07B	12x12 Off-White Floor Tile Mastic	120	SF	1971 Building- Kitchen Hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07C	12x12 Brown Speckled Floor Tile Mastic	1,350	SF	1971 Building- 1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07D	12x12 Off-White Speckled Floor Tile Mastic	1,350	SF	1971 Building- 1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07E	12x12 Beige Streaked Floor Tile Mastic	1,125	SF	1971 Building- Rooms 120, 121, & 124	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07F	12x12 Light Brown Streaked Floor Tile Mastic	1,125	SF	1971 Building- Rooms 120, 121, & 124	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Warren School  
**Address** 9239 S Jeffrey

**Unit** 25761  
Chicago, IL, 60617

**Building ID** 6350  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
07G	12x12 Brown Floor Tile Mastic	375	SF	1971 Building- Room 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07H	12x12 Beige Mottled Floor Tile Mastic	375	SF	1971 Building- Room 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07I	12x12 Gray Floor Tile Mastic	450	SF	1971 Building- Lunchroom Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08A	12x12 Brown Speckled Floor Tile Mastic	1,490	SF	1959 Building- Teachers Lounge, Corridors, Room 113	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08B	12x12 Off White Speckled Floor Tile Mastic	1,490	SF	1959 Building- Teachers' Lounge, Corridor, Room 113	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08C	12x12 Tan Speckled Floor Tile	1,300	SF	1959 Building- Room 112	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09A	9x9 Tan Speckled Floor Tile Mastic	5,650	SF	1959 Building- Rooms 105, 106, 107, 108, 109, 110 & 111	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09B	9x9 Brown Speckled Floor Tile Mastic	200	SF	1959 Building- Room 112	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	Black Mopboard - NO ACBM			1971 Building- Throughout Facility	No ACBM	MISC					
10B	Black Mopboard - NO ACBM			1971 Building- Throughout Facility	No ACBM	MISC					
11A	Black Mopboard Mastic - NO ACBM			1971 Building- Throughout Facility	No ACBM	MISC					
11B	Black Mopboard Mastic - NO ACBM			1971 Building- Throughout Facility	No ACBM	MISC					
12	Red Carpet Mastic-NOT OBSERVED			1971 Building- Rooms 122, 123, 124, 125, 126, 221, 222, 223, 224, 225, 226, 228, and 230	No ACBM	MISC					
13	Wallboard - NO ACBM			Throughout Interior Walls	No ACBM	SURFACE					
14	Interior Window Caulk - NO ACBM			1971 Building- Throughout Facility	No ACBM	MISC					
40	Beige Carpet Mastic	600	SF	1971 Building- Main Office, and Room 226	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12x12 Red Floor Tile	4,000	SF	1971 Building- Rooms 125, 126, 122, 222, 225, 230, and 232	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12x12 Red Floor Tile Mastic	4,000	SF	1971 Building- Rooms 125, 126, 122, 222, 225, 230, and 232	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12x12 Dark Blue Floor Tile	800	SF	1971 Building- Rooms 123, 221, and 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12x12 Dark Blue Floor Tile Mastic	800	SF	1971 Building- Rooms 123, 221 & 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12x12 Light Blue Floor Tile	800	SF	Rooms 123, 221, and 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12x12 Light Blue Floor Tile Mastic	800	SF	Rooms 123, 221, and 223.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12x12 Bright Blue Floor Tile	600	SF	1971 Building- Room 228	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12x12 Bright Blue Floor Tile Mastic	600	SF	1971 Building- Room 228	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Green and Blue Carpet Mastic- NOT OBSERVED			Library	Assumed	MISC					
50	Brown and Black Mosaic Ceramic Tile Grout	1,400	SF	1971 Building- Kitchen, Kitchen Locker	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan



# Chicago Public Schools

**School** Warren School  
**Address** 9239 S Jeffrey

**Unit** 25761  
Chicago, IL, 60617

**Building ID** 6350  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Room and All Vestibules							
51	Brown and Black Mosaic Ceramic Tile Adhesive	1,400	SF	1971 Building- Kitchen, Kitchen Locker Room and All Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	White Ceramic Tile Grout	20	SF	1971 Building- Patches in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	White Ceramic Tile Adhesive	20	SF	1971 Building- Patches in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Black Ceramic Tile Grout	20	SF	1971 Building- Patches in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Multi-Colored Ceramic Tile Adhesive	20	SF	1971 Building- Patches in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Yellow Mosaic Ceramic Tile Grout	10	SF	1971 Building- Patches in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Yellow Mosaic Ceramic Tile Adhesive	10	SF	1971 Building- Patches in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	Gray and Green Carpet Adhesive	2,650	SF	1971 Building- Library, 121, Main Office and Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Beige w/Red Specks Terrazzo Floor	400	SF	1971 Building- Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Brown Carpet Adhesive	675	SF	1971 Building- Room 226	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Blue Mosaic Ceramic Tile Grout	560	SF	1971 Building- Men's and Boy's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Blue Mosaic Ceramic Tile Adhesive	560	SF	1971 Building- Men's and Boy's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Brown Mosaic Ceramic Tile Grout	600	SF	1971 Building- Women's and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	Brown Mosaic Ceramic Tile Adhesive	600	SF	1971 Building- Women's and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	2'x4' White Fissured Ceiling Tile	28,000	SF	1971 Building- Throughout	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
66	2'x4' Smooth Ceiling Tile	1,800	SF	1971 Building- Kitchen, Washrooms and Patched Areas	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
67	Dark Grey Mosaic Ceramic Tile Grout	800	SF	1959 Building- Vestibules, and Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Dark Grey Mosaic Ceramic Tile Adhesive	800	SF	1959 Building- Vestibules, and Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	Drywall Ceilings	250	SF	1959 Building- Boys' & Girls' Toilets and Janitor's Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Soft Plaster Ceiling	50,000	SF	1959 Building- Throughout Corridor & Classrooms	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
71	12x12 Beige Streaked Vinyl Floor Tile	1,840	SF	1959 Building- 107, 109 and Underneath all Univents	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71A	12x12 Beige Streaked Vinyl Floor Tile Mastic	1,840	SF	1959 Building- 107, 109 and	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Warren School  
**Address** 9239 S Jeffrey

**Unit** 25761  
 Chicago, IL, 60617

**Building ID** 6350  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Underneath all Uni-vents							
F	Aircell Pipe Insulation	30	LF	1959 Building- Bathroom Pipe Chase	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Cardboard Pipe Insulation	30	LF	1959 Building- Bathroom Pipe Chase	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	MJP E/F/V on Aircell Pipe Insulation	10	LF	1959 Building- Bathroom Pipe Chase	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	MJP E/F/V on Cardboard Pipe Insulation	10	LF	1959 Building- Bathroom Pipe Chase	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	MJP on Fiberglass Pipes	120	LF	1971 Building- Main Office Closet, Janitor's Closet, Teacher's Closet, Kitchen, Corridor and Former Toilet Rooms	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Warren School  
**Address** 9239 S Jeffrey

**Unit** 25761  
 Chicago, IL, 60617

**Building ID** 6350  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	7/10/2022
Manager Planner Name	Daniel Juneau
100-03613	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
02A	Replace Damaged Tile in Engineer's Office
02B	
02C	
02D	
02E	
02F	
02G	
02H	
02I	
05A	
05B	
05C	
06A	
06B	
07A	Replace Damaged Tiles in Engineer's Office
07B	
07C	
07D	
07E	
07F	
07G	
07H	

# Chicago Public Schools

**School** Warren School  
**Address** 9239 S Jeffrey

**Unit** 25761  
Chicago, IL, 60617

**Building ID** 6350  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
07I	
08A	
08B	
08C	
09A	
09B	
10A	
10B	
11A	
11B	
12	
13	
14	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	

# Chicago Public Schools

**School** Warren School  
**Address** 9239 S Jeffrey

**Unit** 25761  
 Chicago, IL, 60617

**Building ID** 6350  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
71A	
F	
G	
H	
K	
L	
NEW	

# Chicago Public Schools

**School** Warren School

**Unit** 25761

**Building ID** 6350

**Address** 9239 S Jeffrey

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

***Management Planner's Comments Summarized at the End of the Report***

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*



# Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 Light Beige Speckled Floor Tile/Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1971 Building- Kitchen Office & Storage, Gym, Cafeteria, Janitor's Closets, Teacher's Lunchroom, Office Storage, Vault, Library Work Room & Engineer's Office**

MATERIAL QUANTITY: **6315** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Damage in Engineer's Office**

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 Light Beige Speckled Floor Tile/Mastic**  
MATERIAL LOCATION: **1971 Building- Kitchen Office & Storage, Gym, Cafeteria, Janitor's Closets, Teacher's Lunchroom, Office Storage, Vault, Library Work Room & Engineer's Office**  
MATERIAL QUANTITY: **6315** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Replace Damaged Tile in Engineer's Office

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02B**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1971 Building- Kitchen Hallway**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **02B**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**  
MATERIAL LOCATION: **1971 Building- Kitchen Hallway**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02C**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1971 Building- 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **02C**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile**  
MATERIAL LOCATION: **1971 Building- 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02D**  
MATERIAL DESCRIPTION: **12x12 Off-White Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1971 Building- 1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **02D**  
MATERIAL DESCRIPTION: **12x12 Off-White Speckled Floor Tile**  
MATERIAL LOCATION: **1971 Building- 1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02E**  
MATERIAL DESCRIPTION: **12x12 Beige w/Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1971 Building- Rooms 120, 121, 124**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **02E**  
MATERIAL DESCRIPTION: **12x12 Beige w/Streaks Floor Tile**  
MATERIAL LOCATION: **1971 Building- Rooms 120, 121, 124**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02F**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1971 Building- Rooms 120, 121, and 124**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **02F**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Streaks Floor Tile**  
MATERIAL LOCATION: **1971 Building- Rooms 120, 121, and 124**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02G**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1971 Building- Room 220**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **02G**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
MATERIAL LOCATION: **1971 Building- Room 220**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02H**  
MATERIAL DESCRIPTION: **12x12 Beige Mottled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1971 Building- Room 220**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **02H**  
MATERIAL DESCRIPTION: **12x12 Beige Mottled Floor Tile**  
MATERIAL LOCATION: **1971 Building- Room 220**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02I**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1971 Building- Lunchroom Corridor**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **021**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**  
MATERIAL LOCATION: **1971 Building- Lunchroom Corridor**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1959 Building- Teachers' Lounge, Corridor, and Room 113**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **05A**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile**  
MATERIAL LOCATION: **1959 Building- Teachers' Lounge, Corridor, and Room 113**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05B**  
MATERIAL DESCRIPTION: **12x12 Off-White Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1959 Building- Teachers' Lounge, Corridor, and Room 113**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **05B**  
MATERIAL DESCRIPTION: **12x12 Off-White Speckled Floor Tile**  
MATERIAL LOCATION: **1959 Building- Teachers' Lounge, Corridor, and Room 113**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05C**  
MATERIAL DESCRIPTION: **12x12 Tan Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1959 Building- Room 112**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **05C**  
MATERIAL DESCRIPTION: **12x12 Tan Speckled Floor Tile**  
MATERIAL LOCATION: **1959 Building- Room 112**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **9x9 Tan Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage  
Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage  
Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1959 Building- Rooms 105, 106, 107, 108, 109, 110, and 111**  
MATERIAL QUANTITY: **5650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5650** DAMAGE UNITS: **SF**  
COMMENTS: **Damage is in Rooms 106, 108, 110 & 111. Room 105 is Storage, and not entirely observable & SD**

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **9x9 Tan Speckled Floor Tile**  
MATERIAL LOCATION: **1959 Building- Rooms 105, 106, 107, 108, 109, 110, and 111**  
MATERIAL QUANTITY: **5650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **235** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06B**  
MATERIAL DESCRIPTION: **9x9 Light Brown Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1959 Building- Room 112**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **06B**  
MATERIAL DESCRIPTION: **9x9 Light Brown Speckled Floor Tile**  
MATERIAL LOCATION: **1959 Building- Room 112**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**  
MATERIAL DESCRIPTION: **12x12 Beige Speckeled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1971 Building- Kitchen Office & Storage, Gym, Cafeteria, Janitor's Closets, Engineer's Office, Teacher's Lunchroom, Office Storage, Vault, Library Work Room**

MATERIAL QUANTITY: **6315** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Damaged Tile in Engineer's Office**

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **07A**  
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- Kitchen Office & Storage, Gym, Cafeteria, Janitor's Closets, Engineer's Office, Teacher's Lunchroom, Office Storage, Vault, Library Work Room**  
MATERIAL QUANTITY: **6315** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Replace Damaged Tiles in Engineer's Office

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07B**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Kitchen Hallway**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **07B**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- Kitchen Hallway**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07C**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **07C**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07D**  
MATERIAL DESCRIPTION: **12x12 Off-White Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **07D**  
MATERIAL DESCRIPTION: **12x12 Off-White Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07E**  
MATERIAL DESCRIPTION: **12x12 Beige Streaked Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Rooms 120, 121, & 124**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **07E**  
MATERIAL DESCRIPTION: **12x12 Beige Streaked Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- Rooms 120, 121, & 124**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07F**  
MATERIAL DESCRIPTION: **12x12 Light Brown Streaked Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Rooms 120, 121, & 124**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **07F**  
MATERIAL DESCRIPTION: **12x12 Light Brown Streaked Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- Rooms 120, 121, & 124**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07G**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Room 220**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **07G**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- Room 220**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07H**  
MATERIAL DESCRIPTION: **12x12 Beige Mottled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Room 220**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **07H**  
MATERIAL DESCRIPTION: **12x12 Beige Mottled Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- Room 220**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **071**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Lunchroom Corridor**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **071**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- Lunchroom Corridor**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Teachers Lounge, Corridors, Room 113**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **1959 Building- Teachers Lounge, Corridors, Room 113**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08B**  
MATERIAL DESCRIPTION: **12x12 Off White Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Teachers' Lounge, Corridor, Room 113**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **08B**  
MATERIAL DESCRIPTION: **12x12 Off White Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **1959 Building- Teachers' Lounge, Corridor, Room 113**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08C**  
MATERIAL DESCRIPTION: **12x12 Tan Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1959 Building- Room 112**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **08C**  
MATERIAL DESCRIPTION: **12x12 Tan Speckled Floor Tile**  
MATERIAL LOCATION: **1959 Building- Room 112**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **9x9 Tan Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Rooms 105, 106, 107, 108, 109, 110 & 111**  
MATERIAL QUANTITY: **5650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **9x9 Tan Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **1959 Building- Rooms 105, 106, 107, 108, 109, 110 & 111**  
MATERIAL QUANTITY: **5650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09B**  
MATERIAL DESCRIPTION: **9x9 Brown Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Room 112**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **09B**  
MATERIAL DESCRIPTION: **9x9 Brown Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **1959 Building- Room 112**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **Black Mopboard - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **Black Mopboard - NO ACBM**  
MATERIAL LOCATION: **1971 Building- Throughout Facility**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10B**  
MATERIAL DESCRIPTION: **Black Mopboard - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **10B**  
MATERIAL DESCRIPTION: **Black Mopboard - NO ACBM**  
MATERIAL LOCATION: **1971 Building- Throughout Facility**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **Black Mopboard Mastic - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **Black Mopboard Mastic - NO ACBM**  
MATERIAL LOCATION: **1971 Building- Throughout Facility**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11B**  
MATERIAL DESCRIPTION: **Black Mopboard Mastic - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **11B**  
MATERIAL DESCRIPTION: **Black Mopboard Mastic - NO ACBM**  
MATERIAL LOCATION: **1971 Building- Throughout Facility**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Red Carpet Mastic-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- Rooms 122, 123, 124, 125, 126, 221, 222, 223, 224, 225. 226, 228, and 230**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:  Date: **06/13/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Red Carpet Mastic-NOT OBSERVED**  
MATERIAL LOCATION: **1971 Building- Rooms 122, 123, 124, 125, 126, 221, 222, 223, 224, 225, 226, 228, and 230**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/10/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Wallboard - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Interior Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Wallboard - NO ACBM**

MATERIAL LOCATION: **Throughout Interior Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Interior Window Caulk - NO ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Interior Window Caulk - NO ACBM**

MATERIAL LOCATION: **1971 Building- Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Beige Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Main Office, and Room 226**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Beige Carpet Mastic**  
MATERIAL LOCATION: **1971 Building- Main Office, and Room 226**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1971 Building- Rooms 125, 126, 122, 222, 225, 230, and 232**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **4000** DAMAGE UNITS: **SF**  
COMMENTS: **No Damaged Observed 2022**

Inspector's Signature: \_\_\_\_\_



Date: **06/13/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile**  
MATERIAL LOCATION: **1971 Building- Rooms 125, 126, 122, 222, 225, 230, and 232**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Rooms 125, 126, 122, 222, 225, 230, and 232**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- Rooms 125, 126, 122, 222, 225, 230, and 232**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1971 Building- Rooms 123, 221, and 223**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile**  
MATERIAL LOCATION: **1971 Building- Rooms 123, 221, and 223**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1971 Building- Rooms 123, 221 & 223**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- Rooms 123, 221 & 223**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 123, 221, and 223**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile**  
MATERIAL LOCATION: **Rooms 123, 221, and 223**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 123, 221, and 223.**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 123, 221, and 223.**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12x12 Bright Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1971 Building- Room 228**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12x12 Bright Blue Floor Tile**  
MATERIAL LOCATION: **1971 Building- Room 228**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12x12 Bright Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Room 228**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12x12 Bright Blue Floor Tile Mastic**  
MATERIAL LOCATION: **1971 Building- Room 228**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Green and Blue Carpet Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:



Date: **06/13/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Green and Blue Carpet Mastic- NOT OBSERVED**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Brown and Black Mosaic Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Kitchen, Kitchen Locker Room and All Vestibules**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Brown and Black Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **1971 Building- Kitchen, Kitchen Locker Room and All Vestibules**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Brown and Black Mosaic Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Kitchen, Kitchen Locker Room and All Vestibules**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Brown and Black Mosaic Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1971 Building- Kitchen, Kitchen Locker Room and All Vestibules**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **White Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **White Ceramic Tile Grout**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Black Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Black Ceramic Tile Grout**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Multi-Colored Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Multi-Colored Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Yellow Mosaic Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Yellow Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Yellow Mosaic Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Yellow Mosaic Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1971 Building- Patches in Kitchen**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Gray and Green Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Library, 121, Main Office and Principal's Office**  
MATERIAL QUANTITY: **2650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Gray and Green Carpet Adhesive**  
MATERIAL LOCATION: **1971 Building- Library, 121, Main Office and Principal's Office**  
MATERIAL QUANTITY: **2650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Beige w/Red Specks Terrazzo Floor**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Stairways**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Beige w/Red Specks Terrazzo Floor**  
MATERIAL LOCATION: **1971 Building- Stairways**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Room 226**  
MATERIAL QUANTITY: **675** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**  
MATERIAL LOCATION: **1971 Building- Room 226**  
MATERIAL QUANTITY: **675** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Blue Mosaic Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Men's and Boy's Washrooms**  
MATERIAL QUANTITY: **560** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Blue Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **1971 Building- Men's and Boy's Washrooms**  
MATERIAL QUANTITY: **560** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Blue Mosaic Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1971 Building- Men's and Boy's Washrooms**

MATERIAL QUANTITY: **560** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Blue Mosaic Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1971 Building- Men's and Boy's Washrooms**  
MATERIAL QUANTITY: **560** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Women's and Girls' Washrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **1971 Building- Women's and Girls' Washrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Women's and Girls' Washrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1971 Building- Women's and Girls' Washrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **2'x4' White Fissured Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Throughout**  
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **2'x4' White Fissured Ceiling Tile**  
MATERIAL LOCATION: **1971 Building- Throughout**  
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **2'x4' Smooth Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1971 Building- Kitchen, Washrooms and Patched Areas**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **2'x4' Smooth Ceiling Tile**  
MATERIAL LOCATION: **1971 Building- Kitchen, Washrooms and Patched Areas**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Dark Grey Mosaic Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Vestibules, and Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Dark Grey Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **1959 Building- Vestibules, and Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **Dark Grey Mosaic Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Vestibules, and Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **Dark Grey Mosaic Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1959 Building- Vestibules, and Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **Drywall Ceilings**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Boys' & Girls' Toilets and Janitor's Closet**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **06/13/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **Drywall Ceilings**  
MATERIAL LOCATION: **1959 Building- Boys' & Girls' Toilets and Janitor's Closet**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **Soft Plaster Ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Throughout Corridor & Classrooms**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **Soft Plaster Ceiling**  
MATERIAL LOCATION: **1959 Building- Throughout Corridor & Classrooms**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12x12 Beige Streaked Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- 107, 109 and Underneath all Univents**  
MATERIAL QUANTITY: **1840** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12x12 Beige Streaked Vinyl Floor Tile**  
MATERIAL LOCATION: **1959 Building- 107, 109 and Underneath all Univents**  
MATERIAL QUANTITY: **1840** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71A**  
MATERIAL DESCRIPTION: **12x12 Beige Streaked Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- 107, 109 and Underneath all Uni-vents**  
MATERIAL QUANTITY: **1840** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **71A**  
MATERIAL DESCRIPTION: **12x12 Beige Streaked Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **1959 Building- 107, 109 and Underneath all Uni-vents**  
MATERIAL QUANTITY: **1840** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Bathroom Pipe Chase**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1959 Building- Bathroom Pipe Chase**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Bathroom Pipe Chase**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **1959 Building- Bathroom Pipe Chase**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Bathroom Pipe Chase**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **1959 Building- Bathroom Pipe Chase**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Bathroom Pipe Chase**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **1959 Building- Bathroom Pipe Chase**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUIDLING ID: **6350**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Fenn**  
SCHOOL NAME: **Warren School** INSPECTION DATE: **6/13/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1971 Building- Main Office Closet, Janitor's Closet, Teacher's Closet, Kitchen, Corridor and Former Toliet Rooms**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/13/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25761** BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School** REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey** IDPH LICENSE NO: **100-09786**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipes**  
MATERIAL LOCATION: **1971 Building- Main Office Closet, Janitor's Closet, Teacher's Closet, Kitchen, Corridor and Former Toilet Rooms**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/10/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **25761**      BUILDING ID: **6350**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Warren School**      REVIEW DATE: **7/10/2022**  
ADDRESS: **9239 S Jeffrey**      IDPH LICENSE NO: **100-09786**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 07/10/2022

# APPENDIX B

## Inspector and Management Planner Licenses

---



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JOHN H FENN**  
2829 N TROY ST  
CHICAGO, IL 60618

4/7/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09786

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 09786	<b>ISSUED</b> 4/7/2022	INSPECTOR	3/9/2023
<b>JOHN H FENN</b> 2829 N TROY ST CHICAGO, IL 60618 Environmental Health	<b>EXPIRES</b> 05/15/2023 	MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/9/2023 4/2/2023
		<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
Nationally Accredited by PHAB

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOHN FENN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/09/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/09/2022

Course Dates:

03/09/2023

Expires:

2203BIR04

Certificate Number:



Environmental &  
Occupational Services

37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

A handwritten signature in blue ink that reads "N. Peneff" with a stylized flourish at the end.

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOHN FENN  
has completed the Asbestos Management Planner Refresher course and passed the examination  
on 03/09/2022 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C. Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

03/09/2022

Course Dates:

03/09/2023

Expires:

2203MPR02

Certificate Number:


A handwritten signature in blue ink that reads "N Peneff".

Director of Training  
**Nicholas J. Peneff**  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-011






**ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 03613	3/1/2022	05/15/2023

DANIEL J JUNEAU  
 1408 OAKWOOD AVENUE  
 DES PLAINES, IL 60016



Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/19/2022
MANAGEMENT PLANNER	11/19/2022
PROJECT MANAGER	11/1/2022
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
 This license issued under authority of the State of Illinois  
 Department of Public Health  
 This license is valid only when accompanied by a valid  
 training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: BIR2111192805

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192816

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/12/2022

Exam Date: 12/12/2022

Expiration Date: 12/12/2023

Certificate Number: MPR2212123967

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113645

Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed