

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2882
SCHOOL NAME: Marshall Middle School
ADDRESS OF SCHOOL: 3900 N Lawndale Avenue
CITY: Chicago, IL, 60618

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/28/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/10/2022 ENROLLMENT 1165
IDPH INSPECTOR LICENSE NUMBER: 100-20616
IDPH LICENSED INSPECTOR NAME (Please Print): Antonio Munoz IV
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



11/1/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Marshall Middle School

3900 N Lawndale Avenue
Chicago, IL, 60618

Unit: 26921
Building ID: 7520

IDPH ID Number: 14-016-2990-2882

REPORT DATE:

Tuesday, November 01, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Specialty Consulting, Inc.

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

11/01/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 41081 Region: 01 IDPH ID: 14-016-2990-2882

School: Marshall Middle School Building ID: 7520

Address: 3900 N Lawndale Avenue
Chicago, IL, 60618

Building Contact: Lopez, April Contact Phone: 3126131249

Current Building Owners: Chicago Public Schools

Reinspection Date: 10/10/2022

Review Date: 11/01/2022

Inspector: Antonio Munoz IV Inspector IDPH License: 100-20616
Management Planner: Jigar Shah Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 01, 2022

RE: Marshall Middle School, Unit 26921
3900 N Lawndale Avenue
Chicago, IL, 60618

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Marshall Middle School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Marshall Middle School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Marshall Middle School Unit: 41081 Region: 01
Address: 3900 N Lawndale Avenue Chicago, IL, 60618
IDPH ID: 14-016-2990-2882 Building ID: 7520
Contact: Lopez, April Phone: 3126131249

2. Description of Facility

Original Construction: 1956 Additional Construction: 1924,1952
Total Square Footage: 31184 No of Floors: 4
Current Occupancy: 1165

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: Antonio Munoz IV


Inspector IDPH license # 100-20616
Reinspection Date: 10/10/2022

Signature: 
Date: 10/10/2022

6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342

Signature: 
Date: 11/01/2022

7. Review Date: 11/01/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 11/1/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Marshall Middle School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7520:

B. The following new homogenous areas have been identified for Building 7520:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	1' x 1' Tan Ceiling Tile
100A	1' x 1' Ceiling Tile Mastic Pucks
101	Decorative Plaster
102	1' x 1' Ceiling Tile
102A	1' x 1' Ceiling Tile Mastic Pucks
103	2' x 4' Ceiling Tile
104	2' x 4' Ceiling Tile
105	Fume Hood Panels (Abated)
108	12x12 Lt. Yellow VFT
108A	12x12 Lt. Yellow VFT Mastic
109	12x12 Blue VFT
109A	12x12 Blue VFT Mastic
110	12x12 White w/ gray specks VFT
110A	12x12 White w/ gray specks VFT Mastic
111	Drywall system
112	12x12 Lt. Gray speckled VFT
112A	12x12 Lt. Gray speckled VFT Mastic
113	12x12 Dark gray w/white & gray speckles VFT
113A	12x12 Dark gray w/white & gray speckles VFT Mastic
114	2' x 2' Ceiling Tile
115	Carpet Mastic
116	12x12 Black w/white specks VFT
116A	12x12 Black w/white specks VFT Mastic
117	12x12 Lt. Yellow VFT
117A	12x12 Lt. Yellow VFT Mastic
118	12x12 Blue VFT
118A	12x12 Blue VFT Mastic
119	12x12 White w/gray specks VFT
119A	12x12 White w/gray specks VFT Mastic
120	12x12 Black w/white specks VFT
121	12x12 Black w/white specks VFT Mastic
122	Off white linoleum flooring
122A	Off white Linoleum flooring adhesive
123	Gray Linoleum flooring
123A	Gray Linoleum flooring adhesive
14	9"x 9" Green w/ White Streaks VFT Mastic
43	9"x 9" White w/ Green & Red Waves VFT
44	9"x 9" White w/ Green & Red Waves VFT Mastic
45	9"x 9" Green w/ White & Green Waves VFT
46	9"x 9" Green w/ White & Green Waves VFT Mastic
47	9"x 9" Red w/ White Waves VFT

48	9"x 9" Red w/ White Waves VFT Mastic
51	9"x 9" White w/ Brown Specks VFT
52	9"x 9" White w/ Brown Specks VFT Mastic
56	12"x 12" Tan w/ Tan, Brn, & White Strks VFT Mastic
67	12"x 12" Brown w/ Brown & White Streaks VFT
70	9"x 9" Brown w/ Drk Brown & Tan Streaks VFT Mastic
72	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT Mastic
81	12"x 12' Green w/ White Streaks VFT
82	12"x 12' Green w/ White Streaks VFT Mastic
83	Brown w/ Colored Waves Linoleum
84	Brown w/ Colored Waves Linoleum Mastic
85	12" x 12" White w/ Light Tan Streaks VFT
86	12" x 12" White w/ Light Tan Streaks VFT Mastic
87	12"x12" Lt. Tan w/ Tan specks VFT
87A	12"x12" Lt. Tan w/ Tan specks VFT Mastic
88	12"x12" Off White w/ Tan specks VFT
88A	12"x12" Off White w/ Tan specks VFT Mastic
89	12"x12" White w/ Blue Specks VFT
89A	12"x12" Off White w/ Tan specks VFT Mastic
90	12"x12" Lt. Tan w/ Tan specks VFT
90A	12"x12" Lt. Tan w/ Tan specks VFT Mastic
95	Terrazzo
96	Terrazzo
97	Cardboard Pipe Insulation
98	Stage's Fire Curtain
99	9" x 9" Tan Ceiling Tile
99A	9" x 9" Tan Ceiling Tile Mastic Pucks

The following areas were deemed to be inaccessible:

100	1' x 1' Tan Ceiling Tile
100A	1' x 1' Ceiling Tile Mastic Pucks
101	Decorative Plaster
114	2' x 2' Ceiling Tile
115	Carpet Mastic
75	9"x 9" Dark Brown w/ Black & Tan Waves VFT
76	9"x 9" Dark Brown w/ Black & Tan Waves VFT Mastic
77	9"x 9" Beige w/ Brown & Dark Brown Waves VFT
78	9"x 9" Beige w/ Brown & Drk Brown Waves VFT Mastic
81	12"x 12' Green w/ White Streaks VFT
82	12"x 12' Green w/ White Streaks VFT Mastic

99A

9" x 9" Tan Ceiling Tile Mastic Pucks

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Antonio Munoz IV, IDPH License # 100-20616. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 6/26/2020

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Marshall Middle School Building 7520 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Addition										
107	Yellow Linoleum Flooring - Abated			4th Floor Library Office Storage Room - 1923 Bldg.	ABATED	MISC								
108	12x12 Lt. Yellow VFT	1,200	SF	Rooms (204 and 206 under carpet tiles) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
108A	12x12 Lt. Yellow VFT Mastic	1,200	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	12x12 Blue VFT	1,100	SF	Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
109A	12x12 Blue VFT Mastic	1,100	SF	Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	9"x 9" Gray w/ Yellow & Green Streaks VFT	1,170	SF	4th Floor Corridor, 1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
110	12x12 White w/ gray specks VFT	4,900	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110A	12x12 White w/ gray specks VFT Mastic	4,900	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
111	Drywall system	6,500	SF	Rooms 402, 404, 406, 408, 410 -1923 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
112	12x12 Lt. Gray speckled VFT	150	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
112A	12x12 Lt. Gray speckled VFT Mastic	150	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
113	12x12 Dark gray w/white & gray speckles VFT	100	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
113A	12x12 Dark gray w/white & gray speckles VFT Mastic	100	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	2' x 2' Ceiling Tile	1,000	SF	Rooms 404, 406 -1923Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
115	Carpet Mastic	3,500	SF	4th fl library, 302, 304, 306 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	12x12 Black w/white specks VFT	450	SF	Auditorium -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116A	12x12 Black w/white specks VFT Mastic	450	SF	Auditorium -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	12x12 Lt. Yellow VFT	1,000	SF	Rooms.216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
117A	12x12 Lt. Yellow VFT Mastic	1,000	SF	Rooms.216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	12x12 Blue VFT	700	SF	Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
118A	12x12 Blue VFT Mastic	700	SF	Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119	12x12 White w/gray specks VFT	3,200	SF	Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119A	12x12 White w/gray specks VFT Mastic	3,200	SF	Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				133 & 134 -1953 Bldg										
12	9"x 9" Gray w/ Yellow & Green Streaks VFT Mastic	1,170	SF	4th Floor Corridor, 1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
120	12x12 Black w/white specks VFT	500	SF	Assembly hall -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
121	12x12 Black w/white specks VFT Mastic	500	SF	Assembly hall -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
122	Off white linoleum flooring	2,200	SF	Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
122A	Off white Linoleum flooring adhesive	2,200	SF	Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
123	Gray Linoleum flooring	80	SF	Room 218 - 1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
123A	Gray Linoleum flooring adhesive	80	SF	Room 218 - 1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	9"x 9" Green w/ White Streaks VFT	7,100	SF	Rm 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14	9"x 9" Green w/ White Streaks VFT Mastic	7,100	SF	Rm 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	9"x 9" Black w/ White Streaks VFT	2,800	SF	Assembly Hall, Rooms 419, 423, 427, 431 -1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	9"x 9" Black w/ White Streaks VFT Mastic	2,800	SF	Assembly Hall, Rooms 419, 423, 427, 431 -1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	9"x 9" Khaki w/ White Streaks VFT	100	SF	Room 422(storage) --1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	9"x 9" Khaki w/ White Streaks VFT Mastic	100	SF	Room 422(storage) --1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	9"x 9" Aqua VFT	800	SF	Rooms 414/416 --1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	9"x 9" Aqua VFT Mastic	800	SF	Rooms 414/416 --1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12"x 12" White w/ Gray Specks VFT			Room 420, 1953	ABATED	MISC								
22	12"x 12" White w/ Gray Specks VFT Mastic			Room 420, 1953	ABATED	MISC								
23	9"x 9" Gray VFT	1,000	SF	Rooms 124, 116,	CHR	MISC	N	NONE	0		No	ACBM with the		MODERATE

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Carpet), 1923										
42	9"x 9" Beige VFT Mastic - Abated			Room 400 (Under Carpet), 1923	ABATED	MISC								
43	9"x 9" White w/ Green & Red Waves VFT	120	SF	Room 433 office --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	9"x 9" White w/ Green & Red Waves VFT Mastic	120	SF	Room 433 office --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	9"x 9" Green w/ White & Green Waves VFT	120	SF	Room 433 office, 414, 416 --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	9"x 9" Green w/ White & Green Waves VFT Mastic	120	SF	Room 433 office --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	9"x 9" Red w/ White Waves VFT	70	SF	Room 433 office --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	9"x 9" Red w/ White Waves VFT Mastic	70	SF	Room 433 office --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	9"x 9" Brown w/ White & Brown Streaks VFT - Abated			Room 411, 1923	ABATED	MISC								
50	9"x 9" Brown w/ White & Brown Streaks VFT Mastic - Abated			Room 411, 1923	ABATED	MISC								
51	9"x 9" White w/ Brown Specks VFT	2,900	SF	Rooms 304 (under HA# 88 & 88A), 306 (under carpet), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	9"x 9" White w/ Brown Specks VFT Mastic	2,900	SF	Rooms 304 (under HA# 88 & 88A), 306 (under carpet) --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12"x 12" White w/ Black & Gray Streaks VFT - REMOVED			Room 210 (Hardwood Floor), 1923	ABATED									
54	12"x 12" White w/ Black & Gray Streaks VFT Mastic - REMOVED			Room 210 (Hardwood Floor), 1923	ABATED									
55	12"x 12" Tan w/ Tan, Brown, & White Streaks VFT	850	SF	Room 303 (under HA# 87 & 87A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	12"x 12" Tan w/ Tan, Brn, & White Strks VFT Mastic	850	SF	Room 303 (under HA# 87 & 87A), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	9"x 9" Gray VFT	850	SF	Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	9"x 9" Gray VFT Mastic	850	SF	Room 302 (Under	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				HA# 88 & 88A), 202 (HA# 88 & 88A), 1923								potential for damage		
59	12"x 12" White w/ Brown Specks VFT - ABATED			Room 203, 205, 207, 1923	ABATED									
60	12"x 12" White w/ Brown Specks VFT Mastic (ABATED)			Room 203, 205, 207, 1923	ABATED									
61	9"x 9" Brown w/ Orange & Brown Streaks VFT	5,000	SF	Auditorium, 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	9"x 9" Brown w/ Orange & Brown Streaks VFT Mastic	5,000	SF	Auditorium, 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	9"x 9" White w/ Green & Brown Streaks VFT	1,000	SF	Auditorium, 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	9"x 9" White w/ Green & Brown Streaks VFT Mastic	1,000	SF	Auditorium, 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	9"x 9" Black w/ White Streaks VFT	1,000	SF	Auditorium --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	9"x 9" Black w/ White Streaks VFT Mastic	1,000	SF	Auditorium --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12"x 12" Brown w/ Brown & White Streaks VFT	600	SF	Room 109 (kitchen) --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	12"x 12" Brown w/ Brown & White Streaks VFT Mastic	600	SF	Room 109 (kitchen) --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	9"x 9" Brown w/ Dark Brown & Tan Streaks VFT	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	9"x 9" Brown w/ Drk Brown & Tan Streaks VFT Mastic	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT Mastic	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	9"x 9" Light Tan w/ Tan Streaks VFT	200	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	9"x 9" Light Tan w/ Tan Streaks VFT Mastic	200	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	9"x 9" Dark Brown w/ Black & Tan Waves VFT	450	SF	Room 102 (under HA#79 & 80) --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
76	9"x 9" Dark Brown w/ Black & Tan Waves VFT Mastic	450	SF	Room 102 (under HA#79 & 80) --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	9"x 9" Beige w/ Brown & Dark Brown Waves VFT	450	SF	Room 102 (under HA#79 & 80) --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	9"x 9" Beige w/ Brown & Drk Brown Waves VFT Mastic	450	SF	Room 102 (under HA#79 & 80) --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12"x 12" Beige w/ Brown Specks VFT	1,500	SF	Room 102, 104 --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
80	12"x 12" Beige w/ Brown Specks VFT Mastic	1,500	SF	Room 102, 104 --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	12"x 12" Green w/ White Streaks VFT	600	SF	Room 104 (under existing VFT) --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	12"x 12" Green w/ White Streaks VFT Mastic	600	SF	Room 104 (under existing VFT) --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	Brown w/ Colored Waves Linoleum	300	SF	Dressing Room (Stage), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
84	Brown w/ Colored Waves Linoleum Mastic	300	SF	Dressing Room (Stage), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	12" x 12" White w/ Light Tan Streaks VFT	600	SF	Room 104, 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	12" x 12" White w/ Light Tan Streaks VFT Mastic	600	SF	Room 104, 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	12"x12" Lt. Tan w/ Tan specks VFT	6,500	SF	Rms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
87A	12"x12" Lt. Tan w/ Tan specks VFT Mastic	6,500	SF	Rms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	12"x12" Off White w/ Tan specks VFT	3,200	SF	Rms 307, 101, 302 (304 under carpet) --1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
88A	12"x12" Off White w/ Tan specks VFT Mastic	3,200	SF	Rms 307, 101, 302 (304 under carpet) --1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	12"x12" White w/ Blue Specks VFT	3,900	SF	(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
89A	12"x12" Off White w/ Tan specks VFT Mastic	3,900	SF	--1953 Bldg (Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	12"x12" Lt. Tan w/ Tan specks VFT	3,200	SF	Rms 223, 221, 219, Bsmt Kitchen (1953 bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
90A	12"x12" Lt. Tan w/ Tan specks VFT Mastic	3,200	SF	Rms 223, 221, 219, Bsmt Kitchen (1953 bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	12"x12" Brown VFT - Abated			4th Floor Book Storage by Library (1923 bldg)	ABATED	MISC								
91A	12"x12" Brown VFT Mastic - Abated			4th Floor Book Storage by Library (1923 bldg)	ABATED	MISC								
92	12"x12" Beige VFT - Abated			4th Floor Book Storage by Library (1923 bldg)	ABATED	MISC								
92A	12"x12" Beige VFT Mastic - Abated			4th Floor Book Storage by Library (1923 bldg)	ABATED	MISC								
93	9"x9" Gray w/ Pink & White Streaks VFT - Abated			Rm 428 (1923 bldg)	ABATED	MISC								
93A	9"x9" Gray w/ Pink & White Streaks VFT Mastic - Abated			Rm 428 (1923 bldg)	ABATED	MISC								
94	9"x9" Maroon w/ White Streaks VFT - Abated			Rm 428 (1923 bldg)	ABATED	MISC								
94A	9"x9" Maroon w/ White Streaks VFT Mastic - Abated			Rm 428 (1923 bldg)	ABATED	MISC								
95	Terrazzo	10,000	SF	Corridors, Stairwells (bsmt - 4th fl.), Toilets (all floors), Rm 311, Janitor's Closets, Auditorium Main Entrance (1923 bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
96	Terrazzo	5,000	SF	Corridors (bsmt - 3rd fl.), Stairwells (bsmt - 4th fl) (1953 bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
97	Cardboard Pipe Insulation	80	LF	Auditorium Balcony (behind plaster wall) - 1923 Bldg	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
98	Stage's Fire Curtain	1,000	SF	Auditorium Stage - 1923 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
99	9" x 9" Tan Ceiling Tile	1,500	SF	Auditorium Balcony - 1923 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
99A	9" x 9" Tan Ceiling Tile Mastic Pucks	1,500	SF	Auditorium Balcony - 1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 10/10/2022
Inspector Name Antonio Munoz IV
100-20616 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
100	
100A	
101	
102	
102A	
103	
104	
105	
106	
107	
108	
108A	
109	
109A	

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
11	
110	
110A	
111	
112	
112A	
113	
113A	
114	
115	
116	
116A	
117	
117A	
118	
118A	
119	
119A	
12	
120	
121	
122	
122A	
123	
123A	
13	
14	
15	
16	

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	

Chicago Public Schools

School Marshall Middle School Unit 41081 Building ID 7520

Address 3900 N Lawndale Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
87A	
88	
88A	
89	
89A	
90	
90A	
91	
91A	
92	
92A	
93	
93A	
94	
94A	
95	

Chicago Public Schools

School Marshall Middle School **Unit** 41081 **Building ID** 7520

Address 3900 N Lawndale Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
96	
97	
98	
99	
99A	

Table II

Management Planner's Review

Chicago Public Schools

School Marshall Middle School

Unit 41081

Building ID 7520

Address 3900 N Lawndale Avenue

Chicago, IL, 60618

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12"x 12" Beige w/ Blue & Orange Streaks VFT (Removed)			Lunchroom, Room 002, 1953	Abated						
02	12"x 12" Beige w/ Blue & Orange Streaks VFT Mastic (Removed)			Lunchroom, Room 002, 1953	Abated						
03	9"x 9" Brown w/ Orange & White Streaks VFT	4,500	SF	Room 217, 315, 319, 323, Basement Vestibule, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	9"x 9" Brown w/ Orange & White Streaks VFT Mastic	4,500	SF	Room 217, 315, 319, 323, Basement Vestibule, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	9"x 9" Tan w/ White & Brown Streaks VFT	200	SF	Basement Vestibule, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9"x 9" Tan w/ White & Brown Streaks VFT Mastic	200	SF	Basement Vestibule, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9"x 9" Gray w/ Black & White Streaks VFT	600	SF	Room 422 (storage), art room office (414) -1953 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	9"x 9" Gray w/ Black & White Streaks VFT Mastic	600	SF	Room 422 (storage), art room office (414) -1953 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x 12" Blue VFT (Abated)			Room 002, 1953	Abated						
10	12"x 12" Blue VFT Mastic (Abated)			Room 002, 1953	Abated						
100	1' x 1' Tan Ceiling Tile	4,500	SF	Auditorium - 1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100A	1' x 1' Ceiling Tile Mastic Pucks	4,500	SF	Auditorium - 1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	Decorative Plaster	1,800	SF	Auditorium and Balcony - 1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	1' x 1' Ceiling Tile	9,500	SF	1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102A	1' x 1' Ceiling Tile Mastic Pucks	9,500	SF	1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	2' x 4' Ceiling Tile	1,600	SF	Room 311, 213 -1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	2' x 4' Ceiling Tile	15,000	SF	Throughout -1953 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	Fume Hood Panels (Abated)			Rooms 216- 1953 Addition	Assumed	MISC		0		6 ACBM with the potential for damage	
106	Lab Counter Tops - Abated			Rooms 318, 318A, 316A, 316B - 1953 Addition	Abated	MISC					
107	Yellow Linoleum Flooring - Abated			4th Floor Library Office Storage Room - 1923 Bldg.	Abated	MISC					
108	12x12 Lt. Yellow VFT	1,200	SF	Rooms (204 and 206 under carpet tiles) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108A	12x12 Lt. Yellow VFT Mastic	1,200	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Marshall Middle School
Address 3900 N Lawndale Avenue

Unit 41081
 Chicago, IL, 60618

Building ID 7520
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
109	12x12 Blue VFT	1,100	SF	Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109A	12x12 Blue VFT Mastic	1,100	SF	Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	9"x 9" Gray w/ Yellow & Green Streaks VFT	1,170	SF	4th Floor Corridor, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	12x12 White w/ gray specks VFT	4,900	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110A	12x12 White w/ gray specks VFT Mastic	4,900	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	Drywall system	6,500	SF	Rooms 402, 404, 406, 408, 410 -1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12x12 Lt. Gray speckled VFT	150	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112A	12x12 Lt. Gray speckled VFT Mastic	150	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12x12 Dark gray w/white & gray speckles VFT	100	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113A	12x12 Dark gray w/white & gray speckles VFT Mastic	100	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	2' x 2' Ceiling Tile	1,000	SF	Rooms 404, 406 -1923Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	Carpet Mastic	3,500	SF	4th fl library, 302, 304, 306 -1923Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	12x12 Black w/white specks VFT	450	SF	Auditorium -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116A	12x12 Black w/white specks VFT Mastic	450	SF	Auditorium -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12x12 Lt. Yellow VFT	1,000	SF	Rooms.216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117A	12x12 Lt. Yellow VFT Mastic	1,000	SF	Rooms.216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12x12 Blue VFT	700	SF	Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118A	12x12 Blue VFT Mastic	700	SF	Work room 132, main office hall,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Marshall Middle School
Address 3900 N Lawndale Avenue

Unit 41081
 Chicago, IL, 60618

Building ID 7520
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
119	12x12 White w/gray specks VFT	3,200	SF	Rooms 216, 316, 420 -1953 Bldg Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119A	12x12 White w/gray specks VFT Mastic	3,200	SF	Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9"x 9" Gray w/ Yellow & Green Streaks VFT Mastic	1,170	SF	4th Floor Corridor, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	12x12 Black w/white specks VFT	500	SF	Assembly hall -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12x12 Black w/white specks VFT Mastic	500	SF	Assembly hall -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	Off white linoleum flooring	2,200	SF	Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122A	Off white Linoleum flooring adhesive	2,200	SF	Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	Gray Linoleum flooring	80	SF	Room 218 - 1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123A	Gray Linoleum flooring adhesive	80	SF	Room 218 - 1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	9"x 9" Green w/ White Streaks VFT	7,100	SF	Rm 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	9"x 9" Green w/ White Streaks VFT Mastic	7,100	SF	Rm 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	9"x 9" Black w/ White Streaks VFT	2,800	SF	Assembly Hall, Rooms 419, 423, 427, 431 -1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9"x 9" Black w/ White Streaks VFT Mastic	2,800	SF	Assembly Hall, Rooms 419, 423, 427, 431 -1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	9"x 9" Khaki w/ White Streaks VFT	100	SF	Room 422(storage) --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	9"x 9" Khaki w/ White Streaks VFT Mastic	100	SF	Room 422(storage) --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	9"x 9" Aqua VFT	800	SF	Rooms 414/416 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	9"x 9" Aqua VFT Mastic	800	SF	Rooms 414/416 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12"x 12" White w/ Gray Specks VFT			Room 420, 1953	Abated	MISC					
22	12"x 12" White w/ Gray Specks VFT Mastic			Room 420, 1953	Abated	MISC					
23	9"x 9" Gray VFT	1,000	SF	Rooms 124, 116, 418 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	9"x 9" Gray VFT Mastic	1,000	SF	Rooms 124, 116, 418 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	9"x 9" Orange VFT	180	SF	Rooms 124, 116, 418 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	9"x 9" Orange VFT Mastic	180	SF	Rooms 124, 116, 418 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	9"x 9" White w/ Black Streaks VFT	200	SF	4th Floor Toilet by Rm 415 and storage across from 419 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Marshall Middle School
Address 3900 N Lawndale Avenue

Unit 41081
 Chicago, IL, 60618

Building ID 7520
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
28	9"x 9" White w/ Black Streaks VFT Mastic	200	SF	4th Floor Toilet by Rm 415 and storage across from 419 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	9"x 9" Pink w/ Brown & White Streaks VFT	600	SF	Rooms 415 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	9"x 9" Pink w/ Brown & White Streaks VFT Mastic	600	SF	Rooms 415 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x 12" Beige w/ Thin Black Streaks VFT (ABATED)			Room 316, 1953	Abated	MISC					
32	12"x 12" Beige w/ Thin Black Streaks VFT Mastic (ABATED)			Room 316, 1953	Abated	MISC					
33	9"x 9" Aqua w/ White Streaks VFT	80	SF	Janitor's closet (131) and adjacent toilet --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	9"x 9" Aqua w/ White Streaks VFT Mastic	80	SF	Janitor's closet (131) and adjacent toilet --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	9"x 9" Black w/ Pink & White Streaks VFT	50	SF	1st Floor North Toilet by office 134 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	9"x 9" Black w/ Pink & White Streaks VFT Mastic	50	SF	1st Floor North Toilet by office 134 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	9"x 9" Tan VFT	1,700	SF	Assembly Hall, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	9"x 9" Tan VFT Mastic	1,700	SF	Assembly Hall, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	9"x 9" Brown VFT - Abated			Room 400 (Under Carpet), 1923	Abated	MISC					
40	9"x 9" Brown VFT Mastic - Abated			Room 400 (Under Carpet), 1923	Abated	MISC					
41	9"x 9" Beige VFT - Abated			Room 400 (Under Carpet), 1923	Abated	MISC					
42	9"x 9" Beige VFT Mastic - Abated			Room 400 (Under Carpet), 1923	Abated	MISC					
43	9"x 9" White w/ Green & Red Waves VFT	120	SF	Room 433 office --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	9"x 9" White w/ Green & Red Waves VFT Mastic	120	SF	Room 433 office --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	9"x 9" Green w/ White & Green Waves VFT	120	SF	Room 433 office, 414, 416 --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	9"x 9" Green w/ White & Green Waves VFT Mastic	120	SF	Room 433 office --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	9"x 9" Red w/ White Waves VFT	70	SF	Room 433 office --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	9"x 9" Red w/ White Waves VFT Mastic	70	SF	Room 433 office --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	9"x 9" Brown w/ White & Brown Streaks VFT - Abated			Room 411, 1923	Abated	MISC					
50	9"x 9" Brown w/ White & Brown Streaks VFT Mastic - Abated			Room 411, 1923	Abated	MISC					
51	9"x 9" White w/ Brown Specks VFT	2,900	SF	Rooms 304 (under HA# 88 & 88A), 306 (under carpet), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	9"x 9" White w/ Brown Specks VFT Mastic	2,900	SF	Rooms 304 (under HA# 88 & 88A), 306 (under carpet) --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Marshall Middle School

Unit 41081

Building ID 7520

Address 3900 N Lawndale Avenue

Chicago, IL, 60618

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
53	12"x 12" White w/ Black & Gray Streaks VFT - REMOVED			Room 210 (Hardwood Floor), 1923	Abated						
54	12"x 12" White w/ Black & Gray Streaks VFT Mastic - REMOVED			Room 210 (Hardwood Floor), 1923	Abated						
55	12"x 12" Tan w/ Tan, Brown, & White Streaks VFT	850	SF	Room 303 (under HA# 87 & 87A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12"x 12" Tan w/ Tan, Brn, & White Strks VFT Mastic	850	SF	Room 303 (under HA# 87 & 87A), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	9"x 9" Gray VFT	850	SF	Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	9"x 9" Gray VFT Mastic	850	SF	Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12"x 12" White w/ Brown Specks VFT - ABATED			Room 203, 205, 207, 1923	Abated						
60	12"x 12" White w/ Brown Specks VFT Mastic (ABATED)			Room 203, 205, 207, 1923	Abated						
61	9"x 9" Brown w/ Orange & Brown Streaks VFT	5,000	SF	Auditorium, 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	9"x 9" Brown w/ Orange & Brown Streaks VFT Mastic	5,000	SF	Auditorium, 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	9"x 9" White w/ Green & Brown Streaks VFT	1,000	SF	Auditorium, 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	9"x 9" White w/ Green & Brown Streaks VFT Mastic	1,000	SF	Auditorium, 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	9"x 9" Black w/ White Streaks VFT	1,000	SF	Auditorium --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	9"x 9" Black w/ White Streaks VFT Mastic	1,000	SF	Auditorium --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12"x 12" Brown w/ Brown & White Streaks VFT	600	SF	Room 109 (kitchen) --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12"x 12" Brown w/ Brown & White Streaks VFT Mastic	600	SF	Room 109 (kitchen) --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	9"x 9" Brown w/ Dark Brown & Tan Streaks VFT	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	9"x 9" Brown w/ Drk Brown & Tan Streaks VFT Mastic	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT Mastic	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	9"x 9" Light Tan w/ Tan Streaks VFT	200	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	9"x 9" Light Tan w/ Tan Streaks VFT Mastic	200	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Marshall Middle School
Address 3900 N Lawndale Avenue

Unit 41081
 Chicago, IL, 60618

Building ID 7520
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
75	9"x 9" Dark Brown w/ Black & Tan Waves VFT	450	SF	Room 102 (under HA#79 & 80) --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	9"x 9" Dark Brown w/ Black & Tan Waves VFT Mastic	450	SF	Room 102 (under HA#79 & 80) --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	9"x 9" Beige w/ Brown & Dark Brown Waves VFT	450	SF	Room 102 (under HA#79 & 80) --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	9"x 9" Beige w/ Brown & Drk Brown Waves VFT Mastic	450	SF	Room 102 (under HA#79 & 80) --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12"x 12" Beige w/ Brown Specks VFT	1,500	SF	Room 102, 104 --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	12"x 12" Beige w/ Brown Specks VFT Mastic	1,500	SF	Room 102, 104 --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12"x 12" Green w/ White Streaks VFT	600	SF	Room 104 (under existing VFT) --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12"x 12" Green w/ White Streaks VFT Mastic	600	SF	Room 104 (under existing VFT) --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	Brown w/ Colored Waves Linoleum	300	SF	Dressing Room (Stage), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Brown w/ Colored Waves Linoleum Mastic	300	SF	Dressing Room (Stage), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12" x 12" White w/ Light Tan Streaks VFT	600	SF	Room 104, 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" White w/ Light Tan Streaks VFT Mastic	600	SF	Room 104, 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12"x12" Lt. Tan w/ Tan specks VFT	6,500	SF	Rms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87A	12"x12" Lt. Tan w/ Tan specks VFT Mastic	6,500	SF	Rms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	12"x12" Off White w/ Tan specks VFT	3,200	SF	Rms 307, 101, 302 (304 under carpet) --1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88A	12"x12" Off White w/ Tan specks VFT Mastic	3,200	SF	Rms 307, 101, 302 (304 under carpet) --1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	12"x12" White w/ Blue Specks VFT	3,900	SF	(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89A	12"x12" Off White w/ Tan specks VFT Mastic	3,900	SF	(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12"x12" Lt. Tan w/ Tan specks VFT	3,200	SF	Rms 223, 221, 219, Bsmt Kitchen (1953 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90A	12"x12" Lt. Tan w/ Tan specks VFT Mastic	3,200	SF	Rms 223, 221, 219, Bsmt Kitchen (1953 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	12"x12" Brown VFT - Abated			4th Floor Book Storage by Library (1923 bldg)	Abated	MISC					

Chicago Public Schools

School Marshall Middle School

Unit 41081

Building ID 7520

Address 3900 N Lawndale Avenue

Chicago, IL, 60618

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
91A	12"x12" Brown VFT Mastic - Abated			4th Floor Book Storage by Library (1923 bldg)	Abated	MISC					
92	12"x12" Beige VFT - Abated			4th Floor Book Storage by Library (1923 bldg)	Abated	MISC					
92A	12"x12" Beige VFT Mastic - Abated			4th Floor Book Storage by Library (1923 bldg)	Abated	MISC					
93	9"x9" Gray w/ Pink & White Streaks VFT - Abated			Rm 428 (1923 bldg)	Abated	MISC					
93A	9"x9" Gray w/ Pink & White Streaks VFT Mastic - Abated			Rm 428 (1923 bldg)	Abated	MISC					
94	9"x9" Maroon w/ White Streaks VFT - Abated			Rm 428 (1923 bldg)	Abated	MISC					
94A	9"x9" Maroon w/ White Streaks VFT Mastic - Abated			Rm 428 (1923 bldg)	Abated	MISC					
95	Terrazzo	10,000	SF	Corridors, Stairwells (bsmt - 4th fl.), Toilets (all floors), Rm 311, Janitor's Closets, Auditorium Main Entrance (1923 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	Terrazzo	5,000	SF	Corridors (bsmt - 3rd fl.), Stairwells (bsmt - 4th fl) (1953 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	Cardboard Pipe Insulation	80	LF	Auditorium Balcony (behind plaster wall) - 1923 Bldg	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
98	Stage's Fire Curtain	1,000	SF	Auditorium Stage - 1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	9" x 9" Tan Ceiling Tile	1,500	SF	Auditorium Balcony - 1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99A	9" x 9" Tan Ceiling Tile Mastic Pucks	1,500	SF	Auditorium Balcony - 1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Marshall Middle School
Address 3900 N Lawndale Avenue

Unit 41081
 Chicago, IL, 60618

Building ID 7520
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

Review Date	11/1/2022
Manager Planner Name	Jigar Shah
100-07342	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
100	
100A	
101	
102	
102A	
103	

Chicago Public Schools

School Marshall Middle School
Address 3900 N Lawndale Avenue

Unit 41081
Chicago, IL, 60618

Building ID 7520
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
104	
105	
106	
107	
108	
108A	
109	
109A	
11	
110	
110A	
111	
112	
112A	
113	
113A	
114	
115	
116	
116A	
117	
117A	
118	
118A	
119	
119A	
12	

Chicago Public Schools

School Marshall Middle School
Address 3900 N Lawndale Avenue

Unit 41081
 Chicago, IL, 60618

Building ID 7520
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
120	
121	
122	
122A	
123	
123A	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	

Chicago Public Schools

School Marshall Middle School
Address 3900 N Lawndale Avenue

Unit 41081
Chicago, IL, 60618

Building ID 7520
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	

Chicago Public Schools

School Marshall Middle School
Address 3900 N Lawndale Avenue

Unit 41081
Chicago, IL, 60618

Building ID 7520
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	

Chicago Public Schools

School Marshall Middle School
Address 3900 N Lawndale Avenue

Unit 41081
Chicago, IL, 60618

Building ID 7520
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
87A	
88	
88A	
89	
89A	
90	
90A	
91	
91A	
92	
92A	
93	
93A	
94	
94A	
95	
96	
97	
98	
99	
99A	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Blue & Orange Streaks VFT (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Room 002, 1953**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Blue & Orange Streaks VFT (Removed)**
MATERIAL LOCATION: **Lunchroom, Room 002, 1953**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Blue & Orange Streaks VFT Mastic (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Room 002, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Blue & Orange Streaks VFT Mastic (Removed)**
MATERIAL LOCATION: **Lunchroom, Room 002, 1953**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 217, 315, 319, 323, Basement Vestibule, 1953**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & White Streaks VFT**
MATERIAL LOCATION: **Room 217, 315, 319, 323, Basement Vestibule, 1953**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 217, 315, 319, 323, Basement Vestibule, 1953**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 217, 315, 319, 323, Basement Vestibule, 1953**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **9"x 9" Tan w/ White & Brown Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Vestibule, 1953**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **9"x 9" Tan w/ White & Brown Streaks VFT**
MATERIAL LOCATION: **Basement Vestibule, 1953**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/01/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x 9" Tan w/ White & Brown Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Vestibule, 1953**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x 9" Tan w/ White & Brown Streaks VFT Mastic**
MATERIAL LOCATION: **Basement Vestibule, 1953**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x 9" Gray w/ Black & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 422 (storage), art room office (414) -1953 Bldg**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x 9" Gray w/ Black & White Streaks VFT**
MATERIAL LOCATION: **Room 422 (storage), art room office (414) -1953 Bldg**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9"x 9" Gray w/ Black & White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 422 (storage), art room office (414) -1953 Bldg**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9"x 9" Gray w/ Black & White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 422 (storage), art room office (414) -1953 Bldg**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x 12" Blue VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 002, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x 12" Blue VFT (Abated)**
MATERIAL LOCATION: **Room 002, 1953**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12"x 12" Blue VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 002, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12"x 12" Blue VFT Mastic (Abated)**
MATERIAL LOCATION: **Room 002, 1953**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **1' x 1' Tan Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium - 1923 Bldg**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **1' x 1' Tan Ceiling Tile**
MATERIAL LOCATION: **Auditorium - 1923 Bldg**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/01/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100A**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic Pucks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium - 1923 Bldg**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **100A**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic Pucks**
MATERIAL LOCATION: **Auditorium - 1923 Bldg**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Decorative Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium and Balcony - 1923 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Decorative Plaster**
MATERIAL LOCATION: **Auditorium and Balcony - 1923 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg**
MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**
MATERIAL LOCATION: **1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg**
MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102A**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic Pucks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg**
MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **102A**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic Pucks**
MATERIAL LOCATION: **1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg**
MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 311, 213 -1923 Bldg**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**
MATERIAL LOCATION: **Room 311, 213 -1923 Bldg**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout -1953 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**
MATERIAL LOCATION: **Throughout -1953 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **Fume Hood Panels (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 216- 1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **Fume Hood Panels (Abated)**
MATERIAL LOCATION: **Rooms 216- 1953 Addition**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Lab Counter Tops - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 318, 318A, 316A, 316B - 1953 Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Lab Counter Tops - Abated**
MATERIAL LOCATION: **Rooms 318, 318A, 316A, 316B - 1953 Addition**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Yellow Linoleum Flooring - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor Library Office Storage Room - 1923 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Yellow Linoleum Flooring - Abated**
MATERIAL LOCATION: **4th Floor Library Office Storage Room - 1923 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12x12 Lt. Yellow VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms (204 and 206 under carpet tiles) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12x12 Lt. Yellow VFT**
MATERIAL LOCATION: **Rooms (204 and 206 under carpet tiles) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108A**
MATERIAL DESCRIPTION: **12x12 Lt. Yellow VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **108A**
MATERIAL DESCRIPTION: **12x12 Lt. Yellow VFT Mastic**
MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12x12 Blue VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12x12 Blue VFT**
MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109A**
MATERIAL DESCRIPTION: **12x12 Blue VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **109A**
MATERIAL DESCRIPTION: **12x12 Blue VFT Mastic**
MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x 9" Gray w/ Yellow & Green Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **4th Floor Corridor, 1953**
MATERIAL QUANTITY: **1170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x 9" Gray w/ Yellow & Green Streaks VFT**
MATERIAL LOCATION: **4th Floor Corridor, 1953**
MATERIAL QUANTITY: **1170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/01/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **12x12 White w/ gray specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**
MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **12x12 White w/ gray specks VFT**
MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**
MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110A**
MATERIAL DESCRIPTION: **12x12 White w/ gray specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**

MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **110A**
MATERIAL DESCRIPTION: **12x12 White w/ gray specks VFT Mastic**
MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**
MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **Drywall system**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 402, 404, 406, 408, 410 -1923 Bldg**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **Drywall system**
MATERIAL LOCATION: **Rooms 402, 404, 406, 408, 410 -1923 Bldg**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12x12 Lt. Gray speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12x12 Lt. Gray speckled VFT**
MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112A**
MATERIAL DESCRIPTION: **12x12 Lt. Gray speckled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **112A**
MATERIAL DESCRIPTION: **12x12 Lt. Gray speckled VFT Mastic**
MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12x12 Dark gray w/white & gray speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12x12 Dark gray w/white & gray speckles VFT**
MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113A**
MATERIAL DESCRIPTION: **12x12 Dark gray w/white & gray speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **113A**
MATERIAL DESCRIPTION: **12x12 Dark gray w/white & gray speckles VFT Mastic**
MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 404, 406 -1923Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**
MATERIAL LOCATION: **Rooms 404, 406 -1923Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **4th fl library, 302, 304, 306 -1923Bldg**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **4th fl library, 302, 304, 306 -1923Bldg**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium -1923 Bldg**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT**
MATERIAL LOCATION: **Auditorium -1923 Bldg**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116A**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium -1923 Bldg**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **116A**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT Mastic**
MATERIAL LOCATION: **Auditorium -1923 Bldg**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12x12 Lt. Yellow VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms.216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12x12 Lt. Yellow VFT**
MATERIAL LOCATION: **Rooms.216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117A**
MATERIAL DESCRIPTION: **12x12 Lt. Yellow VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms.216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **117A**
MATERIAL DESCRIPTION: **12x12 Lt. Yellow VFT Mastic**
MATERIAL LOCATION: **Rooms.216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **12x12 Blue VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **12x12 Blue VFT**
MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118A**
MATERIAL DESCRIPTION: **12x12 Blue VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **118A**
MATERIAL DESCRIPTION: **12x12 Blue VFT Mastic**
MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **12x12 White w/gray specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **12x12 White w/gray specks VFT**
MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119A**
MATERIAL DESCRIPTION: **12x12 White w/gray specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **119A**
MATERIAL DESCRIPTION: **12x12 White w/gray specks VFT Mastic**
MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9"x 9" Gray w/ Yellow & Green Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **4th Floor Corridor, 1953**
MATERIAL QUANTITY: **1170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9"x 9" Gray w/ Yellow & Green Streaks VFT Mastic**
MATERIAL LOCATION: **4th Floor Corridor, 1953**
MATERIAL QUANTITY: **1170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly hall -1953 Bldg**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT**
MATERIAL LOCATION: **Assembly hall -1953 Bldg**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly hall -1953 Bldg**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT Mastic**
MATERIAL LOCATION: **Assembly hall -1953 Bldg**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Off white linoleum flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Off white linoleum flooring**
MATERIAL LOCATION: **Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122A**
MATERIAL DESCRIPTION: **Off white Linoleum flooring adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **122A**
MATERIAL DESCRIPTION: **Off white Linoleum flooring adhesive**
MATERIAL LOCATION: **Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **Gray Linoleum flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 218 - 1953 Bldg**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **Gray Linoleum flooring**
MATERIAL LOCATION: **Room 218 - 1953 Bldg**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123A**
MATERIAL DESCRIPTION: **Gray Linoleum flooring adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 218 - 1953 Bldg**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **123A**
MATERIAL DESCRIPTION: **Gray Linoleum flooring adhesive**
MATERIAL LOCATION: **Room 218 - 1953 Bldg**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9"x 9" Green w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953**
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9"x 9" Green w/ White Streaks VFT**
MATERIAL LOCATION: **Rm 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953**
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x 9" Green w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953**
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x 9" Green w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Rm 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953**
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall, Rooms 419, 423, 427, 431 -1953**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT**
MATERIAL LOCATION: **Assembly Hall, Rooms 419, 423, 427, 431 -1953**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall, Rooms 419, 423, 427, 431 -1953**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Assembly Hall, Rooms 419, 423, 427, 431 -1953**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9"x 9" Khaki w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 422(storage) --1953**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9"x 9" Khaki w/ White Streaks VFT**
MATERIAL LOCATION: **Room 422(storage) --1953**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9"x 9" Khaki w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 422(storage) --1953**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9"x 9" Khaki w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 422(storage) --1953**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9"x 9" Aqua VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 414/416 --1953**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9"x 9" Aqua VFT**
MATERIAL LOCATION: **Rooms 414/416 --1953**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **9"x 9" Aqua VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 414/416 --1953**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **9"x 9" Aqua VFT Mastic**
MATERIAL LOCATION: **Rooms 414/416 --1953**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12"x 12" White w/ Gray Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 420, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12"x 12" White w/ Gray Specks VFT**
MATERIAL LOCATION: **Room 420, 1953**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"x 12" White w/ Gray Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 420, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"x 12" White w/ Gray Specks VFT Mastic**
MATERIAL LOCATION: **Room 420, 1953**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9"x 9" Gray VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9"x 9" Gray VFT**
MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **9"x 9" Gray VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **9"x 9" Gray VFT Mastic**
MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **9"x 9" Orange VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **9"x 9" Orange VFT**
MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **9"x 9" Orange VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **9"x 9" Orange VFT Mastic**
MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **9"x 9" White w/ Black Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **4th Floor Toilet by Rm 415 and storage across from 419 --1953**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **9"x 9" White w/ Black Streaks VFT**
MATERIAL LOCATION: **4th Floor Toilet by Rm 415 and storage across from 419 --1953**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9"x 9" White w/ Black Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **4th Floor Toilet by Rm 415 and storage across from 419 --1953**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9"x 9" White w/ Black Streaks VFT Mastic**
MATERIAL LOCATION: **4th Floor Toilet by Rm 415 and storage across from 419 --1953**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **9"x 9" Pink w/ Brown & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 415 --1953**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **9"x 9" Pink w/ Brown & White Streaks VFT**
MATERIAL LOCATION: **Rooms 415 --1953**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9"x 9" Pink w/ Brown & White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 415 --1953**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9"x 9" Pink w/ Brown & White Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 415 --1953**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Thin Black Streaks VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 316, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Thin Black Streaks VFT (ABATED)**
MATERIAL LOCATION: **Room 316, 1953**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Thin Black Streaks VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 316, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Thin Black Streaks VFT Mastic (ABATED)**
MATERIAL LOCATION: **Room 316, 1953**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **9"x 9" Aqua w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Janitor's closet (131) and adjacent toilet --1953**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **9"x 9" Aqua w/ White Streaks VFT**
MATERIAL LOCATION: **Janitor's closet (131) and adjacent toilet --1953**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **9"x 9" Aqua w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Janitor's closet (131) and adjacent toilet --1953**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **9"x 9" Aqua w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Janitor's closet (131) and adjacent toilet --1953**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **9"x 9" Black w/ Pink & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor North Toilet by office 134 --1953**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **9"x 9" Black w/ Pink & White Streaks VFT**
MATERIAL LOCATION: **1st Floor North Toilet by office 134 --1953**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **9"x 9" Black w/ Pink & White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor North Toilet by office 134 --1953**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **9"x 9" Black w/ Pink & White Streaks VFT Mastic**
MATERIAL LOCATION: **1st Floor North Toilet by office 134 --1953**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **9"x 9" Tan VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall, 1953**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **9"x 9" Tan VFT**
MATERIAL LOCATION: **Assembly Hall, 1953**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **9"x 9" Tan VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall, 1953**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **9"x 9" Tan VFT Mastic**
MATERIAL LOCATION: **Assembly Hall, 1953**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **9"x 9" Brown VFT - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **9"x 9" Brown VFT - Abated**
MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **9"x 9" Brown VFT Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **9"x 9" Brown VFT Mastic - Abated**
MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **9"x 9" Beige VFT - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **9"x 9" Beige VFT - Abated**
MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **9"x 9" Beige VFT Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **9"x 9" Beige VFT Mastic - Abated**
MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Red Waves VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 433 office --1923**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Red Waves VFT**
MATERIAL LOCATION: **Room 433 office --1923**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Red Waves VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 433 office --1923**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Red Waves VFT Mastic**
MATERIAL LOCATION: **Room 433 office --1923**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **9"x 9" Green w/ White & Green Waves VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 433 office, 414, 416 --1923**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **9"x 9" Green w/ White & Green Waves VFT**
MATERIAL LOCATION: **Room 433 office, 414, 416 --1923**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **9"x 9" Green w/ White & Green Waves VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 433 office --1923**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **9"x 9" Green w/ White & Green Waves VFT Mastic**
MATERIAL LOCATION: **Room 433 office --1923**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **9"x 9" Red w/ White Waves VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 433 office --1923**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **9"x 9" Red w/ White Waves VFT**
MATERIAL LOCATION: **Room 433 office --1923**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **9"x 9" Red w/ White Waves VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 433 office --1923**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **9"x 9" Red w/ White Waves VFT Mastic**
MATERIAL LOCATION: **Room 433 office --1923**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ White & Brown Streaks VFT - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 411, 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ White & Brown Streaks VFT - Abated**
MATERIAL LOCATION: **Room 411, 1923**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ White & Brown Streaks VFT Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 411, 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ White & Brown Streaks VFT Mastic - Abated**
MATERIAL LOCATION: **Room 411, 1923**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9"x 9" White w/ Brown Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 304 (under HA# 88 & 88A), 306 (under carpet), 1923**
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9"x 9" White w/ Brown Specks VFT**
MATERIAL LOCATION: **Rooms 304 (under HA# 88 & 88A), 306 (under carpet), 1923**
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **9"x 9" White w/ Brown Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 304 (under HA# 88 & 88A), 306 (under carpet) --1923**
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **9"x 9" White w/ Brown Specks VFT Mastic**
MATERIAL LOCATION: **Rooms 304 (under HA# 88 & 88A), 306 (under carpet) --1923**
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12"x 12" White w/ Black & Gray Streaks VFT - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 210 (Hardwood Floor), 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12"x 12" White w/ Black & Gray Streaks VFT - REMOVED**
MATERIAL LOCATION: **Room 210 (Hardwood Floor), 1923**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12"x 12" White w/ Black & Gray Streaks VFT Mastic - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 210 (Hardwood Floor), 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12"x 12" White w/ Black & Gray Streaks VFT Mastic - REMOVED**
MATERIAL LOCATION: **Room 210 (Hardwood Floor), 1923**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12"x 12" Tan w/ Tan, Brown, & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 303 (under HA# 87 & 87A), 1923**

MATERIAL QUANTITY: **850**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12"x 12" Tan w/ Tan, Brown, & White Streaks VFT**
MATERIAL LOCATION: **Room 303 (under HA# 87 & 87A), 1923**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12"x 12" Tan w/ Tan, Brn, & White Strks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 303 (under HA# 87 & 87A), 1923**

MATERIAL QUANTITY: **850**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12"x 12" Tan w/ Tan, Brn, & White Strks VFT Mastic**
MATERIAL LOCATION: **Room 303 (under HA# 87 & 87A), 1923**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **9"x 9" Gray VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **9"x 9" Gray VFT**
MATERIAL LOCATION: **Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **9"x 9" Gray VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **9"x 9" Gray VFT Mastic**
MATERIAL LOCATION: **Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **12"x 12" White w/ Brown Specks VFT - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 203, 205, 207, 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **12"x 12" White w/ Brown Specks VFT - ABATED**
MATERIAL LOCATION: **Room 203, 205, 207, 1923**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12"x 12" White w/ Brown Specks VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 203, 205, 207, 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12"x 12" White w/ Brown Specks VFT Mastic (ABATED)**
MATERIAL LOCATION: **Room 203, 205, 207, 1923**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & Brown Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, 1923**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & Brown Streaks VFT**
MATERIAL LOCATION: **Auditorium, 1923**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & Brown Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, 1923**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & Brown Streaks VFT Mastic**
MATERIAL LOCATION: **Auditorium, 1923**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Brown Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, 1923**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Brown Streaks VFT**
MATERIAL LOCATION: **Auditorium, 1923**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Brown Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, 1923**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Brown Streaks VFT Mastic**
MATERIAL LOCATION: **Auditorium, 1923**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium --1923**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT**
MATERIAL LOCATION: **Auditorium --1923**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium --1923**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Auditorium --1923**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12"x 12" Brown w/ Brown & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 109 (kitchen) --1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12"x 12" Brown w/ Brown & White Streaks VFT**
MATERIAL LOCATION: **Room 109 (kitchen) --1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12"x 12" Brown w/ Brown & White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 109 (kitchen) --1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12"x 12" Brown w/ Brown & White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 109 (kitchen) --1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Dark Brown & Tan Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Dark Brown & Tan Streaks VFT**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Drk Brown & Tan Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **9"x 9" Brown w/ Drk Brown & Tan Streaks VFT Mastic**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **9"x 9" Dark Tan w/ Brown & Tan Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **9"x 9" Dark Tan w/ Brown & Tan Streaks VFT**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **9"x 9" Dark Tan w/ Brown & Tan Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **9"x 9" Dark Tan w/ Brown & Tan Streaks VFT Mastic**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **9"x 9" Light Tan w/ Tan Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **9"x 9" Light Tan w/ Tan Streaks VFT**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **9"x 9" Light Tan w/ Tan Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **9"x 9" Light Tan w/ Tan Streaks VFT Mastic**
MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **9"x 9" Dark Brown w/ Black & Tan Waves VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **9"x 9" Dark Brown w/ Black & Tan Waves VFT**
MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **9"x 9" Dark Brown w/ Black & Tan Waves VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**

MATERIAL QUANTITY: **450**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **9"x 9" Dark Brown w/ Black & Tan Waves VFT Mastic**
MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **9"x 9" Beige w/ Brown & Dark Brown Waves VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **9"x 9" Beige w/ Brown & Dark Brown Waves VFT**
MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **9"x 9" Beige w/ Brown & Drk Brown Waves VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **9"x 9" Beige w/ Brown & Drk Brown Waves VFT Mastic**
MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Brown Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 102, 104 --1923**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Brown Specks VFT**
MATERIAL LOCATION: **Room 102, 104 --1923**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Brown Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102, 104 --1923**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Brown Specks VFT Mastic**
MATERIAL LOCATION: **Room 102, 104 --1923**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12"x 12' Green w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104 (under existing VFT) --1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12"x 12' Green w/ White Streaks VFT**
MATERIAL LOCATION: **Room 104 (under existing VFT) --1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **12"x 12' Green w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104 (under existing VFT) --1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **12"x 12' Green w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 104 (under existing VFT) --1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **Brown w/ Colored Waves Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Dressing Room (Stage), 1923**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **Brown w/ Colored Waves Linoleum**
MATERIAL LOCATION: **Dressing Room (Stage), 1923**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **Brown w/ Colored Waves Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Dressing Room (Stage), 1923**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **Brown w/ Colored Waves Linoleum Mastic**
MATERIAL LOCATION: **Dressing Room (Stage), 1923**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Tan Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104, 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Tan Streaks VFT**
MATERIAL LOCATION: **Room 104, 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Tan Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104, 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Tan Streaks VFT Mastic**
MATERIAL LOCATION: **Room 104, 1923**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT**
MATERIAL LOCATION: **Rms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87A**
MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **87A**
MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT Mastic**
MATERIAL LOCATION: **Rms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms 307, 101, 302 (304 under carpet) --1923 Bldg**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan specks VFT**
MATERIAL LOCATION: **Rms 307, 101, 302 (304 under carpet) --1923 Bldg**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88A**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rms 307, 101, 302 (304 under carpet) --1923 Bldg**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **88A**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan specks VFT Mastic**
MATERIAL LOCATION: **Rms 307, 101, 302 (304 under carpet) --1923 Bldg**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **12"x12" White w/ Blue Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg**

MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **12"x12" White w/ Blue Specks VFT**
MATERIAL LOCATION: **(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg**
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89A**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg**

MATERIAL QUANTITY: **3900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **89A**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan specks VFT Mastic**
MATERIAL LOCATION: **(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg**
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms 223, 221, 219, Bsmt Kitchen (1953 bldg)**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT**
MATERIAL LOCATION: **Rms 223, 221, 219, Bsmt Kitchen (1953 bldg)**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90A**
MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rms 223, 221, 219, Bsmt Kitchen (1953 bldg)**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **90A**
MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT Mastic**
MATERIAL LOCATION: **Rms 223, 221, 219, Bsmt Kitchen (1953 bldg)**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **12"x12" Brown VFT - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **12"x12" Brown VFT - Abated**
MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91A**
MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **91A**
MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic - Abated**
MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **12"x12" Beige VFT - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **12"x12" Beige VFT - Abated**
MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92A**
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **92A**
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic - Abated**
MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Pink & White Streaks VFT - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 428 (1923 bldg)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Pink & White Streaks VFT - Abated**
MATERIAL LOCATION: **Rm 428 (1923 bldg)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93A**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Pink & White Streaks VFT Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 428 (1923 bldg)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **93A**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Pink & White Streaks VFT Mastic - Abated**
MATERIAL LOCATION: **Rm 428 (1923 bldg)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **9"x9" Maroon w/ White Streaks VFT - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 428 (1923 bldg)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **9"x9" Maroon w/ White Streaks VFT - Abated**
MATERIAL LOCATION: **Rm 428 (1923 bldg)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94A**
MATERIAL DESCRIPTION: **9"x9" Maroon w/ White Streaks VFT Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 428 (1923 bldg)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **94A**
MATERIAL DESCRIPTION: **9"x9" Maroon w/ White Streaks VFT Mastic - Abated**
MATERIAL LOCATION: **Rm 428 (1923 bldg)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Corridors, Stairwells (bsmt - 4th fl.), Toilets (all floors), Rm 311, Janitor's Closets, Auditorium Main Entrance (1923 bldg)**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUILDING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Corridors, Stairwells (bsmt - 4th fl.), Toilets (all floors), Rm 311, Janitor's Closets, Auditorium Main Entrance (1923 bldg)**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Corridors (bsmt - 3rd fl.), Stairwells (bsmt - 4th fl) (1953 bldg)**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Corridors (bsmt - 3rd fl.), Stairwells (bsmt - 4th fl) (1953 bldg)**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium Balcony (behind plaster wall) - 1923 Bldg**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Auditorium Balcony (behind plaster wall) - 1923 Bldg**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/01/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **Stage's Fire Curtain**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium Stage - 1923 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 10/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **Stage's Fire Curtain**
MATERIAL LOCATION: **Auditorium Stage - 1923 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **9" x 9" Tan Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium Balcony - 1923 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **9" x 9" Tan Ceiling Tile**
MATERIAL LOCATION: **Auditorium Balcony - 1923 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Marshall Middle School** INSPECTION DATE: **10/10/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99A**
MATERIAL DESCRIPTION: **9" x 9" Tan Ceiling Tile Mastic Pucks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium Balcony - 1923 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41081** BUIDLING ID: **7520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Marshall Middle School** REVIEW DATE: **11/1/2022**
ADDRESS: **3900 N Lawndale Avenue** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **99A**
MATERIAL DESCRIPTION: **9" x 9" Tan Ceiling Tile Mastic Pucks**
MATERIAL LOCATION: **Auditorium Balcony - 1923 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ANTONIO MUNOZ IV
has completed the ASBESTOS INSPECTOR'S INITIAL course and successfully passed the
examination on 03/30/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

03/28/2022-03/30/2022

Course Dates:

03/30/2023

Expires:

2203BI03

Certificate Number:

A handwritten signature in black ink, appearing to read "N Peneff".

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

ANTONIO MUNOZ IV
3211 S HAMILTON
CHICAGO, IL 60608

4/21/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 20616

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 20616	ISSUED 4/21/2022	EXPIRES 05/15/2023		INSPECTOR 3/30/2023	
ANTONIO MUNOZ IV 3211 S HAMILTON CHICAGO, IL 60608 Environmental Health				PROJECT MANAGER 1/22/2023	
				Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES
Nationally Accredited by PHAB

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2023



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/23/2023

Exam Date: 2/23/2023

Expiration Date: 2/23/2024

Certificate Number: MPR2302230560

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: MPR2203090714

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090705

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 07342

ISSUED
4/1/2022

EXPIRES
05/15/2023

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612



Environmental Health

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/1/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

<p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p>		<p>TC EXPIRES</p>
<p>ID NUMBER 100 - 07342</p>	<p>ISSUED 4/1/2022</p>	<p>EXPIRES 05/15/2023</p>	<p>INSPECTOR</p>	<p>3/9/2023</p>	
<p>JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health</p>			<p>PROJECT DESIGNER</p>	<p>3/24/2023</p>	
			<p>MANAGEMENT PLANNER</p>	<p>3/9/2023</p>	
			<p>PROJECT MANAGER</p>	<p>3/2/2023</p>	
			<p>AIR SAMPLING PROFESSIONAL</p>		
			<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed