

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2366
SCHOOL NAME: Murray Academy
ADDRESS OF SCHOOL: 5335 S. Kenwood
CITY: Chicago, IL, 60615

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/15/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 11/1/2022 ENROLLMENT 439
IDPH INSPECTOR LICENSE NUMBER: 100-07278
IDPH LICENSED INSPECTOR NAME (Please Print): Kenneth Karuhn
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



11/18/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Murray Academy

5335 S. Kenwood
Chicago, IL, 60615

Unit: 29221
Building ID: 5030

IDPH ID Number: 14-016-2990-2366

REPORT DATE:

Friday, November 18, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 18, 2022

RE: Murray Academy, Unit 29221
5335 S. Kenwood
Chicago, IL, 60615

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Murray Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Murray Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Murray Academy Unit: 29221 Region: 04
Address: 5335 S. Kenwood Chicago, IL, 60615
IDPH ID: 14-016-2990-2366 Building ID: 5030
Contact: Carey, Joshua Phone: 7737102545

2. Description of Facility

Original Construction: 2002 Additional Construction: 1954,2002
Total Square Footage: 16760 No of Floors: 2
Current Occupancy: 439

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Kenneth Karuhn


Inspector IDPH license # 100-07278
Reinspection Date: 11/1/2022

Signature: 
Date: 11/1/2022

6. Management Planner

Management Planner Name: Evan Christian


Management Planner IDPH license # 100-19466

Signature: 
Date: 11/18/2022

7. Review Date: 11/18/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 11/18/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Murray Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5030:

010	12" x 12" gray w/ black Specks Floor Tile
011	12" x 12" gray Floor Tile
012	12" x 12" Light Gray Floor Tile
52	Duct sealant
53	Gray terrazzo
54	12" x 12" Gray w/ Pink and black Streaks Floor Tile
55	12" x 12" Gray w/ Pink and black Streaks Floor Tile Mastic
56	12" x 12" Green w/ Pink and Black Streaks Floor Tile

57	12" x 12" Green w/ Pink and Black Streaks Floor Tile Mastic
58	12" x 12" Dark Gray Mottled Floor Tile
59	12" x 12" Dark Gray Mottled Floor Tile Mastic
60	1' x 1' Ceiling Tile w/ Holes
61	Cream terrazzo
62	Green terrazzo
63	Purple terrazzo
64	2' x 4' Ceiling Tile w/ Divider and Holes
65	Gray sink undercoating
66	2' x 2' Ceiling Tile w/ Holes
67	Brown carpet mastic
68	Spray-on insulation
69	12" x 12" Green Floor Tile
70	12" x 12" Green Floor Tile Mastic
71	Green linoleum
72	Green linoleum mastic
73	2' x 4' Smooth Ceiling Tile
74	Epoxy Coating on Floor
75	1' x 1' Ceiling Tile w/ Gouges
76	1' x 1' Smooth Ceiling Tile
77	Tongue and Groove Wood Floor
78	Tan and Green Terrazzo
79	12" x 12" Light Blue Floor Tile

80	12" x 12" Light Blue Floor Tile Mastic
81	12" x 12" White w/ Green Streaks Floor Tile
82	12" x 12" White w/ Green Streaks Floor Tile Mastic
83	12" x 12" Beige Mottled Floor Tile
84	12" x 12" Beige Mottled Floor Tile Mastic
FA	Cardboard lag

B. The following new homogenous areas have been identified for Building 5030:

52	Duct sealant
53	Gray terrazzo
54	12" x 12" Gray w/ Pink and black Streaks Floor Tile
55	12" x 12" Gray w/ Pink and black Streaks Floor Tile Mastic
56	12" x 12" Green w/ Pink and Black Streaks Floor Tile
57	12" x 12" Green w/ Pink and Black Streaks Floor Tile Mastic
58	12" x 12" Dark Gray Mottled Floor Tile
59	12" x 12" Dark Gray Mottled Floor Tile Mastic
60	1' x 1' Ceiling Tile w/ Holes
61	Cream terrazzo
62	Green terrazzo
63	Purple terrazzo
64	2' x 4' Ceiling Tile w/ Divider and Holes
65	Gray sink undercoating
66	2' x 2' Ceiling Tile w/ Holes
67	Brown carpet mastic
68	Spray-on insulation
69	12" x 12" Green Floor Tile
70	12" x 12" Green Floor Tile Mastic
71	Green linoleum
72	Green linoleum mastic

73	2' x 4' Smooth Ceiling Tile
74	Epoxy Coating on Floor
75	1' x 1' Ceiling Tile w/ Gouges
76	1' x 1' Smooth Ceiling Tile
77	Tongue and Groove Wood Floor
78	Tan and Green Terrazzo
79	12" x 12" Light Blue Floor Tile
80	12" x 12" Light Blue Floor Tile Mastic
81	12" x 12" White w/ Green Streaks Floor Tile
82	12" x 12" White w/ Green Streaks Floor Tile Mastic
83	12" x 12" Beige Mottled Floor Tile
84	12" x 12" Beige Mottled Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

010	12" x 12" gray w/ black Specks Floor Tile
011	12" x 12" gray Floor Tile
012	12" x 12" Light Gray Floor Tile
10	Paperwrap/aircell pipe insulation wrap
11	Paperwrap/aircell pipe insulation
12	Paperwrap/aircell pipe joint insulation
28	Roof materials (Non-AHERA)
35	12" x 12" Blue Floor Tile
36	12" x 12" White Floor Tile
37	12" x 12" Yellow Floor Tile
48	Blue carpet adhesive
49	Chalk Board and Poster Board Adhesive
50	12" x 12" Light Beige w/ Brown spots Floor Tile
51	12" x 12" Light Beige w/ Brown spots Floor Tile Mastic
52	Duct sealant
53	Gray terrazzo
54	12" x 12" Gray w/ Pink and black Streaks Floor Tile
55	12" x 12" Gray w/ Pink and black Streaks Floor Tile Mastic
56	12" x 12" Green w/ Pink and Black Streaks Floor Tile
57	12" x 12" Green w/ Pink and Black Streaks Floor Tile Mastic
58	12" x 12" Dark Gray Mottled Floor Tile
59	12" x 12" Dark Gray Mottled Floor Tile Mastic
60	1' x 1' Ceiling Tile w/ Holes
61	Cream terrazzo
62	Green terrazzo
63	Purple terrazzo
64	2' x 4' Ceiling Tile w/ Divider and Holes
65	Gray sink undercoating
66	2' x 2' Ceiling Tile w/ Holes
67	Brown carpet mastic
68	Spray-on insulation
69	12" x 12" Green Floor Tile
70	12" x 12" Green Floor Tile Mastic
71	Green linoleum
72	Green linoleum mastic
73	2' x 4' Smooth Ceiling Tile
74	Epoxy Coating on Floor
75	1' x 1' Ceiling Tile w/ Gouges

76	1' x 1' Smooth Ceiling Tile
77	Tongue and Groove Wood Floor
78	Tan and Green Terrazzo
79	12" x 12" Light Blue Floor Tile
7A	12" x 12" Gray, White & Tan Floor Tile
80	12" x 12" Light Blue Floor Tile Mastic
81	12" x 12" White w/ Green Streaks Floor Tile
82	12" x 12" White w/ Green Streaks Floor Tile Mastic
83	12" x 12" Beige Mottled Floor Tile
84	12" x 12" Beige Mottled Floor Tile Mastic
CA	Paperwrap pipe insulation wrap
E	Elbow insulation
EA	Paperwrap pipe insulation
FA	Cardboard lag

The following areas were deemed to be inaccessible:

10	Paperwrap/aircell pipe insulation wrap
11	Paperwrap/aircell pipe insulation
12	Paperwrap/aircell pipe joint insulation
35A	12" x 12" Blue Floor Tile Mastic
48	Blue carpet adhesive
49	Chalk Board and Poster Board Adhesive
51	12" x 12" Light Beige w/ Brown spots Floor Tile Mastic
60	1' x 1' Ceiling Tile w/ Holes
64	2' x 4' Ceiling Tile w/ Divider and Holes
66	2' x 2' Ceiling Tile w/ Holes
68	Spray-on insulation
73	2' x 4' Smooth Ceiling Tile
75	1' x 1' Ceiling Tile w/ Gouges
76	1' x 1' Smooth Ceiling Tile
9A	12" x 12" Gray, White & Tan Floor Tile Mastic
9C	12" x 12" Dark Gray/Orange w/Blk & Tan Streaks Floor Tile Mastic
9D	12" x 12" Beige Floor Tile w/Dark Green Streaks Mastic
9E	12" x 12" Gray Floor Tile w/White Streaks Mastic
E	Elbow insulation
FA	Cardboard lag

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Kenneth Karuhn, IDPH License # 100-07278. The

Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Murray Academy Building 5030 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
010	12" x 12" gray w/ black Specks Floor Tile	800	SF	Room 101	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		HIGH
011	12" x 12" gray Floor Tile	600	SF	Room 108	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		HIGH
012	12" x 12" Light Gray Floor Tile	300	SF	West boys bathroom	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		MODERATE
1	Plaster			Throughout Facility	NO_ACBM	SURFACE								
10	Paperwrap/aircell pipe insulation wrap	250	LF	In various inaccessible areas throughout facility	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
11	Paperwrap/aircell pipe insulation	250	LF	In various inaccessible areas throughout facility	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
12	Paperwrap/aircell pipe joint insulation	50	LF	In various inaccessible areas throughout facility	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
13	Boiler gaskets			Boiler Room	NO_ACBM	MISC								
14	Interior brick			Throughout Building	NO_ACBM	MISC								
15	Interior brick mortar			Throughout Building	NO_ACBM	MISC								
16	Elbow wrap			Boy's Bathroom	NO_ACBM	MISC								
17	Duct vibration material			Equipment Room	NO_ACBM	MISC								
18	Exterior brick - Non-AHERA			Exterior of Building	NO_ACBM	MISC								
19	Exterior brick mortar (Non-AHERA)			Exterior of Building	NO_ACBM	MISC								
20	Exterior door caulk - Non-AHERA			Building Exterior	NO_ACBM	MISC								
21	Plaster			Throughout	NO_ACBM	SURFACE								
22	Green Vinyl Curtain (Cream and Brown)			Gym	NO_ACBM	MISC								
23	12" x 12" Ceiling Tile			Gym, Room 210	NO_ACBM	MISC								
24	Brown carpet			1st Floor Office	NO_ACBM	MISC								
25	Brown carpet adhesive			1st Floor Office	NO_ACBM	MISC								
26	Black felight door trim			2nd Floor Fan Room	NO_ACBM	MISC								
28	Roof materials (Non-AHERA)			Roof	ASSUMED	MISC								
35	12" x 12" Blue Floor Tile	150	SF	Room 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
35A	12" x 12" Blue Floor Tile Mastic	150	SF	Room 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Room	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
36	12" x 12" White Floor Tile	2,500	SF	1st & 2nd Floor Hall, Faculty	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Lounge, 216, 218, 121, 120, 119, 116										
36A	12" x 12" White Floor Tile Mastic			1st & 2nd Floor Hall, 216, 218, 121, 120, 119, 116	NO_ACBM	MISC								
37	12" x 12" Yellow Floor Tile	2,500	SF	1st & 2nd Floor Hall, 219, 221, 118, Annex Multi-Purpose Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
37A	12" x 12" Yellow Floor Tile Mastic			1st & 2nd Hall, 219, 221, 118, Annex Multi-Purpose Room	NO_ACBM	MISC								
48	Blue carpet adhesive	400	SF	Office and Principal's Office Room 200	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
49	Chalk Board and Poster Board Adhesive	150	SF	All Classrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
50	12" x 12" Light Beige w/ Brown spots Floor Tile	100	SF	Engineer's office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
51	12" x 12" Light Beige w/ Brown spots Floor Tile Mastic	100	SF	engineer's office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
52	Duct sealant	5	SF	Boiler Room	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
53	Gray terrazzo	250	SF	North Stairs	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
54	12" x 12" Gray w/ Pink and black Streaks Floor Tile	250	SF	Rooms 202, 201, 206, 208, 205, 207, 210, 107, 108, 105, 104	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
55	12" x 12" Gray w/ Pink and black Streaks Floor Tile Mastic	250	SF	Rooms 202, 201, 206, 208, 205, 207, 210, 107, 108, 105, 104	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
56	12" x 12" Green w/ Pink and Black Streaks Floor Tile	250	SF	Room 203	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
57	12" x 12" Green w/ Pink and Black Streaks Floor Tile Mastic	250	SF	Room 203	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
58	12" x 12" Dark Gray Mottled Floor Tile	50	SF	Room 205 (patch)	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
59	12" x 12" Dark Gray Mottled Floor Tile Mastic	50	SF	Room 205 (patch)	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
60	1' x 1' Ceiling Tile w/ Holes	400	SF	Room 210, Lunchroom	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
61	Cream terrazzo	2,000	SF	East Wing, Park District Annex	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
62	Green terrazzo	250	SF	East Hallway, Park District Annex	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
63	Purple terrazzo	100	SF	East Hallway, Park District Annex	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
64	2' x 4' Ceiling Tile w/ Divider and Holes	1,300	SF	Faculty Lounge, Library, 218 121, 120, 118, 119, 116m 1130Assistant Principal's Office, 111, Annex Office, Annex Multi-Purpose Room	ASSUMED	MISC	N	LOC	10	SF	Yes	ACBM with the potential for damage	9	LOW
65	Gray sink undercoating	5	SF	Faculty Lounge, 116, 108, 104, Annex Pantry	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
66	2' x 2' Ceiling Tile w/ Holes	800	SF	Room 213, 216, 219, 221	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
67	Brown carpet mastic	1,250	SF	Room 213, Library	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
68	Spray-on insulation	15	LF	Closet 215, Closet 115	ASSUMED	TSI	N	NONE	0	LF	Yes	ACBM with the potential for damage		LOW
69	12" x 12" Green Floor Tile	150	SF	Rooms 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Rooms	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
6A	9" x 9" White Floor Tile w/Gray Streaks			Engineer's Office	CHR	MISC								
70	12" x 12" Green Floor Tile Mastic	150	SF	Rooms 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Rooms	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
71	Green linoleum	500	SF	Servery	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
72	Green linoleum mastic	500	SF	Servery	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
73	2' x 4' Smooth Ceiling Tile	800	SF	Kitchen and Kitchen Office	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
74	Epoxy Coating on Floor	800	SF	Kitchen	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
75	1' x 1' Ceiling Tile w/ Gouges	1,000	SF	Lunch Room	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
76	1' x 1' Smooth Ceiling Tile	25	SF	Lunch Room (patches)	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
77	Tongue and Groove Wood Floor	1,500	SF	Lunch Room Gym	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
78	Tan and Green Terrazzo	500	SF	West Stairs	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
79	12" x 12" Light Blue Floor Tile	75	SF	Main Office Bathroom	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
7A	12" x 12" Gray, White & Tan Floor Tile	2,500	SF	1st Floor Corridor, Room 107, & 2nd Floor Library	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
7B	12" x 12" Light Brown Floor Tile w/Dark Brown Streaks			1st & 2nd Floor Corridors - Abated	ABATED	MISC								
7C	12" x 12" Dark Gray/Orange w/Black & Tan Streaks Floor Tile	11,825	SF	Rooms 104, 105, 107, 108, 201-203, 205, 206-208, 210, Library, Principal's Office, Teacher's Lunch Room	CHR	MISC	N	DIST	155	SF	No	ACBM with the potential for damage	5	LOW
7D	12" x 12" Beige Floor Tile w/Dark Green Streaks	1,200	SF	Room 106	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
7E	12" x 12" Gray Floor Tile w/White Streaks	2,250	SF	Rooms 103, 204	CHR	MISC	N	LOC	5	SF	No	ACBM with the potential for damage	5	LOW
80	12" x 12" Light Blue Floor Tile Mastic	75	SF	Main Office Bathroom	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
81	12" x 12" White w/ Green Streaks Floor Tile	500	SF	Room 106	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
82	12" x 12" White w/ Green Streaks Floor Tile Mastic	500	SF	Room 106	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
83	12" x 12" Beige Mottled Floor Tile	500	SF	Park District Annex Pantry, Annex Conference Room	ASSUMED	MISC	N	LOC	8	SF	Yes	ACBM with the potential for damage	5	LOW
84	12" x 12" Beige Mottled Floor Tile Mastic	500	SF	Park District Annex Pantry, Annex Conference Room	ASSUMED	MISC	N	LOC	8	SF	Yes	ACBM with the potential for damage	5	LOW
8A	9" x 9" White Floor Tile w/Gray Streaks Mastic			Engineer's Office	CHR	MISC								
9A	12" x 12" Gray, White & Tan Floor Tile Mastic	260	SF	1st Floor Corridor, Room 107, & Library	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
9B	12" x 12" Light Brown Floor Tile w/Dark Brown Streaks Mastic - Abated			1st & 2nd Floor Corridors	ABATED	MISC								
9C	12" x 12" Dark Gray/Orange w/Blk & Tan Streaks Floor Tile Mastic	11,825	SF	Rooms 104, 105, 107, and 108,	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Teacher's Lunch Room, Principal's Office, 201-203, 205-208, Library										
9D	12" x 12" Beige Floor Tile w/Dark Green Streaks Mastic	1,200	SF	Room 106	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
9E	12" x 12" Gray Floor Tile w/White Streaks Mastic	1,200	SF	Rooms 204, 103	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
A	Boiler tank insulation			Boiler Room	NO_ACBM	MISC								
CA	Paperwrap pipe insulation wrap		LF	Boy's Bathroom	ASSUMED	TSI				LF				
E	Elbow insulation	5	LF	Boy's Bathroom	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
EA	Paperwrap pipe insulation	8	LF	Boy's Bathroom Janitor Closet 1st Floor	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
FA	Cardboard lag	5	LF	Boy's Bathroom	ASSUMED	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 11/1/2022
Inspector Name <u>Kenneth Karuhn</u>
100-07278 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
010	
011	
012	
1	
10	Inaccessible 2022
11	Inaccessible 2022
12	Inaccessible 2022
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
28	
35	Inaccessible 2022
35A	Inaccessible 2022

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
36	
36A	
37	
37A	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	Damage in Annex Multi- Purpose Room
65	
66	
67	
68	
69	
6A	Not observed 2022
70	
71	

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
72	
73	
74	
75	
76	
77	
78	
79	
7A	
7B	
7C	Damage in Room 104 (30SF), Room 203 (50 SF), Room 205 (75 SF)
7D	
7E	Damage in Room 204 (5 SF)
80	
81	
82	
83	Damage in Annex Pantry
84	Damage in Annex Pantry
8A	Not observed 2022
9A	
9B	
9C	
9D	
9E	Not observed in room 103
A	
CA	Not observed 2022
E	
EA	Inaccessible 2022
FA	

Chicago Public Schools

School Murray Academy **Unit** 29221 **Building ID** 5030

Address 5335 S. Kenwood **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Murray Academy
Address 5335 S. Kenwood

Unit 29221
 Chicago, IL, 60615

Building ID 5030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
010	12" x 12" gray w/ black Specks Floor Tile	800	SF	Room 101	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
011	12" x 12" gray Floor Tile	600	SF	Room 108	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
012	12" x 12" Light Gray Floor Tile	300	SF	West boys bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1	Plaster			Throughout Facility	No ACBM	SURFACE					
10	Paperwrap/aircell pipe insulation wrap	250	LF	In various inaccessible areas throughout facility	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
11	Paperwrap/aircell pipe insulation	250	LF	In various inaccessible areas throughout facility	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
12	Paperwrap/aircell pipe joint insulation	50	LF	In various inaccessible areas throughout facility	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
13	Boiler gaskets			Boiler Room	No ACBM	MISC					
14	Interior brick			Throughout Building	No ACBM	MISC					
15	Interior brick mortar			Throughout Building	No ACBM	MISC					
16	Elbow wrap			Boy's Bathroom	No ACBM	MISC					
17	Duct vibration material			Equipment Room	No ACBM	MISC					
18	Exterior brick - Non-AHERA			Exterior of Building	No ACBM	MISC					
19	Exterior brick mortar (Non-AHERA)			Exterior of Building	No ACBM	MISC					
20	Exterior door caulk - Non-AHERA			Building Exterior	No ACBM	MISC					
21	Plaster			Throughout	No ACBM	SURFACE					
22	Green Vinyl Curtain (Cream and Brown)			Gym	No ACBM	MISC					
23	12" x 12" Ceiling Tile			Gym, Room 210	No ACBM	MISC					
24	Brown carpet			1st Floor Office	No ACBM	MISC					
25	Brown carpet adhesive			1st Floor Office	No ACBM	MISC					
26	Black felight door trim			2nd Floor Fan Room	No ACBM	MISC					
28	Roof materials (Non-AHERA)			Roof	Assumed	MISC					Follow O&M Plan
35	12" x 12" Blue Floor Tile	150	SF	Room 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi- Purpose Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35A	12" x 12" Blue Floor Tile Mastic	150	SF	Room 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" x 12" White Floor Tile	2,500	SF	1st & 2nd Floor Hall, Faculty Lounge, 216, 218, 121, 120, 119, 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36A	12" x 12" White Floor Tile Mastic			1st & 2nd Floor Hall, 216, 218, 121, 120, 119, 116	No ACBM	MISC					

Chicago Public Schools

School Murray Academy
Address 5335 S. Kenwood

Unit 29221
Chicago, IL, 60615

Building ID 5030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
37	12" x 12" Yellow Floor Tile	2,500	SF	1st & 2nd Floor Hall, 219, 221, 118, Annex Multi-Purpose Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37A	12" x 12" Yellow Floor Tile Mastic			1st & 2nd Hall, 219, 221, 118, Annex Multi-Purpose Room	No ACBM	MISC					
48	Blue carpet adhesive	400	SF	Office and Principal's Office Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Chalk Board and Poster Board Adhesive	150	SF	All Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12" x 12" Light Beige w/ Brown spots Floor Tile	100	SF	Engineer's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12" x 12" Light Beige w/ Brown spots Floor Tile Mastic	100	SF	engineer's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Duct sealant	5	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Gray terrazzo	250	SF	North Stairs	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" Gray w/ Pink and black Streaks Floor Tile	250	SF	Rooms 202, 201, 206, 208, 205, 207, 210, 107, 108, 105, 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" x 12" Gray w/ Pink and black Streaks Floor Tile Mastic	250	SF	Rooms 202, 201, 206, 208, 205, 207, 210, 107, 108, 105, 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12" x 12" Green w/ Pink and Black Streaks Floor Tile	250	SF	Room 203	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12" x 12" Green w/ Pink and Black Streaks Floor Tile Mastic	250	SF	Room 203	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12" x 12" Dark Gray Mottled Floor Tile	50	SF	Room 205 (patch)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12" x 12" Dark Gray Mottled Floor Tile Mastic	50	SF	Room 205 (patch)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	1' x 1' Ceiling Tile w/ Holes	400	SF	Room 210, Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Cream terrazzo	2,000	SF	East Wing, Park District Annex	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Green terrazzo	250	SF	East Hallway, Park District Annex	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Purple terrazzo	100	SF	East Hallway, Park District Annex	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	2' x 4' Ceiling Tile w/ Divider and Holes	1,300	SF	Faculty Lounge, Library, 218 121, 120, 118, 119, 116m 1130Assistant Principal's Office, 111, Annex Office, Annex Multi-Purpose Room	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
65	Gray sink undercoating	5	SF	Faculty Lounge, 116, 108, 104, Annex Pantry	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	2' x 2' Ceiling Tile w/ Holes	800	SF	Room 213, 216, 219, 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	Brown carpet mastic	1,250	SF	Room 213, Library	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Spray-on insulation	15	LF	Closet 215, Closet 115	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
69	12" x 12" Green Floor Tile	150	SF	Rooms 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Murray Academy
Address 5335 S. Kenwood

Unit 29221
Chicago, IL, 60615

Building ID 5030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
6A	9" x 9" White Floor Tile w/Gray Streaks			Engineer's Office	Chrysotile	MISC					Follow O&M Plan
70	12" x 12" Green Floor Tile Mastic	150	SF	Rooms 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Green linoleum	500	SF	Servery	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Green linoleum mastic	500	SF	Servery	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	2' x 4' Smooth Ceiling Tile	800	SF	Kitchen and Kitchen Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	Epoxy Coating on Floor	800	SF	Kitchen	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	1' x 1' Ceiling Tile w/ Gouges	1,000	SF	Lunch Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	1' x 1' Smooth Ceiling Tile	25	SF	Lunch Room (patches)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Tongue and Groove Wood Floor	1,500	SF	Lunch Room Gym	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	Tan and Green Terrazzo	500	SF	West Stairs	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12" x 12" Light Blue Floor Tile	75	SF	Main Office Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7A	12" x 12" Gray, White & Tan Floor Tile	2,500	SF	1st Floor Corridor, Room 107, & 2nd Floor Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7B	12" x 12" Light Brown Floor Tile w/Dark Brown Streaks			1st & 2nd Floor Corridors - Abated	Abated	MISC					
7C	12" x 12" Dark Gray/Orange w/Black & Tan Streaks Floor Tile	11,825	SF	Rooms 104, 105, 107, 108, 201-203, 205, 206-208, 210, Library, Principal's Office, Teacher's Lunch Room	Chrysotile	MISC	No	155	SF	6 ACBM with the potential for damage	Repair
7D	12" x 12" Beige Floor Tile w/Dark Green Streaks	1,200	SF	Room 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7E	12" x 12" Gray Floor Tile w/White Streaks	2,250	SF	Rooms 103, 204	Chrysotile	MISC	No	5	SF	6 ACBM with the potential for damage	Repair
80	12" x 12" Light Blue Floor Tile Mastic	75	SF	Main Office Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12" x 12" White w/ Green Streaks Floor Tile	500	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12" x 12" White w/ Green Streaks Floor Tile Mastic	500	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12" x 12" Beige Mottled Floor Tile	500	SF	Park District Annex Pantry, Annex Conference Room	Assumed	MISC	No	8	SF	6 ACBM with the potential for damage	Repair
84	12" x 12" Beige Mottled Floor Tile Mastic	500	SF	Park District Annex Pantry, Annex Conference Room	Assumed	MISC	No	8	SF	6 ACBM with the potential for damage	Repair
8A	9" x 9" White Floor Tile w/Gray Streaks Mastic			Engineer's Office	Chrysotile	MISC					Follow O&M Plan
9A	12" x 12" Gray, White & Tan Floor Tile Mastic	260	SF	1st Floor Corridor, Room 107, & Library	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9B	12" x 12" Light Brown Floor Tile w/Dark Brown Streaks Mastic - Abated			1st & 2nd Floor Corridors	Abated	MISC					
9C	12" x 12" Dark Gray/Orange w/Blk & Tan Streaks Floor Tile Mastic	11,825	SF	Rooms 104, 105, 107, and 108, Teacher's Lunch Room, Principal's Office, 201-203, 205-208, Library	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Murray Academy
Address 5335 S. Kenwood

Unit 29221
 Chicago, IL, 60615

Building ID 5030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
9D	12" x 12" Beige Floor Tile w/Dark Green Streaks Mastic	1,200	SF	Room 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9E	12" x 12" Gray Floor Tile w/White Streaks Mastic	1,200	SF	Rooms 204, 103	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Boiler tank insulation			Boiler Room	No ACBM	MISC					
CA	Paperwrap pipe insulation wrap		LF	Boy's Bathroom	Assumed	TSI			LF		Follow O&M Plan
E	Elbow insulation	5	LF	Boy's Bathroom	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
EA	Paperwrap pipe insulation	8	LF	Boy's Bathroom Janitor Closet 1st Floor	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
FA	Cardboard lag	5	LF	Boy's Bathroom	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Murray Academy
Address 5335 S. Kenwood

Unit 29221
 Chicago, IL, 60615

Building ID 5030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	11/18/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
010	
011	
012	
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
28	
35	
35A	

Chicago Public Schools

School Murray Academy
Address 5335 S. Kenwood

Unit 29221
 Chicago, IL, 60615

Building ID 5030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
36	
36A	
37	
37A	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
6A	

Chicago Public Schools

School Murray Academy
Address 5335 S. Kenwood

Unit 29221
 Chicago, IL, 60615

Building ID 5030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
7A	
7B	
7C	
7D	
7E	
80	
81	
82	
83	
84	
8A	
9A	
9B	
9C	
9D	
9E	
A	

Chicago Public Schools

School Murray Academy
Address 5335 S. Kenwood

Unit 29221
Chicago, IL, 60615

Building ID 5030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
CA	
E	
EA	
FA	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **12" x 12" gray w/ black Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **12" x 12" gray w/ black Specks Floor Tile**
MATERIAL LOCATION: **Room 101**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **12" x 12" gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **12" x 12" gray Floor Tile**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **West boys bathroom**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile**
MATERIAL LOCATION: **West boys bathroom**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Paperwrap/aircell pipe insulation wrap**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **In various inaccessible areas throughout facility**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS: **Inaccessible 2022**

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Paperwrap/aircell pipe insulation wrap**
MATERIAL LOCATION: **In various inaccessible areas throughout facility**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Paperwrap/aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **In various inaccessible areas throughout facility**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS: **Inaccessible 2022**

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Paperwrap/aircell pipe insulation**
MATERIAL LOCATION: **In various inaccessible areas throughout facility**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Paperwrap/aircell pipe joint insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **In various inaccessible areas throughout facility**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS: **Inaccessible 2022**

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Paperwrap/aircell pipe joint insulation**
MATERIAL LOCATION: **In various inaccessible areas throughout facility**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Boiler gaskets**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Boiler gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Interior brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Interior brick**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Interior brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Interior brick mortar**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Elbow wrap**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boy's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Elbow wrap**

MATERIAL LOCATION: **Boy's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Duct vibration material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Equipment Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Duct vibration material**

MATERIAL LOCATION: **Equipment Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Exterior brick mortar (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Exterior brick mortar (Non-AHERA)**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Exterior door caulk - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Exterior door caulk - Non-AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Green Vinyl Curtain (Cream and Brown)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Green Vinyl Curtain (Cream and Brown)**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym, Room 210**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12" x 12" Ceiling Tile**

MATERIAL LOCATION: **Gym, Room 210**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Brown carpet**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Brown carpet**

MATERIAL LOCATION: **1st Floor Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Brown carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Brown carpet adhesive**

MATERIAL LOCATION: **1st Floor Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Black felight door trim**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Black felight door trim**

MATERIAL LOCATION: **2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Roof materials (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Roof materials (Non-AHERA)**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi- Purpose Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2022**

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **Room 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi- Purpose Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35A**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2022**

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **35A**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **Room 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Hall, Faculty Lounge, 216, 218, 121, 120, 119, 116**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **1st & 2nd Floor Hall, Faculty Lounge, 216, 218, 121, 120, 119, 116**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36A**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Hall, 216, 218, 121, 120, 119, 116**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **36A**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
MATERIAL LOCATION: **1st & 2nd Floor Hall, 216, 218, 121, 120, 119, 116**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Hall, 219, 221, 118, Annex Multi-Purpose Room**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**
MATERIAL LOCATION: **1st & 2nd Floor Hall, 219, 221, 118, Annex Multi-Purpose Room**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37A**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Hall, 219, 221, 118, Annex Multi-Purpose Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **37A**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**

MATERIAL LOCATION: **1st & 2nd Hall, 219, 221, 118, Annex Multi-Purpose Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Blue carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office and Principal's Office Room 200**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Blue carpet adhesive**
MATERIAL LOCATION: **Office and Principal's Office Room 200**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Chalk Board and Poster Board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Classrooms**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Chalk Board and Poster Board Adhesive**
MATERIAL LOCATION: **All Classrooms**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Brown spots Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Brown spots Floor Tile**
MATERIAL LOCATION: **Engineer's office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Brown spots Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **engineer's office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Brown spots Floor Tile Mastic**
MATERIAL LOCATION: **engineer's office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **6A**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Gray Streaks**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7A**
MATERIAL DESCRIPTION: **12" x 12" Gray, White & Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor, Room 107, & 2nd Floor Library**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **7A**
MATERIAL DESCRIPTION: **12" x 12" Gray, White & Tan Floor Tile**
MATERIAL LOCATION: **1st Floor Corridor, Room 107, & 2nd Floor Library**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7B**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Dark Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **7B**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Dark Brown Streaks**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7C**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray/Orange w/Black & Tan Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 104, 105, 107, 108, 201-203, 205, 206-208, 210, Library, Principal's Office, Teacher's Lunch Room**
MATERIAL QUANTITY: **11825** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **11825** DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 104 (30SF), Room 203 (50 SF), Room 205 (75 SF)**

Inspector's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **7C**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray/Orange w/Black & Tan Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 104, 105, 107, 108, 201-203, 205, 206-208, 210, Library, Principal's Office, Teacher's Lunch Room**
MATERIAL QUANTITY: **11825** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **155** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7D**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Dark Green Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **7D**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Dark Green Streaks**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7E**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 103, 204**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2250** DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 204 (5 SF)**

Inspector's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **7E**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Streaks**

MATERIAL LOCATION: **Rooms 103, 204**

MATERIAL QUANTITY: **2250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8A**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **8A**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Gray Streaks Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9A**
MATERIAL DESCRIPTION: **12" x 12" Gray, White & Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor, Room 107, & Library**

MATERIAL QUANTITY: **260**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **9A**
MATERIAL DESCRIPTION: **12" x 12" Gray, White & Tan Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor, Room 107, & Library**
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9B**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Dark Brown Streaks Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **9B**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Dark Brown Streaks Mastic - Abated**

MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9C**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray/Orange w/Blk & Tan Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 104, 105, 107, and 108, Teacher's Lunch Room, Principal's Office, 201-203, 205-208, Library**

MATERIAL QUANTITY: **11825**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **9C**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray/Orange w/Blk & Tan Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 104, 105, 107, and 108, Teacher's Lunch Room, Principal's Office, 201-203, 205-208, Library**
MATERIAL QUANTITY: **11825** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9D**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Dark Green Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **9D**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Dark Green Streaks Mastic**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9E**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 204, 103**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in room 103**

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **9E**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Streaks Mastic**
MATERIAL LOCATION: **Rooms 204, 103**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Boiler tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler tank insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CA**
MATERIAL DESCRIPTION: **Paperwrap pipe insulation wrap**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boy's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **CA**

MATERIAL DESCRIPTION: **Paperwrap pipe insulation wrap**

MATERIAL LOCATION: **Boy's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Elbow insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boy's Bathroom**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Elbow insulation**
MATERIAL LOCATION: **Boy's Bathroom**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EA**
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boy's Bathroom Janitor Closet 1st Floor**

MATERIAL QUANTITY: **8** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **8** DAMAGE UNITS: **LF**

COMMENTS: **Inaccessible 2022**

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **EA**
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**
MATERIAL LOCATION: **Boy's Bathroom Janitor Closet 1st Floor**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA**
MATERIAL DESCRIPTION: **Cardboard lag**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boy's Bathroom**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **FA**
MATERIAL DESCRIPTION: **Cardboard lag**
MATERIAL LOCATION: **Boy's Bathroom**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Duct sealant**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Kenneth Karuhn

Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Duct sealant**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Pink and black Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 202, 201, 206, 208, 205, 207, 210, 107, 108, 105, 104**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**

ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile w/ Divider and Holes**

MATERIAL LOCATION: **Faculty Lounge, Library, 218 121, 120, 118, 119, 116m 1130Assistant Principal's Office, 111, Annex Office, Annex Multi-Purpose Room**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Gray sink undercoating**
MATERIAL LOCATION: **Faculty Lounge, 116, 108, 104, Annex Pantry**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form


LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Gray sink undercoating**
MATERIAL LOCATION: **Faculty Lounge, 116, 108, 104, Annex Pantry**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Gray terrazzo**
MATERIAL LOCATION: **North Stairs**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **SURFACE** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Gray terrazzo**
MATERIAL LOCATION: **North Stairs**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Pink and black Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 202, 201, 206, 208, 205, 207, 210, 107, 108, 105, 104**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Kenneth Karuhn

Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Pink and black Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 202, 201, 206, 208, 205, 207, 210, 107, 108, 105, 104**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile w/ Holes**
MATERIAL LOCATION: **Room 210, Lunchroom**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Kenneth Karuhn

Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile w/ Holes**
MATERIAL LOCATION: **Room 210, Lunchroom**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile w/ Holes**
MATERIAL LOCATION: **Room 213, 216, 219, 221**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **Epoxy Coating on Floor**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **SURFACE** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **Epoxy Coating on Floor**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **Tan and Green Terrazzo**
MATERIAL LOCATION: **West Stairs**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12" x 12" Beige Mottled Floor Tile**
MATERIAL LOCATION: **Park District Annex Pantry, Annex Conference Room**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **8** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in Annex Pantry

Inspector's Signature:



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12" x 12" Beige Mottled Floor Tile**
MATERIAL LOCATION: **Park District Annex Pantry, Annex Conference Room**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mottled Floor Tile Mastic**
MATERIAL LOCATION: **Room 205 (patch)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Brown carpet mastic**
MATERIAL LOCATION: **Room 213, Library**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **SURFACE** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Brown carpet mastic**
MATERIAL LOCATION: **Room 213, Library**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12" x 12" White w/ Green Streaks Floor Tile**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Kenneth Karuhn

Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **12" x 12" White w/ Green Streaks Floor Tile**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **12" x 12" White w/ Green Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Kenneth Karuhn

Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **12" x 12" White w/ Green Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Rooms**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Kenneth Karuhn

Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Rooms**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile w/ Gouges**
MATERIAL LOCATION: **Lunch Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Kenneth Karuhn

Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile w/ Gouges**
MATERIAL LOCATION: **Lunch Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Purple terrazzo**
MATERIAL LOCATION: **East Hallway, Park District Annex**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **SURFACE** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Purple terrazzo**
MATERIAL LOCATION: **East Hallway, Park District Annex**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**
MATERIAL LOCATION: **Rooms 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Rooms**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**
MATERIAL LOCATION: **Rooms 219, 221, 218, 121, 120, 118, 119, 116, Annex Multi-Purpose Rooms**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Green linoleum**
MATERIAL LOCATION: **Servery**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Green linoleum**
MATERIAL LOCATION: **Servery**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tile**
MATERIAL LOCATION: **Lunch Room (patches)**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Kenneth Karuhn

Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form


LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tile**
MATERIAL LOCATION: **Lunch Room (patches)**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUIDLING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile**
MATERIAL LOCATION: **Main Office Bathroom**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile**
MATERIAL LOCATION: **Main Office Bathroom**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	11/1/2022		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-07278		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	80			
MATERIAL DESCRIPTION:	12" x 12" Light Blue Floor Tile Mastic			
MATERIAL LOCATION:	Main Office Bathroom			
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
		DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile Mastic**
MATERIAL LOCATION: **Main Office Bathroom**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12" x 12" Green w/ Pink and Black Streaks Floor Tile**
MATERIAL LOCATION: **Room 203**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12" x 12" Green w/ Pink and Black Streaks Floor Tile**
MATERIAL LOCATION: **Room 203**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Green linoleum mastic**
MATERIAL LOCATION: **Servery**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Green linoleum mastic**
MATERIAL LOCATION: **Servery**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**
MATERIAL LOCATION: **Kitchen and Kitchen Office**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**
MATERIAL LOCATION: **Kitchen and Kitchen Office**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mottled Floor Tile**
MATERIAL LOCATION: **Room 205 (patch)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mottled Floor Tile**
MATERIAL LOCATION: **Room 205 (patch)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Green terrazzo**
MATERIAL LOCATION: **East Hallway, Park District Annex**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **SURFACE** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Green terrazzo**
MATERIAL LOCATION: **East Hallway, Park District Annex**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Spray-on insulation**
MATERIAL LOCATION: **Closet 215, Closet 115**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **TSI** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Spray-on insulation**
MATERIAL LOCATION: **Closet 215, Closet 115**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Tongue and Groove Wood Floor**
MATERIAL LOCATION: **Lunch Room Gym**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **SURFACE** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **11/01/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Tongue and Groove Wood Floor**
MATERIAL LOCATION: **Lunch Room Gym**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" Beige Mottled Floor Tile Mastic**
MATERIAL LOCATION: **Park District Annex Pantry, Annex Conference Room**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **8** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in Annex Pantry

Inspector's Signature:



Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" Beige Mottled Floor Tile Mastic**
MATERIAL LOCATION: **Park District Annex Pantry, Annex Conference Room**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" Green w/ Pink and Black Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 203**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Kenneth Karuhn

Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12" x 12" Green w/ Pink and Black Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Murray Academy** INSPECTION DATE: **11/1/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Cream terrazzo**
MATERIAL LOCATION: **East Wing, Park District Annex**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **SURFACE** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Kenneth Karuhn

Date: 11/01/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29221** BUILDING ID: **5030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Murray Academy** REVIEW DATE: **11/18/2022**
ADDRESS: **5335 S. Kenwood** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Cream terrazzo**
MATERIAL LOCATION: **East Wing, Park District Annex**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Kenneth Karuhn

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/9/2022

Exam Date: 9/9/2022

Expiration Date: 9/9/2023

Certificate Number: BIR2209092154

Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 07278

ISSUED
4/15/2022

EXPIRES
05/15/2023

KENNETH A KARUHN
600 W VAN BUREN ST., STE 5
CHICAGO, IL 60607

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL

10/9/2022

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Kenneth Karuhn

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082269

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

**EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622**

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed