

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2086  
SCHOOL NAME: Black Magnet  
ADDRESS OF SCHOOL: 9101 S Euclid Avenue  
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/21/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 7/20/2022 ENROLLMENT 385

IDPH INSPECTOR LICENSE NUMBER: 100-18281

IDPH LICENSED INSPECTOR NAME (Please Print): Christopher Antonopoulos

IDPH MP LICENSE NUMBER: 100-09870

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

8/12/2022

*Richard J. Schleyer*

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Black Magnet**

9101 S Euclid Avenue  
Chicago, IL, 60617

Unit: 29381  
Building ID: 7860

IDPH ID Number: 14-016-2990-2086

**REPORT DATE:**

Friday, August 12, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

08/12/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 29381            Region: 06            IDPH ID: 14-016-2990-2086

School: Black Magnet            Building ID: 7860

Address: 9101 S Euclid Avenue

Chicago, IL, 60617

Building Contact: Gonzalez, Cecilia

Contact Phone: 7737097028

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/20/2022

Review Date: 08/12/2022

Inspector: Christopher Antonopoulos

Inspector IDPH License: 100-18281

Management Planner: Todd Huffer

Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Todd Huffer  
100-09870

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 12, 2022

RE: Black Magnet, Unit 29381  
9101 S Euclid Avenue  
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Black Magnet , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Black Magnet, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Black Magnet  
Address: 9101 S Euclid Avenue  
IDPH ID: 14-016-2990-2086  
Contact: Gonzalez, Cecilia

Unit: 29381  
Chicago, IL, 60617  
Building ID: 7860  
Phone: 7737097028

Region: 06

### 2. Description of Facility

Original Construction: 1956  
Total Square Footage: 4290  
Current Occupancy: 385

Additional Construction: 1959  
No of Floors: 1

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant


MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Christopher Antonopoulos


Inspector IDPH license # 100-18281  
Reinspection Date: 7/20/2022

  
Signature:  
Date: 7/20/2022

### 6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870


  
Signature:  
Date: 08/12/2022

### 7. Review Date: 08/12/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 8/12/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Black Magnet. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7860:

31	1'x1' Ceiling Tile
46	12x12 Black, White & Grey Floor Tile
46A	12x12 Black, White & Grey Floor Tile Mastic
47	Wood Patterned Linoleum
E	Aircell Pipe Insulation
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 7860:

47	Wood Patterned Linoleum
48	12"x12" Brown and White Floor Tile - Abated
49	Mastic associated with 12" Brown and White Floor Tile
NEW	Newly Installed Suspect ACM



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

09B	12x12 Brown w/Cream Floor Tile
09C	12x12 Beige w/Tan Specks Floor Tile
09D	12x12 White w/Tan Specks Floor Tile
09E	12x12 Light Brown w/Tan Specks Floor Tile
09G	12x12 Brown Speckled Floor Tile
11C	9x9 Light Brown Floor Tile Mastic
11D	9x9 Cream w/Dark Brown Streaks Floor Tile Mastic
12B	12x12 Brown w/Cream Floor Tile Mastic
12C	12x12 Beige w/Tan Speckles Floor Tile Mastic
12D	12x12 White w/Tan Specks Floor Tile Mastic
12E	12x12 Light Brown w/Tan Specks Floor Tile Mastic
25	12x12 Tan w/Cream & Dark Brown Speckles Floor Tile
26	12x12 Tan w/Cream and Dark Brown Specks Floor Tile Mastic
27	9x9 Beige w/Brown Streaks Floor Tile
27A	9x9 Brown w/Cream Streaks Floor Tile
27B	9x9 Gray w/Black & White Specks Floor Tile
27C	9x9 Light Brown w/Dark Brown Streaks Floor Tile
28	9x9 Beige w/Brown Streaks Floor Tile Mastic
28A	9x9 Brown w/Cream Streaks Floor Tile Mastic
28C	9x9 Light Brown with Dark Brown Streaks Floor Tile Mastic
29	Red Carpet Mastic
29A	Maroon Carpet Mastic
30	Beige Terrazzo
31	1'x1' Ceiling Tile
32	2'x2' Ceiling Tile
33	2'x4' Ceiling Tile
34	12x12 Beige Cream & Tan Speckled Floor Tile
35	12x12 Beige, Cream & Tan Speckled Floor Tile Mastic
36	12x12 Tan w/Cream Speckles Floor Tile
37	12x12 Tan w/Cream Speckles Floor Tile Mastic
38	Brown, Cream and Beige Ceramic Tile Grout
39	Stair Tread
40	Stair Tread Mastic
41	12x12 Tan Speckled Floor Tile
42	12x12 Tan Speckled Floor Tile Mastic
43	Green Ceramic Tile Grout
44	12x12 Beige w/Tan Streaks Floor Tile
45	12x12 Beige w/Tan Streaks Floor Tile mastic

46	12x12 Black, White & Grey Floor Tile
46A	12x12 Black, White & Grey Floor Tile Mastic
47	Wood Patterned Linoleum
B	9x9 Brown w/Red Streaks Floor Tile
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

04	Scratch Coat Plaster No ACBM
12C	12x12 Beige w/Tan Speckles Floor Tile Mastic
12D	12x12 White w/Tan Specks Floor Tile Mastic
12E	12x12 Light Brown w/Tan Specks Floor Tile Mastic
12G	12x12 Brown Speckled Floor Tile Mastic
20	9x9 Brown w/Cream Speckles Floor Tile Mastic
26	12x12 Tan w/Cream and Dark Brown Specks Floor Tile Mastic
28D	9x9 Brown w/Red Streaks Floor Tile Mastic
29	Red Carpet Mastic
29A	Maroon Carpet Mastic
32	2'x2' Ceiling Tile
35	12x12 Beige, Cream & Tan Speckled Floor Tile Mastic
37	12x12 Tan w/Cream Speckles Floor Tile Mastic
40	Stair Tread Mastic
42	12x12 Tan Speckled Floor Tile Mastic
45	12x12 Beige w/Tan Streaks Floor Tile mastic
E	Aircell Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Christopher Antonopoulos, IDPH License # 100-18281. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Black Magnet Building 7860 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Black Magnet Unit 29381 Building ID 7860

Address 9101 S Euclid Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Acoustical Plaster	13,975	SF	Stage, Auditorium and Teachers' Lounge	CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
02	Acoustical Plaster	8,800	SF	Classrooms, Offices, Main Entrance	CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
04	Scratch Coat Plaster No ACBM			Classrooms, Offices and Main Entrance	NO_ACBM	SURFACE								
05	Scratch Coat Plaster No ACBM			Classrooms, Stage and Auditorium	NO_ACBM	SURFACE								
09A	12x12 Orange w/Cream Speckles Floor Tile			Room 103		MISC		None						
09B	12x12 Brown w/Cream Floor Tile	550	SF	Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09C	12x12 Beige w/Tan Specks Floor Tile	800	SF	Auditorium, Kitchen and Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09D	12x12 White w/Tan Specks Floor Tile	400	SF	Rooms 100W and 100E, Locker Room and Outside Engineer's Office, & Entry Area 7	ASSUMED	MISC	N	DIST	126		No	ACBM with potential for significant damage	5	MODERATE
09E	12x12 Light Brown w/Tan Specks Floor Tile	41	SF	Locker Room & Adjacent Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09F	12x12 White w/Brown Specks Floor Tile			Room 112		MISC		None						Moderate
09G	12x12 Brown Speckled Floor Tile	418	SF	Computer Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10A	9x9 Light Brown w/Green Floor Tile			Rooms 102-111		MISC		None						Low
10B	9x9 Light and Dark Brown Floor Tile ABATED			Room 104	ABATED	MISC								
10C	9x9 Light Brown Floor Tile			Room 108 and Additional Building		MISC		None						Low
10D	9x9 Cream with Dark Brown Streaks Floor Tile			Room 103		MISC		None						Low
11A	9x9 Brown w/Green Floor Tile Mastic			Rooms 102-111		MISC		None						Low
11B	9x9 Light & Dark Brown Floor Tile Mastic			Room 104	ABATED	MISC								
11C	9x9 Light Brown Floor Tile Mastic			Room 108 and Additional Building	ASSUMED	MISC		None						Low
11D	9x9 Cream w/Dark Brown Streaks Floor Tile Mastic			Room 103	ASSUMED	MISC		None						Low
12A	12x12 Orange w/Cream Speckles Floor Tile Mastic			Room 103		MISC		None						Low
12B	12x12 Brown w/Cream Floor Tile Mastic	550	SF	Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12C	12x12 Beige w/Tan Speckles Floor Tile Mastic	800	SF	Auditorium, Kitchen and Corridor	ASSUMED	MISC	N	None	0		No	ACBM with the potential for damage		LOW
12D	12x12 White w/Tan Specks Floor Tile	400	SF	Rooms 100W and	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Black Magnet Unit 29381 Building ID 7860

Address 9101 S Euclid Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Mastic			100E, Locker Room and Outside Engineer's Office								potential for damage		
12E	12x12 Light Brown w/Tan Specks Floor Tile Mastic	41	SF	Locker Room and Adjacent Corridor, Entry Door 7	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12F	12x12 White w/Brown Specks Floor Tile Mastic			Room 112		MISC		None						Low
12G	12x12 Brown Speckled Floor Tile Mastic	418	SF	Computer Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Vinyl Baseboard			Throughout Main Building	NO_ACBM	MISC								
14	Vinyl Baseboard Mastic			Throughout Main Building	NO_ACBM	MISC								
19	9x9 Brown & Cream Speckles Floor Tile	1,000	SF	1957 Addition Building- Stage, Teachers' Lounge Storages and NE Stairway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	9x9 Brown w/Cream Speckles Floor Tile Mastic	1,000	SF	1957 Addition Building- Stage, Teachers' Lounge Storages and the NE Stairway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Vinyl Baseboard			1957 Addition Building	NO_ACBM	MISC								
21A	Vinyl Baseboard			Locker Room 100M-S and Room 112	NO_ACBM	MISC								
22	Vinyl Baseboard Mastic			1957 Addition Building	NO_ACBM	MISC								
22A	Vinyl Baseboard Mastic			Locker Room 100M-S and Room 112	NO_ACBM	MISC								
23	Acoustical Plaster			1957 Addition Building	NO_ACBM	SURFACE								
24	Scratch Coat Plaster			1957 Addition Building	NO_ACBM	SURFACE								
25	12x12 Tan w/Cream & Dark Brown Speckles Floor Tile	800	SF	1957 Addition Building- Main Office, Coat Room, Principal's Office and Storage across from Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Black Magnet Unit 29381 Building ID 7860

Address 9101 S Euclid Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
26	12x12 Tan w/Cream and Dark Brown Specks Floor Tile Mastic	800	SF	1957 Addition Building- Main Office, Coat Room, Principal's Office and the Storage across from Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	9x9 Beige w/Brown Streaks Floor Tile			Principal's Office	ASSUMED	MISC		None						Low
27A	9x9 Brown w/Cream Streaks Floor Tile			Principal's Office	ASSUMED	MISC		None						Low
27B	9x9 Gray w/Black & White Specks Floor Tile			Kitchen	ASSUMED	MISC		None						Low
27C	9x9 Light Brown w/Dark Brown Streaks Floor Tile	900	SF	Room 101	ASSUMED	MISC		NONE	0					Low
27D	9x9 Brown w/Red Streaks Floor Tile	28	SF	Custodial Staff Break Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	9x9 Beige w/Brown Streaks Floor Tile Mastic			Principal's Office	ASSUMED	MISC		None						Low
28A	9x9 Brown w/Cream Streaks Floor Tile Mastic			Principal's Office	ASSUMED	MISC								
28B	9x9 Gray w/Black & White Specks Floor Tile Mastic ABATED			Kitchen	ABATED	MISC								
28C	9x9 Light Brown with Dark Brown Streaks Floor Tile Mastic			Room 101 - NOT OBSERVED	ASSUMED	MISC		None						Low
28D	9x9 Brown w/Red Streaks Floor Tile Mastic	28	SF	Custodial Staff Break Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Red Carpet Mastic	144	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29A	Maroon Carpet Mastic	26	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	Beige Terrazzo	3,000	SF	Main Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	1'x1' Ceiling Tile	1,750	SF	Art Room	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
32	2'x2' Ceiling Tile	10,000	SF	Gym	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
33	2'x4' Ceiling Tile	8,700	SF	Corridor, Classrooms	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
34	12x12 Beige Cream & Tan Speckled Floor Tile	500	SF	Teachers' Lounge and Room 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12x12 Beige, Cream & Tan Speckled Floor Tile Mastic	500	SF	Teachers' Lounge and Room 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12x12 Tan w/Cream Speckles Floor Tile	3,000	SF	East Vestibule and Gym	ASSUMED	MISC	N	DIST	35		No	ACBM with the potential for damage	5	MODERATE
37	12x12 Tan w/Cream Speckles Floor Tile	3,000	SF	East Vestibule and	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Black Magnet Unit 29381 Building ID 7860

Address 9101 S Euclid Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Mastic			Gym								potential for damage		
38	Brown, Cream and Beige Ceramic Tile Grout	750	SF	North and South Men's Washroom, North Women's Washroom, and Art Room Men's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Stair Tread	25	SF	Stairs near Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Stair Tread Mastic	25	SF	Stairs near Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	12x12 Tan Speckled Floor Tile	5,300	SF	Rooms 101 and 103-114	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12x12 Tan Speckled Floor Tile Mastic	5,300	SF	Rooms 101 and 103-114	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Green Ceramic Tile Grout	200	SF	South Women's Washroom and Art Room Women's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	12x12 Beige w/Tan Streaks Floor Tile	200	SF	Storage and Vestibule Outside Fan Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12x12 Beige w/Tan Streaks Floor Tile mastic	200	SF	Storage Vestibule Outside Fan Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12x12 Black, White & Grey Floor Tile	1,000	SF	Basement Drama Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
46A	12x12 Black, White & Grey Floor Tile Mastic	1,000	SF	Basement Drama Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
47	Wood Patterned Linoleum	1,000	SF	Teachers' Lounge & Library	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
48	12"x12" Brown and White Floor Tile - Abated			Custodial Staff Breakroom	ABATED	MISC								
49	Mastic associated with 12" Brown and White Floor Tile			Custodial Staff Breakroom	ABATED	MISC								
B	9x9 Brown w/Red Streaks Floor Tile			Mechanical Areas and Fan Rooms	ASSUMED	MISC		None						Low
E	Aircell Pipe Insulation	30	LF	Mechanical Areas, Fan Rooms and Storage Area in the Basement and the Art Room	CHR	TSI	Y	LOC	5		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
F	MJP E/F/V on Aircell Pipe Insulation	300	LF	Mechanical Areas, Fan Rooms and Storage Area in the	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Black Magnet Unit 29381 Building ID 7860

Address 9101 S Euclid Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Basement and the Art Room										
G	MJP E/F/V on Fiberglass Pipe Insulation	20	LF	1957 Addition	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	MJP E/F/V on Mag Block Pipe Insulation	100	LF	Mechanical Areas and Meter Room	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

# Chicago Public Schools

School Black Magnet Unit 29381 Building ID 7860

Address 9101 S Euclid Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>7/20/2022</b>
Inspector Name <b>Christopher Antonopoulos</b>
<b>100-18281</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
04	
05	
09A	Not Observed 2019 & 2022
09B	
09C	
09D	
09E	
09F	Not Observed 2019 & 2022
09G	
10A	Not Observed 2019 & 2022
10B	
10C	Not Observed 2019 & 2022
10D	Not Observed 2019 & 2022
11A	Not Observed 2019 & 2022
11B	
11C	Not Observed 2019 & 2022
11D	Not Observed 2019 & 2022
12A	Not Observed 2019 & 2022
12B	
12C	
12D	
12E	

# Chicago Public Schools

School Black Magnet Unit 29381 Building ID 7860

Address 9101 S Euclid Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
12F	Not Observed 2019 & 2022
12G	
13	
14	
19	Not Observed in Teachers' Lounge. New HA
20	Not Observed in Teachers' Lounge. New HA
21	
21A	
22	
22A	
23	
24	
25	
26	
27	Not Observed 2019
27A	Not Observed 2019 & 2022. New HA
27B	Not Observed 2019 & 2022
27C	Not Observed 2019 & 2022
27D	Not Observed 2022. New HA
28	Not Observed 2019 & 2022
28A	Not Observed 2019 & 2022
28B	Not Observed 2019 & 2022
28C	Not Observed 2019 & 2022
28D	Not Observed 2022. New HA
29	
29A	
30	
31	
32	

# Chicago Public Schools

School Black Magnet Unit 29381 Building ID 7860

Address 9101 S Euclid Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
33	
34	Not Observed in Teachers' Lounge 2022
35	Not Observed in Teachers' Lounge 2022
36	Damage in Gym
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
46A	
47	
48	
49	
B	Not Observed 2019 & 2022
E	
F	
G	
H	
NEW	

# Chicago Public Schools

**School** Black Magnet **Unit** 29381 **Building ID** 7860

**Address** 9101 S Euclid Avenue **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Black Magnet  
Address 9101 S Euclid Avenue

Unit 29381  
Chicago, IL, 60617

Building ID 7860  
Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Acoustical Plaster	13,975	SF	Stage, Auditorium and Teachers' Lounge	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	Acoustical Plaster	8,800	SF	Classrooms, Offices, Main Entrance	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	Scratch Coat Plaster No ACBM			Classrooms, Offices and Main Entrance	No ACBM	SURFACE					
05	Scratch Coat Plaster No ACBM			Classrooms, Stage and Auditorium	No ACBM	SURFACE					
09A	12x12 Orange w/Cream Speckles Floor Tile			Room 103		MISC					
09B	12x12 Brown w/Cream Floor Tile	550	SF	Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09C	12x12 Beige w/Tan Specks Floor Tile	800	SF	Auditorium, Kitchen and Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09D	12x12 White w/Tan Specks Floor Tile	400	SF	Rooms 100W and 100E, Locker Room and Outside Engineer's Office, & Entry Area 7	Assumed	MISC	No	126	SF	5 ACBM with potential for significant damage	Repair
09E	12x12 Light Brown w/Tan Specks Floor Tile	41	SF	Locker Room & Adjacent Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09F	12x12 White w/Brown Specks Floor Tile			Room 112		MISC					
09G	12x12 Brown Speckled Floor Tile	418	SF	Computer Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	9x9 Light Brown w/Green Floor Tile			Rooms 102-111		MISC					
10B	9x9 Light and Dark Brown Floor Tile ABATED			Room 104	Abated	MISC					
10C	9x9 Light Brown Floor Tile			Room 108 and Additional Building		MISC					
10D	9x9 Cream with Dark Brown Streaks Floor Tile			Room 103		MISC					
11A	9x9 Brown w/Green Floor Tile Mastic			Rooms 102-111		MISC					
11B	9x9 Light & Dark Brown Floor Tile Mastic			Room 104	Abated	MISC					
11C	9x9 Light Brown Floor Tile Mastic			Room 108 and Additional Building	Assumed	MISC					
11D	9x9 Cream w/Dark Brown Streaks Floor Tile Mastic			Room 103	Assumed	MISC					
12A	12x12 Orange w/Cream Speckles Floor Tile Mastic			Room 103		MISC					
12B	12x12 Brown w/Cream Floor Tile Mastic	550	SF	Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12C	12x12 Beige w/Tan Speckles Floor Tile Mastic	800	SF	Auditorium, Kitchen and Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12D	12x12 White w/Tan Specks Floor Tile Mastic	400	SF	Rooms 100W and 100E, Locker Room and Outside Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12E	12x12 Light Brown w/Tan Specks Floor Tile Mastic	41	SF	Locker Room and Adjacent Corridor, Entry Door 7	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12F	12x12 White w/Brown Specks Floor Tile Mastic			Room 112		MISC					
12G	12x12 Brown Speckled Floor Tile Mastic	418	SF	Computer Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Vinyl Baseboard			Throughout Main Building	No ACBM	MISC					
14	Vinyl Baseboard Mastic			Throughout Main Building	No ACBM	MISC					
19	9x9 Brown & Cream Speckles Floor Tile	1,000	SF	1957 Addition Building- Stage, Teachers' Lounge Storages and NE	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Black Magnet  
Address 9101 S Euclid Avenue

Unit 29381  
Chicago, IL, 60617

Building ID 7860  
Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
20	9x9 Brown w/Cream Speckles Floor Tile Mastic	1,000	SF	Stairway 1957 Addition Building- Stage, Teachers' Lounge Storages and the NE Stairway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Vinyl Baseboard			1957 Addition Building	No ACBM	MISC					
21A	Vinyl Baseboard			Locker Room 100M-S and Room 112	No ACBM	MISC					
22	Vinyl Baseboard Mastic			1957 Addition Building	No ACBM	MISC					
22A	Vinyl Baseboard Mastic			Locker Room 100M-S and Room 112	No ACBM	MISC					
23	Acoustical Plaster			1957 Addition Building	No ACBM	SURFACE					
24	Scratch Coat Plaster			1957 Addition Building	No ACBM	SURFACE					
25	12x12 Tan w/Cream & Dark Brown Speckles Floor Tile	800	SF	1957 Addition Building- Main Office, Coat Room, Principal's Office and Storage across from Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12x12 Tan w/Cream and Dark Brown Specks Floor Tile Mastic	800	SF	1957 Addition Building- Main Office, Coat Room, Principal's Office and Storage across from Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	9x9 Beige w/Brown Streaks Floor Tile			Principal's Office	Assumed	MISC					
27A	9x9 Brown w/Cream Streaks Floor Tile			Principal's Office	Assumed	MISC					
27B	9x9 Gray w/Black & White Specks Floor Tile			Kitchen	Assumed	MISC					
27C	9x9 Light Brown w/Dark Brown Streaks Floor Tile	900	SF	Room 101	Assumed	MISC		0	SF		
27D	9x9 Brown w/Red Streaks Floor Tile	28	SF	Custodial Staff Break Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
28	9x9 Beige w/Brown Streaks Floor Tile Mastic			Principal's Office	Assumed	MISC					
28A	9x9 Brown w/Cream Streaks Floor Tile Mastic			Principal's Office	Assumed	MISC					
28B	9x9 Gray w/Black & White Specks Floor Tile Mastic ABATED			Kitchen	Abated	MISC					
28C	9x9 Light Brown with Dark Brown Streaks Floor Tile Mastic			Room 101 - NOT OBSERVED	Assumed	MISC					
28D	9x9 Brown w/Red Streaks Floor Tile Mastic	28	SF	Custodial Staff Break Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
29	Red Carpet Mastic	144	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29A	Maroon Carpet Mastic	26	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Beige Terrazzo	3,000	SF	Main Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	1'x1' Ceiling Tile	1,750	SF	Art Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
32	2'x2' Ceiling Tile	10,000	SF	Gym	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	2'x4' Ceiling Tile	8,700	SF	Corridor, Classrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan



# Chicago Public Schools

**School** Black Magnet  
**Address** 9101 S Euclid Avenue

**Unit** 29381  
Chicago, IL, 60617

**Building ID** 7860  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
34	12x12 Beige Cream & Tan Speckled Floor Tile	500	SF	Teachers' Lounge and Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12x12 Beige, Cream & Tan Speckled Floor Tile Mastic	500	SF	Teachers' Lounge and Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12x12 Tan w/Cream Speckles Floor Tile	3,000	SF	East Vestibule and Gym	Assumed	MISC	No	35	SF	6 ACBM with the potential for damage	Repair
37	12x12 Tan w/Cream Speckles Floor Tile Mastic	3,000	SF	East Vestibule and Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Brown, Cream and Beige Ceramic Tile Grout	750	SF	North and South Men's Washroom, North Women's Washroom, and Art Room Men's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Stair Tread	25	SF	Stairs near Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Stair Tread Mastic	25	SF	Stairs near Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12x12 Tan Speckled Floor Tile	5,300	SF	Rooms 101 and 103-114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12x12 Tan Speckled Floor Tile Mastic	5,300	SF	Rooms 101 and 103-114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Green Ceramic Tile Grout	200	SF	South Women's Washroom and Art Room Women's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12x12 Beige w/Tan Streaks Floor Tile	200	SF	Storage and Vestibule Outside Fan Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12x12 Beige w/Tan Streaks Floor Tile mastic	200	SF	Storage Vestibule Outside Fan Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12x12 Black, White & Grey Floor Tile	1,000	SF	Basement Drama Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46A	12x12 Black, White & Grey Floor Tile Mastic	1,000	SF	Basement Drama Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Wood Patterned Linoleum	1,000	SF	Teachers' Lounge & Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12"x12" Brown and White Floor Tile - Abated			Custodial Staff Breakroom	Abated	MISC					
49	Mastic associated with 12" Brown and White Floor Tile			Custodial Staff Breakroom	Abated	MISC					
B	9x9 Brown w/Red Streaks Floor Tile			Mechanical Areas and Fan Rooms	Assumed	MISC					
E	Aircell Pipe Insulation	30	LF	Mechanical Areas, Fan Rooms and Storage Area in the Basement and the Art Room	Chrysotile	TSI	Yes	5	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
F	MJP E/F/V on Aircell Pipe Insulation	300	LF	Mechanical Areas, Fan Rooms and Storage Area in the Basement and the Art Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
G	MJP E/F/V on Fiberglass Pipe Insulation	20	LF	1957 Addition	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	MJP E/F/V on Mag Block Pipe Insulation	100	LF	Mechanical Areas and Meter Room	Chrysotile	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Black Magnet  
**Address** 9101 S Euclid Avenue

**Unit** 29381  
Chicago, IL, 60617

**Building ID** 7860  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	8/12/2022
Manager Planner Name	Todd Huffer
100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
04	
05	
09A	Material not observed in 2019 & 2022
09B	
09C	

# Chicago Public Schools

**School** Black Magnet  
**Address** 9101 S Euclid Avenue

**Unit** 29381  
 Chicago, IL, 60617

**Building ID** 7860  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
09D	Repair and follow O&M
09E	
09F	Not Observed 2019 & 2022
09G	
10A	Not Observed 2019 & 2022
10B	
10C	Not Observed 2019 & 2022
10D	Not Observed 2019 & 2022
11A	Not Observed 2019 & 2022
11B	
11C	Not Observed 2019 & 2022
11D	Not Observed 2019 & 2022
12A	Not Observed 2019 & 2022
12B	
12C	
12D	
12E	
12F	Not Observed 2019 & 2022
12G	
13	
14	
19	Not Observed in Teachers' Lounge. New HA
20	Not Observed in Teachers' Lounge. New HA
21	
21A	
22	
22A	

# Chicago Public Schools

**School** Black Magnet  
**Address** 9101 S Euclid Avenue

**Unit** 29381  
 Chicago, IL, 60617

**Building ID** 7860  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
23	
24	
25	
26	
27	
27A	Not Observed 2019 & 2022. New HA
27B	Not Observed 2019 & 2022.
27C	Not Observed 2019 & 2022
27D	Not Observed 2019 & 2022
28	Not Observed 2019 & 2022
28A	Not Observed 2019 & 2022
28B	Not Observed 2019 & 2022
28C	Not Observed 2019 & 2022
28D	Not Observed 2022. New HA
29	
29A	
30	
31	
32	
33	
34	Not Observed in Teachers' Lounge 2022
35	Not Observed in Teachers' Lounge 2022
36	Damage in Gym
37	
38	
39	
40	

# Chicago Public Schools

**School** Black Magnet  
**Address** 9101 S Euclid Avenue

**Unit** 29381  
 Chicago, IL, 60617

**Building ID** 7860  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
41	
42	
43	
44	
45	
46	
46A	
47	
48	
49	
B	Not Observed 2019 & 2022
E	Patch and Repair/Follow O&M
F	
G	
H	
NEW	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Acoustical Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stage, Auditorium and Teachers' Lounge**

MATERIAL QUANTITY: **13975**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Acoustical Plaster**  
MATERIAL LOCATION: **Stage, Auditorium and Teachers' Lounge**  
MATERIAL QUANTITY: **13975** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **Acoustical Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms, Offices, Main Entrance**  
MATERIAL QUANTITY: **8800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **Acoustical Plaster**  
MATERIAL LOCATION: **Classrooms, Offices, Main Entrance**  
MATERIAL QUANTITY: **8800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Scratch Coat Plaster No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms, Offices and Main Entrance**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Scratch Coat Plaster No ACBM**

MATERIAL LOCATION: **Classrooms, Offices and Main Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Scratch Coat Plaster No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms, Stage and Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Scratch Coat Plaster No ACBM**

MATERIAL LOCATION: **Classrooms, Stage and Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022** \_\_\_\_\_

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **12x12 Orange w/Cream Speckles Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **12x12 Orange w/Cream Speckles Floor Tile**  
MATERIAL LOCATION: **Room 103**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material not observed in 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09B**  
MATERIAL DESCRIPTION: **12x12 Brown w/Cream Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridors**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **09B**  
MATERIAL DESCRIPTION: **12x12 Brown w/Cream Floor Tile**  
MATERIAL LOCATION: **Corridors**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09C**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium, Kitchen and Corridor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **09C**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Specks Floor Tile**  
MATERIAL LOCATION: **Auditorium, Kitchen and Corridor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09D**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 100W and 100E, Locker Room and Outside Engineer's Office, & Entry Area 7**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **400** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **09D**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile**  
MATERIAL LOCATION: **Rooms 100W and 100E, Locker Room and Outside Engineer's Office, & Entry Area 7**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **126** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Repair and follow O&M

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09E**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Tan Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Locker Room & Adjacent Corridor**  
MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **09E**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Tan Specks Floor Tile**  
MATERIAL LOCATION: **Locker Room & Adjacent Corridor**  
MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09F**  
MATERIAL DESCRIPTION: **12x12 White w/Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **09F**  
MATERIAL DESCRIPTION: **12x12 White w/Brown Specks Floor Tile**  
MATERIAL LOCATION: **Room 112**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09G**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Computer Room**  
MATERIAL QUANTITY: **418** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **09G**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile**  
MATERIAL LOCATION: **Computer Room**  
MATERIAL QUANTITY: **418** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **9x9 Light Brown w/Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 102-111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **9x9 Light Brown w/Green Floor Tile**  
MATERIAL LOCATION: **Rooms 102-111**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10B**  
MATERIAL DESCRIPTION: **9x9 Light and Dark Brown Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **10B**  
MATERIAL DESCRIPTION: **9x9 Light and Dark Brown Floor Tile ABATED**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10C**  
MATERIAL DESCRIPTION: **9x9 Light Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 108 and Additional Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **10C**  
MATERIAL DESCRIPTION: **9x9 Light Brown Floor Tile**  
MATERIAL LOCATION: **Room 108 and Additional Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10D**  
MATERIAL DESCRIPTION: **9x9 Cream with Dark Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **10D**  
MATERIAL DESCRIPTION: **9x9 Cream with Dark Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Room 103**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 29381    BUILDING ID: 7860  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Black Magnet    INSPECTION DATE: 7/20/2022  
ADDRESS: 9101 S Euclid Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11A  
MATERIAL DESCRIPTION: 9x9 Brown w/Green Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE:    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Rooms 102-111

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2019 & 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **9x9 Brown w/Green Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 102-111**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11B**  
MATERIAL DESCRIPTION: **9x9 Light & Dark Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **11B**  
MATERIAL DESCRIPTION: **9x9 Light & Dark Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022** \_\_\_\_\_

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11C**  
MATERIAL DESCRIPTION: **9x9 Light Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 108 and Additional Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **11C**  
MATERIAL DESCRIPTION: **9x9 Light Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Room 108 and Additional Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11D**  
MATERIAL DESCRIPTION: **9x9 Cream w/Dark Brown Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **11D**  
MATERIAL DESCRIPTION: **9x9 Cream w/Dark Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 103**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **12x12 Orange w/Cream Speckles Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **12x12 Orange w/Cream Speckles Floor Tile Mastic**  
MATERIAL LOCATION: **Room 103**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 29381    BUIDLING ID: 7860  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Black Magnet    INSPECTION DATE: 7/20/2022  
ADDRESS: 9101 S Euclid Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12B  
MATERIAL DESCRIPTION: 12x12 Brown w/Cream Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Corridors  
MATERIAL QUANTITY: 550    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **12B**  
MATERIAL DESCRIPTION: **12x12 Brown w/Cream Floor Tile Mastic**  
MATERIAL LOCATION: **Corridors**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 29381 BUIDLING ID: 7860  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Black Magnet INSPECTION DATE: 7/20/2022  
ADDRESS: 9101 S Euclid Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12C  
MATERIAL DESCRIPTION: 12x12 Beige w/Tan Speckles Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Auditorium, Kitchen and Corridor  
MATERIAL QUANTITY: 800 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **12C**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Speckles Floor Tile Mastic**  
MATERIAL LOCATION: **Auditorium, Kitchen and Corridor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12D**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 100W and 100E, Locker Room and Outside Engineer's Office**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **12D**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 100W and 100E, Locker Room and Outside Engineer's Office**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12E**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Tan Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Locker Room and Adjacent Corridor, Entry Door 7**

MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **12E**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Tan Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Locker Room and Adjacent Corridor, Entry Door 7**  
MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12F**  
MATERIAL DESCRIPTION: **12x12 White w/Brown Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **12F**  
MATERIAL DESCRIPTION: **12x12 White w/Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 112**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12G**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Computer Room**  
MATERIAL QUANTITY: **418** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **12G**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Computer Room**  
MATERIAL QUANTITY: **418** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Vinyl Baseboard**  
MATERIAL LOCATION: **Throughout Main Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9x9 Brown & Cream Speckles Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1957 Addition Building- Stage, Teachers' Lounge Storages and NE Stairway**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Teachers' Lounge. New HA**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9x9 Brown & Cream Speckles Floor Tile**  
MATERIAL LOCATION: **1957 Addition Building- Stage, Teachers' Lounge Storages and NE Stairway**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Not Observed in Teachers' Lounge. New HA

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9x9 Brown w/Cream Speckles Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1957 Addition Building- Stage, Teachers' Lounge Storages and the NE Stairway**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Teachers' Lounge. New HA**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9x9 Brown w/Cream Speckles Floor Tile Mastic**  
MATERIAL LOCATION: **1957 Addition Building- Stage, Teachers' Lounge Storages and the NE Stairway**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Not Observed in Teachers' Lounge. New HA

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1957 Addition Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Vinyl Baseboard**

MATERIAL LOCATION: **1957 Addition Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022** \_\_\_\_\_

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 29381    BUILDING ID: 7860  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Black Magnet    INSPECTION DATE: 7/20/2022  
ADDRESS: 9101 S Euclid Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21A  
MATERIAL DESCRIPTION: Vinyl Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Locker Room 100M-S and Room 112

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **21A**  
MATERIAL DESCRIPTION: **Vinyl Baseboard**  
MATERIAL LOCATION: **Locker Room 100M-S and Room 112**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022** \_\_\_\_\_

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1957 Addition Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

MATERIAL LOCATION: **1957 Addition Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 29381    BUILDING ID: 7860  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Black Magnet    INSPECTION DATE: 7/20/2022  
ADDRESS: 9101 S Euclid Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22A  
MATERIAL DESCRIPTION: Vinyl Baseboard Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Locker Room 100M-S and Room 112

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **22A**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Locker Room 100M-S and Room 112**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Acoustical Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1957 Addition Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Acoustical Plaster**

MATERIAL LOCATION: **1957 Addition Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Scratch Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1957 Addition Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Scratch Coat Plaster**  
MATERIAL LOCATION: **1957 Addition Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12x12 Tan w/Cream & Dark Brown Speckles Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1957 Addition Building- Main Office, Coat Room, Principal's Office and Storage across from Office**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12x12 Tan w/Cream & Dark Brown Speckles Floor Tile**  
MATERIAL LOCATION: **1957 Addition Building- Main Office, Coat Room, Principal's Office and Storage across from Office**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12x12 Tan w/Cream and Dark Brown Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1957 Addition Building- Main Office, Coat Room, Principal's Office and the Storage across from Office**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12x12 Tan w/Cream and Dark Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **1957 Addition Building- Main Office, Coat Room, Principal's Office and the Storage across from Office**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **9x9 Beige w/Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **9x9 Beige w/Brown Streaks Floor Tile**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27A**  
MATERIAL DESCRIPTION: **9x9 Brown w/Cream Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022. New HA**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **27A**

MATERIAL DESCRIPTION: **9x9 Brown w/Cream Streaks Floor Tile**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022. New HA

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27B**  
MATERIAL DESCRIPTION: **9x9 Gray w/Black & White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **27B**  
MATERIAL DESCRIPTION: **9x9 Gray w/Black & White Specks Floor Tile**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022.

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27C**  
MATERIAL DESCRIPTION: **9x9 Light Brown w/Dark Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **27C**  
MATERIAL DESCRIPTION: **9x9 Light Brown w/Dark Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Room 101**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27D**  
MATERIAL DESCRIPTION: **9x9 Brown w/Red Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Custodial Staff Break Room**  
MATERIAL QUANTITY: **28** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed 2022. New HA**

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **27D**  
MATERIAL DESCRIPTION: **9x9 Brown w/Red Streaks Floor Tile**  
MATERIAL LOCATION: **Custodial Staff Break Room**  
MATERIAL QUANTITY: **28** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **9x9 Beige w/Brown Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **9x9 Beige w/Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28A**  
MATERIAL DESCRIPTION: **9x9 Brown w/Cream Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28A**  
MATERIAL DESCRIPTION: **9x9 Brown w/Cream Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28B**  
MATERIAL DESCRIPTION: **9x9 Gray w/Black & White Specks Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28B**  
MATERIAL DESCRIPTION: **9x9 Gray w/Black & White Specks Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28C**  
MATERIAL DESCRIPTION: **9x9 Light Brown with Dark Brown Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 101 - NOT OBSERVED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28C**  
MATERIAL DESCRIPTION: **9x9 Light Brown with Dark Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 101 - NOT OBSERVED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28D**  
MATERIAL DESCRIPTION: **9x9 Brown w/Red Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Custodial Staff Break Room**

MATERIAL QUANTITY: **28**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2022. New HA**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28D**  
MATERIAL DESCRIPTION: **9x9 Brown w/Red Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Custodial Staff Break Room**  
MATERIAL QUANTITY: **28** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Not Observed 2022. New HA

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Red Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall**  
MATERIAL QUANTITY: **144** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Red Carpet Mastic**  
MATERIAL LOCATION: **Assembly Hall**  
MATERIAL QUANTITY: **144** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 29381    BUILDING ID: 7860  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Black Magnet    INSPECTION DATE: 7/20/2022  
ADDRESS: 9101 S Euclid Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29A  
MATERIAL DESCRIPTION: Maroon Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Engineer's Office  
MATERIAL QUANTITY: 26    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29A**  
MATERIAL DESCRIPTION: **Maroon Carpet Mastic**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **26** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Beige Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Hall**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Beige Terrazzo**  
MATERIAL LOCATION: **Main Hall**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Art Room**  
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**  
MATERIAL LOCATION: **Art Room**  
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 29381    BUIDLING ID: 7860  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Black Magnet    INSPECTION DATE: 7/20/2022  
ADDRESS: 9101 S Euclid Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32  
MATERIAL DESCRIPTION: 2'x2' Ceiling Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Gym  
MATERIAL QUANTITY: 10000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridor, Classrooms**  
MATERIAL QUANTITY: **8700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
MATERIAL LOCATION: **Corridor, Classrooms**  
MATERIAL QUANTITY: **8700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12x12 Beige Cream & Tan Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teachers' Lounge and Room 102**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Teachers' Lounge 2022**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12x12 Beige Cream & Tan Speckled Floor Tile**  
MATERIAL LOCATION: **Teachers' Lounge and Room 102**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Not Observed in Teachers' Lounge 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12x12 Beige, Cream & Tan Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teachers' Lounge and Room 102**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Teachers' Lounge 2022**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12x12 Beige, Cream & Tan Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Teachers' Lounge and Room 102**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Not Observed in Teachers' Lounge 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12x12 Tan w/Cream Speckles Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **East Vestibule and Gym**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3000** DAMAGE UNITS: **SF**  
COMMENTS: **Damage in Gym**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12x12 Tan w/Cream Speckles Floor Tile**  
MATERIAL LOCATION: **East Vestibule and Gym**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **35** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Damage in Gym

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Tan w/Cream Speckles Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Vestibule and Gym**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Tan w/Cream Speckles Floor Tile Mastic**  
MATERIAL LOCATION: **East Vestibule and Gym**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Brown, Cream and Beige Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North and South Men's Washroom, North Women's Washroom, and Art Room Men's Washroom**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Brown, Cream and Beige Ceramic Tile Grout**  
MATERIAL LOCATION: **North and South Men's Washroom, North Women's Washroom, and Art Room Men's Washroom**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Stair Tread**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairs near Library**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Stair Tread**  
MATERIAL LOCATION: **Stairs near Library**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 29381    BUIDLING ID: 7860  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Black Magnet    INSPECTION DATE: 7/20/2022  
ADDRESS: 9101 S Euclid Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 40  
MATERIAL DESCRIPTION: Stair Tread Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Stairs near Library  
MATERIAL QUANTITY: 25    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Stair Tread Mastic**  
MATERIAL LOCATION: **Stairs near Library**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12x12 Tan Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 101 and 103-114**  
MATERIAL QUANTITY: **5300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12x12 Tan Speckled Floor Tile**  
MATERIAL LOCATION: **Rooms 101 and 103-114**  
MATERIAL QUANTITY: **5300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 29381 BUIDLING ID: 7860  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Black Magnet INSPECTION DATE: 7/20/2022  
ADDRESS: 9101 S Euclid Avenue IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 42  
MATERIAL DESCRIPTION: 12x12 Tan Speckled Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 101 and 103-114  
MATERIAL QUANTITY: 5300 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12x12 Tan Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 101 and 103-114**  
MATERIAL QUANTITY: **5300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Green Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **South Women's Washroom and Art Room Women's Washroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Green Ceramic Tile Grout**  
MATERIAL LOCATION: **South Women's Washroom and Art Room Women's Washroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Storage and Vestibule Outside Fan Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile**  
MATERIAL LOCATION: **Storage and Vestibule Outside Fan Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Storage Vestibule Outside Fan Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile mastic**  
MATERIAL LOCATION: **Storage Vestibule Outside Fan Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Black, White & Grey Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Drama Room**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Black, White & Grey Floor Tile**  
MATERIAL LOCATION: **Basement Drama Room**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46A**  
MATERIAL DESCRIPTION: **12x12 Black, White & Grey Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Drama Room**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **46A**  
MATERIAL DESCRIPTION: **12x12 Black, White & Grey Floor Tile Mastic**  
MATERIAL LOCATION: **Basement Drama Room**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **9x9 Brown w/Red Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Mechanical Areas and Fan Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **9x9 Brown w/Red Streaks Floor Tile**  
MATERIAL LOCATION: **Mechanical Areas and Fan Rooms**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Not Observed 2019 & 2022

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mechanical Areas, Fan Rooms and Storage Area in the Basement and the Art Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **30** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Mechanical Areas, Fan Rooms and Storage Area in the Basement and the Art Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Patch and Repair/Follow O&M

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mechanical Areas, Fan Rooms and Storage Area in the Basement and the Art Room**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Mechanical Areas, Fan Rooms and Storage Area in the Basement and the Art Room**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 29381    BUIDLING ID: 7860  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Black Magnet    INSPECTION DATE: 7/20/2022  
ADDRESS: 9101 S Euclid Avenue    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: G  
MATERIAL DESCRIPTION: MJP E/F/V on Fiberglass Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1957 Addition  
MATERIAL QUANTITY: 20    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **1957 Addition**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet** INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mechanical Areas and Meter Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUIDLING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Mechanical Areas and Meter Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **29381**    BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet**    INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue**    IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Wood Patterned Linoleum**  
MATERIAL LOCATION: **Teachers' Lounge & Library**  
MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **29381**      BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet**      REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Wood Patterned Linoleum**  
MATERIAL LOCATION: **Teachers' Lounge & Library**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 08/12/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **29381**      BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet**      REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 08/12/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **29381**      BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet**      INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12"x12" Brown and White Floor Tile - Abated**  
MATERIAL LOCATION: **Custodial Staff Breakroom**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Abated**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY:  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **29381**      BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet**      REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12"x12" Brown and White Floor Tile - Abated**  
MATERIAL LOCATION: **Custodial Staff Breakroom**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **29381**      BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Black Magnet**      INSPECTION DATE: **7/20/2022**  
ADDRESS: **9101 S Euclid Avenue**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Mastic associated with 12" Brown and White Floor Tile**  
MATERIAL LOCATION: **Custodial Staff Breakroom**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Abated**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29381** BUILDING ID: **7860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Black Magnet** REVIEW DATE: **8/12/2022**  
ADDRESS: **9101 S Euclid Avenue** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Mastic associated with 12" Brown and White Floor Tile**

MATERIAL LOCATION: **Custodial Staff Breakroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **08/12/2022**

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER ANTONOPOULOS  
has completed the **ASBESTOS INSPECTOR'S REFRESHER** course and successfully passed the  
examination on 06/01/2021 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II; Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

06/01/2021

Course Dates:

06/01/2022

Expires:

2106BIR11

Certificate Number:

A handwritten signature in black ink, appearing to read "N Penneff", written over a rectangular stamp area.

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER J. ANTONOPOULOS  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 06/03/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

06/03/2022

Course Dates:

06/03/2023

Expires:

2206BIR01

Certificate Number:



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in black ink, appearing to read "N. Peneff", is written over a light gray rectangular background.


Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081


FORM # A-010B

 **ASBESTOS  
PROFESSIONAL  
LICENSE**

<b>ID NUMBER</b>	<b>ISSUED</b>	<b>EXPIRES</b>
100 - 18281	2/10/2022	05/15/2023

**CHRISTOPHER J ANTONOPO**  
1736 W 102nd ST  
CHICAGO, IL 60643

Environmental Health



<b>ENDORSEMENT</b>	<b>TC EXPIRES</b>
INSPECTOR	6/1/2022

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**TODD T HUFFER**  
315 HATLEN COURT  
MT. PROSPECT, IL 60056

2/18/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	<b>ASBESTOS PROFESSIONAL LICENSE</b>		INSPECTOR	11/1/2022
<b>ID NUMBER</b> 100 - 09870	<b>ISSUED</b> 2/18/2022	<b>EXPIRES</b> 05/15/2023	MANAGEMENT PLANNER	11/19/2022
<b>TODD T HUFFER</b> 315 HATLEN COURT MT. PROSPECT, IL 60056 Environmental Health			PROJECT MANAGER	10/20/2022
			AIR SAMPLING PROFESSIONAL	
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

## Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815

  
Kathy DeSalvo, Director





OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255

  
Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265

  
Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed