

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2846
SCHOOL NAME: Clark Academic Prep HS
ADDRESS OF SCHOOL: 5101 W. Harrison
CITY: Chicago, IL, 60644

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/5/2019**


If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/21/2022 ENROLLMENT 428
IDPH INSPECTOR LICENSE NUMBER: 100-20129
IDPH LICENSED INSPECTOR NAME (Please Print): Joshua Karlson
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



9/30/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Clark Academic Prep HS

5101 W. Harrison
Chicago, IL, 60644

Unit: 41051
Building ID: 6620

IDPH ID Number: 14-016-2990-2846

REPORT DATE:

Friday, September 30, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

09/30/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 41051 Region: 03 IDPH ID: 14-016-2990-2846

School: Clark Academic Prep HS Building ID: 6620

Address: 5101 W. Harrison

Chicago, IL, 60644

Building Contact: Mejia, Enrique

Contact Phone: 3123710502

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/21/2022

Review Date: 09/30/2022

Inspector: Joshua Karlson

Inspector IDPH License: 100-20129

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 30, 2022

RE: Clark Academic Prep HS, Unit 41051
5101 W. Harrison
Chicago, IL, 60644

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Clark Academic Prep HS , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Clark Academic Prep HS, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Clark Academic Prep HS Unit: 41051 Region: 03
Address: 5101 W. Harrison Chicago, IL, 60644
IDPH ID: 14-016-2990-2846 Building ID: 6620
Contact: Mejia, Enrique Phone: 3123710502

2. Description of Facility

Original Construction: 1972 Additional Construction:
Total Square Footage: 150700 No of Floors: 2
Current Occupancy: 428

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Joshua Karlson


Inspector IDPH license # 100-20129
Reinspection Date: 9/21/2022


Signature:
Date: 9/21/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466



Signature:
Date: 09/30/2022

7. Review Date: 09/30/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 9/30/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Clark Academic Prep HS. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6620:

1	12" x 12" Brown Floor Tile w/Pink and White Streaks
100	12" x 12" Light Gray Mottled Floor Tile
101	Mastic Associated w/ 12" x 12" Light Gray Mottled Floor Tile
102	12" x 12" White w/ Tan Streak Floor Tile
103	Mastic Associated w/ 12" x 12" White w/ Tan Streak Floor Tile
104	Gray and Blue Streaked Carpet Mastic
105	Pool heater duct insulation
14	Water tank insulation

45	12" x 12" Brown w/Pink & White Streaks Floor Tile Mastic
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile
85	1' x 1' Smooth Ceiling Tiles
86	Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile
88	Brown carpet adhesive
89	12" x 12" White w/ Dark Gray Streak Floor Tile
90	Mastic assoc. W/ 12" x 12" White w/ Dark Gray Streak Floor Tile
91	Wood Tongue and Groove Flooring
92	12" x 12" Yellow w/ Blue Streak Floor Tile
93	12" x 12" Gray Mottled Floor Tile
94	12" x 12" Dark Gray Mottled Floor Tile
95	Mastic Associated w/ 12" x 12" Gray, Dark Gray and Yellow Floor Tile
96	2'x2' rough texture ceiling tile
97	Blue carpet adhesive
98	Fire door
99	Gray pattern carpet mastic

B. The following new homogenous areas have been identified for Building 6620:

100	12" x 12" Light Gray Mottled Floor Tile
101	Mastic Associated w/ 12" x 12" Light Gray Mottled Floor Tile
102	12" x 12" White w/ Tan Streak Floor Tile
103	Mastic Associated w/ 12" x 12" White w/ Tan Streak Floor Tile
104	Gray and Blue Streaked Carpet Mastic
105	Pool heater duct insulation
88	Brown carpet adhesive
89	12" x 12" White w/ Dark Gray Streak Floor Tile
90	Mastic assoc. W/ 12" x 12" White w/ Dark Gray Streak Floor Tile
91	Wood Tongue and Groove Flooring
92	12" x 12" Yellow w/ Blue Streak Floor Tile
93	12" x 12" Gray Mottled Floor Tile
94	12" x 12" Dark Gray Mottled Floor Tile
95	Mastic Associated w/ 12" x 12" Gray, Dark Gray and Yellow Floor Tile
96	2'x2' rough texture ceiling tile
97	Blue carpet adhesive
98	Fire door
99	Gray pattern carpet mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	12" x 12" Light Gray Mottled Floor Tile
101	Mastic Associated w/ 12" x 12" Light Gray Mottled Floor Tile
102	12" x 12" White w/ Tan Streak Floor Tile
103	Mastic Associated w/ 12" x 12" White w/ Tan Streak Floor Tile
104	Gray and Blue Streaked Carpet Mastic
105	Pool heater duct insulation
2	12" x 12" Yellow Floor Tile
5	12" x 12" Brown Speckled Floor Tile
54	Purple/lavender/tan ceramic tile grout
55	Wall tile caulk
56	Wall tile adhesive
57	Blue carpet mastic
58	Orange carpet mastic
59	Gray carpet mastic
60	12" x 12" Light Gray Floor Tile
61	12" x 12" Light Gray Floor Tile Mastic
67	12" x 12" Blue Floor Tile
68	12" x 12" Blue Floor Tile Mastic
69	Purple carpet mastic
71	12" x 12" Beige Floor Tile Mastic
76	Blue linoleum flooring
77	Blue linoleum mastic
78	12" x 12" Dark Brown w/Light Gray Spec's Floor Tile
79	12" x 12" Dark Brown w/Light Gray Specks Floor Tile Mastic
80	Ceramic floor grout
81	12" x 12" Brown w/White-Gray Spec's Floor Tile
82M	12" x 12" Brown w/White-Gray Floor Tile Mastic
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile
85	1' x 1' Smooth Ceiling Tiles
86	Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile
87	Beige speckled floor tile
88	Brown carpet adhesive
89	12" x 12" White w/ Dark Gray Streak Floor Tile
90	Mastic assoc. W/ 12" x 12" White w/ Dark Gray Streak Floor Tile

91	Wood Tongue and Groove Flooring
92	12" x 12" Yellow w/ Blue Streak Floor Tile
93	12" x 12" Gray Mottled Floor Tile
94	12" x 12" Dark Gray Mottled Floor Tile
95	Mastic Associated w/ 12" x 12" Gray, Dark Gray and Yellow Floor Tile
96	2'x2' rough texture ceiling tile
97	Blue carpet adhesive
98	Fire door
99	Gray pattern carpet mastic
AA	Pink/White flooring material
BB	Mastic associate w/ HA# AA

The following areas were deemed to be inaccessible:

17A	12" x 12" Yellow Floor Tile Mastic
17B	12" x 12" Brown Speckled Floor Tile Mastic
23	Mastic beneath orange rubber flooring
25	12" x 12" Maroon Floor Tile w/White Flecks Mastic
37	12" x 12" White Floor Tile w/Gray Streaks Mastic
55	Wall tile caulk
57	Blue carpet mastic
58	Orange carpet mastic
59	Gray carpet mastic
61	12" x 12" Light Gray Floor Tile Mastic
68	12" x 12" Blue Floor Tile Mastic
69	Purple carpet mastic
71	12" x 12" Beige Floor Tile Mastic
75	Transite panel in floor radiators
77	Blue linoleum mastic
79	12" x 12" Dark Brown w/Light Gray Specks Floor Tile Mastic
82M	12" x 12" Brown w/White-Gray Floor Tile Mastic
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile
86	Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile
97	Blue carpet adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Joshua Karlson, IDPH License # 100-20129. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Clark Academic Prep HS Building 6620 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
3	12" x 12" Beige Floor Tile			2nd Floor Corridor	NO_ACBM	MISC								
30	Cinder block			Throughout Facility	NO_ACBM	MISC								
31	Cinder block mortar			Throughout Facility	NO_ACBM	MISC								
32	Wall tile adhesive			Boy's Pool Locker Room	NO_ACBM	MISC								
33	Wall tile caulk			Boy's Pool Locker Room	NO_ACBM	MISC								
34	Clay floor tile			Kitchen	NO_ACBM	MISC								
35	Clay floor tile mortar			Kitchen	NO_ACBM	MISC								
36	Ceramic wall grout			Kitchen	NO_ACBM	MISC								
37	12" x 12" White Floor Tile w/Gray Streaks Mastic	1,728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Engineer Office, Rooms 230 and 232, South Stairwell Landings	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
38	Terrazzo			Stairways and Landings	NO_ACBM	SURFACE								
39	Brown ceramic tile grout			Boy's Bathrooms, Men's Bathrooms	NO_ACBM	MISC								
4	12" x 12" White Floor Tile w/Gray Streaks	1,728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Eng Office, Rooms 230 and 232, South Stairwell Landings, Kitchen Storage	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
40	Yellow ceramic tile grout			Girl's Bathrooms, Women's Bathrooms	NO_ACBM	MISC								
41	White ceramic wall tile grout			Custodial Rooms in Boy's Bathrooms	NO_ACBM	MISC								
42	Terrazzo basins			Custodial Rooms in Boy's Bathrooms	NO_ACBM	MISC								
43	4" Black vinyl baseboard			Throughout Facility	NO_ACBM	MISC								
44	4" Black vinyl baseboard mastic			Throughout Facility	NO_ACBM	MISC								
45	12" x 12" Brown w/Pink & White Streaks Floor Tile Mastic	20,000	SF	Rooms 107, 115, 116, 122, 205, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement	CHR	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
67	12" x 12" Blue Floor Tile	200	SF	MDF Room in 116,212	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
68	12" x 12" Blue Floor Tile Mastic	200	SF	MDF Room in 116	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
69	Purple carpet mastic	556	SF	Room 107,110	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
7	Plaster Ceilings and Walls			Throughout Facility	NO_ACBM	SURFACE								
70	Purple carpet mastic			1st & 2nd Floor Corridors, Faculty Lounge, 1211, 123-125, 130-134, 141, 143-145, 147, 149, 152-155, 150-154, Lockers, 216	NO_ACBM	MISC								
71	12" x 12" Beige Floor Tile Mastic	500	SF	2nd Floor Corridor	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
75	Transite panel in floor radiators	4,000	SF	Rooms	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
76	Blue linoleum flooring	3,600	SF	Rooms 142, 223, 223A, 221, 241, 241 and 243, Elevator	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
77	Blue linoleum mastic	3,600	SF	Rooms 142, 223, 223A, 221, 241, 241A, 243, Elevator	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
78	12" x 12" Dark Brown w/Light Gray Spec's Floor Tile	400	SF	1st Floor Activity Center Nr. Stairs	ASSUMED	MISC	N	LOC	5	SF	No	ACBM with the potential for damage	3	LOW
79	12" x 12" Dark Brown w/Light Gray Specks Floor Tile Mastic	400	SF	1st Floor Activity Center Nr. Stairs	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
8	Lab table tops	400	SF	Rooms 122, 243, 241, 221, 221A, 223	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
80	Ceramic floor grout	4,500	SF	Pool, 1st & 2nd Fl. Girl's/Boy's Rest Rooms and Lockers	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
81	12" x 12" Brown w/White-Gray Spec's Floor Tile	3,800	SF	Front Entrance Hallway	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
82M	12" x 12" Brown w/White-Gray Floor Tile Mastic	3,800	SF	Front Entrance Hallway	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1,000	SF	Rooms 109 and 205	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1,000	SF	Rooms 109 and 205	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
85	1' x 1' Smooth Ceiling Tiles	2,000	SF	Kitchen	ASSUMED	MISC	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
BB	Mastic associate w/ HA# AA			Rooms 221, 241, 122, 142, 222, 242	ASSUMED	MISC								
CC	Panels over moveable doors room divide	2,850	SF	123/121, 132/134, 152/154, 232/234, 252/254, House commons 1,2 and Gym	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 9/21/2022
Inspector Name Joshua Karlson
100-20129 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	Basement outside mechanical room Water damage floor tile and physical damage floor tiles loose exposed mastic.
100	
101	
102	
103	
104	
105	Damage in Pump Room
11	Not observed 2022
12	Damage in Pump Room
13	
14	
15	
16	Not observed 2022
17A	
17B	
18	
19	
2	Not observed 2022
20	Not observed 2022
21	Not observed 2022
22	
23	
24	

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
51	
52	
53	
54	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	Not observed in 110
7	
70	
71	
75	
76	
77	
78	Damage in first floor activity center - 5 loose floor tiles, exposed mastic
79	
8	

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
80	
81	
82M	
83	
84	
85	
86	
87	
88	
89	
9	Not observed 2022
90	
91	
92	
93	
94	
95	
96	
97	
98	Damage in Floor 1 Book Room
99	
AA	Not observed 2022
BB	Not observed 2022
CC	

Chicago Public Schools

School Clark Academic Prep HS **Unit** 41051 **Building ID** 6620

Address 5101 W. Harrison **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	12" x 12" Brown Floor Tile w/Pink and White Streaks	19,500	SF	107, 115, 116, 122,142, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement 249A, 249B, 1st Floor Corridor, 2nd Floor Corridor, 203, 204, 206, 128	Chrysotile	MISC	No	150	SF	6 ACBM with the potential for damage	Repair
100	12" x 12" Light Gray Mottled Floor Tile	300	SF	Room 147	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	Mastic Associated w/ 12" x 12" Light Gray Mottled Floor Tile	300	SF	Room 147	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	12" x 12" White w/ Tan Streak Floor Tile	1,200	SF	Room 110, 109B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Mastic Associated w/ 12" x 12" White w/ Tan Streak Floor Tile	1,200	SF	Room 110, 109B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	Gray and Blue Streaked Carpet Mastic	2,500	SF	Gurley Center	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	Pool heater duct insulation	30	LF	Pump Room	Assumed	TSI	Yes	2	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
11	Spray on fire proofing			Inaccessible, Access to Roof Area by Girl's Locker Room	Chrysotile	SURFACE					Follow O&M Plan
12	Cementitious Fitting Insulation on Cold Water Line			Throughout	No ACBM	TSI					
13	Cementitious Fitting Insulation on Hot Water Lines			Throughout	No ACBM	TSI					
14	Water tank insulation	280	SF	Basement	Amosite	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
15	Tank Breaching on Domestic Hot Water Tank			Pool Mechanical Room	No ACBM	MISC					
16	Metal 2' x 4' Lay In Ceiling Panels			Throughout Facility	Not Tested	MISC					Follow O&M Plan
17A	12" x 12" Yellow Floor Tile Mastic	15	SF	Elevator by Faculty Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17B	12" x 12" Brown Speckled Floor Tile Mastic	30,000	SF	1st & 2nd Floor Corridors, 227	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Water heater breaching			Mechanical Room	No ACBM	TSI					
19	Water inlet pipe insulation			Mechanical Room	No ACBM	TSI					
2	12" x 12" Yellow Floor Tile			Elevator by Faculty Lounge	Assumed	MISC					Follow O&M Plan
20	Block inside water heater			Mechanical Room	Chrysotile	MISC					Follow O&M Plan
21	Mud inside water heater			Mechanical Room	Chrysotile	MISC					Follow O&M Plan
22	Orange rubber flooring			Gym	No ACBM	MISC					
23	Mastic beneath orange rubber flooring	1,500	SF	Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12" x 12" Maroon Floor Tile w/White Flecks	1,000	SF	Girls & Boys Locker Rooms, Coaches Offices, Storage Room off Gym, H3, H4, Storage by 206, Kitchen Office, Floor 1 Book Room, Floor 1 West Book Room, Auditorium Storage Room,	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Telecom Room in Main Office, Basement Corridor							
25	12" x 12" Maroon Floor Tile w/White Flecks Mastic	1,000	SF	Girls & Boys Locker Rooms, Coaches Offices, Storage Room off Gym, H3, H4, Kitchen Office, Floor 1 Book Room, Floor 1 West Book Room, Auditorium Storage, Telecom Room in Main Office, Basement Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Brown baseboard			Gym, Girls & Boys Locker Rooms, Coaches Offices	No ACBM	MISC					
27	Brown baseboard mastic			Gym, Girls & Boys Locker Rooms, Coaches Offices	No ACBM	MISC					
28	Ceramic wall base grout			Pool Room, Girl's and Boy's Locker Rooms	No ACBM	MISC					
29	Ceramic floor tile grout			Pool Room, Girl's and Boy's Locker Rooms	No ACBM	MISC					
3	12" x 12" Beige Floor Tile			2nd Floor Corridor	No ACBM	MISC					
30	Cinder block			Throughout Facility	No ACBM	MISC					
31	Cinder block mortar			Throughout Facility	No ACBM	MISC					
32	Wall tile adhesive			Boy's Pool Locker Room	No ACBM	MISC					
33	Wall tile caulk			Boy's Pool Locker Room	No ACBM	MISC					
34	Clay floor tile			Kitchen	No ACBM	MISC					
35	Clay floor tile mortar			Kitchen	No ACBM	MISC					
36	Ceramic wall grout			Kitchen	No ACBM	MISC					
37	12" x 12" White Floor Tile w/Gray Streaks Mastic	1,728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Engineer Office, Rooms 230 and 232, South Stairwell Landings	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Terrazzo			Stairways and Landings	No ACBM	SURFACE					
39	Brown ceramic tile grout			Boy's Bathrooms, Men's Bathrooms	No ACBM	MISC					
4	12" x 12" White Floor Tile w/Gray Streaks	1,728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Eng Office, Rooms 230 and 232, South Stairwell Landings, Kitchen Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Yellow ceramic tile grout			Girl's Bathrooms, Women's Bathrooms	No ACBM	MISC					
41	White ceramic wall tile grout			Custodial Rooms in Boy's Bathrooms	No ACBM	MISC					

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
42	Terrazzo basins			Custodial Rooms in Boy's Bathrooms	No ACBM	MISC					
43	4" Black vinyl baseboard			Throughout Facility	No ACBM	MISC					
44	4" Black vinyl baseboard mastic			Throughout Facility	No ACBM	MISC					
45	12" x 12" Brown w/Pink & White Streaks Floor Tile Mastic	20,000	SF	Rooms 107, 115, 116, 122, 205, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	4" Light brown vinyl baseboard (cove base)			Rooms 102 and 148	No ACBM	MISC					
47	4" Light brown vinyl baseboard (cove base) mastic			Rooms 102 and 148	No ACBM	MISC					
48	Drywall			Room 220, Industrial Arts Corridor	No ACBM	MISC					
49	Interior brick			Throughout Facility	No ACBM	MISC					
5	12" x 12" Brown Speckled Floor Tile	50	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Interior brick mortar			Throughout Facility	No ACBM	MISC					
51	Interior door caulk	10	LF	Corridor by 241	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
52	Interior window caulk			Throughout Facility	No ACBM	MISC					
53	Interior window glazing non ahera			Throughout Facility	No ACBM	MISC					
54	Purple/lavender/tan ceramic tile grout	100	SF	Office Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Wall tile caulk	100	SF	Office Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Wall tile adhesive	100	SF	Office Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Blue carpet mastic	6,500	SF	Rooms 101-103, 202 and 214, and LRC Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	Orange carpet mastic	4,600	SF	Activity Circle	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Gray carpet mastic	6,200	SF	Activity Circle, Rooms 122, 142, 241, 150	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	12" x 12" Wormy Ceiling Tile			Basement, Activity Circle, 1st Floor Men's & Women's Bathrooms	No ACBM	MISC					
60	12" x 12" Light Gray Floor Tile	100	SF	At Doors of Commons 1+2	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12" x 12" Light Gray Floor Tile Mastic	100	SF	At Doors of Commons 1+2	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Exterior door caulk (Non-AHERA)			Building Exterior	No ACBM	MISC					
63	12" x 12" Light Brown Floor Tile w/Dark Brown Streaks			Room 217	Abated	MISC					
64	12" x 12" Light Brown Floor Tile w/Dark Brown Streaks Mastic			Room 217	Abated	MISC					
65	Exterior brick - Non-AHERA			Building Exterior	No ACBM	MISC					
66	Exterior brick mortar - Non-AHERA			Building Exterior	No ACBM	MISC					
67	12" x 12" Blue Floor Tile	200	SF	MDF Room in 116,212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
68	12" x 12" Blue Floor Tile Mastic	200	SF	MDF Room in 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	Purple carpet mastic	556	SF	Room 107,110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7	Plaster Ceilings and Walls			Throughout Facility	No ACBM	SURFACE					
70	Purple carpet mastic			1st & 2nd Floor Corridors, Faculty Lounge, 1211, 123-125, 130-134, 141, 143-145, 147, 149, 152-155, 150-154, Lockers, 216	No ACBM	MISC					
71	12" x 12" Beige Floor Tile Mastic	500	SF	2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	Transite panel in floor radiators	4,000	SF	Rooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	Blue linoleum flooring	3,600	SF	Rooms 142, 223, 223A, 221, 241, 241 and 243, Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Blue linoleum mastic	3,600	SF	Rooms 142, 223, 223A, 221, 241, 241A, 243, Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" Dark Brown w/Light Gray Spec's Floor Tile	400	SF	1st Floor Activity Center Nr. Stairs	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Repair
79	12" x 12" Dark Brown w/Light Gray Specks Floor Tile Mastic	400	SF	1st Floor Activity Center Nr. Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	Lab table tops	400	SF	Rooms 122, 243, 241, 221, 221A, 223	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Ceramic floor grout	4,500	SF	Pool, 1st & 2nd Fl. Girl's/Boy's Rest Rooms and Lockers	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12" x 12" Brown w/White-Gray Spec's Floor Tile	3,800	SF	Front Entrance Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82M	12" x 12" Brown w/White-Gray Floor Tile Mastic	3,800	SF	Front Entrance Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1,000	SF	Rooms 109 and 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1,000	SF	Rooms 109 and 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	1' x 1' Smooth Ceiling Tiles	2,000	SF	Kitchen	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
86	Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile	2,000	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Beige speckled floor tile	50	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Brown carpet adhesive	900	SF	Room 231, 233, 253, 251, 250, 248, 247, 244, 242, 240, 200, 218, 220, 220A, 225, 226, 209, 214, 210, 213, 211, 220 Storage, 201, 202, 153, 154, Receiving Room 106, 133, 134, 127, 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
89	12" x 12" White w/ Dark Gray Streak Floor Tile	1,500	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9	Mag block duct insulation			Kitchen & Storage area in Basement	Chrysotile	TSI					Follow O&M Plan
90	Mastic assoc. W/ 12" x 12" White w/ Dark Gray Streak Floor Tile	1,500	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	Wood Tongue and Groove Flooring	3,000	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12" x 12" Yellow w/ Blue Streak Floor Tile	500	SF	Floor 2 Locker Rooms , 205, 252, 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93	12" x 12" Gray Mottled Floor Tile	300	SF	2nd Floor Locker Rooms, 205, 252, 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12" x 12" Dark Gray Mottled Floor Tile	300	SF	2nd Floor Locker Rooms, 205, 252, 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
95	Mastic Associated w/ 12" x 12" Gray, Dark Gray and Yellow Floor Tile	1,100	SF	2nd Floor Locker Rooms, 205, 252 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	2'x2' rough texture ceiling tile	2,500	SF	Room 241A, 221A, 143 Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	Blue carpet adhesive	1,000	SF	Room 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	Fire door	50	SF	Floor 1 Book Room	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Repair
99	Gray pattern carpet mastic	1,500	SF	Room 143 Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AA	Pink/White flooring material			Rooms 241, 122, 142,	Assumed	MISC					Follow O&M Plan
BB	Mastic associate w/ HA# AA			Rooms 221, 241, 122, 142, 222, 242	Assumed	MISC					Follow O&M Plan
CC	Panels over moveable doors room divide	2,850	SF	123/121, 132/134, 152/154,232/234, 252/254, House commons 1,2 and Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	9/30/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
100	
101	
102	
103	
104	
105	Sample to determine ACM contact
11	
12	
13	
14	
15	
16	
17A	
17B	
18	
19	
2	
20	
21	

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
47	
48	
49	
5	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
71	
75	
76	
77	
78	
79	
8	
80	
81	
82M	
83	
84	
85	
86	
87	
88	
89	
9	
90	
91	
92	
93	
94	
95	
96	
97	
98	

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
99	
AA	
BB	
CC	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Pink and White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Water**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Vibration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **107, 115, 116, 122,142, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement 249A, 249B, 1st Floor Corridor, 2nd Floor Corridor, 203, 204, 206, 128**
MATERIAL QUANTITY: **19500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Basement outside mechanical room Water damage floor tile and physical damage floor tiles loose exposed mastic.**

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Pink and White Streaks**
MATERIAL LOCATION: **107, 115, 116, 122,142, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement 249A, 249B, 1st Floor Corridor, 2nd Floor Corridor, 203, 204, 206, 128**
MATERIAL QUANTITY: **19500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **150** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Spray on fire proofing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Inaccessible, Access to Roof Area by Girl's Locker Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Spray on fire proofing**
MATERIAL LOCATION: **Inaccessible, Access to Roof Area by Girl's Locker Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Cementitious Fitting Insulation on Cold Water Line**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Damage in Pump Room**

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Cementitious Fitting Insulation on Cold Water Line**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Cementitious Fitting Insulation on Hot Water Lines**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Cementitious Fitting Insulation on Hot Water Lines**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Water tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Water tank insulation**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Tank Breeching on Domestic Hot Water Tank**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Tank Breeching on Domestic Hot Water Tank**

MATERIAL LOCATION: **Pool Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Metal 2' x 4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Metal 2' x 4' Lay In Ceiling Panels**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Elevator by Faculty Lounge**

MATERIAL QUANTITY: **15**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**
MATERIAL LOCATION: **Elevator by Faculty Lounge**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17B**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, 227**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **17B**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, 227**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Water heater breeching**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Water heater breeching**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Water inlet pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Water inlet pipe insulation**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Elevator by Faculty Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**
MATERIAL LOCATION: **Elevator by Faculty Lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Block inside water heater**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Block inside water heater**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Mud inside water heater**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Mud inside water heater**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Orange rubber flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Orange rubber flooring**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Mastic beneath orange rubber flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Mastic beneath orange rubber flooring**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Maroon Floor Tile w/White Flecks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices, Storage Room off Gym, H3, H4, Storage by 206, Kitchen Office, Floor 1 Book Room, Floor 1 West Book Room, Auditorium Storage Room, Telecom Room in Main Office, Basement Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Maroon Floor Tile w/White Flecks**
MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices, Storage Room off Gym, H3, H4, Storage by 206, Kitchen Office, Floor 1 Book Room, Floor 1 West Book Room, Auditorium Storage Room, Telecom Room in Main Office, Basement Corridor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12" x 12" Maroon Floor Tile w/White Flecks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices, Storage Room off Gym, H3, H4, Kitchen Office, Floor 1 Book Room, Floor 1 West Book Room, Auditorium Storage, Telecom Room in Main Office, Basement Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12" x 12" Maroon Floor Tile w/White Flecks Mastic**
MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices, Storage Room off Gym, H3, H4, Kitchen Office, Floor 1 Book Room, Floor 1 West Book Room, Auditorium Storage, Telecom Room in Main Office, Basement Corridor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Brown baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym, Girls & Boys Locker Rooms, Coaches Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Brown baseboard**

MATERIAL LOCATION: **Gym, Girls & Boys Locker Rooms, Coaches Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Brown baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym, Girls & Boys Locker Rooms, Coaches Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Brown baseboard mastic**

MATERIAL LOCATION: **Gym, Girls & Boys Locker Rooms, Coaches Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Ceramic wall base grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Room, Girl's and Boy's Locker Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Ceramic wall base grout**

MATERIAL LOCATION: **Pool Room, Girl's and Boy's Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Ceramic floor tile grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Room, Girl's and Boy's Locker Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Ceramic floor tile grout**
MATERIAL LOCATION: **Pool Room, Girl's and Boy's Locker Rooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Cinder block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Cinder block**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Cinder block mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Cinder block mortar**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Wall tile adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boy's Pool Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Wall tile adhesive**

MATERIAL LOCATION: **Boy's Pool Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Wall tile caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boy's Pool Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Wall tile caulk**
MATERIAL LOCATION: **Boy's Pool Locker Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Clay floor tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Clay floor tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Clay floor tile mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Clay floor tile mortar**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Ceramic wall grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Ceramic wall grout**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Engineer Office, Rooms 230 and 232, South Stairwell Landings**

MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks Mastic**
MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Engineer Office, Rooms 230 and 232, South Stairwell Landings**
MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stairways and Landings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Stairways and Landings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Brown ceramic tile grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boy's Bathrooms, Men's Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Brown ceramic tile grout**
MATERIAL LOCATION: **Boy's Bathrooms, Men's Bathrooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Eng Office, Rooms 230 and 232, South Stairwell Landings, Kitchen Storage**

MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks**
MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Eng Office, Rooms 230 and 232, South Stairwell Landings, Kitchen Storage**
MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Yellow ceramic tile grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girl's Bathrooms, Women's Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Yellow ceramic tile grout**

MATERIAL LOCATION: **Girl's Bathrooms, Women's Bathrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **White ceramic wall tile grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Custodial Rooms in Boy's Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **White ceramic wall tile grout**

MATERIAL LOCATION: **Custodial Rooms in Boy's Bathrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Terrazzo basins**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Custodial Rooms in Boy's Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Terrazzo basins**

MATERIAL LOCATION: **Custodial Rooms in Boy's Bathrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **4" Black vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **4" Black vinyl baseboard**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **4" Black vinyl baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **4" Black vinyl baseboard mastic**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Pink & White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 107, 115, 116, 122, 205, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Pink & White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 107, 115, 116, 122, 205, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **4" Light brown vinyl baseboard (cove base)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 102 and 148**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **4" Light brown vinyl baseboard (cove base)**
MATERIAL LOCATION: **Rooms 102 and 148**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **4" Light brown vinyl baseboard (cove base) mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 102 and 148**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **4" Light brown vinyl baseboard (cove base) mastic**

MATERIAL LOCATION: **Rooms 102 and 148**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 220, Industrial Arts Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Room 220, Industrial Arts Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Interior brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Interior brick**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Interior brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Interior brick mortar**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Interior door caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridor by 241**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Interior door caulk**
MATERIAL LOCATION: **Corridor by 241**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Interior window caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Interior window caulk**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Interior window glazing non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Interior window glazing non ahera**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Purple/lavender/tan ceramic tile grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office Bathroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Purple/lavender/tan ceramic tile grout**
MATERIAL LOCATION: **Office Bathroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Wall tile caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office Bathroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Wall tile caulk**
MATERIAL LOCATION: **Office Bathroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Wall tile adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office Bathroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Wall tile adhesive**
MATERIAL LOCATION: **Office Bathroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Blue carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 101-103, 202 and 214, and LRC Offices**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Blue carpet mastic**
MATERIAL LOCATION: **Rooms 101-103, 202 and 214, and LRC Offices**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Orange carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Activity Circle**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Orange carpet mastic**
MATERIAL LOCATION: **Activity Circle**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Gray carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Activity Circle, Rooms 122, 142, 241, 150**
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Gray carpet mastic**
MATERIAL LOCATION: **Activity Circle, Rooms 122, 142, 241, 150**
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **12" x 12" Wormy Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement, Activity Circle, 1st Floor Men's & Women's Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **12" x 12" Wormy Ceiling Tile**
MATERIAL LOCATION: **Basement, Activity Circle, 1st Floor Men's & Women's Bathrooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **At Doors of Commons 1+2**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile**
MATERIAL LOCATION: **At Doors of Commons 1+2**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **At Doors of Commons 1+2**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile Mastic**
MATERIAL LOCATION: **At Doors of Commons 1+2**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Exterior door caulk (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Exterior door caulk (Non-AHERA)**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Dark Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 217**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Dark Brown Streaks**
MATERIAL LOCATION: **Room 217**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Dark Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 217**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Dark Brown Streaks Mastic**

MATERIAL LOCATION: **Room 217**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **MDF Room in 116,212**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **MDF Room in 116,212**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **MDF Room in 116**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **MDF Room in 116**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Purple carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 107,110**
MATERIAL QUANTITY: **556** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in 110**

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Purple carpet mastic**
MATERIAL LOCATION: **Room 107,110**
MATERIAL QUANTITY: **556** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Plaster Ceilings and Walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Plaster Ceilings and Walls**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Purple carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Faculty Lounge, 1211, 123-125, 130-134, 141 , 143-145, 147, 149 , 152-155, 150-154, Lockers, 216**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Purple carpet mastic**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Faculty Lounge, 1211, 123-125, 130-134, 141 , 143-145, 147, 149 , 152-155, 150-154, Lockers, 216**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Transite panel in floor radiators**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Transite panel in floor radiators**
MATERIAL LOCATION: **Rooms**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **Blue linoleum flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 142, 223, 223A, 221, 241, 241 and 243, Elevator**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **Blue linoleum flooring**
MATERIAL LOCATION: **Rooms 142, 223, 223A, 221, 241, 241 and 243, Elevator**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Blue linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 142, 223, 223A, 221, 241, 241A, 243, Elevator**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Blue linoleum mastic**
MATERIAL LOCATION: **Rooms 142, 223, 223A, 221, 241, 241A, 243, Elevator**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/Light Gray Spec's Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Activity Center Nr. Stairs**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **400** DAMAGE UNITS: **SF**
COMMENTS: **Damage in first floor activity center - 5 loose floor tiles, exposed mastic**

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/Light Gray Spec's Floor Tile**
MATERIAL LOCATION: **1st Floor Activity Center Nr. Stairs**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/Light Gray Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Activity Center Nr. Stairs**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/Light Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Activity Center Nr. Stairs**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Lab table tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 122, 243, 241, 221, 221A, 223**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Lab table tops**
MATERIAL LOCATION: **Rooms 122, 243, 241, 221, 221A, 223**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Ceramic floor grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Pool, 1st & 2nd Fl. Girl's/Boy's Rest Rooms and Lockers**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Ceramic floor grout**
MATERIAL LOCATION: **Pool, 1st & 2nd Fl. Girl's/Boy's Rest Rooms and Lockers**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White-Gray Spec's Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Front Entrance Hallway**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White-Gray Spec's Floor Tile**
MATERIAL LOCATION: **Front Entrance Hallway**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82M**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White-Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Front Entrance Hallway**

MATERIAL QUANTITY: **3800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **82M**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White-Gray Floor Tile Mastic**
MATERIAL LOCATION: **Front Entrance Hallway**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 109 and 205**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile**
MATERIAL LOCATION: **Rooms 109 and 205**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 109 and 205**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile**
MATERIAL LOCATION: **Rooms 109 and 205**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tiles**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Beige speckled floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Beige speckled floor tile**
MATERIAL LOCATION: **Cafeteria**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Mag block duct insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen & Storage area in Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Mag block duct insulation**

MATERIAL LOCATION: **Kitchen & Storage area in Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **Pink/White flooring material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 241, 122, 142,**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **Pink/White flooring material**
MATERIAL LOCATION: **Rooms 241, 122, 142,**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB**
MATERIAL DESCRIPTION: **Mastic associate w/ HA# AA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 221, 241, 122, 142, 222, 242**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **BB**

MATERIAL DESCRIPTION: **Mastic associate w/ HA# AA**

MATERIAL LOCATION: **Rooms 221, 241, 122, 142, 222, 242**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CC**
MATERIAL DESCRIPTION: **Panels over moveable doors room divide**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **123/121, 132/134, 152/154,232/234, 252/254, House commons 1,2 and Gym**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **CC**
MATERIAL DESCRIPTION: **Panels over moveable doors room divide**
MATERIAL LOCATION: **123/121, 132/134, 152/154,232/234, 252/254, House commons 1,2 and Gym**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/ Blue Streak Floor Tile**
MATERIAL LOCATION: **Floor 2 Locker Rooms , 205, 252, 109**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022** _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/ Blue Streak Floor Tile**
MATERIAL LOCATION: **Floor 2 Locker Rooms , 205, 252, 109**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **Gray pattern carpet mastic**

MATERIAL LOCATION: **Room 143 Offices**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **Gray and Blue Streaked Carpet Mastic**
MATERIAL LOCATION: **Gurley Center**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **Gray and Blue Streaked Carpet Mastic**

MATERIAL LOCATION: **Gurley Center**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS:

SF

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **Wood Tongue and Groove Flooring**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **Wood Tongue and Groove Flooring**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mottled Floor Tile**
MATERIAL LOCATION: **2nd Floor Locker Rooms, 205, 252, 109**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White w/ Tan Streak Floor Tile**

MATERIAL LOCATION: **Room 110, 109B**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **Pool heater duct insulation**
MATERIAL LOCATION: **Pump Room**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **TSI** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACBM**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **2** DAMAGE REASON:
DAMAGE UNITS: **LF**

COMMENTS:
Damage in Pump Room

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **Pool heater duct insulation**

MATERIAL LOCATION: **Pump Room**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **2** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM contact

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Brown carpet adhesive**

MATERIAL LOCATION: **Room 231, 233, 253, 251, 250, 248, 247, 244, 242, 240, 200, 218, 220, 220A, 225, 226, 209, 214, 210, 213, 211, 220 Storage, 201, 202, 153, 154, Receiving Room 106, 133, 134, 127, 128**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **Mastic assoc. W/ 12" x 12" White w/ Dark Gray Streak Floor Tile**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **Blue carpet adhesive**
MATERIAL LOCATION: **Room 212**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Streak Floor Tile**
MATERIAL LOCATION: **Room 110, 109B**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Streak Floor Tile**

MATERIAL LOCATION: **Room 110, 109B**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Gray, Dark Gray and Yellow Floor Tile**
MATERIAL LOCATION: **2nd Floor Locker Rooms, 205, 252 109**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022** _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Gray, Dark Gray and Yellow Floor Tile**
MATERIAL LOCATION: **2nd Floor Locker Rooms, 205, 252 109**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Light Gray Mottled Floor Tile**
MATERIAL LOCATION: **Room 147**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Light Gray Mottled Floor Tile**

MATERIAL LOCATION: **Room 147**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **2'x2' rough texture ceiling tile**
MATERIAL LOCATION: **Room 241A, 221A, 143 Offices**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **12" x 12" White w/ Dark Gray Streak Floor Tile**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **12" x 12" White w/ Dark Gray Streak Floor Tile**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12" x 12" Gray Mottled Floor Tile**
MATERIAL LOCATION: **2nd Floor Locker Rooms, 205, 252, 109**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **9/21/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **Fire door**
MATERIAL LOCATION: **Floor 1 Book Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **3** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in Floor 1 Book Room

Inspector's Signature: _____



Date: 09/21/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **Fire door**

MATERIAL LOCATION: **Floor 1 Book Room**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **9/30/2022**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Mottled Floor Tile**

MATERIAL LOCATION: **Room 147**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

APPENDIX B

Inspector and Management Planner Licenses



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Joshua Karlson

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 4/8/2022

Exam Date: 4/8/2022

Expiration Date: 4/8/2023

Certificate Number: BIR2204081028

Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER

100 - 20129

ISSUED

4/15/2022

EXPIRES

05/15/2023

**JOSHUA E KARLSON
15504 S LAVERGNE AVE
OAK FOREST, IL 60452**

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

4/8/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER

3/28/2023

AIR SAMPLING PROFESSIONAL


Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid

training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed