

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2050
SCHOOL NAME: Air Force High School (formerly Abbott School)
ADDRESS OF SCHOOL: 3630 S. Wells
CITY: Chicago, IL, 60609

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/5/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/30/2022 ENROLLMENT 134
IDPH INSPECTOR LICENSE NUMBER: 100-19554
IDPH LICENSED INSPECTOR NAME (Please Print): Carol Ashman
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



10/12/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Air Force High School (formerly Abbott School)

3630 S. Wells
Chicago, IL, 60609

Unit: 45231
Building ID: 2010

IDPH ID Number: 14-016-2990-2050

REPORT DATE:

Wednesday, October 12, 2022

Prepared for:

**Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

10/12/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 45231 Region: 04 IDPH ID: 14-016-2990-2050

School: Air Force High School (formerly Abbott School) Building ID: 2010

Address: 3630 S. Wells

Chicago, IL, 60609

Building Contact: McNamara, Sean

Contact Phone: 7737096980

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/30/2022

Review Date: 10/12/2022

Inspector: Carol Ashman

Inspector IDPH License: 100-19554

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 12, 2022

RE: Air Force High School (formerly Abbott School), Unit 45231
3630 S. Wells
Chicago, IL, 60609

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Air Force High School (formerly Abbott School) , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Air Force High School (formerly Abbott School), there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Air Force High School Unit: 45231 Region: 04
(formerly Abbott School)
Address: 3630 S. Wells Chicago, IL, 60609
IDPH ID: 14-016-2990-2050 Building ID: 2010
Contact: McNamara, Sean Phone: 7737096980

2. Description of Facility

Original Construction: 1954 Additional Construction: 1949,1961
Total Square Footage: 11792 No of Floors: 2
Current Occupancy: 134

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Carol Ashman


Inspector IDPH license # 100-19554
Reinspection Date: 9/30/2022

Signature:
Date: 9/30/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature: 
Date: 10/12/2022

7. Review Date: 10/12/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/12/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Air Force High School (formerly Abbott School). This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2010:

146	12" x 12" Light Beige w/ White Streaks Floor Tile
147	12" x 12" Light Beige w/ White Streaks Floor Tile Mastic
148	Black science lab counter tables
149	Black science lab counter
150	12"x 12" Gray w/ Black Spots Floor Tile
151	12"x 12" Gray w/ Black Spots Floor Tile Mastic
152	Vinyl Blue, gray and Light gray
153	Blue carpet Mastic
88	9" x 9" Cream Floor Tile w/ White Streaks

- 89 9" x 9" Cream Floor Tile w/ White Streaks Mastic
- 90 9" x 9" Light Brown Mottled Floor Tile
- 91 9" x 9" Light Brown Mottled Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 2010:

146	12" x 12" Light Beige w/ White Streaks Floor Tile
147	12" x 12" Light Beige w/ White Streaks Floor Tile Mastic
148	Black science lab counter tables
149	Black science lab counter
150	12"x 12" Gray w/ Black Spots Floor Tile
151	12"x 12" Gray w/ Black Spots Floor Tile Mastic
152	Vinyl Blue, gray and Light gray
153	Blue carpet Mastic
74	9" x 9" Light Brown Floor Tile
88	9" x 9" Cream Floor Tile w/ White Streaks
89	9" x 9" Cream Floor Tile w/ White Streaks Mastic
90	9" x 9" Light Brown Mottled Floor Tile
91	9" x 9" Light Brown Mottled Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

082	12" x 12" Sandy Beige Floor Tile
086	12" x 12" Off-White Floor Tile
096	Vault door insulation
107	Roofing materials (non ahera)
108	Roofing materials (non ahera)
109	Roofing materials (non ahera)
110	Interior window caulk
111	12" x 12" Light Beige w/Brown & White. Streaks floor tile
112	12" x 12" White w/ Off-White & Beige Streaks Floor Tile
113	Mastic for HA 111 & HA 112 Checkerboard Floor Tile Pattern
114	12" x 12" Red Floor Tile
115	12" x 12" Red Floor Tile Mastic
116	12" x 12" Blue Floor Tile
117	12" x 12" Blue Floor Tile Mastic
118	Green carpet adhesive
119	Acoustical ceiling
120	12" x 12" Beige mix Floor Tile
121	Mastic associated w/ 12" x 12" Beige mix Floor Tile
122	Red carpet adhesive
123	Black board/ marker board adhesive
124	Gray and Black Mix Terrazzo Flooring
125	12" x 12" Tand w/Brown and White Streaks Floor Tile
126	12" x 12" Tand w/Brown and White Streaks Floor Tile Mastic
127	Cork board adhesive
128	Green carpet adhesive
139	Transite laboratory countertop
142	Blue sheet flooring
143	Blue sheet flooring mastic
144	Transite electrical panel
146	12" x 12" Light Beige w/ White Streaks Floor Tile
147	12" x 12" Light Beige w/ White Streaks Floor Tile Mastic
148	Black science lab counter tables
149	Black science lab counter
150	12"x 12" Gray w/ Black Spots Floor Tile
151	12"x 12" Gray w/ Black Spots Floor Tile Mastic
152	Vinyl Blue, gray and Light gray

153	Blue carpet Mastic
88	9" x 9" Cream Floor Tile w/ White Streaks
89	9" x 9" Cream Floor Tile w/ White Streaks Mastic
90	9" x 9" Light Brown Mottled Floor Tile
91	9" x 9" Light Brown Mottled Floor Tile Mastic

The following areas were deemed to be inaccessible:

075	Mastic on 9" x 9" Light Brown Floor Tile
083	Mastic on 12" x 12" Sandy Beige Floor Tile
085	Mastic on 9" x 9" Orange Floor Tile
087	Mastic on 12" x 12" Off-White Floor Tile
145	Electrical Wiring Associated w/ Wall Mounted Clocks

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Carol Ashman, IDPH License # 100-19554. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Air Force High School (formerly Abbott School) Building 2010 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Air Force High School (formerly Abbott School) Unit 45231 Building ID 2010
 Address 3630 S. Wells Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room										
137	Gray sink undercoating			Rooms 128, 130, and 133	NO_ACBM	MISC								
138	Carpet mastic			Rooms 134 and 212	NO_ACBM	MISC								
139	Transite laboratory countertop	400	SF	Rooms 109 and 226	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
140	Wood pattern sheet flooring			Gym	NO_ACBM	MISC								
141	Wood pattern sheet flooring mastic			Gym	NO_ACBM	MISC								
142	Blue sheet flooring		SF	Room 126	ASSUMED	MISC				SF				
143	Blue sheet flooring mastic		SF	Room 126	ASSUMED	MISC				SF				
144	Transite electrical panel	200	SF	Basement Electrical Vault	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
145	Electrical Wiring Associated w/ Wall Mounted Clocks	150	LF	Throughout Building	CHR	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
146	12" x 12" Light Beige w/ White Streaks Floor Tile	25,000	SF	Rooms 106, 104,101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
147	12" x 12" Light Beige w/ White Streaks Floor Tile Mastic	25,000	SF	Rooms 106, 104,101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
148	Black science lab counter tables	46	EA	Rooms 109, 226,	ASSUMED	MISC	N	NONE	0	EA	Yes	ACBM with the		LOW

Chicago Public Schools

School Air Force High School (formerly Abbott School) Unit 45231 Building ID 2010
Address 3630 S. Wells Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 9/30/2022
Inspector Name Carol Ashman
100-19554 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
006	
007	Not observed 2022
008	Not observed 2022
009	Not observed 2022
010	Not observed 2022
011	
012	Not observed 2022
013	Not observed 2022
014	Not observed 2022
015	
016	
017	Not observed 2022
018	
019	
020	
021	Not observed 2022
022	Not observed 2022
023	Not observed 2022
024	Not observed 2022
025	
026	Not observed 2022
027	Not observed 2022
028	Not observed 2022
029	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
030	
031	Not observed 2022
032	
033	Not observed 2022
034	
035	
036	
037	
038	
039	Not observed 2022
040	
041	
042	
043	Not observed 2022
044	Not observed 2022
045	
046	
047	
048	
049	Not observed 2022
050	Not observed 2022
051	
052	
053	
054	
055	Not observed 2022
056	
057	
058	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
059	
060	
061	Not observed 2022
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	Not observed 2022
072	Not observed 2022
073	
074	
075	
076	
077	
078	
079	Not observed 2022
080	
081	
082	
083	
084	Damage in engineer's corridor
085	
086	
087	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
088	
089	
090	
091	Not observed 2022
092	
093	
094	
095	
096	Not observed 2022
097	
098	
099	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	Not observed 2022
111	Not observed 2022
112	Not observed 2022
113	Not observed 2022
114	Not observed 2022
115	Not observed 2022
116	Not observed 2022

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
117	Not observed 2022
118	Not observed 2022
119	
120	Not observed 2022
121	Not observed 2022
122	Not observed 2022
123	
124	
125	Not observed 2022
126	Not observed 2022
127	Not observed 2022
128	Not observed 2022
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	Not observed 2022
143	Not observed 2022
144	
145	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
146	
147	
148	
149	
150	
151	
152	
153	
74	Damage in Store Room
88	
89	
90	
91	
B	Not observed 2022
C	Not observed 2022
D	Not observed 2022
E	Not observed 2022
F	Not observed 2022
G	Not observed 2022
H	Not observed 2022
I	Not observed 2022
J	
K	
L	Not observed 2022
L-1	Not observed 2022
M	Not observed 2022
N	Not observed 2022
O	
P	Not observed 2022

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
Q	Not observed 2022
R	Not observed 2022
S	Not observed 2022
T	
U	Not observed 2022

Table II

Management Planner's Review

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
006	12" x 12" Beige Floor Tile w/Brown & White Streaks			Material Not Present	No ACBM	MISC					
007	12" x 12" Light Brown Floor Tile w/Brown & White Streaks			Material Not Present	Chrysotile	MISC					Follow O&M Plan
008	Mastic on 9" x 9" Dark Brown Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
009	Mastic on 12" x 12" Dark Brown w/Brown & White Streaks Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
010	Mastic on 12" x 12" Light Brown w/Brown & White Streaks Floor Tile			1953 Building, Room 212A (MDF Room)	Chrysotile	MISC					Follow O&M Plan
011	Partition floor joiner compound			1946/53 Connection by Room 104	No ACBM	MISC					
012	12" x 12" Light Brown w/Brown & White Streaks Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
013	Mastic on 12" x 12" Light Brown w/Brown & White Streaks Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
014	Carpet adhesive			Material Not Present	Chrysotile	MISC					Follow O&M Plan
015	Black vinyl baseboard			Material Not Present	No ACBM	MISC					
016	Black vinyl baseboard adhesive			Material Not Present	No ACBM	MISC					
017	Sink bottom caulking			Material Not Present	Chrysotile	MISC					Follow O&M Plan
018	Plaster			1946 Building	No ACBM	SURFACE					
019	Interior brick walls			1946 Building	No ACBM	MISC					
020	Interior brick walls mortar			1946 Building	No ACBM	MISC					
021	12" x 12" Green Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
022	Mastic on 12" x 12" Green Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
023	Tar Paper and Mastic in Vault Closet Areas			Material Not Present	Chrysotile	MISC					Follow O&M Plan
024	Vibration isolator			1946 Building, Attic Above 200 and 201	No ACBM	MISC					
025	Fan unit door lining			1946 Building, Attic above 200 and 201	No ACBM	TSI					
026	Dirt on Floor			Material Not Present	Chrysotile	TSI					Follow O&M Plan
027	Mastic on 12" x 12" Beige w/Brown & White Streaks Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
028	Partition wall joiner compound			1946/1953 Buildings by 104 & 204	Chrysotile	MISC					Follow O&M Plan
029	12" x 12" Dark Gray w/White & Brown Streaks Floor Tile			Material Not Present	No ACBM	MISC					
030	12" x 12" Dark Gray Floor Tile w/Beige Mix			Material Not Present	No ACBM	MISC					
031	Mastic on 12" x 12" Dark Gray w/Beige Mix Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
032	12" x 12" Light Beige Mix Floor Tile			Material Not Present	No ACBM	MISC					
033	Mastic on 12" x 12" Light Beige Mix Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
034	12" x 12" Dark Pink Floor Tile			Material Not Present	No ACBM	MISC					
035	Adhesive for 12" x 12" Dark Pink Floor Tile			Material Not Present	No ACBM	MISC					
036	12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile			Material Not Present	No ACBM	MISC					
037	Mastic on 12" x 12" Dark Beige w/Brown & White Streaks Floor Tile			Material Not Present	No ACBM	MISC					
038	12" x 12" Light Gray Mix Floor Tile			Material Not Present	No ACBM	MISC					
039	Mastic on 12" x 12" Light Gray Mix Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
040	Gray and Yellow Mix Linoleum			Material Not Present	No ACBM	MISC					
041	Burlap w/ Adhesive Under Gray & Yellow Linoleum			Material Not Present	No ACBM	MISC					
042	12" x 12" Blue Floor Tile			Material Not Present	No ACBM	MISC					
043	Mastic on 12" x 12" Blue Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
044	Mastic 12" x 12" Dark Gray w/White & Brown Streaks Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
045	Interior brick			1953 Building	No ACBM	MISC					
046	Interior brick mortar			1953 Building	No ACBM	MISC					
047	Plaster			1953 Building	No ACBM	SURFACE					
048	Light gray vinyl baseboard			Material Not Present	No ACBM	MISC					
049	9" x 9" Brown Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
050	Mastic on 9" x 9" Brown Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
051	Desk top linoleum			Material Not Present	No ACBM	MISC					
052	Desk top linoleum adhesive			Material Not Present	No ACBM	MISC					
053	Black vinyl baseboard			Material Not Present	No ACBM	MISC					
054	Black vinyl baseboard adhesive			Material Not Present	No ACBM	MISC					
055	12" x 12" Dark Beige w/Brown & White Streaks Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
056	12" x 12" Blue Floor Tile			Material Not Present	No ACBM	MISC					
057	12" x 12" Blue Floor Tile Adhesive			Material Not Present	No ACBM	MISC					
058	Dark gray vinyl baseboard			Material Not Present	No ACBM	MISC					
059	Dark gray vinyl baseboard adhesive			Material Not Present	No ACBM	MISC					
060	12" x 12" Gray Mix Floor Tile			Material Not Present	No ACBM	MISC					
061	Mastic on 12" x 12" Gray Mix Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
062	Cork insulation			Fan Room by 214	No ACBM	TSI					
063	Vibration isolator			Fan Room by 214	No ACBM	MISC					
064	12" x 12" Beige Floor Tile w/Brown & White Streaks			Material Not Present	No ACBM	MISC					
065	Mastic on 12" x 12" Beige Floor Tile w/Brown & White Streaks			Material Not Present	No ACBM	MISC					
066	12" x 12" Light Brown Floor Tile			Material Not Present	No ACBM	MISC					
067	12" x 12" Light Brown Floor Tile Adhesive			Material Not Present	No ACBM	MISC					
068	12" x 12" Dark Pink Floor Tile			Material Not Present	No ACBM	MISC					
069	12" x 12" Dark Pink Floor Tile Adhesive			Material Not Present	No ACBM	MISC					
070	Fan unit door lining insulation			1946 Building, Basement	No ACBM	TSI					
071	9" x 9" Gray Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
072	Mastic on 12" x 12" Gray Floor Tile			Material Not Present	Chrysotile	MISC					Follow O&M Plan
073	Partition wall compound			Between 1953/60 Buildings, 1st and 2nd Floor Corridors	No ACBM	MISC					
074	9" x 9" Light Brown Floor Tile	200	SF	1960 Building, Store Room by Engineer's Office	Chrysotile	MISC	No	10	SF	6 ACBM with the potential for damage	
075	Mastic on 9" x 9" Light Brown Floor Tile	200	SF	1960 Building, Store Room by Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
076	Dark gray vinyl baseboard			Material Not Present	No ACBM	MISC					
077	Dark gray vinyl baseboard adhesive			Material Not Present	No ACBM	MISC					
078	Pump floor/unit caulk			1960 Building, Boiler Room	No ACBM	MISC					
079	Boiler gasket material			Material Not Present	Chrysotile	TSI					Follow O&M Plan
080	Interior brick			1960 Building	No ACBM	MISC					
081	Interior brick mortar			1960 Building	No ACBM	MISC					
082	12" x 12" Sandy Beige Floor Tile	250	SF	1960 Building, Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
083	Mastic on 12" x 12" Sandy Beige Floor Tile	250	SF	1960 Building, Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
084	9" x 9" Orange Floor Tile	108	SF	1960 Building, Engineer's Office Corridor	Chrysotile	MISC	No	3	SF	6 ACBM with the potential for damage	Repair
085	Mastic on 9" x 9" Orange Floor Tile	108	SF	1960 building, Engineer's Office Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
086	12" x 12" Off-White Floor Tile	30	SF	1960 Building, Store Room Bathroom Across from Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
087	Mastic on 12" x 12" Off-White Floor Tile	30	SF	1960 Building, Store Room Bathroom Across from Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
088	12" x 12" Light Gray Mix Floor Tile			Material Not Present	No ACBM	MISC					
089	12" x 12" Light Gray Mix Floor Tile Mastic			Material Not Present	No ACBM	MISC					
090	Radiator grill lining material			1960 Building	No ACBM	TSI					
091	Incinerator Gasket Material by Fire Hole			Material Not Present	Chrysotile	TSI					Follow O&M Plan
092	Incinerator interior brick			Material Not Present	No ACBM	MISC					
093	Incinerator ash chamber brick			Material Not Present	No ACBM	MISC					
094	Vibration isolator			1946 Building, Fan Unit	No ACBM	MISC					
095	White Chalky Material and Soil Mix			1953 Building, Unfinished Pipe Space	No ACBM	MISC					
096	Vault door insulation			Material Not Present	Assumed	MISC					Follow O&M Plan
097	Light gray vinyl baseboard			Material Not Present	No ACBM	MISC					
098	Light gray vinyl baseboard adhesive			Material Not Present	No ACBM	MISC					
099	Beaver board			Material Not Present	No ACBM	MISC					
100	Exterior brick			1946 Building	No ACBM	MISC					
101	Exterior brick mortar			1946 Building	No ACBM	MISC					
102	Exterior brick			1953 Building	No ACBM	MISC					
103	Exterior brick mortar			1953 Building	No ACBM	MISC					
104	Exterior brick			1960 Building	No ACBM	MISC					
105	Exterior brick mortar			1960 Building	No ACBM	MISC					
106	Exterior door caulk (non ahera)			1960 Building	No ACBM	MISC					
107	Roofing materials (non ahera)			1946 Building	Assumed	MISC					Follow O&M Plan
108	Roofing materials (non ahera)			1953 Building	Assumed	MISC					Follow O&M Plan
109	Roofing materials (non ahera)			1960 Building	Assumed	MISC					Follow O&M Plan
110	Interior window caulk			Material Not Present	Assumed	MISC					Follow O&M Plan
111	12" x 12" Light Beige w/Brown & White. Streaks floor tile			Material Not Present	Assumed	MISC					Follow O&M Plan
112	12" x 12" White w/ Off-White & Beige Streaks Floor Tile			Material Not Present	Assumed	MISC					Follow O&M Plan
113	Mastic for HA 111 & HA 112 Checkerboard Floor Tile Pattern			Material Not Present	Assumed	MISC					Follow O&M Plan
114	12" x 12" Red Floor Tile			Material Not Present	Assumed	MISC					Follow O&M Plan
115	12" x 12" Red Floor Tile Mastic			Material Not Present	Assumed	MISC					Follow O&M Plan
116	12" x 12" Blue Floor Tile			Material Not Present	Assumed	MISC					Follow O&M Plan
117	12" x 12" Blue Floor Tile Mastic			Material Not Present	Assumed	MISC					Follow O&M Plan
118	Green carpet adhesive			Material Not Present	Assumed	MISC					Follow O&M Plan

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
119	Acoustical ceiling	10,000	SF	Throughout Hallways of the 1960 Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
120	12" x 12" Beige mix Floor Tile			Material Not Present	Assumed	MISC					Follow O&M Plan
121	Mastic associated w/ 12" x 12" Beige mix Floor Tile			Material Not Present	Assumed	MISC					Follow O&M Plan
122	Red carpet adhesive			Material Not Present	Assumed	MISC					Follow O&M Plan
123	Black board/ marker board adhesive	5,000	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	Gray and Black Mix Terrazzo Flooring	4,000	SF	East Enterances and Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125	12" x 12" Tand w/Brown and White Streaks Floor Tile			Material Not Present	Assumed	MISC					Follow O&M Plan
126	12" x 12" Tand w/Brown and White Streaks Floor Tile Mastic			Material Not Present	Assumed	MISC					Follow O&M Plan
127	Cork board adhesive			Material Not Present	Assumed	MISC					Follow O&M Plan
128	Green carpet adhesive			Material Not Present	Assumed	MISC					Follow O&M Plan
129	12" x 12" White Mottled Floor Tile			Throughout Corridors, Classrooms, and Offices	No ACBM	MISC					
130	12" x 12" White Mottled Floor Tile Mastic			Throughout Corridors, Classrooms, and Offices	No ACBM	MISC					
131	12" x 12" Blue Mottled Floor Tile			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	No ACBM	MISC					
132	12" x 12" Blue Mottled Floor Tile Mastic			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	No ACBM	MISC					
133	2' x 2' Lay-in Ceiling Tile			First Floor Corridor	No ACBM	MISC					
134	2' x 4' Lay-in Ceiling Tile			Rooms 112A, 126, and 226	No ACBM	MISC					
135	4" Gray baseboard			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room	No ACBM	MISC					
136	4" Gray baseboard mastic			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage,	No ACBM	MISC					

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Lunch Room, and 2nd Floor Store Room							
137	Gray sink undercoating			Rooms 128, 130, and 133	No ACBM	MISC					
138	Carpet mastic			Rooms 134 and 212	No ACBM	MISC					
139	Transite laboratory countertop	400	SF	Rooms 109 and 226	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	Wood pattern sheet flooring			Gym	No ACBM	MISC					
141	Wood pattern sheet flooring mastic			Gym	No ACBM	MISC					
142	Blue sheet flooring		SF	Room 126	Assumed	MISC			SF		Follow O&M Plan
143	Blue sheet flooring mastic		SF	Room 126	Assumed	MISC			SF		Follow O&M Plan
144	Transite electrical panel	200	SF	Basement Electrical Vault	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	Electrical Wiring Associated w/ Wall Mounted Clocks	150	LF	Throughout Building	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
146	12" x 12" Light Beige w/ White Streaks Floor Tile	25,000	SF	Rooms 106, 104,101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201	Assumed	SURFACE	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
147	12" x 12" Light Beige w/ White Streaks Floor Tile Mastic	25,000	SF	Rooms 106, 104,101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148	Black science lab counter tables	46	EA	Rooms 109, 226, 216	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
149	Black science lab counter	90	SF	Rooms 109, 226, 216	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
150	12"x 12" Gray w/ Black Spots Floor Tile	800	SF	Rooms 133, 134	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151	12"x 12" Gray w/ Black Spots Floor Tile Mastic	800	SF	Rooms 133, 134	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152	Vinyl Blue, gray and Light gray	500	SF	Room 216	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153	Blue carpet Mastic	500	SF	Room 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	9" x 9" Light Brown Floor Tile	200	SF	1960 Building, Store Room by Engineer's Office	Chrysotile	MISC	No	10	SF	5 ACBM with potential for significant damage	Remove
88	9" x 9" Cream Floor Tile w/ White Streaks	10	SF	Engineer's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	9" x 9" Cream Floor Tile w/ White Streaks Mastic	10	SF	Engineer's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	9" x 9" Light Brown Mottled Floor Tile	4	SF	Engineer's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	9" x 9" Light Brown Mottled Floor Tile Mastic	5	SF	Engineer's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
B	Distributed Pipe Insulation on Floor			Material Not Present	Chrysotile	MISC					Follow O&M Plan
C	Aircell pipe insulation			1946 Building, Walls and Pipe Chases	Chrysotile	TSI					Follow O&M Plan
D	Joint Compound off Fiberglass Pipe Insulation			Material Not Present	Chrysotile	TSI					Follow O&M Plan
E	Joint compound off fiberglass pipe insulation			Material Not Present	Chrysotile	TSI					Follow O&M Plan
F	Distributed Pipe Insulation in Dirt on Floor			Material Not Present	Chrysotile	TSI					Follow O&M Plan
G	Distributed Pipe Insulation in Dirt on Floor			Material Not Present	Chrysotile	TSI					Follow O&M Plan
H	Aircell pipe insulation			Material Not Present	Chrysotile	TSI					Follow O&M Plan
I	Aircell pipe insulation			Material Not Present	Chrysotile	TSI					Follow O&M Plan
J	Paperwrap pipe insulation			1946 Building, Pipe Chases	No ACBM	TSI					
K	Hard Joint Compound off Paperwrap Pipe Insulation	75	LF	1946 Building, Walls and Pipe Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present	Chrysotile	TSI					Follow O&M Plan
L-1	Hard Joint Compound off Aircell Pipe Insulation			1946 Building, Walls and Pipe Chases	Chrysotile	TSI					Follow O&M Plan
M	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present	Chrysotile	TSI					Follow O&M Plan
N	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present	Chrysotile	TSI					Follow O&M Plan
O	Duct interior insulation			1960 Building, Boiler Room	No ACBM	TSI					
P	Magblock pipe insulation			Material Not Present	Amosite	TSI					Follow O&M Plan
Q	Magblock pipe insulation joint compound			Material Not Present	Chrysotile	TSI					Follow O&M Plan
R	Water tank insulation			Material Not Present	Chrysotile	TSI					Follow O&M Plan
S	Aircell duct insulation			Material Not Present	Chrysotile	TSI					Follow O&M Plan
T	Magblock insulation	15	LF	1946 Building, Coal/Ash Room Abandoned Mech. Unit	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
U	Duct insulation - black tar like adhesive			1953 Building, Unfinished Pipe Spaces	Chrysotile	TSI					Follow O&M Plan

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	10/12/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
006	
007	
008	
009	
010	
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
021	
022	
023	
024	
025	
026	
027	
028	
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
047	
048	
049	
050	
051	
052	
053	
054	
055	
056	
057	
058	
059	
060	
061	
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	
072	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
073	
074	
075	
076	
077	
078	
079	
080	
081	
082	
083	
084	
085	
086	
087	
088	
089	
090	
091	
092	
093	
094	
095	
096	
097	
098	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
099	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	
143	
144	
145	
146	
147	
148	
149	
150	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
151	
152	
153	
74	
88	
89	
90	
91	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
L-1	
M	
N	
O	
P	
Q	
R	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
S	
T	
U	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Brown & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Brown & White Streaks**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Brown & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Brown & White Streaks**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Dark Brown Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Dark Brown w/Brown & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Dark Brown w/Brown & White Streaks Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Brown w/Brown & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building, Room 212A (MDF Room)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Brown w/Brown & White Streaks Floor Tile**
MATERIAL LOCATION: **1953 Building, Room 212A (MDF Room)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **Partition floor joiner compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946/53 Connection by Room 104**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **Partition floor joiner compound**
MATERIAL LOCATION: **1946/53 Connection by Room 104**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/Brown & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/Brown & White Streaks Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Brown w/Brown & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Brown w/Brown & White Streaks Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **Carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **Carpet adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **Black vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **Black vinyl baseboard**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **Black vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **Black vinyl baseboard adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **Sink bottom caulking**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **Sink bottom caulking**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **1946 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **Interior brick walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **Interior brick walls**
MATERIAL LOCATION: **1946 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **Interior brick walls mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **Interior brick walls mortar**
MATERIAL LOCATION: **1946 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **021**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Green Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **Tar Paper and Mastic in Vault Closet Areas**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **Tar Paper and Mastic in Vault Closet Areas**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **Vibration isolator**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building, Attic Above 200 and 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **Vibration isolator**
MATERIAL LOCATION: **1946 Building, Attic Above 200 and 201**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **Fan unit door lining**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building, Attic above 200 and 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **Fan unit door lining**
MATERIAL LOCATION: **1946 Building, Attic above 200 and 201**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **Dirt on Floor**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **Dirt on Floor**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Beige w/Brown & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Beige w/Brown & White Streaks Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028**
MATERIAL DESCRIPTION: **Partition wall joiner compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946/1953 Buildings by 104 & 204**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **028**
MATERIAL DESCRIPTION: **Partition wall joiner compound**
MATERIAL LOCATION: **1946/1953 Buildings by 104 & 204**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/White & Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **029**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/White & Brown Streaks Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Floor Tile w/Beige Mix**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Floor Tile w/Beige Mix**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Dark Gray w/Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Dark Gray w/Beige Mix Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **032**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Mix Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Beige Mix Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **12" x 12" Dark Pink Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **12" x 12" Dark Pink Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **Adhesive for 12" x 12" Dark Pink Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **Adhesive for 12" x 12" Dark Pink Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Dark Beige w/Brown & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Dark Beige w/Brown & White Streaks Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Mix Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Gray Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Gray Mix Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **Gray and Yellow Mix Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **Gray and Yellow Mix Linoleum**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **Burlap w/ Adhesive Under Gray & Yellow Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **Burlap w/ Adhesive Under Gray & Yellow Linoleum**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **Mastic 12" x 12" Dark Gray w/White & Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **Mastic 12" x 12" Dark Gray w/White & Brown Streaks Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Interior brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Interior brick**
MATERIAL LOCATION: **1953 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Interior brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Interior brick mortar**
MATERIAL LOCATION: **1953 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **1953 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **Light gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **Light gray vinyl baseboard**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Brown Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **Desk top linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **Desk top linoleum**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **052**
MATERIAL DESCRIPTION: **Desk top linoleum adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **052**
MATERIAL DESCRIPTION: **Desk top linoleum adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Black vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Black vinyl baseboard**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **Black vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **Black vinyl baseboard adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **12" x 12" Dark Beige w/Brown & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **12" x 12" Dark Beige w/Brown & White Streaks Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **056**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **057**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **057**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **058**
MATERIAL DESCRIPTION: **Dark gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **058**
MATERIAL DESCRIPTION: **Dark gray vinyl baseboard**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **Dark gray vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **Dark gray vinyl baseboard adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **061**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Gray Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **061**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Gray Mix Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **062**
MATERIAL DESCRIPTION: **Cork insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fan Room by 214**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **062**
MATERIAL DESCRIPTION: **Cork insulation**
MATERIAL LOCATION: **Fan Room by 214**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **063**
MATERIAL DESCRIPTION: **Vibration isolator**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fan Room by 214**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **063**
MATERIAL DESCRIPTION: **Vibration isolator**
MATERIAL LOCATION: **Fan Room by 214**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **064**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Brown & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **064**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Brown & White Streaks**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **065**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Beige Floor Tile w/Brown & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **065**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Beige Floor Tile w/Brown & White Streaks**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **066**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **066**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **067**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **067**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **068**
MATERIAL DESCRIPTION: **12" x 12" Dark Pink Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **068**
MATERIAL DESCRIPTION: **12" x 12" Dark Pink Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **069**
MATERIAL DESCRIPTION: **12" x 12" Dark Pink Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **069**
MATERIAL DESCRIPTION: **12" x 12" Dark Pink Floor Tile Adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **070**
MATERIAL DESCRIPTION: **Fan unit door lining insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building, Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **070**
MATERIAL DESCRIPTION: **Fan unit door lining insulation**
MATERIAL LOCATION: **1946 Building, Basement**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **071**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **071**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **072**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **072**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Gray Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **073**
MATERIAL DESCRIPTION: **Partition wall compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Between 1953/60 Buildings, 1st and 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **073**
MATERIAL DESCRIPTION: **Partition wall compound**
MATERIAL LOCATION: **Between 1953/60 Buildings, 1st and 2nd Floor Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **074**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1960 Building, Store Room by Engineer's Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **074**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile**
MATERIAL LOCATION: **1960 Building, Store Room by Engineer's Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **075**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Light Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 Building, Store Room by Engineer's Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **075**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Light Brown Floor Tile**
MATERIAL LOCATION: **1960 Building, Store Room by Engineer's Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **076**
MATERIAL DESCRIPTION: **Dark gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **076**
MATERIAL DESCRIPTION: **Dark gray vinyl baseboard**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **077**
MATERIAL DESCRIPTION: **Dark gray vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **077**
MATERIAL DESCRIPTION: **Dark gray vinyl baseboard adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **078**
MATERIAL DESCRIPTION: **Pump floor/unit caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 Building, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **078**
MATERIAL DESCRIPTION: **Pump floor/unit caulk**
MATERIAL LOCATION: **1960 Building, Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **079**
MATERIAL DESCRIPTION: **Boiler gasket material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **079**
MATERIAL DESCRIPTION: **Boiler gasket material**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **080**
MATERIAL DESCRIPTION: **Interior brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **080**
MATERIAL DESCRIPTION: **Interior brick**
MATERIAL LOCATION: **1960 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **081**
MATERIAL DESCRIPTION: **Interior brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **081**
MATERIAL DESCRIPTION: **Interior brick mortar**
MATERIAL LOCATION: **1960 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **082**
MATERIAL DESCRIPTION: **12" x 12" Sandy Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 Building, Engineer's Office**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **082**
MATERIAL DESCRIPTION: **12" x 12" Sandy Beige Floor Tile**
MATERIAL LOCATION: **1960 Building, Engineer's Office**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **083**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Sandy Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 Building, Engineer's Office**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **083**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Sandy Beige Floor Tile**
MATERIAL LOCATION: **1960 Building, Engineer's Office**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **084**
MATERIAL DESCRIPTION: **9" x 9" Orange Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1960 Building, Engineer's Office Corridor**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in engineeer's corridor**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **084**
MATERIAL DESCRIPTION: **9" x 9" Orange Floor Tile**
MATERIAL LOCATION: **1960 Building, Engineer's Office Corridor**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **085**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Orange Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 building, Engineer's Office Corridor**

MATERIAL QUANTITY: **108**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **085**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Orange Floor Tile**
MATERIAL LOCATION: **1960 building, Engineer's Office Corridor**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **086**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 Building, Store Room Bathroom Across from Engineer's Office**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **086**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile**
MATERIAL LOCATION: **1960 Building, Store Room Bathroom Across from Engineer's Office**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **087**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Off-White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 Building, Store Room Bathroom Across from Engineer's Office**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **087**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" Off-White Floor Tile**
MATERIAL LOCATION: **1960 Building, Store Room Bathroom Across from Engineer's Office**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **088**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **088**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Mix Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **089**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **089**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Mix Floor Tile Mastic**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **090**
MATERIAL DESCRIPTION: **Radiator grill lining material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **090**
MATERIAL DESCRIPTION: **Radiator grill lining material**
MATERIAL LOCATION: **1960 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **091**
MATERIAL DESCRIPTION: **Incinerator Gasket Material by Fire Hole**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **091**
MATERIAL DESCRIPTION: **Incinerator Gasket Material by Fire Hole**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **092**
MATERIAL DESCRIPTION: **Incinerator interior brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **092**
MATERIAL DESCRIPTION: **Incinerator interior brick**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **093**
MATERIAL DESCRIPTION: **Incinerator ash chamber brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **093**
MATERIAL DESCRIPTION: **Incinerator ash chamber brick**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **094**
MATERIAL DESCRIPTION: **Vibration isolator**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building, Fan Unit**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **094**
MATERIAL DESCRIPTION: **Vibration isolator**
MATERIAL LOCATION: **1946 Building, Fan Unit**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **095**
MATERIAL DESCRIPTION: **White Chalky Material and Soil Mix**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building, Unfinished Pipe Space**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **095**
MATERIAL DESCRIPTION: **White Chalky Material and Soil Mix**
MATERIAL LOCATION: **1953 Building, Unfinished Pipe Space**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **096**
MATERIAL DESCRIPTION: **Vault door insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **096**
MATERIAL DESCRIPTION: **Vault door insulation**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **097**
MATERIAL DESCRIPTION: **Light gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **097**
MATERIAL DESCRIPTION: **Light gray vinyl baseboard**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **098**
MATERIAL DESCRIPTION: **Light gray vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **098**
MATERIAL DESCRIPTION: **Light gray vinyl baseboard adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **099**
MATERIAL DESCRIPTION: **Beaver board**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **099**
MATERIAL DESCRIPTION: **Beaver board**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **Exterior brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **Exterior brick**
MATERIAL LOCATION: **1946 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Exterior brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Exterior brick mortar**
MATERIAL LOCATION: **1946 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **Exterior brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **Exterior brick**
MATERIAL LOCATION: **1953 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Exterior brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Exterior brick mortar**
MATERIAL LOCATION: **1953 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **Exterior brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **Exterior brick**
MATERIAL LOCATION: **1960 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **Exterior brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **Exterior brick mortar**
MATERIAL LOCATION: **1960 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Exterior door caulk (non ahera)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Exterior door caulk (non ahera)**
MATERIAL LOCATION: **1960 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Roofing materials (non ahera)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Roofing materials (non ahera)**
MATERIAL LOCATION: **1946 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **Roofing materials (non ahera)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **Roofing materials (non ahera)**
MATERIAL LOCATION: **1953 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **Roofing materials (non ahera)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **Roofing materials (non ahera)**
MATERIAL LOCATION: **1960 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Interior window caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Interior window caulk**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/Brown & White. Streaks floor tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/Brown & White. Streaks floor tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12" x 12" White w/ Off-White & Beige Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12" x 12" White w/ Off-White & Beige Streaks Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **Mastic for HA 111 & HA 112 Checkerboard Floor Tile Pattern**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **Mastic for HA 111 & HA 112 Checkerboard Floor Tile Pattern**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **Green carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **Green carpet adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Acoustical ceiling**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Hallways of the 1960 Building**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Acoustical ceiling**
MATERIAL LOCATION: **Throughout Hallways of the 1960 Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **12" x 12" Beige mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **12" x 12" Beige mix Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **Mastic associated w/ 12" x 12" Beige mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **Mastic associated w/ 12" x 12" Beige mix Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Red carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Red carpet adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **Black board/ marker board adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **Black board/ marker board adhesive**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **Gray and Black Mix Terrazzo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **East Enterances and Stairwells**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **Gray and Black Mix Terrazzo Flooring**
MATERIAL LOCATION: **East Enterances and Stairwells**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **12" x 12" Tand w/Brown and White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **12" x 12" Tand w/Brown and White Streaks Floor Tile**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **12" x 12" Tand w/Brown and White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **12" x 12" Tand w/Brown and White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **Cork board adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **Cork board adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **Green carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **Green carpet adhesive**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**
MATERIAL DESCRIPTION: **12" x 12" White Mottled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Corridors, Classrooms, and Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **129**
MATERIAL DESCRIPTION: **12" x 12" White Mottled Floor Tile**
MATERIAL LOCATION: **Throughout Corridors, Classrooms, and Offices**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **12" x 12" White Mottled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Corridors, Classrooms, and Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **12" x 12" White Mottled Floor Tile Mastic**
MATERIAL LOCATION: **Throughout Corridors, Classrooms, and Offices**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **12" x 12" Blue Mottled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **12" x 12" Blue Mottled Floor Tile**
MATERIAL LOCATION: **Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **12" x 12" Blue Mottled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **12" x 12" Blue Mottled Floor Tile Mastic**
MATERIAL LOCATION: **Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **2' x 2' Lay-in Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **2' x 2' Lay-in Ceiling Tile**
MATERIAL LOCATION: **First Floor Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 112A, 126, and 226**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Tile**
MATERIAL LOCATION: **Rooms 112A, 126, and 226**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **4" Gray baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226,
228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd
Floor Store Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **4" Gray baseboard**
MATERIAL LOCATION: **Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **4" Gray baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **4" Gray baseboard mastic**
MATERIAL LOCATION: **Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **Gray sink undercoating**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 128, 130, and 133**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **Gray sink undercoating**
MATERIAL LOCATION: **Rooms 128, 130, and 133**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 134 and 212**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **Carpet mastic**
MATERIAL LOCATION: **Rooms 134 and 212**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **Transite laboratory countertop**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 109 and 226**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **Transite laboratory countertop**
MATERIAL LOCATION: **Rooms 109 and 226**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **Wood pattern sheet flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **Wood pattern sheet flooring**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **Wood pattern sheet flooring mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **Wood pattern sheet flooring mastic**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **Blue sheet flooring**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 126**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **Blue sheet flooring**
MATERIAL LOCATION: **Room 126**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **Blue sheet flooring mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 126**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **Blue sheet flooring mastic**
MATERIAL LOCATION: **Room 126**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **Transite electrical panel**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Electrical Vault**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **Transite electrical panel**
MATERIAL LOCATION: **Basement Electrical Vault**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **Electrical Wiring Associated w/ Wall Mounted Clocks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **Electrical Wiring Associated w/ Wall Mounted Clocks**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Distributed Pipe Insulation on Floor**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Distributed Pipe Insulation on Floor**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building, Walls and Pipe Chases**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
MATERIAL LOCATION: **1946 Building, Walls and Pipe Chases**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Joint Compound off Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Joint Compound off Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Joint compound off fiberglass pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Joint compound off fiberglass pipe insulation**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Distributed Pipe Insulation in Dirt on Floor**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Distributed Pipe Insulation in Dirt on Floor**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Distributed Pipe Insulation in Dirt on Floor**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Distributed Pipe Insulation in Dirt on Floor**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building, Pipe Chases**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**
MATERIAL LOCATION: **1946 Building, Pipe Chases**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Hard Joint Compound off Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1946 Building, Walls and Pipe Chases**

MATERIAL QUANTITY: **75**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Hard Joint Compound off Paperwrap Pipe Insulation**
MATERIAL LOCATION: **1946 Building, Walls and Pipe Chases**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L-1**
MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building, Walls and Pipe Chases**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **L-1**
MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**
MATERIAL LOCATION: **1946 Building, Walls and Pipe Chases**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Duct interior insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 Building, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **O**
MATERIAL DESCRIPTION: **Duct interior insulation**
MATERIAL LOCATION: **1960 Building, Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Magblock pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Amosite** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Magblock pipe insulation**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **Magblock pipe insulation joint compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** REVIEW DATE: **10/12/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **Magblock pipe insulation joint compound**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **Water tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Water tank insulation**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Aircell duct insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____

Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Aircell duct insulation**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **Magblock insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1946 Building, Coal/Ash Room Abandoned Mech. Unit**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **Magblock insulation**
MATERIAL LOCATION: **1946 Building, Coal/Ash Room Abandoned Mech. Unit**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School (formerly
Abbott School)** INSPECTION DATE: **9/30/2022**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**
MATERIAL DESCRIPTION: **Duct insulation - black tar like adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building, Unfinished Pipe Spaces**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **U**
MATERIAL DESCRIPTION: **Duct insulation - black tar like adhesive**
MATERIAL LOCATION: **1953 Building, Unfinished Pipe Spaces**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **147**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 106, 104,101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **SURFACE** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **147**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 106, 104,101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **151**
MATERIAL DESCRIPTION: **12"x 12" Gray w/ Black Spots Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 133, 134**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **10/12/2022**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **151**

MATERIAL DESCRIPTION: **12"x 12" Gray w/ Black Spots Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 133, 134**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **152**
MATERIAL DESCRIPTION: **Vinyl Blue, gray and Light gray**
MATERIAL LOCATION: **Room 216**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **10/12/2022**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **152**

MATERIAL DESCRIPTION: **Vinyl Blue, gray and Light gray**

MATERIAL LOCATION: **Room 216**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/ White Streaks Mastic**
MATERIAL LOCATION: **Engineer's office**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **10/12/2022**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/ White Streaks Mastic**

MATERIAL LOCATION: **Engineer's office**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/ White Streaks**
MATERIAL LOCATION: **Engineer's office**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/ White Streaks**

MATERIAL LOCATION: **Engineer's office**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **150**
MATERIAL DESCRIPTION: **12"x 12" Gray w/ Black Spots Floor Tile**
MATERIAL LOCATION: **Rooms 133, 134**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **10/12/2022**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **150**

MATERIAL DESCRIPTION: **12"x 12" Gray w/ Black Spots Floor Tile**

MATERIAL LOCATION: **Rooms 133, 134**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Mottled Floor Tile**
MATERIAL LOCATION: **Engineer's office**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Mottled Floor Tile**

MATERIAL LOCATION: **Engineer's office**

MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **149**
MATERIAL DESCRIPTION: **Black science lab counter**
MATERIAL LOCATION: **Rooms 109, 226, 216**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **10/12/2022**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **149**

MATERIAL DESCRIPTION: **Black science lab counter**

MATERIAL LOCATION: **Rooms 109, 226, 216**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **148**
MATERIAL DESCRIPTION: **Black science lab counter tables**
MATERIAL LOCATION: **Rooms 109, 226, 216**
MATERIAL QUANTITY: **46** MATERIAL UNITS: **EA**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **EA**
COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **10/12/2022**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **148**

MATERIAL DESCRIPTION: **Black science lab counter tables**

MATERIAL LOCATION: **Rooms 109, 226, 216**

MATERIAL QUANTITY: **46** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Mottled Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's office**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Engineer's office**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile**
MATERIAL LOCATION: **1960 Building, Store Room by Engineer's Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Chrysotile**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **10** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in Store Room

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **10/12/2022**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile**

MATERIAL LOCATION: **1960 Building, Store Room by Engineer's Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **153**
MATERIAL DESCRIPTION: **Blue carpet Mastic**
MATERIAL LOCATION: **Room 212**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **153**

MATERIAL DESCRIPTION: **Blue carpet Mastic**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Air Force High School** INSPECTION DATE: **9/30/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **146**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ White Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 106, 104,101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **SURFACE** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Air Force High School** REVIEW DATE: **10/12/2022**
(formerly Abbott School)
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **146**
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ White Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 106, 104,101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

APPENDIX B

Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otsafety.com

2022

OCCUPATIONAL TRAINING & SUPPLY, INC.



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Carol Ashman

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 5/16/2022

Exam Date: 5/16/2022




Expiration Date: 5/16/2023

Certificate Number: BIR2205161413


Kathy Desalvo, Director

Carol Ashman

Illinois Licensed Building Inspector

 ILLINOIS DEPARTMENT OF PUBLIC HEALTH IDPH INSPECTING EVALUATING EMPOWERING	ASBESTOS PROFESSIONAL LICENSE	
ID NUMBER 100 - 19554	ISSUED 4/19/2022	EXPIRES 05/15/2023
CAROL L ASHMAN 1633 Mc KAY ST WAUKEGAN, IL 60087 Environmental Health		

ENDORSEMENTS	TC EXPIRES
INSPECTOR	5/7/2022
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/28/2023

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed