

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-048Y  
SCHOOL NAME: Hancock High School  
ADDRESS OF SCHOOL: 4034 W. 56th St.  
CITY: Chicago, IL, 60652

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/16/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 12/8/2022 ENROLLMENT 1000  
IDPH INSPECTOR LICENSE NUMBER: 100-07278  
IDPH LICENSED INSPECTOR NAME (Please Print): Kenneth Karuhn  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



12/20/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Hancock High School**

4034 W. 56th St.  
Chicago, IL, 60652

Unit: 46021  
Building ID: 1200

IDPH ID Number: 14-016-2990-048Y

**REPORT DATE:**

Tuesday, December 20, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

12/20/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 46021            Region: 04            IDPH ID: 14-016-2990-048Y

School: Hancock High School            Building ID: 1200

Address: 4034 W. 56th St.

Chicago, IL, 60652

Building Contact: Snodgrass, James

Contact Phone: 7737106525

Current Building Owners: Chicago Public Schools

Reinspection Date: 12/8/2022

Review Date: 12/20/2022

Inspector: Kenneth Karuhn

Inspector IDPH License: 100-07278

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: December 20, 2022

RE: Hancock High School, Unit 46021  
4034 W. 56th St.  
Chicago, IL, 60652

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Hancock High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Hancock High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Hancock High School                      Unit: 46021                      Region: 04  
Address: 4034 W. 56th St.                      Chicago, IL, 60652  
IDPH ID: 14-016-2990-048Y                      Building ID: 1200  
Contact: Snodgrass, James                      Phone: 7737106525

### 2. Description of Facility

Original Construction: 1956                      Additional Construction:  
Total Square Footage: 169086                      No of Floors: 4  
Current Occupancy: 1000

### 3. LEA Designated Person

Contact: Richard J.Schleyer                      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602


### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900                      Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Kenneth Karuhn


Inspector IDPH license # 100-07278  
Reinspection Date: 12/8/2022

Signature:   
Date: 12/8/2022

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


Signature:   
Date: 12/20/2022

### 7. Review Date: 12/20/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 12/20/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Hancock High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1200:

009	9" x 9" Green w/White Floor Tile
066	9" x 9" Green w/White Vinyl Floor Tile MASTIC FOR HA #9
132	2' x 2' Multi colored Tile
133	2' x 2' Multi Colored Tile Mastic
134	Stairwell flooring
135	Stairwell flooring mastic
136	4 Inch gray mapboard
137	4 Inch gray mapboard Mastic
138	2' x 4' Ceiling Tile (White)

139	2' x 2' Ceiling Tile (White)
140	Drywall
141	Drywall compound
142	12" x 12" Gray w/ Black and White Specks Floor Tile
143	12" x 12" Light Blue w/ Black and White Specks Floor Tile
144	12" x 12" Gray w/ Black and White Specks & Light Blue w/ Black and White Specks Floor Tile Mastic
145	Blue carpet mastic
19	Plaster



B. The following new homogenous areas have been identified for Building 1200:

142	12" x 12" Gray w/ Black and White Specks Floor Tile
143	12" x 12" Light Blue w/ Black and White Specks Floor Tile
144	12" x 12" Gray w/ Black and White Specks & Light Blue w/ Black and White Specks Floor Tile Mastic
145	Blue carpet mastic
18	Hard plaster
19	Plaster
33	Chiller Pump piping
34	Heat Pump insulation
35	Pipe joint compound

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

2	1' x 1' Acoustical Wall Tiles
001	1' x 1' ceiling tile REMOVED
004	1' x 1' Holed Act.
005	1' x 1' Metal Pan Act.
006	1' x 1' Ceiling Tile: pocked Act.
007	2' x 4' Ceiling Tile
009	9" x 9" Green w/White Floor Tile
011	9" x 9" Gray Floor tile
014	Cottage Cheese Sprayed on Material
017	Trowled on plaster mateial
018	Plaster
019	Plaster
020	Transite ceiling panels
022	Pipe joint compound
025	Exposed aircell
033	Chiller Pump piping
034	Heat Pump insulation
035	Pipe joint compound
043	Exposed aircell
045	Fire Curtain, baby Blue
046	Asbestos oven
047	Fire brick
050	9" x 9" Tan w/ Red & White: Floor Tile
051	9" x 9" Brown w/ Tan: Floor tile
060	Lab table tops
066	9" x 9" Green w/White Vinyl Floor Tile MASTIC FOR HA #9
072	9" x 9" Mastic for Type d Floor Tile
073	Mastic for Type E Floor Tile
074	Mastic for Type F Floor Tile
075	Mastic for Type G Floor Tile
079	Mortar for terrazzo
094	12" x 12" BLACK W/ White Streaks Vinyl Floor Tile
095	12" x 12" BLACK W/ White Streaks Vinyl Floor Tile-MASTIC
096	12" x 12" GRAYISH Green Vinyl Floor Tile
097	12" x 12" GRAYISH Green Vinyl Floor Tile- MASTIC
098	12" x 12" Blue Vinyl Floor Tile
099	12" x 12" Blue Vinyl Floor Tile-MASTIC
100	Plaster ceiling patch

101	Pipe joint compound
110	12" x 12" White & BLACK CHECKERBOARD Vinyl Floor Tile
111	12" x 12" White & BLACK CHECKERBOARD Vinyl Floor Tile-MASTIC
112	12" x 12" MARBLE LOOKING TAN Vinyl Floor Tile
113	12" x 12" MARBLE LOOKING BLACK Vinyl Floor Tile
114	Mastic for ha #112 & 113
115	9" x 9" Dark Green Vinyl Floor Tile
121	12" x 12" White w/ Red & Blue Specks Floor Tile
122	12" x 12" White w/ Red & Blue Specks Floor Tile Mastic
123	12" x 12" Purple Floor Tile
124	12" x 12" Purple Floor Tile Mastic
127	Gray mix terrazzo
128	Green carpet adhesive
129	Peach linoleum
130	Peach linoleum adhesive
131	Brown carpet adhesive
132	2' x 2' Multi colored Tile
133	2' x 2' Multi Colored Tile Mastic
134	Stairwell flooring
135	Stairwell flooring mastic
136	4 Inch gray mapboard
137	4 Inch gray mapboard Mastic
138	2' x 4' Ceiling Tile (White)
139	2' x 2' Ceiling Tile (White)
140	Drywall
141	Drywall compound
142	12" x 12" Gray w/ Black and White Specks Floor Tile
143	12" x 12" Light Blue w/ Black and White Specks Floor Tile
144	12" x 12" Gray w/ Black and White Specks & Light Blue w/ Black and White Specks Floor Tile Mastic
145	Blue carpet mastic
18	Hard plaster
19	Plaster
33	Chiller Pump piping
34	Heat Pump insulation
35	Pipe joint compound

The following areas were deemed to be inaccessible:

066	9" x 9" Green w/White Vinyl Floor Tile MASTIC FOR HA #9
097	12" x 12" GRAYISH Green Vinyl Floor Tile- MASTIC
099	12" x 12" Blue Vinyl Floor Tile-MASTIC
114	Mastic for ha #112 & 113
133	2' x 2' Multi Colored Tile Mastic
135	Stairwell flooring mastic
137	4 Inch gray mapboard Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Kenneth Karuhn, IDPH License # 100-07278. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Hancock High School Building 1200 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Hancock High School Unit 46021 Building ID 1200

Address 4034 W. 56th St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
2	1' x 1' Acoustical Wall Tiles	400	SF	Annex: Corridors, Lobby to auditorium, CL17, CL18,CL20,CL21, CL07,CL10	ASSUMED	MISC	Y	NONE	0	SF	No	ACBM with the potential for damage		LOW
001	1' x 1' ceiling tile REMOVED			music practice rooms	ASSUMED	MISC								
002	9" x 9" Brown w/White & red Streaks Floor Tile			original Building Cafeteria snack bar.	ABATED	MISC								
003	1' x 1' Solid Act Ceiling Tile			Rooms 307,309 (above new drop ceiling)	ABATED	MISC								
004	1' x 1' Holed Act.	5,000	SF	Original Building 1st, 2nd,3rd,4th floor & corridor (above new tile)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		MODERATE
005	1' x 1' Metal Pan Act.			Faculty Lounge, Faculty lounge	ASSUMED	MISC								
006	1' x 1' Ceiling Tile: pocked Act.		SF	Original Building: Ground Floor Lobby, south entrance.	ASSUMED	MISC				SF				
007	2' x 4' Ceiling Tile	900	SF	2nd floor Workout room above gym offices, library	ASSUMED	MISC	Y	NONE	0	SF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
008	9" x 9" Gray w/White Streaks Floor Tile			Annex: Halls & Room's 102,105,104,106,30 2,305,304,405,402, 406, 304, 400, 304, 303, 301, 102, 101, 104, 103, auditorium ramps & stairwells, 2nd floor MDF room	ABATED	MISC								
009	9" x 9" Green w/White Floor Tile	1,000	SF	Annex: auditorium stairwells & balcony	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		MODERATE
010	12" x 12" Gray Vinyl Floor Tile			Room 111, patch in 3rd floor hallway	ABATED	MISC								
011	9" x 9" Gray Floor tile	250	SF	ROOMS: A434 411, 415, 417, 419, 421, 422A, 442, 428, 412, 413, 406, A323, 225, 113, 150, MDF Room,	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Hancock High School Unit 46021 Building ID 1200  
 Address 4034 W. 56th St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				303 office, (new room numbers: see inspector's comment, freight elevator										
012	12x 12 tan vinyl floor tile			ROOMS: 420B, 420A, 424, 423, 425, 426, 422A, 422B, 405, 407, 305, 412,413,415,420,43 2,445,444,405,401,4 02,403,325,326,327 new Room,numbers - see ins's comments	ABATED	MISC								
013	9" x 9" Green Vinyl Floor Tile			Library entrance., ROOMS: 411, 416,424,427,430,43 3,435,312,314,315,3 18 - new room numbers - see inspector's comments	ABATED	MISC								
014	Cottage Cheese Sprayed on Material	100	SF	Annex: 2nd flr. Library	ASSUMED	SURFACE	Y	NONE	0	SF	No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
015	Cove base molding			Annex: Rooms 405,402,104,106,40 6,404,102,105,305,3 02,304 - room numbers - see inspector's comments	ABATED	MISC								
016	Exposed aicell pipe insulation			Original Building: Classrooms	ABATED	TSI								
017	Trowled on plaster mateial	1,000	SF	Annex: Lobby	ASSUMED	SURFACE	Y	NONE	0	SF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
018	Plaster	3,900	SF	Annex: 1st, 3rd, 4th floor Classrooms and Corridors	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
019	Plaster	8,000	SF	Original Building: Classrooms and crdrds	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
020	Transite ceiling panels	500	SF	Original Building: Gym Storage room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW















# Chicago Public Schools

School Hancock High School Unit 46021 Building ID 1200

Address 4034 W. 56th St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				FLOOR & WALLS										
118	9" x 9" Brown & TAN CHECKERBOARD Vinyl Floor Tile			ROOMS 401, 403, C406, C404, C204, C205 (new Room 415, corridor and Library work and storage rooms)	ABATED	MISC								
119	9" x 9" Brown & TAN CHECKERBOARD Vinyl Floor Tile-MASTIC			ROOMS 101, C406, C404, C204, C205 (new Room 415, corridor and Library work and storage rooms)	ABATED	MISC								
120	Gray carpet mastic			ROOM C307 (new room 342)	ABATED	MISC								
121	12" x 12" White w/ Red & Blue Specks Floor Tile		SF	Convent Basement	ASSUMED	MISC				SF				
122	12" x 12" White w/ Red & Blue Specks Floor Tile Mastic		SF	Convent Basement	ASSUMED	MISC				SF				
123	12" x 12" Purple Floor Tile		SF	Convent Basement	ASSUMED	MISC				SF				
124	12" x 12" Purple Floor Tile Mastic		SF	Convent Basement	ASSUMED	MISC				SF				
125	12" x 12" Light Gray w/ White Floor Tile			Room 412, 416	ABATED	MISC								
126	12" x 12" Light Gray w/White Floor Tile Mastic			Room 412, 416	ABATED	MISC								
127	Gray mix terrazzo	4,500	SF	1st, 2nd, 3rd Floor Hallways	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
128	Green carpet adhesive		SF	Room 310	ASSUMED	MISC				SF				
129	Peach linoleum		SF	Room 302, 308, 313, 315	ASSUMED	MISC				SF				
130	Peach linoleum adhesive		SF	Rooms 302, 308, 313, 315	ASSUMED	MISC				SF				
131	Brown carpet adhesive		SF	Main Office (101A) CLOSET	ASSUMED	MISC				SF				
132	2' x 2' Multi colored Tile	100,000	SF	Throughout 4th Floor, Storage Rooms, 306, 213, 217 and associated offices, Cafeteria	ASSUMED	MISC	N	LOC	4	SF	Yes	ACBM with the potential for damage	5	LOW
133	2' x 2' Multi Colored Tile Mastic	100,000	SF	Throughout 1st, 2nd, 3rd, & 4th Floors, 306	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
134	Stairwell flooring	6,000	SF	Throughout 1st, 2nd, 3rd, & 4th Floors	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
135	Stairwell flooring mastic	6,000	SF	Throughout 1st, 2nd,	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the		LOW

# Chicago Public Schools

School Hancock High School Unit 46021 Building ID 1200

Address 4034 W. 56th St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				3rd, & 4th Floors								potential for damage		
136	4 Inch gray mapboard	10,000	LF	Throughout 1st, 2nd, 3rd & 4th Floors room 303, 301	ASSUMED	MISC	N	NONE	0	LF	Yes	ACBM with the potential for damage		LOW
137	4 Inch gray mapboard Mastic	10,000	LF	Throughout 1st, 2nd, 3rd, & 4th Floors, room 303, room 301	ASSUMED	MISC	N	NONE	0	LF	Yes	ACBM with the potential for damage		LOW
138	2' x 4' Ceiling Tile (White)	50,000	SF	Throughout Classrooms on 1st, 2nd, 3rd, & 4th Floors	ASSUMED	MISC	Y	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
139	2' x 2' Ceiling Tile (White)	35,000	SF	Hallways throughout 1st, 2nd, 3rd, & 4th Floors	ASSUMED	MISC	Y	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
140	Drywall	60,000	SF	Throughout building	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
141	Drywall compound	6,000	SF	Throughout Building	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
142	12" x 12" Gray w/ Black and White Specks Floor Tile	800	SF	Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201, 203, 204, 207, 209, 208, 211, 215, Cafeteria, 162, 121, 119, 103, 102, 101	ASSUMED	MISC	N	LOC	10	SF	Yes	ACBM with the potential for damage	2	LOW
143	12" x 12" Light Blue w/ Black and White Specks Floor Tile	200	SF	Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201, 203, 204, 207, 209, 208, 211, 215, Cafeteria, 162, 121, 119, 103, 102, 101	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
144	12" x 12" Gray w/ Black and White Specks & Light Blue w/ Black and White Specks Floor Tile Mastic	1,000	SF	Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201, 203, 204, 207, 209,	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW





# Chicago Public Schools

School Hancock High School Unit 46021 Building ID 1200  
Address 4034 W. 56th St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>12/8/2022</b>
Inspector Name <b><u>Kenneth Karuhn</u></b>
<b>100-07278</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
2	
001	
002	
003	
004	
005	Not observed 2022
006	Not observed 2022
007	
008	
009	
010	
011	2021 confirmed in MDF
012	
013	
014	
015	
016	
017	
018	
019	
020	
022	
023	
024	

# Chicago Public Schools

School Hancock High School Unit 46021 Building ID 1200

Address 4034 W. 56th St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
025	
026	
027	
029	
030	
031	
032	
033	Not observed 2022
034	Not observed 2022
035	Not observed 2022
036	
037	
038	
039	
040	
041	
042	
043	Not observed 2022
044	
045	
046	Not observed 2022
047	Not observed 2022
048	
050	Not observed 2022
051	Not observed 2022
053	
054	
055	
056	

# Chicago Public Schools

School Hancock High School Unit 46021 Building ID 1200

Address 4034 W. 56th St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
057	
058	
060	
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	
072	Not observed 2022
073	Not observed 2022
074	Not observed 2022
075	Not observed 2022
076	
077	
078	
079	
080	
081	
082	
083	
084	
085	
086	
087	

# Chicago Public Schools

School Hancock High School Unit 46021 Building ID 1200

Address 4034 W. 56th St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
089	
090	
091	
093	
094	Not observed 2022
095	Not observed 2022
096	Under radiator in 210
097	
098	
099	
100	
101	Not observed 2022
102	
103	
104	
104-M	
105	
105-M	
107	
108	
109	
110	Not observed 2022
111	Not observed 2022
112	
113	
114	
115	
116	
117	

# Chicago Public Schools

School Hancock High School Unit 46021 Building ID 1200

Address 4034 W. 56th St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
118	
119	
120	
121	Not observed 2022
122	Not observed 2022
123	Not observed 2022
124	Not observed 2022
125	
126	
127	
128	Not observed 2022
129	Not observed 2022
130	Not observed 2022
131	Not observed 2022
132	Damage in 4th floor hallway
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	Damage in 309
143	
144	
145	
18	

# Chicago Public Schools

School Hancock High School Unit 46021 Building ID 1200

Address 4034 W. 56th St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
19	
33	Not observed 2022
34	Not observed 2022
35	Not observed 2022

**Table II**

**Management Planner's Review**

---



# Chicago Public Schools

**School** Hancock High School  
**Address** 4034 W. 56th St.

**Unit** 46021  
Chicago, IL, 60652

**Building ID** 1200  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
2	1' x 1' Acoustical Wall Tiles	400	SF	Annex: Corridors, Lobby to auditorium, CL17,CL18,CL20,CL21,CL07,CL10	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
001	1' x 1' ceiling tile REMOVED			music practice rooms	Assumed	MISC					Follow O&M Plan
002	9" x 9" Brown w/White & red Streaks Floor Tile			original Building Cafeteria snack bar.	Abated	MISC					
003	1' x 1' Solid Act Ceiling Tile			Rooms 307,309 (above new drop ceiling)	Abated	MISC					
004	1' x 1' Holed Act.	5,000	SF	Original Building 1st, 2nd,3rd,4th floor & corridor (above new tile)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
005	1' x 1' Metal Pan Act.			Faculty Lounge, Faculty lounge	Assumed	MISC					Follow O&M Plan
006	1' x 1' Ceiling Tile: pocked Act.		SF	Original Building: Ground Floor Lobby, south entrance.	Assumed	MISC			SF		Follow O&M Plan
007	2' x 4' Ceiling Tile	900	SF	2nd floor Workout room above gym offices, library	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
008	9" x 9" Gray w/White Streaks Floor Tile			Annex: Halls & Room's 102,105,104,106,302,305,304,405,402, 406, 304, 400, 304, 303, 301, 102, 101, 104, 103, auditorium ramps & stariwells, 2nd floor MDF room	Abated	MISC					
009	9" x 9" Green w/White Floor Tile	1,000	SF	Annex: auditorium stairwells & balcony	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
010	12" x 12" Gray Vinyl Floor Tile			Room 111, patch in 3rd floor hallway	Abated	MISC					
011	9" x 9" Gray Floor tile	250	SF	ROOMS: A434 411, 415, 417, 419, 421, 422A, 442, 428, 412, 413, 406, A323, 225, 113, 150, MDF Room, 303 office, (new room numbers: see inspector's comment, freight elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
012	12x 12 tan vinyl floor tile			ROOMS: 420B, 420A, 424, 423, 425, 426, 422A, 422B, 405, 407, 305, 412,413,415,420,432,445,444,405,401, 402,403,325,326,327 new Room, numbers - see ins's comments	Abated	MISC					
013	9" x 9" Green Vinyl Floor Tile			Library entrance., ROOMS: 411, 416,424,427,430,433,435,312,314,315, 318 - new room numbers - see inspector's comments	Abated	MISC					
014	Cottage Cheese Sprayed on Material	100	SF	Annex: 2nd flr. Library	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable	Follow O&M Plan

# Chicago Public Schools

**School** Hancock High School  
**Address** 4034 W. 56th St.

**Unit** 46021  
Chicago, IL, 60652

**Building ID** 1200  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
015	Cove base molding			Annex: Rooms 405,402,104,106,406,404,102,105,305,302,304 - room numbers - see inspector's comments	Abated	MISC				suspect ACBM	
016	Exposed aicell pipe insulation			Original Building: Classrooms	Abated	TSI					
017	Trowled on plaster mateial	1,000	SF	Annex: Lobby	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
018	Plaster	3,900	SF	Annex: 1st, 3rd, 4th floor Classrooms and Corridors	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	
019	Plaster	8,000	SF	Original Building: Classrooms and crrdrs	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	
020	Transite ceiling panels	500	SF	Original Building: Gym Storage room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022	Pipe joint compound	1,000	LF	Annex: Pipe Tunnel, basement above ceilings	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
023	Mag block insulation			Annex: Pipe Tunnel	Abated	TSI					
024	Aircell pipe insulation			Original Building: Pipe Tunnels	Abated	TSI					
025	Exposed aircell	30	LF	Original Building: Pipe Tunnels	Assumed	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
026	Pipe joint compound			Original Building: Boiler Room	Abated	TSI					
027	Mag block insulation-removed			Original Building: Boiler Room: Boiler #1, Boiler #2	Abated	TSI					
029	Mag block insulation			Original Building: Boiler Room & ADJACENT RMS IN BASEMENT, tunnels to boiler	Abated	TSI					
030	Boiler breeching material			Original Building: Boiler Room in basement	Abated	TSI					
031	Mag block insulation			Original Building: Boiler Room: Oil Preheater	Abated	TSI					
032	Gasket material			Original Building: Boiler Room:	Abated	TSI					
033	Chilller Pump piping			Annex: Pump Room Basement	Assumed	TSI					Follow O&M Plan
034	Heat Pump insulation			Annx: Basement pump room	Assumed	TSI					Follow O&M Plan
035	Pipe joint compound			Annex: Pump Room basement	Assumed	TSI					Follow O&M Plan
036	Aircell pipe insulation			Convent: basement	Abated	TSI					
037	Cold water reservoir tank insulation			Convent: Pump/Tank Storage Room	Abated	TSI					
038	Insulation on Cold Water Circulation Pumps			Convent: Pump/Tank Storage Room	Abated	TSI					

# Chicago Public Schools

School Hancock High School

Unit 46021

Building ID 1200

Address 4034 W. 56th St.

Chicago, IL, 60652

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
039	Plaster			Convent: Student Cafeteria	Abated	SURFACE					
040	Cottage Cheese Sprayed on Material, acoustical ceiling, concrete ceiling			Convent: Student Cafeteria	Abated	SURFACE					
041	9" x 9" Red VFloor Tile			Convent: Student Actviity Room, Basement, Balcony, freight elevator	Abated	MISC					
042	Cove base molding			Convent: Student Activity Room, Basement	Abated	MISC					
043	Exposed aircell			Convent: student activity Room basement.	Assumed	TSI					Follow O&M Plan
044	Chemical flow hood-abated			Original Building: Science Room	Abated	MISC					
045	Fire Curtain, baby Blue	3,500	SF	Annex: Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
046	Asbestos oven			Original Building: Science Room	Assumed	MISC					Follow O&M Plan
047	Fire brick			Original Building: Art Room Kiln	Assumed	MISC					Follow O&M Plan
048	9" x 9" White w/ Green Floor Tile			Annex:	Abated	MISC					
050	9" x 9" Tan w/ Red & White: Floor Tile		SF	Annex: Library, room 200	Assumed	MISC			SF		Follow O&M Plan
051	9" x 9" Brown w/ Tan: Floor tile		SF	Annex: Library and adjacent rooms, 200	Assumed	MISC			SF		Follow O&M Plan
053	9" x 9" Green, Tan, Black & Orange: Floor			Annex: corridor to convent, rooms A413, 318 (new room numbers: 426C, 303, corridor to convent)	Abated	MISC					
054	9" x 9" Light Green: Floor			Original Building: Rooms A426, 317,202,204,223,203,205,224,228,222 - new Room numbers - see ins's com-s	Abated	MISC					
055	12" x 12" tan w/ Black & White: Floor Tile			Original Building: Corridors to Annex on 3rd floor	Abated	MISC					
056	12" x 12" Brown tan w/Dark & White Streaks Vinyl Floor Tile			Original Building: Corridor leading to library, 2nd floor	Abated	MISC					
057	5"x5" swirl pattern Floor tile: Blue			Original Building: Parenta Supervisor's teachers Lounge	Abated	MISC					
058	5"x5" gold & brown tile: floor tile			Original Building: teachers. Lounge	Abated	MISC					
060	Lab table tops	150	SF	Original Building: Science Room 312 (new room 308)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
062	9" x 9" Green swirl VFloor Tile.			Convent: Student Cafeteria, Room 306, 211, 208, 205, 204, 203, 201	Abated	MISC					
063	9" x 9" Tan swirl Vinyl Floor Tile.			Convent: Student Cafeteria	Abated	MISC					
064	12" x 12" Gray and White VFloor Tile			Original Building: Cafeteria Snack Bar	Abated	MISC					

# Chicago Public Schools

School Hancock High School

Unit 46021

Building ID 1200

Address 4034 W. 56th St.

Chicago, IL, 60652

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
065	Mastic for HA #8 Floor Tile			Annex: Halls & Room's 102,105,104,106,302,305,304,405,402, auditorium ramps & stairwells	Abated	MISC					
066	9" x 9" Green w/White Vinyl Floor Tile MASTIC FOR HA #9	1,000	SF	Annex: stairwells, 1st, 2nd, 3rd, 4th flr corridors, auditorium stairwells & balcony	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
067	Mastic for HA #13			ROOMS: 416,424,427,430,433,435,312,314,315, 318	Abated	MISC					
068	Mastic for HA #10			Original Building: Room A434 (new room number 412)	Abated	MISC					
069	Mastic for HA #11			ROOMS: A434, 442, 428, 412, 413, 406, A323, 225, 113, 150 (see new Room numbers in comments)	Abated	MISC					
070	Mastic for HA #12 Floor Tile			ROOMS: 412,413,415,420,432,445,444,405,401, 402,403,325,326,327 (see new Roomnumbers in insp'comments)	Abated	MISC					
071	9" x 9" red Vinyl Floor Tile Mastic			Convent: Basement activity room, flight elevator	Abated	MISC					
072	9" x 9" Mastic for Type d Floor Tile		SF	Annex: Storage Room	Assumed	MISC			SF		Follow O&M Plan
073	Mastic for Type E Floor Tile			Annex: Natural Gas main	Assumed	MISC					Follow O&M Plan
074	Mastic for Type F Floor Tile		SF	Annex: Student Library	Assumed	MISC			SF		Follow O&M Plan
075	Mastic for Type G Floor Tile			Annex: Student Library	Assumed	MISC					Follow O&M Plan
076	Mastic for Type H Floor Tile			Annex: Classroom	Abated	MISC					
077	Mastic for Type M Floor Tile			Original Building: Classroom	Abated	MISC					
078	Mastic for Type N Floor Tile			Original Building: Classroom	Abated	MISC					
079	Mortar for terrazzo	4,000	SF	Original Building: corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
080	Mastic for Type P Floor Tile			Original Building: Hallway	Abated	MISC					
081	5x5 Blue swirl pattern Vinyl Floor Tile Mastic			Original Building: Non Smoking Faculty Lounge	Abated	MISC					
082	5x5 gold/brown vinyl floor tile mastic			Original Building: Non Smoking Faculty Lounge	Abated	MISC					
083	Mastic for Type S Floor Tile			Original Building: Gym Offices/Locker Room	Abated	MISC					
084	Green swirl Floor Tile Mastic			Convent: Student Cafeteria	Abated	MISC					

# Chicago Public Schools

School Hancock High School

Unit 46021

Building ID 1200

Address 4034 W. 56th St.

Chicago, IL, 60652

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
085	Tan swirl Floor Tile Mastic			Convent: Student Cafeteria	Abated	MISC					
086	12x 12 gray & White Floor Tile Mastic			Original Building: Cafeteria Snack Bar	Abated	MISC					
087	Mastic for Type A Cove Base Molding			Original Building and Annex: Classrooms and Corridors	Abated	MISC					
089	12" x 12" Brown tan w/Dark & White Streaks Vinyl Floor Tile-MASTIC			Original Building: Corridor leading to library, 2nd floor	Abated	MISC					
090	12" x 12" tan Speckled VFloor Tile.			2nd flr. Corridor leading to library, Room 209	Abated	MISC					
091	12" x 12" tan Speckled VFloor Tile Mastic			2nd flr corridor leading to library	Abated	MISC					
093	9" x 9" Brown w/White & red Streaks Floor Tile Mastic			original Building Cafeteria snack bar.	Abated	MISC					
094	12" x 12" BLACK W/ White Streaks Vinyl Floor Tile		SF	ROOM 106B (new room 142)	Assumed	MISC			SF		Follow O&M Plan
095	12" x 12" BLACK W/ White Streaks Vinyl Floor Tile-MASTIC		SF	ROOM 106B	Assumed	MISC			SF		Follow O&M Plan
096	12" x 12" GRAYISH Green Vinyl Floor Tile	2,500	SF	ANNEX: BASEMENT, DRESSING ROOM, CL07, RM 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
097	12" x 12" GRAYISH Green Vinyl Floor Tile-MASTIC	2,500	SF	ANNEX: BASEMENT, DRESSING ROOM, CL07, RM 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
098	12" x 12" Blue Vinyl Floor Tile	2,500	SF	ANNEX: BASEMENT UNDER AUDITORIUM	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
099	12" x 12" Blue Vinyl Floor Tile-MASTIC	2,500	SF	ANNEX: BASEMENT UNDER AUDITORIUM	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	Plaster ceiling patch	50	SF	CONVENT BASEMENT, STUDENT ACTIVITY ROOM	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	Pipe joint compound			CONVENT BASEMENT	Assumed	TSI					Follow O&M Plan
102	12" x 12" RED Vinyl Floor Tile			ROOM A423 (new room number 420)	Abated	MISC					
103	12" x 12" RED Vinyl Floor Tile-MASTIC			ROOM A423 (new room number 420)	Abated	MISC					
104	12" x 12" Off-White Vinyl Floor Tile			ROOMS 125, A322, A316, 301, 441, 409, 317, 307, A227 (new room numbers 125, 301, 305, 313, 401, East Corridor), 109, Main Office	Abated	MISC					
104-M	12" x 12" Off-White Vinyl Floor Tile-MASTIC			ROOMS 125, A322, A316, 301, 441, A227 (new room numbers 125, 301, 305, 313, 401, East Corridor), 109, Main office	Abated	MISC					
105	9" x 9" Green & GRAY CHECKERBOARD W/			4TH FLR OF ORIGINAL BLDG, A313,	Abated	MISC					

# Chicago Public Schools

School Hancock High School

Unit 46021

Building ID 1200

Address 4034 W. 56th St.

Chicago, IL, 60652

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	BLACK BORDER Vinyl Floor Tile			A310, 207, 103 (new room numbers: 121, 207, 125)							
105-M	Mastic for ha #105			4TH FLR OF ORIGINAL BLDG, A313, A310, 207, 103 (new room numbers: 121, 207, 125)	Abated	MISC					
107	Purple carpet mastic			ROOM A152 (new room number 101)	Abated	MISC					
108	Gray carpet mastic			ROOMS A141, 155, 144, 146, 148, 147 (new room numbers A141, 101A, 1-7, 105, 103, 109)	Abated	MISC					
109	Tan carpet mastic			ROOMS 114, 121 (new room numbers 110, 115)	Abated	MISC					
110	12" x 12" White & BLACK CHECKERBOARD Vinyl Floor Tile		SF	ROOM 119	Assumed	MISC			SF		Follow O&M Plan
111	12" x 12" White & BLACK CHECKERBOARD Vinyl Floor Tile-MASTIC		SF	ROOM 119	Assumed	MISC			SF		Follow O&M Plan
112	12" x 12" MARBLE LOOKING TAN Vinyl Floor Tile	1,200	SF	LOBBY OF AUDITORIUM	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12" x 12" MARBLE LOOKING BLACK Vinyl Floor Tile	1,200	SF	LOBBY OF AUDITORIUM	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	Mastic for ha #112 & 113	2,400	SF	LOBBY OF AUDITORIUM	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	9" x 9" Dark Green Vinyl Floor Tile	1,500	SF	AUDITORIUM FLOOR & WALLS & BALCONY	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	9" x 9" RED Vinyl Floor Tile			AUDITORIUM FLOOR & WALLS	Abated	MISC					
117	Mastic for ha #115 & 116			AUDITORIUM FLOOR & WALLS	Abated	MISC					
118	9" x 9" Brown & TAN CHECKERBOARD Vinyl Floor Tile			ROOMS 401, 403, C406, C404, C204, C205 (new Room 415, corridor and Library work and storage rooms)	Abated	MISC					
119	9" x 9" Brown & TAN CHECKERBOARD Vinyl Floor Tile-MASTIC			ROOMS 101, C406, C404, C204, C205 (new Room 415, corridor and Library work and storage rooms)	Abated	MISC					
120	Gray carpet mastic			ROOM C307 (new room 342)	Abated	MISC					
121	12" x 12" White w/ Red & Blue Specks Floor Tile		SF	Convent Basement	Assumed	MISC			SF		Follow O&M Plan
122	12" x 12" White w/ Red & Blue Specks Floor Tile Mastic		SF	Convent Basement	Assumed	MISC			SF		Follow O&M Plan
123	12" x 12" Purple Floor Tile		SF	Convent Basement	Assumed	MISC			SF		Follow O&M Plan
124	12" x 12" Purple Floor Tile Mastic		SF	Convent Basement	Assumed	MISC			SF		Follow O&M Plan
125	12" x 12" Light Gray w/ White Floor Tile			Room 412, 416	Abated	MISC					

# Chicago Public Schools

School Hancock High School

Unit 46021

Building ID 1200

Address 4034 W. 56th St.

Chicago, IL, 60652

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
126	12" x 12" Light Gray w/White Floor Tile Mastic			Room 412, 416	Abated	MISC					
127	Gray mix terrazzo	4,500	SF	1st, 2nd, 3rd Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
128	Green carpet adhesive		SF	Room 310	Assumed	MISC			SF		Follow O&M Plan
129	Peach linoleum		SF	Room 302, 308, 313, 315	Assumed	MISC			SF		Follow O&M Plan
130	Peach linoleum adhesive		SF	Rooms 302, 308, 313, 315	Assumed	MISC			SF		Follow O&M Plan
131	Brown carpet adhesive		SF	Main Office (101A) CLOSET	Assumed	MISC			SF		Follow O&M Plan
132	2' x 2' Multi colored Tile	100,000	SF	Throughout 4th Floor, Storage Rooms, 306, 213, 217 and associated offices, Cafeteria	Assumed	MISC	No	4	SF	6 ACBM with the potential for damage	Repair
133	2' x 2' Multi Colored Tile Mastic	100,000	SF	Throughout 1st, 2nd, 3rd, & 4th Floors, 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	Stairwell flooring	6,000	SF	Throughout 1st, 2nd, 3rd, & 4th Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	Stairwell flooring mastic	6,000	SF	Throughout 1st, 2nd, 3rd, & 4th Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	4 Inch gray mapboard	10,000	LF	Throughout 1st, 2nd, 3rd & 4th Floors room 303, 301	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
137	4 Inch gray mapboard Mastic	10,000	LF	Throughout 1st, 2nd, 3rd, & 4th Floors, room 303, room 301	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
138	2' x 4' Ceiling Tile (White)	50,000	SF	Throughout Classrooms on 1st, 2nd, 3rd, & 4th Floors	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
139	2' x 2' Ceiling Tile (White)	35,000	SF	Hallways throughout 1st, 2nd, 3rd, & 4th Floors	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	Drywall	60,000	SF	Throughout building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
141	Drywall compound	6,000	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142	12" x 12" Gray w/ Black and White Specks Floor Tile	800	SF	Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201, 203, 204, 207, 209, 208, 211, 215, Cafeteria, 162, 121, 119, 103, 102, 101	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
143	12" x 12" Light Blue w/ Black and White Specks Floor Tile	200	SF	Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201, 203, 204, 207, 209, 208, 211, 215, Cafeteria, 162, 121, 119, 103, 102, 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	12" x 12" Gray w/ Black and White Specks & Light Blue w/ Black and White Specks Floor Tile Mastic	1,000	SF	Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Hancock High School  
**Address** 4034 W. 56th St.

**Unit** 46021  
 Chicago, IL, 60652

**Building ID** 1200  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				203, 204, 207, 209, 208, 211, 215, Cafeteria, 162, 121, 119, 103, 102, 101							
145	Blue carpet mastic	2,500	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Hard plaster	3,900	SF	Annex: 1st, 3rd, 4th floor Classrooms and Corridors; 303,301	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Plaster	8,000	SF	Original Building: Classrooms and crdrsr; room 109; room 100	Assumed	SURFACE	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
33	Chiller Pump piping			Annex: Pump Room Basement	Assumed	TSI					Follow O&M Plan
34	Heat Pump insulation			Annx: Basement pump room	Assumed	TSI					Follow O&M Plan
35	Pipe joint compound			Annex: Pump Room basement	Assumed	TSI					Follow O&M Plan



# Chicago Public Schools

**School** Hancock High School  
**Address** 4034 W. 56th St.

**Unit** 46021  
 Chicago, IL, 60652

**Building ID** 1200  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	12/20/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
2	
001	
002	
003	
004	
005	
006	
007	
008	
009	
010	
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	
022	
023	
024	
025	
026	

# Chicago Public Schools

**School** Hancock High School  
**Address** 4034 W. 56th St.

**Unit** 46021  
Chicago, IL, 60652

**Building ID** 1200  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
027	
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
050	
051	
053	
054	
055	
056	

# Chicago Public Schools

**School** Hancock High School  
**Address** 4034 W. 56th St.

**Unit** 46021  
 Chicago, IL, 60652

**Building ID** 1200  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
057	
058	
060	
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	
072	
073	
074	
075	
076	
077	
078	
079	
080	
081	
082	
083	
084	
085	

# Chicago Public Schools

**School** Hancock High School  
**Address** 4034 W. 56th St.

**Unit** 46021  
Chicago, IL, 60652

**Building ID** 1200  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
086	
087	
089	
090	
091	
093	
094	
095	
096	
097	
098	
099	
100	
101	
102	
103	
104	
104-M	
105	
105-M	
107	
108	
109	
110	
111	
112	
113	

# Chicago Public Schools

**School** Hancock High School  
**Address** 4034 W. 56th St.

**Unit** 46021  
Chicago, IL, 60652

**Building ID** 1200  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
114	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	

# Chicago Public Schools

**School** Hancock High School

**Unit** 46021

**Building ID** 1200

**Address** 4034 W. 56th St.

Chicago, IL, 60652

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
141	
142	
143	
144	
145	
18	Sample to determine ACM content
19	Sample to determine ACM content
33	
34	
35	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

Carnow, Conibear and Associates

*2022 AHERA REINSPECTION*



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **1' x 1' Acoustical Wall Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex: Corridors, Lobby to auditorium, CL17,CL18,CL20,CL21,CL07,CL10**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **1' x 1' Acoustical Wall Tiles**  
MATERIAL LOCATION: **Annex: Corridors, Lobby to auditorium, CL17,CL18,CL20,CL21,CL07,CL10**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**  
MATERIAL DESCRIPTION: **1' x 1' ceiling tile REMOVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **music practice rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **001**

MATERIAL DESCRIPTION: **1' x 1' ceiling tile REMOVED**

MATERIAL LOCATION: **music practice rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/White & red Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **original Building Cafeteria snack bar.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **002**

MATERIAL DESCRIPTION: **9" x 9" Brown w/White & red Streaks Floor Tile**

MATERIAL LOCATION: **original Building Cafeteria snack bar.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003**  
MATERIAL DESCRIPTION: **1' x 1' Solid Act Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 307,309 (above new drop ceiling)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **003**  
MATERIAL DESCRIPTION: **1' x 1' Solid Act Ceiling Tile**  
MATERIAL LOCATION: **Rooms 307,309 (above new drop ceiling)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**  
MATERIAL DESCRIPTION: **1' x 1' Holed Act.**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Original Building 1st, 2nd,3rd,4th floor & corridor (above new tile)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **004**  
MATERIAL DESCRIPTION: **1' x 1' Holed Act.**  
MATERIAL LOCATION: **Original Building 1st, 2nd,3rd,4th floor & corridor (above new tile)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**  
MATERIAL DESCRIPTION: **1' x 1' Metal Pan Act.**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Faculty Lounge, Faculty lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **005**

MATERIAL DESCRIPTION: **1' x 1' Metal Pan Act.**

MATERIAL LOCATION: **Faculty Lounge, Faculty lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**  
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile: pocked Act.**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Ground Floor Lobby, south entrance.**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **006**  
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile: pocked Act.**  
MATERIAL LOCATION: **Original Building: Ground Floor Lobby, south entrance.**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd floor Workout room above gym offices, library**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **007**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**  
MATERIAL LOCATION: **2nd floor Workout room above gym offices, library**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Halls & Room's 102,105,104,106,302,305,304,405,402, 406, 304, 400, 304, 303, 301, 102, 101, 104, 103, auditorium ramps & stariwells, 2nd floor MDF room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **008**

MATERIAL DESCRIPTION: **9" x 9" Gray w/White Streaks Floor Tile**

MATERIAL LOCATION: **Annex: Halls & Room's 102,105,104,106,302,305,304,405,402, 406, 304, 400, 304, 303, 301, 102, 101, 104, 103, auditorium ramps & stariwells, 2nd floor MDF room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**  
MATERIAL DESCRIPTION: **9" x 9" Green w/White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Annex: auditorium stairwells & balcony**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **009**  
MATERIAL DESCRIPTION: **9" x 9" Green w/White Floor Tile**  
MATERIAL LOCATION: **Annex: auditorium stairwells & balcony**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**  
MATERIAL DESCRIPTION: **12" x 12" Gray Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111, patch in 3rd floor hallway**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **010**

MATERIAL DESCRIPTION: **12" x 12" Gray Vinyl Floor Tile**

MATERIAL LOCATION: **Room 111, patch in 3rd floor hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46021 BUIDLING ID: 1200  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Kenneth Karuhn  
SCHOOL NAME: Hancock High School INSPECTION DATE: 12/8/2022  
ADDRESS: 4034 W. 56th St. IDPH LICENSE NO: 100-07278

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 011  
MATERIAL DESCRIPTION: 9" x 9" Gray Floor tile  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **ROOMS: A434 411, 415, 417, 419, 421, 422A, 442, 428, 412, 413, 406, A323, 225, 113, 150, MDF Room, 303 office, (new room numbers: see inspector's comment, freight elevator**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **2021 confirmed in MDF**

Inspector's Signature:



Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **011**  
MATERIAL DESCRIPTION: **9" x 9" Gray Floor tile**  
MATERIAL LOCATION: **ROOMS: A434 411, 415, 417, 419, 421, 422A, 442, 428, 412, 413, 406, A323, 225, 113, 150, MDF Room, 303 office, (new room numbers: see inspector's comment, freight elevator**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**  
MATERIAL DESCRIPTION: **12x 12 tan vinyl floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS: 420B, 420A, 424, 423, 425, 426, 422A, 422B, 405, 407, 305, 412,413,415,420,432,445,444,405,401,402,403,325,326,327 new Room,numbers - see ins's comments**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **012**

MATERIAL DESCRIPTION: **12x 12 tan vinyl floor tile**

MATERIAL LOCATION: **ROOMS: 420B, 420A, 424, 423, 425, 426, 422A, 422B, 405, 407, 305, 412,413,415,420,432,445,444,405,401,402,403,325,326,327 new Room,numbers - see ins's comments**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**  
MATERIAL DESCRIPTION: **9" x 9" Green Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library entrance,. ROOMS: 411, 416,424,427,430,433,435,312,314,315,318 - new room numbers - see inspector's comments**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **013**  
MATERIAL DESCRIPTION: **9" x 9" Green Vinyl Floor Tile**  
MATERIAL LOCATION: **Library entrance,. ROOMS: 411, 416,424,427,430,433,435,312,314,315,318 - new room numbers - see inspector's comments**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014**  
MATERIAL DESCRIPTION: **Cottage Cheese Sprayed on Material**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Annex: 2nd flr. Library**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **014**  
MATERIAL DESCRIPTION: **Cottage Cheese Sprayed on Material**  
MATERIAL LOCATION: **Annex: 2nd flr. Library**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**  
MATERIAL DESCRIPTION: **Cove base molding**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Rooms 405,402,104,106,406,404,102,105,305,302,304 - room numbers - see inspector's comments**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **015**  
MATERIAL DESCRIPTION: **Cove base molding**  
MATERIAL LOCATION: **Annex: Rooms 405,402,104,106,406,404,102,105,305,302,304 - room numbers - see inspector's comments**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**  
MATERIAL DESCRIPTION: **Exposed icell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **016**

MATERIAL DESCRIPTION: **Exposed aicell pipe insulation**

MATERIAL LOCATION: **Original Building: Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017**  
MATERIAL DESCRIPTION: **Trowled on plaster mateial**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex: Lobby**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **017**  
MATERIAL DESCRIPTION: **Trowled on plaster mateial**  
MATERIAL LOCATION: **Annex: Lobby**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex: 1st, 3rd, 4th floor Classrooms and Corridors**  
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **018**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Annex: 1st, 3rd, 4th floor Classrooms and Corridors**  
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Original Building: Classrooms and crrdrs**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **019**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Original Building: Classrooms and crrdrs**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020**  
MATERIAL DESCRIPTION: **Transite ceiling panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Original Building: Gym Storage room**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **020**  
MATERIAL DESCRIPTION: **Transite ceiling panels**  
MATERIAL LOCATION: **Original Building: Gym Storage room**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022**  
MATERIAL DESCRIPTION: **Pipe joint compound**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Annex: Pipe Tunnel, basement above ceilings**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **022**  
MATERIAL DESCRIPTION: **Pipe joint compound**  
MATERIAL LOCATION: **Annex: Pipe Tunnel, basement above ceilings**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**  
MATERIAL DESCRIPTION: **Mag block insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Pipe Tunnel**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **023**

MATERIAL DESCRIPTION: **Mag block insulation**

MATERIAL LOCATION: **Annex: Pipe Tunnel**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Pipe Tunnels**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **024**

MATERIAL DESCRIPTION: **Aircell pipe insulation**

MATERIAL LOCATION: **Original Building: Pipe Tunnels**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**  
MATERIAL DESCRIPTION: **Exposed aircell**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Original Building: Pipe Tunnels**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **025**  
MATERIAL DESCRIPTION: **Exposed aircell**  
MATERIAL LOCATION: **Original Building: Pipe Tunnels**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**  
MATERIAL DESCRIPTION: **Pipe joint compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **026**

MATERIAL DESCRIPTION: **Pipe joint compound**

MATERIAL LOCATION: **Original Building: Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027**  
MATERIAL DESCRIPTION: **Mag block insulation-removed**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Boiler Room: Boiler #1, Boiler #2**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **027**

MATERIAL DESCRIPTION: **Mag block insulation-removed**

MATERIAL LOCATION: **Original Building: Boiler Room: Boiler #1, Boiler #2**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029**  
MATERIAL DESCRIPTION: **Mag block insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Boiler Room & ADJACENT RMS IN BASEMENT, tunnels to boiler**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **029**  
MATERIAL DESCRIPTION: **Mag block insulation**  
MATERIAL LOCATION: **Original Building: Boiler Room & ADJACENT RMS IN BASEMENT, tunnels to boiler**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030**  
MATERIAL DESCRIPTION: **Boiler breeching material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Boiler Room in basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **030**  
MATERIAL DESCRIPTION: **Boiler breaching material**  
MATERIAL LOCATION: **Original Building: Boiler Room in basement**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031**  
MATERIAL DESCRIPTION: **Mag block insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Boiler Room: Oil Preheater**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **031**

MATERIAL DESCRIPTION: **Mag block insulation**

MATERIAL LOCATION: **Original Building: Boiler Room: Oil Preheater**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032**  
MATERIAL DESCRIPTION: **Gasket material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Boiler Room:**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **032**

MATERIAL DESCRIPTION: **Gasket material**

MATERIAL LOCATION: **Orignal Building: Boiler Room:**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033**  
MATERIAL DESCRIPTION: **Chiller Pump piping**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Pump Room Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **033**

MATERIAL DESCRIPTION: **Chiller Pump piping**

MATERIAL LOCATION: **Annex: Pump Room Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034**  
MATERIAL DESCRIPTION: **Heat Pump insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annx: Basement pump room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **034**

MATERIAL DESCRIPTION: **Heat Pump insulation**

MATERIAL LOCATION: **Annx: Basement pump room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**  
MATERIAL DESCRIPTION: **Pipe joint compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Pump Room basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **035**

MATERIAL DESCRIPTION: **Pipe joint compound**

MATERIAL LOCATION: **Annex: Pump Room basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **036**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
MATERIAL LOCATION: **Convent: basement**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037**  
MATERIAL DESCRIPTION: **Cold water reservoir tank insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: Pump/Tank Storage Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **037**

MATERIAL DESCRIPTION: **Cold water reservoir tank insulation**

MATERIAL LOCATION: **Convent: Pump/Tank Storage Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**  
MATERIAL DESCRIPTION: **Insulation on Cold Water Circulation Pumps**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: Pump/Tank Storage Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **038**

MATERIAL DESCRIPTION: **Insulation on Cold Water Circulation Pumps**

MATERIAL LOCATION: **Convent: Pump/Tank Storage Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: Student Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **039**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Convent: Student Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**  
MATERIAL DESCRIPTION: **Cottage Cheese Sprayed on Material, acoustical ceiling, concrete ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: Student Cafeteria**


MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **040**  
MATERIAL DESCRIPTION: **Cottage Cheese Sprayed on Material, acoustical ceiling, concrete ceiling**  
MATERIAL LOCATION: **Convent: Student Cafeteria**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041**  
MATERIAL DESCRIPTION: **9" x 9" Red VFloor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: Student Actviity Room, Basement, Balcony, freight elevator**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **041**  
MATERIAL DESCRIPTION: **9" x 9" Red VFloor Tile**  
MATERIAL LOCATION: **Convent: Student Actviity Room, Basement, Balcony, freight elevator**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042**  
MATERIAL DESCRIPTION: **Cove base molding**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: Student Activity Room, Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **042**  
MATERIAL DESCRIPTION: **Cove base molding**  
MATERIAL LOCATION: **Convent: Student Activity Room, Basement**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**  
MATERIAL DESCRIPTION: **Exposed aircell**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: student activitiy Room basement.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **043**

MATERIAL DESCRIPTION: **Exposed aircell**

MATERIAL LOCATION: **Convent: student activitiy Room basement.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044**  
MATERIAL DESCRIPTION: **Chemical flow hood-abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Science Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **044**

MATERIAL DESCRIPTION: **Chemical flow hood-abated**

MATERIAL LOCATION: **Original Building: Science Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045**  
MATERIAL DESCRIPTION: **Fire Curtain, baby Blue**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex: Auditorium**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **045**  
MATERIAL DESCRIPTION: **Fire Curtain, baby Blue**  
MATERIAL LOCATION: **Annex: Auditorium**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046**  
MATERIAL DESCRIPTION: **Asbestos oven**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Science Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **046**

MATERIAL DESCRIPTION: **Asbestos oven**

MATERIAL LOCATION: **Original Building: Science Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047**  
MATERIAL DESCRIPTION: **Fire brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Origianl Building: Art Room Kiln**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **047**  
MATERIAL DESCRIPTION: **Fire brick**  
MATERIAL LOCATION: **Origianl Building: Art Room Kiln**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048**  
MATERIAL DESCRIPTION: **9" x 9" White w/ Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex:**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **048**

MATERIAL DESCRIPTION: **9" x 9" White w/ Green Floor Tile**

MATERIAL LOCATION: **Annex:**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/ Red & White: Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Library, room 200**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **050**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ Red & White: Floor Tile**

MATERIAL LOCATION: **Annex: Library, room 200**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/ Tan: Floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Library and adjacent rooms, 200**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **051**

MATERIAL DESCRIPTION: **9" x 9" Brown w/ Tan: Floor tile**

MATERIAL LOCATION: **Annex: Library and adjacent rooms, 200**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053**  
MATERIAL DESCRIPTION: **9" x 9" Green, Tan, Black & Orange: Floor**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: corridor to convent, rooms A413, 318 (new room numbers: 426C, 303, corridor to convent)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **053**  
MATERIAL DESCRIPTION: **9" x 9" Green, Tan, Black & Orange: Floor**  
MATERIAL LOCATION: **Annex: corridor to convent, rooms A413, 318 (new room numbers: 426C, 303, corridor to convent)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054**  
MATERIAL DESCRIPTION: **9" x 9" Light Green: Floor**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Rooms A426,317,202,204,223,203,205,224,228,222 - new Room numbers - see ins's com-s**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **054**

MATERIAL DESCRIPTION: **9" x 9" Light Green: Floor**

MATERIAL LOCATION: **Original Building: Rooms A426,317,202,204,223,203,205,224,228,222 - new Room numbers - see ins's com-s**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055**  
MATERIAL DESCRIPTION: **12" x 12" tan w/ Black & White: Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building; Corridors to Annex on 3rd floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **055**

MATERIAL DESCRIPTION: **12" x 12" tan w/ Black & White: Floor Tile**

MATERIAL LOCATION: **Original Building; Corridors to Annex on 3rd floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056**  
MATERIAL DESCRIPTION: **12" x 12" Brown tan w/Dark & White Streaks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Corridor leading to library, 2nd floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **056**  
MATERIAL DESCRIPTION: **12" x 12" Brown tan w/Dark & White Streaks Vinyl Floor Tile**  
MATERIAL LOCATION: **Original Building: Corridor leading to library, 2nd floor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **057**  
MATERIAL DESCRIPTION: **5"x5" swirl pattern Floor tile: Blue**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Parenta Supervisor's teachers Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **057**

MATERIAL DESCRIPTION: **5"x5" swirl pattern Floor tile: Blue**

MATERIAL LOCATION: **Original Building: Parenta Supervisor's teachers Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **058**  
MATERIAL DESCRIPTION: **5"x5" gold & brown tile: floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: teachers. Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **058**

MATERIAL DESCRIPTION: **5"x5" gold & brown tile: floor tile**

MATERIAL LOCATION: **Original Building: teachers. Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **060**  
MATERIAL DESCRIPTION: **Lab table tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Original Building: Science Room 312 (new room 308)**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **060**  
MATERIAL DESCRIPTION: **Lab table tops**  
MATERIAL LOCATION: **Orignal Building: Science Room 312 (new room 308)**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **062**  
MATERIAL DESCRIPTION: **9" x 9" Green swirl VFloor Tile.**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: Student Cafeteria, Room 306, 211, 208, 205, 204, 203, 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **062**  
MATERIAL DESCRIPTION: **9" x 9" Green swirl VFloor Tile.**  
MATERIAL LOCATION: **Convent: Student Cafeteria, Room 306, 211, 208, 205, 204, 203, 201**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **063**  
MATERIAL DESCRIPTION: **9" x 9" Tan swirl Vinyl Floor Tile.**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: Student Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **063**

MATERIAL DESCRIPTION: **9" x 9" Tan swirl Vinyl Floor Tile.**

MATERIAL LOCATION: **Convent: Student Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **064**  
MATERIAL DESCRIPTION: **12" x 12" Gray and White VFloor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Cafeteria Snack Bar**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **064**

MATERIAL DESCRIPTION: **12" x 12" Gray and White VFloor Tile**

MATERIAL LOCATION: **Original Building: Cafeteria Snack Bar**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **065**  
MATERIAL DESCRIPTION: **Mastic for HA #8 Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Halls & Room's 102,105,104,106,302,305,304,405,402,auditorium ramps & stariwells**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **065**  
MATERIAL DESCRIPTION: **Mastic for HA #8 Floor Tile**  
MATERIAL LOCATION: **Annex: Halls & Room's 102,105,104,106,302,305,304,405,402,auditorium ramps & stariwells**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **066**  
MATERIAL DESCRIPTION: **9" x 9" Green w/White Vinyl Floor Tile MASTIC FOR HA #9**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. Any remaining friable ACBM or friable suspect ACBM

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex: stairwells, 1st, 2nd, 3rd, 4th flr corridors, auditorium stairwells & balcony**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **066**  
MATERIAL DESCRIPTION: **9" x 9" Green w/White Vinyl Floor Tile MASTIC FOR HA #9**  
MATERIAL LOCATION: **Annex: stairwells, 1st, 2nd, 3rd, 4th flr corridors, auditorium stairwells & balcony**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **067**  
MATERIAL DESCRIPTION: **Mastic for HA #13**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS: 416,424,427,430,433,435,312,314,315,318**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **067**

MATERIAL DESCRIPTION: **Mastic for HA #13**

MATERIAL LOCATION: **ROOMS: 416,424,427,430,433,435,312,314,315,318**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **068**  
MATERIAL DESCRIPTION: **Mastic for HA #10**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Room A434 (new room number 412)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **068**

MATERIAL DESCRIPTION: **Mastic for HA #10**

MATERIAL LOCATION: **Original Building: Room A434 (new room number 412)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **069**  
MATERIAL DESCRIPTION: **Mastic for HA #11**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS: A434, 442, 428, 412, 413, 406, A323, 225, 113, 150 (see new Room numbers in comments)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **069**

MATERIAL DESCRIPTION: **Mastic for HA #11**

MATERIAL LOCATION: **ROOMS: A434, 442, 428, 412, 413, 406, A323, 225, 113, 150 (see new Room numbers in comments)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **070**  
MATERIAL DESCRIPTION: **Mastic for HA #12 Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS: 412,413,415,420,432,445,444,405,401,402,403,325,326,327 (see new Roomnumbers in insp'comments)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **070**

MATERIAL DESCRIPTION: **Mastic for HA #12 Floor Tile**

MATERIAL LOCATION: **ROOMS: 412,413,415,420,432,445,444,405,401,402,403,325,326,327 (see new Roomnumbers in insp'comments)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **071**  
MATERIAL DESCRIPTION: **9" x 9" red Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: Basement activity room, flight elevator**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **071**

MATERIAL DESCRIPTION: **9" x 9" red Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Convent: Basement activity room, flight elevator**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **072**  
MATERIAL DESCRIPTION: **9" x 9" Mastic for Type d Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Storage Room**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **072**  
MATERIAL DESCRIPTION: **9" x 9" Mastic for Type d Floor Tile**  
MATERIAL LOCATION: **Annex: Storage Room**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **073**  
MATERIAL DESCRIPTION: **Mastic for Type E Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Natural Gas main**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **073**

MATERIAL DESCRIPTION: **Mastic for Type E Floor Tile**

MATERIAL LOCATION: **Annex: Natural Gas main**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **074**  
MATERIAL DESCRIPTION: **Mastic for Type F Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Student Library**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **074**  
MATERIAL DESCRIPTION: **Mastic for Type F Floor Tile**  
MATERIAL LOCATION: **Annex: Student Library**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **075**  
MATERIAL DESCRIPTION: **Mastic for Type G Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Student Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **075**

MATERIAL DESCRIPTION: **Mastic for Type G Floor Tile**

MATERIAL LOCATION: **Annex: Student Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **076**  
MATERIAL DESCRIPTION: **Mastic for Type H Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **076**  
MATERIAL DESCRIPTION: **Mastic for Type H Floor Tile**  
MATERIAL LOCATION: **Annex: Classroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **077**  
MATERIAL DESCRIPTION: **Mastic for Type M Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **077**

MATERIAL DESCRIPTION: **Mastic for Type M Floor Tile**

MATERIAL LOCATION: **Original Building: Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **078**  
MATERIAL DESCRIPTION: **Mastic for Type N Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **078**

MATERIAL DESCRIPTION: **Mastic for Type N Floor Tile**

MATERIAL LOCATION: **Original Building: Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **079**  
MATERIAL DESCRIPTION: **Mortar for terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Original Building: corridor**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **079**  
MATERIAL DESCRIPTION: **Mortar for terrazzo**  
MATERIAL LOCATION: **Original Building: corridor**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **080**  
MATERIAL DESCRIPTION: **Mastic for Type P Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **080**

MATERIAL DESCRIPTION: **Mastic for Type P Floor Tile**

MATERIAL LOCATION: **Original Building: Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **081**  
MATERIAL DESCRIPTION: **5x5 Blue swirl pattern Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Non Smoking Faculty Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **081**

MATERIAL DESCRIPTION: **5x5 Blue swirl pattern Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Original Building: Non Smoking Faculty Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **082**  
MATERIAL DESCRIPTION: **5x5 gold/brown vinyl floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Non Smoking Faculty Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **082**

MATERIAL DESCRIPTION: **5x5 gold/brown vinyl floor tile mastic**

MATERIAL LOCATION: **Original Building: Non Smoking Faculty Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **083**  
MATERIAL DESCRIPTION: **Mastic for Type S Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Gym Offices/Locker Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **083**  
MATERIAL DESCRIPTION: **Mastic for Type S Floor Tile**  
MATERIAL LOCATION: **Original Building: Gym Offices/Locker Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **084**  
MATERIAL DESCRIPTION: **Green swirl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: Student Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **084**

MATERIAL DESCRIPTION: **Green swirl Floor Tile Mastic**

MATERIAL LOCATION: **Convent: Student Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **085**  
MATERIAL DESCRIPTION: **Tan swirl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent: Student Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **085**

MATERIAL DESCRIPTION: **Tan swirl Floor Tile Mastic**

MATERIAL LOCATION: **Convent: Student Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **086**  
MATERIAL DESCRIPTION: **12x 12 gray & White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Cafeteria Snack Bar**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **086**  
MATERIAL DESCRIPTION: **12x 12 gray & White Floor Tile Mastic**  
MATERIAL LOCATION: **Original Building: Cafeteria Snack Bar**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **087**  
MATERIAL DESCRIPTION: **Mastic for Type A Cove Base Molding**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Original Building and Annex: Classrooms and Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **087**  
MATERIAL DESCRIPTION: **Mastic for Type A Cove Base Molding**  
MATERIAL LOCATION: **Original Building and Annex: Classrooms and Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **089**  
MATERIAL DESCRIPTION: **12" x 12" Brown tan w/Dark & White Streaks Vinyl Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Corridor leading to library, 2nd floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **089**  
MATERIAL DESCRIPTION: **12" x 12" Brown tan w/Dark & White Streaks Vinyl Floor Tile-MASTIC**  
MATERIAL LOCATION: **Original Building: Corridor leading to library, 2nd floor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **090**  
MATERIAL DESCRIPTION: **12" x 12" tan Speckled VFloor Tile.**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd flr. Corridor leading to library, Room 209**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **090**

MATERIAL DESCRIPTION: **12" x 12" tan Speckled VFloor Tile.**

MATERIAL LOCATION: **2nd flr. Corridor leading to library, Room 209**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **091**  
MATERIAL DESCRIPTION: **12" x 12" tan Speckled VFloor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd flr corridor leading to library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **091**

MATERIAL DESCRIPTION: **12" x 12" tan Speckled VFloor Tile Mastic**

MATERIAL LOCATION: **2nd flr corridor leading to library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **093**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/White & red Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **original Building Cafeteria snack bar.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **093**

MATERIAL DESCRIPTION: **9" x 9" Brown w/White & red Streaks Floor Tile Mastic**

MATERIAL LOCATION: **original Building Cafeteria snack bar.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **094**  
MATERIAL DESCRIPTION: **12" x 12" BLACK W/ White Streaks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM 106B (new room 142)**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **094**  
MATERIAL DESCRIPTION: **12" x 12" BLACK W/ White Streaks Vinyl Floor Tile**  
MATERIAL LOCATION: **ROOM 106B (new room 142)**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **095**  
MATERIAL DESCRIPTION: **12" x 12" BLACK W/ White Streaks Vinyl Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM 106B**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **095**  
MATERIAL DESCRIPTION: **12" x 12" BLACK W/ White Streaks Vinyl Floor Tile-MASTIC**  
MATERIAL LOCATION: **ROOM 106B**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **096**  
MATERIAL DESCRIPTION: **12" x 12" GRAYISH Green Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **ANNEX: BASEMENT, DRESSING ROOM, CL07, RM 210**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Under radiator in 210**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **096**  
MATERIAL DESCRIPTION: **12" x 12" GRAYISH Green Vinyl Floor Tile**  
MATERIAL LOCATION: **ANNEX: BASEMENT, DRESSING ROOM, CL07, RM 210**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **097**  
MATERIAL DESCRIPTION: **12" x 12" GRAYISH Green Vinyl Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ANNEX: BASEMENT, DRESSING ROOM, CL07, RM 210**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **097**  
MATERIAL DESCRIPTION: **12" x 12" GRAYISH Green Vinyl Floor Tile-MASTIC**  
MATERIAL LOCATION: **ANNEX: BASEMENT, DRESSING ROOM, CL07, RM 210**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **098**  
MATERIAL DESCRIPTION: **12" x 12" Blue Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ANNEX: BASEMENT UNDER AUDITORIUM**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **098**  
MATERIAL DESCRIPTION: **12" x 12" Blue Vinyl Floor Tile**  
MATERIAL LOCATION: **ANNEX: BASEMENT UNDER AUDITORIUM**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **099**  
MATERIAL DESCRIPTION: **12" x 12" Blue Vinyl Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ANNEX: BASEMENT UNDER AUDITORIUM**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **099**  
MATERIAL DESCRIPTION: **12" x 12" Blue Vinyl Floor Tile-MASTIC**  
MATERIAL LOCATION: **ANNEX: BASEMENT UNDER AUDITORIUM**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Plaster ceiling patch**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **CONVENT BASEMENT, STUDENT ACTIVITY ROOM**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Plaster ceiling patch**  
MATERIAL LOCATION: **CONVENT BASEMENT, STUDENT ACTIVITY ROOM**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **Pipe joint compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **CONVENT BASEMENT**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **Pipe joint compound**

MATERIAL LOCATION: **CONVENT BASEMENT**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **12" x 12" RED Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM A423 (new room number 420)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **12" x 12" RED Vinyl Floor Tile**

MATERIAL LOCATION: **ROOM A423 (new room number 420)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **12" x 12" RED Vinyl Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM A423 (new room number 420)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **12" x 12" RED Vinyl Floor Tile-MASTIC**

MATERIAL LOCATION: **ROOM A423 (new room number 420)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12" x 12" Off-White Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS 125, A322, A316, 301, 441, 409, 317, 307, A227 (new room numbers 125, 301, 305, 313, 401, East Corridor), 109, Main Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **12" x 12" Off-White Vinyl Floor Tile**

MATERIAL LOCATION: **ROOMS 125, A322, A316, 301, 441, 409, 317, 307, A227 (new room numbers 125, 301, 305, 313, 401, East Corridor), 109, Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104-M**  
MATERIAL DESCRIPTION: **12" x 12" Off-White Vinyl Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS 125, A322, A316, 301, 441, A227 (new room numbers 125, 301, 305, 313, 401, East Corridor), 109, Main office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **104-M**

MATERIAL DESCRIPTION: **12" x 12" Off-White Vinyl Floor Tile-MASTIC**

MATERIAL LOCATION: **ROOMS 125, A322, A316, 301, 441, A227 (new room numbers 125, 301, 305, 313, 401, East Corridor), 109, Main office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **9" x 9" Green & GRAY CHECKERBOARD W/ BLACK BORDER Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4TH FLR OF ORIGINAL BLDG, A313, A310, 207, 103 (new room numbers: 121, 207, 125)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **9" x 9" Green & GRAY CHECKERBOARD W/ BLACK BORDER Vinyl Floor Tile**  
MATERIAL LOCATION: **4TH FLR OF ORIGINAL BLDG, A313, A310, 207, 103 (new room numbers: 121, 207, 125)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105-M**  
MATERIAL DESCRIPTION: **Mastic for ha #105**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4TH FLR OF ORIGINAL BLDG, A313, A310, 207, 103 (new room numbers: 121, 207, 125)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **105-M**

MATERIAL DESCRIPTION: **Mastic for ha #105**

MATERIAL LOCATION: **4TH FLR OF ORIGINAL BLDG, A313, A310, 207, 103 (new room numbers: 121, 207, 125)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **Purple carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM A152 (new room number 101)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **Purple carpet mastic**

MATERIAL LOCATION: **ROOM A152 (new room number 101)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **Gray carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS A141, 155, 144, 146, 148, 147 (new room numbers A141, 101A, 1-7, 105, 103, 109)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **Gray carpet mastic**  
MATERIAL LOCATION: **ROOMS A141, 155, 144, 146, 148, 147 (new room numbers A141, 101A, 1-7, 105, 103, 109)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **Tan carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS 114, 121 (new room numbers 110, 115)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **Tan carpet mastic**

MATERIAL LOCATION: **ROOMS 114, 121 (new room numbers 110, 115)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **12" x 12" White & BLACK CHECKERBOARD Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM 119**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **12" x 12" White & BLACK CHECKERBOARD Vinyl Floor Tile**  
MATERIAL LOCATION: **ROOM 119**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **12" x 12" White & BLACK CHECKERBOARD Vinyl Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM 119**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **12" x 12" White & BLACK CHECKERBOARD Vinyl Floor Tile-MASTIC**  
MATERIAL LOCATION: **ROOM 119**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12" x 12" MARBLE LOOKING TAN Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **LOBBY OF AUDITORIUM**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12" x 12" MARBLE LOOKING TAN Vinyl Floor Tile**  
MATERIAL LOCATION: **LOBBY OF AUDITORIUM**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12" x 12" MARBLE LOOKING BLACK Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **LOBBY OF AUDITORIUM**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12" x 12" MARBLE LOOKING BLACK Vinyl Floor Tile**  
MATERIAL LOCATION: **LOBBY OF AUDITORIUM**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Mastic for ha #112 & 113**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **LOBBY OF AUDITORIUM**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Mastic for ha #112 & 113**  
MATERIAL LOCATION: **LOBBY OF AUDITORIUM**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **9" x 9" Dark Green Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **AUDITORIUM FLOOR & WALLS & BALCONY**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **9" x 9" Dark Green Vinyl Floor Tile**  
MATERIAL LOCATION: **AUDITORIUM FLOOR & WALLS & BALCONY**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **9" x 9" RED Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **AUDITORIUM FLOOR & WALLS**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **9" x 9" RED Vinyl Floor Tile**  
MATERIAL LOCATION: **AUDITORIUM FLOOR & WALLS**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **Mastic for ha #115 & 116**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **AUDITORIUM FLOOR & WALLS**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **Mastic for ha #115 & 116**

MATERIAL LOCATION: **AUDITORIUM FLOOR & WALLS**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **9" x 9" Brown & TAN CHECKERBOARD Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS 401, 403, C406, C404, C204, C205 (new Room 415, corridor and Library work and storage rooms)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **9" x 9" Brown & TAN CHECKERBOARD Vinyl Floor Tile**  
MATERIAL LOCATION: **ROOMS 401, 403, C406, C404, C204, C205 (new Room 415, corridor and Library work and storage rooms)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **9" x 9" Brown & TAN CHECKERBOARD Vinyl Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS 101, C406, C404, C204, C205 (new Room 415, corridor and Library work and storage rooms)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **9" x 9" Brown & TAN CHECKERBOARD Vinyl Floor Tile-MASTIC**  
MATERIAL LOCATION: **ROOMS 101, C406, C404, C204, C205 (new Room 415, corridor and Library work and storage rooms)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **Gray carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM C307 (new room 342)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **Gray carpet mastic**  
MATERIAL LOCATION: **ROOM C307 (new room 342)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Red & Blue Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent Basement**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **12" x 12" White w/ Red & Blue Specks Floor Tile**

MATERIAL LOCATION: **Convent Basement**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Red & Blue Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent Basement**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Red & Blue Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Convent Basement**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **12" x 12" Purple Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent Basement**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **12" x 12" Purple Floor Tile**  
MATERIAL LOCATION: **Convent Basement**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **12" x 12" Purple Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Convent Basement**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **124**

MATERIAL DESCRIPTION: **12" x 12" Purple Floor Tile Mastic**

MATERIAL LOCATION: **Convent Basement**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 412, 416**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **125**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Floor Tile**

MATERIAL LOCATION: **Room 412, 416**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 412, 416**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **126**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/White Floor Tile Mastic**

MATERIAL LOCATION: **Room 412, 416**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Gray mix terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Hallways**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Gray mix terrazzo**  
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Hallways**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **Green carpet adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 310**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **Green carpet adhesive**  
MATERIAL LOCATION: **Room 310**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **Peach linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 302, 308, 313, 315**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **Peach linoleum**  
MATERIAL LOCATION: **Room 302, 308, 313, 315**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **Peach linoleum adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 302, 308, 313, 315**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **Peach linoleum adhesive**  
MATERIAL LOCATION: **Rooms 302, 308, 313, 315**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **Brown carpet adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office (101A) CLOSET**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **131**

MATERIAL DESCRIPTION: **Brown carpet adhesive**

MATERIAL LOCATION: **Main Office (101A) CLOSET**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **2' x 2' Multi colored Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 4th Floor, Storage Rooms, 306, 213, 217 and associated offices, Cafeteria**  
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage in 4th floor hallway**

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **2' x 2' Multi colored Tile**  
MATERIAL LOCATION: **Throughout 4th Floor, Storage Rooms, 306, 213, 217 and associated offices, Cafeteria**  
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **2' x 2' Multi Colored Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1st, 2nd, 3rd, & 4th Floors, 306**

MATERIAL QUANTITY: **100000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **2' x 2' Multi Colored Tile Mastic**  
MATERIAL LOCATION: **Throughout 1st, 2nd, 3rd, & 4th Floors, 306**  
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **Stairwell flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1st, 2nd, 3rd, & 4th Floors**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **Stairwell flooring**  
MATERIAL LOCATION: **Throughout 1st, 2nd, 3rd, & 4th Floors**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **Stairwell flooring mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1st, 2nd, 3rd, & 4th Floors**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **Stairwell flooring mastic**  
MATERIAL LOCATION: **Throughout 1st, 2nd, 3rd, & 4th Floors**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **4 Inch gray mapboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1st, 2nd, 3rd & 4th Floors room 303, 301**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **4 Inch gray mapboard**  
MATERIAL LOCATION: **Throughout 1st, 2nd, 3rd & 4th Floors room 303, 301**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **4 Inch gray mapboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1st, 2nd, 3rd, & 4th Floors, room 303,room 301**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **4 Inch gray mapboard Mastic**  
MATERIAL LOCATION: **Throughout 1st, 2nd, 3rd, & 4th Floors, room 303,room 301**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile (White)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Classrooms on 1st, 2nd, 3rd, & 4th Floors**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile (White)**  
MATERIAL LOCATION: **Throughout Classrooms on 1st, 2nd, 3rd, & 4th Floors**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile (White)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Hallways throughout 1st, 2nd, 3rd, & 4th Floors**  
MATERIAL QUANTITY: **35000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile (White)**  
MATERIAL LOCATION: **Hallways throughout 1st, 2nd, 3rd, & 4th Floors**  
MATERIAL QUANTITY: **35000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout building**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Throughout building**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUIDLING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **Drywall compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **Drywall compound**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46021**    BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School**    INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.**    IDPH LICENSE NO: **100-07278**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Hard plaster**  
MATERIAL LOCATION: **Annex: 1st, 3rd, 4th floor Classrooms and Corridors; 303,301**  
MATERIAL QUANTITY: **3900**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **SURFACE**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46021**      BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School**      REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.**      IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Hard plaster**  
MATERIAL LOCATION: **Annex: 1st, 3rd, 4th floor Classrooms and Corridors; 303,301**  
MATERIAL QUANTITY: **3900**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### COMMENTS:

Sample to determine ACM content

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **Blue carpet mastic**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46021**      BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School**      REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.**      IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **Blue carpet mastic**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **2500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School** INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **143**

MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ Black and White Specks Floor Tile**

MATERIAL LOCATION: **Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201, 203, 204, 207, 209, 208, 211, 215, Cafeteria, 162, 121, 119, 103, 102, 101**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46021**      BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School**      REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.**      IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **143**

MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ Black and White Specks Floor Tile**

MATERIAL LOCATION: **Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201, 203, 204, 207, 209, 208, 211, 215, Cafeteria, 162, 121, 119, 103, 102, 101**

MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46021**      BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School**      INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.**      IDPH LICENSE NO: **100-07278**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **144**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black and White Specks & Light Blue w/ Black and White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201, 203, 204, 207, 209, 208, 211, 215, Cafeteria, 162, 121, 119, 103, 102, 101**

MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Kenneth Karuhn*

Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **144**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black and White Specks & Light Blue w/ Black and White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201, 203, 204, 207, 209, 208, 211, 215, Cafeteria, 162, 121, 119, 103, 102, 101**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46021**      BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School**      INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.**      IDPH LICENSE NO: **100-07278**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Heat Pump insulation**  
MATERIAL LOCATION: **Annx: Basement pump room**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **TSI**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
  
COMMENTS:  
Not observed 2022

Inspector's Signature: \_\_\_\_\_

*Kenneth Karuhn*

Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46021**      BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School**      REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.**      IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Heat Pump insulation**  
MATERIAL LOCATION: **Annx: Basement pump room**

MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022



# Chicago Public Schools

## Carnow, Conibear and Associates 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46021	BUILDING ID:	1200
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Hancock High School	INSPECTION DATE:	12/8/2022		
ADDRESS:	4034 W. 56th St.	IDPH LICENSE NO:	100-07278		

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	142		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Black and White Specks Floor Tile		
MATERIAL LOCATION:	Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201, 203, 204, 207, 209, 208, 211, 215, Cafeteria, 162, 121, 119, 103, 102, 101		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	Damaged
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	10	DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:	Damage in 309		

Inspector's Signature:  Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **142**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black and White Specks Floor Tile**

MATERIAL LOCATION: **Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302, 321, 322, 323, 326, 325, library storage, 201, 203, 204, 207, 209, 208, 211, 215, Cafeteria, 162, 121, 119, 103, 102, 101**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **12/20/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46021**    BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School**    INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.**    IDPH LICENSE NO: **100-07278**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Original Building: Classrooms and crrdrs; room 109; room 100**  
MATERIAL QUANTITY: **8000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **SURFACE**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Kenneth Karuhn*

Date: 12/08/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Original Building: Classrooms and crdrds; room 109; room 100**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### COMMENTS:

Sample to determine ACM content

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022

# Chicago Public Schools

## Carnow, Conibear and Associates 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46021**      BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School**      INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.**      IDPH LICENSE NO: **100-07278**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Chiller Pump piping**  
MATERIAL LOCATION: **Annex: Pump Room Basement**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **TSI**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
  
COMMENTS:  
Not observed 2022

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46021** BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School** REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Chiller Pump piping**

MATERIAL LOCATION: **Annex: Pump Room Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 12/20/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46021**      BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Kenneth Karuhn**  
SCHOOL NAME: **Hancock High School**      INSPECTION DATE: **12/8/2022**  
ADDRESS: **4034 W. 56th St.**      IDPH LICENSE NO: **100-07278**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Pipe joint compound**  
MATERIAL LOCATION: **Annex: Pump Room basement**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **TSI**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
  
COMMENTS:  
Not observed 2022

Inspector's Signature:



Date: **12/08/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46021**      BUILDING ID: **1200**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Hancock High School**      REVIEW DATE: **12/20/2022**  
ADDRESS: **4034 W. 56th St.**      IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Pipe joint compound**  
MATERIAL LOCATION: **Annex: Pump Room basement**

MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **12/20/2022**



# APPENDIX B

## Inspector and Management Planner Licenses

---



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## Kenneth Karuhn

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/9/2022

Exam Date: 9/9/2022

Expiration Date: 9/9/2023

Certificate Number: BIR2209092154

Kathy DeSalvo, Director



# ASBESTOS PROFESSIONAL LICENSE

ID NUMBER  
**100 - 07278**

ISSUED  
**4/15/2022**

EXPIRES  
**05/15/2023**

**KENNETH A KARUHN**  
600 W VAN BUREN ST., STE 5  
CHICAGO, IL 60607

Environmental Health



## ENDORSEMENTS

## TC EXPIRES

INSPECTOR

10/8/2022

PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL

10/9/2022

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Kenneth Karuhn**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082269

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519

  
Kathy DeSalvo, Director



# ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

**100 - 19466**

ISSUED

**4/22/2022**

EXPIRES

**05/15/2023**

**EVAN I CHRISTIAN**  
**1119 N HOYNE AVE, APT 1**  
**CHICAGO, IL 60622**

Environmental Health



## ENDORSEMENTS

## TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**

This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director





# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed