

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0003  
SCHOOL NAME: Bogan Technical High School  
ADDRESS OF SCHOOL: 3939 W. 79th St.  
CITY: Chicago, IL, 60652

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/30/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 8/18/2022 ENROLLMENT 620  
IDPH INSPECTOR LICENSE NUMBER: 100-11070  
IDPH LICENSED INSPECTOR NAME (Please Print): Mallory Jones  
IDPH MP LICENSE NUMBER: 100-01784  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Geneser

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer*

8/30/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Bogan Technical High School**

3939 W. 79th St.  
Chicago, IL, 60652

Unit: 46041  
Building ID: 1230

IDPH ID Number: 14-016-2990-0003

**REPORT DATE:**

Tuesday, August 30, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

08/29/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 46041                      Region: 05                      IDPH ID: 14-016-2990-0003

School: Bogan Technical High School                      Building ID: 1230

Address: 3939 W. 79th St.

Chicago, IL, 60652

Building Contact: Lowe, Jeffrey

Contact Phone: 7737096100

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/18/2022

Review Date: 08/29/2022

Inspector: Mallory Jones


Inspector IDPH License: 100-11070

Management Planner: Steven Geneser

Management Planner IDPH License: 100-01784

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Steven Geneser  
100-01784

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 30, 2022

RE: Bogan Technical High School, Unit 46041  
3939 W. 79th St.  
Chicago, IL, 60652

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Bogan Technical High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Bogan Technical High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Bogan Technical High School  
Address: 3939 W. 79th St.  
IDPH ID: 14-016-2990-0003  
Contact: Lowe, Jeffrey

Unit: 46041  
Chicago, IL, 60652  
Building ID: 1230  
Phone: 7737096100

Region: 05

### 2. Description of Facility

Original Construction: 1959  
Total Square Footage: 184611  
Current Occupancy: 620

Additional Construction:  
No of Floors: 2

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant


MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Mallory Jones


Inspector IDPH license # 100-11070  
Reinspection Date: 8/18/2022

  
Signature:  
Date: 8/18/2022

### 6. Management Planner

Management Planner Name: Steven Geneser

Management Planner IDPH license # 100-01784

  
Signature:  
Date: 08/29/2022

### 7. Review Date: 08/29/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

  
Signature:

Date: 8/30/2022

Name: Richard J.Schleyer



## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Bogan Technical High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1230:

28	Acoustical Ceiling Tile
NEW	Newly Installed Suspect ACM
T	12"x12" Orange Floor Tile
U	Mastic associated with 12"x12" Orange Floor Tile
V	12"x12" Black Floor Tile
W	Mastic associated with 12"x12" Black Floor Tile



B. The following new homogenous areas have been identified for Building 1230:

NEW	Newly Installed Suspect ACM
T	12"x12" Orange Floor Tile
U	Mastic associated with 12"x12" Orange Floor Tile
V	12"x12" Black Floor Tile
W	Mastic associated with 12"x12" Black Floor Tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

09A	12x12 Off-White w/Speckles
101	Pink Terrazzo
102	Green Terrazzo
103	Black Vinyl Flooring
104	Mastic on Duct
105	Marker Board Mastic
106	24"x24" Light Gray Vinyl Floor Tile
106A	24"x24" Light Gray Vinyl Floor Tile Mastic
107	24"x24" Dark Gray Vinyl Floor Tile
107A	24"x24" Dark Gray Vinyl Floor Tile Mastic
12A	12"x12" Beige w/Specks Floor Tile Mastic
13A	12x12 Off-White w/Speckles Floor Tile Mastic
14	12x12 Blue Floor Tile
14A	Tan Linoleum w/Blue Trim
15	12x12 White w/Blue Specks Floor Tile
15A	Tan Linoleum Mastic (Abated in 112, 117 & 119)
16	Transite Table Tops
16A	12x12 White w/Blue Specks Floor Tile Mastic
17	Transite Counter Tops
17A	12x12 Blue Floor Tile Mastic
18	Transite Fume Hood
19	1'x1' White w/Holes Ceiling Tile
20	1'x1' White w/Holes Ceiling Tile Mastic
21	Baseboard
22	Baseboard Mastic
23	Burgundy Carpet Mastic
24	2'x4' White Ceiling Tile, Spaghetti Pattern
25	2' x 4' White Ceiling Tile, Spaghetti Pattern Mastic
28	Acoustical Ceiling Tile
29	Acoustical Ceiling Tile Mastic
30	2'x4' White Ceiling Tile
31	2'x4' White Ceiling Tile Mastic
32	Ceiling Plaster
CM	Tan Carpet Mastic
H	Tank Insulation
HA-100	2'x4' White Ceiling Tiles with Holes
J	Fire Doors
NEW	Newly Installed Suspect ACM
O	Incinerator Insulation
P	Boiler Gaskets
R	Aircell Pipe Cover
S	Aircell Pipe Fitting Insulation

T	12"x12" Orange Floor Tile
U	Mastic associated with 12"x12" Orange Floor Tile
V	12"x12" Black Floor Tile
W	Mastic associated with 12"x12" Black Floor Tile

The following areas were deemed to be inaccessible:

106A	24"x24" Light Gray Vinyl Floor Tile Mastic
107A	24"x24" Dark Gray Vinyl Floor Tile Mastic
12A	12"x12" Beige w/Specks Floor Tile Mastic
12C	9x9 Gray Floor Tile Mastic
12D	9x9 Red Vinyl Floor Tile Mastic
13A	12x12 Off-White w/Speckles Floor Tile Mastic
15A	Tan Linoleum Mastic (Abated in 112, 117 & 119)
16A	12x12 White w/Blue Specks Floor Tile Mastic
20	1'x1' White w/Holes Ceiling Tile Mastic
22	Baseboard Mastic
23	Burgundy Carpet Mastic
25	2' x 4' White Ceiling Tile, Spaghetti Pattern Mastic
29	Acoustical Ceiling Tile Mastic
31	2'x4' White Ceiling Tile Mastic
CM	Tan Carpet Mastic
F	Mudded Fittings on Fiberglass Lines
G	Breeching
O	Incinerator Insulation
P	Boiler Gaskets
S	Aircell Pipe Fitting Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mallory Jones, IDPH License # 100-11070. The Management Plan was updated by Steven Geneser, IDPH License # 100-01784. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	7/16/2019
	7/16/2019
	11/16/2020
	11/16/2020
	11/16/2020
	11/16/2020

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Bogan Technical High School Building 1230 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Bogan Technical High School Unit 46041 Building ID 1230

Address 3939 W. 79th St. Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
08A	12"x12" Beige w/Specks Floor Tile	1,100	SF	Office Storeroom, Nurse's Office, Security Office	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
08B	9x9 Brown Vinyl Floor Tile ABATED			Kitchen, Office	ABATED	MISC		None						Moderate
08C	9x9 Gray Vinyl Floor Tile	10,000	SF	South Stairwell near Auditorium, Northwest Basement Entry Stairwell, Auditorium	CHR	MISC	N	DIST	0		No	ACBM with the potential for damage	5	LOW
08D	9x9 Red Vinyl Floor Tile	200	SF	Security Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
08E	9x9 Tan & Blue Vinyl Floor Tile ABATED			113	ABATED	MISC		None						Moderate
09A	12x12 Off-White w/Speckles	3,760	SF	Room 102, Main Office, Social Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	Pink Terrazzo	3,000	SF	1st Floor Main Corridor & Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	Green Terrazzo	500	SF	Bathrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	Black Vinyl Flooring	1,000	SF	Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	Mastic on Duct	350	SF	Room 239	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	Marker Board Mastic	1,000	SF	All Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	24"x24" Light Gray Vinyl Floor Tile	1,890	SF	Rooms 112, 117, 119	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106A	24"x24" Light Gray Vinyl Floor Tile Mastic	1,890	SF	Rooms 112, 117, 119	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	24"x24" Dark Gray Vinyl Floor Tile	970	SF	Rooms 112, 117, 119	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107A	24"x24" Dark Gray Vinyl Floor Tile Mastic	970	SF	Rooms 112, 117, 119	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10A	Baseboard ABATED			Throughout	ABATED	MISC		None						Moderate
11A	Baseboard Mastic ABATED			Throughout	ABATED	MISC		None						Moderate
12A	12"x12" Beige w/Specks Floor Tile Mastic	1,200	SF	Office Storeroom, Nurse's Office, Security Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		
12B	9x9 Brown Vinyl Floor Tile Mastic ABATED			Kitchen, Office	ABATED	MISC								
12C	9x9 Gray Floor Tile Mastic	11,450	SF	South Stairwell near Auditorium, Northwest Basement Entry Stairwell, Auditorium	CHR	MISC	N	DIST	0		No	ACBM with the potential for damage	5	LOW

# Chicago Public Schools

School Bogan Technical High School Unit 46041 Building ID 1230

Address 3939 W. 79th St. Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
12D	9x9 Red Vinyl Floor Tile Mastic	200	SF	Security Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12E	9x9 Tan Vinyl Floor Tile Mastic ABATED			113	ABATED	MISC		None						Moderate
13A	12x12 Off-White w/Speckles Floor Tile Mastic	3,760	SF	Room 102, Main Office, Social Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12x12 Blue Floor Tile	57	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14A	Tan Linoleum w/Blue Trim	33,400	SF	Throughout Classrooms, Nurse's Office, Cafeteria, Library, Counselor's Office, Rooms 113, 105, 107	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12x12 White w/Blue Specks Floor Tile	20,100	SF	Throughout Corridors, 139, 141, 143, Kitchen, Office, & Band Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15A	Tan Linoleum Mastic (Abated in 112, 117 & 119)	33,400	SF	Throughout Classrooms (Abated in 112, 117 & 119)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	Transite Table Tops	200	SF	Lab Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16A	12x12 White w/Blue Specks Floor Tile Mastic	20,100	SF	Throughout Corridors, 139, 141, 143, Kitchen, Office, & Band Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Transite Counter Tops	900	SF	Lab Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17A	12x12 Blue Floor Tile Mastic	57	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Transite Fume Hood	300	SF	Room 221	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	1'x1' White w/Holes Ceiling Tile	15,000	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
20	1'x1' White w/Holes Ceiling Tile Mastic	15,000	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Baseboard	180,000	SF	Throughout School	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		LOW
22	Baseboard Mastic	180,000	SF	Throughout School	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Burgundy Carpet Mastic	3,000	SF	Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with potential		LOW





# Chicago Public Schools

School Bogan Technical High School Unit 46041 Building ID 1230

Address 3939 W. 79th St. Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan or After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		
O	Incinerator Insulation	400	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
P	Boiler Gaskets	100	LF	Boiler room	ASSUMED	TSI	N	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
Q	Tank Insulation ABATED			Pool Filter Room	ABATED	TSI								
R	Aircell Pipe Cover	3,000	LF	Unexcavated Area in Basement	ASSUMED	TSI	Y	DIST	50		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
S	Aircell Pipe Fitting Insulation	300	SF	Unexcavated Area in Basement	ASSUMED	TSI	Y	DIST	15		No	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
T	12"x12" Orange Floor Tile	1,000	SF	Rooms 228 & 234	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
U	Mastic associated with 12"x12" Orange Floor Tile	1,000	SF	Rooms 228 & 234	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
V	12"x12" Black Floor Tile	600	SF	Rooms 228 & 234	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
W	Mastic associated with 12"x12" Black Floor Tile	600	SF	Rooms 228 & 234	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Bogan Technical High School Unit 46041 Building ID 1230  
Address 3939 W. 79th St. Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>8/18/2022</b>
Inspector Name <b>Mallory Jones</b>
<b>100-11070</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
08A	Changed per Inspector's Notes
08B	
08C	25 tiles Cracked and chipped floor tiles Intact
08D	
08E	
09A	
101	
102	
103	
104	
105	
106	
106A	
107	
107A	
10A	
11A	
12A	Changed per Inspector's Notes
12B	
12C	25 tiles Cracked and chipped floor tiles Intact
12D	
12E	
13A	
14	

# Chicago Public Schools

School Bogan Technical High School Unit 46041 Building ID 1230

Address 3939 W. 79th St. Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
14A	No Blue Trim in Rooms 105 & 107. ABATED From 112, 117 & 119.
15	
15A	ABATED From 112, 117 & 119.
16	
16A	
17	
17A	
18	
19	
20	
21	
22	
23	
24	
25	
28	
29	
30	
31	
32	
A	Material Not Observed 2019
C	
CM	Not Observed 2022
E	Not Observed 2019
F	
G	
H	
HA-100	
I	Not Observed 2019

# Chicago Public Schools

**School** Bogan Technical High School **Unit** 46041 **Building ID** 1230  
**Address** 3939 W. 79th St. **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
J	
K	Not Observed 2019
NEW	
O	
P	
Q	
R	July 2019 partial abatement for crawlspace pipes servicing Rooms 112, 117, and 119
S	July 2019 partial abatement for crawlspace pipes servicing Rooms 112, 117, and 119
T	Nov 2020 abatement Room 228 & 234
U	Nov 2020 abatement Room 228 & 234
V	Nov 2020 abatement Room 228 & 234
W	Nov 2020 abatement Room 228 & 234

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Bogan Technical High School

**Unit** 46041

**Building ID** 1230

**Address** 3939 W. 79th St.

Chicago, IL, 60652

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
08A	12"x12" Beige w/Specks Floor Tile	1,100	SF	Office Storeroom, Nurse's Office, Security Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
08B	9x9 Brown Vinyl Floor Tile ABATED			Kitchen, Office	Abated	MISC					
08C	9x9 Gray Vinyl Floor Tile	10,000	SF	South Stairwell near Auditorium, Northwest Basement Entry Stairwell, Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08D	9x9 Red Vinyl Floor Tile	200	SF	Security Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08E	9x9 Tan & Blue Vinyl Floor Tile ABATED			113	Abated	MISC					
09A	12x12 Off-White w/Speckles	3,760	SF	Room 102, Main Office, Social Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	Pink Terrazzo	3,000	SF	1st Floor Main Corridor & Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	Green Terrazzo	500	SF	Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Black Vinyl Flooring	1,000	SF	Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	Mastic on Duct	350	SF	Room 239	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	Marker Board Mastic	1,000	SF	All Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	24"x24" Light Gray Vinyl Floor Tile	1,890	SF	Rooms 112, 117, 119	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106A	24"x24" Light Gray Vinyl Floor Tile Mastic	1,890	SF	Rooms 112, 117, 119	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	24"x24" Dark Gray Vinyl Floor Tile	970	SF	Rooms 112, 117, 119	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107A	24"x24" Dark Gray Vinyl Floor Tile Mastic	970	SF	Rooms 112, 117, 119	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	Baseboard ABATED			Throughout	Abated	MISC					
11A	Baseboard Mastic ABATED			Throughout	Abated	MISC					
12A	12"x12" Beige w/Specks Floor Tile Mastic	1,200	SF	Office Storeroom, Nurse's Office, Security Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
12B	9x9 Brown Vinyl Floor Tile Mastic ABATED			Kitchen, Office	Abated	MISC					
12C	9x9 Gray Floor Tile Mastic	11,450	SF	South Stairwell near Auditorium, Northwest Basement Entry Stairwell, Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12D	9x9 Red Vinyl Floor Tile Mastic	200	SF	Security Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12E	9x9 Tan Vinyl Floor Tile Mastic ABATED			113	Abated	MISC					
13A	12x12 Off-White w/Speckles Floor Tile Mastic	3,760	SF	Room 102, Main Office, Social Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12x12 Blue Floor Tile	57	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14A	Tan Linoleum w/Blue Trim	33,400	SF	Throughout Classrooms, Nurse's Office, Cafeteria, Library, Counselor's Office, Rooms 113, 105, 107	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12x12 White w/Blue Specks Floor Tile	20,100	SF	Throughout Corridors, 139, 141, 143,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Bogan Technical High School

Unit 46041

Building ID 1230

Address 3939 W. 79th St.

Chicago, IL, 60652

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Kitchen, Office, & Band Room							
15A	Tan Linoleum Masitc (Abated in 112, 117 & 119)	33,400	SF	Throughout Classrooms (Abated in 112, 117 & 119)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Transite Table Tops	200	SF	Lab Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16A	12x12 White w/Blue Specks Floor Tile Mastic	20,100	SF	Throughout Corridors, 139, 141, 143, Kitchen, Office, & Band Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Transite Counter Tops	900	SF	Lab Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17A	12x12 Blue Floor Tile Mastic	57	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Transite Fume Hood	300	SF	Room 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	1'x1' White w/Holes Ceiling Tile	15,000	SF	Throughout	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
20	1'x1' White w/Holes Ceiling Tile Mastic	15,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Baseboard	180,000	SF	Throughout School	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
22	Baseboard Mastic	180,000	SF	Throughout School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Burgundy Carpet Mastic	3,000	SF	Principal's Office	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
24	2'x4' White Ceiling Tile, Spaghetti Pattern	30,000	SF	1st and 2nd Floor Hallways	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
25	2' x 4' White Ceiling Tile, Spaghetti Pattern Mastic	30,000	SF	1st and 2nd Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Acoustical Ceiling Tile	4,000	SF	143 Band Room, 221	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
29	Acoustical Ceiling Tile Mastic	4,000	SF	143 Band Room, 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	2'x4' White Ceiling Tile	6,000	SF	Rooms 142, 239, 110, 144, 102, and Kitchen	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
31	2'x4' White Ceiling Tile Mastic	6,000	SF	Rooms 142, 239, 110, 144, 102, and Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Ceiling Plaster	10,000	SF	Auditorium	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Millboard			Boiler Room & Basement	Chrysotile	MISC					
C	Fire Curtain	640	SF	Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM	Tan Carpet Mastic	300	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
E	Light Fixture Insulators			1st Floor North Wing	Chrysotile	MISC					
F	Mudded Fittings on Fiberglass Lines	600	LF	Chases & Basement, 120, 121, 131, 133, 135, Bathroom near 120	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Bogan Technical High School

**Unit** 46041

**Building ID** 1230

**Address** 3939 W. 79th St.

Chicago, IL, 60652

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
G	Breeching	700	SF	Boiler Room	Amosite	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	Tank Insulation	300	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
HA-100	2'x4' White Ceiling Tiles with Holes	100	SF	Engineer's Office	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Cardboard Fittings			Throughout	Chrysotile	TSI		0			
J	Fire Doors	20	EA	Throughout	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
K	Cardboard Pipe Insulation			Throughout	Chrysotile	TSI					
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan or After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan
O	Incinerator Insulation	400	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
P	Boiler Gaskets	100	LF	Boiler room	Assumed	TSI	No	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Q	Tank Insulation ABATED			Pool Filter Room	Abated	TSI					
R	Aircell Pipe Cover	3,000	LF	Unexcavated Area in Basement	Assumed	TSI	Yes	50	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
S	Aircell Pipe Fitting Insulation	300	SF	Unexcavated Area in Basement	Assumed	TSI	Yes	15	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
T	12"x12" Orange Floor Tile	1,000	SF	Rooms 228 & 234	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
U	Mastic associated with 12"x12" Orange Floor Tile	1,000	SF	Rooms 228 & 234	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
V	12"x12" Black Floor Tile	600	SF	Rooms 228 & 234	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
W	Mastic associated with 12"x12" Black Floor Tile	600	SF	Rooms 228 & 234	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan



# Chicago Public Schools

**School** Bogan Technical High School

**Unit** 46041

**Building ID** 1230

**Address** 3939 W. 79th St.

Chicago, IL, 60652

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	8/29/2022
Manager Planner Name	Steven Geneser
100-01784	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
08A	
08B	
08C	Repair and conduct O&M
08D	
08E	
09A	
101	
102	
103	
104	
105	
106	
106A	
107	
107A	

# Chicago Public Schools

**School** Bogan Technical High School

**Unit** 46041

**Building ID** 1230

**Address** 3939 W. 79th St.

Chicago, IL, 60652

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
10A	
11A	
12A	
12B	
12C	Repair and conduct O&M
12D	
12E	
13A	
14	
14A	
15	
15A	
16	
16A	
17	
17A	
18	
19	
20	
21	
22	
23	
24	
25	
28	
29	

# Chicago Public Schools

**School** Bogan Technical High School

**Unit** 46041

**Building ID** 1230

**Address** 3939 W. 79th St.

Chicago, IL, 60652

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
30	
31	
32	
A	
C	
CM	
E	
F	
G	
H	
HA-100	
I	
J	
K	
NEW	
O	
P	
Q	
R	Restrict access in affected areas. Remove or Repair damaged material
S	Restrict access in affected areas. Remove or repair damaged materials
T	
U	
V	
W	

# Chicago Public Schools

**School** Bogan Technical High  
School

**Unit** 46041

**Building ID** 1230

**Address** 3939 W. 79th St.

Chicago, IL, 60652

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

# APPENDIX A


## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.

## 2022 AHERA REINSPECTION




**ASBESTOS REINSPECTION KEY NOTES:**



HA-T 12"x12" Orange Floor Tile


Bass School First Floor  
2022 Asbestos Reinspection




<b>CLIENT:</b> Chicago Public Schools 42 West Madison Street Chicago, Illinois 60602	<b>PROJECT NAME:</b> 2022 Asbestos Reinspection Bogan High School 3339 W. 79th Street Chicago, Illinois 60652	<b>SHEET NAME:</b> Bogan High School Second Floor - HA-T  <b>INSPECTED BY:</b> Mallory Jones  IDPH License # 100-11070	<b>DRAWN BY:</b> MRC <b>DATE:</b> 11/10/22 <b>CHECKED BY:</b>	174 North Brandon Drive Glendale Heights, IL 60139 (630) 790-0880 (630) 790-0861 FAX  ENVIRONMENTAL, INC.	TEM PROJECT No.
			<b>REVIEWED BY:</b> <b>DATE:</b> <b>CHECKED BY:</b>		INSPECTION DATE: 08/18/2022
			<b>REVIEWED BY:</b> <b>DATE:</b> <b>CHECKED BY:</b>		NEW HA ID: HA-T

# Chicago Public Schools


## TEM Environmental, Inc. 2022 AHERA REINSPECTION



**ASBESTOS REINSPECTION KEY NOTES:**

 HA-U 12"x12" Orange Floor Tile Mastic


Bass School First Floor  
2022 Asbestos Reinspection 

<b>CLIENT:</b> Chicago Public Schools 42 West Madison Street Chicago, Illinois 60602	<b>PROJECT NAME:</b> 2022 Asbestos Reinspection Bogan High School 3939 W. 79th Street Chicago, Illinois 60652	<b>SHEET NAME:</b> Bogan High School Second Floor - HA-T	DRAWN BY: MRC    DATE: 11/10/22    CHECKED BY: REVIEWED BY:    DATE:    CHECKED BY: REVIEWED BY:    DATE:    CHECKED BY: REVIEWED BY:    DATE:    CHECKED BY:	174 North Brandon Drive Glendale Heights, IL 60139 (630) 790-0880 (630) 790-0861 FAX   ENVIRONMENTAL, INC.	TEM PROJECT No.
		INSPECTED BY: Malloy Jones    IDPH License # 100-11070	INSPECTION DATE: 08/18/2022		
			NEW IHA ID: HA-U		

# Chicago Public Schools

TEM Environmental, Inc.

## 2022 AHERA REINSPECTION



2nd Floor - DU


**ASBESTOS REINSPECTION KEY NOTES:**



HA-V 12"x12" Black Floor Tile

Bass School First Floor  
2022 Asbestos Reinspection




<b>CLIENT:</b> Chicago Public Schools 42 West Madison Street Chicago, Illinois 60602	<b>PROJECT NAME:</b> 2022 Asbestos Reinspection Bogan High School 3939 W. 79th Street Chicago, Illinois 60652	<b>SHEET NAME:</b> Bogan High School Second Floor - HA-T	DRAWN BY: MRC    DATE: 11/10/22    CHECKED BY: REVIEWED BY:    DATE:    CHECKED BY: REVIEWED BY:    DATE:    CHECKED BY: REVIEWED BY:    DATE:    CHECKED BY:	174 North Brandon Drive Glendale Heights, IL 60139 (630) 790-0880 (630) 790-0861 FAX 	TEM PROJECT No.
		INSPECTED BY: Mallory Jones    IDPH License # 100-11070	INSPECTION DATE: 08/18/2022		
		NEW IHA ID:	HA-V		
		(Empty)	(Empty)		



# Chicago Public Schools

TEM Environmental, Inc.

## 2022 AHERA REINSPECTION



2nd Floor - DU


**ASBESTOS REINSPECTION KEY NOTES:**



HA-W 12"x12" Black Floor Tile Mastic

Bass School First Floor  
2022 Asbestos Reinspection



<b>CLIENT:</b> Chicago Public Schools 42 West Madison Street Chicago, Illinois 60602	<b>PROJECT NAME:</b> 2022 Asbestos Reinspection Bogan High School 3939 W. 79th Street Chicago, Illinois 60652	<b>SHEET NAME:</b> Bogan High School Second Floor - HA-T	DRAWN BY: MRC    DATE: 11/10/22    CHECKED BY: REVIEWED BY:    DATE:    CHECKED BY: REVIEWED BY:    DATE:    CHECKED BY: REVIEWED BY:    DATE:    CHECKED BY:	174 North Brandon Drive Glendale Heights, IL 60139 (630) 790-0880 (630) 790-0861 FAX 	TEM PROJECT No.
		<b>INSPECTED BY:</b> Mallory Jones    IDPH License # 100-11070	INSPECTION DATE: 08/18/2022		
			NEW IHA ID: HA-W		

# Chicago Public Schools

TEM Environmental, Inc.

## 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **12"x12" Beige w/Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Office Storeroom, Nurse's Office, Security Office**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Changed per Inspector's Notes**

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **12"x12" Beige w/Specks Floor Tile**  
MATERIAL LOCATION: **Office Storeroom, Nurse's Office, Security Office**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08B**  
MATERIAL DESCRIPTION: **9x9 Brown Vinyl Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Kitchen, Office**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **08B**  
MATERIAL DESCRIPTION: **9x9 Brown Vinyl Floor Tile ABATED**  
MATERIAL LOCATION: **Kitchen, Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08C**  
MATERIAL DESCRIPTION: **9x9 Gray Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage  
Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---


## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage  
Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **South Stairwell near Auditorium, Northwest Basement Entry Stairwell, Auditorium**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS: **25 tiles Cracked and chipped floor tiles Intact**

Inspector's Signature: \_\_\_\_\_



Date: 08/18/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **08C**  
MATERIAL DESCRIPTION: **9x9 Gray Vinyl Floor Tile**  
MATERIAL LOCATION: **South Stairwell near Auditorium, Northwest Basement Entry Stairwell, Auditorium**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Repair and conduct O&M

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08D**  
MATERIAL DESCRIPTION: **9x9 Red Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Security Office**

MATERIAL QUANTITY: **200**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **08D**  
MATERIAL DESCRIPTION: **9x9 Red Vinyl Floor Tile**  
MATERIAL LOCATION: **Security Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08E**  
MATERIAL DESCRIPTION: **9x9 Tan & Blue Vinyl Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**


MATERIAL LOCATION: **113**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **08E**  
MATERIAL DESCRIPTION: **9x9 Tan & Blue Vinyl Floor Tile ABATED**  
MATERIAL LOCATION: **113**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Speckles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 102, Main Office, Social Room**  
MATERIAL QUANTITY: **3760** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Speckles**  
MATERIAL LOCATION: **Room 102, Main Office, Social Room**  
MATERIAL QUANTITY: **3760** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **Pink Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Main Corridor & Entrance**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **Pink Terrazzo**  
MATERIAL LOCATION: **1st Floor Main Corridor & Entrance**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **Green Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Bathrooms**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **Green Terrazzo**  
MATERIAL LOCATION: **Bathrooms**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Black Vinyl Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairwells**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Black Vinyl Flooring**  
MATERIAL LOCATION: **Stairwells**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **Mastic on Duct**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 239**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **Mastic on Duct**  
MATERIAL LOCATION: **Room 239**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **Marker Board Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Classrooms**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **Marker Board Mastic**  
MATERIAL LOCATION: **All Classrooms**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **24"x24" Light Gray Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 112, 117, 119**  
MATERIAL QUANTITY: **1890** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **24"x24" Light Gray Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 112, 117, 119**  
MATERIAL QUANTITY: **1890** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106A**  
MATERIAL DESCRIPTION: **24"x24" Light Gray Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 112, 117, 119**  
MATERIAL QUANTITY: **1890** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **106A**  
MATERIAL DESCRIPTION: **24"x24" Light Gray Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 112, 117, 119**  
MATERIAL QUANTITY: **1890** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **24"x24" Dark Gray Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 112, 117, 119**  
MATERIAL QUANTITY: **970** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **24"x24" Dark Gray Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 112, 117, 119**  
MATERIAL QUANTITY: **970** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107A**  
MATERIAL DESCRIPTION: **24"x24" Dark Gray Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 112, 117, 119**  
MATERIAL QUANTITY: **970** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **107A**  
MATERIAL DESCRIPTION: **24"x24" Dark Gray Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 112, 117, 119**  
MATERIAL QUANTITY: **970** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **Baseboard ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**


MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **Baseboard ABATED**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **Baseboard Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **Baseboard Mastic ABATED**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **12"x12" Beige w/Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Office Storeroom, Nurse's Office, Security Office**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Changed per Inspector's Notes**

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **12"x12" Beige w/Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Office Storeroom, Nurse's Office, Security Office**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12B**  
MATERIAL DESCRIPTION: **9x9 Brown Vinyl Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen, Office**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **12B**  
MATERIAL DESCRIPTION: **9x9 Brown Vinyl Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **Kitchen, Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12C**  
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---


## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **South Stairwell near Auditorium, Northwest Basement Entry Stairwell, Auditorium**  
MATERIAL QUANTITY: **11450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **11450** DAMAGE UNITS: **SF**  
COMMENTS: **25 tiles Cracked and chipped floor tiles Intact**

Inspector's Signature: \_\_\_\_\_



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **12C**  
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile Mastic**  
MATERIAL LOCATION: **South Stairwell near Auditorium, Northwest Basement Entry Stairwell, Auditorium**  
MATERIAL QUANTITY: **11450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Repair and conduct O&M

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12D**  
MATERIAL DESCRIPTION: **9x9 Red Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Security Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **12D**  
MATERIAL DESCRIPTION: **9x9 Red Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Security Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12E**  
MATERIAL DESCRIPTION: **9x9 Tan Vinyl Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **113**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **12E**  
MATERIAL DESCRIPTION: **9x9 Tan Vinyl Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **113**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Speckles Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 102, Main Office, Social Room**  
MATERIAL QUANTITY: **3760** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **13A**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Speckles Floor Tile Mastic**  
MATERIAL LOCATION: **Room 102, Main Office, Social Room**  
MATERIAL QUANTITY: **3760** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **57** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **57** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **Tan Linoleum w/Blue Trim**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Classrooms, Nurse's Office, Cafeteria, Library, Counselor's Office, Rooms 113, 105, 107**

MATERIAL QUANTITY: **33400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **No Blue Trim in Rooms 105 & 107. ABATED From 112, 117 & 119.**

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **Tan Linoleum w/Blue Trim**  
MATERIAL LOCATION: **Throughout Classrooms, Nurse's Office, Cafeteria, Library, Counselor's Office, Rooms 113, 105, 107**  
MATERIAL QUANTITY: **33400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Corridors, 139, 141, 143, Kitchen, Office, & Band Room**  
MATERIAL QUANTITY: **20100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/18/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Floor Tile**  
MATERIAL LOCATION: **Throughout Corridors, 139, 141, 143, Kitchen, Office, & Band Room**  
MATERIAL QUANTITY: **20100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **Tan Linoleum Masitc (Abated in 112, 117 & 119)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Classrooms (Abated in 112, 117 & 119)**  
MATERIAL QUANTITY: **33400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **ABATED From 112, 117 & 119.**

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **Tan Linoleum Masitc (Abated in 112, 117 & 119)**  
MATERIAL LOCATION: **Throughout Classrooms (Abated in 112, 117 & 119)**  
MATERIAL QUANTITY: **33400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Transite Table Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lab Rooms**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Transite Table Tops**  
MATERIAL LOCATION: **Lab Rooms**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Corridors, 139, 141, 143, Kitchen, Office, & Band Room**  
MATERIAL QUANTITY: **20100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout Corridors, 139, 141, 143, Kitchen, Office, & Band Room**  
MATERIAL QUANTITY: **20100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Transite Counter Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lab Rooms**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Transite Counter Tops**  
MATERIAL LOCATION: **Lab Rooms**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **57** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile Mastic**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **57** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Transite Fume Hood**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 221**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Transite Fume Hood**  
MATERIAL LOCATION: **Room 221**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **1'x1' White w/Holes Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **1'x1' White w/Holes Ceiling Tile**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **1'x1' White w/Holes Ceiling Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **1'x1' White w/Holes Ceiling Tile Mastic**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **180000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Baseboard**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **180000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **180000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **180000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Burgundy Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Burgundy Carpet Mastic**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile, Spaghetti Pattern**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Hallways**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile, Spaghetti Pattern**  
MATERIAL LOCATION: **1st and 2nd Floor Hallways**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **2' x 4' White Ceiling Tile, Spaghetti Pattern Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Hallways**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **2' x 4' White Ceiling Tile, Spaghetti Pattern Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Hallways**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Acoustical Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **143 Band Room, 221**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Acoustical Ceiling Tile**  
MATERIAL LOCATION: **143 Band Room, 221**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Acoustical Ceiling Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **143 Band Room, 221**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Acoustical Ceiling Tile Mastic**  
MATERIAL LOCATION: **143 Band Room, 221**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 142, 239, 110, 144, 102, and Kitchen**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**  
MATERIAL LOCATION: **Rooms 142, 239, 110, 144, 102, and Kitchen**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 142, 239, 110, 144, 102, and Kitchen**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile Mastic**  
MATERIAL LOCATION: **Rooms 142, 239, 110, 144, 102, and Kitchen**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Ceiling Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Ceiling Plaster**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Millboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room & Basement**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material Not Observed 2019**

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Millboard**  
MATERIAL LOCATION: **Boiler Room & Basement**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Fire Curtain**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Fire Curtain**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM**  
MATERIAL DESCRIPTION: **Tan Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **CM**  
MATERIAL DESCRIPTION: **Tan Carpet Mastic**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Light Fixture Insulators**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor North Wing**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Light Fixture Insulators**  
MATERIAL LOCATION: **1st Floor North Wing**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Mudded Fittings on Fiberglass Lines**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Chases & Basement, 120, 121, 131, 133, 135, Bathroom near 120**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Mudded Fittings on Fiberglass Lines**  
MATERIAL LOCATION: **Chases & Basement, 120, 121, 131, 133, 135, Bathroom near 120**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Breeching**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Breeching**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-100**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tiles with Holes**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **HA-100**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tiles with Holes**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Cardboard Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Cardboard Fittings**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Fire Doors**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Incinerator Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Incinerator Insulation**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Boiler Gaskets**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Boiler Gaskets**  
MATERIAL LOCATION: **Boiler room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Tank Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Filter Room**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Tank Insulation ABATED**  
MATERIAL LOCATION: **Pool Filter Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Aircell Pipe Cover**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---


### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Unexcavated Area in Basement**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **3000** DAMAGE UNITS: **LF**  
COMMENTS: **July 2019 partial abatement for crawlspace pipes servicing Rooms 112, 117, and 119**

Inspector's Signature: \_\_\_\_\_



Date: 08/18/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Aircell Pipe Cover**  
MATERIAL LOCATION: **Unexcavated Area in Basement**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

#### **Repair**

Comments:

Restrict access in affected areas. Remove or Repair damaged material

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School** INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Aircell Pipe Fitting Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---


### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Unexcavated Area in Basement**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS: **July 2019 partial abatement for crawlspace pipes servicing Rooms 112, 117, and 119**

Inspector's Signature: \_\_\_\_\_



Date: 08/18/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46041** BUIDLING ID: **1230**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School** REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Aircell Pipe Fitting Insulation**  
MATERIAL LOCATION: **Unexcavated Area in Basement**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

#### **Repair**

Comments:

Restrict access in affected areas. Remove or repair damaged materials

Management Planner's Signature:



Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)


LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46041**      BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School**      INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.**      IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **12"x12" Orange Floor Tile**  
MATERIAL LOCATION: **Rooms 228 & 234**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Nov 2020 abatement Room 228 & 234

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46041**      BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School**      REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.**      IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **12"x12" Orange Floor Tile**  
MATERIAL LOCATION: **Rooms 228 & 234**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)


LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46041**      BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School**      INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.**      IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Black Floor Tile**  
MATERIAL LOCATION: **Rooms 228 & 234**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Nov 2020 abatement Room 228 & 234

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46041**      BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School**      REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.**      IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Black Floor Tile**  
MATERIAL LOCATION: **Rooms 228 & 234**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **08/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)


LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46041**      BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School**      INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.**      IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Orange Floor Tile**  
MATERIAL LOCATION: **Rooms 228 & 234**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Nov 2020 abatement Room 228 & 234

Inspector's Signature:



Date: **08/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46041**      BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School**      REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.**      IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Orange Floor Tile**  
MATERIAL LOCATION: **Rooms 228 & 234**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)


LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46041**    BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School**    INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.**    IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **12"x12" Black Floor Tile**  
MATERIAL LOCATION: **Rooms 228 & 234**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Nov 2020 abatement Room 228 & 234

Inspector's Signature: \_\_\_\_\_



Date: 08/18/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46041**      BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School**      REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.**      IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **12"x12" Black Floor Tile**  
MATERIAL LOCATION: **Rooms 228 & 234**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **08/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)


LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46041**      BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Bogan Technical High School**      INSPECTION DATE: **8/18/2022**  
ADDRESS: **3939 W. 79th St.**      IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan or After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/18/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46041**      BUILDING ID: **1230**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Bogan Technical High School**      REVIEW DATE: **8/29/2022**  
ADDRESS: **3939 W. 79th St.**      IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan or After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **08/29/2022**

# APPENDIX B

## Inspector and Management Planner Licenses

---



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**MALLORY JONES**  
524 HOMELAND ROAD  
MATTESON, IL 60443

3/16/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11070

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>	
ID NUMBER <b>100 - 11070</b>	ISSUED <b>3/16/2022</b>	EXPIRES <b>05/15/2023</b>	
<b>MALLORY JONES</b> 524 HOMELAND ROAD MATTESON, IL 60443 Environmental Health			
		<b>ENDORSEMENTS</b> SUPERVISOR/WORKER INSPECTOR	<b>TC EXPIRES</b> 6/5/2022 3/9/2023
		PROJECT MANAGER AIR SAMPLING PROFESSIONAL	6/5/2022
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
Nationally Accredited by PHAB

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MALLORY JONES  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/09/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/09/2022

Course Dates:

03/09/2023

Expires:

2203BIR06

Certificate Number:

**PHS** Environmental &  
Occupational Services

37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)



**Director of Training**

**Nicholas J. Peneff**

**Doctor of Public Health**

Phone: 312-491-0081

**FORM # A-010B**

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that*

**Steve Geneser**

*has on 4/6/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: April 6, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: April 6, 2022

Expiration Date: April 6, 2023

Certificate Number: BIR/1044

*William S. Williams*

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois ☐ 217.787.9800 ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that* **Steve Geneser**

*has on 4/06/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: April 6, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: April 6, 2022

Expiration Date: April 6, 2023

*William S. Williams*

Certificate Number: MPR/0470

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois ☐ 217.787.9800 ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)





**ASBESTOS  
 PROFESSIONAL  
 LICENSE**

**ID NUMBER**  
**100 - 01784**

**ISSUED**  
**3/1/2022**

**EXPIRES**  
**05/15/2023**

**STEVEN B GENESER**  
**210 BARNSIDE CIRCLE**  
**GENEVA, IL 60134**

Environmental Health



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

5/5/2022

MANAGEMENT PLANNER

5/5/2022

PROJECT MANAGER

8/4/2022

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
 This license issued under authority of the State of Illinois  
 Department of Public Health  
 This license is valid only when accompanied by a valid  
 training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed