

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0012  
SCHOOL NAME: Fenger Academy  
ADDRESS OF SCHOOL: 11220 S. Wallace  
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **10/8/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 9/15/2022 ENROLLMENT 244  
IDPH INSPECTOR LICENSE NUMBER: 100-18281  
IDPH LICENSED INSPECTOR NAME (Please Print): Christopher Antonopoulos  
IDPH MP LICENSE NUMBER: 100-09870  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



10/13/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Fenger Academy**

11220 S. Wallace  
Chicago, IL, 60628

Unit: 46111  
Building ID: 1310

IDPH ID Number: 14-016-2990-0012

**REPORT DATE:**

Thursday, October 13, 2022

**Prepared for:**

**Chicago Public Schools  
42 W. Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

10/10/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 46111            Region: 06            IDPH ID: 14-016-2990-0012

School: Fenger Academy            Building ID: 1310

Address: 11220 S. Wallace

Chicago, IL, 60628

Building Contact: Gaynor, Mark

Contact Phone: 3129720733

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/15/2022

Review Date: 10/10/2022

Inspector: Christopher Antonopoulos

Inspector IDPH License: 100-18281

Management Planner: Todd Huffer

Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Todd Huffer  
100-09870

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: October 13, 2022

RE: Fenger Academy, Unit 46111  
11220 S. Wallace  
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Fenger Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Fenger Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Fenger Academy  
Address: 11220 S. Wallace  
IDPH ID: 14-016-2990-0012  
Contact: Gaynor, Mark

Unit: 46111  
Chicago, IL, 60628  
Building ID: 1310  
Phone: 3129720733

Region: 06

### 2. Description of Facility

Original Construction: 1926  
Total Square Footage: 341000  
Current Occupancy: 244

Additional Construction:  
No of Floors: 3

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Christopher Antonopoulos



Inspector IDPH license # 100-18281  
Reinspection Date: 9/15/2022

Signature:  
Date: 9/15/2022

### 6. Management Planner

Management Planner Name: Todd Huffer



Management Planner IDPH license # 100-09870

Signature:  
Date: 10/10/2022

### 7. Review Date: 10/10/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/13/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Fenger Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1310:

|     |  |
|-----|--|
| 41  | 12"x12" Red Green & White Mix Floor Tile                       |
| 42  | Mastic associated with 12"x12" Red Green & White Floor Tile    |
| 43  | 12"x12" Orange/Dark Grey Mix Floor Tile                        |
| 44  | Mastic associated with 12"x12" Orange/Dark Grey Mix Floor Tile |
| NEW | Newly Installed Suspect ACM                                    |
| T   | Green Carpet Adhesive  |

B. The following new homogenous areas have been identified for Building 1310:

|     |  |
|-----|--|
| 41  | 12"x12" Red Green & White Mix Floor Tile                       |
| 42  | Mastic associated with 12"x12" Red Green & White Floor Tile    |
| 43  | 12"x12" Orange/Dark Grey Mix Floor Tile                        |
| 44  | Mastic associated with 12"x12" Orange/Dark Grey Mix Floor Tile |
| NEW | Newly Installed Suspect ACM                                    |



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

|         |  |
|---------|--|
| 04      | Wainscoat  |
| 06      | Lab Table Tops   |
| 100     | 12" x 12" White Floor Tile w/Black Swirls                      |
| 17      | 12"x12" Gray Floor Tile  |
| 17A     | 12"x12" Gray Floor Tile Mastic                                 |
| 19      | Ceramic Tile Grout   |
| 20      | Terrazzo   |
| 24      | 1x1 Ceramic Tile Grout   |
| 25      | Green Linoleum   |
| 26      | Green Linoleum Mastic  |
| 27      | Cream Baseboard  |
| 28      | Cream Baseboard Mastic   |
| 29      | Black Vinyl Baseboard  |
| 30      | Black Vinyl Baseboard Mastic                                   |
| 31      | White Acoustic Wall Panels                                     |
| 32      | Decorative Plaster   |
| 33      | Aircell Pipe Insulation  |
| 34      | Orange Carpet Mastic   |
| 35      | Tan Carpet Mastic  |
| 36      | Green & Maroon Carpet Mastic                                   |
| 37      | 2'x2' White Ceiling Tile                                       |
| 38      | Dark Green Carpet Mastic                                       |
| 39      | Red Carpet Mastic  |
| 41      | 12"x12" Red Green & White Mix Floor Tile                       |
| 42      | Mastic associated with 12"x12" Red Green & White Floor Tile    |
| 43      | 12"x12" Orange/Dark Grey Mix Floor Tile                        |
| 44      | Mastic associated with 12"x12" Orange/Dark Grey Mix Floor Tile |
| CM1     | Brown Carpet Mastic  |
| CM2     | Mauve Carpet Mastic  |
| CM4     | Beige Carpet Mastic  |
| CM5     | Green Carpet Mastic  |
| CM6     | Blue Carpet Mastic   |
| HA-1000 | 2'x4' White Lay In Ceiling Tile                                |
| HA-1001 | 1'x1' White Ceiling Tile                                       |
| HA-1002 | Glue for 1'x1' White Ceiling Tile                              |
| HA-1003 | 2'x2' White Ceiling Tile                                       |
| JJ      | 2'x2' Creamic Floor Tile                                       |
| KK      | Blue Carpet Mastic   |
| LL      | Grey Carpet Mastic   |
| MFT-1   | 12x12 Red Floor Tile   |

|        |   |
|--------|---|
| MFT-2  | 12 x 12 Beige w/Brown Streaks Floor Tile        |
| MFTM-1 | 12x12 Red Floor Tile Mastic                     |
| MFTM-2 | 12 x 12 Beige w/Brown Streaks Floor Tile Mastic |
| MM     | Silver Duct Insulation                          |
| NEW    | Newly Installed Suspect ACM                     |
| OO     | 2'x4' Lay In Ceiling Tile                       |
| Q      | Carpet Mastic                                   |
| R      | Brown Carpet & Carpet Adhesive                  |
| RR     | Fire Brick and Mortar                           |
| S      | Grey/Purple Carpet Adhesive                     |
| SPA-1  | Plaster on Wire Mesh                            |
| SS     | Black Pool Lining Material                      |
| T      | Green Carpet Adhesive                           |
| U      | Brown Carpet Mastic                             |
| X      | Grey Linoleum and Adhesive                      |

The following areas were deemed to be inaccessible:

|         |   |
|---------|---|
| 08      | 9"x9" Cream w/Brown Streaks Floor Tile Mastic       |
| 09      | 12"x12" Off-White w/Tan Specks Floor Tile Mastic    |
| 14A     | 12"x12" Cream w/Tan Streaks Floor Tile Mastic       |
| 16A     | 12"x12" Dark Beige w/Brown Specks Floor Tile Mastic |
| 18A     | Black Linoleum Mastic                               |
| 26      | Green Linoleum Mastic                               |
| 28      | Cream Baseboard Mastic                              |
| 30      | Black Vinyl Baseboard Mastic                        |
| 36      | Green & Maroon Carpet Mastic                        |
| 38      | Dark Green Carpet Mastic                            |
| BB      | 12"x12" White Floor Tile Mastic                     |
| CM1     | Brown Carpet Mastic                                 |
| CM2     | Mauve Carpet Mastic                                 |
| CM4     | Beige Carpet Mastic                                 |
| CM5     | Green Carpet Mastic                                 |
| CM6     | Blue Carpet Mastic                                  |
| DD      | 12"x12" Brown Floor Tile Mastic                     |
| FF      | 12"x12" Cream w/Brown Specks Floor Tile Mastic      |
| HA-1002 | Glue for 1'x1' White Ceiling Tile                   |
| KK      | Blue Carpet Mastic                                  |
| LL      | Grey Carpet Mastic                                  |
| MFTM-1  | 12x12 Red Floor Tile Mastic                         |
| MFTM-2  | 12 x 12 Beige w/Brown Streaks Floor Tile Mastic     |
| P       | Wire Insulation                                     |
| Q       | Carpet Mastic                                       |
| R       | Brown Carpet & Carpet Adhesive                      |
| S       | Grey/Purple Carpet Adhesive                         |

|   |                                     |
|---|-------------------------------------|
| T | Green Carpet Adhesive               |
| U | Brown Carpet Mastic                 |
| W | 12"x12" Off White Floor Tile Mastic |
| Z | 9'x9' Beige Floor Tile Mastic       |

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Christopher Antonopoulos, IDPH License # 100-18281. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Fenger Academy Building 1310 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Fenger Academy Unit 46111 Building ID 1310

Address 11220 S. Wallace Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                     | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 01    | 12"x12" Off-White w/Tan Specks Floor Tile                | 8,976             | SF             | Rooms 144, 148, 143, 130, 131, 129, 128, 127, 115, 146, 217, 331, 348 & Serving Area            | CHR           | MISC              | N       | LOC         | 25              |              | No                            | ACBM with the potential for damage | 2             | LOW                   |
| 02    | 9x9 Cream w/Brown Streaks Floor Tile                     | 2,990             | SF             | Boiler Room, Engineer's Office, Cafeteria Office, Main Office Vault                             | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 04    | Wainscoat  | 20,000            | SF             | NOT LISTED  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 06    | Lab Table Tops   | 1,500             | SF             | Rooms 101, 105, 203, 207, 303, 307, and 301   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 08    | 9"x9" Cream w/Brown Streaks Floor Tile Mastic            | 2,290             | SF             | Boiler Room, Engineer's Office, Main Hall, 1st Floor, Main Office Vault                         | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 09    | 12"x12" Off-White w/Tan Specks Floor Tile Mastic         | 8,976             | SF             | Rooms 144, 148, 143, 130, 131, 129, 128, 127, 115, 217, 146, Main Office, Serving Area.         | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 10    | 9"x9" Beige Floor Tile w/Tan Steaks NOT OBSERVED         |                   |                | 1st Floor North Corridor  |               | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 100   | 12" x 12" White Floor Tile w/Black Swirls                | 750               | SF             | Room 500  | ASSUMED       | MISC              | N       |             | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 10A   | 9"x9" Beige w/Tan Streaks Floor Tile Mastic NOT OBSERVED |                   |                | 1st Floor North Corridor  |               | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 11    | 9"x9" Brown Floor Tile w/Red Streaks NOT OBSERVED        |                   |                | ROTC Vault Room, 115  |               | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 11A   | 9"x9" Brown w/Red Streaks Floor Tile Mastic NOTOBSERVED  |                   |                | ROTC Vault Room, 115  |               | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 12    | 9"x9" Green Floor Tile w/Tan Streaks NOT OBSERVED        |                   |                | Main Office Vault   |               | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 12A   | 9"x9" Green w/Tan Streaks Floor Tile Mastic NOTOBSERVED  |                   |                | Main Office Vault   |               | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 13    | 9"x9" Pink Floor Tile ABATED                             |                   |                | Room 331  | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 13A   | 9"x9" Pink Floor Tile Mastic ABATED                      |                   |                | Room 331  | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 14    | 12"x12" Cream w/Tan Specks Floor Tile                    | 19,730            | SF             | Throughout Facility, Including: 1st, 2nd & 3rd Floor Halls, Rooms 111, 113, 133, 135, 201, 209. | CHR           | MISC              | N       | NONE        | 30              |              | No                            | ACBM with the potential for damage | 3             | LOW                   |

# Chicago Public Schools

School Fenger Academy Unit 46111 Building ID 1310

Address 11220 S. Wallace Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       |   |                   |                | 211, 213, 229, 232, 233, 235, 250, 309, 311, 312, 313, 314, 315, 316, 320, 322, 323, 326, 329, 333, 335, 337, 342, and 2nd Floor Teachers' Lounge   |               |                   |         |             |                 |              |                               |                                    |               |                       |
| 14A   | 12"x12" Cream w/Tan Streaks Floor Tile Mastic       | 19,730            | SF             | Throughout Facility, Including: 1st, 2nd & 3rd Floor Halls, Rooms 111, 113, 133, 135, 201, 209, 211, 213, 229, 232, 233, 235, 250, 309, 311, 312, 313, 314, 315, 316, 320, 322, 323, 326, 329, 333, 335, 337, 342, and 2nd Floor Teachers' Lounge | CHR           | MISC              | N       | NONE        | 30              |              | No                            | ACBM with the potential for damage | 2             | LOW                   |
| 15    | 12"x12" Light Gray Floor Tile w/ Gray Streaks       | 20,363            | SF             | Rooms 111, 113, 212, 214, 216, 228, 233, 242, 244, 319, 322, 326, 330, 335, 344, 348, 350, 331, 328, 249, 239A, 230, 202, 128, 131, 135, 133, 143, 148, 148A, Band Room, Auditorium Corridor, Cafeteria, Serving Line                             | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 15A   | 12"x12" Light Gray w/Gray Streaks Floor Tile Mastic | 20,363            | SF             | Rooms 111, 113, 212, 214, 216, 228, 233, 242, 244, 319, 322, 326, 330, 335, 344, 348, 350, 331, 328, 249, 239A, 230, 202, 128, 131, 135, 133, 143, 148, 148A, Band Room, Auditorium Corridor, Cafeteria, Serving Line.                            | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Fenger Academy Unit 46111 Building ID 1310

Address 11220 S. Wallace Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 16    | 12"x12" Dark Beige Floor Tile w/Beige Specks        | 5,096             | SF             | Rms 317, 318, Serving Line, Kitchen, Dishwashing Area, Central Hall 1st Floor, Engineer's Wshrm      | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 16A   | 12"x12" Dark Beige w/Brown Specks Floor Tile Mastic | 5,096             | SF             | Rooms 317, 318, Serving Line, Kitchen, Dishwashing Area, Central Hall 1st Floor, Engineer's Washroom | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 17    | 12"x12" Gray Floor Tile                             | 5,846             | SF             | Rooms 101, 105, 203, 207, 303, and 307   | ASSUMED       | MISC              | N       |             | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 17A   | 12"x12" Gray Floor Tile Mastic                      | 5,846             | SF             | Rooms 101, 105, 203, 207, 303, and 307   | ASSUMED       | MISC              | N       |             | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 18    | Black Linoleum                                      | 5,472             | SF             | Auditorium   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 18A   | Black Linoleum Mastic                               | 5,472             | SF             | Auditorium   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 19    | Ceramic Tile Grout                                  | 5,000             | SF             | All Washrooms, Locker Rooms, Pool Area, 1st Floor Ramps, & Weight Room                               | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 20    | Terrazzo  | 27,702            | SF             | All Stairway Entries and Borders of all Hallways   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 21    | Transite Panels (Exhaust Hoods)                     |                   |                | Rooms 303, 307, 305  |               | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 22    | Gray Mopboard                                       |                   |                | Room 220   |               | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 22A   | Gray Mopboard Mastic                                |                   |                | Room 220   |               | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 23    | Aircell Sheeting ABATED                             |                   |                | Swimming Pool Area (Behind Radiator) - (Abated)  | ABATED        | TSI               |         |             |                 |              |                               |                                    |               |                       |
| 24    | 1x1 Ceramic Tile Grout                              | 1,400             | SF             | Swimming Pool Area   | ASSUMED       | MISC              | N       |             | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 25    | Green Linoleum                                      | 6,000             | SF             | Rooms 307, 301, 244A, 244, 303, 207, 203, 101, 103,  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |



# Chicago Public Schools

School Fenger Academy Unit 46111 Building ID 1310

Address 11220 S. Wallace Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
|       |   |                   |                | 105  |               |                   |         |             |                 |              |                               |  |               |                       |
| 26    | Green Linoleum Mastic                                       | 6,000             | SF             | Rooms 307, 301, 244A, 244, 303, 207, 203, 101, 103, 105                | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 27    | Cream Baseboard   | 5,800             | SF             | Rooms 307, 303, 344, 244A, 207, 203, 170, 103, 101, 105, and Cafeteria | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 28    | Cream Baseboard Mastic                                      | 5,800             | LF             | Rooms 307, 303, 344, 244A, 207, 203, 170, 103, 101, 105, and Cafeteria | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 29    | Black Vinyl Baseboard                                       | 200               | LF             | Room 220   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 30    | Black Vinyl Baseboard Mastic                                | 200               | LF             | Room 220   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 31    | White Acoustic Wall Panels                                  | 6,000             | SF             | Room 220, Auditorium   | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 32    | Decorative Plaster  | 100,000           | SF             | Auditorium, Auditorium Corridor, Library, Room 122, 120, Foyer         | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 33    | Aircell Pipe Insulation                                     | 45                | LF             | 2nd Floor Auditorium Storage   | ASSUMED       | TSI               | Y       | NONE        | 0               |              | No                            | Any remaining friable ACBM or friable suspect ACBM |               | LOW                   |
| 34    | Orange Carpet Mastic  | 2,000             | SF             | Room 115   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 35    | Tan Carpet Mastic   | 2,000             | SF             | Room 117   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 36    | Green & Maroon Carpet Mastic                                | 27,000            | SF             | Room 116, Offices, & Library   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 37    | 2'x2' White Ceiling Tile                                    | 2,000             | SF             | Room 117   | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 38    | Dark Green Carpet Mastic                                    | 200               | SF             | Main Office  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 39    | Red Carpet Mastic   | 700               | SF             | Room 142   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 40    | Red Linoleum  |                   |                | Room 140   |               | MISC              |         |             |                 |              |                               |  |               |                       |
| 41    | 12"x12" Red Green & White Mix Floor Tile                    | 2,000             | SF             | Room 101/105   | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage                 |               | LOW                   |
| 42    | Mastic associated with 12"x12" Red Green & White Floor Tile | 5,000             | SF             | Room 101/105   | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage                 |               | LOW                   |

# Chicago Public Schools

School Fenger Academy Unit 46111 Building ID 1310

Address 11220 S. Wallace Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

| HA No   | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|---------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 43      | 12"x12" Orange/Dark Grey Mix Floor Tile                        | 700               | SF             | Room 129   | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | LOW                   |
| 44      | Mastic associated with 12"x12" Orange/Dark Grey Mix Floor Tile | 700               | SF             | Room 129   | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | LOW                   |
| A       | Aircell Duct Wrap  | 105               | SF             | Auditorium (Stage)   | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| AA      | 12"x12 White Floor Tile  | 2,500             | SF             | Rooms 201, 318, Engineer's Office and Serving Area                 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| BB      | 12"x12" White Floor Tile Mastic                                | 2,500             | SF             | Rooms 201, 218, Engineer's Office and Serving Area                 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| CC      | 12"x12" Brown Floor Tile                                       | 4,000             | SF             | Rooms 201, 318, Cafeteria, Serving Area and Engineer's Office      | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| CM1     | Brown Carpet Mastic  | 800               | SF             | Main Office & Room 114   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| CM2     | Mauve Carpet Mastic  | 500               |                | Conference Room, Health Services Office, Student Act. Room         | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| CM4     | Beige Carpet Mastic  | 500               | SF             | Principal's Office   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| CM5     | Green Carpet Mastic  | 1,000             | SF             | Room 112, Library 2nd Floor  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| CM6     | Blue Carpet Mastic   |                   | SF             | Auditorium and Balcony   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| DD      | 12"x12" Brown Floor Tile Mastic                                | 4,000             | SF             | Room 201, 318, Cafeteria, Serving Area and Engineers Office        | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| EE      | 12"x12" Cream w/Brown Specks Floor Tile                        | 900               | SF             | Room 150   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| FF      | 12"x12" Cream w/Brown Specks Floor Tile Mastic                 | 900               | SF             | Room 150   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| GG      | 12"x12" Grey Floor Tile  |                   |                | Room 307   |               | MISC              |         |             |                 |              |                               |                                    |               |                       |
| HA-1000 | 2'x4' White Lay In Ceiling Tile                                | 200,000           | SF             | Hallways and Classrooms  | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| HA-1001 | 1'x1' White Ceiling Tile                                       | 2,500             | SF             | Kitchen Serving Line, Rooms 331, 323 315, 314, 313, 249, 128 & 114 | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| HA-1002 | Glue for 1'x1' White Ceiling Tile                              | 2,400             | SF             | Kitchen Serving  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the                      |               | LOW                   |

# Chicago Public Schools

School Fenger Academy Unit 46111 Building ID 1310

Address 11220 S. Wallace Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

| HA No   | Material Description                            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|---------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|         |   |                   |                | Line, Rooms 331, 323, 315, 314, 313, 249, 128                           |               |                   |         |             |                 |              |                               | potential for damage               |               |                       |
| HA-1003 | 2'x2' White Ceiling Tile                        | 1,000             | SF             | Kitchen Food Prep Area  | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| HH      | 12"x12" Grey Floor Tile Mastic                  |                   |                | Room 307  |               | MISC              |         |             |                 |              |                               |                                    |               |                       |
| II      | Orange Linoleum and Adhesive                    |                   |                | Room 301  |               | MISC              |         | None        |                 |              |                               |                                    |               | Low                   |
| JJ      | 2'x2' Creamic Floor Tile                        | 1,500             | SF             | Washrooms   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| KK      | Blue Carpet Mastic                              |                   |                | Auditorium  | ASSUMED       | MISC              | N       |             | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| LL      | Grey Carpet Mastic                              |                   |                | Main Office, Auditorium, 248, 118                                       | ASSUMED       | MISC              | N       |             | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| MFT-1   | 12x12 Red Floor Tile                            | 180               | SF             | 1st Floor Hallway   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| MFT-2   | 12 x 12 Beige w/Brown Streaks Floor Tile        | 9,000             | SF             | 1st Floor Hallway, 170, 171   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| MFTM-1  | 12x12 Red Floor Tile Mastic                     | 180               | SF             | 1st Floor Hallway   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| MFTM-2  | 12 x 12 Beige w/Brown Streaks Floor Tile Mastic | 9,000             | SF             | 1st Floor Hallway, 170, 171   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| MM      | Silver Duct Insulation                          | 300               | LF             | Basement  | ASSUMED       | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| NEW     | Newly Installed Suspect ACM                     |                   |                | Installed After Implementation of Management Plan and After Renovations | ASSUMED       | MISC              |         | UNKNO WN    |                 |              | Yes                           | ACBM with the potential for damage |               |                       |
| NN      | Hair Dryer Insulation                           |                   |                | Drying Room   |               | SURFACE           |         |             |                 |              |                               |                                    |               |                       |
| OO      | 2'x4' Lay In Ceiling Tile                       | 4,000             | SF             | Throughout  | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| P       | Wire Insulation                                 | 250               | LF             | Auditorium  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| PP      | MJP E/F/V on Pipe Insulation                    | 50                | LF             | Boiler Room   | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| Q       | Carpet Mastic                                   | 8,272             | SF             | Auditorium, 114, 123, 126, 130  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| QQ      | MJP E/F/V on Pipe Insulation                    | 3,000             | LF             | Air Tunnels and Basement Corridors                                      | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| R       | Brown Carpet & Carpet Adhesive                  | 1,500             | SF             | Main Office, 126  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| RR      | Fire Brick and Mortar                           | 5,000             | SF             | Throughout Interior Wall Cavities and                                   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Fenger Academy Unit 46111 Building ID 1310

Address 11220 S. Wallace Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|-------------------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       |                                     |                   |                | Roof Deck                 |               |                   |         |             |                 |              |                               |                                    |               |                       |
| S     | Grey/Purple Carpet Adhesive         | 3,200             | SF             | Rooms 132, 220, 122, 120  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| SPA-1 | Plaster on Wire Mesh                | 50,000            | SF             | Throughout School         | ASSUMED       | SURFACE           | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| SS    | Black Pool Lining Material          | 2,000             | SF             | Pool Room                 | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| T     | Green Carpet Adhesive               | 1,500             | SF             | Rooms 117 and 223         | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | LOW                   |
| U     | Brown Carpet Mastic                 | 1,500             | SF             | Rooms 112, 130 and 116    | ASSUMED       | MISC              | N       |             | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| V     | 12"x12" Off White Floor Tile        | 300               | SF             | Only observed in Room 342 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| W     | 12"x12" Off White Floor Tile Mastic | 300               | SF             | Only Observed in Room 342 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| X     | Grey Linoleum and Adhesive          | 6,200             | SF             | Only Observed in Room 346 | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| Y     | 9'x9' Beige Floor Tile              | 100               | SF             | Room 100C                 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| Z     | 9'x9' Beige Floor Tile Mastic       | 100               | SF             | 100C                      | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Fenger Academy Unit 46111 Building ID 1310  
Address 11220 S. Wallace Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

|   |
|---|
| Reinspection Date <b>9/15/2022</b>                |
| Inspector Name <b>Christopher Antonopoulos</b>    |
| <b>100-18281</b> <b>5/15/2023</b>                 |
| Inspector's IDPH License Number / Expiration Date |

### Inspector's Comments

| HA Number: | Inspector Comments:                      |
|------------|--|
| 01         | 25 SF of Damaged Tile in Room 128        |
| 02         | Not Observed in Room 130                 |
| 04         | Not Observed 2022                        |
| 06         |  |
| 08         | Not Observed in Main Hall                |
| 09         | Not Observed in Main Office & Room 130   |
| 10         | Not Observed 2019 & 2022                 |
| 100        |  |
| 10A        | Not Observed 2019 & 2022                 |
| 11         | Not Observed 2019                        |
| 11A        | Not Observed 2019                        |
| 12         | Not Observed 2019 & 2022                 |
| 12A        | Not Observed 2019 & 2022                 |
| 13         |  |
| 13A        |  |
| 14         | 30 SF of Damaged Tile in Rooms 250 & 329 |
| 14A        | 30 SF of Damaged Tile in Rooms 250 & 329 |
| 15         | No Access to Room 148A                   |
| 15A        | No Access to Room 148A                   |
| 16         |  |
| 16A        |  |
| 17         | Not Observed in Room 101 or 105          |
| 17A        | Not Observed in Room 101 or 105          |
| 18         | Not Observed. Possibly Under Carpet      |

# Chicago Public Schools

School Fenger Academy Unit 46111 Building ID 1310

Address 11220 S. Wallace Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments:                 |
|------------|-------------------------------------|
| 18A        | Not Observed. Possibly Under Carpet |
| 19         | Not Observed in Weight Room         |
| 20         |                                     |
| 21         | Not Observed 2019 & 2022            |
| 22         | Not Observed 2019 & 2022            |
| 22A        | Not Observed 2019 & 2022            |
| 23         |                                     |
| 24         |                                     |
| 25         | Not Observed in Rooms 101 or 105    |
| 26         | Not Observed in Rooms 101 or 105    |
| 27         |                                     |
| 28         |                                     |
| 29         |                                     |
| 30         |                                     |
| 31         |                                     |
| 32         |                                     |
| 33         |                                     |
| 34         |                                     |
| 35         |                                     |
| 36         |                                     |
| 37         |                                     |
| 38         |                                     |
| 39         |                                     |
| 40         | Not Observed in Rooms 2019 & 2022   |
| 41         |                                     |
| 42         |                                     |
| 43         |                                     |
| 44         |                                     |
| A          |                                     |

# Chicago Public Schools

School Fenger Academy Unit 46111 Building ID 1310

Address 11220 S. Wallace Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments:               |
|------------|-----------------------------------|
| AA         | Not Observed in Engineer's Office |
| BB         | Not Observed in Engineer's Office |
| CC         | Not Observed in Engineer's Office |
| CM1        |                                   |
| CM2        |                                   |
| CM4        |                                   |
| CM5        |                                   |
| CM6        |                                   |
| DD         | Not Observed in Engineer's Office |
| EE         |                                   |
| FF         |                                   |
| GG         | Not Observed 2019 & 2022          |
| HA-1000    |                                   |
| HA-1001    |                                   |
| HA-1002    |                                   |
| HA-1003    |                                   |
| HH         | Not Observed 2019 & 2022          |
| II         | Not Observed 2019 & 2022          |
| JJ         |                                   |
| KK         |                                   |
| LL         |                                   |
| MFT-1      |                                   |
| MFT-2      |                                   |
| MFTM-1     |                                   |
| MFTM-2     |                                   |
| MM         |                                   |
| NEW        |                                   |
| NN         | Not Observed 2019 & 2022          |
| OO         |                                   |

# Chicago Public Schools

School Fenger Academy Unit 46111 Building ID 1310

Address 11220 S. Wallace Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments:      |
|------------|--------------------------|
| P          |                          |
| PP         |                          |
| Q          | Not Observed in Room 126 |
| QQ         |                          |
| R          | Not Observed in Room 126 |
| RR         |                          |
| S          |                          |
| SPA-1      |                          |
| SS         |                          |
| T          |                          |
| U          |                          |
| V          | See 01                   |
| W          | See 09                   |
| X          |                          |
| Y          |                          |
| Z          |                          |



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Fenger Academy  
Address 11220 S. Wallace

Unit 46111  
Chicago, IL, 60628

Building ID 1310  
Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description                                     | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 01     | 12"x12" Off-White w/Tan Specks Floor Tile                | 8,976             | SF             | Rooms 144, 148, 143, 130, 131, 129, 128, 127, 115, 146, 217, 331, 348 & Serving Area  | Chrysotile    | MISC              | No      | 25              | SF           | 6 ACBM with the potential for damage | Repair          |
| 02     | 9x9 Cream w/Brown Streaks Floor Tile                     | 2,990             | SF             | Boiler Room, Engineer's Office, Cafeteria Office, Main Office Vault   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 04     | Wainscoat  | 20,000            | SF             | NOT LISTED  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 06     | Lab Table Tops   | 1,500             | SF             | Rooms 101, 105, 203, 207, 303, 307, and 301   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 08     | 9"x9" Cream w/Brown Streaks Floor Tile Mastic            | 2,290             | SF             | Boiler Room, Engineer's Office, Main Hall, 1st Floor, Main Office Vault   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 09     | 12"x12" Off-White w/Tan Specks Floor Tile Mastic         | 8,976             | SF             | Rooms 144, 148, 143, 130, 131, 129, 128, 127, 115, 217, 146, Main Office, Serving Area.   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 10     | 9"x9" Beige Floor Tile w/Tan Steaks NOT OBSERVED         |                   |                | 1st Floor North Corridor  |               | MISC              |         |                 |              |                                      |                 |
| 100    | 12" x 12" White Floor Tile w/Black Swirls                | 750               | SF             | Room 500  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 10A    | 9"x9" Beige w/Tan Streaks Floor Tile Mastic NOT OBSERVED |                   |                | 1st Floor North Corridor  |               | MISC              |         |                 |              |                                      |                 |
| 11     | 9"x9" Brown Floor Tile w/Red Streaks NOT OBSERVED        |                   |                | ROTC Vault Room, 115  |               | MISC              |         |                 |              |                                      |                 |
| 11A    | 9"x9" Brown w/Red Streaks Floor Tile Mastic NOTOBSERVED  |                   |                | ROTC Vault Room, 115  |               | MISC              |         |                 |              |                                      |                 |
| 12     | 9"x9" Green Floor Tile w/Tan Streaks NOT OBSERVED        |                   |                | Main Office Vault   |               | MISC              |         |                 |              |                                      |                 |
| 12A    | 9"x9" Green w/Tan Streaks Floor Tile Mastic NOTOBSERVED  |                   |                | Main Office Vault   |               | MISC              |         |                 |              |                                      |                 |
| 13     | 9"x9" Pink Floor Tile ABATED                             |                   |                | Room 331  | Abated        | MISC              |         |                 |              |                                      |                 |
| 13A    | 9"x9" Pink Floor Tile Mastic ABATED                      |                   |                | Room 331  | Abated        | MISC              |         |                 |              |                                      |                 |
| 14     | 12"x12" Cream w/Tan Specks Floor Tile                    | 19,730            | SF             | Throughout Facility, Including: 1st, 2nd & 3rd Floor Halls, Rooms 111, 113, 133, 135, 201, 209, 211, 213, 229, 232, 233, 235, 250, 309, 311, 312, 313, 314, 315, 316, 320, 322, 323, 326, 329, 333, 335, 337, 342, and 2nd Floor Teachers' Lounge | Chrysotile    | MISC              | No      | 30              | SF           | 6 ACBM with the potential for damage | Repair          |
| 14A    | 12"x12" Cream w/Tan Streaks Floor Tile Mastic            | 19,730            | SF             | Throughout Facility, Including: 1st, 2nd  | Chrysotile    | MISC              | No      | 30              | SF           | 6 ACBM with the potential for damage | Repair          |

# Chicago Public Schools

School Fenger Academy

Unit 46111

Building ID 1310

Address 11220 S. Wallace

Chicago, IL, 60628

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description                                | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
|        |   |                   |                | & 3rd Floor Halls, Rooms 111, 113, 133, 135, 201, 209, 211, 213, 229, 232, 233, 235, 250, 309, 311, 312, 313, 314, 315, 316, 320, 322, 323, 326, 329, 333, 335, 337, 342, and 2nd Floor Teachers' Lounge               |               |                   |         |                 |              |                                      |                 |
| 15     | 12"x12" Light Gray Floor Tile w/ Gray Streaks       | 20,363            | SF             | Rooms 111, 113, 212, 214, 216, 228, 233, 242, 244, 319, 322, 326, 330, 335, 344, 348, 350, 331, 328, 249, 239A, 230, 202, 128, 131, 135, 133, 143, 148, 148A, Band Room, Auditorium Corridor, Cafeteria, Serving Line  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 15A    | 12"x12" Light Gray w/Gray Streaks Floor Tile Mastic | 20,363            | SF             | Rooms 111, 113, 212, 214, 216, 228, 233, 242, 244, 319, 322, 326, 330, 335, 344, 348, 350, 331, 328, 249, 239A, 230, 202, 128, 131, 135, 133, 143, 148, 148A, Band Room, Auditorium Corridor, Cafeteria, Serving Line. | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 16     | 12"x12" Dark Beige Floor Tile w/Beige Specks        | 5,096             | SF             | Rms 317, 318, Serving Line, Kitchen, Dishwashing Area, Central Hall 1st Floor, Engineer's Wshrm  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 16A    | 12"x12" Dark Beige w/Brown Specks Floor Tile Mastic | 5,096             | SF             | Rooms 317, 318, Serving Line, Kitchen, Dishwashing Area, Central Hall 1st Floor, Engineer's Washroom   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 17     | 12"x12" Gray Floor Tile                             | 5,846             | SF             | Rooms 101, 105, 203, 207, 303, and 307   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 17A    | 12"x12" Gray Floor Tile Mastic                      | 5,846             | SF             | Rooms 101, 105, 203, 207, 303, and 307   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18     | Black Linoleum                                      | 5,472             | SF             | Auditorium   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18A    | Black Linoleum Mastic                               | 5,472             | SF             | Auditorium   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 19     | Ceramic Tile Grout                                  | 5,000             | SF             | All Washrooms, Locker Rooms, Pool Area, 1st Floor Ramps, & Weight Room   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 20     | Terrazzo  | 27,702            | SF             | All Stairway Entries and Borders of all Hallways   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 21     | Transite Panels (Exhaust Hoods)                     |                   |                | Rooms 303, 307, 305  |               | MISC              |         |                 |              |                                      |                 |

# Chicago Public Schools

School Fenger Academy

Unit 46111

Building ID 1310

Address 11220 S. Wallace

Chicago, IL, 60628

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                                      | Response        |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 22     | Gray Mopboard  |                   |                | Room 220   |               | MISC              |         |                 |              |  |                 |
| 22A    | Gray Mopboard Mastic   |                   |                | Room 220   |               | MISC              |         |                 |              |  |                 |
| 23     | Aircell Sheeting ABATED  |                   |                | Swimming Pool Area (Behind Radiator) - (Abated)                        | Abated        | TSI               |         |                 |              |  |                 |
| 24     | 1x1 Ceramic Tile Grout   | 1,400             | SF             | Swimming Pool Area   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 25     | Green Linoleum   | 6,000             | SF             | Rooms 307, 301, 244A, 244, 303, 207, 203, 101, 103, 105                | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 26     | Green Linoleum Mastic  | 6,000             | SF             | Rooms 307, 301, 244A, 244, 303, 207, 203, 101, 103, 105                | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 27     | Cream Baseboard  | 5,800             | SF             | Rooms 307, 303, 344, 244A, 207, 203, 170, 103, 101, 105, and Cafeteria | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 28     | Cream Baseboard Mastic   | 5,800             | LF             | Rooms 307, 303, 344, 244A, 207, 203, 170, 103, 101, 105, and Cafeteria | Assumed       | MISC              | No      | 0               | LF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 29     | Black Vinyl Baseboard  | 200               | LF             | Room 220   | Assumed       | MISC              | No      | 0               | LF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 30     | Black Vinyl Baseboard Mastic                                   | 200               | LF             | Room 220   | Assumed       | MISC              | No      | 0               | LF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 31     | White Acoustic Wall Panels                                     | 6,000             | SF             | Room 220, Auditorium   | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 32     | Decorative Plaster   | 100,000           | SF             | Auditorium, Auditorium Corridor, Library, Room 122, 120, Foyer         | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 33     | Aircell Pipe Insulation  | 45                | LF             | 2nd Floor Auditorium Storage   | Assumed       | TSI               | Yes     | 0               | LF           | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 34     | Orange Carpet Mastic   | 2,000             | SF             | Room 115   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 35     | Tan Carpet Mastic  | 2,000             | SF             | Room 117   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 36     | Green & Maroon Carpet Mastic                                   | 27,000            | SF             | Room 116, Offices, & Library   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 37     | 2'x2' White Ceiling Tile                                       | 2,000             | SF             | Room 117   | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 38     | Dark Green Carpet Mastic                                       | 200               | SF             | Main Office  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 39     | Red Carpet Mastic  | 700               | SF             | Room 142   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 40     | Red Linoleum   |                   |                | Room 140   |               | MISC              |         |                 |              |  |                 |
| 41     | 12"x12" Red Green & White Mix Floor Tile                       | 2,000             | SF             | Room 101/105   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 42     | Mastic associated with 12"x12" Red Green & White Floor Tile    | 5,000             | SF             | Room 101/105   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 43     | 12"x12" Orange/Dark Grey Mix Floor Tile                        | 700               | SF             | Room 129   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 44     | Mastic associated with 12"x12" Orange/Dark Grey Mix Floor Tile | 700               | SF             | Room 129   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| A      | Aircell Duct Wrap  | 105               | SF             | Auditorium (Stage)   | Chrysotile    | TSI               | Yes     | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| AA     | 12"x12 White Floor Tile  | 2,500             | SF             | Rooms 201, 318, Engineer's Office and                                  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |

# Chicago Public Schools

School Fenger Academy

Unit 46111

Building ID 1310

Address 11220 S. Wallace

Chicago, IL, 60628

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

| HA Num  | Material Description                            | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|---------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
|         |   |                   |                | Serving Area   |               |                   |         |                 |              |                                      |                 |
| BB      | 12"x12" White Floor Tile Mastic                 | 2,500             | SF             | Rooms 201, 218, Engineer's Office and Serving Area                 | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| CC      | 12"x12" Brown Floor Tile                        | 4,000             | SF             | Rooms 201, 318, Cafeteria, Serving Area and Engineer's Office      | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| CM1     | Brown Carpet Mastic                             | 800               | SF             | Main Office & Room 114   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| CM2     | Mauve Carpet Mastic                             | 500               |                | Conference Room, Health Services Office, Student Act. Room         | Assumed       | MISC              | No      | 0               |              | 6 ACBM with the potential for damage | Follow O&M Plan |
| CM4     | Beige Carpet Mastic                             | 500               | SF             | Principal's Office   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| CM5     | Green Carpet Mastic                             | 1,000             | SF             | Room 112, Library 2nd Floor  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| CM6     | Blue Carpet Mastic                              |                   | SF             | Auditorium and Balcony   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| DD      | 12"x12" Brown Floor Tile Mastic                 | 4,000             | SF             | Room 201, 318, Cafeteria, Serving Area and Engineers Office        | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| EE      | 12"x12" Cream w/Brown Specks Floor Tile         | 900               | SF             | Room 150   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| FF      | 12"x12" Cream w/Brown Specks Floor Tile Mastic  | 900               | SF             | Room 150   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| GG      | 12"x12" Grey Floor Tile                         |                   |                | Room 307   |               | MISC              |         |                 |              |                                      |                 |
| HA-1000 | 2'x4' White Lay In Ceiling Tile                 | 200,000           | SF             | Hallways and Classrooms  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1001 | 1'x1' White Ceiling Tile                        | 2,500             | SF             | Kitchen Serving Line, Rooms 331, 323 315, 314, 313, 249, 128 & 114 | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1002 | Glue for 1'x1' White Ceiling Tile               | 2,400             | SF             | Kitchen Serving Line, Rooms 331, 323 315, 314, 313, 249, 128       | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1003 | 2'x2' White Ceiling Tile                        | 1,000             | SF             | Kitchen Food Prep Area   | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HH      | 12"x12" Grey Floor Tile Mastic                  |                   |                | Room 307   |               | MISC              |         |                 |              |                                      |                 |
| II      | Orange Linoleum and Adhesive                    |                   |                | Room 301   |               | MISC              |         |                 |              |                                      |                 |
| JJ      | 2'x2' Creamic Floor Tile                        | 1,500             | SF             | Washrooms  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| KK      | Blue Carpet Mastic                              |                   |                | Auditorium   | Assumed       | MISC              | No      | 0               |              | 6 ACBM with the potential for damage | Follow O&M Plan |
| LL      | Grey Carpet Mastic                              |                   |                | Main Office, Auditorium, 248, 118                                  | Assumed       | MISC              | No      | 0               |              | 6 ACBM with the potential for damage | Follow O&M Plan |
| MFT-1   | 12x12 Red Floor Tile                            | 180               | SF             | 1st Floor Hallway  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| MFT-2   | 12 x 12 Beige w/Brown Streaks Floor Tile        | 9,000             | SF             | 1st Floor Hallway, 170, 171  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| MFTM-1  | 12x12 Red Floor Tile Mastic                     | 180               | SF             | 1st Floor Hallway  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| MFTM-2  | 12 x 12 Beige w/Brown Streaks Floor Tile Mastic | 9,000             | SF             | 1st Floor Hallway, 170, 171  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Fenger Academy  
**Address** 11220 S. Wallace

**Unit** 46111  
 Chicago, IL, 60628

**Building ID** 1310  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

| HA Num | Material Description                | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|-------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| MM     | Silver Duct Insulation              | 300               | LF             | Basement  | Assumed       | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| NEW    | Newly Installed Suspect ACM         |                   |                | Installed After Implementation of Management Plan and After Renovations | Assumed       | MISC              |         |                 |              | 6 ACBM with the potential for damage | Follow O&M Plan |
| NN     | Hair Dryer Insulation               |                   |                | Drying Room   |               | SURFACE           |         |                 |              |                                      |                 |
| OO     | 2'x4' Lay In Ceiling Tile           | 4,000             | SF             | Throughout  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| P      | Wire Insulation                     | 250               | LF             | Auditorium  | Chrysotile    | MISC              | No      | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| PP     | MJP E/F/V on Pipe Insulation        | 50                | LF             | Boiler Room   | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| Q      | Carpet Mastic                       | 8,272             | SF             | Auditorium, 114, 123, 126, 130  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| QQ     | MJP E/F/V on Pipe Insulation        | 3,000             | LF             | Air Tunnels and Basement Corridors                                      | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| R      | Brown Carpet & Carpet Adhesive      | 1,500             | SF             | Main Office, 126  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| RR     | Fire Brick and Mortar               | 5,000             | SF             | Throughout Interior Wall Cavities and Roof Deck                         | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| S      | Grey/Purple Carpet Adhesive         | 3,200             | SF             | Rooms 132, 220, 122, 120  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| SPA-1  | Plaster on Wire Mesh                | 50,000            | SF             | Throughout School   | Assumed       | SURFACE           | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| SS     | Black Pool Lining Material          | 2,000             | SF             | Pool Room   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| T      | Green Carpet Adhesive               | 1,500             | SF             | Rooms 117 and 223   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| U      | Brown Carpet Mastic                 | 1,500             | SF             | Rooms 112, 130 and 116  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| V      | 12"x12" Off White Floor Tile        | 300               | SF             | Only observed in Room 342   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| W      | 12"x12" Off White Floor Tile Mastic | 300               | SF             | Only Observed in Room 342   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| X      | Grey Linoleum and Adhesive          | 6,200             | SF             | Only Observed in Room 346   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| Y      | 9'x9' Beige Floor Tile              | 100               | SF             | Room 100C   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| Z      | 9'x9' Beige Floor Tile Mastic       | 100               | SF             | 100C  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Fenger Academy  
**Address** 11220 S. Wallace

**Unit** 46111  
 Chicago, IL, 60628

**Building ID** 1310  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

|                                    |             |
|------------------------------------|-------------|
| Review Date                        | 10/10/2022  |
| Manager Planner Name               | Todd Huffer |
| 100-09870                          | 5/15/2023   |
| Manager IDPH License No/Expiration |             |

| HA Number | Management Comments           |
|-----------|-------------------------------|
| 01        | Patch & Repair                |
| 02        |                               |
| 04        |                               |
| 06        |                               |
| 08        |                               |
| 09        |                               |
| 10        |                               |
| 100       |                               |
| 10A       |                               |
| 11        |                               |
| 11A       |                               |
| 12        |                               |
| 12A       |                               |
| 13        |                               |
| 13A       |                               |
| 14        | Patch and Repair Damaged Tile |

# Chicago Public Schools

**School** Fenger Academy  
**Address** 11220 S. Wallace

**Unit** 46111  
Chicago, IL, 60628

**Building ID** 1310  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments        |
|-----------|----------------------------|
| 14A       | Patch & Repair. Follow O&M |
| 15        |                            |
| 15A       |                            |
| 16        |                            |
| 16A       |                            |
| 17        |                            |
| 17A       |                            |
| 18        |                            |
| 18A       |                            |
| 19        |                            |
| 20        |                            |
| 21        |                            |
| 22        |                            |
| 22A       |                            |
| 23        |                            |
| 24        |                            |
| 25        |                            |
| 26        |                            |
| 27        |                            |
| 28        |                            |
| 29        |                            |
| 30        |                            |
| 31        |                            |
| 32        |                            |
| 33        |                            |
| 34        |                            |
| 35        |                            |



# Chicago Public Schools

**School** Fenger Academy  
**Address** 11220 S. Wallace

**Unit** 46111  
 Chicago, IL, 60628

**Building ID** 1310  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 36        |                     |
| 37        |                     |
| 38        |                     |
| 39        |                     |
| 40        |                     |
| 41        |                     |
| 42        |                     |
| 43        |                     |
| 44        |                     |
| A         |                     |
| AA        |                     |
| BB        |                     |
| CC        |                     |
| CM1       |                     |
| CM2       |                     |
| CM4       |                     |
| CM5       |                     |
| CM6       |                     |
| DD        |                     |
| EE        |                     |
| FF        |                     |
| GG        |                     |
| HA-1000   |                     |
| HA-1001   |                     |
| HA-1002   |                     |
| HA-1003   |                     |
| HH        |                     |

# Chicago Public Schools

**School** Fenger Academy  
**Address** 11220 S. Wallace

**Unit** 46111  
 Chicago, IL, 60628

**Building ID** 1310  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| II        |                     |
| JJ        |                     |
| KK        |                     |
| LL        |                     |
| MFT-1     |                     |
| MFT-2     |                     |
| MFTM-1    |                     |
| MFTM-2    |                     |
| MM        |                     |
| NEW       |                     |
| NN        |                     |
| OO        |                     |
| P         |                     |
| PP        |                     |
| Q         |                     |
| QQ        |                     |
| R         |                     |
| RR        |                     |
| S         |                     |
| SPA-1     |                     |
| SS        |                     |
| T         |                     |
| U         |                     |
| V         |                     |
| W         |                     |
| X         |                     |
| Y         |                     |

# Chicago Public Schools

**School** Fenger Academy  
**Address** 11220 S. Wallace

**Unit** 46111  
Chicago, IL, 60628

**Building ID** 1310  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| Z         |                     |

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

## 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12"x12" Off-White w/Tan Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 144, 148, 143, 130, 131, 129, 128, 127, 115, 146, 217, 331, 348 & Serving Area**  
MATERIAL QUANTITY: **8976** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **8976** DAMAGE UNITS: **SF**  
COMMENTS: **25 SF of Damaged Tile in Room 128**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12"x12" Off-White w/Tan Specks Floor Tile**  
MATERIAL LOCATION: **Rooms 144, 148, 143, 130, 131, 129, 128, 127, 115, 146, 217, 331, 348 & Serving Area**  
MATERIAL QUANTITY: **8976** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Patch & Repair

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 02  
MATERIAL DESCRIPTION: 9x9 Cream w/Brown Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Boiler Room, Engineer's Office, Cafeteria Office, Main Office Vault  
MATERIAL QUANTITY: 2990    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Room 130

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **9x9 Cream w/Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Boiler Room, Engineer's Office, Cafeteria Office, Main Office Vault**  
MATERIAL QUANTITY: **2990** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04  
MATERIAL DESCRIPTION: Wainscoat  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: NOT LISTED  
MATERIAL QUANTITY: 20000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Wainscoat**  
MATERIAL LOCATION: **NOT LISTED**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 06  
MATERIAL DESCRIPTION: Lab Table Tops  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 101, 105, 203, 207, 303, 307, and 301  
MATERIAL QUANTITY: 1500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Lab Table Tops**  
MATERIAL LOCATION: **Rooms 101, 105, 203, 207, 303, 307, and 301**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 08  
MATERIAL DESCRIPTION: 9"x9" Cream w/Brown Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Boiler Room, Engineer's Office, Main Hall, 1st Floor, Main Office Vault  
MATERIAL QUANTITY: 2290    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Main Hall

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **9"x9" Cream w/Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Boiler Room, Engineer's Office, Main Hall, 1st Floor, Main Office Vault**  
MATERIAL QUANTITY: **2290** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" Off-White w/Tan Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 144, 148, 143, 130, 131, 129, 128, 127, 115, 217, 146, Main Office, Serving Area.**  
MATERIAL QUANTITY: **8976** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Main Office & Room 130**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" Off-White w/Tan Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 144, 148, 143, 130, 131, 129, 128, 127, 115, 217, 146, Main Office, Serving Area.**  
MATERIAL QUANTITY: **8976** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile w/Tan Steaks NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor North Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile w/Tan Steaks NOT OBSERVED**  
MATERIAL LOCATION: **1st Floor North Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 100  
MATERIAL DESCRIPTION: 12" x 12" White Floor Tile w/Black Swirls  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 500  
MATERIAL QUANTITY: 750    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Black Swirls**  
MATERIAL LOCATION: **Room 500**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **9"x9" Beige w/Tan Streaks Floor Tile Mastic NOT OBSERVED**  
MATERIAL LOCATION: **1st Floor North Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile w/Red Streaks NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROTC Vault Room, 115**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile w/Red Streaks NOT OBSERVED**

MATERIAL LOCATION: **ROTC Vault Room, 115**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **9"X9" Brown w/Red Streaks Floor Tile Mastic NOTOBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROTC Vault Room, 115**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **9"X9" Brown w/Red Streaks Floor Tile Mastic NOTOBSERVED**  
MATERIAL LOCATION: **ROTC Vault Room, 115**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022** \_\_\_\_\_



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9"x9" Green Floor Tile w/Tan Streaks NOT OBSERVED**

MATERIAL LOCATION: **Main Office Vault**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **9"x9" Green w/Tan Streaks Floor Tile Mastic NOTOBSERVED**  
MATERIAL LOCATION: **Main Office Vault**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13  
MATERIAL DESCRIPTION: 9"x9" Pink Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Room 331  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9"x9" Pink Floor Tile ABATED**

MATERIAL LOCATION: **Room 331**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13A  
MATERIAL DESCRIPTION: 9"x9" Pink Floor Tile Mastic ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Room 331  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13A**  
MATERIAL DESCRIPTION: **9"x9" Pink Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **Room 331**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Facility, Including: 1st, 2nd & 3rd Floor Halls, Rooms 111, 113, 133, 135, 201, 209, 211, 213, 229, 232, 233, 235, 250, 309, 311, 312, 313, 314, 315, 316, 320, 322, 323, 326, 329, 333, 335, 337, 342, and 2nd Floor Teachers' Lounge**  
MATERIAL QUANTITY: **19730** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **30 SF of Damaged Tile in Rooms 250 & 329**

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Specks Floor Tile**  
MATERIAL LOCATION: **Throughout Facility, Including: 1st, 2nd & 3rd Floor Halls, Rooms 111, 113, 133, 135, 201, 209, 211, 213, 229, 232, 233, 235, 250, 309, 311, 312, 313, 314, 315, 316, 320, 322, 323, 326, 329, 333, 335, 337, 342, and 2nd Floor Teachers' Lounge**  
MATERIAL QUANTITY: **19730** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Patch and Repair Damaged Tile

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Facility, Including: 1st, 2nd & 3rd Floor Halls, Rooms 111, 113, 133, 135, 201, 209, 211, 213, 229, 232, 233, 235, 250, 309, 311, 312, 313, 314, 315, 316, 320, 322, 323, 326, 329, 333, 335, 337, 342, and 2nd Floor Teachers' Lounge**  
MATERIAL QUANTITY: **19730** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **30 SF of Damaged Tile in Rooms 250 & 329**

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout Facility, Including: 1st, 2nd & 3rd Floor Halls, Rooms 111, 113, 133, 135, 201, 209, 211, 213, 229, 232, 233, 235, 250, 309, 311, 312, 313, 314, 315, 316, 320, 322, 323, 326, 329, 333, 335, 337, 342, and 2nd Floor Teachers' Lounge**  
MATERIAL QUANTITY: **19730** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Patch & Repair. Follow O&M

Management Planner's Signature: \_\_\_\_\_



Date: 10/10/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12"x12" Light Gray Floor Tile w/ Gray Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 111, 113, 212, 214, 216, 228, 233, 242, 244, 319, 322, 326, 330, 335, 344, 348, 350, 331, 328, 249, 239A, 230, 202, 128, 131, 135, 133, 143, 148, 148A, Band Room, Auditorium Corridor, Cafeteria, Serving Line**

MATERIAL QUANTITY: **20363** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **No Access to Room 148A**

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12"x12" Light Gray Floor Tile w/ Gray Streaks**  
MATERIAL LOCATION: **Rooms 111, 113, 212, 214, 216, 228, 233, 242, 244, 319, 322, 326, 330, 335, 344, 348, 350, 331, 328, 249, 239A, 230, 202, 128, 131, 135, 133, 143, 148, 148A, Band Room, Auditorium Corridor, Cafeteria, Serving Line**  
MATERIAL QUANTITY: **20363** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/10/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/Gray Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 111, 113, 212, 214, 216, 228, 233, 242, 244, 319, 322, 326, 330, 335, 344, 348, 350, 331, 328, 249, 239A, 230, 202, 128, 131, 135, 133, 143, 148, 148A, Band Room, Auditorium Corridor, Cafeteria, Serving Line.**

MATERIAL QUANTITY: **20363** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **No Access to Room 148A**

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/Gray Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 111, 113, 212, 214, 216, 228, 233, 242, 244, 319, 322, 326, 330, 335, 344, 348, 350, 331, 328, 249, 239A, 230, 202, 128, 131, 135, 133, 143, 148, 148A, Band Room, Auditorium Corridor, Cafeteria, Serving Line.**  
MATERIAL QUANTITY: **20363** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/10/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12"x12" Dark Beige Floor Tile w/Beige Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rms 317, 318, Serving Line, Kitchen, Dishwashing Area, Central Hall 1st Floor, Engineer's Wshrm**

MATERIAL QUANTITY: **5096** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12"x12" Dark Beige Floor Tile w/Beige Specks**  
MATERIAL LOCATION: **Rms 317, 318, Serving Line, Kitchen, Dishwashing Area, Central Hall 1st Floor, Engineer's Wshrm**  
MATERIAL QUANTITY: **5096** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12"x12" Dark Beige w/Brown Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 317, 318, Serving Line, Kitchen, Dishwashing Area, Central Hall 1st Floor, Engineer's Washroom**

MATERIAL QUANTITY: **5096** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12"x12" Dark Beige w/Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 317, 318, Serving Line, Kitchen, Dishwashing Area, Central Hall 1st Floor, Engineer's Washroom**  
MATERIAL QUANTITY: **5096** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17  
MATERIAL DESCRIPTION: 12"x12" Gray Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 101, 105, 203, 207, 303, and 307  
MATERIAL QUANTITY: 5846    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Room 101 or 105

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile**  
MATERIAL LOCATION: **Rooms 101, 105, 203, 207, 303, and 307**  
MATERIAL QUANTITY: **5846** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17A  
MATERIAL DESCRIPTION: 12"x12" Gray Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 101, 105, 203, 207, 303, and 307  
MATERIAL QUANTITY: 5846 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Not Observed in Room 101 or 105

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 101, 105, 203, 207, 303, and 307**  
MATERIAL QUANTITY: **5846** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18  
MATERIAL DESCRIPTION: Black Linoleum  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Auditorium  
MATERIAL QUANTITY: 5472 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Not Observed. Possibly Under Carpet

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Black Linoleum**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **5472** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **Black Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **5472** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed. Possibly Under Carpet**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **Black Linoleum Mastic**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **5472** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 19  
MATERIAL DESCRIPTION: Ceramic Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: All Washrooms, Locker Rooms, Pool Area, 1st Floor Ramps, & Weight Room  
MATERIAL QUANTITY: 5000 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Not Observed in Weight Room

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Ceramic Tile Grout**  
MATERIAL LOCATION: **All Washrooms, Locker Rooms, Pool Area, 1st Floor Ramps, & Weight Room**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Stairway Entries and Borders of all Hallways**  
MATERIAL QUANTITY: **27702** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **All Stairway Entries and Borders of all Hallways**  
MATERIAL QUANTITY: **27702** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Transite Panels (Exhaust Hoods)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 303, 307, 305**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Transite Panels (Exhaust Hoods)**

MATERIAL LOCATION: **Rooms 303, 307, 305**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Gray Mopboard**

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22A**  
MATERIAL DESCRIPTION: **Gray Mopboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Room 220**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **22A**  
MATERIAL DESCRIPTION: **Gray Mopboard Mastic**  
MATERIAL LOCATION: **Room 220**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23  
MATERIAL DESCRIPTION: Aircell Sheeting ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Swimming Pool Area (Behind Radiator) - (Abated)

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Aircell Sheeting ABATED**  
MATERIAL LOCATION: **Swimming Pool Area (Behind Radiator) - (Abated)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **1x1 Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Swimming Pool Area**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **1x1 Ceramic Tile Grout**  
MATERIAL LOCATION: **Swimming Pool Area**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Green Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 307, 301, 244A, 244, 303, 207, 203, 101, 103, 105**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Rooms 101 or 105**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Green Linoleum**  
MATERIAL LOCATION: **Rooms 307, 301, 244A, 244, 303, 207, 203, 101, 103, 105**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 26  
MATERIAL DESCRIPTION: Green Linoleum Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 307, 301, 244A, 244, 303, 207, 203, 101, 103, 105  
MATERIAL QUANTITY: 6000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Rooms 101 or 105

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
MATERIAL LOCATION: **Rooms 307, 301, 244A, 244, 303, 207, 203, 101, 103, 105**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Cream Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 307, 303, 344, 244A, 207, 203, 170, 103, 101, 105, and Cafeteria**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Cream Baseboard**  
MATERIAL LOCATION: **Rooms 307, 303, 344, 244A, 207, 203, 170, 103, 101, 105, and Cafeteria**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Cream Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 307, 303, 344, 244A, 207, 203, 170, 103, 101, 105, and Cafeteria**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Cream Baseboard Mastic**  
MATERIAL LOCATION: **Rooms 307, 303, 344, 244A, 207, 203, 170, 103, 101, 105, and Cafeteria**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29  
MATERIAL DESCRIPTION: Black Vinyl Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 220  
MATERIAL QUANTITY: 200 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**  
MATERIAL LOCATION: **Room 220**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30  
MATERIAL DESCRIPTION: Black Vinyl Baseboard Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 220  
MATERIAL QUANTITY: 200 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Room 220**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31  
MATERIAL DESCRIPTION: White Acoustic Wall Panels  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 220, Auditorium  
MATERIAL QUANTITY: 6000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **White Acoustic Wall Panels**  
MATERIAL LOCATION: **Room 220, Auditorium**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium, Auditorium Corridor, Library, Room 122, 120, Foyer**  
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
MATERIAL LOCATION: **Auditorium, Auditorium Corridor, Library, Room 122, 120, Foyer**  
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Auditorium Storage**  
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **45** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **2nd Floor Auditorium Storage**  
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Orange Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Orange Carpet Mastic**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Tan Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 117**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Tan Carpet Mastic**  
MATERIAL LOCATION: **Room 117**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 36  
MATERIAL DESCRIPTION: Green & Maroon Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 116, Offices, & Library  
MATERIAL QUANTITY: 27000 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Green & Maroon Carpet Mastic**  
MATERIAL LOCATION: **Room 116, Offices, & Library**  
MATERIAL QUANTITY: **27000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 117**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
MATERIAL LOCATION: **Room 117**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 38  
MATERIAL DESCRIPTION: Dark Green Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Main Office  
MATERIAL QUANTITY: 200 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Dark Green Carpet Mastic**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39  
MATERIAL DESCRIPTION: Red Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 142  
MATERIAL QUANTITY: 700    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Red Carpet Mastic**  
MATERIAL LOCATION: **Room 142**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Red Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Room 140**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS: **Not Observed in Rooms 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Red Linoleum**

MATERIAL LOCATION: **Room 140**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Duct Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium (Stage)**  
MATERIAL QUANTITY: **105** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Duct Wrap**  
MATERIAL LOCATION: **Auditorium (Stage)**  
MATERIAL QUANTITY: **105** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: AA  
MATERIAL DESCRIPTION: 12"x12 White Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 201, 318, Engineer's Office and Serving Area  
MATERIAL QUANTITY: 2500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Engineer's Office

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **12"x12 White Floor Tile**  
MATERIAL LOCATION: **Rooms 201, 318, Engineer's Office and Serving Area**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB**  
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 201, 218, Engineer's Office and Serving Area**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Engineer's Office**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BB**  
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 201, 218, Engineer's Office and Serving Area**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: CC  
MATERIAL DESCRIPTION: 12"x12" Brown Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 201, 318, Cafeteria, Serving Area and Engineer's Office  
MATERIAL QUANTITY: 4000 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Not Observed in Engineer's Office

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **CC**  
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**  
MATERIAL LOCATION: **Rooms 201, 318, Cafeteria, Serving Area and Engineer's Office**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: CM1  
MATERIAL DESCRIPTION: Brown Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Main Office & Room 114  
MATERIAL QUANTITY: 800    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **CM1**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **Main Office & Room 114**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM2**  
MATERIAL DESCRIPTION: **Mauve Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Conference Room, Health Services Office, Student Act. Room**  
MATERIAL QUANTITY: **500** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **CM2**  
MATERIAL DESCRIPTION: **Mauve Carpet Mastic**  
MATERIAL LOCATION: **Conference Room, Health Services Office, Student Act. Room**  
MATERIAL QUANTITY: **500** MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM4**  
MATERIAL DESCRIPTION: **Beige Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **CM4**  
MATERIAL DESCRIPTION: **Beige Carpet Mastic**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM5**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 112, Library 2nd Floor**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **CM5**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
MATERIAL LOCATION: **Room 112, Library 2nd Floor**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM6**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium and Balcony**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **CM6**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **Auditorium and Balcony**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DD**  
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 201, 318, Cafeteria, Serving Area and Engineers Office**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Engineer's Office**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **DD**  
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Room 201, 318, Cafeteria, Serving Area and Engineers Office**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: EE  
MATERIAL DESCRIPTION: 12"x12" Cream w/Brown Specks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 150  
MATERIAL QUANTITY: 900    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **EE**  
MATERIAL DESCRIPTION: **12"x12" Cream w/Brown Specks Floor Tile**  
MATERIAL LOCATION: **Room 150**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FF  
MATERIAL DESCRIPTION: 12"x12" Cream w/Brown Specks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 150  
MATERIAL QUANTITY: 900    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FF**  
MATERIAL DESCRIPTION: **12"x12" Cream w/Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 150**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: GG  
MATERIAL DESCRIPTION: 12"x12" Grey Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 307

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2019 & 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **GG**

MATERIAL DESCRIPTION: **12"x12" Grey Floor Tile**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: HA-1000  
MATERIAL DESCRIPTION: 2'x4' White Lay In Ceiling Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Hallways and Classrooms  
MATERIAL QUANTITY: 200000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **HA-1000**  
MATERIAL DESCRIPTION: **2'x4' White Lay In Ceiling Tile**  
MATERIAL LOCATION: **Hallways and Classrooms**  
MATERIAL QUANTITY: **200000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1001**  
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Kitchen Serving Line, Rooms 331, 323 315, 314, 313, 249, 128 & 114**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **HA-1001**  
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile**  
MATERIAL LOCATION: **Kitchen Serving Line, Rooms 331, 323 315, 314, 313, 249, 128 & 114**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1002**  
MATERIAL DESCRIPTION: **Glue for 1'x1' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen Serving Line, Rooms 331, 323 315, 314, 313, 249, 128**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **HA-1002**  
MATERIAL DESCRIPTION: **Glue for 1'x1' White Ceiling Tile**  
MATERIAL LOCATION: **Kitchen Serving Line, Rooms 331, 323 315, 314, 313, 249, 128**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1003**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen Food Prep Area**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **HA-1003**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
MATERIAL LOCATION: **Kitchen Food Prep Area**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HH**  
MATERIAL DESCRIPTION: **12"x12" Grey Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Room 307**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **HH**  
MATERIAL DESCRIPTION: **12"x12" Grey Floor Tile Mastic**  
MATERIAL LOCATION: **Room 307**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **II**  
MATERIAL DESCRIPTION: **Orange Linoleum and Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 301**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **II**  
MATERIAL DESCRIPTION: **Orange Linoleum and Adhesive**  
MATERIAL LOCATION: **Room 301**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: JJ  
MATERIAL DESCRIPTION: 2'x2' Creamic Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Washrooms  
MATERIAL QUANTITY: 1500 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **JJ**  
MATERIAL DESCRIPTION: **2'x2' Creamic Floor Tile**  
MATERIAL LOCATION: **Washrooms**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **KK**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **KK**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **LL**  
MATERIAL DESCRIPTION: **Grey Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Auditorium, 248, 118**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **LL**  
MATERIAL DESCRIPTION: **Grey Carpet Mastic**  
MATERIAL LOCATION: **Main Office, Auditorium, 248, 118**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: MFT-1  
MATERIAL DESCRIPTION: 12x12 Red Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1st Floor Hallway  
MATERIAL QUANTITY: 180    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **MFT-1**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile**  
MATERIAL LOCATION: **1st Floor Hallway**  
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: MFT-2  
MATERIAL DESCRIPTION: 12 x 12 Beige w/Brown Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Hallway, 170, 171**

MATERIAL QUANTITY: **9000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **MFT-2**  
MATERIAL DESCRIPTION: **12 x 12 Beige w/Brown Streaks Floor Tile**  
MATERIAL LOCATION: **1st Floor Hallway, 170, 171**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MFTM-1**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Hallway**  
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **MFTM-1**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Hallway**  
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: MFTM-2  
MATERIAL DESCRIPTION: 12 x 12 Beige w/Brown Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1st Floor Hallway, 170, 171  
MATERIAL QUANTITY: 9000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **MFTM-2**  
MATERIAL DESCRIPTION: **12 x 12 Beige w/Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Hallway, 170, 171**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MM**  
MATERIAL DESCRIPTION: **Silver Duct Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **MM**  
MATERIAL DESCRIPTION: **Silver Duct Insulation**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **NN**  
MATERIAL DESCRIPTION: **Hair Dryer Insulation**  
MATERIAL LOCATION: **Drying Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **00**  
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **OO**  
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Tile**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Wire Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Wire Insulation**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **PP**  
MATERIAL DESCRIPTION: **MJP E/F/V on Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **PP**  
MATERIAL DESCRIPTION: **MJP E/F/V on Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium, 114, 123, 126, 130**  
MATERIAL QUANTITY: **8272** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Room 126**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Auditorium, 114, 123, 126, 130**  
MATERIAL QUANTITY: **8272** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: QQ  
MATERIAL DESCRIPTION: MJP E/F/V on Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Air Tunnels and Basement Corridors  
MATERIAL QUANTITY: 3000 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **QQ**  
MATERIAL DESCRIPTION: **MJP E/F/V on Pipe Insulation**  
MATERIAL LOCATION: **Air Tunnels and Basement Corridors**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: R  
MATERIAL DESCRIPTION: Brown Carpet & Carpet Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Main Office, 126  
MATERIAL QUANTITY: 1500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Room 126

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Brown Carpet & Carpet Adhesive**  
MATERIAL LOCATION: **Main Office, 126**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **RR**  
MATERIAL DESCRIPTION: **Fire Brick and Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Interior Wall Cavities and Roof Deck**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **RR**  
MATERIAL DESCRIPTION: **Fire Brick and Mortar**  
MATERIAL LOCATION: **Throughout Interior Wall Cavities and Roof Deck**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: S  
MATERIAL DESCRIPTION: Grey/Purple Carpet Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 132, 220, 122, 120  
MATERIAL QUANTITY: 3200    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Grey/Purple Carpet Adhesive**  
MATERIAL LOCATION: **Rooms 132, 220, 122, 120**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: SPA-1  
MATERIAL DESCRIPTION: Plaster on Wire Mesh  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Throughout School  
MATERIAL QUANTITY: 50000 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **SPA-1**  
MATERIAL DESCRIPTION: **Plaster on Wire Mesh**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **SS**  
MATERIAL DESCRIPTION: **Black Pool Lining Material**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Pool Room**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **SS**  
MATERIAL DESCRIPTION: **Black Pool Lining Material**  
MATERIAL LOCATION: **Pool Room**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 117 and 223**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
MATERIAL LOCATION: **Rooms 117 and 223**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46111    BUILDING ID: 1310  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy    INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: U  
MATERIAL DESCRIPTION: Brown Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 112, 130 and 116  
MATERIAL QUANTITY: 1500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **Rooms 112, 130 and 116**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Only observed in Room 342**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **See 01**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile**  
MATERIAL LOCATION: **Only observed in Room 342**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Only Observed in Room 342**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **See 09**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile Mastic**  
MATERIAL LOCATION: **Only Observed in Room 342**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46111 BUIDLING ID: 1310  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Fenger Academy INSPECTION DATE: 9/15/2022  
ADDRESS: 11220 S. Wallace IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: X  
MATERIAL DESCRIPTION: Grey Linoleum and Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Only Observed in Room 346  
MATERIAL QUANTITY: 6200 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **Grey Linoleum and Adhesive**  
MATERIAL LOCATION: **Only Observed in Room 346**  
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **9'x9' Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 100C**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **9'x9' Beige Floor Tile**  
MATERIAL LOCATION: **Room 100C**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUIDLING ID: **1310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy** INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **9'x9' Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **100C**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **9'x9' Beige Floor Tile Mastic**  
MATERIAL LOCATION: **100C**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/10/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46111**    BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy**    INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace**    IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Red Green & White Floor Tile**  
MATERIAL LOCATION: **Room 101/105**  
MATERIAL QUANTITY: **5000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Red Green & White Floor Tile**

MATERIAL LOCATION: **Room 101/105**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/10/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46111**      BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy**      REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12"x12" Orange/Dark Grey Mix Floor Tile**

MATERIAL LOCATION: **Room 129**

MATERIAL QUANTITY: **700**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/10/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46111**      BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy**      REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Orange/Dark Grey Mix Floor Tile**

MATERIAL LOCATION: **Room 129**

MATERIAL QUANTITY: **700**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/10/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46111**      BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy**      INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12"x12" Red Green & White Mix Floor Tile**  
MATERIAL LOCATION: **Room 101/105**  
MATERIAL QUANTITY: **2000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12"x12" Red Green & White Mix Floor Tile**  
MATERIAL LOCATION: **Room 101/105**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/10/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46111**      BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Fenger Academy**      INSPECTION DATE: **9/15/2022**  
ADDRESS: **11220 S. Wallace**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/15/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46111** BUILDING ID: **1310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Fenger Academy** REVIEW DATE: **10/10/2022**  
ADDRESS: **11220 S. Wallace** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/10/2022

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER ANTONOPOULOS  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 06/01/2021 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II; Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

06/01/2021

Course Dates:

06/01/2022

Expires:

2106BIR11

Certificate Number:

A handwritten signature in black ink, appearing to read "N Penneff".

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER J. ANTONOPOULOS  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 06/03/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

06/03/2022

Course Dates:

06/03/2023

Expires:

2206BIR01

Certificate Number:




37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in black ink, appearing to read "N. Penef", is written over a light gray rectangular background.

Director of Training  
Nicholas J. Penef  
Doctor of Public Health

Phone: 312-491-0081


FORM # A-010B

 **ASBESTOS  
PROFESSIONAL  
LICENSE**

|                  |               |                |
|------------------|---------------|----------------|
| <b>ID NUMBER</b> | <b>ISSUED</b> | <b>EXPIRES</b> |
| 100 - 18281      | 2/10/2022     | 05/15/2023     |

**CHRISTOPHER J ANTONOPO**  
1736 W 102nd ST  
CHICAGO, IL 60643

Environmental Health



|                    |                   |
|--------------------|-------------------|
| <b>ENDORSEMENT</b> | <b>TC EXPIRES</b> |
| INSPECTOR          | 6/1/2022          |

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**TODD T HUFFER**  
315 HATLEN COURT  
MT. PROSPECT, IL 60056

2/18/2022


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

|   |                            |                              |  |  |  |  |                          |
|---|----------------------------|------------------------------|--|--|--|--|--------------------------|
|    |                            |                              | <b>ASBESTOS PROFESSIONAL LICENSE</b>   |  | <b>ENDORSEMENTS</b>  |  | <b>TC EXPIRES</b>        |
| <b>ID NUMBER</b><br>100 - 09870   | <b>ISSUED</b><br>2/18/2022 | <b>EXPIRES</b><br>05/15/2023 | INSPECTOR  |  |  |  | 11/1/2022                |
| <b>TODD T HUFFER</b><br>315 HATLEN COURT<br>MT. PROSPECT, IL 60056<br>Environmental Health  |                            |                              |  |  | MANAGEMENT PLANNER<br>PROJECT MANAGER<br>AIR SAMPLING PROFESSIONAL |  | 11/19/2022<br>10/20/2022 |
| <b>Alteration of this license shall result in legal action</b><br>This license issued under authority of the State of Illinois<br>Department of Public Health<br>This license is valid only when accompanied by a valid<br>training course certificate. |                            |                              |  |  |  |  |                          |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

## Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815

  
Kathy DeSalvo, Director





OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255

  
Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265

  
Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

|                          | <b>CODE</b> | <b>KEY</b>                             |
|--------------------------|-------------|--|
| <b>MATERIAL</b>          |             |  |
|                          | ACBM        | Asbestos Containing Building Materials |
| <b>MATERIAL CATEGORY</b> |             |  |
|                          | MISC        | Miscellaneous                          |
|                          | SURF        | Surfacing                              |
|                          | TSI         | Thermal System Insulation              |
| <b>MATERIAL UNITS</b>    |             |  |
|                          | LF          | Linear Feet                            |
|                          | SF          | Square Feet                            |
|                          | CF          | Cubic Feet                             |
| <b>DAMAGE TYPE</b>       |             |  |
|                          | Loc         | Localized                              |
|                          | Dist        | Distributed                            |