

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0015  
SCHOOL NAME: Gage Park High School  
ADDRESS OF SCHOOL: 5630 S. Rockwell  
CITY: Chicago, IL, 60629

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/22/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 6/30/2022 ENROLLMENT 322  
IDPH INSPECTOR LICENSE NUMBER: 100-20411  
IDPH LICENSED INSPECTOR NAME (Please Print): Benyamen Maradkel  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



7/14/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Gage Park High School**

5630 S. Rockwell  
Chicago, IL, 60629

Unit: 46141  
Building ID: 1340

IDPH ID Number: 14-016-2990-0015

**REPORT DATE:**

Thursday, July 14, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

07/14/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 46141                      Region: 04                      IDPH ID: 14-016-2990-0015

School: Gage Park High School                      Building ID: 1340

Address: 5630 S. Rockwell

Chicago, IL, 60629

Building Contact:                      Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 6/30/2022

Review Date: 07/14/2022

Inspector: Benyamen Maradkel

Inspector IDPH License: 100-20411

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: July 14, 2022

RE: Gage Park High School, Unit 46141  
5630 S. Rockwell  
Chicago, IL, 60629

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Gage Park High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Gage Park High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Gage Park High School Unit: 46141 Region: 04  
Address: 5630 S. Rockwell Chicago, IL, 60629  
IDPH ID: 14-016-2990-0015 Building ID: 1340  
Contact: Phone:

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: 1440 No of Floors:  
Current Occupancy: 322

### 3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602


### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Benyamen Maradkel


Inspector IDPH license # 100-20411  
Reinspection Date: 6/30/2022

Signature:   
Date: 6/30/2022

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


Signature:   
Date: 07/14/2022

### 7. Review Date: 07/14/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 7/14/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Gage Park High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1340:

25C	12" x 12" flesh w/tan & White Specks Floor Tile
26A	12" x 12" rose Specksed Floor Tile Mastic
26C	12" x 12" flesh w/tan & White Floor Tile Mastic
34	12" x 12" Beige w/ Dark Beige Spots Floor Tile
35	Mastic Associated w/ 12" x 12" Beige w/ Dark Beige Spots Floor Tile
36	12" x 12" Dark Beige w/ White Specks Floor Tile
37	Mastic Associated w/ 12" x 12" Dark Beige w/ White Specks Floor Tile
38	12" x 12" Bright Red Floor Tile

39	12" x 12" Bright Red Floor Tile Mastic
40	12" x 12" Cream w/ Multicolor Specks Floor Tile
41	12" x 12" Cream w/ Multicolor Specks Floor Tile Mastic
42	12" x 12" White ceiling tile
43	12" x 12" Gray w/ Light Gray Specks Floor Tile
44	12" x 12" Gray w/ Light Gray Specks Floor Tile Mastic
45	Chalk boards
A(46)	Air cell pipe insulation intact
J	Aircell hard joints intact
M	2' x 4' ACT



B. The following new homogenous areas have been identified for Building 1340:

- 38 12" x 12" Bright Red Floor Tile
- 39 12" x 12" Bright Red Floor Tile Mastic
- 40 12" x 12" Cream w/ Multicolor Specks Floor Tile
- 41 12" x 12" Cream w/ Multicolor Specks Floor Tile Mastic
- 42 12" x 12" White ceiling tile
- 43 12" x 12" Gray w/ Light Gray Specks Floor Tile
- 44 12" x 12" Gray w/ Light Gray Specks Floor Tile Mastic
- 45 Chalk boards

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

25	12" x 12" Light Green w/Dark Green Specks Floor Tile
25A	12" x 12" White Specksed Floor Tile
25B	12" x 12" black w/White Specks Floor Tile
25C	12" x 12" flesh w/tan & White Specks Floor Tile
26	12" x 12" Light Green w/Dark Green Specks Floor Tile Mastic
26A	12" x 12" rose Specksed Floor Tile Mastic
26B	12" x 12" black w/White Specks Floor Tile Mastic
28/08	9x18 black Floor Tile Mastic
28/10	9" x 9" rose w/White Streaks Floor Tile Mastic not visible
28/24	12" x 12" White w/Brown spots Floor Tile Mastic
33	Pink & tweed Green carpet Mastic
33A	12" x 12" Burgundy tweed carpet Mastic
33B	Pea Green carpet Mastic
33C	Gold carpet Mastic
34	12" x 12" Beige w/ Dark Beige Spots Floor Tile
35	Mastic Associated w/ 12" x 12" Beige w/ Dark Beige Spots Floor Tile
36	12" x 12" Dark Beige w/ White Specks Floor Tile
37	Mastic Associated w/ 12" x 12" Dark Beige w/ White Specks Floor Tile
38	12" x 12" Bright Red Floor Tile
39	12" x 12" Bright Red Floor Tile Mastic
40	12" x 12" Cream w/ Multicolor Specks Floor Tile
41	12" x 12" Cream w/ Multicolor Specks Floor Tile Mastic
42	12" x 12" White ceiling tile
43	12" x 12" Gray w/ Light Gray Specks Floor Tile
44	12" x 12" Gray w/ Light Gray Specks Floor Tile Mastic
45	Chalk boards
E	FG hard joints intact
F	White 12" x 12" Vinyl Floor Tile
G	Mastic for White 12" x 12" Vinyl Floor Tile
H	Gray carpet Mastic
I	Air cell pipe insulation
J	Aircell hard joints intact
K	1' x 1' ACT
L	1' x 1' act Mastic
M	2' x 4' ACT

N	12" x 12" Vinyl Floor Tile White W/ Beige Specks
N-1	12" x 12" Vinyl Floor Tile White W/ Beige SPECKS- MASTIC
O	12" x 12" White w/ Tan Specks Vinyl Floor Tile
O-1	12" x 12" White w/ Tan Specks Vinyl Floor Tile Mastic
P	12" x 12" Vinyl Floor Tile Dark red w/ red Specks
P-1	12" x 12" Vinyl Floor Tile Dark RED W/ RED SPECKS-MASTIC intact
Q	12" x 12" TAN W/ Brown Specks Vinyl Floor Tile
Q-1	12" x 12" TAN W/ Brown SPEC Vinyl Floor Tile-MASTIC
R	12" x 12" Brown W/ White Specks Vinyl Floor Tile
R/S-1	MASTIC FOR 12" x 12" Floor Tile (HA 'R' & 'S')
S	12" x 12" White W/ Beige Specks Vinyl Floor Tile
T	12" x 12" Dark RED Vinyl Floor Tile
T/U-1	MASTIC FOR 12" x 12" Vinyl Floor Tile (HA 'T' & 'U')
U	12" x 12" White W/ GRAY Streaks Floor Tile
V	12" x 12" Brown W/ White Specks Vinyl Floor Tile intact
V-1	MASTIC FOR 12" x 12" Brown W/ White Specks Vinyl Floor Tile

The following areas were deemed to be inaccessible:

26	12" x 12" Light Green w/Dark Green Specks Floor Tile Mastic
26C	12" x 12" flesh w/tan & White Floor Tile Mastic
27/16	9" x 9" Light tan w/Brown & White Streaks Floor Tile-
28/17	9" x 9" red w/White Streaks Floor Tile Mastic
28/18	9" x 9" drk Brown w/White & Gold streak Floor Tile Mastic
28/19	12" x 12" White w/Multicolor Streaks Floor Tile
28/22	9" x 9" gray Green Floor Tile Mastic not visible
28/24	12" x 12" White w/Brown spots Floor Tile Mastic
35	Mastic Associated w/ 12" x 12" Beige w/ Dark Beige Spots Floor Tile
37	Mastic Associated w/ 12" x 12" Dark Beige w/ White Specks Floor Tile
42	12" x 12" White ceiling tile
E	FG hard joints intact
FTM-1	12" x 12" Beige Vinyl Floor Tile Mastic
FTM-2	12" x 12" Burgundy w/ White Streaks Floor Tile Mastic

I	Air cell pipe insulation
K	1' x 1' ACT
L	1' x 1' act Mastic
N-1	12" x 12" Vinyl Floor Tile White W/ Beige SPECKS- MASTIC
O-1	12" x 12" White w/ Tan Specks Vinyl Floor Tile Mastic
P-1	12" x 12" Vinyl Floor Tile Dark RED W/ RED SPECKS-MASTIC intact
Q-1	12" x 12" TAN W/ Brown SPEC Vinyl Floor Tile- MASTIC
R/S-1	MASTIC FOR 12" x 12" Floor Tile (HA 'R' & 'S')
T/U-1	MASTIC FOR 12" x 12" Vinyl Floor Tile (HA 'T' & 'U')
V-1	MASTIC FOR 12" x 12" Brown W/ White Specks Vinyl Floor Tile

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Benyamen Maradkel, IDPH License # 100-20411. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Gage Park High School Building 1340 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---







# Chicago Public Schools

School Gage Park High School Unit 46141 Building ID 1340

Address 5630 S. Rockwell Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
34	12" x 12" Beige w/ Dark Beige Spots Floor Tile	1,120	SF	Room 307	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
35	Mastic Associated w/ 12" x 12" Beige w/ Dark Beige Spots Floor Tile	1,120	SF	Room 307	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
36	12" x 12" Dark Beige w/ White Specks Floor Tile	1,650	SF	Driver's ED Trailer	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
37	Mastic Associated w/ 12" x 12" Dark Beige w/ White Specks Floor Tile	1,650	SF	Driver's ED Trailer	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
38	12" x 12" Bright Red Floor Tile	20	SF	Lunchroom	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
39	12" x 12" Bright Red Floor Tile Mastic	20	SF	Lunchroom	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
40	12" x 12" Cream w/ Multicolor Specks Floor Tile	50	SF	Lunchroom, teachers lounge, 128 (attendance office)	ASSUMED	MISC	N	LOC	1	SF	Yes	ACBM with the potential for damage	5	LOW
41	12" x 12" Cream w/ Multicolor Specks Floor Tile Mastic	50	SF	Lunchroom, teachers lounge, 128 (attendance office)	ASSUMED	MISC	N	LOC	1	SF	Yes	ACBM with the potential for damage	5	LOW
42	12" x 12" White ceiling tile	5,000	SF	lunchroom, Room 332, 330	ASSUMED	MISC	N	DIST	7	SF	Yes	ACBM with the potential for damage	5	LOW
43	12" x 12" Gray w/ Light Gray Specks Floor Tile	2,000	SF	Room 120	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
44	12" x 12" Gray w/ Light Gray Specks Floor Tile Mastic	2,000	SF	Room 120	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
45	Chalk boards	10,000	SF	throughout 1st, 2nd, 3rd floor classrooms	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
A(46)	Air cell pipe insulation intact	250	LF	basement	CHR	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
AA	Drywall (trailer demolished 2011)			ALL WALLS AND CEILINGS IN 2 CLASSROOMS TRAILER ON NORTH SIDE OF SCHOOL	ABATED	MISC								
B(45)	Aircell hard joints-abated.			boiler room, basement, rest rooms	ABATED	TSI								
D	Mag block on heat exchanger intact		LF	Basement pool chemical room	AMO	TSI				LF				
E	FG hard joints intact	195	LF	basement unexcavated area, boiler room, mechanical room	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

School Gage Park High School Unit 46141 Building ID 1340

Address 5630 S. Rockwell Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
F	White 12" x 12" Vinyl Floor Tile	720	SF	Room 221	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
FT-1	12" x 12" Beige Floor Tile	3,700	SF	Room 216, 221, 222, 217A, 225, 307, teacher's lounge, Principal's office, Room 123, Assistant Principal's office, parm, 113, 125	CHR	MISC	N	DIST	37	SF	No	ACBM with the potential for damage	5	LOW
FT-2	12" x 12" Burgundy w/ White Streaks Floor Tile	9,400	SF	1st, 2nd & 3rd fl. Corridors	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
FTM-1	12" x 12" Beige Vinyl Floor Tile Mastic	3,700	SF	Room 216, 221, 222, 217A, 225, 307, teacher's lounge, principal's office, asst. principal's office, Room 123, parm, 113, 125	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
FTM-2	12" x 12" Burgundy w/ White Streaks Floor Tile Mastic	9,400	SF	1st, 2nd & 3rd fl corridors	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
G	Mastic for White 12" x 12" Vinyl Floor Tile	720	SF	room 221	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
H	Gray carpet Mastic			Room 125	ASSUMED	MISC								
I	Air cell pipe insulation	250	LF	basement.	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
J	Aircell hard joints intact	35	LF	boiler room, basement, rest rooms	ASSUMED	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
K	1' x 1' ACT	20,000	SF	1st, 2nd, 3rd floor corridors and lunchroom, hallways	ASSUMED	MISC	N	DIST	10	SF	No	ACBM with the potential for damage	5	LOW
L	1' x 1' act Mastic	20,000	SF	1st, 2nd, 3rd floor corridors and lunchroom	ASSUMED	MISC	N	DIST	3	SF	No	ACBM with the potential for damage	3	LOW
M	2' x 4' ACT	15,000	SF	all classrooms on 1st, 2nd and 3rd	ASSUMED	MISC	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
N	12" x 12" Vinyl Floor Tile White W/ Beige Specks	1,500	SF	ROOM 121 & 125	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
N-1	12" x 12" Vinyl Floor Tile White W/ Beige SPECKS- MASTIC	1,600	SF	ROOMS 121 & 125	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
O	12" x 12" White w/ Tan Specks Vinyl Floor Tile	23,500	SF	1st, 2nd, 3rd floor hallways, auditorium,	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW





# Chicago Public Schools

School Gage Park High School Unit 46141 Building ID 1340  
Address 5630 S. Rockwell Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>6/30/2022</b>
Inspector Name <b>Benyamen Maradkel</b>
<b>100-20411</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
25	
25A	
25B	Not observed 2022
25C	
26	
26A	
26B	Not observed 2022
26C	
27/06	Not observed 2022
27/07	Not observed 2022
27/08	Not observed 2022
27/09	Not Observed 2022
27/10	Not Observed 2022
27/14	Not Observed 2022
27/16	
27/17	
27/18	
27/19	Not Observed 2022
27/22	
27/23	Not observed 2022
27/24	
27/27	Not Observed 2022
27/28	Not observed 2022
28/06	Not observed 2022

# Chicago Public Schools

School Gage Park High School Unit 46141 Building ID 1340

Address 5630 S. Rockwell Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
28/07	Not observed 2022
28/08	Not observed 2022
28/09	
28/10	Not Observed 2022
28/14	Not observed 2022
28/17	
28/18	
28/19	
28/22	
28/24	
28/27	Not observed 2022
28/28	Not observed 2022
29	
30	
33	Not observed 2022
33A	Not observed 2022
33B	Not observed 2022
33C	Not observed 2022
34	
35	
36	
37	
38	
39	
40	Damage in teacher's lounge
41	Damage in teacher's lounge
42	Damage in lunchroom ceiling, room 332
43	
44	

# Chicago Public Schools

School Gage Park High School Unit 46141 Building ID 1340

Address 5630 S. Rockwell Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
45	
A(46)	
AA	
B(45)	
D	Not observed 2022 - Removed
E	
F	
FT-1	Slight damage in Room 307
FT-2	
FTM-1	
FTM-2	
G	
H	Not observed 2022
I	
J	
K	Damage in 2 floor hallways (207)
L	Damage in lunchroom ceiling
M	
N	
N-1	
O	
O-1	
P	
P-1	
Q	
Q-1	
R	
R/S-1	
S	

# Chicago Public Schools

School Gage Park High School Unit 46141 Building ID 1340

Address 5630 S. Rockwell Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
T	Damage in room 332, room 330
T/U-1	
U	Damage in room 332, room 330
V	
V-1	
W	Abated
W-1	Abated
X	Abated
Y	Abated
Z	
Z-1	



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Gage Park High School

Unit 46141

Building ID 1340

Address 5630 S. Rockwell

Chicago, IL, 60629

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
25	12" x 12" Light Green w/Dark Green Specks Floor Tile	400	SF	room 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25A	12" x 12" White Specksed Floor Tile	200	SF	main office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25B	12" x 12" black w/White Specks Floor Tile		SF	auditorium	Assumed	MISC			SF		Follow O&M Plan
25C	12" x 12" flesh w/tan & White Specks Floor Tile	1,125	SF	room 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12" x 12" Light Green w/Dark Green Specks Floor Tile Mastic	400	SF	room 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26A	12" x 12" rose Specksed Floor Tile Mastic	400	SF	main office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26B	12" x 12" black w/White Specks Floor Tile Mastic			auditorium	Assumed	MISC					Follow O&M Plan
26C	12" x 12" flesh w/tan & White Floor Tile Mastic	1,120	SF	room 221	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27/06	9" x 9" black Floor Tile			1st, 2nd & 3rd floor corridors	Chrysotile	MISC					Follow O&M Plan
27/07	9" x 9" maroon Floor Tile			1st, 2nd & 3rd floor corridors, Auditorium.	Chrysotile	MISC					Follow O&M Plan
27/08	9x18 black Floor Tile			2nd & 3rd floor corridors	Chrysotile	MISC					Follow O&M Plan
27/09	9" x 9" black w/White Streaks Floor Tile			engineer's locker room, patched areas	Chrysotile	MISC					Follow O&M Plan
27/10	9" x 9" rose w/White streak Floor Tile			engineers office corridor	Chrysotile	MISC					Follow O&M Plan
27/14	9" x 9" chocolate Brown w/ White streak Floor Tile			1st,2nd, 3rd floor corridors-abated	Chrysotile	MISC					Follow O&M Plan
27/16	9" x 9" Light tan w/Brown & White Streaks Floor Tile-	523	SF	room 121-material removed.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27/17	9" x 9" red w/White Streaks Floor Tile	325	SF	POLICE OFFICE, engineer's office, engineer's locker room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27/18	9" x 9" Dark Brown w/White and Gold Streaks Floor Tile	259	SF	corridor outside engineer's office, POLICE OFFICE	Chrysotile	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
27/19	9" x 9" olive Floor Tile w/White Streaks			engineer's office	Chrysotile	MISC					Follow O&M Plan
27/22	9" x 9" black & White Floor Tile	265	SF	girls' coaches office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27/23	9" x 9" black and White Floor Tile		SF	girls exam room	Chrysotile	MISC			SF		Follow O&M Plan
27/24	12" x 12" White w/Brown spots Floor Tile	1,825	SF	rooms 225, 305	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27/27	9" x 9" tan leopard Floor Tile Not visible			room 302	Chrysotile	MISC					Follow O&M Plan
27/28	9" x 9" Brown leopard Floor Tile			room 307	Chrysotile	MISC					Follow O&M Plan
28/06	9" x 9" black Floor Tile Mastic, w/ HA 27/6			1st, 2nd & 3rd floor corridors	Chrysotile	MISC					Follow O&M Plan
28/07	9" x 9" maroon Floor Tile Mastic, w/ HA 27/7			1st, 2nd & 3rd floor corridors, auditorium.	Chrysotile	MISC					Follow O&M Plan
28/08	9x18 black Floor Tile Mastic			1st, 2nd & 3rd floor corridors	Assumed	MISC					Follow O&M Plan
28/09	9" x 9" chocolate Brown w/White Streaks Floor Tile Mastic	300	SF	engineer's locker room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Gage Park High School

Unit 46141

Building ID 1340

Address 5630 S. Rockwell

Chicago, IL, 60629

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
28/10	9" x 9" rose w/White Streaks Floor Tile Mastic not visible			1st & 2nd,3rd floor corridors, patched areas	Assumed	MISC					Follow O&M Plan
28/14	9" x 9" chocolate Brown w/White streak Floor Tile Mastic			1st,2nd,3rd floor corridors	Chrysotile	MISC					Follow O&M Plan
28/17	9" x 9" red w/White Streaks Floor Tile Mastic	325	SF	Police office. engineer's office, engineer's locker room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28/18	9" x 9" drk Brown w/White & Gold streak Floor Tile Mastic	259	SF	corridor outside engineer's office, police office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28/19	12" x 12" White w/Multicolor Streaks Floor Tile	134	SF	engineer's office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28/22	9" x 9" gray Green Floor Tile Mastic not visible	248	SF	girls' coaches office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28/24	12" x 12" White w/Brown spots Floor Tile Mastic	1,825	SF	rooms 225, 305	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28/27	9" x 9" tan leopard Floor Tile Mastic			room 307	Chrysotile	MISC					Follow O&M Plan
28/28	9" x 9" Brown leopard Floor Tile Mastic			room 307	Chrysotile	MISC					Follow O&M Plan
29	Transite table tops	200	SF	Room 321, 322, 317, 213, 215, 217, 217a	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Transite lab hood	20	SF	room 317	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Pink & tweed Green carpet Mastic			Room 124, 125, 128, assistant principal's office	Assumed	MISC					Follow O&M Plan
33A	12" x 12" Burgundy tweed carpet Mastic			Room 120,126, 123, 117, principal's office, PARM, assembly hall,	Assumed	MISC					Follow O&M Plan
33B	Pea Green carpet Mastic			room 216	Assumed	MISC					Follow O&M Plan
33C	Gold carpet Mastic			room 113	Assumed	MISC					Follow O&M Plan
34	12" x 12" Beige w/ Dark Beige Spots Floor Tile	1,120	SF	Room 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Mastic Associated w/ 12" x 12" Beige w/ Dark Beige Spots Floor Tile	1,120	SF	Room 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" x 12" Dark Beige w/ White Specks Floor Tile	1,650	SF	Driver's ED Trailer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Mastic Associated w/ 12" x 12" Dark Beige w/ White Specks Floor Tile	1,650	SF	Driver's ED Trailer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12" x 12" Bright Red Floor Tile	20	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12" x 12" Bright Red Floor Tile Mastic	20	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12" x 12" Cream w/ Multicolor Specks Floor Tile	50	SF	Lunchroom, teachers lounge, 128 (attendance office)	Assumed	MISC	No	1	SF	6 ACBM with the potential for damage	Repair
41	12" x 12" Cream w/ Multicolor Specks Floor Tile Mastic	50	SF	Lunchroom, teachers lounge, 128 (attendance office)	Assumed	MISC	No	1	SF	6 ACBM with the potential for damage	Repair
42	12" x 12" White ceiling tile	5,000	SF	lunchroom, Room 332, 330	Assumed	MISC	No	7	SF	6 ACBM with the potential for damage	Repair
43	12" x 12" Gray w/ Light Gray Specks Floor Tile	2,000	SF	Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Gage Park High School

Unit 46141

Building ID 1340

Address 5630 S. Rockwell

Chicago, IL, 60629

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
44	12" x 12" Gray w/ Light Gray Specks Floor Tile Mastic	2,000	SF	Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Chalk boards	10,000	SF	throughout 1st, 2nd, 3rd floor classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A(46)	Air cell pipe insulation intact	250	LF	basement	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
AA	Drywall (trailer demolished 2011)			ALL WALLS AND CEILINGS IN 2 CLASSROOMS TRAILER ON NORTH SIDE OF SCHOOL	Abated	MISC					
B(45)	Aircell hard joints-abated.			boiler room, basement, rest rooms	Abated	TSI					
D	Mag block on heat excahnger intact		LF	Basement pool chemical room	Amosite	TSI			LF		Follow O&M Plan
E	FG hard joints intact	195	LF	basement unexcavated area, boiler room, mechanical room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	White 12" x 12" Vinyl Floor Tile	720	SF	Room 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-1	12" x 12" Beige Floor Tile	3,700	SF	Room 216, 221, 222, 217A, 225, 307, teacher's lounge, Principal's office, Room 123, Assistant Principal's office, parm, 113, 125	Chrysotile	MISC	No	37	SF	6 ACBM with the potential for damage	Repair
FT-2	12" x 12" Burgundy w/ White Streaks Floor Tile	9,400	SF	1st, 2nd & 3rd fl. Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	12" x 12" Beige Vinyl Floor Tile Mastic	3,700	SF	Room 216, 221, 222, 217A, 225, 307, teacher's lounge, principal's office, asst. principal's office, Room 123, parm, 113, 125	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-2	12" x 12" Burgundy w/ White Streaks Floor Tile Mastic	9,400	SF	1st, 2nd & 3rd fl corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Mastic for White 12" x 12" Vinyl Floor Tile	720	SF	room 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
H	Gray carpet Mastic			Room 125	Assumed	MISC					Follow O&M Plan
I	Air cell pipe insulation	250	LF	basement.	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	Aircell hard joints intact	35	LF	boiler room, basement, rest rooms	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	1' x 1' ACT	20,000	SF	1st, 2nd, 3rd floor corriors and lunchroom, hallways	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
L	1' x 1' act Mastic	20,000	SF	1st, 2nd, 3rd floor corriors and lunchroom	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Repair
M	2' x 4' ACT	15,000	SF	all classrooms on 1st,2nd and 3rd	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable	Follow O&M Plan

# Chicago Public Schools

**School** Gage Park High School

**Unit** 46141

**Building ID** 1340

**Address** 5630 S. Rockwell

Chicago, IL, 60629

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
										suspect ACBM	
N	12" x 12" Vinyl Floor Tile White W/ Beige Specks	1,500	SF	ROOM 121 & 125	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
N-1	12" x 12" Vinyl Floor Tile White W/ Beige SPECKS-MASTIC	1,600	SF	ROOMS 121 & 125	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
O	12" x 12" White w/ Tan Specks Vinyl Floor Tile	23,500	SF	1st,2nd,3rd floor hallways,auditorium, eng's office,Room 126,117,124, girls & boys dean's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
O-1	12" x 12" White w/ Tan Specks Vinyl Floor Tile Mastic	23,500	SF	1st,2nd,3rd floor hallways,auditorium, eng's office,Room 126,117,124, girls & boys dean's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
P	12" x 12" Vinyl Floor Tile Dark red w/ red Specks	7,100	SF	perimeter of 1st, 2nd and 3rd floor hallways, & auditorium, main office, library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
P-1	12" x 12" Vinyl Floor Tile Dark RED W/ RED SPECKS-MASTIC intact	7,100	SF	PERIMETER OF 1ST, 2ND & 3RD FLOOR HALLWAYS, main office, library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Q	12" x 12" TAN W/ Brown Specks Vinyl Floor Tile	650	SF	ROOM 222	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Q-1	12" x 12" TAN W/ Brown SPEC Vinyl Floor Tile-MASTIC	650	SF	ROOM 222	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
R	12" x 12" Brown W/ White Specks Vinyl Floor Tile	700	SF	ROOM 305 & 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
R/S-1	MASTIC FOR 12" x 12" Floor Tile (HA 'R' & 'S')	1,400	SF	ROOM 305 & 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
S	12" x 12" White W/ Beige Specks Vinyl Floor Tile	700	SF	ROOM 305 & 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
T	12" x 12" Dark RED Vinyl Floor Tile	2,950	SF	LUNCHROOM, ROOMS 330, 332	Assumed	MISC	No	4	SF	6 ACBM with the potential for damage	Repair
T/U-1	MASTIC FOR 12" x 12" Vinyl Floor Tile (HA 'T' & 'U')	5,900	SF	LUNCHROOM, ROOMS 330, 332	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
U	12" x 12" White W/ GRAY Streaks Floor Tile	2,950	SF	LUNCHROOM, ROOMS 330, 332	Assumed	MISC	No	4	SF	6 ACBM with the potential for damage	Repair
V	12" x 12" Brown W/ White Specks Vinyl Floor Tile intact	790	SF	ROOM 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
V-1	MASTIC FOR 12" x 12" Brown W/ White Specks Vinyl Floor Tile	790	SF	ROOM 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
W	12" x 12" Vinyl Floor Tile White W/ Brown Specks			ROOMS 990, 991,992, 993,994,995,996,997 & HALLWAYS, MEN,WOMEN,BOY & GIRL TOILETS (ALL IN W. TRAILER)	Abated	MISC					
W-1	12" x 12" Vinyl Floor Tile White W/ Brown Specks-MASTIC			ROOMS 990, 991,992, 993,994,995,996,997 & HALLWAYS,	Abated	MISC					

# Chicago Public Schools

**School** Gage Park High School

**Unit** 46141

**Building ID** 1340

**Address** 5630 S. Rockwell

Chicago, IL, 60629

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				MEN,WOMEN,BOY & GIRL TOILETS (ALL IN W. TRAILER)							
X	2' x 2' S. ACT-White abated			ALL CEILING OF WEST TRAILER	Abated	MISC					
Y	Drywall			ALL WALLS AND ABOVE S. ACT IN WEST TRAILER	Abated	MISC					
Z	12" x 12" Vinyl Floor Tile White W/ TAN Specks (Building Demolished 2011)			2 CLASSROOM TRAILER ON NORTH SIDE OF SCHOOL BLDG	Abated	MISC					
Z-1	12" x 12" Vinyl Floor Tile White W/ TAN Specks-MASTIC (Building Demolished 2011)			2 CLASSROOM TRAILER ON NORTH SIDE OF --SCHOOL BLDG	Abated	MISC					

# Chicago Public Schools

**School** Gage Park High School

**Unit** 46141

**Building ID** 1340

**Address** 5630 S. Rockwell

Chicago, IL, 60629

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	7/14/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
25	
25A	
25B	
25C	
26	
26A	
26B	
26C	
27/06	
27/07	
27/08	
27/09	
27/10	
27/14	
27/16	
27/17	
27/18	
27/19	
27/22	
27/23	
27/24	
27/27	
27/28	
28/06	
28/07	
28/08	

# Chicago Public Schools

**School** Gage Park High School

**Unit** 46141

**Building ID** 1340

**Address** 5630 S. Rockwell

Chicago, IL, 60629

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
28/09	
28/10	
28/14	
28/17	
28/18	
28/19	
28/22	
28/24	
28/27	
28/28	
29	
30	
33	
33A	
33B	
33C	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	



# Chicago Public Schools

**School** Gage Park High School

**Unit** 46141

**Building ID** 1340

**Address** 5630 S. Rockwell

Chicago, IL, 60629

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
45	
A(46)	
AA	
B(45)	
D	
E	
F	
FT-1	
FT-2	
FTM-1	
FTM-2	
G	
H	
I	
J	
K	
L	
M	
N	
N-1	
O	
O-1	
P	
P-1	
Q	
Q-1	
R	

# Chicago Public Schools

**School** Gage Park High School  
**Address** 5630 S. Rockwell

**Unit** 46141  
Chicago, IL, 60629

**Building ID** 1340  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
R/S-1	
S	
T	
T/U-1	
U	
V	
V-1	
W	
W-1	
X	
Y	
Z	
Z-1	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

Carnow, Conibear and Associates

*2022 AHERA REINSPECTION*

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/Dark Green Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 128**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12" x 12" Light Green w/Dark Green Specks Floor Tile**

MATERIAL LOCATION: **room 128**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25A**  
MATERIAL DESCRIPTION: **12" x 12" White Specksed Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **main office**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **25A**  
MATERIAL DESCRIPTION: **12" x 12" White Specksed Floor Tile**  
MATERIAL LOCATION: **main office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25B**  
MATERIAL DESCRIPTION: **12" x 12" black w/White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **25B**  
MATERIAL DESCRIPTION: **12" x 12" black w/White Specks Floor Tile**  
MATERIAL LOCATION: **auditorium**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25C**  
MATERIAL DESCRIPTION: **12" x 12" flesh w/tan & White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 221**

MATERIAL QUANTITY: **1125**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **25C**  
MATERIAL DESCRIPTION: **12" x 12" flesh w/tan & White Specks Floor Tile**  
MATERIAL LOCATION: **room 221**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/Dark Green Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 128**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/Dark Green Specks Floor Tile Mastic**  
MATERIAL LOCATION: **room 128**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26A**  
MATERIAL DESCRIPTION: **12" x 12" rose Specksed Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **main office**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **26A**  
MATERIAL DESCRIPTION: **12" x 12" rose Specksed Floor Tile Mastic**  
MATERIAL LOCATION: **main office**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26B**  
MATERIAL DESCRIPTION: **12" x 12" black w/White Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **26B**

MATERIAL DESCRIPTION: **12" x 12" black w/White Specks Floor Tile Mastic**

MATERIAL LOCATION: **auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26C**  
MATERIAL DESCRIPTION: **12" x 12" flesh w/tan & White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 221**

MATERIAL QUANTITY: **1120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **26C**  
MATERIAL DESCRIPTION: **12" x 12" flesh w/tan & White Floor Tile Mastic**  
MATERIAL LOCATION: **room 221**  
MATERIAL QUANTITY: **1120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/06**  
MATERIAL DESCRIPTION: **9" x 9" black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd floor corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/06**

MATERIAL DESCRIPTION: **9" x 9" black Floor Tile**

MATERIAL LOCATION: **1st, 2nd & 3rd floor corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/07**  
MATERIAL DESCRIPTION: **9" x 9" maroon Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd floor corridors, Auditorium.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/07**

MATERIAL DESCRIPTION: **9" x 9" maroon Floor Tile**

MATERIAL LOCATION: **1st, 2nd & 3rd floor corridors, Auditorium.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/08**  
MATERIAL DESCRIPTION: **9x18 black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd & 3rd floor corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/08**

MATERIAL DESCRIPTION: **9x18 black Floor Tile**

MATERIAL LOCATION: **2nd & 3rd floor corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/09**  
MATERIAL DESCRIPTION: **9" x 9" black w/White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **engineer's locker room, patched areas**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/09**

MATERIAL DESCRIPTION: **9" x 9" black w/White Streaks Floor Tile**

MATERIAL LOCATION: **engineer's locker room, patched areas**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/10**  
MATERIAL DESCRIPTION: **9" x 9" rose w/White streak Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **engineers office corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/10**

MATERIAL DESCRIPTION: **9" x 9" rose w/White streak Floor Tile**

MATERIAL LOCATION: **engineers office corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/14**  
MATERIAL DESCRIPTION: **9" x 9" chocolate Brown w/ White streak Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st,2nd, 3rd floor corridors-abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/14**

MATERIAL DESCRIPTION: **9" x 9" chocolate Brown w/ White streak Floor Tile**

MATERIAL LOCATION: **1st,2nd, 3rd floor corridors-abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/16**  
MATERIAL DESCRIPTION: **9" x 9" Light tan w/Brown & White Streaks Floor Tile-**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 121-material removed.**

MATERIAL QUANTITY: **523**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/16**  
MATERIAL DESCRIPTION: **9" x 9" Light tan w/Brown & White Streaks Floor Tile-**  
MATERIAL LOCATION: **room 121-material removed.**  
MATERIAL QUANTITY: **523** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/17**  
MATERIAL DESCRIPTION: **9" x 9" red w/White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **POLICE OFFICE, engineer's office, engineer's locker room**  
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/17**

MATERIAL DESCRIPTION: **9" x 9" red w/White Streaks Floor Tile**

MATERIAL LOCATION: **POLICE OFFICE, engineer's office, engineer's locker room**

MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/18**  
MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/White and Gold Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **corridor outside engineer's office, POLICE OFFICE**

MATERIAL QUANTITY: **259**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/18**  
MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/White and Gold Streaks Floor Tile**  
MATERIAL LOCATION: **corridor outside engineer's office, POLICE OFFICE**  
MATERIAL QUANTITY: **259** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/19**  
MATERIAL DESCRIPTION: **9" x 9" olive Floor Tile w/White Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **engineer's office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/19**

MATERIAL DESCRIPTION: **9" x 9" olive Floor Tile w/White Streaks**

MATERIAL LOCATION: **engineer's office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/22**  
MATERIAL DESCRIPTION: **9" x 9" black & White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **girls' coaches office**  
MATERIAL QUANTITY: **265** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/22**

MATERIAL DESCRIPTION: **9" x 9" black & White Floor Tile**

MATERIAL LOCATION: **girls' coaches office**

MATERIAL QUANTITY: **265**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/23**  
MATERIAL DESCRIPTION: **9" x 9" black and White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **girls exam room**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/23**

MATERIAL DESCRIPTION: **9" x 9" black and White Floor Tile**

MATERIAL LOCATION: **girls exam room**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/24**  
MATERIAL DESCRIPTION: **12" x 12" White w/Brown spots Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **rooms 225, 305**

MATERIAL QUANTITY: **1825**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/24**

MATERIAL DESCRIPTION: **12" x 12" White w/Brown spots Floor Tile**

MATERIAL LOCATION: **rooms 225, 305**

MATERIAL QUANTITY: **1825**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46141 BUIDLING ID: 1340  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Benyamen Maradkel  
SCHOOL NAME: Gage Park High School INSPECTION DATE: 6/30/2022  
ADDRESS: 5630 S. Rockwell IDPH LICENSE NO: 100-20411

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27/27  
MATERIAL DESCRIPTION: 9" x 9" tan leopard Floor Tile Not visible  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: room 302

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/27**

MATERIAL DESCRIPTION: **9" x 9" tan leopard Floor Tile Not visible**

MATERIAL LOCATION: **room 302**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27/28**  
MATERIAL DESCRIPTION: **9" x 9" Brown leopard Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27/28**

MATERIAL DESCRIPTION: **9" x 9" Brown leopard Floor Tile**

MATERIAL LOCATION: **room 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46141    BUILDING ID: 1340  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Benyamen Maradkel  
SCHOOL NAME: Gage Park High School    INSPECTION DATE: 6/30/2022  
ADDRESS: 5630 S. Rockwell    IDPH LICENSE NO: 100-20411

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28/06  
MATERIAL DESCRIPTION: 9" x 9" black Floor Tile Mastic, w/ HA 27/6  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Chrysotile    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st, 2nd & 3rd floor corridors

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2022

Inspector's Signature:



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/06**

MATERIAL DESCRIPTION: **9" x 9" black Floor Tile Mastic, w/ HA 27/6**

MATERIAL LOCATION: **1st, 2nd & 3rd floor corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28/07**  
MATERIAL DESCRIPTION: **9" x 9" maroon Floor Tile Mastic, w/ HA 277**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd floor corridors,auditorium.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/07**

MATERIAL DESCRIPTION: **9" x 9" maroon Floor Tile Mastic, w/ HA 27/7**

MATERIAL LOCATION: **1st, 2nd & 3rd floor corridors, auditorium.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28/08**  
MATERIAL DESCRIPTION: **9x18 black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd floor corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/08**

MATERIAL DESCRIPTION: **9x18 black Floor Tile Mastic**

MATERIAL LOCATION: **1st, 2nd & 3rd floor corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28/09**  
MATERIAL DESCRIPTION: **9" x 9" chocolate Brown w/White Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **engineer's locker room**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/09**

MATERIAL DESCRIPTION: **9" x 9" chocolate Brown w/White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **engineer's locker room**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28/10**  
MATERIAL DESCRIPTION: **9" x 9" rose w/White Streaks Floor Tile Mastic not visible**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd,3rd floor corridors, patched areas**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/10**

MATERIAL DESCRIPTION: **9" x 9" rose w/White Streaks Floor Tile Mastic not visible**

MATERIAL LOCATION: **1st & 2nd,3rd floor corridors, patched areas**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28/14**  
MATERIAL DESCRIPTION: **9" x 9" chocolate Brown w/White streak Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st,2nd,3rd floor corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/14**

MATERIAL DESCRIPTION: **9" x 9" chocolate Brown w/White streak Floor Tile Mastic**

MATERIAL LOCATION: **1st,2nd,3rd floor corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28/17**  
MATERIAL DESCRIPTION: **9" x 9" red w/White Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Police office, engineer's office, engineer's locker room**

MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/17**

MATERIAL DESCRIPTION: **9" x 9" red w/White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Police office. engineer's office, engineer's locker room**

MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28/18**  
MATERIAL DESCRIPTION: **9" x 9" drk Brown w/White & Gold streak Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **corridor outside engineer's office, police office**

MATERIAL QUANTITY: **259**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/18**  
MATERIAL DESCRIPTION: **9" x 9" drk Brown w/White & Gold streak Floor Tile Mastic**  
MATERIAL LOCATION: **corridor outside engineer's office, police office**  
MATERIAL QUANTITY: **259** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28/19**  
MATERIAL DESCRIPTION: **12" x 12" White w/Multicolor Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **engineer's office**

MATERIAL QUANTITY: **134**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/19**

MATERIAL DESCRIPTION: **12" x 12" White w/Multicolor Streaks Floor Tile**

MATERIAL LOCATION: **engineer's office**

MATERIAL QUANTITY: **134**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28/22**  
MATERIAL DESCRIPTION: **9" x 9" gray Green Floor Tile Mastic not visible**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **girls' coaches office**  
MATERIAL QUANTITY: **248** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/22**

MATERIAL DESCRIPTION: **9" x 9" gray Green Floor Tile Mastic not visible**

MATERIAL LOCATION: **girls' coaches office**

MATERIAL QUANTITY: **248**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28/24**  
MATERIAL DESCRIPTION: **12" x 12" White w/Brown spots Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rooms 225, 305**  
MATERIAL QUANTITY: **1825** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/24**

MATERIAL DESCRIPTION: **12" x 12" White w/Brown spots Floor Tile Mastic**

MATERIAL LOCATION: **rooms 225, 305**

MATERIAL QUANTITY: **1825**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46141    BUIDLING ID: 1340  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Benyamen Maradkel  
SCHOOL NAME: Gage Park High School    INSPECTION DATE: 6/30/2022  
ADDRESS: 5630 S. Rockwell    IDPH LICENSE NO: 100-20411

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28/27  
MATERIAL DESCRIPTION: 9" x 9" tan leopard Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Chrysotile    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: room 307

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2022

Inspector's Signature:



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/27**

MATERIAL DESCRIPTION: **9" x 9" tan leopard Floor Tile Mastic**

MATERIAL LOCATION: **room 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28/28**  
MATERIAL DESCRIPTION: **9" x 9" Brown leopard Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28/28**

MATERIAL DESCRIPTION: **9" x 9" Brown leopard Floor Tile Mastic**

MATERIAL LOCATION: **room 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Transite table tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 321, 322, 317, 213, 215, 217, 217a**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Transite table tops**  
MATERIAL LOCATION: **Room 321, 322, 317, 213, 215, 217, 217a**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Transite lab hood**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 317**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Transite lab hood**

MATERIAL LOCATION: **room 317**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Pink & tweed Green carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 124, 125, 128, assistant principal's office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Pink & tweed Green carpet Mastic**

MATERIAL LOCATION: **Room 124, 125, 128, assistant principal's office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46141    BUILDING ID: 1340  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Benyamen Maradkel  
SCHOOL NAME: Gage Park High School    INSPECTION DATE: 6/30/2022  
ADDRESS: 5630 S. Rockwell    IDPH LICENSE NO: 100-20411

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33A  
MATERIAL DESCRIPTION: 12" x 12" Burgundy tweed carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 120,126, 123, 117, principal's office, PARM, assembly hall,

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS: Not observed 2022

Inspector's Signature:



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **33A**  
MATERIAL DESCRIPTION: **12" x 12" Burgundy tweed carpet Mastic**  
MATERIAL LOCATION: **Room 120,126, 123, 117, principal's office, PARM, assembly hall,**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33B**  
MATERIAL DESCRIPTION: **Pea Green carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 216**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **33B**

MATERIAL DESCRIPTION: **Pea Green carpet Mastic**

MATERIAL LOCATION: **room 216**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33C**  
MATERIAL DESCRIPTION: **Gold carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 113**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **33C**

MATERIAL DESCRIPTION: **Gold carpet Mastic**

MATERIAL LOCATION: **room 113**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Beige Spots Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY: **1120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Beige Spots Floor Tile**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY: **1120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige w/ Dark Beige Spots Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY: **1120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige w/ Dark Beige Spots Floor Tile**  
MATERIAL LOCATION: **Room 307**  
MATERIAL QUANTITY: **1120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12" x 12" Dark Beige w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Driver's ED Trailer**  
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" Dark Beige w/ White Specks Floor Tile**

MATERIAL LOCATION: **Driver's ED Trailer**

MATERIAL QUANTITY: **1650**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Dark Beige w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Driver's ED Trailer**  
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Dark Beige w/ White Specks Floor Tile**  
MATERIAL LOCATION: **Driver's ED Trailer**  
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A(46)**  
MATERIAL DESCRIPTION: **Air cell pipe insulation intact**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **basement**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **A(46)**

MATERIAL DESCRIPTION: **Air cell pipe insulation intact**

MATERIAL LOCATION: **basement**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **Drywall (trailer demolished 2011)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ALL WALLS AND CEILINGS IN 2 CLASSROOMS TRAILER ON NORTH SIDE OF SCHOOL**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **Drywall (trailer demolished 2011)**  
MATERIAL LOCATION: **ALL WALLS AND CEILINGS IN 2 CLASSROOMS TRAILER ON NORTH SIDE OF SCHOOL**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B(45)**  
MATERIAL DESCRIPTION: **Aircell hard joints-abated.**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **boiler room, basement, rest rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **B(45)**

MATERIAL DESCRIPTION: **Aircell hard joints-abated.**

MATERIAL LOCATION: **boiler room, basement, rest rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Mag block on heat excahnger intact**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Amosite** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement pool chemical room**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Not observed 2022 - Removed**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Mag block on heat excahnger intact**

MATERIAL LOCATION: **Basement pool chemical room**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **FG hard joints intact**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **basement unexcavated area, boiler room, mechanical room**  
MATERIAL QUANTITY: **195** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **FG hard joints intact**  
MATERIAL LOCATION: **basement unexcavated area, boiler room, mechanical room**  
MATERIAL QUANTITY: **195** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **White 12" x 12" Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 221**  
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **White 12" x 12" Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 221**  
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 216, 221, 222, 217A, 225, 307, teacher's lounge, Principal's office, Room 123,  
Assistant Principal's office, parm, 113, 125**  
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Slight damage in Room 307**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**  
MATERIAL LOCATION: **Room 216, 221, 222, 217A, 225, 307, teacher's lounge, Principal's office, Room 123, Assistant Principal's office, parm, 113, 125**  
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **37** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **12" x 12" Burgundy w/ White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd & 3rd fl. Corridors**

MATERIAL QUANTITY: **9400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **12" x 12" Burgundy w/ White Streaks Floor Tile**  
MATERIAL LOCATION: **1st, 2nd & 3rd fl. Corridors**  
MATERIAL QUANTITY: **9400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12" x 12" Beige Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 216, 221, 222, 217A, 225, 307, teacher's lounge, principal's office, asst. principal's office, Room 123, parm, 113, 125**

MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12" x 12" Beige Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 216, 221, 222, 217A, 225, 307, teacher's lounge, principal's office, asst. principal's office, Room 123, parm, 113, 125**  
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-2**  
MATERIAL DESCRIPTION: **12" x 12" Burgundy w/ White Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd & 3rd fl corridors**

MATERIAL QUANTITY: **9400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **FTM-2**  
MATERIAL DESCRIPTION: **12" x 12" Burgundy w/ White Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1st, 2nd & 3rd fl corridors**  
MATERIAL QUANTITY: **9400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Mastic for White 12" x 12" Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 221**

MATERIAL QUANTITY: **720**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Mastic for White 12" x 12" Vinyl Floor Tile**  
MATERIAL LOCATION: **room 221**  
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Gray carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 125**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Gray carpet Mastic**

MATERIAL LOCATION: **Room 125**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Air cell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **basement.**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Air cell pipe insulation**  
MATERIAL LOCATION: **basement.**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Aircell hard joints intact**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **boiler room, basement, rest rooms**  
MATERIAL QUANTITY: **35** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Aircell hard joints intact**  
MATERIAL LOCATION: **boiler room, basement, rest rooms**  
MATERIAL QUANTITY: **35** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **1' x 1' ACT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, 3rd floor corriors and lunchroom, hallways**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage in 2 floor hallways (207)**

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **1' x 1' ACT**  
MATERIAL LOCATION: **1st, 2nd, 3rd floor corriors and lunchroom, hallways**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **1' x 1' act Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, 3rd floor corriors and lunchroom**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage in lunchroom ceiling**

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **1' x 1' act Mastic**  
MATERIAL LOCATION: **1st, 2nd, 3rd floor corriors and lunchroom**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **2' x 4' ACT**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **all classrooms on 1st,2nd and 3rd**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **2' x 4' ACT**  
MATERIAL LOCATION: **all classrooms on 1st,2nd and 3rd**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ Beige Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ROOM 121 & 125**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ Beige Specks**  
MATERIAL LOCATION: **ROOM 121 & 125**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N-1**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ Beige SPECKS- MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **ROOMS 121 & 125**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **N-1**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ Beige SPECKS- MASTIC**  
MATERIAL LOCATION: **ROOMS 121 & 125**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st,2nd,3rd floor hallways,auditorium,eng's office,Room 126,117,124, girls & boys dean's office**

MATERIAL QUANTITY: **23500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Specks Vinyl Floor Tile**

MATERIAL LOCATION: **1st,2nd,3rd floor hallways,auditorium,eng's office,Room 126,117,124, girls & boys dean's office**

MATERIAL QUANTITY: **23500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **O-1**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st,2nd,3rd floor hallways,auditorium,eng's office,Room 126,117,124, girls & boys dean's office**

MATERIAL QUANTITY: **23500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **O-1**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **1st,2nd,3rd floor hallways,auditorium,eng's office,Room 126,117,124, girls & boys dean's office**  
MATERIAL QUANTITY: **23500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile Dark red w/ red Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **perimeter of 1st, 2nd and 3rd floor hallways, & auditorium, main office, library**  
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile Dark red w/ red Specks**  
MATERIAL LOCATION: **perimeter of 1st, 2nd and 3rd floor hallways, & auditorium, main office, library**  
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P-1**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile Dark RED W/ RED SPECKS-MASTIC intact**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **PERIMETER OF 1ST, 2ND & 3RD FLOOR HALLWAYS, main office, library**  
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **P-1**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile Dark RED W/ RED SPECKS-MASTIC intact**  
MATERIAL LOCATION: **PERIMETER OF 1ST, 2ND & 3RD FLOOR HALLWAYS, main office, library**  
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **12" x 12" TAN W/ Brown Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ROOM 222**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **12" x 12" TAN W/ Brown Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **ROOM 222**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q-1**  
MATERIAL DESCRIPTION: **12" x 12" TAN W/ Brown SPEC Vinyl Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **ROOM 222**

MATERIAL QUANTITY: **650**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **Q-1**  
MATERIAL DESCRIPTION: **12" x 12" TAN W/ Brown SPEC Vinyl Floor Tile-MASTIC**  
MATERIAL LOCATION: **ROOM 222**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **12" x 12" Brown W/ White Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ROOM 305 & 303**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **12" x 12" Brown W/ White Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **ROOM 305 & 303**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R/S-1**  
MATERIAL DESCRIPTION: **MASTIC FOR 12" x 12" Floor Tile (HA 'R' & 'S')**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ROOM 305 & 303**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **R/S-1**

MATERIAL DESCRIPTION: **MASTIC FOR 12" x 12" Floor Tile (HA 'R' & 'S')**

MATERIAL LOCATION: **ROOM 305 & 303**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **12" x 12" White W/ Beige Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ROOM 305 & 303**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **12" x 12" White W/ Beige Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **ROOM 305 & 303**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **12" x 12" Dark RED Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **LUNCHROOM, ROOMS 330, 332**  
MATERIAL QUANTITY: **2950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage in room 332, room 330**

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **12" x 12" Dark RED Vinyl Floor Tile**  
MATERIAL LOCATION: **LUNCHROOM, ROOMS 330, 332**  
MATERIAL QUANTITY: **2950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T/U-1**  
MATERIAL DESCRIPTION: **MASTIC FOR 12" x 12" Vinyl Floor Tile (HA 'T' & 'U')**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **LUNCHROOM, ROOMS 330, 332**

MATERIAL QUANTITY: **5900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **T/U-1**  
MATERIAL DESCRIPTION: **MASTIC FOR 12" x 12" Vinyl Floor Tile (HA 'T' & 'U')**  
MATERIAL LOCATION: **LUNCHROOM, ROOMS 330, 332**  
MATERIAL QUANTITY: **5900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **12" x 12" White W/ GRAY Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **LUNCHROOM, ROOMS 330, 332**  
MATERIAL QUANTITY: **2950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage in room 332, room 330**

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **12" x 12" White W/ GRAY Streaks Floor Tile**  
MATERIAL LOCATION: **LUNCHROOM, ROOMS 330, 332**  
MATERIAL QUANTITY: **2950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **12" x 12" Brown W/ White Specks Vinyl Floor Tile intact**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ROOM 115**  
MATERIAL QUANTITY: **790** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **12" x 12" Brown W/ White Specks Vinyl Floor Tile intact**  
MATERIAL LOCATION: **ROOM 115**  
MATERIAL QUANTITY: **790** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V-1**  
MATERIAL DESCRIPTION: **MASTIC FOR 12" x 12" Brown W/ White Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ROOM 115**  
MATERIAL QUANTITY: **790** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **V-1**  
MATERIAL DESCRIPTION: **MASTIC FOR 12" x 12" Brown W/ White Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **ROOM 115**  
MATERIAL QUANTITY: **790** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ Brown Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS 990, 991,992, 993,994,995,996,997 & HALLWAYS,MEN,WOMEN,BOY & GIRL TOILETS (ALL IN W. TRAILER)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **W**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ Brown Specks**

MATERIAL LOCATION: **ROOMS 990, 991,992, 993,994,995,996,997 & HALLWAYS,MEN,WOMEN,BOY & GIRL TOILETS  
(ALL IN W. TRAILER)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W-1**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ Brown Specks-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOMS 990, 991,992, 993,994,995,996,997 & HALLWAYS,MEN,WOMEN,BOY & GIRL TOILETS (ALL IN W. TRAILER)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **W-1**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ Brown Specks-MASTIC**  
MATERIAL LOCATION: **ROOMS 990, 991,992, 993,994,995,996,997 & HALLWAYS,MEN,WOMEN,BOY & GIRL TOILETS  
(ALL IN W. TRAILER)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **2' x 2' S. ACT-White abated**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ALL CEILING OF WEST TRAILER**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **X**

MATERIAL DESCRIPTION: **2' x 2' S. ACT-White abated**

MATERIAL LOCATION: **ALL CEILING OF WEST TRAILER**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ALL WALLS AND ABOVE S. ACT IN WEST TRAILER**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated**

Inspector's Signature:



Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **Y**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **ALL WALLS AND ABOVE S. ACT IN WEST TRAILER**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ TAN Specks (Building Demolished 2011)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2 CLASSROOM TRAILER ON NORTH SIDE OF SCHOOL BLDG**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/30/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **Z**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ TAN Specks (Building Demolished 2011)**

MATERIAL LOCATION: **2 CLASSROOM TRAILER ON NORTH SIDE OF SCHOOL BLDG**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z-1**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ TAN Specks-MASTIC (Building Demolished 2011)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2 CLASSROOM TRAILER ON NORTH SIDE OF --SCHOOL BLDG**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: **06/30/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **Z-1**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White W/ TAN Specks-MASTIC (Building Demolished 2011)**  
MATERIAL LOCATION: **2 CLASSROOM TRAILER ON NORTH SIDE OF --SCHOOL BLDG**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46141**    BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School**    INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell**    IDPH LICENSE NO: **100-20411**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12" x 12" White ceiling tile**  
MATERIAL LOCATION: **lunchroom, Room 332, 330**  
MATERIAL QUANTITY: **5000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **Damaged**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Not Reachable**    DAMAGE REASON:  
DAMAGE QUANTITY: **7**    DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:  
Damage in lunchroom ceiling, room 332

Inspector's Signature:



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12" x 12" White ceiling tile**  
MATERIAL LOCATION: **lunchroom, Room 332, 330**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **7** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46141**      BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School**      INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell**      IDPH LICENSE NO: **100-20411**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Light Gray Specks Floor Tile**  
MATERIAL LOCATION: **Room 120**  
MATERIAL QUANTITY: **2000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Light Gray Specks Floor Tile**  
MATERIAL LOCATION: **Room 120**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Light Gray Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 120**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Light Gray Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 120**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46141**    BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School**    INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell**    IDPH LICENSE NO: **100-20411**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Chalk boards**  
MATERIAL LOCATION: **throughout 1st, 2nd, 3rd floor classrooms**  
MATERIAL QUANTITY: **10000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46141**      BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School**      REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell**      IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Chalk boards**  
MATERIAL LOCATION: **throughout 1st, 2nd, 3rd floor classrooms**  
MATERIAL QUANTITY: **10000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46141**      BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School**      INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell**      IDPH LICENSE NO: **100-20411**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" x 12" Cream w/ Multicolor Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Lunchroom, teachers lounge, 128 (attendance office)**  
MATERIAL QUANTITY: **50**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **Damaged**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **1**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Damage in teacher's lounge

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" x 12" Cream w/ Multicolor Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Lunchroom, teachers lounge, 128 (attendance office)**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/14/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46141**      BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School**      INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell**      IDPH LICENSE NO: **100-20411**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12" x 12" Bright Red Floor Tile**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **20**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12" x 12" Bright Red Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUIDLING ID: **1340**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School** INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12" x 12" Bright Red Floor Tile Mastic**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12" x 12" Bright Red Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46141**      BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Gage Park High School**      INSPECTION DATE: **6/30/2022**  
ADDRESS: **5630 S. Rockwell**      IDPH LICENSE NO: **100-20411**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12" x 12" Cream w/ Multicolor Specks Floor Tile**  
MATERIAL LOCATION: **Lunchroom, teachers lounge, 128 (attendance office)**  
MATERIAL QUANTITY: **50**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION: **Damaged**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **1**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Damage in teacher's lounge

Inspector's Signature: \_\_\_\_\_



Date: 06/30/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46141** BUILDING ID: **1340**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gage Park High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **5630 S. Rockwell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12" x 12" Cream w/ Multicolor Specks Floor Tile**  
MATERIAL LOCATION: **Lunchroom, teachers lounge, 128 (attendance office)**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# APPENDIX B

## Inspector and Management Planner Licenses

---

# Benyamen Maradkel

Illinois Licensed Building Inspector



**ASBESTOS  
PROFESSIONAL  
LICENSE**

**ID NUMBER**  
**100 - 20411**

**ISSUED**  
**3/17/2022**

**EXPIRES**  
**05/15/2023**

**BENYAMEN C MARADKEL**  
**706 W HACKBERRY DR**  
**ARLINGTON HEIGHTS, IL 6000**  
*Environmental Health*



**ENDORSEMENTS**

INSPECTOR

**EXPIRES**

5/9/2023

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.





OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Benyamen Maradkel**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090703

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519

  
Kathy DeSalvo, Director



# ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

**100 - 19466**

ISSUED

**4/22/2022**

EXPIRES

**05/15/2023**

**EVAN I CHRISTIAN**  
**1119 N HOYNE AVE, APT 1**  
**CHICAGO, IL 60622**

Environmental Health



## ENDORSEMENTS

## TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**

This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed