

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0026
SCHOOL NAME: Lakeview High School
ADDRESS OF SCHOOL: 4015 N. Ashland
CITY: Chicago, IL, 60613

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **10/15/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 8/5/2022 ENROLLMENT 1304
IDPH INSPECTOR LICENSE NUMBER: 100-11093
IDPH LICENSED INSPECTOR NAME (Please Print): David Avila
IDPH MP LICENSE NUMBER: 100-04019
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



8/26/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Lakeview High School

4015 N. Ashland
Chicago, IL, 60613

Unit: 46211
Building ID: 1430

IDPH ID Number: 14-016-2990-0026

REPORT DATE:

Friday, August 26, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Specialty Consulting, Inc.

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

08/26/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 46211 Region: 01 IDPH ID: 14-016-2990-0026

School: Lakeview High School Building ID: 1430

Address: 4015 N. Ashland
Chicago, IL, 60613

Building Contact: Rizzo, Michael Contact Phone: 7737097567

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/5/2022

Review Date: 08/26/2022

Inspector: David Avila Inspector IDPH License: 100-11093
Management Planner: Arturo Saenz Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Arturo Saenz
100-04019

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 26, 2022

RE: Lakeview High School, Unit 46211
4015 N. Ashland
Chicago, IL, 60613

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Lakeview High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Lakeview High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Lakeview High School
Address: 4015 N. Ashland
IDPH ID: 14-016-2990-0026
Contact: Rizzo, Michael

Unit: 46211
Chicago, IL, 60613
Building ID: 1430
Phone: 7737097567

Region: 01

2. Description of Facility

Original Construction: 1915
Total Square Footage: 111018
Current Occupancy: 1304

Additional Construction: 1898,1938
No of Floors: 4

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant


MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575

Fax: (312) 319-7580

5. Inspector

Inspector Name: David Avila


Inspector IDPH license # 100-11093
Reinspection Date: 8/5/2022

Signature: 
Date: 8/5/2022

6. Management Planner

Management Planner Name: Arturo Saenz


Management Planner IDPH license # 100-04019

Signature: 
Date: 08/26/2022

7. Review Date: 08/26/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 8/26/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Lakeview High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1430:

B. The following new homogenous areas have been identified for Building 1430:

159	Black w/ Speaks VFT
159A	Black w/ Speaks VFT Mastic
160	White w/ Speaks VFT
160A	White w/ Speaks VFT Mastic
161	Beige W/ Speaks VFT
161A	Beige W/ Speaks VFT Mastic
162	Counter & tabletops
163	Fume Hood

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

101 A	Terrazzo
101A	Green Linoleum
102A	Green Linoleum Mastic
117	Fire doors
118	12"x12" offwhite w/ light grey & grey specks VFT
118A	12"x12" oof white w/ light gray and gray specks VFT MASTIC
119	Decorative plaster
11A	Light Brown Linoleum
121	Carpet MASTIC
122	Pyroboard
124	Carpet MASTIC
125	Carpet MASTIC
129	12"x12" Brown wood grain VFT
129A	12"x12" brown wood grain VFT MASTIC
130	Drywall system
131	9"x9" light green w/ black and white striations VFT
131A	9"x9" light green w/ black and white striations VFT MASTIC
132	9"x9" light green w/ black and white striations VFT
132A	9"x9" light green w/ black and white striations VFT MASTIC
133	12"x12" white w/ tan specks VFT
133A	12"x12 white w/ tan specks VFT MASTIC
134	12 x 12 Dark Gray w/ specks
135	12 x 12 Dark Gray w/ specks mastic
136	12 x 12 Gray w/ Specks VFT
137	12 x 12 Gray w/ specks VFT Mastic
138	12 x 12 White w/ Specks VFT
139	12 x 12 White w/ specks VFT mastic
140	12 x 12 Red w/ Specks VFT
141	12 x 12 red w/ specks VFT mastic
142	12 x 12 Dark gray w/ specks VFT
143	12 x 12 dark gray w/ specks VFT Mastic
144	12 x 12 Gray w/ Specks VFT
145	12 x 12 gray w/ Specks VFT Mastic
146	12 x 12 White w/ specks VFT
147	12 x 12 white w/ specks VFT Mastic
148	12 x 12 Red w/ specks VFT
149	12 x 12 Red w/ Specks VFT Mastic
14A	Plaster Wall & Plaster Ceiling
150	12 x 12 Dark gray w/ specks VFT

151	12 x 12 Dark gray w/ specks VFT Mastic
152	12 x 12 Gray w specks VFT
153	12 x 12 gray w/ specks VFT Mastic
154	12 x 12 White w/ specks VFT
155	12 x 12 White w/ specks VFT Mastic
156	12 x 12 Red w/ specks VFT
157	12 x 12 Red w/ specks VFT Mastic
158	2' x 2' ceiling tile
159	Black w/ Speaks VFT
159A	Black w/ Speaks VFT Mastic
160	White w/ Speaks VFT
160A	White w/ Speaks VFT Mastic
161	Beige W/ Speaks VFT
161A	Beige W/ Speaks VFT Mastic
162	Counter & tabletops
163	Fume Hood
16A	Light Brown Linoleum Mastic
18A	Black Laboratory Countertop
19A	Black Lab Countertop
20A	Black Laboratory Countertop
21A	12"x12" Light Brown w/Dark Speckles VFT
22A	12"x12" Light Brown w/Dark Speckles VFT Mastic
55A	12"x 12" Tan w/Tan Streaks VFT (Pink)
56A	12"x 12" Red w/Tan Streaks VFT Mastic (Pink)
67A	12"x12" Gray w/White & Brown Streaks VFT
73A	12"x12" Tan w/Brown & Gray Streaks VFT
74A	12"x12" Tan w/Brown & Gray Streaks VFT Mastic
89A	Brown Linoelum
90A	Brown Linoelum Mastic
93A	12"x12" Beige VFT (under new HA)
94A	12"x12" Beige VFT Mastic (under new HA)
HA-1000	2'x4' white ceiling tile
HA-1004	1'x1' white fissured ceiling tile
HA-1005	Glue for 1'x1' wh, fissured tile
HA-1006	12x12 Black w/white specks VFT
HA-1006A	12x12 Black w/white specks VFT Mastic
HA-1007	12x12 White w/black & gray specks VFT
HA-1007A	12x12 White w/black & gray specks VFT Mastic
HA-1008	12x12 Tan w/brown & tan specks VFT
HA-1008A	12x12 Tan w/brown & tan specks VFT Mastic
HA-1009	2x2 Ceiling Tile
HA-1010	12x12 Black w/white specks VFT
HA-1010A	12x12 Black w/white specks VFT Mastic
HA-1011	12x12 Tan w/brown & tan specks VFT
HA-1011A	12x12 Tan w/brown & tan specks VFT Mastic
HA-1012	12x12 Black VFT
HA-1012A	12x12 Black VFT Mastic
HA-1013	2x2 Ceiling Tile

HA-1017	Spray on fire-proofing
HA-1018	12x12 Black w/white specks VFT
HA-1018A	12x12 Black w/white specks VFT Mastic
HA-1019	12x12 White w/black & gray specks VFT
HA-1019A	12x12 White w/black & gray specks VFT Mastic
HA-1020	12x12 Tan w/brown & tan specks VFT
HA-1020A	12x12 Tan w/brown & tan specks VFT Mastic
HA-1021	Mastic Pucks
HA-1022	12x12 Beige w/brown, white, blue & black specks VFT
HA-1022A	12x12 Beige w/brown, white, blue & black specks VFT Mastic
HA-1023	12x12 Purple VFT
HA-1023A	12x12 Purple VFT Mastic
HA-1024	12x12 Peach w/blue & cream specks VFT
HA-1024A	12x12 Peach w/blue & cream specks VFT Mastic
HA-1025	2x2 Ceiling Tile
HA-1026	Carpet Mastic
HA-1027	1x1 Ceiling Tile w/ white grooves & holes
HA-1027A	1x1 Ceiling Tile w/ white grooves & holes pucks

The following areas were deemed to be inaccessible:

06A	12"x12" Beige w/White Streaks VFT
08A	12"x12" Beige w/White Streaks VFT Mastic
122	Pyroboard
139	12 x 12 White w/ specks VFT mastic
HA-1005	Glue for 1'x1' wh, fissured tile
HA-1019A	12x12 White w/black & gray specks VFT Mastic
HA-1021	Mastic Pucks

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by David Avila, IDPH License # 100-11093. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	6/23/2020
	7/30/2020
	4/18/2022

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Lakeview High School Building 1430 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
006	Aircell Pipe Insulation	80	LF	1st Floor Darkroom, Room 110, 328 (Abated), Lunchroom Storage under Stairs, LRS #2 Bathroom Chase - 1938 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
009	MJP on Aircell Pipe Insulation	16	LF	1st Floor Darkroom, Room 110, Lunchroom Storage under Stairs, LRS #2 Bathroom Chase - 1938 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
01A	9"x9" Gray VFT	4,550	SF	Rooms: 232 (Library - Under Carpet/plywood substrate), 334, 325, 337, MDF Rm 232A -1915 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02A	12"x12" Beige w/White Spots VFT (ABATED)			Rooms 119, 122, 124, 215, 220, 222 - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
03A	9"x9" Gray VFT Mastic	4,550	SF	Rooms: 232 (Library - Under Carpet/plywood substrate), 334 325 and 337(under new HA), MDF Rm 232A -1915 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04A	12"x12" Beige w/White Spots VFT Mastic (ABATED)			Rooms 119, 122, 124, 215, 220, 222 - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
05A	9"x9" Gray w/White & Black Streaks VFT	2,250	SF	Rooms 121, 123, 125, 129, 228, 229 (under carpet, 422 (under carpet) Under New HA & sound closet, R.O.T.C room -1898 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
06A	12"x12" Beige w/White Streaks VFT	1,900	SF	224/226 (Under HA 25A & 26A -1898 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07A	9"x9" Gray w/White & Black Streaks VFT Mastic	2,250	SF	Rooms 121, 123, 125, 129, 228, 229 all under new HA	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				(under carpet, 422 (under carpet) & sound closet, R.O.T. C room -1898 Bldg.										
08A	12"x12" Beige w/White Streaks VFT Mastic	1,900	SF	224/226, (Under HA 25A & 26A) 320, 328 - 1898 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09A	12"x12" Flesh VFT (ABATED)			Room 212 - 1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
100 A	Terrazzo	1,500	SF	Landing between 1898 and 1915 Buildings, First Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
100A	12"x12" Solid Maroon VFT Mastic	15	SF	Lunchroom closet (NE corner)- 1938	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101 A	Terrazzo	1,500	SF	Stairs and Landings - 1938	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
101A	Green Linoleum	200	SF	Room 200L (Fire Escape passage) - 1898 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102A	Green Linoleum Mastic	200	SF	Room 200L(Fire Escape passage) - 1898 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103A	Grey Linoleum (Abated)			Room 324 - 1898 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
104A	Grey Linoleum Mastic (Abated)			Room 324 - 1898 Bldg.	ABATED	MISC								
105A	9"x9" Brown w/ White VFT (Abated)	900		Room 233 (231) - 1898 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
106A	9"x9" Brown w/ White VFT Mastic (Abated)	900		Room 233 (231) - 1898 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
107A	12"x12" Black with white specks VFT (Abated)	500		3rd floor corridor between room 314 & 316 - 1915 Bldg	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
108A	12"x12" Black with white specks VFT MASTIC (Abated)	500		3rd floor corridor between rooms 314 & 316 - 1915 Bldg	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
109A	12"x12" White with black & gray specks VFT (Abated)	3,900		Assembly hall & south vestibule,	ABATED	MISC						Any remaining friable ACBM or friable		

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Rooms 115 & Prep-Room, 117/119, 215, 335, 337, 1st floor corridor between 115-119 - 1915 Bldg.								suspect ACBM		
10A	12"x12" Flesh VFT Mastic (ABATED)			Room 212 - 1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
110A	12"x12" White with black & gray specks VFT MASTIC (Abated)	4,900		Assembly hall & south vestibule, Rooms 115 & Prep-Room, 117/119, 215, 335, 337, 1st floor corridor between 115-119 - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
111A	12"x12" Red speckled VFT (Abated)	1,500		Assembly hall & south vestibule, 1st floor corridor between 115-119 -1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
112A	12"x12" Red VFT MASTIC (Abated)	1,500		Assembly hall & south vestibule, 1st floor corridor between 115-119 -1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
113A	12"x12" White with black & gray specks VFT (Abated)	2,500		1st floor corridors, 135 and women's toilet across 135 - 1898 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
114A	12"x12" White with black & gray specks VFT MASTIC (Abated)	1,800		1st floor corridors, 135 and women's toilet across 135 - 1898 Bldg.	ABATED	MISC						ACBM with the potential for damage		
115A	12"x12" Red speckled VFT (Abated)	300		1st floor corridor -1898 Bldg	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
116A	12"x12" Red speckled VFT MASTIC (Abated)	300		1st floor corridor -1898 Bldg	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
117	Fire doors	16	EA	Assembly hall, stage, projector room, and balcony	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	12"x12" offwhite w/ light grey & grey	900	SF	Assembly hall stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	specks VFT											potential for damage		
118A	12"x12" oof white w/ light gray and gray specks VFT MASTIC	900	SF	Assembly hall stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119	Decorative plaster	4,000	SF	Assembly hall, NW lobby of auditorium, assembly hall balcony	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11A	Light Brown Linoleum	50	SF	Room 229 Vault -1898 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
120	12"x12" tan w/ white and light brown specks VFT (Abated)	450		Room 302 -1938 Bldg	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
120A	12"x12" tan w/ white and light brown specks VFT MASTIC (Abated)			Room 302 -1938 Bldg	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
121	Carpet MASTIC	4,600	SF	rooms 136, 138, library -1915 Bldg 232, media center	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
122	Pyroboard	200	SF	Attic	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
123	12"x12" off white with grey specks VFT - Abated			Main office	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
123A	12"x12" off white w/ grey specks VFT MASTIC (ABATED)			Main office	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
124	Carpet MASTIC	1,300	SF	Room 111, 112, 113, addition 1938	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
125	Carpet MASTIC	2,000	SF	Room 229, 227 (removed), 422 (removed), - Addition 1898	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
126	12"x12" tan w/ white specks VFT (Abated)			Room 304 -1938 Bldg	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
126A	12"x12" tan w/ white specks VFT MASTIC (Abated)	750		Room 304 -1938 Bldg	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
127	12"x12" tan w/ white and light brown specks VFT (ABATED)			Room 126- Addition 1898	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
127A	12"x12" tan w/ white and light brown specks VFT MASTIC (ABATED)			Room 126- addition 1898	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
128	12"x12" tan w/ light brown and white specks VFT (ABATED)			Room 314 & 136-addition 1915	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
128A	12"x12" tan w/ light brown and white specks VFT MASTIC (ABATED)			Room 314 & 136-addition 1915	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
129	12"x12" Brown wood grain VFT	50	SF	Women faculty across from room 135	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
129A	12"x12" brown wood grain VFT MASTIC	50	SF	Women faculty across from room 135	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12A	Grey w/Orange & Black Streaks Linoleum (Abated)				ABATED	MISC								
130	Drywall system	1,200	SF	Room 102, 101A, 105, -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
131	9"x9" light green w/ black and white striations VFT	2,300	SF	ROTC 090 -1898 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
131A	9"x9" light green w/ black and white striations VFT MASTIC	2,300	SF	ROTC 090 -1898 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
132	9"x9" light green w/ black and white striations VFT	1,000	SF	Room 116B Storage (gym) -1915 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
132A	9"x9" light green w/ black and white striations VFT MASTIC	1,000	SF	Room 116B Storage (gym) -1915 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
133	12"x12" white w/ tan specks VFT	300	SF	1st floor gym office by 116B - 1915 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
133A	12"x12 white w/ tan specks VFT MASTIC	300	SF	1st floor gym office by 116B - 1915 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	12 x 12 Dark Gray w/ specks	7,500	SF	Assembly hall, 231, 215, 314, 422, 426 and 428 -1915 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
135	12 x 12 Dark Gray w/ specks mastic	7,500	SF	Assembly hall, Room 231, 215, 314, 317, 318, 330, 332, 334, 422, 426 and 428 - 1915 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
136	12 x 12 Gray w/ Specks VFT	10,000	SF	1st, 2nd, 3rd, 4th Floor corridors - 1915 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
137	12 x 12 Gray w/ specks VFT Mastic	10,000	SF	1st, 2nd, 3rd, 4th Floor corridors - 1915 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
138	12 x 12 White w/ Specks VFT	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
139	12 x 12 White w/ specks VFT mastic	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
140	12 x 12 Red w/ Specks VFT	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
141	12 x 12 red w/ specks VFT mastic	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
142	12 x 12 Dark gray w/ specks VFT	10,000	SF	Room 209, 302, 304, Lunchroom, serving room, old teacher lunch room - 1938 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
143	12 x 12 dark gray w/ specks VFT Mastic	10,000	SF	Room 209, 302, 304, Lunchroom, serving room, old teacher lunch room - 1938 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
144	12 x 12 Gray w/ Specks VFT	10,000	SF	1st, 2nd, 3rd floor corridors - 1938 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
145	12 x 12 gray w/ Specks VFT Mastic	10,000	SF	1st, 2nd, 3rd floor corridors - 1938 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
146	12 x 12 White w/ specks VFT	15,000	SF	1st, 2nd, 3rd floor	ASSUMED	MISC	N	NONE	0			ACBM with the		LOW

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg								potential for damage		
147	12 x 12 white w/ specks VFT Mastic	15,000	SF	1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
148	12 x 12 Red w/ specks VFT	15,000	SF	1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
149	12 x 12 Red w/ Specks VFT Mastic	15,000	SF	1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
14A	Plaster Wall & Plaster Ceiling	60,000	SF	Throughout - 1898 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
150	12 x 12 Dark gray w/ specks VFT	10,000	SF	Rooms 100E, 123, 125, 129, 220, 226, 228, 325, 328, 328A, 335, 337, 432 -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
151	12 x 12 Dark gray w/ specks VFT Mastic	10,000	SF	Rooms 100E, 123, 125, 129, 220, 226, 228, 325, 328, 328A, 335, 337, 432 -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
152	12 x 12 Gray w specks VFT	7,500	SF	1st, 2nd, 3rd, 4th floor corridor. room 231 -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
153	12 x 12 gray w/ specks VFT Mastic	7,500	SF	1st, 2nd, 3rd, 4th floor corridor. room 231 -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
154	12 x 12 White w/ specks VFT	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325,	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				328, 328A, 335, 337, 432, -1898 Bldg										
155	12 x 12 White w/ specks VFT Mastic	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432, -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
156	12 x 12 Red w/ specks VFT	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432, -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
157	12 x 12 Red w/ specks VFT Mastic	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432, -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
158	2' x 2' ceiling tile	30,000	SF	1st, 2nd, 3rd floor corridor	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
159	Black w/ Speaks VFT	840	SF	Room 122, 124 & 126 -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
159A	Black w/ Speaks VFT Mastic	840	SF	Room 122, 124 & 126 -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		
160	White w/ Speaks VFT	840	SF	Room 122, 124 & 126 -1898 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
160A	White w/ Speaks VFT Mastic	840	SF	Room 122, 124 & 126 - Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		
161	Beige W/ Speaks VFT	840	SF	Room 113D, 122, 124 & 126 - 1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		
161A	Beige W/ Speaks VFT Mastic	840	SF	Room 122, 124 & 126 -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		
162	Counter & tabletops	1,200	SF	room 122 & 126 -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		
163	Fume Hood	20	SF	room 122 & 126 -1898 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		
16A	Light Brown Linoleum Mastic	50	SF	Room 229 Vault	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.										
37A	12"x12" White w/Black Streaks VFT	700	SF	Room 235 Bldg. - 1915 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38A	12"x12" White w/Black Streaks VFT Mastic	700	SF	Room 235 Bldg. -1915 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39A	12"x12" Beige VFT (ABATED)			Room 335 - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
40A	12"x12" Beige VFT Mastic (ABATED)			Room 335 - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
41A	12"x12" Beige w/Tan Spots VFT (ABATED)			Rooms 115 & 117 - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
42A	12"x12" Beige w/Tan Spots VFT Mastic (ABATED)			Rooms 115 & 117 - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
43A	9"x9" Brown w/Black Streaks VFT (ABATED)			1st Floor Auditorium - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
44A	9"x9" Brown w/Black Streaks VFT Mastic (ABATED)			1st Floor Auditorium - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
45A	12"x12" Tan w/Tan Spots VFT (Abated)	3,600		1st Floor Corridor - 1915 Bldg. (abated)	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
46A	12"x12" Tan w/Tan Spots VFT Mastic (abated)	3,600		1st Floor Corridor - 1915 Bldg. (Abated)	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
49A	12"x12" Cream VFT- (ABATED)			Stage - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
50A	12"x12" Cream VFT Mastic -(ABATED)			Stage - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
51A	9"x9" Maroon VFT (ABATED)			1st Floor Gym Vestibule - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
52A	9"x9" Maroon VFT Mastic (ABATED)			1st Floor Gym Vestibule - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
53A	9"x9" Black VFT (ABATED)			1st Floor Gym Vestibule - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
54A	9"x9" Black VFT Mastic (ABATED)			1st Floor Gym Vestibule - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
55A	12"x 12" Tan w/Tan Streaks VFT (Pink)	1,000	SF	Room 317, 317A - 1915 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
56A	12"x 12" Red w/Tan Streaks VFT Mastic (Pink)	1,000	SF	Room 317, 317A - 1915 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57A	9"x9" Black w/White Streaks VFT (abated)	500		3rd Floor Corridor between Rooms 314 & 318 - 1915 Bldg. (under HA107A & 108A) (abated)	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
58A	9"x9" Black w/White Streaks VFT Mastic (abated)	500		3rd Floor Corridor between Rooms 314 & 318 - 1915 Bldg. (under HA107A & 108A) (abated)	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
59A	12"x12" Peach VFT (abated)	3,500		Rooms: 209 (painted black) ; 1st, 2nd & 3rd Floor Corridors - 1938 Bldg. (abated)	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
60A	12"x12" Peach VFT Mastic (abated)	3,500		Rooms: 209 (painted black) ; 1st, 2nd & 3rd Floor Corridors - 1938 Bldg. (abated)	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
61A	12"x12" Black VFT (abated)	200		1st, 2nd & 3rd Floor Corridors - 1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
62A	12"x12" Black VFT Mastic (abated)	200		1st, 2nd & 3rd Floor Corridors - 1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
65A	12"x12" Gray VFT (abated)			Room 304 - 1938 Bldg.	ABATED									
66A	12"x12" Gray VFT Mastic (abated)			Room 304 - 1938 Bldg.	NO_ACBM									
67A	12"x12" Gray w/White & Brown Streaks VFT	400	SF	Rooms 207 - 1938 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
68A	12"x12" Gray w/White & Brown Streaks VFT Mastic	400	SF	Rooms 207 - 1938 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69A	9"x9" Black VFT	10	SF	Storage Room (200E) across Room 213 -1938	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.										
70A	9"x9" Black VFT Mastic	10	SF	Storage Room (200E) across Room 213 -1938 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71A	9"x9" Gray w/Red & White VFT	2,000	SF	Room 113, 112, 111 (all areas under carpet) -1938 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72A	9"x9" Gray w/Red & White VFT Mastic	690	SF	Room 113, 112, 111 (all areas under carpet) -1938 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73A	12"x12" Tan w/Brown & Gray Streaks VFT	1,300	SF	Rooms 109 - 1938 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
74A	12"x12" Tan w/Brown & Gray Streaks VFT Mastic	1,300	SF	Rooms 109 - 1938 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75A	12"x12" Black w/White Streaks VFT - Removed			Room 112 (Under Carpet) - 1938 Bldg.	NO_ACBM									
76A	12"x12" Black w/White Streaks VFT Mastic - Removed			Room 112 (Under Carpet) - 1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		Low
77A	9"x9" Tan VFT (abated)	400		Basement Lunch room lockers (women 010D) -1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
78A	9"x9" Tan VFT Mastic (abated)	400		Basement Lunch room lockers (women 010D) -1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
79A	12"x12" White VFT (abated)	750		Kitchen Dishwashing Room (not observed), Teacher's Lunchroom (Not Observed), & Kitchen Office - 1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
80A	12"x12" White VFT Mastic (abated)	750		Kitchen Dishwashing Room (not observed), Teacher's Lunchroom (Not Observed), & Kitchen Office - 1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
81A	12"x12" Red VFT (abated)	3,000		Lunchrooms #1 &	ABATED	MISC						Any remaining friable		

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				#2, Serving Line, Kitchen - 1938 Bldg.								ACBM or friable suspect ACBM		
82A	12"x12" Red VFT Mastic (abated)	3,000		Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
83A	12"x12" Blue VFT (abated)	3,000		Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
84A	12"x12" Blue VFT Mastic (abated)	3,000		Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
85A	Cardboard Pipe Insulation	130	LF	Basement: Teacher's Lunchroom, Serving Line, Above Ceiling in Kitchen - 1938 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
86A	MJP E/F/V on Cardboard Pipe Insulation	18	LF	Basement: Teacher's Lunchroom, Lunchrooms 1 & 2, Serving Line, Above Ceiling in Kitchen - 1938 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
87A	Grey, Black, Orange & Marble Linoleum (abated)	650		Room 330 - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
88A	Grey, Black, Orange & Marble Linoleum Mastic (abated)	650		Room 330 - 1915 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
89A	Brown Linoelum	1,000	SF	Auditorium Balcony - 1915 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90A	Brown Linoelum Mastic	1,000	SF	Auditorium Balcony - 1915 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91A	12"x12" Green VFT - Removed			Room 207 - 1938 Bldg.	NO_ACBM									
92A	12"x12" Green VFT Mastic - Removed			Room 207 - 1938 Bldg.	NO_ACBM									
93A	12"x12" Beige VFT (under new HA)	800	SF	Room 109 - 1938 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
94A	12"x12" Beige VFT Mastic (under new HA)	800	SF	Room 109 - 1938 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
97A	12"x12" Solid Black VFT	15	SF	Lunchroom closet (NE corner) -1938 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
98A	12"x12" Solid Black VFT Mastic	15	SF	Lunchroom closet	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				(NE corner) -1938 Bldg								potential for damage		
99A	12"x12" Solid Maroon VFT	15	SF	Lunchroom closet (NE corner) -1938 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CCA106	MJP on Fiberglass Pipe Insulation (ABATED)			Room 122, & 126	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
CCA53	Cardboard Pipe Insulation	250	LF	Attic, Rm 228 NW closet - 1898 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
CCA54	MJP on Cardboard Pipe Insulation	40	LF	Attic - 1898 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Boiler Duct Packing Insulation	50	SF	Boiler Room - 1898 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1000	2'x4' white ceiling tile	90,000	SF	Classrooms on 1st, 2nd, 3rd floors, 1st, 2nd, 3rd fl halls -1898 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1001	2'x2' white ceiling tile			GYM, 1,2, and 3 floor corridors -1915 BLD	NO_ACBM	MISC								
HA-1002	1'x1' white ceiling tile with uniform holes			rm. 322	NO_ACBM	MISC	Y							
HA-1003	Glue for 1'x1' white ceiling tile with uniform hol			rm. 322	NO_ACBM	MISC	N							
HA-1004	1'x1' white fissured ceiling tile	15,000	SF	classrooms on 4th, 3rd, 2nd, 1st -1898 BLDg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1005	Glue for 1'x1' wh, fissured tile	27,000	SF	classrooms on 4th, 3rd, 2nd, 1st -1898 BLDg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1006	12x12 Black w/white specks VFT	2,500	SF	Rooms 120, 122 (Abated), 124 (Abated), 126 (Abated), 220, 320, 325, 328, 328A -1898 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1006A	12x12 Black w/white specks VFT Mastic	2,500	SF	Rooms 120, 122 (Abated), 124 (Abated), 126 (Abated), 220, 320, 325, 328, 328A -1898 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1007	12x12 White w/black & gray specks VFT	2,900	SF	Rooms 120, 122 (Abated), 124	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				(Abated), 126 (Abated), 220, 320, 325, 328, 328A -1898 Bldg										
HA-1007A	12x12 White w/black & gray specks VFT Mastic	2,900	SF	Rooms 120, 122 (Abated), 124 (Abated), 126 (Abated), 220, 320, 325, 328, 328A -1898 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1008	12x12 Tan w/brown & tan specks VFT	2,600	SF	Rooms 120, 122 (Abated), 124 (Abated), 126 (Abated), 220, 320, 325, 328, 328A -1898 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1008A	12x12 Tan w/brown & tan specks VFT Mastic	2,600	SF	Rooms 120, 122 (Abated), 124 (Abated), 126 (Abated), 220, 320, 325, 328, 328A -1898 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1009	2x2 Ceiling Tile	1,500	SF	Rooms 325, 323 -1898 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1010	12x12 Black w/white specks VFT	1,800	SF	Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1010A	12x12 Black w/white specks VFT Mastic	1,800	SF	Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1011	12x12 Tan w/brown & tan specks VFT	1,500	SF	Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1011A	12x12 Tan w/brown & tan specks VFT Mastic	1,500	SF	Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1012	12x12 Black VFT	24	SF	3rd Floor entry area by Rms 342 and 340 -1915 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1012A	12x12 Black VFT Mastic	24	SF	3rd Floor entry area by Rms 342 and 340	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				-1915 Bldg										
HA-1013	2x2 Ceiling Tile	1,000	SF	Rooms 340, 342 -1915 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1014	12x12 Brown w/White & Brown streaks VFT (Abated)	1,200		2nd & 3rd Floor auditorium balcony -1915 Bldg	ABATED	MISC						ACBM with the potential for damage		
HA-1014A	12x12 Brown w/White & Brown streaks VFT Mastic (Abated)	1,200		2nd & 3rd Floor auditorium balcony -1915 Bldg	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
HA-1015	9x9 Brown w/white & orange streaks VFT (Abated)	100		2nd Floor Library Storage -1915 Bldg	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
HA-1015A	9x9 Brown w/white & orange streaks VFT Mastic (Abated)	100		2nd Floor Library Storage -1915 Bldg	ABATED	MISC			0			Any remaining friable ACBM or friable suspect ACBM		
HA-1016	12x12 Lt. Gray speckled VFT (Abated)	3,200		Rm 136 closet, main office and all associated rooms in main office	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
HA-1016A	12x12 Lt. Gray speckled VFT Mastic (Abated)	3,200		Rm 136 closet, main office and all associated rooms in main office	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
HA-1017	Spray on fire-proofing	2,800	SF	Basement auditorium plenum chamber, basement corridor by North entry door to auditorium plenum chamber	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1018	12x12 Black w/white specks VFT	1,600	SF	Rooms 102, 105, 205, 212, 305/309 -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1018A	12x12 Black w/white specks VFT Mastic	1,600	SF	Rooms 102, 105, 205, 212, 305/309 -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1019	12x12 White w/black & gray specks VFT	1,800	SF	Rooms 102, 105, 205, 212, 305/309 -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1019A	12x12 White w/black & gray specks VFT Mastic	1,800	SF	Rooms 102, 105, 205, 212, 305/309 -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1020	12x12 Tan w/brown & tan specks VFT	1,800	SF	Rooms 102, 105, 205, 212, 305/309	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				-1938 Bldg										
HA-1020A	12x12 Tan w/brown & tan specks VFT Mastic	1,800	SF	Rooms 102, 105, 205, 212, 305/309 -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1021	Mastic Pucks	2,500	SF	Gym 201 -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1022	12x12 Beige w/brown, white, blue & black specks VFT	1,100	SF	Room 101A (health office) -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1022A	12x12 Beige w/brown, white, blue & black specks VFT Mastic	1,100	SF	Room 101A (health office) -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1023	12x12 Purple VFT	20	SF	Room 101A (health office) -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1023A	12x12 Purple VFT Mastic	20	SF	Room 101A (health office) -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1024	12x12 Peach w/blue & cream specks VFT	40	SF	Room 101A (health office) -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1024A	12x12 Peach w/blue & cream specks VFT Mastic	40	SF	Room 101A (health office) -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1025	2x2 Ceiling Tile	900	SF	Room 101A (health office) -1938 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1026	Carpet Mastic	250	SF	Room 101A (health office) north end of office -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1027	1x1 Ceiling Tile w/ white grooves & holes	14,000	SF	Basement lunchroom, teacher's lunch room, serving line room, kitchen -1938 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1027A	1x1 Ceiling Tile w/ white grooves & holes pucks	14,000	SF	Basement lunchroom, teacher's lunch room, serving line room, kitchen -1938 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
I	MJP on Fiberglass Pipe Insulation	10	SF	Pump Room - 1898 Bldg.	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/5/2022
Inspector Name David Avila
100-11093 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
006	
009	
01A	
02A	
03A	
04A	
05A	
06A	
07A	
08A	
09A	
100 A	
100A	
101 A	
101A	
102A	
103A	
104A	
105A	
106A	
107A	
108A	
109A	
10A	

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
110A	
111A	
112A	
113A	
114A	
115A	
116A	
117	
118	
118A	
119	
11A	
120	
120A	
121	
122	
123	
123A	
124	
125	
126	
126A	
127	
127A	
128	
128A	
129	
129A	
12A	

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
130	
131	
131A	
132	
132A	
133	
133A	
134	
135	
136	
137	
138	
139	
140	
141	
142	
143	
144	
145	
146	
147	
148	
149	
14A	
150	
151	
152	
153	
154	

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
155	
156	
157	
158	
159	
159A	
160	
160A	
161	
161A	
162	
163	
16A	
17A	
18A	
19A	
20A	
21A	
22A	
23A	
24A	
25A	
26A	
27A	
28A	
31A	
32A	
33A	
34A	

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
35A	
36A	
37A	
38A	
39A	
40A	
41A	
42A	
43A	
44A	
45A	
46A	
49A	
50A	
51A	
52A	
53A	
54A	
55A	
56A	
57A	
58A	
59A	
60A	
61A	
62A	
65A	
66A	
67A	

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
68A	
69A	
70A	
71A	
72A	
73A	
74A	
75A	
76A	
77A	
78A	
79A	
80A	
81A	
82A	
83A	
84A	
85A	
86A	
87A	
88A	
89A	
90A	
91A	
92A	
93A	
94A	
97A	
98A	

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
99A	
CCA106	
CCA53	
CCA54	
H	
HA-1000	
HA-1001	
HA-1002	
HA-1003	
HA-1004	
HA-1005	
HA-1006	
HA-1006A	
HA-1007	
HA-1007A	
HA-1008	
HA-1008A	
HA-1009	
HA-1010	
HA-1010A	
HA-1011	
HA-1011A	
HA-1012	
HA-1012A	
HA-1013	
HA-1014	
HA-1014A	
HA-1015	
HA-1015A	

Chicago Public Schools

School Lakeview High School Unit 46211 Building ID 1430

Address 4015 N. Ashland Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
HA-1016	
HA-1016A	
HA-1017	
HA-1018	
HA-1018A	
HA-1019	
HA-1019A	
HA-1020	
HA-1020A	
HA-1021	
HA-1022	
HA-1022A	
HA-1023	
HA-1023A	
HA-1024	
HA-1024A	
HA-1025	
HA-1026	
HA-1027	
HA-1027A	
I	

Table II

Management Planner's Review

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
006	Aircell Pipe Insulation	80	LF	1st Floor Darkroom, Room 110, 328 (Abated), Lunchroom Storage under Stairs, LRS #2 Bathroom Chase - 1938 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
009	MJP on Aircell Pipe Insulation	16	LF	1st Floor Darkroom, Room 110, Lunchroom Storage under Stairs, LRS #2 Bathroom Chase - 1938 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
01A	9"x9" Gray VFT	4,550	SF	Rooms: 232 (Library - Under Carpet/plywood substrate), 334, 325, 337, MDF Rm 232A -1915 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02A	12"x12" Beige w/White Spots VFT (ABATED)			Rooms 119, 122, 124, 215, 220, 222 - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
03A	9"x9" Gray VFT Mastic	4,550	SF	Rooms: 232 (Library - Under Carpet/plywood substrate), 334 325 and 337(under new HA), MDF Rm 232A -1915 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04A	12"x12" Beige w/White Spots VFT Mastic (ABATED)			Rooms 119, 122, 124, 215, 220, 222 - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
05A	9"x9" Gray w/White & Black Streaks VFT	2,250	SF	Rooms 121, 123, 125, 129, 228, 229 (under carpet, 422 (under carpet) Under New HA & sound closet, R.O.T. C room -1898 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	12"x12" Beige w/White Streaks VFT	1,900	SF	224/226 (Under HA 25A & 26A -1898 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07A	9"x9" Gray w/White & Black Streaks VFT Mastic	2,250	SF	Rooms 121, 123, 125, 129, 228, 229 all under new HA (under carpet, 422 (under carpet) & sound closet, R.O.T.C room -1898 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08A	12"x12" Beige w/White Streaks VFT Mastic	1,900	SF	224/226, (Under HA 25A & 26A) 320, 328 - 1898 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09A	12"x12" Flesh VFT (ABATED)			Room 212 - 1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
100 A	Terrazzo	1,500	SF	Landing between 1898 and 1915 Buildings, First Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100A	12"x12" Solid Maroon VFT Mastic	15	SF	Lunchroom closet (NE corner)- 1938	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101 A	Terrazzo	1,500	SF	Stairs and Landings - 1938	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
101A	Green Linoleum	200	SF	Room 200L (Fire Escape passage) - 1898 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102A	Green Linoleum Mastic	200	SF	Room 200L(Fire Escape passage) - 1898 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103A	Grey Linoleum (Abated)			Room 324 - 1898 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
104A	Grey Linoleum Mastic (Abated)			Room 324 - 1898 Bldg.	Abated	MISC					
105A	9"x9" Brown w/ White VFT (Abated)	900		Room 233 (231) - 1898 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
106A	9"x9" Brown w/ White VFT Mastic (Abated)	900		Room 233 (231) - 1898 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
107A	12"X12" Black with white specks VFT (Abated)	500		3rd floor corridor between room 314 & 316 - 1915 Bldg	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
108A	12"x12" Black with white specks VFT MASTIC (Abated)	500		3rd floor corridor between rooms 314 & 316 - 1915 Bldg	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
109A	12"x12" White with black & gray specks VFT (Abated)	3,900		Assembly hall & south vestibule, Rooms 115 & Prep-Room, 117/119, 215, 335, 337, 1st floor corridor between 115-119 - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
10A	12"x12" Flesh VFT Mastic (ABATED)			Room 212 - 1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
110A	12"x12" White with black & gray specks VFT MASTIC (Abated)	4,900		Assembly hall & south vestibule, Rooms 115 & Prep-Room, 117/119, 215, 335, 337, 1st floor corridor between 115-119 - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
111A	12"x12" Red speckled VFT (Abated)	1,500		Assembly hall & south vestibule, 1st floor corridor between 115-119 -1915 Bldg	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
112A	12"x12" Red VFT MASTIC (Abated)	1,500		Assembly hall & south vestibule, 1st floor corridor between 115-119 -1915 Bldg	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
113A	12"x12" White with black & gray specks VFT (Abated)	2,500		1st floor corridors, 135 and women's toilet across 135 - 1898 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
114A	12"x12" White with black & gray specks VFT MASTIC (Abated)	1,800		1st floor corridors, 135 and women's toilet across 135 - 1898 Bldg.	Abated	MISC				6 ACBM with the potential for damage	
115A	12"x12" Red specked VFT (Abated)	300		1st floor corridor -1898 Bldg	Abated	MISC				7 Any remaining friable ACBM or friable	

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
116A	12"x12" Red speckled VFT MASTIC (Abated)	300		1st floor corridor -1898 Bldg	Abated	MISC					suspect ACBM
117	Fire doors	16	EA	Assembly hall, stage, projector room, and balcony	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
118	12"x12" offwhite w/ light grey & grey specks VFT	900	SF	Assembly hall stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118A	12"x12" oof white w/ light gray and gray specks VFT MASTIC	900	SF	Assembly hall stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	Decorative plaster	4,000	SF	Assembly hall, NW lobby of auditorium, assembly hall balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	Light Brown Linoleum	50	SF	Room 229 Vault -1898 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	12"x12" tan w/ white and light brown specks VFT (Abated)	450		Room 302 -1938 Bldg	Abated	MISC					7 Any remaining friable ACBM or friable suspect ACBM
120A	12"x12" tan w/ white and light brown specks VFT MASTIC (Abated)			Room 302 -1938 Bldg	Abated	MISC					7 Any remaining friable ACBM or friable suspect ACBM
121	Carpet MASTIC	4,600	SF	rooms 136, 138,library -1915 Bldg 232, media center	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	Pyroboard	200	SF	Attic	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	12"x12" off white with grey specks VFT - Abated			Main office	Abated	MISC					7 Any remaining friable ACBM or friable suspect ACBM
123A	12"x12" off white w/ grey specks VFT MASTIC (ABATED)			Main office	Abated	MISC					7 Any remaining friable ACBM or friable suspect ACBM
124	Carpet MASTIC	1,300	SF	Room 111, 112, 113, addition 1938	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125	Carpet MASTIC	2,000	SF	Room 229, 227(removed), 422 (removed), - Addition 1898	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
126	12"x12" tan w/ white specks VFT (Abated)			Room 304 -1938 Bldg	Abated	MISC					7 Any remaining friable ACBM or friable suspect ACBM
126A	12"x12" tan w/ white specks VFT MASTIC (Abated)	750		Room 304 -1938 Bldg	Abated	MISC					7 Any remaining friable ACBM or friable suspect ACBM
127	12"x12" tan w/ white and light brown specks VFT (ABATED)			Room 126- Addition 1898	Abated	MISC					7 Any remaining friable ACBM or friable suspect ACBM
127A	12"x12" tan w/ white and light brown specks VFT MASTIC (ABATED)			Room 126- addition 1898	Abated	MISC					7 Any remaining friable ACBM or friable suspect ACBM
128	12"x12" tan w/ light brown and white specks VFT (ABATED)			Room 314 & 136- addition 1915	Abated	MISC					7 Any remaining friable ACBM or friable suspect ACBM
128A	12"x12" tan w/ light brown and white specks VFT			Room 314 & 136- addition 1915	Abated	MISC					7 Any remaining friable ACBM or friable

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	MASTIC (ABATED)									suspect ACBM	
129	12"x12" Brown wood grain VFT	50	SF	Women faculty across from room 135	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
129A	12"x12" brown wood grain VFT MASTIC	50	SF	Women faculty across from room 135	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12A	Grey w/Orange & Black Streaks Linoleum (Abated)				Abated	MISC					
130	Drywall system	1,200	SF	Room 102, 101A, 105, -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131	9"x9" light green w/ black and white striations VFT	2,300	SF	ROTC 090 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131A	9"x9" light green w/ black and white striations VFT MASTIC	2,300	SF	ROTC 090 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132	9"x9" light green w/ black and white striations VFT	1,000	SF	Room 116B Storage (gym) -1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132A	9"x9" light green w/ black and white striations VFT MASTIC	1,000	SF	Room 116B Storage (gym) -1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
133	12"x12" white w/ tan specks VFT	300	SF	1st floor gym office by 116B - 1915 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
133A	12"x12 white w/ tan specks VFT MASTIC	300	SF	1st floor gym office by 116B - 1915 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	12 x 12 Dark Gray w/ specks	7,500	SF	Assembly hall, 231, 215, 314, 422, 426 and 428 -1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	12 x 12 Dark Gray w/ specks mastic	7,500	SF	Assembly hall, Room 231, 215, 314, 317, 318, 330, 332, 334, 422, 426 and 428 - 1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	12 x 12 Gray w/ Specks VFT	10,000	SF	1st, 2nd, 3rd, 4th Floor corridors - 1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	12 x 12 Gray w/ specks VFT Mastic	10,000	SF	1st, 2nd, 3rd, 4th Floor corridors - 1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	12 x 12 White w/ Specks VFT	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
139	12 x 12 White w/ specks VFT mastic	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	12 x 12 Red w/ Specks VFT	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
141	12 x 12 red w/ specks VFT mastic	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142	12 x 12 Dark gray w/ specks VFT	10,000	SF	Room 209, 302, 304, Lunchroom, serving room, old teacher lunch room - 1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143	12 x 12 dark gray w/ specks VFT Mastic	10,000	SF	Room 209, 302, 304, Lunchroom, serving room, old teacher lunch room - 1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	12 x 12 Gray w/ Specks VFT	10,000	SF	1st, 2nd, 3rd floor corridors - 1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	12 x 12 gray w/ Specks VFT Mastic	10,000	SF	1st, 2nd, 3rd floor corridors - 1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
146	12 x 12 White w/ specks VFT	15,000	SF	1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
147	12 x 12 white w/ specks VFT Mastic	15,000	SF	1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148	12 x 12 Red w/ specks VFT	15,000	SF	1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149	12 x 12 Red w/ Specks VFT Mastic	15,000	SF	1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14A	Plaster Wall & Plaster Ceiling	60,000	SF	Throughout - 1898 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
150	12 x 12 Dark gray w/ specks VFT	10,000	SF	Rooms 100E, 123, 125, 129, 220, 226, 228, 325, 328, 328A, 335, 337, 432 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151	12 x 12 Dark gray w/ specks VFT Mastic	10,000	SF	Rooms 100E, 123, 125, 129, 220, 226, 228, 325, 328, 328A, 335, 337, 432 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152	12 x 12 Gray w specks VFT	7,500	SF	1st, 2nd, 3rd, 4th floor corridor. room 231 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153	12 x 12 gray w/ specks VFT Mastic	7,500	SF	1st, 2nd, 3rd, 4th floor corridor. room 231 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
154	12 x 12 White w/ specks VFT	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, 100E,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg							
155	12 x 12 White w/ specks VFT Mastic	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
156	12 x 12 Red w/ specks VFT	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
157	12 x 12 Red w/ specks VFT Mastic	15,000	SF	1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
158	2' x 2' ceiling tile	30,000	SF	1st, 2nd, 3rd floor corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159	Black w/ Speaks VFT	840	SF	Room 122, 124 & 126 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159A	Black w/ Speaks VFT Mastic	840	SF	Room 122, 124 & 126 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
160	White w/ Speaks VFT	840	SF	Room 122, 124 & 126 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
160A	White w/ Speaks VFT Mastic	840	SF	Room 122, 124 & 126 - Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
161	Beige W/ Speaks VFT	840	SF	Room 113D, 122, 124 & 126 - 1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
161A	Beige W/ Speaks VFT Mastic	840	SF	Room 122, 124 & 126 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
162	Counter & tabletops	1,200	SF	room 122 & 126 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
163	Fume Hood	20	SF	room 122 & 126 -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16A	Light Brown Linoleum Mastic	50	SF	Room 229 Vault (under carpet) -1898 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17A	Grey w/Orange & Black Streaks Linoleum Mastic (Abated)			Rooms 426, & 428 - 1898 Bldg.	Abated	MISC					
18A	Black Laboratory Countertop	800	SF	Throughout - 1898 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19A	Black Lab Countertop	400	SF	Throughout - 1938 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20A	Black Laboratory Countertop	400	SF	Throughout - 1915 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21A	12"x12" Light Brown w/Dark Speckles VFT	1,600	SF	121 (abated), 127, Music Store Room, eng. office -1898 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22A	12"x12" Light Brown w/Dark Speckles VFT Mastic	1,600	SF	121 (abated), 127, Music Store Room, eng. office -1898 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23A	12"x12" Brown w/Dark & White Streaks VFT (ABATED)			Room 328A - 1898 Bldg.	Abated	MISC					
24A	12"x12" Brown w/Dark & White Streaks VFT Mastic (ABATED)			Room 328A - 1898 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
25A	12"x12" Tan w/Dark Streaks VFT	1,900	SF	Rooms: 224 & 226 - 1898 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26A	12"x12" Tan w/Dark Streaks VFT Mastic	1,900	SF	Rooms: 224 & 226 - 1898 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27A	12"x12" Off-White w/Blue Streaks VFT - Abated			1st Floor Teacher's Toilet -1989 Bldg	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
28A	12"x12" Off-White w/Blue Streaks VFT Mastic - Abated			1st Floor Teacher's Toilet -1898 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
31A	12"x12" Peach VFT (abated)			Room 314 & 318 - 1915 Bldg.	Abated	MISC					
32A	12"x12" Peach VFT Mastic (abated)			Room 314 & 318 - 1915 Bldg.	Abated	MISC					
33A	12"x12" White VFT (abated)			Room 332 - 1915 Bldg.	Abated	MISC					
34A	12"x12" White VFT Mastic (abated)			Room 332 - 1915 Bldg.	Abated	MISC					
35A	12"x12" Brown VFT (abated)			Room 332 - 1915 Bldg.	Abated	MISC					
36A	12"x12" Brown VFT Mastic (abated)			Room 332 - 1915 Bldg.	Abated	MISC					
37A	12"x12" White w/Black Streaks VFT	700	SF	Room 235 Bldg. - 1915 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38A	12"x12" White w/Black Streaks VFT Mastic	700	SF	Room 235 Bldg. -1915 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39A	12"x12" Beige VFT (ABATED)			Room 335 - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
40A	12"x12" Beige VFT Mastic (ABATED)			Room 335 - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
41A	12"x12' Beige w/Tan Spots VFT (ABATED)			Rooms 115 & 117 - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
42A	12"x12' Beige w/Tan Spots VFT Mastic (ABATED)			Rooms 115 & 117 - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
43A	9"x9" Brown w/Black Streaks VFT (ABATED)			1st Floor Auditorium - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
44A	9"x9" Brown w/Black Streaks VFT Mastic (ABATED)			1st Floor Auditorium - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
45A	12"x12' Tan w/Tan Spots VFT (Abated)	3,600		1st Floor Corridor - 1915 Bldg. (abated)	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
46A	12"x12' Tan w/Tan Spots VFT Mastic (abated)	3,600		1st Floor Corridor - 1915 Bldg. (Abated)	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
49A	12"x12" Cream VFT- (ABATED)			Stage - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
50A	12"x12" Cream VFT Mastic -(ABATED)			Stage - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
51A	9"x9" Maroon VFT (ABATED)			1st Floor Gym Vestibule - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
52A	9"x9" Maroon VFT Mastic (ABATED)			1st Floor Gym Vestibule - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
53A	9"x9" Black VFT (ABATED)			1st Floor Gym Vestibule - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
54A	9"x9" Black VFT Mastic (ABATED)			1st Floor Gym Vestibule - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
55A	12"x 12" Tan w/Tan Streaks VFT (Pink)	1,000	SF	Room 317, 317A - 1915 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56A	12"x 12" Red w/Tan Streaks VFT Mastic (Pink)	1,000	SF	Room 317, 317A - 1915 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57A	9"x9" Black w/White Streaks VFT (abated)	500		3rd Floor Corridor between Rooms 314 & 318 - 1915 Bldg. (under HA107A & 108A) (abated)	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
58A	9"x9" Black w/White Streaks VFT Mastic (abated)	500		3rd Floor Corridor between Rooms 314 & 318 - 1915 Bldg. (under HA107A & 108A) (abated)	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
59A	12"x12" Peach VFT (abated)	3,500		Rooms: 209 (painted black) ; 1st, 2nd & 3rd Floor Corridors - 1938 Bldg. (abated)	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
60A	12"x12" Peach VFT Mastic (abated)	3,500		Rooms: 209 (painted black) ; 1st, 2nd & 3rd Floor Corridors - 1938 Bldg. (abated)	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
61A	12"x12" Black VFT (abated)	200		1st, 2nd & 3rd Floor Corridors - 1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
62A	12"x12" Black VFT Mastic (abated)	200		1st, 2nd & 3rd Floor Corridors - 1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
65A	12"x12" Gray VFT (abated)			Room 304 - 1938 Bldg.	Abated						
66A	12"x12" Gray VFT Mastic (abated)			Room 304 - 1938 Bldg.	No ACBM						
67A	12"x12" Gray w/White & Brown Streaks VFT	400	SF	Rooms 207 - 1938 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68A	12"x12" Gray w/White & Brown Streaks VFT Mastic	400	SF	Rooms 207 - 1938 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69A	9"x9" Black VFT	10	SF	Storage Room (200E) across Room 213 -1938 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70A	9"x9" Black VFT Mastic	10	SF	Storage Room (200E) across Room 213 -1938 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71A	9"x9" Gray w/Red & White VFT	2,000	SF	Room 113, 112, 111(all areas under carpet) -1938 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72A	9"x9" Gray w/Red & White VFT Mastic	690	SF	Room 113, 112, 111(all areas under carpet) -1938 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
73A	12"x12" Tan w/Brown & Gray Streaks VFT	1,300	SF	Rooms 109 - 1938 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74A	12"x12" Tan w/Brown & Gray Streaks VFT Mastic	1,300	SF	Rooms 109 - 1938 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75A	12"x12" Black w/White Streaks VFT - Removed			Room 112 (Under Carpet) - 1938 Bldg.	No ACBM						
76A	12"x12" Black w/White Streaks VFT Mastic - Removed			Room 112 (Under Carpet) - 1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
77A	9"x9" Tan VFT (abated)	400		Basement Lunch room lockers (women 010D) -1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
78A	9"x9" Tan VFT Mastic (abated)	400		Basement Lunch room lockers (women 010D) -1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
79A	12"x12" White VFT (abated)	750		Kitchen Dishwashing Room (not observed), Teacher's Lunchroom (Not Observed), & Kitchen Office - 1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
80A	12"x12" White VFT Mastic (abated)	750		Kitchen Dishwashing Room (not observed), Teacher's Lunchroom (Not Observed), & Kitchen Office - 1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
81A	12"x12" Red VFT (abated)	3,000		Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
82A	12"x12" Red VFT Mastic (abated)	3,000		Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
83A	12"x12" Blue VFT (abated)	3,000		Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
84A	12"x12" Blue VFT Mastic (abated)	3,000		Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
85A	Cardboard Pipe Insulation	130	LF	Basement: Teacher's Lunchroom, Serving Line, Above Ceiling in Kitchen - 1938 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
86A	MJP E/F/V on Cardboard Pipe Insulation	18	LF	Basement: Teacher's Lunchroom, Lunchrooms 1 & 2, Serving Line, Above Ceiling in Kitchen - 1938 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
87A	Grey, Black, Orange & Marble Linoleum (abated)	650		Room 330 - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
88A	Grey, Black, Orange & Marble Linoleum Mastic (abated)	650		Room 330 - 1915 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
89A	Brown Linoelum	1,000	SF	Auditorium Balcony - 1915 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
90A	Brown Linoelum Mastic	1,000	SF	Auditorium Balcony - 1915 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91A	12"x12" Green VFT - Removed			Room 207 - 1938 Bldg.	No ACBM						
92A	12"x12" Green VFT Mastic - Removed			Room 207 - 1938 Bldg.	No ACBM						
93A	12"x12" Beige VFT (under new HA)	800	SF	Room 109 - 1938 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94A	12"x12" Beige VFT Mastic (under new HA)	800	SF	Room 109 - 1938 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97A	12"x12" Solid Black VFT	15	SF	Lunchroom closet (NE corner) -1938 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98A	12"x12" Solid Black VFT Mastic	15	SF	Lunchroom closet (NE corner) -1938 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99A	12"x12" Solid Maroon VFT	15	SF	Lunchroom closet (NE corner) -1938 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CCA106	MJP on Fiberglass Pipe Insulation (ABATED)			Room 122, & 126	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	
CCA53	Cardboard Pipe Insulation	250	LF	Attic, Rm 228 NW closet - 1898 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
CCA54	MJP on Cardboard Pipe Insulation	40	LF	Attic - 1898 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	Boiler Duct Packing Insulation	50	SF	Boiler Room - 1898 Bldg.	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1000	2'x4' white ceiling tile	90,000	SF	Classrooms on 1st, 2nd, 3rd floors. 1st, 2nd, 3rd fl halls -1898 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1001	2'x2' white ceiling tile			GYM, 1,2, and 3 floor corridors -1915 BLD	No ACBM	MISC					
HA-1002	1'x1' white ceiling tile with uniform holes			rm. 322	No ACBM	MISC	Yes				
HA-1003	Glue for 1'x1' white ceiling tile with uniform hol			rm. 322	No ACBM	MISC	No				
HA-1004	1'x1' white fissured ceiling tile	15,000	SF	classrooms on 4th, 3rd, 2nd, 1st -1898 BLDg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1005	Glue for 1'x1' wh, fissured tile	27,000	SF	classrooms on 4th, 3rd, 2nd, 1st -1898 BLDg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1006	12x12 Black w/white specks VFT	2,500	SF	Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1006A	12x12 Black w/white specks VFT Mastic	2,500	SF	Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1007	12x12 White w/black & gray specks VFT	2,900	SF	Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				-1898 Bldg							
HA-1007A	12x12 White w/black & gray specks VFT Mastic	2,900	SF	Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1008	12x12 Tan w/brown & tan specks VFT	2,600	SF	Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1008A	12x12 Tan w/brown & tan specks VFT Mastic	2,600	SF	Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1009	2x2 Ceiling Tile	1,500	SF	Rooms 325, 323 -1898 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1010	12x12 Black w/white specks VFT	1,800	SF	Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1010A	12x12 Black w/white specks VFT Mastic	1,800	SF	Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1011	12x12 Tan w/brown & tan specks VFT	1,500	SF	Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1011A	12x12 Tan w/brown & tan specks VFT Mastic	1,500	SF	Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1012	12x12 Black VFT	24	SF	3rd Floor entry area by Rms 342 and 340 -1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1012A	12x12 Black VFT Mastic	24	SF	3rd Floor entry area by Rms 342 and 340 -1915 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1013	2x2 Ceiling Tile	1,000	SF	Rooms 340, 342 -1915 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1014	12x12 Brown w/White & Brown streaks VFT (Abated)	1,200		2nd & 3rd Floor auditorium balcony -1915 Bldg	Abated	MISC				6 ACBM with the potential for damage	
HA-1014A	12x12 Brown w/White & Brown streaks VFT Mastic (Abated)	1,200		2nd & 3rd Floor auditorium balcony -1915 Bldg	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
HA-1015	9x9 Brown w/white & orange streaks VFT (Abated)	100		2nd Floor Library Storage -1915 Bldg	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
HA-1015A	9x9 Brown w/white & orange streaks VFT Mastic (Abated)	100		2nd Floor Library Storage -1915 Bldg	Abated	MISC		0		7 Any remaining friable ACBM or friable suspect ACBM	
HA-1016	12x12 Lt. Gray speckled VFT (Abated)	3,200		Rm 136 closet, main office and all associated rooms in main office	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
HA-1016A	12x12 Lt. Gray speckled VFT Mastic (Abated)	3,200		Rm 136 closet, main office and all associated rooms in main office	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
HA-1017	Spray on fire-proofing	2,800	SF	Basement auditorium plenum chamber, basement corridor by North entry door to auditorium plenum chamber	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1018	12x12 Black w/white specks VFT	1,600	SF	Rooms 102, 105, 205, 212, 305/309 -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1018A	12x12 Black w/white specks VFT Mastic	1,600	SF	Rooms 102, 105, 205, 212, 305/309 -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1019	12x12 White w/black & gray specks VFT	1,800	SF	Rooms 102, 105, 205, 212, 305/309 -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1019A	12x12 White w/black & gray specks VFT Mastic	1,800	SF	Rooms 102, 105, 205, 212, 305/309 -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1020	12x12 Tan w/brown & tan specks VFT	1,800	SF	Rooms 102, 105, 205, 212, 305/309 -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1020A	12x12 Tan w/brown & tan specks VFT Mastic	1,800	SF	Rooms 102, 105, 205, 212, 305/309 -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1021	Mastic Pucks	2,500	SF	Gym 201 -1938 BLdg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1022	12x12 Beige w/brown, white, blue & black specks VFT	1,100	SF	Room 101A (health office) -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1022A	12x12 Beige w/brown, white, blue & black specks VFT Mastic	1,100	SF	Room 101A (health office) -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1023	12x12 Purple VFT	20	SF	Room 101A (health office) -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1023A	12x12 Purple VFT Mastic	20	SF	Room 101A (health office) -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1024	12x12 Peach w/blue & cream specks VFT	40	SF	Room 101A (health office) -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1024A	12x12 Peach w/blue & cream specks VFT Mastic	40	SF	Room 101A (health office) -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1025	2x2 Ceiling Tile	900	SF	Room 101A (health office) -1938 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1026	Carpet Mastic	250	SF	Room 101A (health office) north end of office -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-	1x1 Ceiling Tile w/ white grooves & holes	14,000	SF	Basement lunchroom, teacher's lunch	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1027				room, serving line room, kitchen -1938 Bldg							
HA-1027A	1x1 Ceiling Tile w/ white grooves & holes pucks	14,000	SF	Basement lunchroom, teacher's lunch room, serving line room, kitchen -1938 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I	MJP on Fiberglass Pipe Insulation	10	SF	Pump Room - 1898 Bldg.	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

Review Date	8/26/2022
Manager Planner Name	Arturo Saenz
100-04019	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
006	
009	
01A	
02A	
03A	
04A	
05A	
06A	
07A	
08A	
09A	
100 A	
100A	
101 A	
101A	
102A	
103A	
104A	
105A	
106A	
107A	
108A	
109A	
10A	
110A	
111A	
112A	

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
113A	
114A	
115A	
116A	
117	
118	
118A	
119	
11A	
120	
120A	
121	
122	
123	
123A	
124	
125	
126	
126A	
127	
127A	
128	
128A	
129	
129A	
12A	
130	

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
131	
131A	
132	
132A	
133	
133A	
134	
135	
136	
137	
138	
139	
140	
141	
142	
143	
144	
145	
146	
147	
148	
149	
14A	
150	
151	
152	
153	

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
154	
155	
156	
157	
158	
159	
159A	
160	
160A	
161	
161A	
162	
163	
16A	
17A	
18A	
19A	
20A	
21A	
22A	
23A	
24A	
25A	
26A	
27A	
28A	
31A	

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
32A	
33A	
34A	
35A	
36A	
37A	
38A	
39A	
40A	
41A	
42A	
43A	
44A	
45A	
46A	
49A	
50A	
51A	
52A	
53A	
54A	
55A	
56A	
57A	
58A	
59A	
60A	

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
61A	
62A	
65A	
66A	
67A	
68A	
69A	
70A	
71A	
72A	
73A	
74A	
75A	
76A	
77A	
78A	
79A	
80A	
81A	
82A	
83A	
84A	
85A	
86A	
87A	
88A	
89A	

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
90A	
91A	
92A	
93A	
94A	
97A	
98A	
99A	
CCA106	
CCA53	
CCA54	
H	
HA-1000	
HA-1001	
HA-1002	
HA-1003	
HA-1004	
HA-1005	
HA-1006	
HA-1006A	
HA-1007	
HA-1007A	
HA-1008	
HA-1008A	
HA-1009	
HA-1010	
HA-1010A	

Chicago Public Schools

School Lakeview High School
Address 4015 N. Ashland

Unit 46211
 Chicago, IL, 60613

Building ID 1430
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
HA-1011	
HA-1011A	
HA-1012	
HA-1012A	
HA-1013	
HA-1014	
HA-1014A	
HA-1015	
HA-1015A	
HA-1016	
HA-1016A	
HA-1017	
HA-1018	
HA-1018A	
HA-1019	
HA-1019A	
HA-1020	
HA-1020A	
HA-1021	
HA-1022	
HA-1022A	
HA-1023	
HA-1023A	
HA-1024	
HA-1024A	
HA-1025	
HA-1026	

Chicago Public Schools

School Lakeview High School

Unit 46211

Building ID 1430

Address 4015 N. Ashland

Chicago, IL, 60613

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
HA-1027	
HA-1027A	
I	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Darkroom, Room 110, 328 (Abated), Lunchroom Storage under Stairs, LRS #2 Bathroom Chase - 1938 Bldg.**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **1st Floor Darkroom, Room 110, 328 (Abated), Lunchroom Storage under Stairs, LRS #2 Bathroom Chase - 1938 Bldg.**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Darkroom, Room 110, Lunchroom Storage under Stairs, LRS #2 Bathroom Chase - 1938 Bldg.**

MATERIAL QUANTITY: **16**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**
MATERIAL LOCATION: **1st Floor Darkroom, Room 110, Lunchroom Storage under Stairs, LRS #2 Bathroom Chase - 1938 Bldg.**
MATERIAL QUANTITY: **16** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **9"x9" Gray VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms: 232 (Library - Under Carpet/plywood substrate), 334, 325, 337, MDF Rm 232A -1915 Bldg.**

MATERIAL QUANTITY: **4550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **9"x9" Gray VFT**
MATERIAL LOCATION: **Rooms: 232 (Library - Under Carpet/plywood substrate), 334, 325, 337, MDF Rm 232A -1915 Bldg.**
MATERIAL QUANTITY: **4550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02A**
MATERIAL DESCRIPTION: **12"x12" Beige w/White Spots VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 119, 122, 124, 215, 220, 222 - 1915 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **02A**
MATERIAL DESCRIPTION: **12"x12" Beige w/White Spots VFT (ABATED)**
MATERIAL LOCATION: **Rooms 119, 122, 124, 215, 220, 222 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms: 232 (Library - Under Carpet/plywood substrate), 334 325 and 337(under new HA), MDF Rm 232A -1915 Bldg.**

MATERIAL QUANTITY: **4550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic**
MATERIAL LOCATION: **Rooms: 232 (Library - Under Carpet/plywood substrate), 334 325 and 337(under new HA), MDF Rm 232A -1915 Bldg.**
MATERIAL QUANTITY: **4550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **12"x12" Beige w/White Spots VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 119, 122, 124, 215, 220, 222 - 1915 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **12"x12" Beige w/White Spots VFT Mastic (ABATED)**
MATERIAL LOCATION: **Rooms 119, 122, 124, 215, 220, 222 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **9"x9" Gray w/White & Black Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 121, 123, 125, 129, 228, 229 (under carpet, 422 (under carpet) Under New HA & sound closet, R.O.T.C room -1898 Bldg.**

MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **9"x9" Gray w/White & Black Streaks VFT**
MATERIAL LOCATION: **Rooms 121, 123, 125, 129, 228, 229 (under carpet, 422 (under carpet) Under New HA & sound closet, R.O.T.C room -1898 Bldg.**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12"x12" Beige w/White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **224/226 (Under HA 25A & 26A -1898 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12"x12" Beige w/White Streaks VFT**
MATERIAL LOCATION: **224/226 (Under HA 25A & 26A -1898 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **9"x9" Gray w/White & Black Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 121, 123, 125, 129, 228, 229 all under new HA (under carpet, 422 (under carpet) & sound closet, R.O.T.C room -1898 Bldg.**

MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **9"x9" Gray w/White & Black Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 121, 123, 125, 129, 228, 229 all under new HA (under carpet, 422 (under carpet) & sound closet, R.O.T.C room -1898 Bldg.**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **12"x12" Beige w/White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **224/226, (Under HA 25A & 26A) 320, 328 - 1898 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **12"x12" Beige w/White Streaks VFT Mastic**
MATERIAL LOCATION: **224/226, (Under HA 25A & 26A) 320, 328 - 1898 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **12"x12" Flesh VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 212 - 1938 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **12"x12" Flesh VFT (ABATED)**
MATERIAL LOCATION: **Room 212 - 1938 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100 A**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Landing between 1898 and 1915 Buildings, First Floor**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **100 A**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Landing between 1898 and 1915 Buildings, First Floor**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100A**
MATERIAL DESCRIPTION: **12"x12" Solid Maroon VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom closet (NE corner)- 1938**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **100A**
MATERIAL DESCRIPTION: **12"x12" Solid Maroon VFT Mastic**
MATERIAL LOCATION: **Lunchroom closet (NE corner)- 1938**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101 A**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Stairs and Landings - 1938**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **101 A**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Stairs and Landings - 1938**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101A**
MATERIAL DESCRIPTION: **Green Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 200L (Fire Escape passage) - 1898 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **101A**
MATERIAL DESCRIPTION: **Green Linoleum**
MATERIAL LOCATION: **Room 200L (Fire Escape passage) - 1898 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102A**
MATERIAL DESCRIPTION: **Green Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 200L(Fire Escape passage) - 1898 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **102A**
MATERIAL DESCRIPTION: **Green Linoleum Mastic**
MATERIAL LOCATION: **Room 200L(Fire Escape passage) - 1898 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46211 BUIDLING ID: 1430
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: David Avila
SCHOOL NAME: Lakeview High School INSPECTION DATE: 8/5/2022
ADDRESS: 4015 N. Ashland IDPH LICENSE NO: 100-11093

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 103A
MATERIAL DESCRIPTION: Grey Linoleum (Abated)
HISTORICAL AHERA DAMAGE CATEGORY 7
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. Any remaining friable ACBM or friable suspect ACBM

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 324 - 1898 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **103A**
MATERIAL DESCRIPTION: **Grey Linoleum (Abated)**
MATERIAL LOCATION: **Room 324 - 1898 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104A**
MATERIAL DESCRIPTION: **Grey Linoleum Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 324 - 1898 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **104A**
MATERIAL DESCRIPTION: **Grey Linoleum Mastic (Abated)**
MATERIAL LOCATION: **Room 324 - 1898 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105A**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 233 (231) - 1898 Bldg.**

MATERIAL QUANTITY: **900**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **105A**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White VFT (Abated)**
MATERIAL LOCATION: **Room 233 (231) - 1898 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106A**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 233 (231) - 1898 Bldg.**

MATERIAL QUANTITY: **900**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **106A**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White VFT Mastic (Abated)**
MATERIAL LOCATION: **Room 233 (231) - 1898 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107A**
MATERIAL DESCRIPTION: **12"X12" Black with white specks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd floor corridor between room 314 & 316 - 1915 Bldg**

MATERIAL QUANTITY: **500** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **107A**
MATERIAL DESCRIPTION: **12"X12" Black with white specks VFT (Abated)**
MATERIAL LOCATION: **3rd floor corridor between room 314 & 316 - 1915 Bldg**
MATERIAL QUANTITY: **500** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108A**
MATERIAL DESCRIPTION: **12"x12" Black with white specks VFT MASTIC (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd floor corridor between rooms 314 & 316 - 1915 Bldg**

MATERIAL QUANTITY: **500** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **108A**
MATERIAL DESCRIPTION: **12"x12" Black with white specks VFT MASTIC (Abated)**
MATERIAL LOCATION: **3rd floor corridor between rooms 314 & 316 - 1915 Bldg**
MATERIAL QUANTITY: **500** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109A**
MATERIAL DESCRIPTION: **12"x12" White with black & gray specks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly hall & south vestibule, Rooms 115 & Prep-Room, 117/119, 215, 335, 337, 1st floor corridor between 115-119 - 1915 Bldg.**

MATERIAL QUANTITY: **3900** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **109A**
MATERIAL DESCRIPTION: **12"x12" White with black & gray specks VFT (Abated)**
MATERIAL LOCATION: **Assembly hall & south vestibule, Rooms 115 & Prep-Room, 117/119, 215, 335, 337, 1st floor corridor between 115-119 - 1915 Bldg.**
MATERIAL QUANTITY: **3900** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **12"x12" Flesh VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 212 - 1938 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **12"x12" Flesh VFT Mastic (ABATED)**
MATERIAL LOCATION: **Room 212 - 1938 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110A**
MATERIAL DESCRIPTION: **12"x12" White with black & gray specks VFT MASTIC (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly hall & south vestibule, Rooms 115 & Prep-Room, 117/119, 215, 335, 337, 1st floor corridor between 115-119 - 1915 Bldg.**

MATERIAL QUANTITY: **4900** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **110A**
MATERIAL DESCRIPTION: **12"x12" White with black & gray specks VFT MASTIC (Abated)**
MATERIAL LOCATION: **Assembly hall & south vestibule, Rooms 115 & Prep-Room, 117/119, 215, 335, 337, 1st floor corridor between 115-119 - 1915 Bldg.**
MATERIAL QUANTITY: **4900** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111A**
MATERIAL DESCRIPTION: **12"x12" Red speckled VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly hall & south vestibule, 1st floor corridor between 115-119 -1915 Bldg**

MATERIAL QUANTITY: **1500** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **111A**
MATERIAL DESCRIPTION: **12"x12" Red speckled VFT (Abated)**
MATERIAL LOCATION: **Assembly hall & south vestibule, 1st floor corridor between 115-119 -1915 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112A**
MATERIAL DESCRIPTION: **12"x12" Red VFT MASTIC (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly hall & south vestibule, 1st floor corridor between 115-119 -1915 Bldg**

MATERIAL QUANTITY: **1500** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **112A**
MATERIAL DESCRIPTION: **12"x12" Red VFT MASTIC (Abated)**
MATERIAL LOCATION: **Assembly hall & south vestibule, 1st floor corridor between 115-119 -1915 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113A**
MATERIAL DESCRIPTION: **12"x12" White with black & gray specks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st floor corridors, 135 and women's toilet across 135 - 1898 Bldg.**

MATERIAL QUANTITY: **2500** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **113A**
MATERIAL DESCRIPTION: **12"x12" White with black & gray specks VFT (Abated)**
MATERIAL LOCATION: **1st floor corridors, 135 and women's toilet across 135 - 1898 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114A**
MATERIAL DESCRIPTION: **12"x12" White with black & gray specks VFT MASTIC (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st floor corridors, 135 and women's toilet across 135 - 1898 Bldg.**

MATERIAL QUANTITY: **1800** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **114A**
MATERIAL DESCRIPTION: **12"x12" White with black & gray specks VFT MASTIC (Abated)**
MATERIAL LOCATION: **1st floor corridors, 135 and women's toilet across 135 - 1898 Bldg.**
MATERIAL QUANTITY: **1800** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115A**
MATERIAL DESCRIPTION: **12"x12" Red specked VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st floor corridor -1898 Bldg**

MATERIAL QUANTITY: **300**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **115A**
MATERIAL DESCRIPTION: **12"x12" Red specked VFT (Abated)**
MATERIAL LOCATION: **1st floor corridor -1898 Bldg**
MATERIAL QUANTITY: **300** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116A**
MATERIAL DESCRIPTION: **12"x12" Red speckled VFT MASTIC (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st floor corridor -1898 Bldg**

MATERIAL QUANTITY: **300**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **116A**
MATERIAL DESCRIPTION: **12"x12" Red speckled VFT MASTIC (Abated)**
MATERIAL LOCATION: **1st floor corridor -1898 Bldg**
MATERIAL QUANTITY: **300** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **Fire doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly hall, stage, projector room, and balcony**
MATERIAL QUANTITY: **16** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **Fire doors**
MATERIAL LOCATION: **Assembly hall, stage, projector room, and balcony**
MATERIAL QUANTITY: **16** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **12"x12" offwhite w/ light grey & grey specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly hall stage**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **12"x12" offwhite w/ light grey & grey specks VFT**
MATERIAL LOCATION: **Assembly hall stage**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118A**
MATERIAL DESCRIPTION: **12"x12" oof white w/ light gray and gray specks VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Assembly hall stage**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **118A**
MATERIAL DESCRIPTION: **12"x12" oof white w/ light gray and gray specks VFT MASTIC**
MATERIAL LOCATION: **Assembly hall stage**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Decorative plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly hall, NW lobby of auditorium, assembly hall balcony**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Decorative plaster**
MATERIAL LOCATION: **Assembly hall, NW lobby of auditorium, assembly hall balcony**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **Light Brown Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 229 Vault -1898 Bldg.**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **Light Brown Linoleum**
MATERIAL LOCATION: **Room 229 Vault -1898 Bldg.**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **12'x12" tan w/ white and light brown specks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 302 -1938 Bldg**

MATERIAL QUANTITY: **450**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **12'x12" tan w/ white and light brown specks VFT (Abated)**
MATERIAL LOCATION: **Room 302 -1938 Bldg**
MATERIAL QUANTITY: **450** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120A**
MATERIAL DESCRIPTION: **12"x12" tan w/ white and light brown specks VFT MASTIC (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 302 -1938 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **120A**
MATERIAL DESCRIPTION: **12"x12" tan w/ white and light brown specks VFT MASTIC (Abated)**
MATERIAL LOCATION: **Room 302 -1938 Bldg**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **Carpet MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **rooms 136, 138,library -1915 Bldg 232, media center**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **Carpet MASTIC**
MATERIAL LOCATION: **rooms 136, 138, library -1915 Bldg 232, media center**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Pyroboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Attic**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Pyroboard**
MATERIAL LOCATION: **Attic**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **12"x12" off white with grey specks VFT - Abated**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **12"x12" off white with grey specks VFT - Abated**
MATERIAL LOCATION: **Main office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123A**
MATERIAL DESCRIPTION: **12"x12" off white w/ grey specks VFT MASTIC (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **123A**
MATERIAL DESCRIPTION: **12"x12" off white w/ grey specks VFT MASTIC (ABATED)**
MATERIAL LOCATION: **Main office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **Carpet MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 111, 112, 113, addition 1938**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **Carpet MASTIC**
MATERIAL LOCATION: **Room 111, 112, 113, addition 1938**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **Carpet MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 229, 227(removed), 422(removed), - Addition 1898**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **Carpet MASTIC**
MATERIAL LOCATION: **Room 229, 227(removed), 422(removed), - Addition 1898**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **12"x12" tan w/ white specks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 304 -1938 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **12"x12" tan w/ white specks VFT (Abated)**
MATERIAL LOCATION: **Room 304 -1938 Bldg**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126A**
MATERIAL DESCRIPTION: **12"x12" tan w/ white specks VFT MASTIC (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 304 -1938 Bldg**

MATERIAL QUANTITY: **750**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **126A**
MATERIAL DESCRIPTION: **12"x12" tan w/ white specks VFT MASTIC (Abated)**
MATERIAL LOCATION: **Room 304 -1938 Bldg**
MATERIAL QUANTITY: **750** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **12"x12" tan w/ white and light brown specks VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 126- Addition 1898**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **12"x12" tan w/ white and light brown specks VFT (ABATED)**
MATERIAL LOCATION: **Room 126- Addition 1898**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127A**
MATERIAL DESCRIPTION: **12"x12" tan w/ white and light brown specks VFT MASTIC (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 126- addition 1898**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **127A**
MATERIAL DESCRIPTION: **12"x12" tan w/ white and light brown specks VFT MASTIC (ABATED)**
MATERIAL LOCATION: **Room 126- addition 1898**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **12"x12" tan w/ light brown and white specks VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 314 & 136- addition 1915**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **12"x12" tan w/ light brown and white specks VFT (ABATED)**
MATERIAL LOCATION: **Room 314 & 136- addition 1915**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128A**
MATERIAL DESCRIPTION: **12"x12" tan w/ light brown and white specks VFT MASTIC (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 314 & 136- addition 1915**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **128A**
MATERIAL DESCRIPTION: **12"x12" tan w/ light brown and white specks VFT MASTIC (ABATED)**
MATERIAL LOCATION: **Room 314 & 136- addition 1915**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**
MATERIAL DESCRIPTION: **12"x12" Brown wood grain VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Women faculty across from room 135**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **129**
MATERIAL DESCRIPTION: **12"x12" Brown wood grain VFT**
MATERIAL LOCATION: **Women faculty across from room 135**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129A**
MATERIAL DESCRIPTION: **12"x12" brown wood grain VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Women faculty across from room 135**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **129A**
MATERIAL DESCRIPTION: **12"x12" brown wood grain VFT MASTIC**
MATERIAL LOCATION: **Women faculty across from room 135**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **Grey w/Orange & Black Streaks Linoleum (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **12A**

MATERIAL DESCRIPTION: **Grey w/Orange & Black Streaks Linoleum (Abated)**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **Drywall system**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102, 101A, 105, -1938 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **Drywall system**
MATERIAL LOCATION: **Room 102, 101A, 105, -1938 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **9"x9" light green w/ black and white striations VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **ROTC 090 -1898 Bldg**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **9"x9" light green w/ black and white striations VFT**
MATERIAL LOCATION: **ROTC 090 -1898 Bldg**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131A**
MATERIAL DESCRIPTION: **9"x9' light green w/ black and white striations VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **ROTC 090 -1898 Bldg**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **131A**
MATERIAL DESCRIPTION: **9"x9' light green w/ black and white striations VFT MASTIC**
MATERIAL LOCATION: **ROTC 090 -1898 Bldg**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **9"x9" light green w/ black and white striations VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 116B Storage (gym) -1915 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **9"x9" light green w/ black and white striations VFT**
MATERIAL LOCATION: **Room 116B Storage (gym) -1915 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132A**
MATERIAL DESCRIPTION: **9"x9" light green w/ black and white striations VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 116B Storage (gym) -1915 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **132A**
MATERIAL DESCRIPTION: **9"x9" light green w/ black and white striations VFT MASTIC**
MATERIAL LOCATION: **Room 116B Storage (gym) -1915 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **12"x12" white w/ tan specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st floor gym office by 116B - 1915 Bldg.**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **12"x12" white w/ tan specks VFT**
MATERIAL LOCATION: **1st floor gym office by 116B - 1915 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133A**
MATERIAL DESCRIPTION: **12"x12 white w/ tan specks VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st floor gym office by 116B - 1915 Bldg.**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **133A**
MATERIAL DESCRIPTION: **12"x12 white w/ tan specks VFT MASTIC**
MATERIAL LOCATION: **1st floor gym office by 116B - 1915 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **12 x 12 Dark Gray w/ specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly hall, 231, 215, 314, 422, 426 and 428 -1915 Bldg**
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **12 x 12 Dark Gray w/ specks**
MATERIAL LOCATION: **Assembly hall, 231, 215, 314, 422, 426 and 428 -1915 Bldg**
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **12 x 12 Dark Gray w/ specks mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Assembly hall, Room 231, 215, 314, 317, 318, 330, 332, 334, 422, 426 and 428 - 1915 Bldg**

MATERIAL QUANTITY: **7500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **12 x 12 Dark Gray w/ specks mastic**
MATERIAL LOCATION: **Assembly hall, Room 231, 215, 314, 317, 318, 330, 332, 334, 422, 426 and 428 - 1915 Bldg**
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **12 x 12 Gray w/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th Floor corridors - 1915 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **12 x 12 Gray w/ Specks VFT**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th Floor corridors - 1915 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **12 x 12 Gray w/ specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th Floor corridors - 1915 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **12 x 12 Gray w/ specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th Floor corridors - 1915 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **12 x 12 White w/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **12 x 12 White w/ Specks VFT**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **12 x 12 White w/ specks VFT mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **12 x 12 White w/ specks VFT mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **12 x 12 Red w/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **12 x 12 Red w/ Specks VFT**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **12 x 12 red w/ specks VFT mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **12 x 12 red w/ specks VFT mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, assembly hall, 215, 231, 314, 317, 318, 330, 332, 334, 422, 426 and 428 -1915 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **12 x 12 Dark gray w/ specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 209, 302, 304, Lunchroom, serving room, old teacher lunch room - 1938 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **12 x 12 Dark gray w/ specks VFT**
MATERIAL LOCATION: **Room 209, 302, 304, Lunchroom, serving room, old teacher lunch room - 1938 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **12 x 12 dark gray w/ specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 209, 302, 304, Lunchroom, serving room, old teacher lunch room - 1938 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **12 x 12 dark gray w/ specks VFT Mastic**
MATERIAL LOCATION: **Room 209, 302, 304, Lunchroom, serving room, old teacher lunch room - 1938 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **12 x 12 Gray w/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1938 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **12 x 12 Gray w/ Specks VFT**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1938 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **12 x 12 gray w/ Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1938 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **12 x 12 gray w/ Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1938 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **146**
MATERIAL DESCRIPTION: **12 x 12 White w/ specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **146**
MATERIAL DESCRIPTION: **12 x 12 White w/ specks VFT**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147**
MATERIAL DESCRIPTION: **12 x 12 white w/ specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **147**
MATERIAL DESCRIPTION: **12 x 12 white w/ specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **148**
MATERIAL DESCRIPTION: **12 x 12 Red w/ specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **148**
MATERIAL DESCRIPTION: **12 x 12 Red w/ specks VFT**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149**
MATERIAL DESCRIPTION: **12 x 12 Red w/ Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **149**
MATERIAL DESCRIPTION: **12 x 12 Red w/ Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridor, 209, 302, 304, lunchroom, serving room, old teacher lunchroom -1938 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **Plaster Wall & Plaster Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1898 Bldg.**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **Plaster Wall & Plaster Ceiling**
MATERIAL LOCATION: **Throughout - 1898 Bldg.**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **150**
MATERIAL DESCRIPTION: **12 x 12 Dark gray w/ specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 100E, 123, 125, 129, 220, 226, 228, 325, 328, 328A, 335, 337, 432 -1898 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **150**
MATERIAL DESCRIPTION: **12 x 12 Dark gray w/ specks VFT**
MATERIAL LOCATION: **Rooms 100E, 123, 125, 129, 220, 226, 228, 325, 328, 328A, 335, 337, 432 -1898 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151**
MATERIAL DESCRIPTION: **12 x 12 Dark gray w/ specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 100E, 123, 125, 129, 220, 226, 228, 325, 328, 328A, 335, 337, 432 -1898 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **151**
MATERIAL DESCRIPTION: **12 x 12 Dark gray w/ specks VFT Mastic**
MATERIAL LOCATION: **Rooms 100E, 123, 125, 129, 220, 226, 228, 325, 328, 328A, 335, 337, 432 -1898 Bldg**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152**
MATERIAL DESCRIPTION: **12 x 12 Gray w specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor. room 231 -1898 Bldg**
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **152**
MATERIAL DESCRIPTION: **12 x 12 Gray w specks VFT**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor. room 231 -1898 Bldg**
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153**
MATERIAL DESCRIPTION: **12 x 12 gray w/ specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor. room 231 -1898 Bldg**
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **153**
MATERIAL DESCRIPTION: **12 x 12 gray w/ specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor. room 231 -1898 Bldg**
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **154**
MATERIAL DESCRIPTION: **12 x 12 White w/ specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **154**
MATERIAL DESCRIPTION: **12 x 12 White w/ specks VFT**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155**
MATERIAL DESCRIPTION: **12 x 12 White w/ specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **155**
MATERIAL DESCRIPTION: **12 x 12 White w/ specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **156**
MATERIAL DESCRIPTION: **12 x 12 Red w/ specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **156**
MATERIAL DESCRIPTION: **12 x 12 Red w/ specks VFT**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **157**
MATERIAL DESCRIPTION: **12 x 12 Red w/ specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **157**
MATERIAL DESCRIPTION: **12 x 12 Red w/ specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd, 4th floor corridor, 100E, 123, 125, 129, 220, 226, 228, 231, 325, 328, 328A, 335, 337, 432. -1898 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **158**
MATERIAL DESCRIPTION: **2' x 2' ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridor**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **158**
MATERIAL DESCRIPTION: **2' x 2' ceiling tile**
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridor**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**
MATERIAL DESCRIPTION: **Light Brown Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 229 Vault (under carpet) -1898 Bldg.**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **16A**
MATERIAL DESCRIPTION: **Light Brown Linoleum Mastic**
MATERIAL LOCATION: **Room 229 Vault (under carpet) -1898 Bldg.**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **Grey w/Orange & Black Streaks Linoleum Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 426, & 428 - 1898 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **Grey w/Orange & Black Streaks Linoleum Mastic (Abated)**
MATERIAL LOCATION: **Rooms 426, & 428 - 1898 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **Black Laboratory Countertop**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1898 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **Black Laboratory Countertop**
MATERIAL LOCATION: **Throughout - 1898 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **Black Lab Countertop**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1938 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **Black Lab Countertop**
MATERIAL LOCATION: **Throughout - 1938 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20A**
MATERIAL DESCRIPTION: **Black Laboratory Countertop**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1915 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **20A**
MATERIAL DESCRIPTION: **Black Laboratory Countertop**
MATERIAL LOCATION: **Throughout - 1915 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21A**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/Dark Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **121 (abated), 127, Music Store Room, eng. office -1898 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **21A**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/Dark Speckles VFT**
MATERIAL LOCATION: **121 (abated), 127, Music Store Room, eng. office -1898 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22A**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/Dark Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **121 (abated), 127, Music Store Room, eng. office -1898 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **22A**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/Dark Speckles VFT Mastic**
MATERIAL LOCATION: **121 (abated), 127, Music Store Room, eng. office -1898 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23A**
MATERIAL DESCRIPTION: **12"x12" Brown w/Dark & White Streaks VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 328A - 1898 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **23A**
MATERIAL DESCRIPTION: **12"x12" Brown w/Dark & White Streaks VFT (ABATED)**
MATERIAL LOCATION: **Room 328A - 1898 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24A**
MATERIAL DESCRIPTION: **12"x12" Brown w/Dark & White Streaks VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 328A - 1898 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **24A**
MATERIAL DESCRIPTION: **12"x12" Brown w/Dark & White Streaks VFT Mastic (ABATED)**
MATERIAL LOCATION: **Room 328A - 1898 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25A**
MATERIAL DESCRIPTION: **12"x12" Tan w/Dark Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms: 224 & 226 - 1898 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **25A**
MATERIAL DESCRIPTION: **12"x12" Tan w/Dark Streaks VFT**
MATERIAL LOCATION: **Rooms: 224 & 226 - 1898 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26A**
MATERIAL DESCRIPTION: **12"x12" Tan w/Dark Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms: 224 & 226 - 1898 Bldg.**

MATERIAL QUANTITY: **1900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **26A**
MATERIAL DESCRIPTION: **12"x12" Tan w/Dark Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms: 224 & 226 - 1898 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27A**
MATERIAL DESCRIPTION: **12"x12" Off-White w/Blue Streaks VFT - Abated**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Teacher's Toilet -1989 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **27A**

MATERIAL DESCRIPTION: **12"x12" Off-White w/Blue Streaks VFT - Abated**

MATERIAL LOCATION: **1st Floor Teacher's Toilet -1989 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **12"x12" Off-White w/Blue Streaks VFT Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Teacher's Toilet -1898 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **12"x12" Off-White w/Blue Streaks VFT Mastic - Abated**
MATERIAL LOCATION: **1st Floor Teacher's Toilet -1898 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31A**
MATERIAL DESCRIPTION: **12"x12" Peach VFT (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 314 & 318 - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **31A**
MATERIAL DESCRIPTION: **12"x12" Peach VFT (abated)**
MATERIAL LOCATION: **Room 314 & 318 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32A**
MATERIAL DESCRIPTION: **12"x12" Peach VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 314 & 318 - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **32A**
MATERIAL DESCRIPTION: **12"x12" Peach VFT Mastic (abated)**
MATERIAL LOCATION: **Room 314 & 318 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33A**
MATERIAL DESCRIPTION: **12"x12" White VFT (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 332 - 1915 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **33A**
MATERIAL DESCRIPTION: **12"x12" White VFT (abated)**
MATERIAL LOCATION: **Room 332 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34A**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 332 - 1915 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **34A**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic (abated)**
MATERIAL LOCATION: **Room 332 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35A**
MATERIAL DESCRIPTION: **12"x12" Brown VFT (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 332 - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **35A**
MATERIAL DESCRIPTION: **12"x12" Brown VFT (abated)**
MATERIAL LOCATION: **Room 332 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36A**
MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 332 - 1915 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **36A**
MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic (abated)**
MATERIAL LOCATION: **Room 332 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37A**
MATERIAL DESCRIPTION: **12"x12" White w/Black Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 235 Bldg. - 1915 Bldg.**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **37A**
MATERIAL DESCRIPTION: **12"x12" White w/Black Streaks VFT**
MATERIAL LOCATION: **Room 235 Bldg. - 1915 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38A**
MATERIAL DESCRIPTION: **12"x12" White w/Black Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 235 Bldg. -1915 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **38A**
MATERIAL DESCRIPTION: **12"x12" White w/Black Streaks VFT Mastic**
MATERIAL LOCATION: **Room 235 Bldg. -1915 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39A**
MATERIAL DESCRIPTION: **12"x12" Beige VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 335 - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **39A**
MATERIAL DESCRIPTION: **12"x12" Beige VFT (ABATED)**
MATERIAL LOCATION: **Room 335 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40A**
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 335 - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **40A**
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic (ABATED)**
MATERIAL LOCATION: **Room 335 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41A**
MATERIAL DESCRIPTION: **12"x12' Beige w/Tan Spots VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 115 & 117 - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **41A**
MATERIAL DESCRIPTION: **12"x12' Beige w/Tan Spots VFT (ABATED)**
MATERIAL LOCATION: **Rooms 115 & 117 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42A**
MATERIAL DESCRIPTION: **12"x12' Beige w/Tan Spots VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 115 & 117 - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **42A**
MATERIAL DESCRIPTION: **12"x12' Beige w/Tan Spots VFT Mastic (ABATED)**
MATERIAL LOCATION: **Rooms 115 & 117 - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43A**
MATERIAL DESCRIPTION: **9"x9" Brown w/Black Streaks VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Auditorium - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **43A**
MATERIAL DESCRIPTION: **9"x9" Brown w/Black Streaks VFT (ABATED)**
MATERIAL LOCATION: **1st Floor Auditorium - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44A**
MATERIAL DESCRIPTION: **9"x9" Brown w/Black Streaks VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Auditorium - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **44A**
MATERIAL DESCRIPTION: **9"x9" Brown w/Black Streaks VFT Mastic (ABATED)**
MATERIAL LOCATION: **1st Floor Auditorium - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45A**
MATERIAL DESCRIPTION: **12"x12' Tan w/Tan Spots VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1915 Bldg. (abated)**

MATERIAL QUANTITY: **3600**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **45A**
MATERIAL DESCRIPTION: **12"x12' Tan w/Tan Spots VFT (Abated)**
MATERIAL LOCATION: **1st Floor Corridor - 1915 Bldg. (abated)**
MATERIAL QUANTITY: **3600** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46A**
MATERIAL DESCRIPTION: **12"x12' Tan w/Tan Spots VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1915 Bldg. (Abated)**

MATERIAL QUANTITY: **3600**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **46A**
MATERIAL DESCRIPTION: **12"x12' Tan w/Tan Spots VFT Mastic (abated)**
MATERIAL LOCATION: **1st Floor Corridor - 1915 Bldg. (Abated)**
MATERIAL QUANTITY: **3600** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49A**
MATERIAL DESCRIPTION: **12"x12" Cream VFT- (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stage - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **49A**
MATERIAL DESCRIPTION: **12"x12" Cream VFT- (ABATED)**
MATERIAL LOCATION: **Stage - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50A**
MATERIAL DESCRIPTION: **12"x12" Cream VFT Mastic -(ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stage - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **50A**
MATERIAL DESCRIPTION: **12"x12" Cream VFT Mastic -(ABATED)**
MATERIAL LOCATION: **Stage - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51A**
MATERIAL DESCRIPTION: **9"x9" Maroon VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Gym Vestibule - 1915 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **51A**
MATERIAL DESCRIPTION: **9"x9" Maroon VFT (ABATED)**
MATERIAL LOCATION: **1st Floor Gym Vestibule - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52A**
MATERIAL DESCRIPTION: **9"x9" Maroon VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Gym Vestibule - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **52A**
MATERIAL DESCRIPTION: **9"x9" Maroon VFT Mastic (ABATED)**
MATERIAL LOCATION: **1st Floor Gym Vestibule - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53A**
MATERIAL DESCRIPTION: **9"x9" Black VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Gym Vestibule - 1915 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **53A**
MATERIAL DESCRIPTION: **9"x9" Black VFT (ABATED)**
MATERIAL LOCATION: **1st Floor Gym Vestibule - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54A**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Gym Vestibule - 1915 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **54A**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic (ABATED)**
MATERIAL LOCATION: **1st Floor Gym Vestibule - 1915 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55A**
MATERIAL DESCRIPTION: **12"x 12" Tan w/Tan Streaks VFT (Pink)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 317, 317A - 1915 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **55A**
MATERIAL DESCRIPTION: **12"x 12" Tan w/Tan Streaks VFT (Pink)**
MATERIAL LOCATION: **Room 317, 317A - 1915 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56A**
MATERIAL DESCRIPTION: **12"x 12" Red w/Tan Streaks VFT Mastic (Pink)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 317, 317A - 1915 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **56A**
MATERIAL DESCRIPTION: **12"x 12" Red w/Tan Streaks VFT Mastic (Pink)**
MATERIAL LOCATION: **Room 317, 317A - 1915 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57A**
MATERIAL DESCRIPTION: **9"x9" Black w/White Streaks VFT (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Corridor between Rooms 314 & 318 - 1915 Bldg. (under HA107A & 108A)
(abated)**

MATERIAL QUANTITY: **500**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **57A**
MATERIAL DESCRIPTION: **9"x9" Black w/White Streaks VFT (abated)**
MATERIAL LOCATION: **3rd Floor Corridor between Rooms 314 & 318 - 1915 Bldg. (under HA107A & 108A) (abated)**
MATERIAL QUANTITY: **500** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58A**
MATERIAL DESCRIPTION: **9"x9" Black w/White Streaks VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Corridor between Rooms 314 & 318 - 1915 Bldg. (under HA107A & 108A) (abated)**

MATERIAL QUANTITY: **500**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **58A**
MATERIAL DESCRIPTION: **9"x9" Black w/White Streaks VFT Mastic (abated)**
MATERIAL LOCATION: **3rd Floor Corridor between Rooms 314 & 318 - 1915 Bldg. (under HA107A & 108A) (abated)**
MATERIAL QUANTITY: **500** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59A**
MATERIAL DESCRIPTION: **12"x12" Peach VFT (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms: 209 (painted black) ; 1st, 2nd & 3rd Floor Corridors - 1938 Bldg. (abated)**

MATERIAL QUANTITY: **3500** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **59A**
MATERIAL DESCRIPTION: **12"x12" Peach VFT (abated)**
MATERIAL LOCATION: **Rooms: 209 (painted black) ; 1st, 2nd & 3rd Floor Corridors - 1938 Bldg. (abated)**
MATERIAL QUANTITY: **3500** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60A**
MATERIAL DESCRIPTION: **12"x12" Peach VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms: 209 (painted black) ; 1st, 2nd & 3rd Floor Corridors - 1938 Bldg. (abated)**

MATERIAL QUANTITY: **3500** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **60A**
MATERIAL DESCRIPTION: **12"x12" Peach VFT Mastic (abated)**
MATERIAL LOCATION: **Rooms: 209 (painted black) ; 1st, 2nd & 3rd Floor Corridors - 1938 Bldg. (abated)**
MATERIAL QUANTITY: **3500** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61A**
MATERIAL DESCRIPTION: **12"x12" Black VFT (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors - 1938 Bldg.**

MATERIAL QUANTITY: **200**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **61A**
MATERIAL DESCRIPTION: **12"x12" Black VFT (abated)**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors - 1938 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62A**
MATERIAL DESCRIPTION: **12"x12" Black VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors - 1938 Bldg.**

MATERIAL QUANTITY: **200** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **62A**
MATERIAL DESCRIPTION: **12"x12" Black VFT Mastic (abated)**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors - 1938 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65A**
MATERIAL DESCRIPTION: **12"x12" Gray VFT (abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 304 - 1938 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **65A**
MATERIAL DESCRIPTION: **12"x12" Gray VFT (abated)**
MATERIAL LOCATION: **Room 304 - 1938 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66A**
MATERIAL DESCRIPTION: **12"x12" Gray VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 304 - 1938 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **66A**
MATERIAL DESCRIPTION: **12"x12" Gray VFT Mastic (abated)**
MATERIAL LOCATION: **Room 304 - 1938 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67A**
MATERIAL DESCRIPTION: **12"x12" Gray w/White & Brown Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 207 - 1938 Bldg.**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **67A**
MATERIAL DESCRIPTION: **12"x12" Gray w/White & Brown Streaks VFT**
MATERIAL LOCATION: **Rooms 207 - 1938 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68A**
MATERIAL DESCRIPTION: **12"x12" Gray w/White & Brown Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 207 - 1938 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **68A**
MATERIAL DESCRIPTION: **12"x12" Gray w/White & Brown Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 207 - 1938 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69A**
MATERIAL DESCRIPTION: **9"x9" Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Storage Room (200E) across Room 213 -1938 Bldg.**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **69A**
MATERIAL DESCRIPTION: **9"x9" Black VFT**
MATERIAL LOCATION: **Storage Room (200E) across Room 213 -1938 Bldg.**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70A**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Storage Room (200E) across Room 213 -1938 Bldg.**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **70A**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**
MATERIAL LOCATION: **Storage Room (200E) across Room 213 -1938 Bldg.**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71A**
MATERIAL DESCRIPTION: **9"x9" Gray w/Red & White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 113, 112, 111(all areas under carpet) -1938 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **71A**
MATERIAL DESCRIPTION: **9"x9" Gray w/Red & White VFT**
MATERIAL LOCATION: **Room 113, 112, 111(all areas under carpet) -1938 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72A**
MATERIAL DESCRIPTION: **9"x9" Gray w/Red & White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 113, 112, 111(all areas under carpet) -1938 Bldg.**
MATERIAL QUANTITY: **690** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **72A**
MATERIAL DESCRIPTION: **9"x9" Gray w/Red & White VFT Mastic**
MATERIAL LOCATION: **Room 113, 112, 111(all areas under carpet) -1938 Bldg.**
MATERIAL QUANTITY: **690** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73A**
MATERIAL DESCRIPTION: **12"x12" Tan w/Brown & Gray Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 109 - 1938 Bldg.**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **73A**
MATERIAL DESCRIPTION: **12"x12" Tan w/Brown & Gray Streaks VFT**
MATERIAL LOCATION: **Rooms 109 - 1938 Bldg.**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74A**
MATERIAL DESCRIPTION: **12"x12" Tan w/Brown & Gray Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 109 - 1938 Bldg.**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **74A**
MATERIAL DESCRIPTION: **12"x12" Tan w/Brown & Gray Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 109 - 1938 Bldg.**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75A**
MATERIAL DESCRIPTION: **12"x12" Black w/White Streaks VFT - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 112 (Under Carpet) - 1938 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **75A**
MATERIAL DESCRIPTION: **12"x12" Black w/White Streaks VFT - Removed**
MATERIAL LOCATION: **Room 112 (Under Carpet) - 1938 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76A**
MATERIAL DESCRIPTION: **12"x12" Black w/White Streaks VFT Mastic - Removed**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 112 (Under Carpet) - 1938 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **76A**
MATERIAL DESCRIPTION: **12"x12" Black w/White Streaks VFT Mastic - Removed**
MATERIAL LOCATION: **Room 112 (Under Carpet) - 1938 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77A**
MATERIAL DESCRIPTION: **9"x9" Tan VFT (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Lunch room lockers (women 010D) -1938 Bldg.**

MATERIAL QUANTITY: **400** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **77A**
MATERIAL DESCRIPTION: **9"x9" Tan VFT (abated)**
MATERIAL LOCATION: **Basement Lunch room lockers (women 010D) -1938 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78A**
MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Lunch room lockers (women 010D) -1938 Bldg.**

MATERIAL QUANTITY: **400** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **78A**
MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic (abated)**
MATERIAL LOCATION: **Basement Lunch room lockers (women 010D) -1938 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79A**
MATERIAL DESCRIPTION: **12"x12" White VFT (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen Dishwashing Room (not observed), Teacher's Lunchroom (Not Observed), & Kitchen Office - 1938 Bldg.**

MATERIAL QUANTITY: **750** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **79A**
MATERIAL DESCRIPTION: **12"x12" White VFT (abated)**
MATERIAL LOCATION: **Kitchen Dishwashing Room (not observed), Teacher's Lunchroom (Not Observed), & Kitchen Office - 1938 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80A**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen Dishwashing Room (not observed), Teacher's Lunchroom (Not Observed), & Kitchen Office - 1938 Bldg.**

MATERIAL QUANTITY: **750** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **80A**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic (abated)**
MATERIAL LOCATION: **Kitchen Dishwashing Room (not observed), Teacher's Lunchroom (Not Observed), & Kitchen Office - 1938 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81A**
MATERIAL DESCRIPTION: **12"x12" Red VFT (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.**

MATERIAL QUANTITY: **3000** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **81A**
MATERIAL DESCRIPTION: **12"x12" Red VFT (abated)**
MATERIAL LOCATION: **Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82A**
MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.**

MATERIAL QUANTITY: **3000** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **82A**
MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic (abated)**
MATERIAL LOCATION: **Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83A**
MATERIAL DESCRIPTION: **12"x12" Blue VFT (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.**

MATERIAL QUANTITY: **3000** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **83A**
MATERIAL DESCRIPTION: **12"x12" Blue VFT (abated)**
MATERIAL LOCATION: **Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84A**
MATERIAL DESCRIPTION: **12"x12" Blue VFT Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.**

MATERIAL QUANTITY: **3000** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **84A**
MATERIAL DESCRIPTION: **12"x12" Blue VFT Mastic (abated)**
MATERIAL LOCATION: **Lunchrooms #1 & #2, Serving Line, Kitchen - 1938 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85A**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement: Teacher's Lunchroom, Serving Line, Above Ceiling in Kitchen - 1938 Bldg.**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **85A**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Basement: Teacher's Lunchroom, Serving Line, Above Ceiling in Kitchen - 1938 Bldg.**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86A**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement: Teacher's Lunchroom, Lunchrooms 1 & 2, Serving Line, Above Ceiling in Kitchen - 1938 Bldg.**

MATERIAL QUANTITY: **18** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **86A**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Basement: Teacher's Lunchroom, Lunchrooms 1 & 2, Serving Line, Above Ceiling in Kitchen - 1938 Bldg.**
MATERIAL QUANTITY: **18** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87A**
MATERIAL DESCRIPTION: **Grey, Black, Orange & Marble Linoleum (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 330 - 1915 Bldg.**

MATERIAL QUANTITY: **650**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **87A**
MATERIAL DESCRIPTION: **Grey, Black, Orange & Marble Linoleum (abated)**
MATERIAL LOCATION: **Room 330 - 1915 Bldg.**
MATERIAL QUANTITY: **650** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88A**
MATERIAL DESCRIPTION: **Grey, Black, Orange & Marble Linoleum Mastic (abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 330 - 1915 Bldg.**

MATERIAL QUANTITY: **650**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **88A**
MATERIAL DESCRIPTION: **Grey, Black, Orange & Marble Linoleum Mastic (abated)**
MATERIAL LOCATION: **Room 330 - 1915 Bldg.**
MATERIAL QUANTITY: **650** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89A**
MATERIAL DESCRIPTION: **Brown Linoelum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium Balcony - 1915 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **89A**
MATERIAL DESCRIPTION: **Brown Linoelum**
MATERIAL LOCATION: **Auditorium Balcony - 1915 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90A**
MATERIAL DESCRIPTION: **Brown Linoelum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium Balcony - 1915 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **90A**
MATERIAL DESCRIPTION: **Brown Linoelum Mastic**
MATERIAL LOCATION: **Auditorium Balcony - 1915 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91A**
MATERIAL DESCRIPTION: **12"x12" Green VFT - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 207 - 1938 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **91A**
MATERIAL DESCRIPTION: **12"x12" Green VFT - Removed**
MATERIAL LOCATION: **Room 207 - 1938 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92A**
MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 207 - 1938 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **92A**
MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic - Removed**
MATERIAL LOCATION: **Room 207 - 1938 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93A**
MATERIAL DESCRIPTION: **12"x12" Beige VFT (under new HA)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 109 - 1938 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **93A**
MATERIAL DESCRIPTION: **12"x12" Beige VFT (under new HA)**
MATERIAL LOCATION: **Room 109 - 1938 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94A**
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic (under new HA)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 109 - 1938 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **94A**
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic (under new HA)**
MATERIAL LOCATION: **Room 109 - 1938 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97A**
MATERIAL DESCRIPTION: **12"x12" Solid Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom closet (NE corner) -1938 Bldg**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **97A**
MATERIAL DESCRIPTION: **12"x12" Solid Black VFT**
MATERIAL LOCATION: **Lunchroom closet (NE corner) -1938 Bldg**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98A**
MATERIAL DESCRIPTION: **12"x12" Solid Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom closet (NE corner) -1938 Bldg**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **98A**
MATERIAL DESCRIPTION: **12"x12" Solid Black VFT Mastic**
MATERIAL LOCATION: **Lunchroom closet (NE corner) -1938 Bldg**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99A**
MATERIAL DESCRIPTION: **12"x12" Solid Maroon VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom closet (NE corner) -1938 Bldg**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **99A**
MATERIAL DESCRIPTION: **12"x12" Solid Maroon VFT**
MATERIAL LOCATION: **Lunchroom closet (NE corner) -1938 Bldg**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CCA106**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 122, & 126**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **CCA106**

MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation (ABATED)**

MATERIAL LOCATION: **Room 122, & 126**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CCA53**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Attic, Rm 228 NW closet - 1898 Bldg.**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **CCA53**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Attic, Rm 228 NW closet - 1898 Bldg.**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CCA54**
MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Attic - 1898 Bldg.**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **CCA54**

MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Attic - 1898 Bldg.**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Duct Packing Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room - 1898 Bldg.**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Duct Packing Insulation**
MATERIAL LOCATION: **Boiler Room - 1898 Bldg.**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1000**
MATERIAL DESCRIPTION: **2'x4' white ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms on 1st, 2nd, 3rd floors. 1st, 2nd, 3rd fl halls -1898 Bldg**
MATERIAL QUANTITY: **90000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1000**
MATERIAL DESCRIPTION: **2'x4' white ceiling tile**
MATERIAL LOCATION: **Classrooms on 1st, 2nd, 3rd floorsl.1st, 2nd, 3rd fl halls -1898 Bldg**
MATERIAL QUANTITY: **90000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1001**
MATERIAL DESCRIPTION: **2'x2' white ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **GYM, 1,2, and 3 floor corridors -1915 BLD**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1001**
MATERIAL DESCRIPTION: **2'x2' white ceiling tile**
MATERIAL LOCATION: **GYM, 1,2, and 3 floor corridors -1915 BLD**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1002**
MATERIAL DESCRIPTION: **1'x1' white ceiling tile with unifirm holes**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **rm. 322**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1002**

MATERIAL DESCRIPTION: **1'x1' white ceiling tile with uniform holes**

MATERIAL LOCATION: **rm. 322**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1003**
MATERIAL DESCRIPTION: **Glue for 1'x1' white ceiling tile with uniform hol**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **rm. 322**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1003**

MATERIAL DESCRIPTION: **Glue for 1'x1' white ceiling tile with uniform hol**

MATERIAL LOCATION: **rm. 322**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1004**
MATERIAL DESCRIPTION: **1'x1' white fissured ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **classrooms on 4th, 3rd, 2nd, 1st -1898 BLdg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1004**
MATERIAL DESCRIPTION: **1'x1' white fissured ceiling tile**
MATERIAL LOCATION: **classrooms on 4th, 3rd, 2nd, 1st -1898 BLdg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1005**
MATERIAL DESCRIPTION: **Glue for 1'x1' wh, fissured tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **classrooms on 4th, 3rd, 2nd, 1st -1898 BLdg**
MATERIAL QUANTITY: **27000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1005**
MATERIAL DESCRIPTION: **Glue for 1'x1' wh, fissured tile**
MATERIAL LOCATION: **classrooms on 4th, 3rd, 2nd, 1st -1898 BLdg**
MATERIAL QUANTITY: **27000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1006**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1006**

MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT**

MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1006A**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1006A**

MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT Mastic**

MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1007**
MATERIAL DESCRIPTION: **12x12 White w/black & gray specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**

MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1007**

MATERIAL DESCRIPTION: **12x12 White w/black & gray specks VFT**

MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**

MATERIAL QUANTITY: **2900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1007A**
MATERIAL DESCRIPTION: **12x12 White w/black & gray specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**

MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1007A**

MATERIAL DESCRIPTION: **12x12 White w/black & gray specks VFT Mastic**

MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**

MATERIAL QUANTITY: **2900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1008**
MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1008**

MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT**

MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**

MATERIAL QUANTITY: **2600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1008A**
MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1008A**
MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT Mastic**
MATERIAL LOCATION: **Rooms 120, 122(Abated), 124(Abated), 126(Abated), 220, 320, 325, 328, 328A -1898 Bldg**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1009**
MATERIAL DESCRIPTION: **2x2 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 325, 323 -1898 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1009**
MATERIAL DESCRIPTION: **2x2 Ceiling Tile**
MATERIAL LOCATION: **Rooms 325, 323 -1898 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1010**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1010**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT**
MATERIAL LOCATION: **Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1010A**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1010A**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT Mastic**
MATERIAL LOCATION: **Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1011**
MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1011**
MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT**
MATERIAL LOCATION: **Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1011A**
MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1011A**
MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT Mastic**
MATERIAL LOCATION: **Rooms 115, 117/119, 215, 335, 337, Auditorium -- 1915 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1012**
MATERIAL DESCRIPTION: **12x12 Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **3rd Floor entry area by Rms 342 and 340 -1915 Bldg**
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1012**
MATERIAL DESCRIPTION: **12x12 Black VFT**
MATERIAL LOCATION: **3rd Floor entry area by Rms 342 and 340 -1915 Bldg**
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1012A**
MATERIAL DESCRIPTION: **12x12 Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor entry area by Rms 342 and 340 -1915 Bldg**
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1012A**
MATERIAL DESCRIPTION: **12x12 Black VFT Mastic**
MATERIAL LOCATION: **3rd Floor entry area by Rms 342 and 340 -1915 Bldg**
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1013**
MATERIAL DESCRIPTION: **2x2 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 340, 342 -1915 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1013**
MATERIAL DESCRIPTION: **2x2 Ceiling Tile**
MATERIAL LOCATION: **Rooms 340, 342 -1915 Bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1014**
MATERIAL DESCRIPTION: **12x12 Brown w/White & Brown streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd & 3rd Floor auditorium balcony -1915 Bldg**

MATERIAL QUANTITY: **1200** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1014**
MATERIAL DESCRIPTION: **12x12 Brown w/White & Brown streaks VFT (Abated)**
MATERIAL LOCATION: **2nd & 3rd Floor auditorium balcony -1915 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1014A**
MATERIAL DESCRIPTION: **12x12 Brown w/White & Brown streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd & 3rd Floor auditorium balcony -1915 Bldg**

MATERIAL QUANTITY: **1200** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1014A**
MATERIAL DESCRIPTION: **12x12 Brown w/White & Brown streaks VFT Mastic (Abated)**
MATERIAL LOCATION: **2nd & 3rd Floor auditorium balcony -1915 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1015**
MATERIAL DESCRIPTION: **9x9 Brown w/white & orange streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Library Storage -1915 Bldg**

MATERIAL QUANTITY: **100**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1015**
MATERIAL DESCRIPTION: **9x9 Brown w/white & orange streaks VFT (Abated)**
MATERIAL LOCATION: **2nd Floor Library Storage -1915 Bldg**
MATERIAL QUANTITY: **100** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1015A**
MATERIAL DESCRIPTION: **9x9 Brown w/white & orange streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Library Storage -1915 Bldg**

MATERIAL QUANTITY: **100**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1015A**
MATERIAL DESCRIPTION: **9x9 Brown w/white & orange streaks VFT Mastic (Abated)**
MATERIAL LOCATION: **2nd Floor Library Storage -1915 Bldg**
MATERIAL QUANTITY: **100** MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1016**
MATERIAL DESCRIPTION: **12x12 Lt. Gray speckled VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 136 closet, main office and all associated rooms in main office**

MATERIAL QUANTITY: **3200** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1016**
MATERIAL DESCRIPTION: **12x12 Lt. Gray speckled VFT (Abated)**
MATERIAL LOCATION: **Rm 136 closet, main office and all associated rooms in main office**
MATERIAL QUANTITY: **3200** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1016A**
MATERIAL DESCRIPTION: **12x12 Lt. Gray speckled VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 136 closet, main office and all associated rooms in main office**

MATERIAL QUANTITY: **3200** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1016A**
MATERIAL DESCRIPTION: **12x12 Lt. Gray speckled VFT Mastic (Abated)**
MATERIAL LOCATION: **Rm 136 closet, main office and all associated rooms in main office**
MATERIAL QUANTITY: **3200** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1017**
MATERIAL DESCRIPTION: **Spray on fire-proofing**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement auditorium plenum chamber, basement corridor by North entry door to auditorium plenum chamber**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1017**
MATERIAL DESCRIPTION: **Spray on fire-proofing**
MATERIAL LOCATION: **Basement auditorium plenum chamber, basement corridor by North entry door to auditorium plenum chamber**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1018**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1018**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1018A**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1018A**
MATERIAL DESCRIPTION: **12x12 Black w/white specks VFT Mastic**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1019**
MATERIAL DESCRIPTION: **12x12 White w/black & gray specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1019**
MATERIAL DESCRIPTION: **12x12 White w/black & gray specks VFT**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1019A**
MATERIAL DESCRIPTION: **12x12 White w/black & gray specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1019A**
MATERIAL DESCRIPTION: **12x12 White w/black & gray specks VFT Mastic**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1020**
MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1020**
MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1020A**
MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1020A**
MATERIAL DESCRIPTION: **12x12 Tan w/brown & tan specks VFT Mastic**
MATERIAL LOCATION: **Rooms 102, 105, 205, 212, 305/309 -1938 Bldg**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1021**
MATERIAL DESCRIPTION: **Mastic Pucks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym 201 -1938 BLdg**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1021**
MATERIAL DESCRIPTION: **Mastic Pucks**
MATERIAL LOCATION: **Gym 201 -1938 BLdg**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1022**
MATERIAL DESCRIPTION: **12x12 Beige w/brown, white, blue & black specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1022**
MATERIAL DESCRIPTION: **12x12 Beige w/brown, white, blue & black specks VFT**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1022A**
MATERIAL DESCRIPTION: **12x12 Beige w/brown, white, blue & black specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**

MATERIAL QUANTITY: **1100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1022A**
MATERIAL DESCRIPTION: **12x12 Beige w/brown, white, blue & black specks VFT Mastic**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1023**
MATERIAL DESCRIPTION: **12x12 Purple VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1023**
MATERIAL DESCRIPTION: **12x12 Purple VFT**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1023A**
MATERIAL DESCRIPTION: **12x12 Purple VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1023A**
MATERIAL DESCRIPTION: **12x12 Purple VFT Mastic**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1024**
MATERIAL DESCRIPTION: **12x12 Peach w/blue & cream specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1024**
MATERIAL DESCRIPTION: **12x12 Peach w/blue & cream specks VFT**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1024A**
MATERIAL DESCRIPTION: **12x12 Peach w/blue & cream specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1024A**
MATERIAL DESCRIPTION: **12x12 Peach w/blue & cream specks VFT Mastic**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1025**
MATERIAL DESCRIPTION: **2x2 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1025**
MATERIAL DESCRIPTION: **2x2 Ceiling Tile**
MATERIAL LOCATION: **Room 101A (health office) -1938 Bldg**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1026**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101A (health office) north end of office -1938 Bldg**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1026**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Room 101A (health office) north end of office -1938 Bldg**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1027**
MATERIAL DESCRIPTION: **1x1 Ceiling Tile w/ white grooves & holes**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement lunchroom, teacher's lunch room, serving line room, kitchen -1938 Bldg**

MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1027**
MATERIAL DESCRIPTION: **1x1 Ceiling Tile w/ white grooves & holes**
MATERIAL LOCATION: **Basement lunchroom, teacher's lunch room, serving line room, kitchen -1938 Bldg**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1027A**
MATERIAL DESCRIPTION: **1x1 Ceiling Tile w/ white grooves & holes pucks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement lunchroom, teacher's lunch room, serving line room, kitchen -1938 Bldg**

MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **HA-1027A**
MATERIAL DESCRIPTION: **1x1 Ceiling Tile w/ white grooves & holes pucks**
MATERIAL LOCATION: **Basement lunchroom, teacher's lunch room, serving line room, kitchen -1938 Bldg**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pump Room - 1898 Bldg.**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUIDLING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Pump Room - 1898 Bldg.**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **163**
MATERIAL DESCRIPTION: **Fume Hood**
MATERIAL LOCATION: **room 122 & 126 -1898 Bldg**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **163**
MATERIAL DESCRIPTION: **Fume Hood**
MATERIAL LOCATION: **room 122 & 126 -1898 Bldg**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **160A**
MATERIAL DESCRIPTION: **White w/ Speaks VFT Mastic**
MATERIAL LOCATION: **Room 122, 124 & 126 - Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **160A**
MATERIAL DESCRIPTION: **White w/ Speaks VFT Mastic**
MATERIAL LOCATION: **Room 122, 124 & 126 - Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **161A**
MATERIAL DESCRIPTION: **Beige W/ Speaks VFT Mastic**
MATERIAL LOCATION: **Room 122, 124 & 126 -1898 Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **161A**
MATERIAL DESCRIPTION: **Beige W/ Speaks VFT Mastic**
MATERIAL LOCATION: **Room 122, 124 & 126 -1898 Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **159A**
MATERIAL DESCRIPTION: **Black w/ Speaks VFT Mastic**
MATERIAL LOCATION: **Room 122, 124 & 126 -1898 Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **159A**
MATERIAL DESCRIPTION: **Black w/ Speaks VFT Mastic**
MATERIAL LOCATION: **Room 122, 124 & 126 -1898 Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **160**
MATERIAL DESCRIPTION: **White w/ Speaks VFT**
MATERIAL LOCATION: **Room 122, 124 & 126 -1898 Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **160**
MATERIAL DESCRIPTION: **White w/ Speaks VFT**
MATERIAL LOCATION: **Room 122, 124 & 126 -1898 Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **159**
MATERIAL DESCRIPTION: **Black w/ Speaks VFT**
MATERIAL LOCATION: **Room 122, 124 & 126 -1898 Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **159**
MATERIAL DESCRIPTION: **Black w/ Speaks VFT**
MATERIAL LOCATION: **Room 122, 124 & 126 -1898 Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **08/26/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **162**
MATERIAL DESCRIPTION: **Counter & tabletops**
MATERIAL LOCATION: **room 122 & 126 -1898 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/05/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **162**
MATERIAL DESCRIPTION: **Counter & tabletops**
MATERIAL LOCATION: **room 122 & 126 -1898 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 08/26/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**
SCHOOL NAME: **Lakeview High School** INSPECTION DATE: **8/5/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **161**
MATERIAL DESCRIPTION: **Beige W/ Speaks VFT**
MATERIAL LOCATION: **Room 113D, 122, 124 & 126 - 1898 Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **08/05/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46211** BUILDING ID: **1430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lakeview High School** REVIEW DATE: **8/26/2022**
ADDRESS: **4015 N. Ashland** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **161**
MATERIAL DESCRIPTION: **Beige W/ Speaks VFT**
MATERIAL LOCATION: **Room 113D, 122, 124 & 126 - 1898 Bldg**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 08/26/2022

APPENDIX B

Inspector and Management Planner Licenses



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

David Avila

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/9/2022

Exam Date: 9/9/2022

Expiration Date: 9/9/2023

Certificate Number: BIR2209092141


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

David Avila

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/10/2021

Exam Date: 9/10/2021

Expiration Date: 9/10/2022

Certificate Number: BIR2109101942

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

2/28/2022



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 11093

ISSUED
2/28/2022

EXPIRES
05/15/2023

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health





ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p>		<p>TC EXPIRES</p>
<p>ID NUMBER 100 - 11093</p>	<p>ISSUED 2/28/2022</p>	<p>EXPIRES 05/15/2023</p>	<p>INSPECTOR</p>		<p>9/10/2022</p>
<p>DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health</p> 			<p>PROJECT MANAGER</p>		<p>9/11/2022</p>
			<p>AIR SAMPLING PROFESSIONAL</p>		
			<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562


Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

2/28/2022



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 04019

ISSUED
2/28/2022

EXPIRES
05/15/2023

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612



Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 04019	ISSUED 2/28/2022	EXPIRES 05/15/2023	INSPECTOR	11/1/2022
ARTURO SAENZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	11/1/2022
			AIR SAMPLING PROFESSIONAL	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES

Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed