

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0041  
SCHOOL NAME: Steinmetz High School  
ADDRESS OF SCHOOL: 3030 N. Mobile  
CITY: Chicago, IL, 60634

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/20/2020

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2022 ENROLLMENT 1124  
IDPH INSPECTOR LICENSE NUMBER: 100-18350  
IDPH LICENSED INSPECTOR NAME (Please Print): Joseph Hennigan  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



10/24/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Steinmetz High School**

3030 N. Mobile  
Chicago, IL, 60634

Unit: 46291  
Building ID: 1560

IDPH ID Number: 14-016-2990-0041

**REPORT DATE:**

Monday, October 24, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**Specialty Consulting, Inc.**

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

10/24/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 46291                      Region: 02                      IDPH ID: 14-016-2990-0041

School: Steinmetz High School                      Building ID: 1560

Address: 3030 N. Mobile

Chicago, IL, 60634

Building Contact: Wrenn, Charles

Contact Phone: 7737367937

Current Building Owners: Chicago Public Schools

Reinspection Date: 10/1/2022

Review Date: 10/24/2022

Inspector: Joseph Hennigan

Inspector IDPH License: 100-18350

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,  
Specialty Consulting, Inc.



Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: October 24, 2022

RE: Steinmetz High School, Unit 46291  
3030 N. Mobile  
Chicago, IL, 60634

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Steinmetz High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Steinmetz High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Steinmetz High School                      Unit: 46291                      Region: 02  
Address: 3030 N. Mobile                      Chicago, IL, 60634  
IDPH ID: 14-016-2990-0041                      Building ID: 1560  
Contact: Wrenn, Charles                      Phone: 7737367937

### 2. Description of Facility

Original Construction: 1934                      Additional Construction:  
Total Square Footage: 384200                      No of Floors: 4  
Current Occupancy: 1124

### 3. LEA Designated Person

Contact: Richard J.Schleyer                      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren Street  
Phone: (312) 319-7575                      Fax: (312) 319-7580

### 5. Inspector

Inspector Name: Joseph Hennigan




Signature:  
Date: 10/1/2022

Inspector IDPH license # 100-18350  
Reinspection Date: 10/1/2022

### 6. Management Planner

Management Planner Name: Jigar Shah



Signature:  
Date: 10/24/2022

Management Planner IDPH license # 100-07342

### 7. Review Date: 10/24/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/24/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Steinmetz High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1560:

015	9"x9" Brown Streaked Floor Tile
043	Hard Plaster
072	9"x9" Brown Streaked Floor Tile Mastic
073	12"x12" Tan Speckled Floor Tile Mastic
075	1'x1' Ceiling Tile Mastic
078	12"x 24" Brown w/ Dark Brown Streaks Floor Tile (Not Observed)
087	12"x12" Off White w/ Brown Streaks Floor Tile
088	12"x12" Off White w/ Brown Streaks Floor Tile Mastic

091	12"x12" Off White Speckled Floor Tile Mastic
092	12"x12" Cream Speckled Floor Tile Mastic
093	9"x9" Taupe Floor Tile Mastic
097	9"x9" White Splotch Floor Tile Mastic
105	12"x12" Cream Speckled Floor Tile
106	9"x9" Taupe Floor Tile
109	9"x9" White Splotch Floor Tile
115	2' x 4' Cut Pattern Ceiling Tile
148	12 x 12 Gray with gray specks VFT
149	12 x 12 Gray with Gray Specks Mastic



B. The following new homogenous areas have been identified for Building 1560:

160	12x12 Gray w/ Gray Specks VFT
161	12x12 Dark Gray w/ Gray Specks VFT
162	12x12 White w/ Gray Specks VFT
163	12x12 VFT MASTIC
164	9x9 Red VFT
165	9x9 Black VFT
166	9x9 Red and Black VFT MASTIC

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

002	12"x12" Tan Speckled Floor Tile
020	1 x 1 Ceiling Tile
043	Hard Plaster
075	1'x1' Ceiling Tile Mastic
076	Gray w/ White Streaks Linoleum (NOT OBSERVED)
079	Gray w/ White Streaks Linoleum Mastic
082	Lab Table Tops
085	12"x12" Gray w/ White Specks Floor Tile
086	12"x12" Gray w/ White Specks Floor Tile Mastic
089	Marble Linoleum
090	Marble Linoleum Mastic
094	12"x12" Brown Speckled Floor Tile Mastic
102	12"x12" Gray Spotted Floor Tile
103	12"x12" Gray Spotted Floor Tile Mastic
104	12"x12' Off White Speck Floor Tile
107	12"x12" Brown Speckled Floor Tile (Not Observed)
113	Carpet Mastic
114	Carpet Mastic
115	2' x 4' Cut Pattern Ceiling Tile
116	Beige Sheet Flooring
117	Mastic associated with Beige Sheet Flooring
118	6" Brown Vinyl Baseboard
119	Glue associated with 6" Brown Vinyl Baseboard
120	2' x 2' Ceiling Tile With Pinholes
121	12" x 12" White w/Gray Specks Floor Tile
122	Mastic Associated With 12" x 12" White w/Gray Specks Floor Tile
123	4" Tan Vinyl Baseboard
124	Glue Associated With 4" Tan Vinyl Baseboard
125	Red Linoleum
126	Mastic Associated With Red Linoleum
127	Blue Linoleum
128	Mastic Associated With Blue Linoleum
129	Mastic Assoc. w/ 2'x 2' Rubber Flooring Squares
130	2'x 2' Gray Rubber Flooring Squares
131	2' x 4' Drywall Ceiling Tiles
132	12"x12" Gray w/ White Speckles Floor Tile
133	Mastic Assoc. w/12"x12" Gray w/ White Speckles Floor Tile
134	12"x 12" White w/ Brown Specks Floor Tile
135	Mastic Associated w/ 12"x12" White w/ Brown

	Specks Floor Tile
136	12"x12" Dark Gray Floor Tile
137	Mastic Associated w/ 12"x12" Dark Gray Floor Tile
138	6"x6" Black Floor Tile
139	6"x6" Black Floor Tile Mastic
140	6"x6" White Floor Tile
141	6"x6" White Floor Tile Mastic
142	12"x12" Tan Floor Tile
143	12"x12" Tan Floor Tile Mastic
144	2 x 4 Ceiling Tile white with swirls
145	Black Lab Counter Tops
146	12 x 12 VFT White with Black Specks
147	12 x 12 VFT White with Black Specks Mastic
148	12 x 12 Gray with gray specks VFT
149	12 x 12 Gray with Gray Specks Mastic
150	2 x 4 Ceiling Tile White with Pin Hole
151	2 x 2 Ceiling Tile White
152	Fume Hood
153	Red Fire Stop
154	Tansite Panelling
155	12"x12" Gray w/ White Specks VFT
155A	12"x12" Gray w/ White Specks VFT Mastic
156	Decorative Precast Acoustic Plaster Panels
157	2'x2' Pinhole Ceiling Tile
158	Drywall System
159	12"x12" Off White w/ Beige Specks VFT
159A	12"x12" Off White w/Beige Specks VFT Mastic
160	12x12 Gray w/ Gray Specks VFT
161	12x12 Dark Gray w/ Gray Specks VFT
162	12x12 White w/ Gray Specks VFT
163	12x12 VFT MASTIC
164	9x9 Red VFT
165	9x9 Black VFT
166	9x9 Red and Black VFT MASTIC
A	MJP E/F/V on Fiberglass Pipe Insulation
B	Terrazzo

The following areas were deemed to be inaccessible:

079	Gray w/ White Streaks Linoleum Mastic
090	Marble Linoleum Mastic
094	12"x12" Brown Speckled Floor Tile Mastic
103	12"x12" Gray Splotched Floor Tile Mastic
113	Carpet Mastic
139	6"x6" Black Floor Tile Mastic
141	6"x6" White Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Joseph Hennigan, IDPH License # 100-18350. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	8/28/2019
	8/28/2019
	8/28/2019
	8/28/2019

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Steinmetz High School Building 1560 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Steinmetz High School Unit 46291 Building ID 1560

Address 3030 N. Mobile Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
002	12"x12" Tan Speckled Floor Tile	34,000	SF	1st through 3rd Floor Corridor, Auditorium,311	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
015	9"x9" Brown Streaked Floor Tile	1,800	SF	North Band Room & Room 401	CHR	MISC	N	LOC	5		Yes	ACBM with potential for significant damage	5	HIGH
020	1 x 1 Ceiling Tile	4,500	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
021	2'x2' Transite Ceiling Tile	150	SF	Dishwashing Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
026	Lab Fume Hood Lining	60	SF	Office Between Room 322 & 320	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
043	Hard Plaster	110,000	SF	Throughout	ASSUMED	SURFACE	Y	DIST	650		Yes	ACBM with potential for significant damage	10	HIGH
072	9"x9" Brown Streaked Floor Tile Mastic	1,800	SF	North Band Room & Room 401	CHR	MISC	N	LOC	5		Yes	ACBM with potential for significant damage	5	HIGH
073	12"x12" Tan Speckled Floor Tile Mastic	8,000	SF	1st through 3rd Floor Corridor, Auditorium, Rm 311	CHR	MISC	N	DIST	100		Yes	ACBM with potential for significant damage	5	HIGH
075	1'x1' Ceiling Tile Mastic	4,500	SF	Throughout	ASSUMED	MISC	N	LOC	1		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
076	Gray w/ White Streaks Linoleum (NOT OBSERVED)	4,500	SF	Room 214, 216, 314, 316, 318	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
077	9"x9" Brown w/ Dark Brown Streaks Floor Tile (Not Observed)	1,200	SF	Room 128 (Under Carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		Low
078	12"x 24" Brown w/ Dark Brown Streaks Floor Tile (Not Observed)	1,200	SF	Room 128 (Under Carpet)	CHR	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
079	Gray w/ White Streaks Linoleum Mastic	4,500	SF	Room 214, 216, 314, 316, 318	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
082	Lab Table Tops	290	SF	Room 114, 314, 320 & 322	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
083	9"x9" Brown w/ Dark Brown Streaks Floor Tile Mastic (Not Observed)	1,200	SF	Room 128 (Under Carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
084	12"x 24" Brown w/ Dark Brown Streaks Floor Tile Mastic (NOT OBSERVED)	170	SF	Room 128 (Under Carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
085	12"x12" Gray w/ White Specks Floor Tile	450	SF	Room 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
086	12"x12" Gray w/ White Specks Floor Tile Mastic	450	SF	Room 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
087	12"x12" Off White w/ Brown Streaks Floor Tile	200	SF	Corridor Near Room 400, Office Next to Room 400	CHR	MISC	N	LOC	10		Yes	ACBM with potential for significant damage	5	HIGH
088	12"x12" Off White w/ Brown Streaks Floor Tile Mastic	200	SF	Corridor Near Room 400, Office Next to	CHR	MISC	N	LOC	10		Yes	ACBM with potential for significant damage	5	HIGH

# Chicago Public Schools

School Steinmetz High School Unit 46291 Building ID 1560

Address 3030 N. Mobile Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room 400										
089	Marble Linoleum	550	SF	Room 219, 328, 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
090	Marble Linoleum Mastic	550	SF	Room 219, 328, 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
091	12"x12" Off White Speckled Floor Tile Mastic	3,000	SF	1st through 3rd Floor Corridors, 311, 309, 104A Closet, Main Office	CHR	MISC	N	DIST	100		Yes	ACBM with potential for significant damage	5	HIGH
092	12"x12" Cream Speckled Floor Tile Mastic	3,420	SF	Rooms 119, 108, 104, 136, 199, 401, 403, Lunchroom, MDF	CHR	MISC	N	DIST	50		Yes	ACBM with potential for significant damage	5	HIGH
093	9"x9" Taupe Floor Tile Mastic	2,500	SF	Rooms 212, 312, 322, Office between Room 322 & 320	CHR	MISC	N	LOC	245		Yes	ACBM with potential for significant damage	5	HIGH
094	12"x12" Brown Speckled Floor Tile Mastic	750	SF	Room 130, 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
095	9"x9" Green Floor Tile Mastic	4,000	SF	Lunchrooms (127), Serving Area, Kitchen (1000 SF ABATED)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
096	12"x12" Tan w/ White Specks Floor Tile Mastic	750	SF	Room 220	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
097	9"x9" White Splotch Floor Tile Mastic	1,200	SF	Room 319, 319A	CHR	MISC	N	LOC	75		Yes	ACBM with potential for significant damage	5	HIGH
100	Exterior Window Caulk-(ABATED 2010)			Exterior Windows	ABATED	MISC		None				Any remaining friable ACBM or friable suspect ACBM		Low
101	Interior Window Caulk (ABATED 2010)			Interior Windows	ABATED	MISC		None				Any remaining friable ACBM or friable suspect ACBM		Low
102	12"x12" Gray Splotched Floor Tile	2,000	SF	1st Floor Mens and Womens Faculty Toilets, Room 320,220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
103	12"x12" Gray Splotched Floor Tile Mastic	2,000	SF	1st Floor Mens and Womens Faculty Toilets, Room 320	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12"x12" Off White Speck Floor Tile	3,000	SF	1st through 3rd Floor Corridor, 311	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
105	12"x12" Cream Speckled Floor Tile	3,420	SF	Rooms 119, 108, 104, 136, 401, 403, Lunchroom, MDF,	CHR	MISC	N	DIST	50		Yes	ACBM with potential for significant damage	5	HIGH



# Chicago Public Schools

School Steinmetz High School Unit 46291 Building ID 1560

Address 3030 N. Mobile Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				199										
106	9"x9" Taupe Floor Tile	2,500	SF	Rooms 212, 312, & 322, Office Between Room 322 & 320, Outside Office from left	CHR	MISC	N	LOC	245		Yes	ACBM with potential for significant damage	5	HIGH
107	12"x12" Brown Speckled Floor Tile (Not Observed)	750	SF	Room 130, 201 (Not Observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	9"x9" Green Floor Tile	5,000	SF	Lunchrooms, Serving Area, Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
109	9"x9" White Splotch Floor Tile	1,200	SF	Room 319,319A	CHR	MISC	N	LOC	75		Yes	ACBM with potential for significant damage	5	HIGH
110	9"x9" Green w/ White Streaks Floor Tile	2,000	SF	Room 230 (Not Observed), Fire Alarm Room by Boiler Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
111	9"x9" Green w/ White Streaks Floor Tile Mastic	2,000	SF	Rooms 125, 230 (Not Observed), Fire Alarm Room by Boiler Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112	12"x12" Tan w/ White Specks Floor Tile Mastic	750	SF	Room 220	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	Carpet Mastic	3,000	SF	Main Office, Principals Office, Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	Carpet Mastic	2,800	SF	Rooms 104, 106, 118, & 120A & B, 122 (Small Auditorium)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	2' x 4' Cut Pattern Ceiling Tile	5,400	SF	Labs (112, 112A, 114, 116, 214, 216, 218, 314, 316, 318)	ASSUMED	MISC	Y	LOC	5		Yes	Any remaining friable ACBM or friable suspect ACBM	10	MODERATE
116	Beige Sheet Flooring	4,100	SF	Labs 112, 114, 214, 216, 314, 316	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
117	Mastic associated with Beige Sheet Flooring	4,100	SF	Labs (112, 114, 214, 216, 314, 316)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	6" Brown Vinyl Baseboard	420	LF	Labs 112, 112A, 114, 116, 214, 216, 218, 314, 316, 318	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
119	Glue associated with 6" Brown Vinyl Baseboard	420	LF	Labs 112, 114, 116, 214, 216, 218, 314, 316, 318	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
120	2' x 2' Ceiling Tile With Pinholes	16,000	SF	Two Mobile	ASSUMED	MISC	Y	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Steinmetz High School Unit 46291 Building ID 1560

Address 3030 N. Mobile Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Classrooms (Trailers) Located on the South Side of Property								potential for damage		
121	12" x 12" White w/Gray Specks Floor Tile	16,000	SF	Two Mobile Classrooms (Trailers) Located on the South Side of Property	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
122	Mastic Associated With 12" x 12" White w/Gray Specks Floor Tile	16,000	SF	Two Mobile Classrooms (Trailers) Located on the South Side of Property	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
123	4" Tan Vinyl Baseboard	700	LF	Two Mobile Classrooms (Trailers) Located on the South Side of Property	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
124	Glue Associated With 4" Tan Vinyl Baseboard	700	LF	Two Mobile Classrooms (Trailers) Located on the South Side of Property	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
125	Red Linoleum	600	SF	Girls Restrooms in the Two Mobile Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
126	Mastic Associated With Red Linoleum	600	SF	Girls Restrooms in the Two Mobile Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
127	Blue Linoleum	400	SF	Boys Restroom in the Two Mobile Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
128	Mastic Associated With Blue Linoleum	400	SF	Boys Restrooms in the Two Mobile Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
129	Mastic Assoc. w/ 2' 2' Rubber Flooring Squares	3,400	SF	Dish Wash Area, Weight Room, Boys Locker Room, Equipment Room, Team A & B Rooms & Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
130	2'x 2' Gray Rubber Flooring Squares	3,400	SF	Dish Wash Area, Weight Room, Boys Locker Room,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

School Steinmetz High School Unit 46291 Building ID 1560

Address 3030 N. Mobile Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Equipment Room, Team A & B Rooms & Corridor										
131	2' x 4' Drywall Ceiling Tiles	1,000	SF	Dish Wash Area	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
132	12"x12" Gray w/ White Speckles Floor Tile	150	SF	Fire Alarm Room near Engineers Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
133	Mastic Assoc. w/12"x12" Gray w/ White Speckles Floor Tile	150	SF	Fire Alarm Room next to Engineers Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	12"x 12" White w/ Brown Specks Floor Tile	1,350	SF	Room 218, 132, Teachers Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
135	Mastic Associated w/ 12"x12" White w/ Brown Specks Floor Tile	1,350	SF	Room 218, 132, Teachers Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
136	12"x12" Dark Gray Floor Tile	600	SF	2nd Floor Laundry Room near Pool/Locker Rms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
137	Mastic Associated w/ 12"x12" Dark Gray Floor Tile	400	SF	2nd Floor Laundry Room near Pool/Locker Rms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
138	6"x6" Black Floor Tile	300	SF	Rooms 224 & 229	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
139	6"x6" Black Floor Tile Mastic	300	SF	Rooms 224 & 229	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
140	6"x6" White Floor Tile	300	SF	Rooms 224 & 229	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
141	6"x6" White Floor Tile Mastic	300	SF	Rooms 224 & 229	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142	12"x12" Tan Floor Tile	750	SF	Room 318	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
143	12"x12" Tan Floor Tile Mastic	750	SF	Room 318	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
144	2 x 4 Ceiling Tile white with swirls	18,000	SF	Rms. 400 and 401, 3rd Fl. Corridor, 310, 308, 306, 304, 302, 300, 333, 399, 301, 321, 323,325,330,332, 325, 303, 353, 305, 319	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
145	Black Lab Counter Tops	2,100	SF	Rm 316, 314, 214,	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Steinmetz High School Unit 46291 Building ID 1560

Address 3030 N. Mobile Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				216, 114 & 114A								potential for damage		
146	12 x 12 VFT White with Black Specks	1,200	SF	Rm 211 & 116	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
147	12 x 12 VFT White with Black Specks Mastic	1,200	SF	Rm 211 & 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
148	12 x 12 Gray with gray specks VFT	400	SF	Rm 230	ASSUMED	MISC	N	LOC	8		Yes	ACBM with potential for significant damage	5	MODERATE
149	12 x 12 Gray with Gray Specks Mastic	400	SF	Rm 230	ASSUMED	MISC	N	LOC	8		Yes	ACBM with potential for significant damage	5	MODERATE
150	2 x 4 Ceiling Tile White with Pin Hole	2,000	SF	Pool	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
151	2 x 2 Ceiling Tile White	2,500	SF	Rm 122 & 128	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
152	Fume Hood	40	SF	112A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
153	Red Fire Stop	10	LF	Pump room, Throughout basement	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
154	Tansite Panelling	44	SF	Unfinished pipe space	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
155	12"x12" Gray w/ White Specks VFT	3,000	SF	Rooms 320, 322, Office between 320 & 322, 114	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
155A	12"x12" Gray w/ White Specks VFT Mastic	3,000	SF	Rooms 320, 322, Office between 320 & 322, 114	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
156	Decorative Precast Acoustic Plaster Panels	600	SF	Room 200	ASSUMED	SURFACE	N	LOC	15		No	ACBM with the potential for damage	10	LOW
157	2'x2' Pinhole Ceiling Tile	300	SF	320, 322, Office Between 320 & 322, 114	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
158	Drywall System	2,000	SF	Wall between room 119 & 199, Boiler room, Mezzanine, 333, 401, 400, Elevator lobby on 4th Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
159	12"x12" Off White w/ Beige Specks VFT	300	SF	Room 333 and Elevator Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
159A	12"x12" Off White w/Beige Specks VFT Mastic	300	SF	Room 333 and Elevator Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
160	12x12 Gray w/ Gray Specks VFT	500	SF	201	ASSUMED	MISC	N	NONE						LOW
161	12x12 Dark Gray w/ Gray Specks VFT	500	SF	#201	ASSUMED	MISC	N	NONE						LOW
162	12x12 White w/ Gray Specks VFT	500	SF	#201	ASSUMED	MISC	N	NONE						LOW

# Chicago Public Schools

School Steinmetz High School Unit 46291 Building ID 1560

Address 3030 N. Mobile Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
163	12x12 VFT MASTIC	1,500	SF	#201 Computer Lab	ASSUMED	MISC	N	NONE						LOW
164	9x9 Red VFT	10	SF	Assistant Principal's Office Closet #106	ASSUMED	MISC	N	NONE						LOW
165	9x9 Black VFT	10	SF	Assistant Principal's Office Closet #106	ASSUMED	MISC	N	NONE						LOW
166	9x9 Red and Black VFT MASTIC	20	SF	Assistant Principal's Office Closet #106	ASSUMED	MISC	N	NONE						LOW
A	MJP E/F/V on Fiberglass Pipe Insulation	604	LF	Pipe Chase in Room 317, 220	ASSUMED	TSI	Y	NONE	0		No			MODERATE
B	Terrazzo	10,000	SF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

School Steinmetz High School Unit 46291 Building ID 1560  
Address 3030 N. Mobile Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>10/1/2022</b>
Inspector Name <b>Joseph Hennigan</b>
<b>100-18350</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
002	
015	Mastic exposed in #401
020	
021	
026	
043	Damage noted in #357, #319, #399, #323, #325, #18 inner and outer stairwells, #207, #205, #230, 2nd floor girl's bathroom, #200 library, boy's locker room, girl's locker room, coach's office and bathroom, #134 kitchen, bathroom, and hallway, #129, #104
072	Mastic exposed in #401
073	Damage in 1st, 2nd, and 3rd floor corridors
075	Fallen tile w/ glue puck exposed in 1st floor unisex bathroom
076	
077	
078	
079	
082	New installation in #314
083	
084	
085	Material not in #114, observed in #116
086	Material not in #114, observed in #116
087	Broken and chipped tiles in #404
088	Broken and chipped tiles in #404
089	
090	

# Chicago Public Schools

School Steinmetz High School Unit 46291 Building ID 1560

Address 3030 N. Mobile Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
091	Damage in 1st, 2nd, and 3rd floor corridors
092	25 sf damage w/ mastic exposed in #119, 25 sf damage w/ mastic exposed in #199
093	850 sf abated in #322, 145 sf damaged with 25 sf missing and 100 sf repaired with exposed mastic in #312 and #212
094	
095	
096	Material was not in #320 but was observed in #220
097	Damaged tiles with mastic exposed in #319, #319A
100	
101	
102	
103	
104	
105	25 sf damage w/ mastic exposed in #119, 25 sf damage w/ mastic exposed in #199
106	850 sf abated in #322, 120 sf damage with 25 sf missing and 100 sf repaired with mastic exposed in #312 and #212
107	
108	
109	Damaged tiles with exposed mastic in #319, #319A
110	
111	
112	Material was not in #320 but was observed in #220
113	
114	
115	Water damage in #316
116	Not observed in #116
117	Not observed in #116
118	
119	

# Chicago Public Schools

School Steinmetz High School Unit 46291 Building ID 1560

Address 3030 N. Mobile Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	Not observed in #116
135	Not observed in #116
136	
137	
138	
139	
140	
141	
142	
143	
144	
145	
146	
147	
148	Damage w/ mastic exposed



# Chicago Public Schools

School Steinmetz High School Unit 46291 Building ID 1560

Address 3030 N. Mobile Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
149	Damage w/ mastic exposed
150	
151	
152	
153	
154	
155	
155A	
156	Water damage in library
157	
158	
159	
159A	
160	New installation
161	New installation
162	New installation
163	New installation, Mastic associated with HAs 160, 161, 162
164	Closet previously inaccessible
165	Closet previously inaccessible
166	Closet previously inaccessible
A	Added #220 and changed sf to lf
B	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Steinmetz High School

Unit 46291

Building ID 1560

Address 3030 N. Mobile

Chicago, IL, 60634

Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
002	12"x12" Tan Speckled Floor Tile	34,000	SF	1st through 3rd Floor Corridor, Auditorium,311	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
015	9"x9" Brown Streaked Floor Tile	1,800	SF	North Band Room & Room 401	Chrysotile	MISC	No	5	SF	5 ACBM with potential for significant damage	Remove
020	1 x 1 Ceiling Tile	4,500	SF	Throughout	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021	2'x2' Transite Ceiling Tile	150	SF	Dishwashing Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
026	Lab Fume Hood Lining	60	SF	Office Between Room 322 & 320	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
043	Hard Plaster	110,000	SF	Throughout	Assumed	SURFACE	Yes	650	SF	5 ACBM with potential for significant damage	Remove
072	9"x9" Brown Streaked Floor Tile Mastic	1,800	SF	North Band Room & Room 401	Chrysotile	MISC	No	5	SF	5 ACBM with potential for significant damage	Encapsulate
073	12"x12" Tan Speckled Floor Tile Mastic	8,000	SF	1st through 3rd Floor Corridor, Auditorium, Rm 311	Chrysotile	MISC	No	100	SF	5 ACBM with potential for significant damage	Remove
075	1'x1' Ceiling Tile Mastic	4,500	SF	Throughout	Assumed	MISC	No	1	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
076	Gray w/ White Streaks Linoleum (NOT OBSERVED)	4,500	SF	Room 214, 216, 314, 316, 318	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
077	9"x9" Brown w/ Dark Brown Streaks Floor Tile (Not Observed)	1,200	SF	Room 128 (Under Carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
078	12"x 24" Brown w/ Dark Brown Streaks Floor Tile (Not Observed)	1,200	SF	Room 128 (Under Carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
079	Gray w/ White Streaks Linoleum Mastic	4,500	SF	Room 214, 216, 314, 316, 318	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
082	Lab Table Tops	290	SF	Room 114, 314, 320 & 322	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
083	9"x9" Brown w/ Dark Brown Streaks Floor Tile Mastic (Not Observed)	1,200	SF	Room 128 (Under Carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
084	12"x 24" Brown w/ Dark Brown Streaks Floor Tile Mastic (NOT OBSERVED)	170	SF	Room 128 (Under Carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
085	12"x12" Gray w/ White Specks Floor Tile	450	SF	Room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
086	12"x12" Gray w/ White Specks Floor Tile Mastic	450	SF	Room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
087	12"x12" Off White w/ Brown Streaks Floor Tile	200	SF	Corridor Near Room 400, Office Next to Room 400	Chrysotile	MISC	No	10	SF	5 ACBM with potential for significant damage	Remove
088	12"x12" Off White w/ Brown Streaks Floor Tile Mastic	200	SF	Corridor Near Room 400, Office Next to Room 400	Chrysotile	MISC	No	10	SF	5 ACBM with potential for significant damage	Remove
089	Marble Linoleum	550	SF	Room 219, 328, 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
090	Marble Linoleum Mastic	550	SF	Room 219, 328, 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
091	12"x12" Off White Speckled Floor Tile Mastic	3,000	SF	1st through 3rd Floor Corridors, 311,	Chrysotile	MISC	No	100	SF	5 ACBM with potential for significant	Remove

# Chicago Public Schools

School Steinmetz High School

Unit 46291

Building ID 1560

Address 3030 N. Mobile

Chicago, IL, 60634

Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				309, 104A Closet, Main Office						damage	
092	12"x12" Cream Speckled Floor Tile Mastic	3,420	SF	Rooms 119, 108, 104, 136, 199, 401, 403, Lunchroom, MDF	Chrysotile	MISC	No	50	SF	5 ACBM with potential for significant damage	Remove
093	9"x9" Taupe Floor Tile Mastic	2,500	SF	Rooms 212, 312, 322, Office between Room 322 & 320	Chrysotile	MISC	No	245	SF	5 ACBM with potential for significant damage	Remove
094	12"x12" Brown Speckled Floor Tile Mastic	750	SF	Room 130, 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
095	9"x9" Green Floor Tile Mastic	4,000	SF	Lunchrooms (127), Serving Area, Kitchen (1000 SF ABATED)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
096	12"x12" Tan w/ White Specks Floor Tile Mastic	750	SF	Room 220	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
097	9"x9" White Splotch Floor Tile Mastic	1,200	SF	Room 319, 319A	Chrysotile	MISC	No	75	SF	5 ACBM with potential for significant damage	Remove
100	Exterior Window Caulk-(ABATED 2010)			Exterior Windows	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
101	Interior Window Caulk (ABATED 2010)			Interior Windows	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
102	12"x12" Gray Splotched Floor Tile	2,000	SF	1st Floor Mens and Womens Faculty Toilets, Room 320,220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	12"x12" Gray Splotched Floor Tile Mastic	2,000	SF	1st Floor Mens and Womens Faculty Toilets, Room 320	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12"x12" Off White Speck Floor Tile	3,000	SF	1st through 3rd Floor Corridor, 311	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12"x12" Cream Speckled Floor Tile	3,420	SF	Rooms 119, 108, 104, 136, 401, 403, Lunchroom, MDF, 199	Chrysotile	MISC	No	50	SF	5 ACBM with potential for significant damage	Remove
106	9"x9" Taupe Floor Tile	2,500	SF	Rooms 212, 312, & 322, Office Between Room 322 & 320, Outside Office from left	Chrysotile	MISC	No	245	SF	5 ACBM with potential for significant damage	Remove
107	12"x12" Brown Speckled Floor Tile (Not Observed)	750	SF	Room 130, 201 (Not Observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	9"x9" Green Floor Tile	5,000	SF	Lunchrooms, Serving Area, Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	9"x9" White Splotch Floor Tile	1,200	SF	Room 319,319A	Chrysotile	MISC	No	75	SF	5 ACBM with potential for significant damage	Remove
110	9"x9" Green w/ White Streaks Floor Tile	2,000	SF	Room 230 (Not Observed), Fire Alarm Room by Boiler Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	9"x9" Green w/ White Streaks Floor Tile Mastic	2,000	SF	Rooms 125, 230 (Not Observed), Fire Alarm Room by Boiler Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12"x12" Tan w/ White Specks Floor Tile Mastic	750	SF	Room 220	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	Carpet Mastic	3,000	SF	Main Office, Principals Office, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	Carpet Mastic	2,800	SF	Rooms 104, 106, 118, & 120A & B, 122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Steinmetz High School

**Unit** 46291

**Building ID** 1560

**Address** 3030 N. Mobile

Chicago, IL, 60634

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				(Small Auditorium)							
115	2' x 4' Cut Pattern Ceiling Tile	5,400	SF	Labs (112, 112A, 114, 116, 214, 216, 218, 314, 316, 318)	Assumed	MISC	Yes	5	SF	7 Any remaining friable ACBM or friable suspect ACBM	Remove
116	Beige Sheet Flooring	4,100	SF	Labs 112, 114, 214, 216, 314, 316	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	Mastic associated with Beige Sheet Flooring	4,100	SF	Labs (112, 114, 214, 216, 314, 316)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	6" Brown Vinyl Baseboard	420	LF	Labs 112, 112A, 114, 116, 214, 216, 218, 314, 316, 318	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
119	Glue associated with 6" Brown Vinyl Baseboard	420	LF	Labs 112, 114, 116, 214, 216, 218, 314, 316, 318	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
120	2' x 2' Ceiling Tile With Pinholes	16,000	SF	Two Mobile Classrooms (Trailers) Located on the South Side of Property	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12" x 12" White w/Gray Specks Floor Tile	16,000	SF	Two Mobile Classrooms (Trailers) Located on the South Side of Property	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	Mastic Associated With 12" x 12" White w/Gray Specks Floor Tile	16,000	SF	Two Mobile Classrooms (Trailers) Located on the South Side of Property	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	4" Tan Vinyl Baseboard	700	LF	Two Mobile Classrooms (Trailers) Located on the South Side of Property	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
124	Glue Associated With 4" Tan Vinyl Baseboard	700	LF	Two Mobile Classrooms (Trailers) Located on the South Side of Property	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
125	Red Linoleum	600	SF	Girls Restrooms in the Two Mobile Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
126	Mastic Associated With Red Linoleum	600	SF	Girls Restrooms in the Two Mobile Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127	Blue Linoleum	400	SF	Boys Restroom in the Two Mobile Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
128	Mastic Associated With Blue Linoleum	400	SF	Boys Restrooms in the Two Mobile Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
129	Mastic Assoc. w/ 2'x 2' Rubber Flooring Squares	3,400	SF	Dish Wash Area, Weight Room, Boys Locker Room, Equipment Room, Team A & B Rooms & Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
130	2'x 2' Gray Rubber Flooring Squares	3,400	SF	Dish Wash Area, Weight Room, Boys Locker Room, Equipment Room, Team A & B Rooms & Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131	2' x 4' Drywall Ceiling Tiles	1,000	SF	Dish Wash Area	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132	12"x12" Gray w/ White Speckles Floor Tile	150	SF	Fire Alarm Room near Engineers Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
133	Mastic Assoc. w/12"x12" Gray w/ White Speckles	150	SF	Fire Alarm Room next to Engineers	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Steinmetz High School

Unit 46291

Building ID 1560

Address 3030 N. Mobile

Chicago, IL, 60634

Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Floor Tile			Office							
134	12"x12" White w/ Brown Specks Floor Tile	1,350	SF	Room 218, 132, Teachers Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	Mastic Associated w/ 12"x12" White w/ Brown Specks Floor Tile	1,350	SF	Room 218, 132, Teachers Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	12"x12" Dark Gray Floor Tile	600	SF	2nd Floor Laundry Room near Pool/Locker Rms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	Mastic Associated w/ 12"x12" Dark Gray Floor Tile	400	SF	2nd Floor Laundry Room near Pool/Locker Rms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	6"x6" Black Floor Tile	300	SF	Rooms 224 & 229	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
139	6"x6" Black Floor Tile Mastic	300	SF	Rooms 224 & 229	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	6"x6" White Floor Tile	300	SF	Rooms 224 & 229	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
141	6"x6" White Floor Tile Mastic	300	SF	Rooms 224 & 229	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142	12"x12" Tan Floor Tile	750	SF	Room 318	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143	12"x12" Tan Floor Tile Mastic	750	SF	Room 318	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	2 x 4 Ceiling Tile white with swirls	18,000	SF	Rms. 400 and 401, 3rd Fl. Corridor, 310, 308, 306, 304, 302, 300, 333, 399, 301, 321, 323,325,330,332, 325, 303, 353, 305, 319	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	Black Lab Counter Tops	2,100	SF	Rm 316, 314, 214, 216, 114 & 114A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
146	12 x 12 VFT White with Black Specks	1,200	SF	Rm 211 & 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
147	12 x 12 VFT White with Black Specks Mastic	1,200	SF	Rm 211 & 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148	12 x 12 Gray with gray specks VFT	400	SF	Rm 230	Assumed	MISC	No	8	SF	5 ACBM with potential for significant damage	Remove
149	12 x 12 Gray with Gray Specks Mastic	400	SF	Rm 230	Assumed	MISC	No	8	SF	5 ACBM with potential for significant damage	Remove
150	2 x 4 Ceiling Tile White with Pin Hole	2,000	SF	Pool	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151	2 x 2 Ceiling Tile White	2,500	SF	Rm 122 & 128	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152	Fume Hood	40	SF	112A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153	Red Fire Stop	10	LF	Pump room, Throughout basement	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
154	Tansite Panelling	44	SF	Unfinished pipe space	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155	12"x12" Gray w/ White Specks VFT	3,000	SF	Rooms 320, 322, Office between 320 & 322, 114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155A	12"x12" Gray w/ White Specks VFT Mastic	3,000	SF	Rooms 320, 322, Office between 320 & 322, 114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
156	Decorative Precast Acoustic Plaster Panels	600	SF	Room 200	Assumed	SURFACE	No	15	SF	6 ACBM with the potential for damage	Remove

# Chicago Public Schools

School Steinmetz High School

Unit 46291

Building ID 1560

Address 3030 N. Mobile

Chicago, IL, 60634

Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
157	2'x2' Pinhole Ceiling Tile	300	SF	320, 322, Office Between 320 & 322, 114	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
158	Drywall System	2,000	SF	Wall between room 119 & 199, Boiler room, Mezzanine, 333, 401, 400, Elevator lobby on 4th Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159	12"x12" Off White w/ Beige Specks VFT	300	SF	Room 333 and Elevator Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159A	12"x12" Off White w/Beige Specks VFT Mastic	300	SF	Room 333 and Elevator Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
160	12x12 Gray w/ Gray Specks VFT	500	SF	201	Assumed	MISC	No		SF		Follow O&M Plan
161	12x12 Dark Gray w/ Gray Specks VFT	500	SF	#201	Assumed	MISC	No		SF		Follow O&M Plan
162	12x12 White w/ Gray Specks VFT	500	SF	#201	Assumed	MISC	No		SF		Follow O&M Plan
163	12x12 VFT MASTIC	1,500	SF	#201 Computer Lab	Assumed	MISC	No		SF		Follow O&M Plan
164	9x9 Red VFT	10	SF	Assistant Principal's Office Closet #106	Assumed	MISC	No		SF		Follow O&M Plan
165	9x9 Black VFT	10	SF	Assistant Principal's Office Closet #106	Assumed	MISC	No		SF		Follow O&M Plan
166	9x9 Red and Black VFT MASTIC	20	SF	Assistant Principal's Office Closet #106	Assumed	MISC	No		SF		Follow O&M Plan
A	MJP E/F/V on Fiberglass Pipe Insulation	604	LF	Pipe Chase in Room 317, 220	Assumed	TSI	Yes	0	LF		Follow O&M Plan
B	Terrazzo	10,000	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Steinmetz High School

**Unit** 46291

**Building ID** 1560

**Address** 3030 N. Mobile

Chicago, IL, 60634

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

*Management Planner's Comments Summarized at the End of the Report*

Review Date	10/24/2022
Manager Planner Name	Jigar Shah
100-07342	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
002	
015	Remove Damaged ACM ASAP
020	
021	
026	
043	Sample material, Remove Damaged ACM ASAP
072	encapsulate with new non-ACM tiles ASAP
073	Remove Damaged ACM ASAP
075	sample material, remove damaged/broken ACM ASAP
076	
077	
078	
079	
082	
083	
084	
085	
086	
087	Remove Damaged ACM ASAP
088	Remove Damaged ACM ASAP
089	
090	



# Chicago Public Schools

**School** Steinmetz High School

**Unit** 46291

**Building ID** 1560

**Address** 3030 N. Mobile

Chicago, IL, 60634

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
091	Remove Damaged ACM ASAP
092	Remove Damaged ACM ASAP
093	Remove Damaged ACM ASAP
094	
095	
096	
097	Remove Damaged ACM
100	
101	
102	
103	
104	
105	Remove Damaged ACM ASAP
106	Remove Damaged ACM ASAP
107	
108	
109	Remove Damaged ACM ASAP
110	
111	
112	
113	
114	
115	Sample material, Remove Damaged ACM ASAP
116	
117	
118	
119	

# Chicago Public Schools

**School** Steinmetz High School

**Unit** 46291

**Building ID** 1560

**Address** 3030 N. Mobile

Chicago, IL, 60634

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	
143	
144	
145	
146	

# Chicago Public Schools

**School** Steinmetz High School

**Unit** 46291

**Building ID** 1560

**Address** 3030 N. Mobile

Chicago, IL, 60634

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
147	
148	sample material, Remove Damaged ACM ASAP
149	sample material, Remove Damaged ACM ASAP
150	
151	
152	
153	
154	
155	
155A	
156	sample material, remove damaged ACM asap
157	
158	
159	
159A	
160	
161	
162	
163	
164	
165	
166	
A	
B	

# Chicago Public Schools

**School** Steinmetz High School

**Unit** 46291

**Building ID** 1560

**Address** 3030 N. Mobile

Chicago, IL, 60634

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

***Management Planner's Comments Summarized at the End of the Report***

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

Specialty Consulting, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

Specialty Consulting, Inc.

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**  
MATERIAL DESCRIPTION: **12"x12" Tan Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st through 3rd Floor Corridor, Auditorium,311**  
MATERIAL QUANTITY: **34000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **002**  
MATERIAL DESCRIPTION: **12"x12" Tan Speckled Floor Tile**  
MATERIAL LOCATION: **1st through 3rd Floor Corridor, Auditorium,311**  
MATERIAL QUANTITY: **34000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**  
MATERIAL DESCRIPTION: **9"x9" Brown Streaked Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **North Band Room & Room 401**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Mastic exposed in #401**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **015**  
MATERIAL DESCRIPTION: **9"x9" Brown Streaked Floor Tile**  
MATERIAL LOCATION: **North Band Room & Room 401**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Remove Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020**  
MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **020**  
MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021**  
MATERIAL DESCRIPTION: **2'x2' Transite Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Dishwashing Room**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **021**  
MATERIAL DESCRIPTION: **2'x2' Transite Ceiling Tile**  
MATERIAL LOCATION: **Dishwashing Room**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**  
MATERIAL DESCRIPTION: **Lab Fume Hood Lining**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Office Between Room 322 & 320**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **026**  
MATERIAL DESCRIPTION: **Lab Fume Hood Lining**  
MATERIAL LOCATION: **Office Between Room 322 & 320**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**  
MATERIAL DESCRIPTION: **Hard Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Water  
Physical Damage**

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **110000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Damage noted in #357, #319, #399, #323, #325, #18 inner and outer stairwells, #207, #205, #230, 2nd floor girl's bathroom, #200 library, boy's locker room, girl's locker room, coach's office and bathroom, #134 kitchen, bathroom, and hallway, #129, #104**

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **043**  
MATERIAL DESCRIPTION: **Hard Plaster**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **110000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **650** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Sample material, Remove Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **072**  
MATERIAL DESCRIPTION: **9"x9" Brown Streaked Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **North Band Room & Room 401**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Mastic exposed in #401**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **072**  
MATERIAL DESCRIPTION: **9"x9" Brown Streaked Floor Tile Mastic**  
MATERIAL LOCATION: **North Band Room & Room 401**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

encapsulate with new non-ACM tiles ASAP

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **073**  
MATERIAL DESCRIPTION: **12"x12" Tan Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **1st through 3rd Floor Corridor, Auditorium, Rm 311**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage in 1st, 2nd, and 3rd floor corridors**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **073**  
MATERIAL DESCRIPTION: **12"x12" Tan Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **1st through 3rd Floor Corridor, Auditorium, Rm 311**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Remove Damaged ACM ASAP

Management Planner's Signature:  Date: 10/24/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **075**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Fallen tile w/ glue puck exposed in 1st floor unisex bathroom**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **075**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile Mastic**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

sample material, remove damaged/broken ACM ASAP

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **076**  
MATERIAL DESCRIPTION: **Gray w/ White Streaks Linoleum (NOT OBSERVED)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 214, 216, 314, 316, 318**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **076**  
MATERIAL DESCRIPTION: **Gray w/ White Streaks Linoleum (NOT OBSERVED)**  
MATERIAL LOCATION: **Room 214, 216, 314, 316, 318**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **077**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ Dark Brown Streaks Floor Tile (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 128 (Under Carpet)**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **077**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ Dark Brown Streaks Floor Tile (Not Observed)**  
MATERIAL LOCATION: **Room 128 (Under Carpet)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **078**  
MATERIAL DESCRIPTION: **12"x 24" Brown w/ Dark Brown Streaks Floor Tile (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 128 (Under Carpet)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **078**  
MATERIAL DESCRIPTION: **12"x 24" Brown w/ Dark Brown Streaks Floor Tile (Not Observed)**  
MATERIAL LOCATION: **Room 128 (Under Carpet)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **079**  
MATERIAL DESCRIPTION: **Gray w/ White Streaks Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 214, 216, 314, 316, 318**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **079**  
MATERIAL DESCRIPTION: **Gray w/ White Streaks Linoleum Mastic**  
MATERIAL LOCATION: **Room 214, 216, 314, 316, 318**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **082**  
MATERIAL DESCRIPTION: **Lab Table Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 114, 314, 320 & 322**  
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **New installation in #314**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **082**  
MATERIAL DESCRIPTION: **Lab Table Tops**  
MATERIAL LOCATION: **Room 114, 314, 320 & 322**  
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **083**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ Dark Brown Streaks Floor Tile Mastic (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 128 (Under Carpet)**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **083**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ Dark Brown Streaks Floor Tile Mastic (Not Observed)**  
MATERIAL LOCATION: **Room 128 (Under Carpet)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **084**  
MATERIAL DESCRIPTION: **12"x 24" Brown w/ Dark Brown Streaks Floor Tile Mastic (NOT OBSERVED)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 128 (Under Carpet)**  
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **084**  
MATERIAL DESCRIPTION: **12"x 24" Brown w/ Dark Brown Streaks Floor Tile Mastic (NOT OBSERVED)**  
MATERIAL LOCATION: **Room 128 (Under Carpet)**  
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **085**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Material not in #114, observed in #116**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **085**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks Floor Tile**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **086**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Material not in #114, observed in #116**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **086**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **087**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Corridor Near Room 400, Office Next to Room 400**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Broken and chipped tiles in #404**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **087**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Corridor Near Room 400, Office Next to Room 400**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Remove Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **088**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Brown Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Corridor Near Room 400, Office Next to Room 400**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Broken and chipped tiles in #404**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **088**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Corridor Near Room 400, Office Next to Room 400**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Remove Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **089**  
MATERIAL DESCRIPTION: **Marble Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 219, 328, 223**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **089**  
MATERIAL DESCRIPTION: **Marble Linoleum**  
MATERIAL LOCATION: **Room 219, 328, 223**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **090**  
MATERIAL DESCRIPTION: **Marble Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 219, 328, 223**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **090**  
MATERIAL DESCRIPTION: **Marble Linoleum Mastic**  
MATERIAL LOCATION: **Room 219, 328, 223**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **091**  
MATERIAL DESCRIPTION: **12"x12" Off White Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **1st through 3rd Floor Corridors, 311, 309, 104A Closet, Main Office**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage in 1st, 2nd, and 3rd floor corridors**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **091**  
MATERIAL DESCRIPTION: **12"x12" Off White Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **1st through 3rd Floor Corridors, 311, 309, 104A Closet, Main Office**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Remove Damaged ACM ASAP

Management Planner's Signature:  Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **092**  
MATERIAL DESCRIPTION: **12"x12" Cream Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Rooms 119, 108, 104, 136, 199, 401, 403, Lunchroom, MDF**  
MATERIAL QUANTITY: **3420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3420** DAMAGE UNITS: **SF**  
COMMENTS: **25 sf damage w/ mastic exposed in #119, 25 sf damage w/ mastic exposed in #199**

Inspector's Signature: 

Date: **10/01/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **092**  
MATERIAL DESCRIPTION: **12"x12" Cream Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 119, 108, 104, 136, 199, 401, 403, Lunchroom, MDF**  
MATERIAL QUANTITY: **3420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Remove Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: 10/24/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **093**  
MATERIAL DESCRIPTION: **9"x9" Taupe Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Rooms 212, 312, 322, Office between Room 322 & 320**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2500** DAMAGE UNITS: **SF**  
COMMENTS: **850 sf abated in #322, 145 sf damaged with 25 sf missing and 100 sf repaired with exposed mastic in #312 and #212**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **093**  
MATERIAL DESCRIPTION: **9"x9" Taupe Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 212, 312, 322, Office between Room 322 & 320**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **245** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Remove Damaged ACM ASAP

Management Planner's Signature:  Date: 10/24/2022



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **094**  
MATERIAL DESCRIPTION: **12"x12" Brown Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 130, 201**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **094**  
MATERIAL DESCRIPTION: **12"x12" Brown Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Room 130, 201**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 10/24/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **095**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchrooms (127), Serving Area, Kitchen (1000 SF ABATED)**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **095**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**  
MATERIAL LOCATION: **Lunchrooms (127), Serving Area, Kitchen (1000 SF ABATED)**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **096**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 220**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material was not in #320 but was observed in #220**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **096**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 220**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **097**  
MATERIAL DESCRIPTION: **9"x9" White Splotch Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Room 319, 319A**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damaged tiles with mastic exposed in #319, #319A**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **097**  
MATERIAL DESCRIPTION: **9"x9" White Splotch Floor Tile Mastic**  
MATERIAL LOCATION: **Room 319, 319A**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Remove Damaged ACM

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Exterior Window Caulk-(ABATED 2010)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Exterior Windows**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Exterior Window Caulk-(ABATED 2010)**  
MATERIAL LOCATION: **Exterior Windows**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **Interior Window Caulk (ABATED 2010)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Interior Windows**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **Interior Window Caulk (ABATED 2010)**

MATERIAL LOCATION: **Interior Windows**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **12"x12" Gray Splotched Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st Floor Mens and Womens Faculty Toilets, Room 320,220**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **12"x12" Gray Splotched Floor Tile**  
MATERIAL LOCATION: **1st Floor Mens and Womens Faculty Toilets, Room 320,220**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **12"x12" Gray Splotched Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Mens and Womens Faculty Toilets, Room 320**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **12"x12" Gray Spotted Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Mens and Womens Faculty Toilets, Room 320**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12"x12' Off White Speck Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st through 3rd Floor Corridor, 311**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12"x12' Off White Speck Floor Tile**  
MATERIAL LOCATION: **1st through 3rd Floor Corridor, 311**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12"x12" Cream Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Rooms 119, 108, 104, 136, 401, 403, Lunchroom, MDF, 199**  
MATERIAL QUANTITY: **3420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3420** DAMAGE UNITS: **SF**  
COMMENTS: **25 sf damage w/ mastic exposed in #119, 25 sf damage w/ mastic exposed in #199**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12"x12" Cream Speckled Floor Tile**  
MATERIAL LOCATION: **Rooms 119, 108, 104, 136, 401, 403, Lunchroom, MDF, 199**  
MATERIAL QUANTITY: **3420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Remove Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **9"x9" Taupe Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Rooms 212, 312, & 322, Office Between Room 322 & 320, Outside Office from left**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2500** DAMAGE UNITS: **SF**  
COMMENTS: **850 sf abated in #322, 120 sf damage with 25 sf missing and 100 sf repaired with mastic exposed in #312 and #212**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **9"x9" Taupe Floor Tile**  
MATERIAL LOCATION: **Rooms 212, 312, & 322, Office Between Room 322 & 320, Outside Office from left**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **245** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Remove Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12"x12" Brown Speckled Floor Tile (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 130, 201 (Not Observed)**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12"x12" Brown Speckled Floor Tile (Not Observed)**  
MATERIAL LOCATION: **Room 130, 201 (Not Observed)**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Lunchrooms, Serving Area, Kitchen**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**  
MATERIAL LOCATION: **Lunchrooms, Serving Area, Kitchen**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **9"x9" White Splotch Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Room 319,319A**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damaged tiles with exposed mastic in #319, #319A**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **9"x9" White Splotch Floor Tile**  
MATERIAL LOCATION: **Room 319,319A**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Remove Damaged ACM ASAP

Management Planner's Signature:  Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 230 (Not Observed), Fire Alarm Room by Boiler Room**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: 10/01/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks Floor Tile**  
MATERIAL LOCATION: **Room 230 (Not Observed), Fire Alarm Room by Boiler Room**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 125, 230 (Not Observed), Fire Alarm Room by Boiler Room**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 125, 230 (Not Observed), Fire Alarm Room by Boiler Room**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 220**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Material was not in #320 but was observed in #220**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 220**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office, Principals Office, Library**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Main Office, Principals Office, Library**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 104, 106, 118, & 120A & B, 122 (Small Auditorium)**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Rooms 104, 106, 118, & 120A & B, 122 (Small Auditorium)**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **2' x 4' Cut Pattern Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON: **Water**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Labs (112, 112A, 114, 116, 214, 216, 218, 314, 316, 318)**  
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Water damage in #316**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **2' x 4' Cut Pattern Ceiling Tile**  
MATERIAL LOCATION: **Labs (112, 112A, 114, 116, 214, 216, 218, 314, 316, 318)**  
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Sample material, Remove Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **Beige Sheet Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Labs 112, 114, 214, 216, 314, 316**  
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not observed in #116**

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **Beige Sheet Flooring**  
MATERIAL LOCATION: **Labs 112, 114, 214, 216, 314, 316**  
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **Mastic associated with Beige Sheet Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Labs (112, 114, 214, 216, 314, 316)**  
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not observed in #116**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **Mastic associated with Beige Sheet Flooring**  
MATERIAL LOCATION: **Labs (112, 114, 214, 216, 314, 316)**  
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **6" Brown Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Labs 112, 112A, 114, 116, 214, 216, 218, 314, 316, 318**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **6" Brown Vinyl Baseboard**  
MATERIAL LOCATION: **Labs 112, 112A, 114, 116, 214, 216, 218, 314, 316, 318**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **Glue associated with 6" Brown Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Labs 112, 114, 116, 214, 216, 218, 314, 316, 318**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **Glue associated with 6" Brown Vinyl Baseboard**  
MATERIAL LOCATION: **Labs 112, 114, 116, 214, 216, 218, 314, 316, 318**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile With Pinholes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Two Mobile Classrooms (Trailers) Located on the South Side of Property**  
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile With Pinholes**  
MATERIAL LOCATION: **Two Mobile Classrooms (Trailers) Located on the South Side of Property**  
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Two Mobile Classrooms (Trailers) Located on the South Side of Property**  
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Specks Floor Tile**  
MATERIAL LOCATION: **Two Mobile Classrooms (Trailers) Located on the South Side of Property**  
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **Mastic Associated With 12" x 12" White w/Gray Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Two Mobile Classrooms (Trailers) Located on the South Side of Property**  
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **Mastic Associated With 12" x 12" White w/Gray Specks Floor Tile**  
MATERIAL LOCATION: **Two Mobile Classrooms (Trailers) Located on the South Side of Property**  
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **4" Tan Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Two Mobile Classrooms (Trailers) Located on the South Side of Property**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **4" Tan Vinyl Baseboard**  
MATERIAL LOCATION: **Two Mobile Classrooms (Trailers) Located on the South Side of Property**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **Glue Associated With 4" Tan Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Two Mobile Classrooms (Trailers) Located on the South Side of Property**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **Glue Associated With 4" Tan Vinyl Baseboard**  
MATERIAL LOCATION: **Two Mobile Classrooms (Trailers) Located on the South Side of Property**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **Red Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Girls Restrooms in the Two Mobile Classrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **Red Linoleum**  
MATERIAL LOCATION: **Girls Restrooms in the Two Mobile Classrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **Mastic Associated With Red Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Girls Restrooms in the Two Mobile Classrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **Mastic Associated With Red Linoleum**  
MATERIAL LOCATION: **Girls Restrooms in the Two Mobile Classrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Blue Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Boys Restroom in the Two Mobile Classrooms**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Blue Linoleum**  
MATERIAL LOCATION: **Boys Restroom in the Two Mobile Classrooms**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **Mastic Associated With Blue Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boys Restrooms in the Two Mobile Classrooms**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **Mastic Associated With Blue Linoleum**  
MATERIAL LOCATION: **Boys Restrooms in the Two Mobile Classrooms**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **Mastic Assoc. w/ 2'x 2' Rubber Flooring Squares**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Dish Wash Area, Weight Room, Boys Locker Room, Equipment Room, Team A & B Rooms & Corridor**

MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **Mastic Assoc. w/ 2'x 2' Rubber Flooring Squares**  
MATERIAL LOCATION: **Dish Wash Area, Weight Room, Boys Locker Room, Equipment Room, Team A & B Rooms & Corridor**  
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **2'x 2' Gray Rubber Flooring Squares**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Dish Wash Area, Weight Room, Boys Locker Room, Equipment Room, Team A & B Rooms & Corridor**

MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **2'x 2' Gray Rubber Flooring Squares**  
MATERIAL LOCATION: **Dish Wash Area, Weight Room, Boys Locker Room, Equipment Room, Team A & B Rooms & Corridor**  
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **2' x 4' Drywall Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Dish Wash Area**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **2' x 4' Drywall Ceiling Tiles**  
MATERIAL LOCATION: **Dish Wash Area**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Speckles Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Fire Alarm Room near Engineers Office**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Speckles Floor Tile**  
MATERIAL LOCATION: **Fire Alarm Room near Engineers Office**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12" Gray w/ White Speckles Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Fire Alarm Room next to Engineers Office**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12" Gray w/ White Speckles Floor Tile**  
MATERIAL LOCATION: **Fire Alarm Room next to Engineers Office**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **12"x 12" White w/ Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 218, 132, Teachers Lunchroom**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not observed in #116**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **12"x 12" White w/ Brown Specks Floor Tile**  
MATERIAL LOCATION: **Room 218, 132, Teachers Lunchroom**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12"x12" White w/ Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 218, 132, Teachers Lunchroom**

MATERIAL QUANTITY: **1350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in #116**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12"x12" White w/ Brown Specks Floor Tile**  
MATERIAL LOCATION: **Room 218, 132, Teachers Lunchroom**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Laundry Room near Pool/Locker Rms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray Floor Tile**  
MATERIAL LOCATION: **2nd Floor Laundry Room near Pool/Locker Rms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12"x12" Dark Gray Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **2nd Floor Laundry Room near Pool/Locker Rms**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12"x12" Dark Gray Floor Tile**  
MATERIAL LOCATION: **2nd Floor Laundry Room near Pool/Locker Rms**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **6"x6" Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 224 & 229**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **6"x6" Black Floor Tile**  
MATERIAL LOCATION: **Rooms 224 & 229**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **6"x6" Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 224 & 229**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **6"x6" Black Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 224 & 229**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **6"x6" White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 224 & 229**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **6"x6" White Floor Tile**  
MATERIAL LOCATION: **Rooms 224 & 229**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **6"x6" White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 224 & 229**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **6"x6" White Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 224 & 229**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 318**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**  
MATERIAL LOCATION: **Room 318**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 318**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Room 318**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **2 x 4 Ceiling Tile white with swirls**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rms. 400 and 401, 3rd Fl. Corridor, 310, 308, 306, 304, 302, 300, 333, 399, 301, 321, 323, 325, 330, 332, 325, 303, 353, 305, 319**

MATERIAL QUANTITY: **18000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **2 x 4 Ceiling Tile white with swirls**  
MATERIAL LOCATION: **Rms. 400 and 401, 3rd Fl. Corridor, 310, 308, 306, 304, 302, 300, 333, 399, 301, 321, 323,325,330,332, 325, 303, 353, 305, 319**  
MATERIAL QUANTITY: **18000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **Black Lab Counter Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 316, 314, 214, 216, 114 & 114A**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **Black Lab Counter Tops**  
MATERIAL LOCATION: **Rm 316, 314, 214, 216, 114 & 114A**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **12 x 12 VFT White with Black Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rm 211 & 116**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **12 x 12 VFT White with Black Specks**  
MATERIAL LOCATION: **Rm 211 & 116**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **12 x 12 VFT White with Black Specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 211 & 116**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **12 x 12 VFT White with Black Specks Mastic**  
MATERIAL LOCATION: **Rm 211 & 116**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **148**  
MATERIAL DESCRIPTION: **12 x 12 Gray with gray specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rm 230**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage w/ mastic exposed**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **148**  
MATERIAL DESCRIPTION: **12 x 12 Gray with gray specks VFT**  
MATERIAL LOCATION: **Rm 230**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

sample material, Remove Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149**  
MATERIAL DESCRIPTION: **12 x 12 Gray with Gray Specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rm 230**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage w/ mastic exposed**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **149**  
MATERIAL DESCRIPTION: **12 x 12 Gray with Gray Specks Mastic**  
MATERIAL LOCATION: **Rm 230**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

sample material, Remove Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **150**  
MATERIAL DESCRIPTION: **2 x 4 Ceiling Tile White with Pin Hole**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Pool**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **150**  
MATERIAL DESCRIPTION: **2 x 4 Ceiling Tile White with Pin Hole**  
MATERIAL LOCATION: **Pool**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **2 x 2 Ceiling Tile White**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 122 & 128**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **2 x 2 Ceiling Tile White**  
MATERIAL LOCATION: **Rm 122 & 128**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 10/24/2022



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152**  
MATERIAL DESCRIPTION: **Fume Hood**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **112A**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **152**  
MATERIAL DESCRIPTION: **Fume Hood**  
MATERIAL LOCATION: **112A**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153**  
MATERIAL DESCRIPTION: **Red Fire Stop**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Pump room, Throughout basement**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **153**  
MATERIAL DESCRIPTION: **Red Fire Stop**  
MATERIAL LOCATION: **Pump room, Throughout basement**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **154**  
MATERIAL DESCRIPTION: **Tansite Panelling**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unfinished pipe space**  
MATERIAL QUANTITY: **44** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **154**  
MATERIAL DESCRIPTION: **Tansite Panelling**  
MATERIAL LOCATION: **Unfinished pipe space**  
MATERIAL QUANTITY: **44** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 320, 322, Office between 320 & 322, 114**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **155**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT**  
MATERIAL LOCATION: **Rooms 320, 322, Office between 320 & 322, 114**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155A**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 320, 322, Office between 320 & 322, 114**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **155A**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **Rooms 320, 322, Office between 320 & 322, 114**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **156**  
MATERIAL DESCRIPTION: **Decorative Precast Acoustic Plaster Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Water**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Water damage in library**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **156**  
MATERIAL DESCRIPTION: **Decorative Precast Acoustic Plaster Panels**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

sample material, remove damaged ACM asap

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **2'x2' Pinhole Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **320, 322, Office Between 320 & 322, 114**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **2'x2' Pinhole Ceiling Tile**  
MATERIAL LOCATION: **320, 322, Office Between 320 & 322, 114**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **158**  
MATERIAL DESCRIPTION: **Drywall System**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Wall between room 119 & 199, Boiler room, Mezzanine, 333, 401, 400, Elevator lobby on 4th Floor**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **158**  
MATERIAL DESCRIPTION: **Drywall System**  
MATERIAL LOCATION: **Wall between room 119 & 199, Boiler room, Mezzanine, 333, 401, 400, Elevator lobby on 4th Floor**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **159**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Beige Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 333 and Elevator Lobby**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **159**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Beige Specks VFT**  
MATERIAL LOCATION: **Room 333 and Elevator Lobby**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **159A**  
MATERIAL DESCRIPTION: **12"x12" Off White w/Beige Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 333 and Elevator Lobby**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **159A**  
MATERIAL DESCRIPTION: **12"x12" Off White w/Beige Specks VFT Mastic**  
MATERIAL LOCATION: **Room 333 and Elevator Lobby**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Pipe Chase in Room 317, 220**  
MATERIAL QUANTITY: **604** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS: **Added #220 and changed sf to lf**

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Pipe Chase in Room 317, 220**  
MATERIAL QUANTITY: **604** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School** INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUIDLING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **10/24/2022**



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46291**      BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School**      INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile**      IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **12x12 VFT MASTIC**  
MATERIAL LOCATION: **#201 Computer Lab**  
MATERIAL QUANTITY: **1500**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY:  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
New installation, Mastic associated with HAs 160, 161, 162

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46291**      BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School**      REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile**      IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **12x12 VFT MASTIC**  
MATERIAL LOCATION: **#201 Computer Lab**  
MATERIAL QUANTITY: **1500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:      DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46291**    BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School**    INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile**    IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **165**  
MATERIAL DESCRIPTION: **9x9 Black VFT**  
MATERIAL LOCATION: **Assistant Principal's Office Closet #106**  
MATERIAL QUANTITY: **10**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY:  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY:    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Closet previously inaccessible

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **165**

MATERIAL DESCRIPTION: **9x9 Black VFT**

MATERIAL LOCATION: **Assistant Principal's Office Closet #106**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46291**      BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School**      INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile**      IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **162**  
MATERIAL DESCRIPTION: **12x12 White w/ Gray Specks VFT**  
MATERIAL LOCATION: **#201**  
MATERIAL QUANTITY: **500**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY:  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
New installation

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **162**  
MATERIAL DESCRIPTION: **12x12 White w/ Gray Specks VFT**  
MATERIAL LOCATION: **#201**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46291**    BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School**    INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile**    IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **160**  
MATERIAL DESCRIPTION: **12x12 Gray w/ Gray Specks VFT**  
MATERIAL LOCATION: **201**  
MATERIAL QUANTITY: **500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY:  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY:    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
New installation

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46291**      BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School**      REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile**      IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **160**  
MATERIAL DESCRIPTION: **12x12 Gray w/ Gray Specks VFT**  
MATERIAL LOCATION: **201**  
MATERIAL QUANTITY: **500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:      DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46291**    BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School**    INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile**    IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **164**  
MATERIAL DESCRIPTION: **9x9 Red VFT**  
MATERIAL LOCATION: **Assistant Principal's Office Closet #106**  
MATERIAL QUANTITY: **10**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY:  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY:    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Closet previously inaccessible

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **164**

MATERIAL DESCRIPTION: **9x9 Red VFT**

MATERIAL LOCATION: **Assistant Principal's Office Closet #106**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46291**    BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School**    INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile**    IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **166**  
MATERIAL DESCRIPTION: **9x9 Red and Black VFT MASTIC**  
MATERIAL LOCATION: **Assistant Principal's Office Closet #106**  
MATERIAL QUANTITY: **20**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY:  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY:    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Closet previously inaccessible

Inspector's Signature: \_\_\_\_\_



Date: 10/01/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46291** BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School** REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **166**

MATERIAL DESCRIPTION: **9x9 Red and Black VFT MASTIC**

MATERIAL LOCATION: **Assistant Principal's Office Closet #106**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46291**    BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Steinmetz High School**    INSPECTION DATE: **10/1/2022**  
ADDRESS: **3030 N. Mobile**    IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **161**  
MATERIAL DESCRIPTION: **12x12 Dark Gray w/ Gray Specks VFT**  
MATERIAL LOCATION: **#201**  
MATERIAL QUANTITY: **500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY:  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY:    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
New installation

Inspector's Signature:



Date: **10/01/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46291**      BUILDING ID: **1560**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Steinmetz High School**      REVIEW DATE: **10/24/2022**  
ADDRESS: **3030 N. Mobile**      IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **161**  
MATERIAL DESCRIPTION: **12x12 Dark Gray w/ Gray Specks VFT**  
MATERIAL LOCATION: **#201**  
MATERIAL QUANTITY: **500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:      DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/24/2022

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 01/28/2023 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA-II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

01/28/2023

Course Dates:

01/28/2024

Expires:

2301BIR23

Certificate Number:

A handwritten signature in black ink, appearing to read "N Peneff".

**Director of Training**  
**Nicholas J. Peneff**  
**Doctor of Public Health**

Phone: 312-491-0081

FORM # A-010B



# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 01/15/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/15/2022

Course Dates:

01/15/2023

Expires:

2201BIR11

Certificate Number:



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

A handwritten signature in black ink, appearing to read "N Peneff", is written over a light-colored rectangular background.

**Director of Training**  
**Nicholas J. Peneff**  
**Doctor of Public Health**

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois

**JOSEPH L HENNIGAN**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

2/28/2022



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
**100 - 18350**

ISSUED  
**2/28/2022**

EXPIRES  
**05/15/2023**

**JOSEPH L HENNIGAN**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18350

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
ID NUMBER	ISSUED	EXPIRES		INSPECTOR	1/15/2023
<b>100 - 18350</b>	<b>2/28/2022</b>	<b>05/15/2023</b>		PROJECT MANAGER	1/22/2023
<b>JOSEPH L HENNIGAN</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health				AIR SAMPLING PROFESSIONAL	
				<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.


Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*

7233 S. Adams Street | Willowbrook, IL 60527  
(630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2023



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/23/2023

Exam Date: 2/23/2023

Expiration Date: 2/23/2024

Certificate Number: MPR2302230560

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: MPR2203090714

---

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## Jigar Shah

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090705

---

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois



**ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER  
**100 - 07342**

ISSUED  
**4/1/2022**

EXPIRES  
**05/15/2023**

**JIGAR M SHAH**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612



Environmental Health

**JIGAR M SHAH**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/1/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>			<p><b>ENDORSEMENTS</b></p>		<p><b>TC EXPIRES</b></p>
<p>ID NUMBER <b>100 - 07342</b></p>	<p>ISSUED <b>4/1/2022</b></p>	<p>EXPIRES <b>05/15/2023</b></p>	<p>INSPECTOR</p> <p>PROJECT DESIGNER</p> <p>MANAGEMENT PLANNER</p> <p>PROJECT MANAGER</p> <p>AIR SAMPLING PROFESSIONAL</p>	<p>3/9/2023</p> <p>3/24/2023</p> <p>3/9/2023</p> <p>3/2/2023</p>	
<p><b>JIGAR M SHAH</b> 2942 W VAN BUREN ST CHICAGO, IL 60612</p> <p>Environmental Health</p>					<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

Nationally Accredited by PHAB

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed