

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0042
SCHOOL NAME: Sullivan High School
ADDRESS OF SCHOOL: 6631 N. Bosworth Ave.
CITY: Chicago, IL, 60626

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/24/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/9/2022 ENROLLMENT 671
IDPH INSPECTOR LICENSE NUMBER: 100-20525
IDPH LICENSED INSPECTOR NAME (Please Print): Kevin Hanna
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

9/30/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Sullivan High School

6631 N. Bosworth Ave.
Chicago, IL, 60626

Unit: 46301
Building ID: 1570

IDPH ID Number: 14-016-2990-0042

REPORT DATE:

Friday, September 30, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Specialty Consulting, Inc.

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

09/30/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 46301 Region: 01 IDPH ID: 14-016-2990-0042

School: Sullivan High School Building ID: 1570

Address: 6631 N. Bosworth Ave.

Chicago, IL, 60626

Building Contact: Vega, Angel

Contact Phone: 7737107675

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/9/2022

Review Date: 09/30/2022

Inspector: Kevin Hanna

Inspector IDPH License: 100-20525

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 30, 2022

RE: Sullivan High School, Unit 46301
6631 N. Bosworth Ave.
Chicago, IL, 60626

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Sullivan High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Sullivan High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Sullivan High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1570:

B. The following new homogenous areas have been identified for Building 1570:

119	20" x 20" blue Vft & Mastic
119A	20" X 20" blue VFT & Mastic
120	20" x 20" gray VFT and Mastic
120A	20" x 20" gray VFT and Mastic
121	20" x 20" light gray VFT and mastic
121A	20" x 20" light gray VFT and mastic
122	Black countertop

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	2'x4' Dot Pattern Ceiling Tile
100	2'x4' smooth ceiling tile
101	Drywall system
102	12"x12" tan w/ brown & white specks VFT
102A	12"x12" tan w/ brown & white specks MASTIC
103	Black table tops - lab
104	Carpet MASTIC
105	12"x12" white w/ black and gray specks VFT
105A	12"x12" white with black and gray specks MASTIC
106	12"x12" white with blue and tan specks VFT
106A	12"x12" white with blue and tan specks MASTIC
107	12"x12" light blue with dark blue streaks VFT
107A	12"x12" light blue with dark blue streaks MASTIC
108	Decorative plaster
109	12"x12" tan light brown, white and brown specks VFT
109A	12"x12" tan light brown, white and brown specks MASTIC
110	Tectum tiles 2'x2'
111	Tectum tiles 1'x2'
112	12"x12" tan w/ white specks VFT
112A	12"x12" tan w/ white specks MASTIC
113	1'x1' ceiling tile textured
114	12"x12" tan w/brown and white specks VFT
114A	12"x12" tan w/brown and white specks MASTIC
115	2X6 Sky blue Laminate flooring
116	2X6 Dark blue Laminate flooring
117	2X6 Light Gray/white Laminate flooring
118	2X6 Dark Gray Laminate flooring
119	20" x 20" blue Vft & Mastic
119A	20" X 20" blue VFT & Mastic
120	20" x 20" gray VFT and Mastic
120A	20" x 20" gray VFT and Mastic
121	20" x 20" light gray VFT and mastic
121A	20" x 20" light gray VFT and mastic
122	Black countertop
33	Drywall Joint Compound
34	1'x1' Textured Ceiling Tile Mastic
39	Stage Firedoor
50	12"x12" Brown w/ White Streaks VFT
54	12"x12" Tan w/ Black Streaks VFT
55	12"x12" Tan w/ White Streaks VFT

57	12"x12" White w/ Brown Specks VFT
58	12"x12" Brown w/ White Waves VFT
70	12"x12" Brown w/ White Streaks VFT Mastic
75	12"x12" Tan w/ White Streaks Mastic
80	9"x9" Peach Mastic
88	Carpet Mastic
89	12" x 12" grey w/streaks VFT
89A	12" x 12" grey w/streaks Mastic
90	12" x 12" white VFT w/Blue Specks
90A	12" x 12" White w/Blue Speck Mastic
91	12" x 12" Light Blue w/Drk Blue Streaks VFT
91A	12" x 12" Light Blue w/Drk Blue Streaks Mastic
92	Terrazzo
93	12"X12" Tan w/White Streaks VFT
93A	12"X12" Tan w/White Streaks Mastic
94	12"X12" Beige w/White Specks VFT
94A	12"X12" Beige w/White Specks Mastic
95	Trowled-on Plaster
96	1'X1' White w/ Holes, Ceiling Tiles
96A	1'X1' White w/ Holes, Ceiling Tiles Mastic
97	Curtain Wall
98	Linoleum peach
98A	Linoleum peach MASTIC
C	Boiler Rope
H	Cardboard Pipe Insulation
M	1'x1' Textured Ceiling Tile

The following areas were deemed to be inaccessible:

C Boiler Rope

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Kevin Hanna, IDPH License # 100-20525. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 2/9/2022
 9/30/2022
 11/7/2022

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Sullivan High School Building 1570 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Sullivan High School Unit 46301 Building ID 1570

Address 6631 N. Bosworth Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	2'x4' Dot Pattern Ceiling Tile	10,000	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
100	2'x4' smooth ceiling tile	1,200	SF	Room 100 - HHealth center	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
101	Drywall system	4,000	SF	Room 100- Heath center	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
102	12"x12" tan w/ brown & white specks VFT	300	SF	Room 221A, 133	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
102A	12"x12" tan w/ brown & white specks MASTIC	300	SF	Room 221A, 133	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
103	Black table tops - lab	57	EA	Room 226, 225, 224	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
104	Carpet MASTIC	3,400	SF	Rooms 221, 201, 131, 132, 1347	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
105	12"x12" white w/ black and gray specks VFT	850	SF	Room 128	ASSUMED	MISC	N	LOC	3			ACBM with the potential for damage	5	MODERATE
105A	12"x12" white with black and gray specks MASTIC	850	SF	Room 128	ASSUMED	MISC	N	LOC	3			ACBM with the potential for damage	5	MODERATE
106	12"x12" white with blue and tan specks VFT	1,200	SF	Room 100 - Health center	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
106A	12"x12" white with blue and tan specks MASTIC	1,200	SF	Room 100 - health center	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
107	12"x12" light blue with dark blue streaks VFT	200	SF	1st fl. office lobby	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
107A	12"x12" light blue with dark blue streaks MASTIC	200	SF	1st fl. office lobby	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
108	Decorative plaster	2,000	SF	Auditorium, 1st fl. office lobby & corridor by lobby	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
109	12"x12" tan light brown, white and brown specks VFT	4,500	SF	1st fl. corridor	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
109A	12"x12" tan light brown, white and brown specks MASTIC	4,500	SF	1st fl. corridor	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
11	Grey Linoleum Mastic All carpet - NOT OBSERVED	2,400	SF	Rm 215 NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	Tectum tiles 2'x2'	2,500	SF	Gymnasium- boys	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
111	Tectum tiles 1'x2'	1,000	SF	Room 141	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
112	12"x12" tan w/ white specks VFT	0	SF	Room 200	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
112A	12"x12" tan w/ white specks MASTIC	0	SF	Room 200	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
113	1'x1' ceiling tile textured	850	SF	Room 128	ASSUMED	MISC	Y	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Sullivan High School Unit 46301 Building ID 1570

Address 6631 N. Bosworth Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
114	12"x12" tan w/brown and white specks VFT	1,600	SF	Rooms 328 & 328A, 327	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
114A	12"x12" tan w/brown and white specks MASTIC	1,600	SF	rooms 328 & 328A, 327	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
115	2X6 Sky blue Laminate flooring	200	SF	Room 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
116	2X6 Dark blue Laminate flooring	200	SF	Room 200	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
117	2X6 Light Gray/white Laminate flooring	200	SF	Room 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
118	2X6 Dark Gray Laminate flooring	200	SF	Room 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
119	20" x 20" blue Vft & Mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
119A	20" X 20" blue VFT & Mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
120	20" x 20" gray VFT and Mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
120A	20" x 20" gray VFT and Mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
121	20" x 20" light gray VFT and mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
121A	20" x 20" light gray VFT and mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
122	Black countertop	1,000	SF	Rooms 125, 222, 224, 226, 225	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
22	Plaster			Throughout	NO_ACBM						No			
33	Drywall Joint Compound	50	LF	Throughout	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
34	1'x1' Textured Ceiling Tile Mastic	300	SF	Basement Teachers Lounge	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
39	Stage Firedoor	25	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12"x12" Brown w/ White Streaks VFT	1,700	SF	Rms 228, 317	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
51	9"x9" Brown VFT	2,850	SF	2nd Fl Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
52	9"x9" Black VFT	2,850	SF	2nd Fl Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
53	9"x24" Black VFT	1,200	SF	2nd Fl Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
54	12"x12" Tan w/ Black Streaks VFT	850	SF	Room 219	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Sullivan High School Unit 46301 Building ID 1570

Address 6631 N. Bosworth Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
55	12"x12" Tan w/ White Streaks VFT	1,050	SF	Main Office, Rm 222	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
56	12"x12" Off White w/ White Specks VFT		SF	Rm 222	ABATED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
57	12"x12" White w/ Brown Specks VFT	1,600	SF	Rm 223, 225, (Rm 131 Office - not observed), Rm 224	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
58	12"x12" Brown w/ White Waves VFT	850	SF	Rm 226	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
60	9"x9" Tan w/ Beige & Brown Streaks VFT (Under 12"X12" in 2010)	950	SF	Rm 325	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	9"x9" Peach VFT	1,800	SF	Girls Locker Rm Office, Police Rm, Rm 125, 126, 326	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
62	9"x9" Red w/ Yellow Streaks VFT	1,875	SF	3rd Fl Corridor (Under New VFT)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	9"x9" Black w/ Yellow Streaks VFT	3,775	SF	Library, Main Office, 3rd Fl Corridor (Tiled Over)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
64	9"x9" Green w/ White Streaks VFT	3,175	SF	Library, Main, Assistant & Principals Offices, Library Office (All Under Carpet) and Rm 132	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
65	9"x9" Brown w/ Yellow Streaks VFT	260	SF	(Rm 131 Closet - not observed), 1st Floor South Corridor (Patchwork)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
66	9"x9" Black w/ White Streaks VFT (ABATED)	0	SF	Rm 125	ABATED	MISC	N	NONE	0		No			
67	Popcorn Ceiling (Spray Applied Acoustical Plaster)			Band Room, 2nd Floor	NO_ACBM	SURFACE								
68	Transite Tables	1,200	SF	Rm 125 (Abated), 222 (Abated), 128	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	12"x12" Brown w/ White Streaks VFT Mastic	1,700	SF	Room s 228, 317	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
71	9"x9" Brown VFT Mastic	2,850	SF	2nd Fl Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	9"x9" Black VFT Mastic	2,850	SF	2nd Fl Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	9"x24" Black VFT Mastic	1,200	SF	2nd Fl Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Sullivan High School Unit 46301 Building ID 1570

Address 6631 N. Bosworth Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
74	12"x12" Tan w/ Black Streaks Mastic	670	SF	Rm 219	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	12"x12" Tan w/ White Streaks Mastic	1,050	SF	Main Office, Room 222 (Abated)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	12"x12" Off White w/ White Specks Mastic (Abated)	0	SF	Room 222	ABATED	MISC	N	NONE	0					
77	12"x12" White w/ Brown Streaks Mastic	1,600	SF	Rooms 223, 225 (Abated), (131 Office - not observed), 224 (Abated), 134	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12"x12" Brown w/ White Wave Mastic	800	SF	Rm 226	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	9"x9" Tan w/ Beige & Brn Streaks VFT Mastic (Under New 12"x12")	850	SF	Rm 325	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	9"x9" Peach Mastic	2,500	SF	Girls Locker Rm Office, Rm 125, 126, 326	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	9"x9" Red w/ Yellow Streaks VFT Mastic (not observed)	1,875	SF	3rd Fl Corridor (Under New VFT)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	9"x9" Black w/ Yellow Streaks VFT Mastic (not observed)	1,875	SF	3rd Fl Corridor (Under New VFT) and Library	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	9"x9" Green w/ White Streaks Mastic	3,185	SF	Library and Rm 132, Library Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
84	9"x9" Brown w/ Yellow Streaks VFT Mastic	260	SF	(Rm 131 Closet - not observed), 1st Floor (Under New 12" X12") South Corridor (Patchwork)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	9"x9" Black w/ White Streaks VFT Mastic (no access)	20	SF	Rm 125	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	9"x9" Orange w/ Brown Wave VFT Now Wood Floor	0	SF	Basement Lounge (Under Carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	9"x9" Orange w/ Brown Wave Mastic	150	SF	Basement Lounge (Under Carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	Carpet Mastic	2,000	SF	Rooms 132, girl's lockerroom office and main office, 215, 221B, 131, 122, Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	12" x 12" grey w/streaks VFT	1,000	SF	Main office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Sullivan High School Unit 46301 Building ID 1570

Address 6631 N. Bosworth Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
89A	12" x 12" grey w/streaks Mastic	1,000	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	12" x 12" white VFT w/Blue Specks	10,000	SF	1st Flr Corridor 2nd Flr Corridor 3rd Flr Corridor and room 325	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
90A	12" x 12" White w/Blue Speck Mastic	10,000	SF	1st and 2nd Flr Corridors 3rd Flr Corridor and room 325	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	12" x 12" Light Blue w/Drk Blue Streaks VFT	10,000	SF	1st and 2nd Flr Corridors 3rd Flr Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
91A	12" x 12" Light Blue w/Drk Blue Streaks Mastic	10,000	SF	1st and 2nd Flr Corridors 3rd Flr Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92	Terrazzo	4,000	SF	Hallway Borders, Vestibule, Stairwells, Toilet Rooms, Room Next to Rm 200, Kitchen, Lunch Room, Service Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
93	12"X12" Tan w/White Streaks VFT	1,200	SF	2nd Floor Band Room, 1st Floor Women's Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
93A	12"X12" Tan w/White Streaks Mastic	1,200	SF	2nd Floor Band Room, 1st Floor Women's Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
94	12"X12" Beige w/White Specks VFT	1,500	SF	Rms 123, (128 not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
94A	12"X12" Beige w/White Specks Mastic	1,500	SF	Rms 123, (128 not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
95	Trowled-on Plaster	3,000	SF	Auditorium, 1st Floor Main Lobby	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
96	1'X1' White w/ Holes, Ceiling Tiles	3,000	SF	Serving Area, Lunch Room	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
96A	1'X1' White w/ Holes, Ceiling Tiles Mastic	3,000	SF	Serving Area, Lunch Room	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
97	Curtain Wall	800	SF	Stage	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
98	Linoleum peach	1,000	SF	Room 121	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
98A	Linoleum peach MASTIC	1,000	SF	Room 121	ASSUMED	MISC	N	NONE	0			ACBM with the		LOW

Chicago Public Schools

School Sullivan High School Unit 46301 Building ID 1570

Address 6631 N. Bosworth Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
99	12"x12" off white w/ tan specs VFT			Room 134	ABATED	MISC								
99A	12"x12" off white w/ tan specks MASTIC (ABATED)			Room 134	ABATED	MISC								
A	Boiler Tank Insulation	500	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		
B	Boiler Breeching	300	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
C	Boiler Rope	3	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	Water Tank Insulation	600	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		
E	Aircell Duct Insulation			Unexcavated Space	ABATED	TSI								
F	Aircell Pipe Insulation			Excavated space	ABATED	TSI								
G	MJP E/F/V on Aircell Pipe Insulation			Excavated Space	ABATED	TSI								
H	Cardboard Pipe Insulation	3,500	LF	Throughout	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		
I	MJP E/F/V on Cardboard Pipe Insulation	2,000	LF	Throughout (See Hatching Maps)	CHR	TSI	Y	NONE	0		No			
J	Mag Block Pipe Insulation	3,250	LF	Throughout (See Hatching Maps)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		
K	MJP E/F/V on Mag Block Pipe Insulation	600	LF	Throughout (See Hatching Maps)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		
L	MJP E/F/V on Fiberglass Pipe Insulation			Throughout	NO_ACBM						No			
M	1'x1' Textured Ceiling Tile	900	SF	Basement Teachers Lounge	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Sullivan High School Unit 46301 Building ID 1570

Address 6631 N. Bosworth Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 9/9/2022
Inspector Name Kevin Hanna
100-20525 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
100	
101	
102	
102A	
103	removed
104	
105	repair
105A	repair
106	
106A	
107	
107A	
108	
109	
109A	
11	
110	
111	
112	
112A	
113	
114	
114A	

Chicago Public Schools

School Sullivan High School Unit 46301 Building ID 1570

Address 6631 N. Bosworth Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
115	
116	
117	
118	
119	
119A	
120	
120A	
121	
121A	
122	
22	
33	
34	
39	
50	
51	
52	
53	
54	
55	
56	
57	Abated in 224 and 225
58	
60	
61	Abated in 125
62	
63	
64	

Chicago Public Schools

School Sullivan High School Unit 46301 Building ID 1570

Address 6631 N. Bosworth Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
65	
66	Abated
67	
68	Abated in room 125, 222
70	
71	
72	
73	
74	
75	Abated in room 222
76	Abated
77	Abated in rooms 224 and 225
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
89A	
90	
90A	
91	
91A	

Chicago Public Schools

School Sullivan High School Unit 46301 Building ID 1570

Address 6631 N. Bosworth Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
92	
93	
93A	
94	
94A	
95	
96	
96A	
97	
98	
98A	
99	
99A	
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	

Chicago Public Schools

School Sullivan High School **Unit** 46301 **Building ID** 1570

Address 6631 N. Bosworth Ave. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Sullivan High School

Unit 46301

Building ID 1570

Address 6631 N. Bosworth Ave.

Chicago, IL, 60626

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	2'x4' Dot Pattern Ceiling Tile	10,000	SF	Throughout	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	2'x4' smooth ceiling tile	1,200	SF	Room 100 - Health center	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	Drywall system	4,000	SF	Room 100- Heath center	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	12"x12" tan w/ brown & white specks VFT	300	SF	Room 221A, 133	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102A	12"x12" tan w/ brown & white specks MASTIC	300	SF	Room 221A, 133	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Black table tops - lab	57	EA	Room 226, 225, 224	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
104	Carpet MASTIC	3,400	SF	Rooms 221, 201, 131, 132, 1347	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12"x12" white w/ black and gray specks VFT	850	SF	Room 128	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Remove
105A	12"x12" white with black and gray specks MASTIC	850	SF	Room 128	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Remove
106	12"x12" white with blue and tan specks VFT	1,200	SF	Room 100 - Health center	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106A	12"x12" white with blue and tan specks MASTIC	1,200	SF	Room 100 - health center	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12"x12" light blue with dark blue streaks VFT	200	SF	1st fl. office lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107A	12"x12" light blue with dark blue streaks MASTIC	200	SF	1st fl. office lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	Decorative plaster	2,000	SF	Auditorium, 1st fl. office lobby & corridor by lobby	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12"x12" tan light brown, white and brown specks VFT	4,500	SF	1st fl. corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109A	12"x12" tan light brown, white and brown specks MASTIC	4,500	SF	1st fl. corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Grey Linoleum Mastic All carpet - NOT OBSERVED	2,400	SF	Rm 215 NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
110	Tectum tiles 2'x2'	2,500	SF	Gymnasium- boys	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	Tectum tiles 1'x2'	1,000	SF	Room 141	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12"x12" tan w/ white specks VFT	0	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112A	12"x12" tan w/ white specks MASTIC	0	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	1'x1' ceiling tile textured	850	SF	Room 128	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12"x12" tan w/brown and white specks VFT	1,600	SF	Rooms 328 & 328A, 327	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114A	12"x12" tan w/brown and white specks MASTIC	1,600	SF	rooms 328 & 328A, 327	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	2X6 Sky blue Laminate flooring	200	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	2X6 Dark blue Laminate flooring	200	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	2X6 Light Gray/white Laminate flooring	200	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	2X6 Dark Gray Laminate flooring	200	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	20" x 20" blue Vft & Mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
119A	20" X 20" blue VFT & Mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
120	20" x 20" gray VFT and Mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sullivan High School

Unit 46301

Building ID 1570

Address 6631 N. Bosworth Ave.

Chicago, IL, 60626

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
120A	20" x 20" gray VFT and Mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
121	20" x 20" light gray VFT and mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
121A	20" x 20" light gray VFT and mastic	1,300	SF	Rooms 125, 222, 224, 226, 225	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
122	Black countertop	1,000	SF	Rooms 125, 222, 224, 226, 225	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Plaster			Throughout	No ACBM						Follow O&M Plan
33	Drywall Joint Compound	50	LF	Throughout	Assumed	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
34	1'x1' Textured Ceiling Tile Mastic	300	SF	Basement Teachers Lounge	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Stage Firedoor	25	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12"x12" Brown w/ White Streaks VFT	1,700	SF	Rms 228, 317	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	9"x9" Brown VFT	2,850	SF	2nd FI Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	9"x9" Black VFT	2,850	SF	2nd FI Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	9"x24" Black VFT	1,200	SF	2nd FI Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12"x12" Tan w/ Black Streaks VFT	850	SF	Room 219	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12"x12" Tan w/ White Streaks VFT	1,050	SF	Main Office, Rm 222	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12"x12" Off White w/ White Specks VFT		SF	Rm 222	Abated	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12"x12" White w/ Brown Specks VFT	1,600	SF	Rm 223, 225, (Rm 131 Office - not observed), Rm 224	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12"x12" Brown w/ White Waves VFT	850	SF	Rm 226	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	9"x9" Tan w/ Beige & Brown Streaks VFT (Under 12"X12" in 2010)	950	SF	Rm 325	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	9"x9" Peach VFT	1,800	SF	Girls Locker Rm Office, Police Rm, Rm 125, 126, 326	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	9"x9" Red w/ Yellow Streaks VFT	1,875	SF	3rd FI Corridor (Under New VFT)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	9"x9" Black w/ Yellow Streaks VFT	3,775	SF	Library, Main Office, 3rd FI Corridor (Tiled Over)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	9"x9" Green w/ White Streaks VFT	3,175	SF	Library, Main, Assistant & Principals Offices, Library Office (All Under Carpet) and Rm 132	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	9"x9" Brown w/ Yellow Streaks VFT	260	SF	(Rm 131 Closet - not observed), 1st Floor South Corridor (Patchwork)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	9"x9" Black w/ White Streaks VFT (ABATED)	0	SF	Rm 125	Abated	MISC	No	0	SF		
67	Popcorn Ceiling (Spray Applied Acoustical Plaster)			Band Room, 2nd Floor	No ACBM	SURFACE					
68	Transite Tables	1,200	SF	Rm 125 (Abated), 222 (Abated), 128	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12"x12" Brown w/ White Streaks VFT Mastic	1,700	SF	Room s 228, 317	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	9"x9" Brown VFT Mastic	2,850	SF	2nd FI Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sullivan High School

Unit 46301

Building ID 1570

Address 6631 N. Bosworth Ave.

Chicago, IL, 60626

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
72	9"x9" Black VFT Mastic	2,850	SF	2nd Fl Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	9"x24" Black VFT Mastic	1,200	SF	2nd Fl Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12"x12" Tan w/ Black Streaks Mastic	670	SF	Rm 219	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12"x12" Tan w/ White Streaks Mastic	1,050	SF	Main Office, Room 222 (Abated)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12"x12" Off White w/ White Specks Mastic (Abated)	0	SF	Room 222	Abated	MISC	No	0	SF		
77	12"x12" White w/ Brown Streaks Mastic	1,600	SF	Rooms 223, 225 (Abated), (131 Office - not observed), 224(Abated), 134	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12"x12" Brown w/ White Wave Mastic	800	SF	Rm 226	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	9"x9" Tan w/ Beige & Brn Streaks VFT Mastic (Under New 12"X12")	850	SF	Rm 325	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	9"x9" Peach Mastic	2,500	SF	Girls Locker Rm Office, Rm 125, 126, 326	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	9"x9" Red w/ Yellow Streaks VFT Mastic (not observed)	1,875	SF	3rd Fl Corridor (Under New VFT)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	9"x9" Black w/ Yellow Streaks VFT Mastic (not observed)	1,875	SF	3rd Fl Corridor (Under New VFT) and Library	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	9"x9" Green w/ White Streaks Mastic	3,185	SF	Library and Rm 132, Library Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	9"x9" Brown w/ Yellow Streaks VFT Mastic	260	SF	(Rm 131 Closet - not observed), 1st Floor (Under New 12"X12") South Corridor (Patchwork)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	9"x9" Black w/ White Streaks VFT Mastic (no access)	20	SF	Rm 125	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	9"x9" Orange w/ Brown Wave VFT Now Wood Floor	0	SF	Basement Lounge (Under Carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	9"x9" Orange w/ Brown Wave Mastic	150	SF	Basement Lounge (Under Carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Carpet Mastic	2,000	SF	Rooms 132, girl's lockerroom office and main office, 215, 221B, 131, 122, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	12" x 12" grey w/streaks VFT	1,000	SF	Main office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89A	12" x 12" grey w/streaks Mastic	1,000	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12" x 12" white VFT w/Blue Specks	10,000	SF	1st Flr Corridor 2nd Flr Corridor 3rd Flr Corridor and room 325	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90A	12" x 12" White w/Blue Speck Mastic	10,000	SF	1st and 2nd Flr Corridors 3rd Flr Corridor and room 325	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	12" x 12" Light Blue w/Drk Blue Streaks VFT	10,000	SF	1st and 2nd Flr Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sullivan High School

Unit 46301

Building ID 1570

Address 6631 N. Bosworth Ave.

Chicago, IL, 60626

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				3rd Flr Corridor							
91A	12" x 12" Light Blue w/Drk Blue Streaks Mastic	10,000	SF	1st and 2nd Flr Corridors 3rd Flr Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	Terrazzo	4,000	SF	Hallway Borders, Vestibule, Stairwells, Toilet Rooms, Room Next to Rm 200, Kitchen, Lunch Room, Service Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93	12"X12" Tan w/White Streaks VFT	1,200	SF	2nd Floor Band Room, 1st Floor Women's Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93A	12"X12" Tan w/White Streaks Mastic	1,200	SF	2nd Floor Band Room, 1st Floor Women's Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12"X12" Beige w/White Specks VFT	1,500	SF	Rms 123, (128 not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94A	12"X12" Beige w/White Specks Mastic	1,500	SF	Rms 123, (128 not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
95	Trowled-on Plaster	3,000	SF	Auditorium, 1st Floor Main Lobby	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	1'X1' White w/ Holes, Ceiling Tiles	3,000	SF	Serving Area, Lunch Room	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96A	1'X1' White w/ Holes, Ceiling Tiles Mastic	3,000	SF	Serving Area, Lunch Room	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	Curtain Wall	800	SF	Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	Linoleum peach	1,000	SF	Room 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98A	Linoleum peach MASTIC	1,000	SF	Room 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	12"x12" off white w/ tan specs VFT			Room 134	Abated	MISC					
99A	12"x12" off white w/ tan specks MASTIC (ABATED)			Room 134	Abated	MISC					
A	Boiler Tank Insulation	500	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	Boiler Breaching	300	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Boiler Rope	3	SF	Boiler Room	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	Water Tank Insulation	600	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
E	Aircell Duct Insulation			Unexcavated Space	Abated	TSI					
F	Aircell Pipe Insulation			Excavated space	Abated	TSI					
G	MJP E/F/V on Aircell Pipe Insulation			Excavated Space	Abated	TSI					
H	Cardboard Pipe Insulation	3,500	LF	Throughout	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I	MJP E/F/V on Cardboard Pipe Insulation	2,000	LF	Throughout (See Hatching Maps)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
J	Mag Block Pipe Insulation	3,250	LF	Throughout (See Hatching Maps)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	MJP E/F/V on Mag Block Pipe Insulation	600	LF	Throughout (See Hatching Maps)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
L	MJP E/F/V on Fiberglass Pipe Insulation			Throughout	No ACBM						
M	1'x1' Textured Ceiling Tile	900	SF	Basement Teachers Lounge	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sullivan High School
Address 6631 N. Bosworth Ave.

Unit 46301
 Chicago, IL, 60626

Building ID 1570
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

Review Date	9/30/2022
Manager Planner Name	Jigar Shah
100-07342	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
100	
101	
102	
102A	
103	
104	

Chicago Public Schools

School Sullivan High School
Address 6631 N. Bosworth Ave.

Unit 46301
 Chicago, IL, 60626

Building ID 1570
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
105	Sample material, Remove damaged ACM ASAP
105A	Sample material, Remove damaged ACM ASAP
106	
106A	
107	
107A	
108	
109	
109A	
11	
110	
111	
112	
112A	
113	
114	
114A	
115	
116	
117	
118	
119	
119A	
120	
120A	
121	
121A	

Chicago Public Schools

School Sullivan High School
Address 6631 N. Bosworth Ave.

Unit 46301
Chicago, IL, 60626

Building ID 1570
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
122	
22	
33	
34	
39	
50	
51	
52	
53	
54	
55	
56	
57	
58	
60	
61	
62	
63	
64	
65	
66	
67	
68	
70	
71	
72	
73	

Chicago Public Schools

School Sullivan High School
Address 6631 N. Bosworth Ave.

Unit 46301
Chicago, IL, 60626

Building ID 1570
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
89A	
90	
90A	
91	
91A	
92	
93	
93A	
94	
94A	
95	

Chicago Public Schools

School Sullivan High School
Address 6631 N. Bosworth Ave.

Unit 46301
Chicago, IL, 60626

Building ID 1570
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
96	
96A	
97	
98	
98A	
99	
99A	
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **2'x4' Dot Pattern Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **2'x4' Dot Pattern Ceiling Tile**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **2'x4' smooth ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100 - HHealth center**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **2'x4' smooth ceiling tile**
MATERIAL LOCATION: **Room 100 - HHealth center**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Drywall system**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100- Heath center**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Drywall system**
MATERIAL LOCATION: **Room 100- Heath center**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12"x12" tan w/ brown & white specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 221A, 133**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12"x12" tan w/ brown & white specks VFT**
MATERIAL LOCATION: **Room 221A, 133**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102A**
MATERIAL DESCRIPTION: **12"x12" tan w/ brown & white specks MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 221A, 133**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **102A**
MATERIAL DESCRIPTION: **12"x12" tan w/ brown & white specks MASTIC**
MATERIAL LOCATION: **Room 221A, 133**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Black table tops - lab**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 226, 225, 224**
MATERIAL QUANTITY: **57** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**
COMMENTS: **removed**

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Black table tops - lab**
MATERIAL LOCATION: **Room 226, 225, 224**
MATERIAL QUANTITY: **57** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **Carpet MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 221, 201, 131, 132, 1347**
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **Carpet MASTIC**
MATERIAL LOCATION: **Rooms 221, 201, 131, 132, 1347**
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12"x12" white w/ black and gray specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 128**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **repair**

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12"x12" white w/ black and gray specks VFT**
MATERIAL LOCATION: **Room 128**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample material, Remove damaged ACM ASAP

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105A**
MATERIAL DESCRIPTION: **12"x12" white with black and gray specks MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 128**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **repair**

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **105A**
MATERIAL DESCRIPTION: **12"x12" white with black and gray specks MASTIC**
MATERIAL LOCATION: **Room 128**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample material, Remove damaged ACM ASAP

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12"x12" white with blue and tan specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 100 - Health center**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12"x12" white with blue and tan specks VFT**
MATERIAL LOCATION: **Room 100 - Health center**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106A**
MATERIAL DESCRIPTION: **12"x12" white with blue and tan specks MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100 - health center**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **106A**
MATERIAL DESCRIPTION: **12"x12" white with blue and tan specks MASTIC**
MATERIAL LOCATION: **Room 100 - health center**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12"x12" light blue with dark blue streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st fl. office lobby**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12"x12" light blue with dark blue streaks VFT**
MATERIAL LOCATION: **1st fl. office lobby**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107A**
MATERIAL DESCRIPTION: **12"x12" light blue with dark blue streaks MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st fl. office lobby**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **107A**
MATERIAL DESCRIPTION: **12"x12" light blue with dark blue streaks MASTIC**
MATERIAL LOCATION: **1st fl. office lobby**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **Decorative plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, 1st fl. office lobby & corridor by lobby**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **Decorative plaster**
MATERIAL LOCATION: **Auditorium, 1st fl. office lobby & corridor by lobby**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12"x12" tan light brown, white and brown specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st fl. corridor**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12"x12" tan light brown, white and brown specks VFT**
MATERIAL LOCATION: **1st fl. corridor**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109A**
MATERIAL DESCRIPTION: **12"x12" tan light brown, white and brown specks MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st fl. corridor**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **109A**
MATERIAL DESCRIPTION: **12"x12" tan light brown, white and brown specks MASTIC**
MATERIAL LOCATION: **1st fl. corridor**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Grey Linoleum Mastic All carpet - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 215 NOT OBSERVED**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Grey Linoleum Mastic All carpet - NOT OBSERVED**
MATERIAL LOCATION: **Rm 215 NOT OBSERVED**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Tectum tiles 2'x2'**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gymnasium- boys**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Tectum tiles 2'x2'**
MATERIAL LOCATION: **Gymnasium- boys**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **Tectum tiles 1'x2'**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 141**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **Tectum tiles 1'x2'**
MATERIAL LOCATION: **Room 141**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12"x12" tan w/ white specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12"x12" tan w/ white specks VFT**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112A**
MATERIAL DESCRIPTION: **12"x12" tan w/ white specks MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **112A**
MATERIAL DESCRIPTION: **12"x12" tan w/ white specks MASTIC**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **1'x1' ceiling tile textured**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 128**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **1'x1' ceiling tile textured**
MATERIAL LOCATION: **Room 128**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12"x12" tan w/brown and white specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 328 & 328A, 327**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12"x12" tan w/brown and white specks VFT**
MATERIAL LOCATION: **Rooms 328 & 328A, 327**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114A**
MATERIAL DESCRIPTION: **12"x12" tan w/brown and white specks MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **rooms 328 & 328A, 327**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **114A**
MATERIAL DESCRIPTION: **12"x12" tan w/brown and white specks MASTIC**
MATERIAL LOCATION: **rooms 328 & 328A, 327**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **2X6 Sky blue Laminate flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **2X6 Sky blue Laminate flooring**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **2X6 Dark blue Laminate flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **2X6 Dark blue Laminate flooring**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **2X6 Light Gray/white Laminate flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **2X6 Light Gray/white Laminate flooring**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **2X6 Dark Gray Laminate flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **2X6 Dark Gray Laminate flooring**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **1'x1' Textured Ceiling Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Teachers Lounge**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **1'x1' Textured Ceiling Tile Mastic**
MATERIAL LOCATION: **Basement Teachers Lounge**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Stage Firedoor**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Stage Firedoor**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms 228, 317**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT**
MATERIAL LOCATION: **Rms 228, 317**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9"x9" Brown VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd FI Corridor**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9"x9" Brown VFT**
MATERIAL LOCATION: **2nd Fl Corridor**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **9"x9" Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd FI Corridor**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **9"x9" Black VFT**
MATERIAL LOCATION: **2nd Fl Corridor**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **9"x24" Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd FI Corridor**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **9"x24" Black VFT**
MATERIAL LOCATION: **2nd Fl Corridor**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Black Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 219**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Black Streaks VFT**
MATERIAL LOCATION: **Room 219**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Office, Rm 222**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT**
MATERIAL LOCATION: **Main Office, Rm 222**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12"x12" Off White w/ White Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rm 222**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12"x12" Off White w/ White Specks VFT**
MATERIAL LOCATION: **Rm 222**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 223, 225, (Rm 131 Office - not observed), Rm 224**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Abated in 224 and 225**

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Specks VFT**
MATERIAL LOCATION: **Rm 223, 225, (Rm 131 Office - not observed), Rm 224**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Waves VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 226**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Waves VFT**
MATERIAL LOCATION: **Rm 226**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Beige & Brown Streaks VFT (Under 12"X12" in 2010)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 325**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Beige & Brown Streaks VFT (Under 12"X12" in 2010)**
MATERIAL LOCATION: **Rm 325**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **9"x9" Peach VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Girls Locker Rm Office, Police Rm, Rm 125, 126, 326**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Abated in 125**

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **9"x9" Peach VFT**
MATERIAL LOCATION: **Girls Locker Rm Office, Police Rm, Rm 125, 126, 326**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **9"x9" Red w/ Yellow Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd FI Corridor (Under New VFT)**
MATERIAL QUANTITY: **1875** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **9"x9" Red w/ Yellow Streaks VFT**
MATERIAL LOCATION: **3rd FI Corridor (Under New VFT)**
MATERIAL QUANTITY: **1875** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9"x9" Black w/ Yellow Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Library, Main Office, 3rd Fl Corridor (Tiled Over)**
MATERIAL QUANTITY: **3775** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9"x9" Black w/ Yellow Streaks VFT**
MATERIAL LOCATION: **Library, Main Office, 3rd FI Corridor (Tiled Over)**
MATERIAL QUANTITY: **3775** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Library, Main, Assistant & Principals Offices, Library Office (All Under Carpet) and Rm 132**

MATERIAL QUANTITY: **3175** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**
MATERIAL LOCATION: **Library, Main, Assistant & Principals Offices, Library Office (All Under Carpet) and Rm 132**
MATERIAL QUANTITY: **3175** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Yellow Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **(Rm 131 Closet - not observed), 1st Floor South Corridor (Patchwork)**
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Yellow Streaks VFT**
MATERIAL LOCATION: **(Rm 131 Closet - not observed), 1st Floor South Corridor (Patchwork)**
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 125**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Abated**

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT (ABATED)**
MATERIAL LOCATION: **Rm 125**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Popcorn Ceiling (Spray Applied Acoustical Plaster)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Band Room, 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Popcorn Ceiling (Spray Applied Acoustical Plaster)**

MATERIAL LOCATION: **Band Room, 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 09/30/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Transite Tables**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 125 (Abated), 222 (Abated), 128**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Abated in room 125, 222**

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Transite Tables**
MATERIAL LOCATION: **Rm 125 (Abated), 222 (Abated), 128**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room s 228, 317**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Room s 228, 317**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **9"x9" Brown VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd FI Corridor**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **9"x9" Brown VFT Mastic**
MATERIAL LOCATION: **2nd Fl Corridor**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd FI Corridor**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**
MATERIAL LOCATION: **2nd FI Corridor**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **9"x24" Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd FI Corridor**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **9"x24" Black VFT Mastic**
MATERIAL LOCATION: **2nd FI Corridor**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Black Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 219**
MATERIAL QUANTITY: **670** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Black Streaks Mastic**
MATERIAL LOCATION: **Rm 219**
MATERIAL QUANTITY: **670** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office, Room 222 (Abated)**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Abated in room 222**

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks Mastic**
MATERIAL LOCATION: **Main Office, Room 222 (Abated)**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12"x12" Off White w/ White Specks Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 222**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Abated**

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12"x12" Off White w/ White Specks Mastic (Abated)**
MATERIAL LOCATION: **Room 222**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 223, 225 (Abated), (131 Office - not observed), 224(Abated), 134**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Abated in rooms 224 and 225**

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Streaks Mastic**
MATERIAL LOCATION: **Rooms 223, 225 (Abated), (131 Office - not observed), 224(Abated), 134**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Wave Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 226**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Wave Mastic**
MATERIAL LOCATION: **Rm 226**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Beige & Brn Streaks VFT Mastic (Under New 12"X12")**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 325**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Beige & Brn Streaks VFT Mastic (Under New 12"X12")**
MATERIAL LOCATION: **Rm 325**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **9"x9" Peach Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Girls Locker Rm Office, Rm 125, 126, 326**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **9"x9" Peach Mastic**
MATERIAL LOCATION: **Girls Locker Rm Office, Rm 125, 126, 326**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **9"x9" Red w/ Yellow Streaks VFT Mastic (not observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd FI Corridor (Under New VFT)**
MATERIAL QUANTITY: **1875** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **9"x9" Red w/ Yellow Streaks VFT Mastic (not observed)**
MATERIAL LOCATION: **3rd FI Corridor (Under New VFT)**
MATERIAL QUANTITY: **1875** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **9"x9" Black w/ Yellow Streaks VFT Mastic (not observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd FI Corridor (Under New VFT) and Library**

MATERIAL QUANTITY: **1875** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **9"x9" Black w/ Yellow Streaks VFT Mastic (not observed)**
MATERIAL LOCATION: **3rd FI Corridor (Under New VFT) and Library**
MATERIAL QUANTITY: **1875** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library and Rm 132, Library Office**
MATERIAL QUANTITY: **3185** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks Mastic**
MATERIAL LOCATION: **Library and Rm 132, Library Office**
MATERIAL QUANTITY: **3185** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Yellow Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **(Rm 131 Closet - not observed), 1st Floor (Under New 12"X12") South Corridor (Patchwork)**

MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Yellow Streaks VFT Mastic**
MATERIAL LOCATION: **(Rm 131 Closet - not observed), 1st Floor (Under New 12"X12") South Corridor (Patchwork)**
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic (no access)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 125**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic (no access)**
MATERIAL LOCATION: **Rm 125**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **9"x9" Orange w/ Brown Wave VFT Now Wood Floor**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Lounge (Under Carpet)**

MATERIAL QUANTITY: **0**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **9"x9" Orange w/ Brown Wave VFT Now Wood Floor**
MATERIAL LOCATION: **Basement Lounge (Under Carpet)**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **9"x9" Orange w/ Brown Wave Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Lounge (Under Carpet)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **9"x9" Orange w/ Brown Wave Mastic**
MATERIAL LOCATION: **Basement Lounge (Under Carpet)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 132, girl's lockerroom office and main office, 215, 221B, 131, 122, Library**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Rooms 132, girl's lockerroom office and main office, 215, 221B, 131, 122, Library**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **12" x 12" grey w/streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Main office**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **12" x 12" grey w/streaks VFT**
MATERIAL LOCATION: **Main office**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89A**
MATERIAL DESCRIPTION: **12" x 12" grey w/streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **89A**
MATERIAL DESCRIPTION: **12" x 12" grey w/streaks Mastic**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **12" x 12" white VFT w/Blue Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Flr Corridor
2nd Flr Corridor
3rd Flr Corridor and room 325**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **12" x 12" white VFT w/Blue Specks**
MATERIAL LOCATION: **1st Flr Corridor
2nd Flr Corridor
3rd Flr Corridor and room 325**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90A**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Speck Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Flr Corridors
3rd Flr Corridor and room 325**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **90A**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Speck Mastic**
MATERIAL LOCATION: **1st and 2nd Flr Corridors
3rd Flr Corridor and room 325**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/Drk Blue Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st and 2nd Flr Corridors
3rd Flr Corridor**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/Drk Blue Streaks VFT**
MATERIAL LOCATION: **1st and 2nd Flr Corridors
3rd Flr Corridor**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91A**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/Drk Blue Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Flr Corridors
3rd Flr Corridor**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **91A**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/Drk Blue Streaks Mastic**
MATERIAL LOCATION: **1st and 2nd Flr Corridors
3rd Flr Corridor**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallway Borders, Vestibule, Stairwells, Toilet Rooms, Room Next to Rm 200, Kitchen, Lunch Room, Service Area**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Hallway Borders, Vestibule, Stairwells, Toilet Rooms, Room Next to Rm 200, Kitchen, Lunch Room, Service Area**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 09/30/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12"X12" Tan w/White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd Floor Band Room, 1st Floor Women's Toilet**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12"X12" Tan w/White Streaks VFT**
MATERIAL LOCATION: **2nd Floor Band Room, 1st Floor Women's Toilet**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93A**
MATERIAL DESCRIPTION: **12"X12" Tan w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Band Room, 1st Floor Women's Toilet**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **93A**
MATERIAL DESCRIPTION: **12"X12" Tan w/White Streaks Mastic**
MATERIAL LOCATION: **2nd Floor Band Room, 1st Floor Women's Toilet**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12"X12" Beige w/White Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms 123, (128 not observed)**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12"X12" Beige w/White Specks VFT**
MATERIAL LOCATION: **Rms 123, (128 not observed)**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94A**
MATERIAL DESCRIPTION: **12"X12" Beige w/White Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rms 123, (128 not observed)**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **94A**
MATERIAL DESCRIPTION: **12"X12" Beige w/White Specks Mastic**
MATERIAL LOCATION: **Rms 123, (128 not observed)**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **Trowled-on Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, 1st Floor Main Lobby**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **Trowled-on Plaster**
MATERIAL LOCATION: **Auditorium, 1st Floor Main Lobby**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **1'X1' White w/ Holes, Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Serving Area, Lunch Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **1'X1' White w/ Holes, Ceiling Tiles**
MATERIAL LOCATION: **Serving Area, Lunch Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96A**
MATERIAL DESCRIPTION: **1'X1' White w/ Holes, Ceiling Tiles Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Serving Area, Lunch Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **96A**
MATERIAL DESCRIPTION: **1'X1' White w/ Holes, Ceiling Tiles Mastic**
MATERIAL LOCATION: **Serving Area, Lunch Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **Curtain Wall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stage**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **Curtain Wall**
MATERIAL LOCATION: **Stage**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **Linoleum peach**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **Linoleum peach**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98A**
MATERIAL DESCRIPTION: **Linoleum peach MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **98A**
MATERIAL DESCRIPTION: **Linoleum peach MASTIC**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **12"x12" off white w/ tan specs VFT**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 134**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **12"x12" off white w/ tan specs VFT**

MATERIAL LOCATION: **Room 134**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99A**
MATERIAL DESCRIPTION: **12"x12" off white w/ tan specks MASTIC (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 134**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**


HOMOGENEOUS AREA: **99A**
MATERIAL DESCRIPTION: **12"x12" off white w/ tan specks MASTIC (ABATED)**
MATERIAL LOCATION: **Room 134**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Boiler Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Boiler Tank Insulation**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Boiler Breeching**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Boiler Breeching**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Boiler Rope**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **3** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Boiler Rope**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **3** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Water Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Other**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Water Tank Insulation**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Unexcavated Space**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Aircell Duct Insulation**

MATERIAL LOCATION: **Unexcavated Space**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Excavated space**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**


HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Excavated space**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Excavated Space**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **Excavated Space**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **3500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout (See Hatching Maps)**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Air Erosion/Flow Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout (See Hatching Maps)**

MATERIAL QUANTITY: **3250**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps)**
MATERIAL QUANTITY: **3250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout (See Hatching Maps)**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 09/09/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **1'x1' Textured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Teachers Lounge**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUIDLING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **1'x1' Textured Ceiling Tile**
MATERIAL LOCATION: **Basement Teachers Lounge**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**


HOMOGENEOUS AREA: **121A**
MATERIAL DESCRIPTION: **20" x 20" light gray VFT and mastic**
MATERIAL LOCATION: **Rooms 125, 222, 224, 226, 225**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **20" x 20" blue Vft & Mastic**
MATERIAL LOCATION: **Rooms 125, 222, 224, 226, 225**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **120A**
MATERIAL DESCRIPTION: **20" x 20" gray VFT and Mastic**
MATERIAL LOCATION: **Rooms 125, 222, 224, 226, 225**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/30/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**


HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **20" x 20" gray VFT and Mastic**
MATERIAL LOCATION: **Rooms 125, 222, 224, 226, 225**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/30/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**


HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **20" x 20" light gray VFT and mastic**
MATERIAL LOCATION: **Rooms 125, 222, 224, 226, 225**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/30/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Sullivan High School** INSPECTION DATE: **9/9/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **119A**
MATERIAL DESCRIPTION: **20" X 20" blue VFT & Mastic**
MATERIAL LOCATION: **Rooms 125, 222, 224, 226, 225**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **09/09/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **119A**
MATERIAL DESCRIPTION: **20" X 20" blue VFT & Mastic**
MATERIAL LOCATION: **Rooms 125, 222, 224, 226, 225**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46301** BUILDING ID: **1570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Sullivan High School** REVIEW DATE: **9/30/2022**
ADDRESS: **6631 N. Bosworth Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Black countertop**
MATERIAL LOCATION: **Rooms 125, 222, 224, 226, 225**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **09/30/2022**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that KEVIN HANNA
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/15/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA-II, Authorized by both AHERA & ASHARA.

01/15/2022
Course Dates:

01/15/2023
Expires:

2201BIR10
Certificate Number:



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in black ink, appearing to read "N. Peneff". The signature is written in a cursive style and is positioned above the printed name of the Director of Training.

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 20525

ISSUED
4/14/2022

EXPIRES
05/15/2023

KEVIN HANNA
7809 KOLMAR AVE
SKOKIE, IL 60076

Environmental Health



7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2023



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/23/2023

Exam Date: 2/23/2023

Expiration Date: 2/23/2024

Certificate Number: MPR2302230560

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: MPR2203090714

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090705

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 07342

ISSUED
4/1/2022

EXPIRES
05/15/2023

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612



Environmental Health

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/1/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p>		<p>TC EXPIRES</p>
<p>ID NUMBER 100 - 07342</p>	<p>ISSUED 4/1/2022</p>	<p>EXPIRES 05/15/2023</p>	<p>INSPECTOR</p>	<p>3/9/2023</p>	
<p>JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health</p> 			<p>PROJECT DESIGNER</p>	<p>3/24/2023</p>	
			<p>MANAGEMENT PLANNER</p>	<p>3/9/2023</p>	
			<p>PROJECT MANAGER</p>	<p>3/2/2023</p>	
			<p>AIR SAMPLING PROFESSIONAL</p>		
			<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed