

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0048  
SCHOOL NAME: Washington High School  
ADDRESS OF SCHOOL: 3535 E. 114th St.  
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **9/10/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 7/20/2022 ENROLLMENT 1482  
IDPH INSPECTOR LICENSE NUMBER: 100-04208  
IDPH LICENSED INSPECTOR NAME (Please Print): James Lehnhardt  
IDPH MP LICENSE NUMBER: 100-09870  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



8/15/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Washington High School**

3535 E. 114th St.  
Chicago, IL, 60617

Unit: 46331  
Building ID: 1630

IDPH ID Number: 14-016-2990-0048

**REPORT DATE:**

Monday, August 15, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

08/15/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 46331                      Region: 06                      IDPH ID: 14-016-2990-0048

School: Washington High School                      Building ID: 1630

Address: 3535 E. 114th St.

Chicago, IL, 60617

Building Contact: Haraf, Michael

Contact Phone: 7737097249

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/20/2022

Review Date: 08/15/2022

Inspector: James Lehnhardt

Inspector IDPH License: 100-04208

Management Planner: Todd Huffer

Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Todd Huffer  
100-09870

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 15, 2022

RE: Washington High School, Unit 46331  
3535 E. 114th St.  
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Washington High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Washington High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Washington High School Unit: 46331 Region: 06  
Address: 3535 E. 114th St. Chicago, IL, 60617  
IDPH ID: 14-016-2990-0048 Building ID: 1630  
Contact: Haraf, Michael Phone: 7737097249

### 2. Description of Facility

Original Construction: 1957 Additional Construction:  
Total Square Footage: 214541 No of Floors: 3  
Current Occupancy: 1482

### 3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602


### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880 Fax: 630-790-0882

### 5. Inspector

Inspector Name: James Lehnhardt


Inspector IDPH license # 100-04208  
Reinspection Date: 7/20/2022

Signature:   
Date: 7/20/2022

### 6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870


Signature:   
Date: 08/15/2022

### 7. Review Date: 08/15/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 8/15/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Washington High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1630:

77	2'x2' Ceiling Tile w/Fissures & Dots
78	40"x40" Grey & White Floor Tile
79	40"x40" Grey & White Floor Tile Mastic
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 1630:

77	2'x2' Ceiling Tile w/Fissures & Dots
78	40"x40" Grey & White Floor Tile
79	40"x40" Grey & White Floor Tile Mastic
NEW	Newly Installed Suspect ACM



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

15R	12x12 Purple w/White Checkerboard Floor Tile NOT OBSERVED
24	12x12 Variegated Brown Floor Tile
28	12x12 Variegated Brown Floor Tile
31	12x12 Varigated Brown Floor Tile Mastic
36	12x12 Off-White Floor Tile NOT OBSERVED
37	12x12 Off-White Floor Tile Mastic NOT OBSERVED
38	Insulation in Fire Rated Doors
39	Insulation in Fire Rated Doors
41	Insulation in Fire Rated Doors
44	2'x6' Textured Celing
60	12x12 Variegated Brown Floor Tile Mastic
68	12x12 Dark Brown Floor Tile NOT OBSERVED
69	12x12 Brown Floor Tile
70	12x12 Brown Floor Tile Mastic
71	12x12 Brown Speckled Floor Tile
72	12x12 Brown Speckled Floor Tile Mastic
73	Brown Carpet Mastic
74	1x1 Ceiling Tile
75	1x1 Ceiling Tile Mastic
76	Tank Insulation
77	2'x2' Ceiling Tile w/Fissures & Dots
78	40"x40" Grey & White Floor Tile
79	40"x40" Grey & White Floor Tile Mastic
AA	12x12 White w/Tan Specks Vinyl Floor Tile
AA-1	12x12 White w/Tan Specks Vinyl Floor Tile Mastic
BB	Yellowish Linoleum
BB-1	Yellowish Linoleum Mastic
CC	2'x2' S. White ACT
DD	Drywall
K	Insulation Fire Rated Doors
NEW	Newly Installed Suspect ACM
O	Aircell Pipe Insulation
P	MJP E/F/V on Aircell Pipe Insulation NOT OBSERVED
Q	Cardboard Pipe Insulation NOT OBSERVED
R	MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED
V	Vibration Dampener
W	12x12 White w/Gray Specks Vinyl Floor Tile
W-1	12x12 White w/Gray Specks Vinyl Floor Tile

	Mastic
X	12x12 Burgundy Vinyl Floor Tile
X/Y/Z-1	Mastic for HAs X/Y/Z
Y	12x12 Peach Vinyl Floor Tile
Z	12x12 Geen Vinyl Floor Tile

The following areas were deemed to be inaccessible:

23	Transite Arc Shield
32	9x9 Gray w/Blue Floor Tile Mastic NOT OBSERVED
32E	12x12 Cream Floor Tile Mastic
37	12x12 Off-White Floor Tile Mastic NOT OBSERVED
44	2'x6' Textured Celing
48	12x12 Tan Floor Tile Mastic
55	12x12 Brown Speck Floor Tile Mastic
59	Black Baseboard Mastic
60	12x12 Variegated Brown Floor Tile Mastic
61	Linoleum Mastic
70	12x12 Brown Floor Tile Mastic
72	12x12 Brown Speckled Floor Tile Mastic
73	Brown Carpet Mastic
75	1x1 Ceiling Tile Mastic
A	Aircell Pipe Insulation
AA-1	12x12 White w/Tan Specks Vinyl Floor Tile Mastic
B	MJP E/F/V on Aircell Pipe Insulation
BB-1	Yellowish Linoleum Mastic
C	Cardboard Pipe Insulation NOT OBSERVED
D	MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED
F	MJP E/F/V on Fiberglass Pipe Insulation
P	MJP E/F/V on Aircell Pipe Insulation NOT OBSERVED
Q	Cardboard Pipe Insulation NOT OBSERVED
R	MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED
V	Vibration Dampener
W-1	12x12 White w/Gray Specks Vinyl Floor Tile Mastic
X/Y/Z-1	Mastic for HAs X/Y/Z

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by James Lehnhardt, IDPH License # 100-04208. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	7/19/2019
	11/14/2019
	12/30/2019
	4/25/2022
	7/27/2022

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Washington High School Building 1630 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Washington High School Unit 46331 Building ID 1630

Address 3535 E. 114th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
05	2'x2' Lay-In Ceiling Panels	80,000	SF	1967 Building- 1st & 2nd Floor Corridors, Library and Room 104	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
12	9x9 Gray Speckled Floor Tile	600	SF	Room 200	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	2'x2' Transite Panels	10,000	SF	1955 Building- Lunchroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15R	12x12 Purple w/White Checkerboard Floor Tile NOT OBSERVED			Room 002	ASSUMED	MISC								
19	Green Linoleum- No ACBM			Room 130	NO_ACBM	MISC								
20	Green Linoleum Mastic No ACBM			Room 130	NO_ACBM	MISC								
23	Transite Arc Shield	6	SF	1955 Building- Switch Board	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12x12 Variegated Brown Floor Tile	3,900	SF	1955 Building- Corridors and Locker Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12x12 Variegated Brown Floor Tile	26,000	SF	1967 Building- Corridors, Rooms 124, 123, 125, 126, 213, 215, 218, 220, 222, 219, Men's & Women's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	9x9 Gray Speckled Floor Tile Mastic	600	SF	Room 200	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	9x9 Gray w/Blue Floor Tile	2,800	SF	1967 Building- Room 217	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12x12 Varigated Brown Floor Tile Mastic	26,000	SF	1967 Building- Corridors, Rooms 124, 123, 125, 126, 213, 215, 218, 220, 222, 219, Men's & Women's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	9x9 Gray w/Blue Floor Tile Mastic NOT OBSERVED	700	SF	1967 Building- Rooms 214, 216, 217	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32E	12x12 Cream Floor Tile Mastic	800	SF	Room 214	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Lab Tabletops No ACBM			1967 Building- Rooms 124, 126	NO_ACBM	MISC								
34	Drywall NOT OBSERVED			(Material Not Observed)		MISC	N	NONE	0		No			LOW



# Chicago Public Schools

School Washington High School Unit 46331 Building ID 1630

Address 3535 E. 114th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
54	12x12 Brown Speck Floor Tile- No ACBM	16,000	SF	1967 Building- Hallways and Rooms 141, 147, 139, 126, 125, 124, 123, 127, 130, 129, 122, 121, 220, 118, 119, 116, 117, 113, 115, 114, 112, 110, 111, 108, 107, 106, 105, 100, 102, 103, 200A, 202, 204-216, 218, 222	NO_ACBM	MISC								
55	12x12 Brown Speck Floor Tile Mastic	16,000	SF	1967 Building- Hallways and Rooms 141, 147, 139, 126, 125, 124, 123, 127, 130, 129, 122, 121, 220, 118, 119, 116, 117, 113, 115, 114, 112, 110, 111, 108, 107, 106, 105, 100, 102, 103, 200A, 202, 204-216, 218, 222	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Blue Carpet Mastic- No ACBM			1967 Building- Library	NO_ACBM	MISC								
57	Hard Plaster	210,000	SF	1967 Building- Restroom Ceilings, Upper Wall 2nd Floor Corridor	CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
58	Black Baseboard	15,000	LF	1967 Building- Throughout	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Black Baseboard Mastic	1,500	LF	1967 Building- Throughout	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	12x12 Variegated Brown Floor Tile Mastic	3,900	SF	1955 Building- Corridors & Locker Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Linoleum Mastic	300	SF	Rooms 128 & 135	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	Linoleum- No ACBM			Rooms 128 & 135	NO_ACBM	MISC								
68	12x12 Dark Brown Floor Tile NOT OBSERVED			1967 Building- 1st and 2nd Floor Corridor	ASSUMED	MISC								
69	12x12 Brown Floor Tile	4,000	SF	1955 Building- Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Washington High School Unit 46331 Building ID 1630

Address 3535 E. 114th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
70	12x12 Brown Floor Tile Mastic	4,000	SF	1955 Building-Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	12x12 Brown Speckled Floor Tile	1,800	SF	Storage Room, Rooms 138, 136, and Locker Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	12x12 Brown Speckled Floor Tile Mastic	1,800	SF	Storage Room, Rooms 138, 136, and Locker Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	Brown Carpet Mastic	300	SF	Attendance Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	1x1 Ceiling Tile	5,000	SF	1955 Building-Hallways and Classrooms	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
75	1x1 Ceiling Tile Mastic	5,000	SF	1955 Building-Hallways and Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	Tank Insulation	200	SF	1955 Building-Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	2'x2' Ceiling Tile w/Fissures & Dots	40	SF	Hallway Outside Room 104	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
78	40"x40" Grey & White Floor Tile	3,257	SF	Rooms 127 & 129 (Science Labs)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
79	40"x40" Grey & White Floor Tile Mastic	3,257	SF	Rooms 127 & 129 (Science Labs)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation	50,000	LF	1955 Building-Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
AA	12x12 White w/Tan Specks Vinyl Floor Tile	3,420	SF	Rooms 303, 301, 302 & Hallway (All In Trailer)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AA-1	12x12 White w/Tan Specks Vinyl Floor Tile Mastic	3,420	SF	Rooms 303, 301, 302 & Hallway (All In Trailer)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
B	MJP E/F/V on Aircell Pipe Insulation		LF	1955 Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
BB	Yellowish Linoleum	900	SF	Room 304, Boys' & Girls' Restrooms (All In Trailer)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BB-1	Yellowish Linoleum Mastic	900	SF	Room 304, Boys' & Girls' Restrooms (All In Trailer)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
C	Cardboard Pipe Insulation NOT OBSERVED			1955 Building- NOT FOUND										
CC	2'x2' S. White ACT	4,320	SF	All Ceilings in Trailer Classrooms	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Washington High School Unit 46331 Building ID 1630

Address 3535 E. 114th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
D	MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED			1955 Building- NOT OBSERVED	UNDEFINE D									
DD	Drywall	20,000	SF	All Classrooms In Trailer	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
F	MJP E/F/V on Fiberglass Pipe Insulation	30	LF	1955 Building- Throughout	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
J	Insulation in Fire Rated Doors	12	SF	1955 Building- Throughout	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
K	Insulation Fire Rated Doors	50	SF	1967 Building- Throughout	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		
O	Aircell Pipe Insulation		LF	1967 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
P	MJP E/F/V on Aircell Pipe Insulation NOT OBSERVED			1967 Building	ASSUMED	MISC	Y	NONE	0		No			LOW
Q	Cardboard Pipe Insulation NOT OBSERVED			1967 Building	ASSUMED	MISC	Y				No			LOW
R	MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED			1967 Building	ASSUMED	MISC	Y				No			LOW
S	MJP E/F/V on Fiberglass Pipe Insulation- No ACBM			1967 Building	NO_ACBM	MISC								
U	MJP E/F/V on Fiberglass Pipe Insulation- No ACBM			1977 Fan Room	NO_ACBM	TSI								
V	Vibration Dampener	25	SF	1977 Fan Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
W	12x12 White w/Gray Specks Vinyl Floor Tile	1,300	SF	Engineer's Offices and Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
W-1	12x12 White w/Gray Specks Vinyl Floor Tile Mastic	1,300	SF	Engineer's Offices and Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
X	12x12 Burgundy Vinyl Floor Tile	400	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
X/Y/Z-1	Mastic for HAs X/Y/Z	5,700	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Y	12x12 Peach Vinyl Floor Tile	4,800	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Z	12x12 Geen Vinyl Floor Tile	500	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Washington High School Unit 46331 Building ID 1630  
Address 3535 E. 114th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>7/20/2022</b>
Inspector Name <b>James Lehnhardt</b>
<b>100-04208</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
05	100 SF Removed from Crawlspace 2019; 300 SF Removed 2021 (Hall Near 104) and 3 SF from Pool Mechanical Room; 150 SF Removed from Crawlspace 2022
12	
15	
15R	Not Observed
19	Linoleum Not Observed. 12"x12" Beige w/Specks Floor Tile
20	Linoleum Not Observed. 12"x12" Beige w/Specks Floor Tile
23	
24	
28	
29	
30	
31	
32	Not Observed in Room 215 & 216. 12"x12" Beige w/Specks Floor Tile
32E	
33	
34	Not Observed
35	
36	Material Not Observed 2019
37	Material Not Observed 2019
38	
39	
40	
41	

# Chicago Public Schools

School Washington High School Unit 46331 Building ID 1630

Address 3535 E. 114th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
42	
44	
45	
46	
47	
48	
49	
50	
51	
52	
54	Removed From Rooms 127 & 129
55	Removed From Rooms 127 & 129
56	
57	
58	
59	
60	
61	
62	
68	Not Observed
69	
70	
71	
72	
73	
74	
75	
76	
77	

# Chicago Public Schools

School Washington High School Unit 46331 Building ID 1630

Address 3535 E. 114th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
78	
79	
A	
AA	
AA-1	
B	
BB	
BB-1	
C	
CC	
D	
DD	
F	
J	
K	
NEW	
O	64 LF Removed from Weight Room 2022
P	Not Observed 2019
Q	Not Observed
R	Not Observed
S	
U	
V	
W	
W-1	
X	
X/Y/Z-1	
Y	
Z	

# Chicago Public Schools

**School** Washington High School **Unit** 46331 **Building ID** 1630

**Address** 3535 E. 114th St. **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Washington High School

Unit 46331

Building ID 1630

Address 3535 E. 114th St.

Chicago, IL, 60617

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
05	2'x2' Lay-In Ceiling Panels	80,000	SF	1967 Building- 1st & 2nd Floor Corridors, Library and Room 104	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9x9 Gray Speckled Floor Tile	600	SF	Room 200	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	2'x2' Transite Panels	10,000	SF	1955 Building- Lunchroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15R	12x12 Purple w/White Checkerboard Floor Tile NOT OBSERVED			Room 002	Assumed	MISC					
19	Green Linoleum- No ACBM			Room 130	No ACBM	MISC					
20	Green Linoleum Mastic No ACBM			Room 130	No ACBM	MISC					
23	Transite Arc Shield	6	SF	1955 Building- Switch Board	Chrysotile	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12x12 Variegated Brown Floor Tile	3,900	SF	1955 Building- Corridors and Locker Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12x12 Variegated Brown Floor Tile	26,000	SF	1967 Building- Corridors, Rooms 124, 123, 125, 126, 213, 215, 218, 220, 222, 219, Men's & Women's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	9x9 Gray Speckled Floor Tile Mastic	600	SF	Room 200	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	9x9 Gray w/Blue Floor Tile	2,800	SF	1967 Building- Room 217	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12x12 Variegated Brown Floor Tile Mastic	26,000	SF	1967 Building- Corridors, Rooms 124, 123, 125, 126, 213, 215, 218, 220, 222, 219, Men's & Women's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	9x9 Gray w/Blue Floor Tile Mastic NOT OBSERVED	700	SF	1967 Building- Rooms 214, 216, 217	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32E	12x12 Cream Floor Tile Mastic	800	SF	Room 214	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Lab Tabletops No ACBM			1967 Building- Rooms 124, 126	No ACBM	MISC					
34	Drywall NOT OBSERVED			(Material Not Observed)		MISC	No	0			
35	Fire Board- No ACBM			Driver's Education Mobile Unit	No ACBM	MISC					
36	12x12 Off-White Floor Tile NOT OBSERVED	750	SF	Drivers Education Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12x12 Off-White Floor Tile Mastic NOT OBSERVED	750	SF	Drivers Education Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Insulation in Fire Rated Doors	2	EA	Drivers' Education Mobile Unit	Assumed	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
39	Insulation in Fire Rated Doors	2	EA	Storage Building	Assumed	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
40	Hard Plaster No ACBM			1977 Building- Filter Room, Girls' & Boys' Room, Locker Room, Fan Room, 2nd Floor Bleacher Area	No ACBM	SURFACE					
41	Insulation in Fire Rated Doors	14	EA	1977 Building- Throughout	Assumed	TSI	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
42	2'x4' Fissured Ceiling Tile No ACBM			1977 Offices, 1955 Engineer's Office, and 1964 Rooms 128 & 135	No ACBM	MISC					



# Chicago Public Schools

School Washington High School

Unit 46331

Building ID 1630

Address 3535 E. 114th St.

Chicago, IL, 60617

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
44	2'x6' Textured Ceiling	7,200	SF	1977 Pool Ceiling	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12x12 Tan Floor Tile	100	SF	1977 Storeroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Black Baseboard No ACBM			1977	No ACBM	MISC					
47	Black Baseboard Mastic No ACBM			1977	No ACBM	MISC					
48	12x12 Tan Floor Tile Mastic	100	SF	1977 Storeroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12x12 Dark Brown Floor Tile Mastic- No ACBM			1967 Building- 1st & 2nd Floor Corridor	No ACBM	MISC					
50	12x12 Off-White Floor Tile- No ACBM			1967 Building- SE Library Office	No ACBM	MISC					
51	12x12 Off-White Floor Tile Mastic- No ACBM			1967 Building- SE Library Office	No ACBM	MISC					
52	1'x1' Ceiling Tile- No ACBM			1967 Building- Rooms 100, 102-107, 110, 111, 111A, 112-124, 126, 127, 129, 130, 139, 141, 147, 200A, 201-216, 218-222	No ACBM	MISC					
54	12x12 Brown Speck Floor Tile- No ACBM	16,000	SF	1967 Building- Hallways and Rooms 141, 147, 139, 126, 125, 124, 123, 127, 130, 129, 122, 121, 220, 118, 119, 116, 117, 113, 115, 114, 112, 110, 111, 108, 107, 106, 105, 100, 102, 103, 200A, 202, 204-216, 218, 222	No ACBM	MISC			SF		
55	12x12 Brown Speck Floor Tile Mastic	16,000	SF	1967 Building- Hallways and Rooms 141, 147, 139, 126, 125, 124, 123, 127, 130, 129, 122, 121, 220, 118, 119, 116, 117, 113, 115, 114, 112, 110, 111, 108, 107, 106, 105, 100, 102, 103, 200A, 202, 204-216, 218, 222	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Blue Carpet Mastic- No ACBM			1967 Building- Library	No ACBM	MISC					
57	Hard Plaster	210,000	SF	1967 Building- Restroom Ceilings, Upper Wall 2nd Floor Corridor	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	Black Baseboard	15,000	LF	1967 Building- Throughout	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
59	Black Baseboard Mastic	1,500	LF	1967 Building- Throughout	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
60	12x12 Variegated Brown Floor Tile Mastic	3,900	SF	1955 Building- Corridors & Locker Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Linoleum Mastic	300	SF	Rooms 128 & 135	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Linoleum- No ACBM			Rooms 128 & 135	No ACBM	MISC					
68	12x12 Dark Brown Floor Tile NOT OBSERVED			1967 Building- 1st and 2nd Floor Corridor	Assumed	MISC					
69	12x12 Brown Floor Tile	4,000	SF	1955 Building- Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Washington High School

Unit 46331

Building ID 1630

Address 3535 E. 114th St.

Chicago, IL, 60617

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
70	12x12 Brown Floor Tile Mastic	4,000	SF	1955 Building- Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12x12 Brown Speckled Floor Tile	1,800	SF	Storage Room, Rooms 138, 136, and Locker Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12x12 Brown Speckled Floor Tile Mastic	1,800	SF	Storage Room, Rooms 138, 136, and Locker Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Brown Carpet Mastic	300	SF	Attendance Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	1x1 Ceiling Tile	5,000	SF	1955 Building- Hallways and Classrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	1x1 Ceiling Tile Mastic	5,000	SF	1955 Building- Hallways and Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	Tank Insulation	200	SF	1955 Building- Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	2'x2' Ceiling Tile w/Fissures & Dots	40	SF	Hallway Outside Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	40"x40" Grey & White Floor Tile	3,257	SF	Rooms 127 & 129 (Science Labs)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	40"x40" Grey & White Floor Tile Mastic	3,257	SF	Rooms 127 & 129 (Science Labs)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation	50,000	LF	1955 Building- Boiler Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
AA	12x12 White w/Tan Specks Vinyl Floor Tile	3,420	SF	Rooms 303, 301, 302 & Hallway (All In Trailer)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AA-1	12x12 White w/Tan Specks Vinyl Floor Tile Mastic	3,420	SF	Rooms 303, 301, 302 & Hallway (All In Trailer)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	MJP E/F/V on Aircell Pipe Insulation		LF	1955 Building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BB	Yellowish Linoleum	900	SF	Room 304, Boys' & Girls' Restrooms (All In Trailer)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BB-1	Yellowish Linoleum Mastic	900	SF	Room 304, Boys' & Girls' Restrooms (All In Trailer)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Cardboard Pipe Insulation NOT OBSERVED			1955 Building- NOT FOUND							
CC	2'x2' S. White ACT	4,320	SF	All Ceilings in Trailer Classrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED			1955 Building- NOT OBSERVED	Undefined						
DD	Drywall	20,000	SF	All Classrooms In Trailer	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP E/F/V on Fiberglass Pipe Insulation	30	LF	1955 Building- Throughout	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
J	Insulation in Fire Rated Doors	12	SF	1955 Building- Throughout	Chrysotile	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	Insulation Fire Rated Doors	50	SF	1967 Building- Throughout	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan
O	Aircell Pipe Insulation		LF	1967 Building	Assumed	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Washington High School

Unit 46331

Building ID 1630

Address 3535 E. 114th St.

Chicago, IL, 60617

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
P	MJP E/F/V on Aircell Pipe Insulation NOT OBSERVED			1967 Building	Assumed	MISC	Yes	0			
Q	Cardboard Pipe Insulation NOT OBSERVED			1967 Building	Assumed	MISC	Yes				
R	MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED			1967 Building	Assumed	MISC	Yes				
S	MJP E/F/V on Fiberglass Pipe Insulation- No ACBM			1967 Building	No ACBM	MISC					
U	MJP E/F/V on Fiberglass Pipe Insulation- No ACBM			1977 Fan Room	No ACBM	TSI					
V	Vibration Dampener	25	SF	1977 Fan Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
W	12x12 White w/Gray Specks Vinyl Floor Tile	1,300	SF	Engineer's Offices and Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
W-1	12x12 White w/Gray Specks Vinyl Floor Tile Mastic	1,300	SF	Engineer's Offices and Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
X	12x12 Burgundy Vinyl Floor Tile	400	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
X/Y/Z-1	Mastic for HAs X/Y/Z	5,700	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Y	12x12 Peach Vinyl Floor Tile	4,800	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Z	12x12 Geen Vinyl Floor Tile	500	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Washington High School

**Unit** 46331

**Building ID** 1630

**Address** 3535 E. 114th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	8/15/2022
Manager Planner Name	Todd Huffer
100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
05	
12	
15	
15R	
19	
20	
23	
24	
28	
29	
30	
31	
32	
32E	
33	
34	
35	
36	
37	
38	
39	
40	

# Chicago Public Schools

**School** Washington High School  
**Address** 3535 E. 114th St.

**Unit** 46331  
Chicago, IL, 60617

**Building ID** 1630  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
41	
42	
44	
45	
46	
47	
48	
49	
50	
51	
52	
54	
55	
56	
57	
58	
59	
60	
61	
62	
68	
69	
70	
71	
72	
73	
74	

# Chicago Public Schools

**School** Washington High School  
**Address** 3535 E. 114th St.

**Unit** 46331  
 Chicago, IL, 60617

**Building ID** 1630  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
75	
76	
77	
78	
79	
A	
AA	
AA-1	
B	
BB	
BB-1	
C	
CC	
D	
DD	
F	
J	
K	
NEW	
O	
P	
Q	
R	
S	
U	
V	
W	

# Chicago Public Schools

**School** Washington High School

**Unit** 46331

**Building ID** 1630

**Address** 3535 E. 114th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
W-1	
X	
X/Y/Z-1	
Y	
Z	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---



# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

## 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **2'x2' Lay-In Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building- 1st & 2nd Floor Corridors, Library and Room 104**

MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **100 SF Removed from Crawlspace 2019; 300 SF Removed 2021 (Hall Near 104) and 3 SF from Pool Mechanical Room; 150 SF Removed from Crawlspace 2022**

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **2'x2' Lay-In Ceiling Panels**  
MATERIAL LOCATION: **1967 Building- 1st & 2nd Floor Corridors, Library and Room 104**  
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9x9 Gray Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9x9 Gray Speckled Floor Tile**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **2'x2' Transite Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Lunchroom**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **2'x2' Transite Panels**  
MATERIAL LOCATION: **1955 Building- Lunchroom**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15R**  
MATERIAL DESCRIPTION: **12x12 Purple w/White Checkerboard Floor Tile NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 002**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **15R**  
MATERIAL DESCRIPTION: **12x12 Purple w/White Checkerboard Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **Room 002**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Green Linoleum- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Linoleum Not Observed. 12"x12" Beige w/Specks Foor Tile**

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Green Linoleum- No ACBM**  
MATERIAL LOCATION: **Room 130**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Linoleum Not Observed. 12"x12" Beige w/Specks Foor Tile**

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic No ACBM**  
MATERIAL LOCATION: **Room 130**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Transite Arc Shield**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Switch Board**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Transite Arc Shield**  
MATERIAL LOCATION: **1955 Building- Switch Board**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46331**    BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School**    INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.**    IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12x12 Variegated Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Corridors and Locker Rooms**  
MATERIAL QUANTITY: **3900**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12x12 Variegated Brown Floor Tile**  
MATERIAL LOCATION: **1955 Building- Corridors and Locker Rooms**  
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12x12 Variegated Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building- Corridors, Rooms 124, 123, 125, 126, 213, 215, 218, 220, 222, 219, Men's & Women's Washrooms**

MATERIAL QUANTITY: **26000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12x12 Variegated Brown Floor Tile**  
MATERIAL LOCATION: **1967 Building- Corridors, Rooms 124, 123, 125, 126, 213, 215, 218, 220, 222, 219, Men's & Women's Washrooms**  
MATERIAL QUANTITY: **26000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **9x9 Gray Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **9x9 Gray Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **9x9 Gray w/Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building- Room 217**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **9x9 Gray w/Blue Floor Tile**  
MATERIAL LOCATION: **1967 Building- Room 217**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12x12 Varigated Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building- Corridors, Rooms 124, 123, 125, 126, 213, 215, 218, 220, 222, 219, Men's & Women's Washrooms**

MATERIAL QUANTITY: **26000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12x12 Varigated Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1967 Building- Corridors, Rooms 124, 123, 125, 126, 213, 215, 218, 220, 222, 219, Men's & Women's Washrooms**  
MATERIAL QUANTITY: **26000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **9x9 Gray w/Blue Floor Tile Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building- Rooms 214, 216, 217**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Room 215 & 216. 12"x12" Beige w/Specks Floor Tile**

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **9x9 Gray w/Blue Floor Tile Mastic NOT OBSERVED**  
MATERIAL LOCATION: **1967 Building- Rooms 214, 216, 217**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32E**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 214**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **32E**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**  
MATERIAL LOCATION: **Room 214**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Lab Tabletops No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building- Rooms 124, 126**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Lab Tabletops No ACBM**  
MATERIAL LOCATION: **1967 Building- Rooms 124, 126**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Drywall NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **(Material Not Observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Drywall NOT OBSERVED**  
MATERIAL LOCATION: **(Material Not Observed)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Fire Board- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Driver's Education Mobile Unit**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Fire Board- No ACBM**  
MATERIAL LOCATION: **Driver's Education Mobile Unit**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Drivers Education Mobile Unit**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Material Not Observed 2019**

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **Drivers Education Mobile Unit**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Drivers Education Mobile Unit**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Material Not Observed 2019**

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic NOT OBSERVED**  
MATERIAL LOCATION: **Drivers Education Mobile Unit**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Drivers' Education Mobile Unit**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**  
MATERIAL LOCATION: **Drivers' Education Mobile Unit**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Storage Building**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**  
MATERIAL LOCATION: **Storage Building**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Hard Plaster No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1977 Building- Filter Room, Girls' & Boys' Room, Locker Room, Fan Room, 2nd Floor Bleacher Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Hard Plaster No ACBM**  
MATERIAL LOCATION: **1977 Building- Filter Room, Girls' & Boys' Room, Locker Room, Fan Room, 2nd Floor Bleacher Area**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 08/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1977 Building- Throughout**  
MATERIAL QUANTITY: **14** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**  
MATERIAL LOCATION: **1977 Building- Throughout**  
MATERIAL QUANTITY: **14** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **2'x4' Fissured Ceiling Tile No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1977 Offices, 1955 Engineer's Office, and 1964 Rooms 128 & 135**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **2'x4' Fissured Ceiling Tile No ACBM**  
MATERIAL LOCATION: **1977 Offices, 1955 Engineer's Office, and 1964 Rooms 128 & 135**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **2'x6' Textured Celing**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1977 Pool Ceiling**  
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **2'x6' Textured Ceiling**  
MATERIAL LOCATION: **1977 Pool Ceiling**  
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1977 Storeroom**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
MATERIAL LOCATION: **1977 Storeroom**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Black Baseboard No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1977**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Black Baseboard No ACBM**  
MATERIAL LOCATION: **1977**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Black Baseboard Mastic No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1977**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Black Baseboard Mastic No ACBM**  
MATERIAL LOCATION: **1977**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1977 Storeroom**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1977 Storeroom**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building- 1st & 2nd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic- No ACBM**

MATERIAL LOCATION: **1967 Building- 1st & 2nd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building- SE Library Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile- No ACBM**  
MATERIAL LOCATION: **1967 Building- SE Library Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building- SE Library Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic- No ACBM**  
MATERIAL LOCATION: **1967 Building- SE Library Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building- Rooms 100, 102-107, 110, 111, 111A, 112-124, 126, 127, 129, 130, 139, 141, 147, 200A, 201-216, 218-222**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile- No ACBM**  
MATERIAL LOCATION: **1967 Building- Rooms 100, 102-107, 110, 111, 111A, 112-124, 126, 127, 129, 130, 139, 141, 147, 200A, 201-216, 218-222**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 08/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12x12 Brown Speck Floor Tile- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building- Hallways and Rooms 141, 147, 139, 126, 125, 124, 123, 127, 130, 129, 122, 121, 220, 118, 119, 116, 117, 113, 115, 114, 112, 110, 111, 108, 107, 106, 105, 100, 102, 103, 200A, 202, 204-216, 218, 222**

MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Removed From Rooms 127 & 129**

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12x12 Brown Speck Floor Tile- No ACBM**  
MATERIAL LOCATION: **1967 Building- Hallways and Rooms 141, 147, 139, 126, 125, 124, 123, 127, 130, 129, 122, 121, 220, 118, 119, 116, 117, 113, 115, 114, 112, 110, 111, 108, 107, 106, 105, 100, 102, 103, 200A, 202, 204-216, 218, 222**  
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 08/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12x12 Brown Speck Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building- Hallways and Rooms 141, 147, 139, 126, 125, 124, 123, 127, 130, 129, 122, 121, 220, 118, 119, 116, 117, 113, 115, 114, 112, 110, 111, 108, 107, 106, 105, 100, 102, 103, 200A, 202, 204-216, 218, 222**

MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Removed From Rooms 127 & 129**

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12x12 Brown Speck Floor Tile Mastic**  
MATERIAL LOCATION: **1967 Building- Hallways and Rooms 141, 147, 139, 126, 125, 124, 123, 127, 130, 129, 122, 121, 220, 118, 119, 116, 117, 113, 115, 114, 112, 110, 111, 108, 107, 106, 105, 100, 102, 103, 200A, 202, 204-216, 218, 222**  
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building- Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic- No ACBM**  
MATERIAL LOCATION: **1967 Building- Library**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Hard Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building- Restroom Ceilings, Upper Wall 2nd Floor Corridor**  
MATERIAL QUANTITY: **210000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Hard Plaster**  
MATERIAL LOCATION: **1967 Building- Restroom Ceilings, Upper Wall 2nd Floor Corridor**  
MATERIAL QUANTITY: **210000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Black Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building- Throughout**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Black Baseboard**  
MATERIAL LOCATION: **1967 Building- Throughout**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Black Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building- Throughout**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Black Baseboard Mastic**  
MATERIAL LOCATION: **1967 Building- Throughout**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12x12 Variegated Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Corridors & Locker Rooms**  
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12x12 Variegated Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1955 Building- Corridors & Locker Rooms**  
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 128 & 135**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Linoleum Mastic**  
MATERIAL LOCATION: **Rooms 128 & 135**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Linoleum- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 128 & 135**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Linoleum- No ACBM**  
MATERIAL LOCATION: **Rooms 128 & 135**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building- 1st and 2nd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **1967 Building- 1st and 2nd Floor Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Hallways**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
MATERIAL LOCATION: **1955 Building- Hallways**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Hallways**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1955 Building- Hallways**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Storage Room, Rooms 138, 136, and Locker Rooms**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile**  
MATERIAL LOCATION: **Storage Room, Rooms 138, 136, and Locker Rooms**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Storage Room, Rooms 138, 136, and Locker Rooms**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Storage Room, Rooms 138, 136, and Locker Rooms**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attendance Office**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **Attendance Office**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **1x1 Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Hallways and Classrooms**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **1x1 Ceiling Tile**  
MATERIAL LOCATION: **1955 Building- Hallways and Classrooms**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **1x1 Ceiling Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Hallways and Classrooms**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **1x1 Ceiling Tile Mastic**  
MATERIAL LOCATION: **1955 Building- Hallways and Classrooms**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Boiler Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **1955 Building- Boiler Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Boiler Room**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1955 Building- Boiler Room**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 303, 301, 302 & Hallway (All In Trailer)**  
MATERIAL QUANTITY: **3420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 303, 301, 302 & Hallway (All In Trailer)**  
MATERIAL QUANTITY: **3420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA-1**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 303, 301, 302 & Hallway (All In Trailer)**

MATERIAL QUANTITY: **3420**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **AA-1**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 303, 301, 302 & Hallway (All In Trailer)**  
MATERIAL QUANTITY: **3420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1955 Building**

MATERIAL QUANTITY:

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **1955 Building**  
MATERIAL QUANTITY: MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB**  
MATERIAL DESCRIPTION: **Yellowish Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 304, Boys' & Girls' Restrooms (All In Trailer)**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **BB**  
MATERIAL DESCRIPTION: **Yellowish Linoleum**  
MATERIAL LOCATION: **Room 304, Boys' & Girls' Restrooms (All In Trailer)**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB-1**  
MATERIAL DESCRIPTION: **Yellowish Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 304, Boys' & Girls' Restrooms (All In Trailer)**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **BB-1**  
MATERIAL DESCRIPTION: **Yellowish Linoleum Mastic**  
MATERIAL LOCATION: **Room 304, Boys' & Girls' Restrooms (All In Trailer)**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 Building- NOT FOUND**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation NOT OBSERVED**  
MATERIAL LOCATION: **1955 Building- NOT FOUND**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CC**  
MATERIAL DESCRIPTION: **2'x2' S. White ACT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Ceilings in Trailer Classrooms**  
MATERIAL QUANTITY: **4320** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **CC**  
MATERIAL DESCRIPTION: **2'x2' S. White ACT**  
MATERIAL LOCATION: **All Ceilings in Trailer Classrooms**  
MATERIAL QUANTITY: **4320** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Undefined** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 Building- NOT OBSERVED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED**  
MATERIAL LOCATION: **1955 Building- NOT OBSERVED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DD**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Classrooms In Trailer**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **DD**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **All Classrooms In Trailer**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Throughout**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **1955 Building- Throughout**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1955 Building- Throughout**  
MATERIAL QUANTITY: **12** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**  
MATERIAL LOCATION: **1955 Building- Throughout**  
MATERIAL QUANTITY: **12** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Insulation Fire Rated Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1967 Building- Throughout**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Insulation Fire Rated Doors**  
MATERIAL LOCATION: **1967 Building- Throughout**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **64 LF Removed from Weight Room 2022**

Inspector's Signature: \_\_\_\_\_



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1967 Building**  
MATERIAL QUANTITY: MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation NOT OBSERVED**  
MATERIAL LOCATION: **1967 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation NOT OBSERVED**  
MATERIAL LOCATION: **1967 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1967 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED**  
MATERIAL LOCATION: **1967 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1967 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation- No ACBM**  
MATERIAL LOCATION: **1967 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation- No ACBM**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1977 Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation- No ACBM**  
MATERIAL LOCATION: **1977 Fan Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Vibration Dampener**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1977 Fan Room**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Vibration Dampener**  
MATERIAL LOCATION: **1977 Fan Room**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46331**    BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School**    INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.**    IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **12x12 White w/Gray Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Offices and Main Office**  
MATERIAL QUANTITY: **1300**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **12x12 White w/Gray Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Engineer's Offices and Main Office**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W-1**  
MATERIAL DESCRIPTION: **12x12 White w/Gray Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Offices and Main Office**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **W-1**  
MATERIAL DESCRIPTION: **12x12 White w/Gray Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Engineer's Offices and Main Office**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **12x12 Burgundy Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **12x12 Burgundy Vinyl Floor Tile**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X/Y/Z-1**  
MATERIAL DESCRIPTION: **Mastic for HAs X/Y/Z**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **X/Y/Z-1**  
MATERIAL DESCRIPTION: **Mastic for HAs X/Y/Z**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **12x12 Peach Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **12x12 Peach Vinyl Floor Tile**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **12x12 Geen Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **12x12 Geen Vinyl Floor Tile**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/15/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46331	BUIDLING ID:	1630
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	James Lehnhardt		
SCHOOL NAME:	Washington High School	INSPECTION DATE:	7/20/2022		
ADDRESS:	3535 E. 114th St.	IDPH LICENSE NO:	100-04208		

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	NEW	
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM	
MATERIAL LOCATION:	Installed After Implementation of Management Plan and After Renovations	
MATERIAL QUANTITY:		MATERIAL UNITS:
MATERIAL CATEGORY:	MISC	FRIABLE:
ASBESTOS TYPE:	Assumed	
DISTURBANCE POTENTIAL:		CONDITION:
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage	
ACCESSIBILITY:	Within Reach	DAMAGE REASON:
		DAMAGE REASON:
DAMAGE QUANTITY:		DAMAGE REASON:
		DAMAGE UNITS:
COMMENTS:		

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 08/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **40"x40" Grey & White Floor Tile**  
MATERIAL LOCATION: **Rooms 127 & 129 (Science Labs)**  
MATERIAL QUANTITY: **3257** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **40"x40" Grey & White Floor Tile**  
MATERIAL LOCATION: **Rooms 127 & 129 (Science Labs)**  
MATERIAL QUANTITY: **3257** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 08/15/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46331**    BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School**    INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.**    IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **40"x40" Grey & White Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 127 & 129 (Science Labs)**  
MATERIAL QUANTITY: **3257**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **07/20/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **40"x40" Grey & White Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 127 & 129 (Science Labs)**  
MATERIAL QUANTITY: **3257** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 08/15/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUIDLING ID: **1630**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**  
SCHOOL NAME: **Washington High School** INSPECTION DATE: **7/20/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile w/Fissures & Dots**  
MATERIAL LOCATION: **Hallway Outside Room 104**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: 07/20/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46331** BUILDING ID: **1630**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Washington High School** REVIEW DATE: **8/15/2022**  
ADDRESS: **3535 E. 114th St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile w/Fissures & Dots**  
MATERIAL LOCATION: **Hallway Outside Room 104**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 08/15/2022

# APPENDIX B

## Inspector and Management Planner Licenses

---



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Jim Lehnhardt**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082271

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JAMES D LEHNHARDT**  
15301 KILPATRICK AVE, APT. 4  
OAK FOREST, IL 60452

3/15/2022


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04208

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	10/8/2022
100 - 04208	3/15/2022	05/15/2023	PROJECT MANAGER	10/9/2022
<b>JAMES D LEHNHARDT</b> 15301 KILPATRICK AVE, APT. 4 OAK FOREST, IL 60452 Environmental Health			AIR SAMPLING PROFESSIONAL	
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**James Lehnhardt**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: BIR2211033511

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director





525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**TODD T HUFFER**  
315 HATLEN COURT  
MT. PROSPECT, IL 60056

2/18/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	<b>ASBESTOS PROFESSIONAL LICENSE</b>		INSPECTOR	11/1/2022
ID NUMBER 100 - 09870	ISSUED 2/18/2022	EXPIRES 05/15/2023	MANAGEMENT PLANNER	11/19/2022
<b>TODD T HUFFER</b> 315 HATLEN COURT MT. PROSPECT, IL 60056 Environmental Health			PROJECT MANAGER	10/20/2022
			AIR SAMPLING PROFESSIONAL	
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

## Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815

  
Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255

  
Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265

  
Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed