

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0543
SCHOOL NAME: Corliss High School
ADDRESS OF SCHOOL: 821 E. 103rd St.
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **9/9/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/2/2022 ENROLLMENT 287
IDPH INSPECTOR LICENSE NUMBER: 100-04208
IDPH LICENSED INSPECTOR NAME (Please Print): James Lehnhardt
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

9/5/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Corliss High School

821 E. 103rd St.
Chicago, IL, 60628

Unit: 46391
Building ID: 1860

IDPH ID Number: 14-016-2990-0543

REPORT DATE:

Monday, September 05, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

09/05/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 46391 Region: 06 IDPH ID: 14-016-2990-0543

School: Corliss High School Building ID: 1860

Address: 821 E. 103rd St.

Chicago, IL, 60628

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/2/2022

Review Date: 09/05/2022

Inspector: James Lehnhardt

Inspector IDPH License: 100-04208

Management Planner: Todd Huffer

Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 05, 2022

RE: Corliss High School, Unit 46391
821 E. 103rd St.
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Corliss High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Corliss High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Corliss High School
Address: 821 E. 103rd St.
IDPH ID: 14-016-2990-0543
Contact:

Unit: 46391
Chicago, IL, 60628
Building ID: 1860
Phone:

Region: 06

2. Description of Facility

Original Construction:
Total Square Footage:
Current Occupancy: 287

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant


MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: James Lehnhardt


Inspector IDPH license # 100-04208
Reinspection Date: 9/2/2022

Signature: 
Date: 9/2/2022

6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870


Signature: 
Date: 09/05/2022

7. Review Date: 09/05/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 9/5/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Corliss High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1860:

NEW

Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 1860:

L	Hard Fitting on Fiberglass Pipe Insulation
NEW	Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

07A	12x12 Black w/Tan Specks Floor Tile
07B	12x12 Cream Speckled Floor Tile
07C	12x12 Multicolor Beige Floor Tile
07D	12x12 Dark Brown Floor Tile
07E	12x12 Light Blue Floor Tile
07F	12x12 Black w/White Specks Floor Tile
08A	12x12 Black w/Tan Specks Floor Tile Mastic
08B	12x12 Cream Floor Tile Mastic
08C	12x12 Multicolor Beige Floor Tile Mastic
08D	12x12 Dark Brown Floor Tile Mastic
08E	12x12 Light Blue Floor Tile Mastic
08F	12x12 Black w/White Floor Tile Mastic
09	Brown Mopboard
10	Brown Mopboard Mastic
13	Drywall
14	Drywall Compound
15	Gray Carpet Mastic
15A	12x12 Beige & Purple Checkerboard Pattern Floor Tile
15A-M	12x12 Beige & Purple Checkerboard Pattern Floor Tile Mastic
15B	12x12 Cream and Tan Checkerboard Pattern Floor Tile
15B-M	12x12 Cream and Tan Checkerboard Pattern Floor Tile
15K	12x12 Cream w/Red Streaks Floor Tile- NOT OBSERVED
16	Blue Carpet Mastic
17	Orange Carpet Mastic- NOT OBSERVED
18	Mauve Carpet Mastic- NOT OBSERVED
20	Window Caulk
21	Cream w/Maroon Specks Terrazzo Flooring
22	1'x1' White Fissured Ceiling Tile
23	Tan Linoleum
23M	Tan Linoleum Adhesive
24	2'x2' White Fissured Lay-In Ceiling Panels
25	12x12 White w/Brown Streaks Floor Tile
25M	12x12 White w/Brown Streaks Floor Tile Mastic
26	Multi-Colored Carpet Adhesive
27	12x12 Brown w/Tan Specks Floor Tile
27M	12x12 Brown w/Tan Specks Floor Tile Mastic
28	Maroon Carpet Adhesive

29	1'x1' White Fissured Ceiling Tile (Mounted on Wall)
29M	1'x1' White Fissured Ceiling Tile Adhesive (Mounted on Wall)
30	2'x4' White Dotted Lay-In Ceiling Tile
31	Gray Speckled Carpet Adhesive
32	Spray-On Fire-Proofing
34	Blue Carpet Mastic
36	12x12 White Blue Gray Vinyl Floor Tile
36A	12x12 White Blue Gray Vinyl Floor Tile Mastic
E	Mag Joints
F	Mag Duct Insulation
HA-100	Mag Pipe Insulation
J	Insulation in Firedoors
K	Vibration Damper
L	Hard Fitting on Fiberglass Pipe Insulation
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

08A	12x12 Black w/Tan Specks Floor Tile Mastic
08B	12x12 Cream Floor Tile Mastic
08C	12x12 Multicolor Beige Floor Tile Mastic
08D	12x12 Dark Brown Floor Tile Mastic
08E	12x12 Light Blue Floor Tile Mastic
08F	12x12 Black w/White Floor Tile Mastic
10	Brown Mopboard Mastic
15	Gray Carpet Mastic
15A-M	12x12 Beige & Purple Checkerboard Pattern Floor Tile Mastic
16	Blue Carpet Mastic
23M	Tan Linoleum Adhesive
25M	12x12 White w/Brown Streaks Floor Tile Mastic
26	Multi-Colored Carpet Adhesive
27M	12x12 Brown w/Tan Specks Floor Tile Mastic
28	Maroon Carpet Adhesive
29M	1'x1' White Fissured Ceiling Tile Adhesive (Mounted on Wall)
31	Gray Speckled Carpet Adhesive
34	Blue Carpet Mastic
36A	12x12 White Blue Gray Vinyl Floor Tile Mastic
K	Vibration Damper

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by James Lehnhardt, IDPH License # 100-04208. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Corliss High School Building 1860 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Corliss High School Unit 46391 Building ID 1860

Address 821 E. 103rd St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
07A	12x12 Black w/Tan Specks Floor Tile	23,500	SF	Basement, Men's & Women's Locker Rooms and Washrooms, Elevators, Karate Room, Dance room 293, TV studio 134-139, 175-177, 238, 400-408, 605-607, 609-611, 22B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07B	12x12 Cream Speckled Floor Tile	4,500	SF	Room 102, 103, 107, 108, 109, 110, 112, 2nd Floor Corridor, Main Office Copy Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07C	12x12 Multicolor Beige Floor Tile	36,800	SF	SE, SW, NE, Lockers on 2nd Floor, Assistant Engineer's Office, Rooms 124, 125, 142, 180, 181, 210, 211, 216, 220, 229, 236	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07D	12x12 Dark Brown Floor Tile	8,000	SF	Room 118, 119, 120, 124, Corridor of DPA, 175, 177	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07E	12x12 Light Blue Floor Tile	3,200	SF	Rooms 184, 185, 189 and 191	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07F	12x12 Black w/White Specks Floor Tile	14,400	SF	Room 173, 203-208, 219, 221-224	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08A	12x12 Black w/Tan Specks Floor Tile Mastic	20,000	SF	Basement, Men's & Women's Locker Rooms and Washrooms, Elevators, 2nd Floor Lunchroom, 134-138, 140, 173, 175-177, 238, 400-408	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08B	12x12 Cream Floor Tile Mastic	2,500	SF	Room 103, 175, 176, 2nd Floor Corridor, Main Office Copy Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08C	12x12 Multicolor Beige Floor Tile Mastic	36,800	SF	SE, SW, NE, Lockers on 2nd Floor, 2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Corliss High School Unit 46391 Building ID 1860

Address 821 E. 103rd St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	NOT OBSERVED													
16	Blue Carpet Mastic	600	SF	Throughout Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Orange Carpet Mastic- NOT OBSERVED			201-206, 208, 216, 221, 223, 236, 224, 243, 245, 247, 251-255, 268, 269	ASSUMED	MISC								
18	Mauve Carpet Mastic- NOT OBSERVED			Room 618 and Office	ASSUMED	MISC								
20	Window Caulk	4,000	LF	Windows Throughout School	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Cream w/Maroon Specks Terrazzo Flooring	6,000	SF	Corridors, Lobbies, 400, 402, and 403, 2nd Floor Servery, Men's and Women's Toilets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	1'x1' White Fissured Ceiling Tile	2,500	SF	Corridors, Lobbies, Rooms 400, 402, 403 & Basement Corridor	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
23	Tan Linoleum	7,100	SF	Rooms 201, 202, 228, 230, 232 and Corridor by Room 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
23M	Tan Linoleum Adhesive	7,100	SF	Rooms 201, 202, 228, 230, 232 and Corridor by Room 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	2'x2' White Fissured Lay-In Ceiling Panels	1,092	SF	Room 201/202	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
25	12x12 White w/Brown Streaks Floor Tile	9,200	SF	Corridor outside 139, Rooms 140, 141, 168-172, 178, 188, 192, 122, 268, 269	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25M	12x12 White w/Brown Streaks Floor Tile Mastic	9,200	SF	Corridor outside 139, 140, 141, Rooms 168-172, 178, 188, 192 and Rooms 268, 269, and Adjacent Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Multi-Colored Carpet Adhesive	1,170	SF	Rooms 143, 150-152, 154, 156	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Corliss High School Unit 46391 Building ID 1860

Address 821 E. 103rd St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
27	12x12 Brown w/Tan Specks Floor Tile	1,600	SF	Rooms 183 and 190	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
27M	12x12 Brown w/Tan Specks Floor Tile Mastic	1,600	SF	Rooms 183 and 190	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Maroon Carpet Adhesive	1,600	SF	African Museum, Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	1'x1' White Fissured Ceiling Tile (Mounted on Wall)	2,000	SF	Room 319	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
29M	1'x1' White Fissured Ceiling Tile Adhesive (Mounted on Wall)	2,000	SF	Room 319	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
30	2'x4' White Dotted Lay-In Ceiling Tile	3,500	SF	By Auditorium Hall, Men's & Women's Washrooms	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
31	Gray Speckled Carpet Adhesive	3,600	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Spray-On Fire-Proofing	60,000	SF	Throughout Whole School	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
34	Blue Carpet Mastic	1,200	SF	Media Center, Lecture Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Fume Hood Gasket ABATED			Room 114 and Adjacent Hallway	ABATED									
36	12x12 White Blue Gray Vinyl Floor Tile	1,000	SF	Performance Art Center	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
36A	12x12 White Blue Gray Vinyl Floor Tile Mastic	1,000	SF	Performance Art center	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
E	Mag Joints	50	SF	Throughout Mechanical Room in Basement	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		HIGH
F	Mag Duct Insulation	1,300	SF	Basement Mechanical and Storage Rooms, 2nd floor Custodial closet	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
HA-100	Mag Pipe Insulation	50	LF	Switch Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		HIGH
J	Insulation in Firedoors	1,700	SF	Throughout Building	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
K	Vibration Damper	40	LF	Mechanical Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
L	Hard Fitting on Fiberglass Pipe Insulation	35	EA	Pool Mechanical Room & Pool	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Corliss High School Unit 46391 Building ID 1860

Address 821 E. 103rd St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Locker Rooms										
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

Chicago Public Schools

School Corliss High School Unit 46391 Building ID 1860

Address 821 E. 103rd St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 9/2/2022
Inspector Name James Lehnhardt
100-04208 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
07A	
07B	
07C	Room 176 has 12"x12" Black w/Specks Floor Tile
07D	
07E	
07F	
08A	
08B	
08C	
08D	
08E	
08F	
09	
10	
11	
12	
13	
14	
15	
15A	
15A-M	
15B	
15B-M	
15K	Not Observed Multiple Years

Chicago Public Schools

School Corliss High School Unit 46391 Building ID 1860

Address 821 E. 103rd St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
16	
17	Not Observed Multiple Years
18	Not Observed Multiple Years
20	
21	
22	
23	
23M	
24	
25	
25M	
26	
27	
27M	
28	
29	
29M	
30	
31	
32	
34	
35	
36	
36A	
E	
F	
HA-100	
J	
K	

Chicago Public Schools

School Corliss High School **Unit** 46391 **Building ID** 1860

Address 821 E. 103rd St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
L	
NEW	

Table II

Management Planner's Review

Chicago Public Schools

School Corliss High School

Unit 46391

Building ID 1860

Address 821 E. 103rd St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
07A	12x12 Black w/Tan Specks Floor Tile	23,500	SF	Basement, Men's & Women's Locker Rooms and Washrooms, Elevators, Karate Room, Dance room 293, TV studio 134-139, 175-177, 238, 400-408, 605-607, 609-611, 22B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07B	12x12 Cream Speckled Floor Tile	4,500	SF	Room 102, 103, 107, 108, 109, 110, 112, 2nd Floor Corridor, Main Office Copy Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07C	12x12 Multicolor Beige Floor Tile	36,800	SF	SE, SW, NE, Lockers on 2nd Floor, Assistant Engineer's Office, Rooms 124, 125, 142, 180, 181, 210, 211, 216, 220, 229, 236	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07D	12x12 Dark Brown Floor Tile	8,000	SF	Room 118, 119, 120, 124, Corridor of DPA, 175, 177	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07E	12x12 Light Blue Floor Tile	3,200	SF	Rooms 184, 185, 189 and 191	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07F	12x12 Black w/White Specks Floor Tile	14,400	SF	Room 173, 203- 208, 219, 221-224	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08A	12x12 Black w/Tan Specks Floor Tile Mastic	20,000	SF	Basement, Men's & Women's Locker Rooms and Washrooms, Elevators, 2nd Floor Lunchroom, 134-138, 140, 173, 175-177, 238, 400-408	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08B	12x12 Cream Floor Tile Mastic	2,500	SF	Room 103, 175, 176, 2nd Floor Corridor, Main Office Copy Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08C	12x12 Multicolor Beige Floor Tile Mastic	36,800	SF	SE, SW, NE, Lockers on 2nd Floor, 2nd Floor Corridor, Assistant Engineer's Office, Rooms 124, 125, 180, 181, 210, 211, 216, 220, 229, 236, 239-255, 615 & 618	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08D	12x12 Dark Brown Floor Tile Mastic	8,000	SF	Room 118, 119, 120, 124, and Corridor of DPA, and 175, 177	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08E	12x12 Light Blue Floor Tile Mastic	3,200	SF	Rooms 184, 185, 189 & 191	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08F	12x12 Black w/White Floor Tile Mastic	14,400	SF	Room 173, 176, 203- 209, 221-224, 605-607, 609-611	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Brown Mopboard	1,300	LF	Basement Corridor, Men's and Women's Locker Room, Room 400, 404, 406, 408, 308, 312	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
10	Brown Mopboard Mastic	1,300	SF	Basement Corridor, Men's and	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Corliss High School

Unit 46391

Building ID 1860

Address 821 E. 103rd St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Women's Locker Room, Rooms 400, 404, 406, 408, 308, 312							
11	Lab Tabletops ABATED			Rooms 226, 230, 232, 234, 136	Abated	MISC					
12	Transite Hoods ABATED			Rooms 226, 230, 232, 234, 136	Abated	MISC					
13	Drywall	10,000	SF	Arts Building and Gym Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Drywall Compound	10,000	SF	Arts Building and Gym Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Gray Carpet Mastic	1,850	SF	Rooms 238, 222, 187, 289	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12x12 Beige & Purple Checkerboard Pattern Floor Tile	5,000	SF	Rooms 338, 019, 020, 022, 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A-M	12x12 Beige & Purple Checkerboard Pattern Floor Tile Mastic	6,300	SF	Rooms 338, 246 Office, 179, 019, 020, 022, 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15B	12x12 Cream and Tan Checkerboard Pattern Floor Tile	6,300	SF	Room 326, Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15B-M	12x12 Cream and Tan Checkerboard Pattern Floor Tile	1,600	SF	Room 326, Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15K	12x12 Cream w/Red Streaks Floor Tile- NOT OBSERVED			Room 208	Assumed	MISC					
16	Blue Carpet Mastic	600	SF	Throughout Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Orange Carpet Mastic- NOT OBSERVED			201-206, 208, 216, 221, 223, 236, 224, 243, 245, 247, 251-255, 268, 269	Assumed	MISC					
18	Mauve Carpet Mastic- NOT OBSERVED			Room 618 and Office	Assumed	MISC					
20	Window Caulk	4,000	LF	Windows Throughout School	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
21	Cream w/Maroon Specks Terrazzo Flooring	6,000	SF	Corridors, Lobbies, 400, 402, and 403, 2nd Floor Servery, Men's and Women's Toilets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	1'x1' White Fissured Ceiling Tile	2,500	SF	Corridors, Lobbies, Rooms 400, 402, 403 & Basement Corridor	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
23	Tan Linoleum	7,100	SF	Rooms 201, 202, 228, 230, 232 and Corridor by Room 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23M	Tan Linoleum Adhesive	7,100	SF	Rooms 201, 202, 228, 230, 232 and Corridor by Room 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	2'x2' White Fissured Lay-In Ceiling Panels	1,092	SF	Room 201/202	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
25	12x12 White w/Brown Streaks Floor Tile	9,200	SF	Corridor outside 139, Rooms 140, 141, 168-172, 178, 188, 192, 122, 268, 269	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25M	12x12 White w/Brown Streaks Floor Tile Mastic	9,200	SF	Corridor outside 139, 140, 141, Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Corliss High School

Unit 46391

Building ID 1860

Address 821 E. 103rd St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				168-172, 178, 188, 192 and Rooms 268, 269, and Adjacent Corridor							
26	Multi-Colored Carpet Adhesive	1,170	SF	Rooms 143, 150-152, 154, 156	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x12 Brown w/Tan Specks Floor Tile	1,600	SF	Rooms 183 and 190	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27M	12x12 Brown w/Tan Specks Floor Tile Mastic	1,600	SF	Rooms 183 and 190	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Maroon Carpet Adhesive	1,600	SF	African Museum, Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	1'x1' White Fissured Ceiling Tile (Mounted on Wall)	2,000	SF	Room 319	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
29M	1'x1' White Fissured Ceiling Tile Adhesive (Mounted on Wall)	2,000	SF	Room 319	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	2'x4' White Dotted Lay-In Ceiling Tile	3,500	SF	By Auditorium Hall, Men's & Women's Washrooms	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
31	Gray Speckled Carpet Adhesive	3,600	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Spray-On Fire-Proofing	60,000	SF	Throughout Whole School	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
34	Blue Carpet Mastic	1,200	SF	Media Center, Lecture Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Fume Hood Gasket ABATED			Room 114 and Adjacent Hallway	Abated						
36	12x12 White Blue Gray Vinyl Floor Tile	1,000	SF	Performance Art Center	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36A	12x12 White Blue Gray Vinyl Floor Tile Mastic	1,000	SF	Performance Art center	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
E	Mag Joints	50	SF	Throughout Mechanical Room in Basement	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Mag Duct Insulation	1,300	SF	Basement Mechanical and Storage Rooms, 2nd floor Custodial closet	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
HA-100	Mag Pipe Insulation	50	LF	Switch Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	Insulation in Firedoors	1,700	SF	Throughout Building	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	Vibration Damper	40	LF	Mechanical Room	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
L	Hard Fitting on Fiberglass Pipe Insulation	35	EA	Pool Mechanical Room & Pool Locker Rooms	Assumed	TSI	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Corliss High School
Address 821 E. 103rd St.

Unit 46391
 Chicago, IL, 60628

Building ID 1860
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	9/5/2022
Manager Planner Name	Todd Huffer
100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
07A	
07B	
07C	
07D	
07E	
07F	
08A	
08B	
08C	

Chicago Public Schools

School Corliss High School
Address 821 E. 103rd St.

Unit 46391
 Chicago, IL, 60628

Building ID 1860
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
08D	
08E	
08F	
09	
10	
11	
12	
13	
14	
15	
15A	
15A-M	
15B	
15B-M	
15K	
16	
17	
18	
20	
21	
22	
23	
23M	
24	
25	
25M	
26	

Chicago Public Schools

School Corliss High School
Address 821 E. 103rd St.

Unit 46391
 Chicago, IL, 60628

Building ID 1860
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
27	
27M	
28	
29	
29M	
30	
31	
32	
34	
35	
36	
36A	
E	
F	
HA-100	
J	
K	
L	
NEW	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **12x12 Black w/Tan Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Delamination**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement, Men's & Women's Locker Rooms and Washrooms, Elevators, Karate Room, Dance room 293, TV studio 134-139, 175-177, 238, 400-408, 605-607, 609-611, 22B**

MATERIAL QUANTITY: **23500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **12x12 Black w/Tan Specks Floor Tile**
MATERIAL LOCATION: **Basement, Men's & Women's Locker Rooms and Washrooms, Elevators, Karate Room, Dance room 293, TV studio 134-139, 175-177, 238, 400-408, 605-607, 609-611, 22B**
MATERIAL QUANTITY: **23500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07B**
MATERIAL DESCRIPTION: **12x12 Cream Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 102, 103, 107, 108, 109, 110, 112, 2nd Floor Corridor, Main Office Copy Room**

MATERIAL QUANTITY: **4500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **07B**
MATERIAL DESCRIPTION: **12x12 Cream Speckled Floor Tile**
MATERIAL LOCATION: **Room 102, 103, 107, 108, 109, 110, 112, 2nd Floor Corridor, Main Office Copy Room**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07C**
MATERIAL DESCRIPTION: **12x12 Multicolor Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **SE, SW, NE, Lockers on 2nd Floor, Assistant Engineer's Office, Rooms 124, 125, 142, 180, 181, 210, 211, 216, 220, 229, 236**

MATERIAL QUANTITY: **36800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Room 176 has 12"x12" Black w/Specks Floor Tile**

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **07C**
MATERIAL DESCRIPTION: **12x12 Multicolor Beige Floor Tile**
MATERIAL LOCATION: **SE, SW, NE, Lockers on 2nd Floor, Assistant Engineer's Office, Rooms 124, 125, 142, 180, 181, 210, 211, 216, 220, 229, 236**
MATERIAL QUANTITY: **36800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07D**
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 118, 119, 120, 124, Corridor of DPA, 175, 177**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **07D**
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile**
MATERIAL LOCATION: **Room 118, 119, 120, 124, Corridor of DPA, 175, 177**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07E**
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 184, 185, 189 and 191**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **07E**
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile**
MATERIAL LOCATION: **Rooms 184, 185, 189 and 191**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07F**
MATERIAL DESCRIPTION: **12x12 Black w/White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 173, 203- 208, 219, 221-224**
MATERIAL QUANTITY: **14400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **07F**
MATERIAL DESCRIPTION: **12x12 Black w/White Specks Floor Tile**
MATERIAL LOCATION: **Room 173, 203- 208, 219, 221-224**
MATERIAL QUANTITY: **14400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **12x12 Black w/Tan Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement, Men's & Women's Locker Rooms and Washrooms, Elevators, 2nd Floor Lunchroom, 134-138, 140, 173, 175-177, 238, 400-408**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **12x12 Black w/Tan Specks Floor Tile Mastic**
MATERIAL LOCATION: **Basement, Men's & Women's Locker Rooms and Washrooms, Elevators, 2nd Floor Lunchroom, 134-138, 140, 173, 175-177, 238, 400-408**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08B**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 103, 175, 176, 2nd Floor Corridor, Main Office Copy Room**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **08B**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**
MATERIAL LOCATION: **Room 103, 175, 176, 2nd Floor Corridor, Main Office Copy Room**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08C**
MATERIAL DESCRIPTION: **12x12 Multicolor Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **SE, SW, NE, Lockers on 2nd Floor, 2nd Floor Corridor, Assistant Engineer's Office, Rooms 124, 125, 180, 181, 210, 211, 216, 220, 229, 236, 239-255, 615 & 618**

MATERIAL QUANTITY: **36800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **08C**
MATERIAL DESCRIPTION: **12x12 Multicolor Beige Floor Tile Mastic**
MATERIAL LOCATION: **SE, SW, NE, Lockers on 2nd Floor, 2nd Floor Corridor, Assistant Engineer's Office, Rooms 124, 125, 180, 181, 210, 211, 216, 220, 229, 236, 239-255, 615 & 618**
MATERIAL QUANTITY: **36800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08D**
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 118, 119, 120, 124, and Corridor of DPA, and 175, 177**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **08D**
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 118, 119, 120, 124, and Corridor of DPA, and 175, 177**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08E**
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 184, 185, 189 & 191**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **08E**
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 184, 185, 189 & 191**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08F**
MATERIAL DESCRIPTION: **12x12 Black w/White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 173, 176, 203- 209, 221-224, 605-607, 609-611**
MATERIAL QUANTITY: **14400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **08F**
MATERIAL DESCRIPTION: **12x12 Black w/White Floor Tile Mastic**
MATERIAL LOCATION: **Room 173, 176, 203- 209, 221-224, 605-607, 609-611**
MATERIAL QUANTITY: **14400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Brown Mopboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Corridor, Men's and Women's Locker Room, Room 400, 404, 406, 408, 308, 312**

MATERIAL QUANTITY: **1300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Brown Mopboard**
MATERIAL LOCATION: **Basement Corridor, Men's and Women's Locker Room, Room 400, 404, 406, 408, 308, 312**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Brown Mopboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Corridor, Men's and Women's Locker Room, Rooms 400, 404, 406, 408, 308, 312**

MATERIAL QUANTITY: **1300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Brown Mopboard Mastic**
MATERIAL LOCATION: **Basement Corridor, Men's and Women's Locker Room, Rooms 400, 404, 406, 408, 308, 312**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Lab Tabletops ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 226, 230, 232, 234, 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Lab Tabletops ABATED**

MATERIAL LOCATION: **Rooms 226, 230, 232, 234, 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022** _____

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Transite Hoods ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 226, 230, 232, 234, 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Transite Hoods ABATED**
MATERIAL LOCATION: **Rooms 226, 230, 232, 234, 136**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Arts Building and Gym Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Arts Building and Gym Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Arts Building and Gym Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Arts Building and Gym Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 238, 222, 187, 289**
MATERIAL QUANTITY: **1850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
MATERIAL LOCATION: **Rooms 238, 222, 187, 289**
MATERIAL QUANTITY: **1850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **12x12 Beige & Purple Checkerboard Pattern Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 338, 019, 020, 022, 104**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **12x12 Beige & Purple Checkerboard Pattern Floor Tile**
MATERIAL LOCATION: **Rooms 338, 019, 020, 022, 104**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A-M**
MATERIAL DESCRIPTION: **12x12 Beige & Purple Checkerboard Pattern Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 338, 246 Office, 179, 019, 020, 022, 104**

MATERIAL QUANTITY: **6300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **15A-M**
MATERIAL DESCRIPTION: **12x12 Beige & Purple Checkerboard Pattern Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 338, 246 Office, 179, 019, 020, 022, 104**
MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15B**
MATERIAL DESCRIPTION: **12x12 Cream and Tan Checkerboard Pattern Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 326, Main Office**
MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **15B**
MATERIAL DESCRIPTION: **12x12 Cream and Tan Checkerboard Pattern Floor Tile**
MATERIAL LOCATION: **Room 326, Main Office**
MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15B-M**
MATERIAL DESCRIPTION: **12x12 Cream and Tan Checkerboard Pattern Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 326, Main Office**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **15B-M**
MATERIAL DESCRIPTION: **12x12 Cream and Tan Checkerboard Pattern Floor Tile**
MATERIAL LOCATION: **Room 326, Main Office**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15K**
MATERIAL DESCRIPTION: **12x12 Cream w/Red Streaks Floor Tile- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **15K**
MATERIAL DESCRIPTION: **12x12 Cream w/Red Streaks Floor Tile- NOT OBSERVED**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Main Office**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Throughout Main Office**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Orange Carpet Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **201-206, 208, 216, 221, 223, 236, 224, 243, 245, 247, 251-255, 268, 269**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Orange Carpet Mastic- NOT OBSERVED**

MATERIAL LOCATION: **201-206, 208, 216, 221, 223, 236, 224, 243, 245, 247, 251-255, 268, 269**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Mauve Carpet Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 618 and Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Mauve Carpet Mastic- NOT OBSERVED**

MATERIAL LOCATION: **Room 618 and Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Windows Throughout School**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Window Caulk**
MATERIAL LOCATION: **Windows Throughout School**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Cream w/Maroon Specks Terrazzo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridors, Lobbies, 400, 402, and 403, 2nd Floor Servery, Men's and Women's Toilets**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Cream w/Maroon Specks Terrazzo Flooring**
MATERIAL LOCATION: **Corridors, Lobbies, 400, 402, and 403, 2nd Floor Servery, Men's and Women's Toilets**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **1'x1' White Fissured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Corridors, Lobbies, Rooms 400, 402, 403 & Basement Corridor**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **1'x1' White Fissured Ceiling Tile**
MATERIAL LOCATION: **Corridors, Lobbies, Rooms 400, 402, 403 & Basement Corridor**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUILDING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Tan Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 201, 202, 228, 230, 232 and Corridor by Room 225**
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Tan Linoleum**
MATERIAL LOCATION: **Rooms 201, 202, 228, 230, 232 and Corridor by Room 225**
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23M**
MATERIAL DESCRIPTION: **Tan Linoleum Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 201, 202, 228, 230, 232 and Corridor by Room 225**
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **23M**
MATERIAL DESCRIPTION: **Tan Linoleum Adhesive**
MATERIAL LOCATION: **Rooms 201, 202, 228, 230, 232 and Corridor by Room 225**
MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **2'x2' White Fissured Lay-In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 201/202**
MATERIAL QUANTITY: **1092** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **2'x2' White Fissured Lay-In Ceiling Panels**
MATERIAL LOCATION: **Room 201/202**
MATERIAL QUANTITY: **1092** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12x12 White w/Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridor outside 139, Rooms 140, 141, 168-172, 178, 188, 192, 122, 268, 269**
MATERIAL QUANTITY: **9200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12x12 White w/Brown Streaks Floor Tile**
MATERIAL LOCATION: **Corridor outside 139, Rooms 140, 141, 168-172, 178, 188, 192, 122, 268, 269**
MATERIAL QUANTITY: **9200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25M**
MATERIAL DESCRIPTION: **12x12 White w/Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor outside 139, 140, 141, Rooms 168-172, 178, 188, 192 and Rooms 268, 269, and Adjacent Corridor**

MATERIAL QUANTITY: **9200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **25M**
MATERIAL DESCRIPTION: **12x12 White w/Brown Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Corridor outside 139, 140, 141, Rooms 168-172, 178, 188, 192 and Rooms 268, 269, and Adjacent Corridor**
MATERIAL QUANTITY: **9200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Multi-Colored Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 143, 150-152, 154, 156**
MATERIAL QUANTITY: **1170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Multi-Colored Carpet Adhesive**
MATERIAL LOCATION: **Rooms 143, 150-152, 154, 156**
MATERIAL QUANTITY: **1170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12x12 Brown w/Tan Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 183 and 190**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12x12 Brown w/Tan Specks Floor Tile**
MATERIAL LOCATION: **Rooms 183 and 190**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27M**
MATERIAL DESCRIPTION: **12x12 Brown w/Tan Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 183 and 190**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **27M**
MATERIAL DESCRIPTION: **12x12 Brown w/Tan Specks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 183 and 190**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Maroon Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **African Museum, Engineer's Office**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Maroon Carpet Adhesive**
MATERIAL LOCATION: **African Museum, Engineer's Office**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **1'x1' White Fissured Ceiling Tile (Mounted on Wall)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 319**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **1'x1' White Fissured Ceiling Tile (Mounted on Wall)**
MATERIAL LOCATION: **Room 319**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29M**
MATERIAL DESCRIPTION: **1'x1' White Fissured Ceiling Tile Adhesive (Mounted on Wall)**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 319**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **29M**
MATERIAL DESCRIPTION: **1'x1' White Fissured Ceiling Tile Adhesive (Mounted on Wall)**
MATERIAL LOCATION: **Room 319**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2'x4' White Dotted Lay-In Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **By Auditorium Hall, Men's & Women's Washrooms**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2'x4' White Dotted Lay-In Ceiling Tile**
MATERIAL LOCATION: **By Auditorium Hall, Men's & Women's Washrooms**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Gray Speckled Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Gray Speckled Carpet Adhesive**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Spray-On Fire-Proofing**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout Whole School**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Spray-On Fire-Proofing**
MATERIAL LOCATION: **Throughout Whole School**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Media Center, Lecture Hall**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Media Center, Lecture Hall**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Fume Hood Gasket ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 114 and Adjacent Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Fume Hood Gasket ABATED**

MATERIAL LOCATION: **Room 114 and Adjacent Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/05/2022** _____

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12x12 White Blue Gray Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Performance Art Center**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12x12 White Blue Gray Vinyl Floor Tile**
MATERIAL LOCATION: **Performance Art Center**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36A**
MATERIAL DESCRIPTION: **12x12 White Blue Gray Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Performance Art center**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **36A**
MATERIAL DESCRIPTION: **12x12 White Blue Gray Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Performance Art center**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Mag Joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Throughout Mechanical Room in Basement**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Mag Joints**
MATERIAL LOCATION: **Throughout Mechanical Room in Basement**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Mag Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Mechanical and Storage Rooms, 2nd floor Custodial closet**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Mag Duct Insulation**
MATERIAL LOCATION: **Basement Mechanical and Storage Rooms, 2nd floor Custodial closet**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **Mag Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Switch Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **Mag Pipe Insulation**
MATERIAL LOCATION: **Switch Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Insulation in Firedoors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Insulation in Firedoors**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Vibration Damper**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mechanical Room**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUIDLING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Vibration Damper**
MATERIAL LOCATION: **Mechanical Room**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/05/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUILDING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS:
COMMENTS:

Inspector's Signature: _____



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUILDING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/05/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUILDING ID: **1860**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **James Lehnhardt**
SCHOOL NAME: **Corliss High School** INSPECTION DATE: **9/2/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Hard Fitting on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Pool Mechanical Room & Pool Locker Rooms**
MATERIAL QUANTITY: **35** MATERIAL UNITS: **EA**
MATERIAL CATEGORY: **TSI** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **EA**
COMMENTS:

Inspector's Signature:



Date: **09/02/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46391** BUILDING ID: **1860**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Corliss High School** REVIEW DATE: **9/5/2022**
ADDRESS: **821 E. 103rd St.** IDPH LICENSE NO: **100-04208**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Hard Fitting on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Pool Mechanical Room & Pool Locker Rooms**
MATERIAL QUANTITY: **35** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/05/2022

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Jim Lehnhardt

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082271

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JAMES D LEHNHARDT
15301 KILPATRICK AVE, APT. 4
OAK FOREST, IL 60452

3/15/2022


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04208

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	10/8/2022
100 - 04208	3/15/2022	05/15/2023	PROJECT MANAGER	10/9/2022
JAMES D LEHNHARDT 15301 KILPATRICK AVE, APT. 4 OAK FOREST, IL 60452 Environmental Health			AIR SAMPLING PROFESSIONAL	
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

James Lehnhardt

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: BIR2211033511

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

TODD T HUFFER
315 HATLEN COURT
MT. PROSPECT, IL 60056

2/18/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

			ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS		TC EXPIRES
ID NUMBER 100 - 09870	ISSUED 2/18/2022	EXPIRES 05/15/2023	INSPECTOR				11/1/2022
TODD T HUFFER 315 HATLEN COURT MT. PROSPECT, IL 60056 Environmental Health					MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL		11/19/2022 10/20/2022
					Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265


Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed