

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0532
SCHOOL NAME: Al Raby High School
ADDRESS OF SCHOOL: 3545 West Fulton Avenue
CITY: Chicago, IL, 60624

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **11/21/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 12/15/2022 ENROLLMENT 164
IDPH INSPECTOR LICENSE NUMBER: 100-07134
IDPH LICENSED INSPECTOR NAME (Please Print): Ron Brock
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



12/27/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Al Raby High School

3545 West Fulton Avenue
Chicago, IL, 60624

Unit: 46471
Building ID: 7690

IDPH ID Number: 14-016-2990-0532

REPORT DATE:

Tuesday, December 27, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

12/27/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 46471 Region: 03 IDPH ID: 14-016-2990-0532

School: Al Raby High School Building ID: 7690

Address: 3545 West Fulton Avenue

Chicago, IL, 60624

Building Contact: Sullivan, Michael

Contact Phone: 7737095981

Current Building Owners: Chicago Public Schools

Reinspection Date: 12/15/2022

Review Date: 12/27/2022

Inspector: Ron Brock

Inspector IDPH License: 100-07134

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: December 27, 2022

RE: Al Raby High School, Unit 46471
3545 West Fulton Avenue
Chicago, IL, 60624

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Al Raby High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Al Raby High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Al Raby High School Unit: 46471 Region: 03
Address: 3545 West Fulton Avenue Chicago, IL, 60624
IDPH ID: 14-016-2990-0532 Building ID: 7690
Contact: Sullivan, Michael Phone: 7737095981

2. Description of Facility

Original Construction: 1927 Additional Construction:
Total Square Footage: 156248 No of Floors: 4
Current Occupancy: 164

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Ron Brock


Inspector IDPH license # 100-07134
Reinspection Date: 12/15/2022


Signature:
Date: 12/15/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


Signature:
Date: 12/27/2022

7. Review Date: 12/27/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature:

Date: 12/27/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Al Raby High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7690:

157	12" x 12" Beige w/ Color Floor Tile
158	Mastic Associated w/ 12" x 12" Beige w/ Color Floor Tile
159	12" x 12" Coffee w/ Cream Floor Tile
160	Mastic Associated w/ 12" x 12" Coffee w/ Cream Floor Tile
161	12" x 12" Cream and Coffee Floor Tile
162	Mastic Associated w/ 12" x 12" Cream and Coffee Floor Tile
163	Linoleum
164	Mastic Associated w/ Linoleum

- 166 Mastic Associated w/ 12" x 12" Beige and Coffee Floor Tile
- 168 12" x 12" White w/ brown specks Floor Tile
- 169 Mastic Associated w/ 12" x 12" White w/ brown specks Floor Tile
- 170 Mastic associated with 12" x 12" Dark Brown w/ light brown Streaks Floor tiles
- 171 12" x 12" Dark Brown w/ light brown Streaks Floor tiles
- 172 Gray with light gray streaks Linoleum
- 63 9" x 9" Dark Brown Floor Tile/White & Brown Streaks Mastic
- 64 9" x 9" Orange Speckled Floor Tile Mastic
- 8 9" x 9" Orange Speckled Floor Tile

B. The following new homogenous areas have been identified for Building 7690:

- | | |
|-----|--------------------------------------------------------------------------------|
| 167 | Tongue and groove wooden floor |
| 168 | 12" x 12" White w/ brown specks Floor Tile |
| 169 | Mastic Associated w/ 12" x 12" White w/ brown specks Floor Tile |
| 170 | Mastic associated with 12" x 12" Dark Brown w/ light brown Streaks Floor tiles |
| 171 | 12" x 12" Dark Brown w/ light brown Streaks Floor tiles |
| 172 | Gray with light gray streaks Linoleum |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

106	Carpet mastic
107	Carpet mastic (green) - removed
108	1" Square white ceramic (tile grout)
109	Insulation inside firedoors
110	Roofing material - Non-AHERA
112	Roofing material - Non-AHERA
113	Roof flashing - Non-AHERA
114	Roofing material - Non-AHERA
115	Roofing material - Non-AHERA
116	Exterior brick - Non-AHERA
117	Exterior brick mortar - Non-AHERA
12	9" x 9" Black Floor Tile w/ Green & White Streaks
121	1' x 2' Black Floor Tile Mastic
124	Blue/red/beige carpet mastic
125	12" x 12" White Floor Tile w/Black & Orange Streaks
126	12" x 12" White Floor Tile w/Black & Orange Streaks Mastic
127	2" Black baseboard
128	2" Black baseboard mastic
129	Purple carpet mastic
130	Insulation Inside of Vault Door
131	12" x 12" White Floor Tile w/Gray Streaks
132	12" x 12" White Floor Tile w/Gray Streaks Mastic
133	White Linoleum w/Gray & Blue Specks
134	White Linoleum w/Gray & Blue Specks Mastic
135	2' x 4' Lay-In Ceiling Panels
136	9" x 9" Black Floor Tile Mastic
137	9" x 9" Dark Green Floor Tile Mastic
138	Roofing material - Non-AHERA
139	Roof flashing - Non-AHERA
140	12" x 12" White w/Brown Streaks Floor Tile
141	12" x 12" White w/Brown Streaks Floor Tile Mastic
142	Window caulk
143	Green carpet adhesive
144	12" x 12" White w/Blue Streaks Floor Tile
145	12" x 12" White w/Blue Streaks Floor Tile Mastic
146	9" x 9" Light Tan Floor Tile Patching
147	9" x 9" Light Tan Floor Tile Patching Mastic
148	12" x 12" Black Floor Tile
149	12" x 12" Brown Floor Tile
149M	12" x 12" Black & Brown Floor Tile Mastic

150	White Ceramic Flooring and Grout
151	White ceramic tile mastic
152	White & Blue Ceramic Floor Tile and Grout
153	White blue ceramic tile mastic
154	Brown ceramic floor & grout
155	Brown ceramic tile mastic
156	Brown, gold, blue carpet mastic
157	12" x 12" Beige w/ Color Floor Tile
158	Mastic Associated w/ 12" x 12" Beige w/ Color Floor Tile
159	12" x 12" Coffee w/ Cream Floor Tile
16	White/green/red/gold linoleum
160	Mastic Associated w/ 12" x 12" Coffee w/ Cream Floor Tile
161	12" x 12" Cream and Coffee Floor Tile
162	Mastic Associated w/ 12" x 12" Cream and Coffee Floor Tile
163	Linoleum
164	Mastic Associated w/ Linoleum
165	12" x 12" Beige and Coffee Floor Tile
166	Mastic Associated w/ 12" x 12" Beige and Coffee Floor Tile
167	Tongue and groove wooden floor
168	12" x 12" White w/ brown specks Floor Tile
169	Mastic Associated w/ 12" x 12" White w/ brown specks Floor Tile
17	12" x 12" Charcoal Floor Tile w/White Speckles
170	Mastic associated with 12" x 12" Dark Brown w/ light brown Streaks Floor tiles
171	12" x 12" Dark Brown w/ light brown Streaks Floor tiles
172	Gray with light gray streaks Linoleum
21	Brown cementitious floor sheeting
22	12" x 12" White Floor Tile w/Tan Speckles
24	12" x 12" Tan w/White & Brown Streaks Floor Tile
3	12" x 12" Tan Floor Tile w/ White & Brown Streaks
36	Transite desk tops (black)
4	9" x 9" Black Floor Tile
5	9" x 9" Dark Green Floor Tile
58	Gold/white terrazzo
59	Gray/white terrazzo
60	Fireplace brick
61	Fireplace brick mortar
66	9" x 9" Black (w/White Streaks) Floor Tile Mastic
68	9" x 9" Bright Green w/White Floor Tile Mastic
69	9" x 9" Green Floor Tile Mastic
7	12" x 12" Gray Floor Tile w/ Brown & White Streaks

71	12" x 12" Gray Floor Tile
76	12" x 12" White Floor Tile w/ Black Spots
77	12" x 12" White Floor Tile w/ Black Spots Mastic
82	White/green/red/gold linoleum adhesive
90	12" x 12" Brown Floor Tile w/ Dark Brown & White Streaks
FT-001	9" x 9" Orange Floor Tile
FT-002	12" x 12" White Floor Tile
FTM-001	9" x 9" Orange Floor Tile Mastic
FTM-002	12" x 12" White Floor Tile Mastic

The following areas were deemed to be inaccessible:

105	Gasket material inside door (fire door gaskets)
109	Insulation inside fire doors
130	Insulation Inside of Vault Door
149	12" x 12" Brown Floor Tile
149M	12" x 12" Black & Brown Floor Tile Mastic
151	White ceramic tile mastic
153	White blue ceramic tile mastic
155	Brown ceramic tile mastic
158	Mastic Associated w/ 12" x 12" Beige w/ Color Floor Tile
160	Mastic Associated w/ 12" x 12" Coffee w/ Cream Floor Tile
162	Mastic Associated w/ 12" x 12" Cream and Coffee Floor Tile
164	Mastic Associated w/ Linoleum
166	Mastic Associated w/ 12" x 12" Beige and Coffee Floor Tile
28	2' x 2' Acoustical Ceiling Tile

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Ron Brock, IDPH License # 100-07134. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Al Raby High School Building 7690 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Al Raby High School Unit 46471 Building ID 7690

Address 3545 West Fulton Avenue Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
124	Blue/red/beige carpet mastic	3,328	SF	Library	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
125	12" x 12" White Floor Tile w/Black & Orange Streaks	4,500	SF	Rooms 221, 225, 226, and 308, 310, 322, 220, 216, 114 (patches)	ASSUMED	MISC	N	LOC	18	SF	No	ACBM with the potential for damage	3	LOW
126	12" x 12" White Floor Tile w/Black & Orange Streaks Mastic		SF	Rooms 221, 225, 226, and 308, 310, 322, 220, 216, 114 (patches).	ASSUMED	MISC				SF				
127	2" Black baseboard	800	LF	Rooms 221, 225, 418, and 420	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
128	2" Black baseboard mastic	800	LF	Rooms 221, 225, 418, and 420	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
129	Purple carpet mastic			328 (Door Reads 324)	ASSUMED	MISC								
13	9" x 9" Bright Green Floor Tile w/White Streaks			Library - ABATED	ABATED	MISC								
130	Insulation Inside of Vault Door	32	SF	Room 411	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
131	12" x 12" White Floor Tile w/Gray Streaks	3,300	SF	Rooms 409, 418, 420, 426, 414, 411, 312 (patches)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
132	12" x 12" White Floor Tile w/Gray Streaks Mastic	3,300	SF	Rooms 409, 418, 420, 426, 414, 411, 312 (patches)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
133	White Linoleum w/Gray & Blue Specks		SF	Room 414	ASSUMED	MISC				SF				
134	White Linoleum w/Gray & Blue Specks Mastic		SF	Room 414	ASSUMED	MISC				SF				
135	2' x 4' Lay-In Ceiling Panels	1,440	SF	Room 414	ASSUMED	MISC	Y	NONE	0	SF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
136	9" x 9" Black Floor Tile Mastic	2,800	SF	2nd, 3rd & 4th Floor Corridors (not observed 2nd or 3rd)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
137	9" x 9" Dark Green Floor Tile Mastic	2,800	SF	2nd, 3rd & 4th Floor Corridors (not observed 2nd and 3rd)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
138	Roofing material - Non-AHERA			Roof Exterior	ASSUMED	MISC								
139	Roof flashing - Non-AHERA				ASSUMED	MISC								
14	9" x 9" Green Floor Tile w/White Streaks			Library and Room 122 - ABATED	ABATED	MISC								
140	12" x 12" White w/Brown Streaks Floor	750	SF	Rooms 102, 206,	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the		LOW

Chicago Public Schools

School Al Raby High School Unit 46471 Building ID 7690

Address 3545 West Fulton Avenue Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Tile			110, 110C, 114								potential for damage		
141	12" x 12" White w/Brown Streaks Floor Tile Mastic	700	SF	Rooms 102, 206, 110, 110C, 114	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
142	Window caulk	1,000	LF	Throughout Building	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
143	Green carpet adhesive			Library	ASSUMED	MISC								
144	12" x 12" White w/Blue Streaks Floor Tile	3,000	SF	Rooms 122, 209, 221, 326 409, the Library & the Basement Locker Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
145	12" x 12" White w/Blue Streaks Floor Tile Mastic	3,000	SF	Rooms 122, 209, 221, 326 409, the Library & the Basement Locker Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
146	9" x 9" Light Tan Floor Tile Patching	20	SF	Room 112	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
147	9" x 9" Light Tan Floor Tile Patching Mastic	20	SF	Room 112	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
148	12" x 12" Black Floor Tile	1,462	SF	2nd Floor Hallways	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
149	12" x 12" Brown Floor Tile	1,462	SF	2nd Floor Hallway	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
149M	12" x 12" Black & Brown Floor Tile Mastic	2,925	SF	2nd Floor Hallway	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
15	9" x 9" Bluish Green Floor Tile w/White Streaks			Library - ABATED	ABATED	MISC								
150	White Ceramic Flooring and Grout	200	SF	Engineer Office and Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
151	White ceramic tile mastic	200	SF	Engineer Office & Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
152	White & Blue Ceramic Floor Tile and Grout	400	SF	1st Floor SE Boys Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
153	White blue ceramic tile mastic	400	SF	1st Floor SE Boys Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
154	Brown ceramic floor & grout	2,500	SF	3, 4, Boys and Girls Bathroom & 2nd Floor Girls Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
155	Brown ceramic tile mastic	2,500	SF	3, 4, Floor Boys & Girls Bathroom and 2 Floor Girls Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Al Raby High School Unit 46471 Building ID 7690

Address 3545 West Fulton Avenue Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
156	Brown, gold, blue carpet mastic			Teachers Lunchroom, 222 library,	ASSUMED	MISC								
157	12" x 12" Beige w/ Color Floor Tile	425	SF	Room 308	ASSUMED	MISC	N	LOC	8	SF	Yes	Any remaining friable ACBM or friable suspect ACBM	5	LOW
158	Mastic Associated w/ 12" x 12" Beige w/ Color Floor Tile	425	SF	Room 308	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
159	12" x 12" Coffee w/ Cream Floor Tile	500	SF	Room 330	ASSUMED	MISC	N	LOC	500	SF	Yes	Any remaining friable ACBM or friable suspect ACBM	5	LOW
16	White/green/red/gold linoleum			Rooms 215 and 221	ASSUMED	MISC								
160	Mastic Associated w/ 12" x 12" Coffee w/ Cream Floor Tile	500	SF	Room 330	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
161	12" x 12" Cream and Coffee Floor Tile	800	SF	Rooms 120-122	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
162	Mastic Associated w/ 12" x 12" Cream and Coffee Floor Tile	800	SF	Rooms 120-122	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
163	Linoleum	800	SF	Rooms 324-326	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
164	Mastic Associated w/ Linoleum	800	SF	Rooms 324-326	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
165	12" x 12" Beige and Coffee Floor Tile	900	SF	Room 420, 422B (patches), 426, 425, 406A, 406, 322, 225, 220, 216, 102	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
166	Mastic Associated w/ 12" x 12" Beige and Coffee Floor Tile	900	SF	Room 420, 422B (patches), 426, 425, 406A, 406, 322, 225, 220, 216, 102	ASSUMED	MISC	N	LOC	14	SF	Yes	ACBM with the potential for damage	3	LOW
167	Tongue and groove wooden floor			Room 424, 410, 408, 306, 309, 311, 313, 314, 315, 318, 321, 325, 327, 215, 214, 211/211A, 210, gymnasium, auditorium stage.	ASSUMED	MISC								
168	12" x 12" White w/ brown specks Floor Tile	600	SF	425, 426, 120	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
169	Mastic Associated w/ 12" x 12" White w/ brown specks Floor Tile	600	SF	425, 426, 120	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
17	12" x 12" Charcoal Floor Tile w/White Speckles			Room 225 (not observed)	ASSUMED	MISC								
170	Mastic associated with 12" x 12" Dark	600	SF	Rooms 414, 416	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the		LOW

Chicago Public Schools

School Al Raby High School Unit 46471 Building ID 7690

Address 3545 West Fulton Avenue Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Serving Room										
32	Ceiling plaster			Throughout Facility	NO_ACBM	SURFACE								
33	Plaster walls			Throughout Facility	NO_ACBM	SURFACE								
34	Stucco plaster			Assembly Hall and Balcony	NO_ACBM	SURFACE								
35	Lab hoods			Rooms 411, 414, 421, 422, and 422A	NO_ACBM	MISC								
36	Transite desk tops (black)	600	SF	Rooms 411, 415 (not observed 411)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
37	Black transite counter tops	1,000	SF	Rooms 411, 414, 415, 421 (not observed 411)	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
38	Green transite desk tops			Rooms 411, 414, 421 (not observed 411)	NO_ACBM	MISC								
39	Aircell pipe insulation			Possibly in Pipe Chases	CHR	TSI								
4	9" x 9" Black Floor Tile	4,500	SF	2nd, 3rd & 4th Floor Corridors (not observed)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
40	Aircell pipe insulation joints			Possibly in Pipe Chases	CHR	TSI								
41	Paperwrap on Insulation			Room 322	CHR	TSI								
49	Insulation Beneath Shell of Incinerator			Boiler Room	NO_ACBM	TSI								
5	9" x 9" Dark Green Floor Tile	4,500	SF	2nd, 3rd & 4th Floor Corridors (not observed 2nd and 3rd)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
52	Vibration Absorbers on Ducts			Throughout Facility	NO_ACBM	TSI								
53	Brown floor sheeting	200	SF	Auditorium	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
54	Floor tile mastic	4,900	SF	1st Floor Corridor, Rooms 104, 226, 324, 414, 422, and Offices	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
54 A	12" x 12" Tan Floor Tile w/White & Brown Streaks Mastic	4,800	SF	324, 422 & Storage, 310 (patches)	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
54 B	12" x 12" White Floor Tile Mastic	800	SF	1st Floor Corridor	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
54 C	12" x 12" Tan Floor Tile w/ White & Brown Streaks Mastic	750	SF	104	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
54 D	12" x 12" Gray Floor Tile w/Brown & White Streaks Mastic	4,500	SF	1st Floor Corridor, 2 Offices Across From 118, Main Office,	CHR	MISC	N	LOC	4	SF	No	ACBM with the potential for damage	3	LOW

Chicago Public Schools

School Al Raby High School Unit 46471 Building ID 7690

Address 3545 West Fulton Avenue Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 12/15/2022
Inspector Name Ron Brock
100-07134 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
100	
101	
102	
103	
104	Not observed in Room 104, 413 - Now concrete floor 9' x 9' tiles not Observed in Room 226, 411- 2023 Damage in Room between 411 & 415, 106
105	
106	Not observed 2022
107	
108	
109	
11	Not observed 2022
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	Not observed 2022

Chicago Public Schools

School Al Raby High School Unit 46471 Building ID 7690

Address 3545 West Fulton Avenue Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
12	Not observed 2022
120	
121	Not observed 2022
124	
125	Not observed in Room 226, damage in rooms 310, 225
126	Not observed 2022
127	
128	
129	Not observed 2022
13	
130	
131	Not observed in Room 418 - 2022
132	Not observed in Room 418 - 2022
133	Not observed 2022
134	Not observed 2022
135	
136	Not observed on 2nd and 3rd floor
137	
138	
139	
14	
140	
141	
142	
143	Not observed 2022
144	Not observed in Rooms 326, 209, and 122
145	Not observed in Rooms 326, 209, and 122
146	
147	

Chicago Public Schools

School Al Raby High School Unit 46471 Building ID 7690

Address 3545 West Fulton Avenue Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
148	
149	
149M	
15	
150	
151	
152	
153	
154	
155	
156	Not observed 2022
157	Damage in Room 308
158	
159	Damage in Room 330 cracked and buckling
16	Not observed 2022
160	
161	
162	
163	
164	
165	
166	Damage observed in 406
167	Not observed 2022
168	
169	
17	Not observed 2022
170	
171	
172	

Chicago Public Schools

School Al Raby High School Unit 46471 Building ID 7690

Address 3545 West Fulton Avenue Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
18	
19	Not observed 2022
2	Not observed in Room 414
20	
21	
22	
23	
24	
25	Damage in Assembly Hall
26	Not observed 2022
27	
28	
29	
3	Not observed in Rooms 324, 326, and 330
30	
31	
32	
33	Damage in 425 with peeling paint observed in room 415 storage, 314, 313, 315
34	
35	
36	
37	
38	
39	Not observed 2022
4	Not observed on 2nd and 3rd floors
40	Not observed 2022
41	Not observed 2022
49	
5	Not observed on 2nd and 3rd floors - same 2019, 2022

Chicago Public Schools

School Al Raby High School Unit 46471 Building ID 7690

Address 3545 West Fulton Avenue Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
52	
53	
54	
54 A	Not observed in Room 324
54 B	
54 C	
54 D	Damage in room 118
55	
56	
57	
58	
59	
6	Not observed 2022
60	
61	
62	
63	Damage located in the assembly hall and 1st floor storage
64	Damage in basement
65	
66	Not observed 2022
67	
68	Not observed 2022
69	Not observed 2022
7	
70	
71	Not observed in Room 110
72	
73	Not observed 2022
74	Not observed 2022

Chicago Public Schools

School Al Raby High School Unit 46471 Building ID 7690

Address 3545 West Fulton Avenue Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
75	Not observed in Room 308
76	
77	Not observed 2022
78	Not observed 2022
79	Not observed 2022
8	Damage located in the boiler room and room 106
80	
81	
82	Not observed 2022
83	
84	
85	
86	
87	
88	
89	
9	Damage in 112
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
FT-001	
FT-002	Not observed 2022

Chicago Public Schools

School Al Raby High School **Unit** 46471 **Building ID** 7690

Address 3545 West Fulton Avenue **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
FTM-001	
FTM-002	Not observed 2022

Table II

Management Planner's Review

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	9" x 9" Brown Floor Tile - Abated				Abated	MISC					
10	9" x 9" Black Floor Tile w/White Streaks - Abated			Womens' 1st Floor Bathroom	Abated	MISC					
100	Marker boards (chalk boards)			Throughout Facility	No ACBM	MISC					
101	Bulletin boards (poster board)			Throughout Facility	No ACBM	MISC					
102	12" x 5" Glazed (Finished) Brick Mortar			Girls and Boys Bathrooms and Lunchroom	No ACBM	MISC					
103	Window caulk			West Side of Building (406, 420, 226, Library)	No ACBM	MISC					
104	9" x 9" Beige Floor Tile w/White & Brown Streaks Mastic	2,900	SF	Offices, 226, 411, 415, 416, and Room Between 411 & 415, 106	Chrysotile	MISC	No	10	SF	6 ACBM with the potential for damage	Remove
105	Gasket material inside door (fire door gaskets)	10	SF	Auditorium Doors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	Carpet mastic			Room 122	Assumed	MISC					Follow O&M Plan
107	Carpet mastic (green) - removed			Room 218	Assumed	MISC					Follow O&M Plan
108	1" Square white ceramic (tile grout)	300	SF	Locker Rooms and Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	Insulation inside firedoors	70	SF	Entrances and Exits	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	9" x 9" Dark Green Floor Tile w/White Streaks			Rooms 102, 118 (not observed 102)	Chrysotile	MISC					Follow O&M Plan
110	Roofing material - Non-AHERA			Main Roof	Assumed	MISC					Follow O&M Plan
111	Roof flashing - Non-AHERA			Main Roof	Chrysotile	MISC					Follow O&M Plan
112	Roofing material - Non-AHERA			2nd Floor Roof	Assumed	MISC					Follow O&M Plan
113	Roof flashing - Non-AHERA			2nd Floor Roof	Assumed	MISC					Follow O&M Plan
114	Roofing material - Non-AHERA			Gym Roof	Assumed	MISC					Follow O&M Plan
115	Roofing material - Non-AHERA			Auditorium Roof	Assumed	MISC					Follow O&M Plan
116	Exterior brick - Non-AHERA			Entire	Assumed	MISC					Follow O&M Plan
117	Exterior brick mortar - Non-AHERA			Building Exterior	Assumed	MISC					Follow O&M Plan
118	Exterior window grout - Non-AHERA			Exterior of Building	Chrysotile	MISC					Follow O&M Plan
119	9" x 9" Dark Green Floor Tile w/ White Streaks Mastic			Rooms 102, 118 & 326 (not observed 326, 102)	Chrysotile	MISC					Follow O&M Plan
12	9" x 9" Black Floor Tile w/ Green & White Streaks			Library (not observed)	Assumed	MISC					Follow O&M Plan
120	9" x 9" Bluish Green Floor Tile w/White Streaks Mastic			Library - ABATED	Abated	MISC					
121	1' x 2' Black Floor Tile Mastic			Teacher's Lunchroom	Assumed	MISC					Follow O&M Plan
124	Blue/red/beige carpet mastic	3,328	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125	12" x 12" White Floor Tile w/Black & Orange Streaks	4,500	SF	Rooms 221, 225, 226, and 308, 310, 322, 220, 216, 114 (patches)	Assumed	MISC	No	18	SF	6 ACBM with the potential for damage	Repair
126	12" x 12" White Floor Tile w/Black & Orange		SF	Rooms 221, 225, 226, and 308, 310,	Assumed	MISC			SF		Follow O&M Plan

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Streaks Mastic			322, 220, 216, 114 (patches),							
127	2" Black baseboard	800	LF	Rooms 221, 225, 418, and 420	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
128	2" Black baseboard mastic	800	LF	Rooms 221, 225, 418, and 420	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
129	Purple carpet mastic			328 (Door Reads 324)	Assumed	MISC					Follow O&M Plan
13	9" x 9" Bright Green Floor Tile w/White Streaks			Library - ABATED	Abated	MISC					
130	Insulation Inside of Vault Door	32	SF	Room 411	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131	12" x 12" White Floor Tile w/Gray Streaks	3,300	SF	Rooms 409, 418, 420, 426, 414, 411, 312 (patches)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132	12" x 12" White Floor Tile w/Gray Streaks Mastic	3,300	SF	Rooms 409, 418, 420, 426, 414, 411, 312 (patches)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
133	White Linoleum w/Gray & Blue Specks		SF	Room 414	Assumed	MISC			SF		Follow O&M Plan
134	White Linoleum w/Gray & Blue Specks Mastic		SF	Room 414	Assumed	MISC			SF		Follow O&M Plan
135	2' x 4' Lay-In Ceiling Panels	1,440	SF	Room 414	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
136	9" x 9" Black Floor Tile Mastic	2,800	SF	2nd, 3rd & 4th Floor Corridors (not observed 2nd or 3rd)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	9" x 9" Dark Green Floor Tile Mastic	2,800	SF	2nd, 3rd & 4th Floor Corridors (not observed 2nd and 3rd)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	Roofing material - Non-AHERA			Roof Exterior	Assumed	MISC					Follow O&M Plan
139	Roof flashing - Non-AHERA				Assumed	MISC					Follow O&M Plan
14	9" x 9" Green Floor Tile w/White Streaks			Library and Room 122 - ABATED	Abated	MISC					
140	12" x 12" White w/Brown Streaks Floor Tile	750	SF	Rooms 102, 206, 110, 110C, 114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
141	12" x 12" White w/Brown Streaks Floor Tile Mastic	700	SF	Rooms 102, 206, 110, 110C, 114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142	Window caulk	1,000	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
143	Green carpet adhesive			Library	Assumed	MISC					Follow O&M Plan
144	12" x 12" White w/Blue Streaks Floor Tile	3,000	SF	Rooms 122, 209, 221, 326 409, the Library & the Basement Locker Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	12" x 12" White w/Blue Streaks Floor Tile Mastic	3,000	SF	Rooms 122, 209, 221, 326 409, the Library & the Basement Locker Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
146	9" x 9" Light Tan Floor Tile Patching	20	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
147	9" x 9" Light Tan Floor Tile Patching Mastic	20	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148	12" x 12" Black Floor Tile	1,462	SF	2nd Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149	12" x 12" Brown Floor Tile	1,462	SF	2nd Floor Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149M	12" x 12" Black & Brown Floor Tile Mastic	2,925	SF	2nd Floor Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	9" x 9" Bluish Green Floor Tile w/White Streaks			Library - ABATED	Abated	MISC					

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
150	White Ceramic Flooring and Grout	200	SF	Engineer Office and Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151	White ceramic tile mastic	200	SF	Engineer Office & Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152	White & Blue Ceramic Floor Tile and Grout	400	SF	1st Floor SE Boys Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153	White blue ceramic tile mastic	400	SF	1st Floor SE Boys Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
154	Brown ceramic floor & grout	2,500	SF	3, 4, Boys and Girls Bathroom & 2nd Floor Girls Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155	Brown ceramic tile mastic	2,500	SF	3, 4, Floor Boys & Girls Bathroom and 2 Floor Girls Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
156	Brown, gold, blue carpet mastic			Teachers Lunchroom, 222 library,	Assumed	MISC					Follow O&M Plan
157	12" x 12" Beige w/ Color Floor Tile	425	SF	Room 308	Assumed	MISC	No	8	SF	7 Any remaining friable ACBM or friable suspect ACBM	Repair
158	Mastic Associated w/ 12" x 12" Beige w/ Color Floor Tile	425	SF	Room 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159	12" x 12" Coffee w/ Cream Floor Tile	500	SF	Room 330	Assumed	MISC	No	500	SF	7 Any remaining friable ACBM or friable suspect ACBM	Repair
16	White/green/red/gold linoleum			Rooms 215 and 221	Assumed	MISC					Follow O&M Plan
160	Mastic Associated w/ 12" x 12" Coffee w/ Cream Floor Tile	500	SF	Room 330	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
161	12" x 12" Cream and Coffee Floor Tile	800	SF	Rooms 120-122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
162	Mastic Associated w/ 12" x 12" Cream and Coffee Floor Tile	800	SF	Rooms 120-122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
163	Linoleum	800	SF	Rooms 324-326	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
164	Mastic Associated w/ Linoleum	800	SF	Rooms 324-326	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
165	12" x 12" Beige and Coffee Floor Tile	900	SF	Room 420, 422B (patches), 426, 425, 406A, 406, 322, 225, 220, 216, 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
166	Mastic Associated w/ 12" x 12" Beige and Coffee Floor Tile	900	SF	Room 420, 422B (patches), 426, 425, 406A, 406, 322, 225, 220, 216, 102	Assumed	MISC	No	14	SF	6 ACBM with the potential for damage	Repair
167	Tongue and groove wooden floor			Room 424, 410, 408, 306, 309, 311, 313, 314, 315, 318, 321, 325, 327, 215, 214, 211/211A, 210, gymnasium, auditorium stage.	Assumed	MISC					Follow O&M Plan
168	12" x 12" White w/ brown specks Floor Tile	600	SF	425, 426, 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
169	Mastic Associated w/ 12" x 12" White w/ brown specks Floor Tile	600	SF	425, 426, 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12" x 12" Charcoal Floor Tile w/White Speckles			Room 225 (not observed)	Assumed	MISC					Follow O&M Plan
170	Mastic associated with 12" x 12" Dark Brown w/	600	SF	Rooms 414, 416 (patches), 411, 312	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
 Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	light brown Streaks Floor tiles			(patches)							
171	12" x 12" Dark Brown w/ light brown Streaks Floor tiles	600	SF	Room 414, 416 (patches), 411, 312 (patches)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
172	Gray with light gray streaks Linoleum	600	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12" x 12" Beige w/White Floor Tile	1,495	SF	Room 212, 209	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	9" x 9" Gray Floor Tile w/White Streaks			Matrons Room & Room 208	Chrysotile	MISC					Follow O&M Plan
2	9" x 9" Beige Floor Tile w/White and Brown Streaks	2,630	SF	Rooms 411, 414, 415, 416, 413, and 421 (not observed 414)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Dark green linoleum			Gym Office and 206	No ACBM	MISC					
21	Brown cementitious floor sheeting	200	SF	Balcony and Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" White Floor Tile w/Tan Speckles	4,500	SF	1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	9" x 9" Dark Orange Floor Tile	675	SF	Engineer's Office & Bathroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12" x 12" Tan w/White & Brown Streaks Floor Tile	380	SF	Room 104 (no access)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	9" x 9" Dark Brown Floor Tile w/White and Brown Streaks	1,600	SF	Assembly Hall	Chrysotile	MISC	No	20	SF	6 ACBM with the potential for damage	Remove
26	1' x 2' Black Floor Tile			Teacher's Lunchroom (not observed)	Chrysotile	MISC					Follow O&M Plan
27	1' x 1' White Wormed Ceiling Tile			Lunch Room, Serving Room and 218	No ACBM	MISC					
28	2' x 2' Acoustical Ceiling Tile	500	SF	Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	White pegboard ceiling tile			Dishwashing Room	No ACBM	MISC					
3	12" x 12" Tan Floor Tile w/ White & Brown Streaks	4,800	SF	Rooms 324, 422 & Storage, 326/330, 320, 208, 218 (not observed), 310 (patches)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	1' x 1' White Gouged Ceiling Tile			Lunch Room & Serving Room (not observed)	No ACBM	MISC					
31	1' x 1' White Ceiling Tile			Room 122 & Serving Room	No ACBM	MISC					
32	Ceiling plaster			Throughout Facility	No ACBM	SURFACE					
33	Plaster walls			Throughout Facility	No ACBM	SURFACE					
34	Stucco plaster			Assembly Hall and Balcony	No ACBM	SURFACE					
35	Lab hoods			Rooms 411, 414, 421, 422, and 422A	No ACBM	MISC					
36	Transite desk tops (black)	600	SF	Rooms 411, 415 (not observed 411)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Black transite counter tops	1,000	SF	Rooms 411, 414, 415, 421 (not observed 411)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Green transite desk tops			Rooms 411, 414, 421 (not observed 411)	No ACBM	MISC					
39	Aircell pipe insulation			Possibly in Pipe Chases	Chrysotile	TSI					Follow O&M Plan

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
 Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
4	9" x 9" Black Floor Tile	4,500	SF	2nd, 3rd & 4th Floor Corridors (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Aircell pipe insulation joints			Possibly in Pipe Chases	Chrysotile	TSI					Follow O&M Plan
41	Paperwrap on Insulation			Room 322	Chrysotile	TSI					Follow O&M Plan
49	Insulation Beneath Shell of Incinerator			Boiler Room	No ACBM	TSI					
5	9" x 9" Dark Green Floor Tile	4,500	SF	2nd, 3rd & 4th Floor Corridors (not observed 2nd and 3rd)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Vibration Absorbers on Ducts			Throughout Facility	No ACBM	TSI					
53	Brown floor sheeting	200	SF	Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Floor tile mastic	4,900	SF	1st Floor Corridor, Rooms 104, 226, 324, 414, 422, and Offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54 A	12" x 12" Tan Floor Tile w/White & Brown Streaks Mastic	4,800	SF	324, 422 & Storage, 310 (patches)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54 B	12" x 12" White Floor Tile Mastic	800	SF	1st Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54 C	12" x 12" Tan Floor Tile w/ White & Brown Streaks Mastic	750	SF	104	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54 D	12" x 12" Gray Floor Tile w/Brown & White Streaks Mastic	4,500	SF	1st Floor Corridor, 2 Offices Across From 118, Main Office, 226,	Chrysotile	MISC	No	4	SF	6 ACBM with the potential for damage	Remove
55	White/orange/green/brown terrazzo			Hallways, Stairwells, Stairs, Kitchen, Lunchroom Complex	No ACBM	MISC					
56	Gray terrazzo stall panels			Bathrooms and Locker Rooms	No ACBM	MISC					
57	Gray/black/white terrazzo			Foyer	No ACBM	MISC					
58	Gold/white terrazzo	240	SF	Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Gray/white terrazzo	240	SF	Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	9" x 9" White Floor Tile w/ Brown and Orange Streaks			Nurse's Room	Chrysotile	MISC					Follow O&M Plan
60	Fireplace brick	200	SF	Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Fireplace brick mortar	200	SF	Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Gray wall tile caulk			Girl's & Boy's Bathrooms, Library, Locker Rooms 106, 318, 406, 408, 410	No ACBM	MISC					
63	9" x 9" Dark Brown Floor Tile w/White & Brown Streaks Mastic	2,000	SF	Assembly Hall	Chrysotile	MISC	No	500	SF	6 ACBM with the potential for damage	Repair
64	9" x 9" Orange Speckled Floor Tile Mastic	2,400	SF	Room 106, 108 & Basement Locker Room	Chrysotile	MISC	No	260	SF	6 ACBM with the potential for damage	Repair
65	12" x 12" Beige w/White Floor Tile Mastic	1,450	SF	Room 212, 209	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	9" x 9" Black (w/White Streaks) Floor Tile Mastic			Women's 1st Floor Bathroom	Assumed	MISC					Follow O&M Plan

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
67	6 Sided ceramic tile grout			Bathrooms and Locker Rooms	No ACBM	MISC					
68	9" x 9" Bright Green w/White Floor Tile Mastic			Library	Assumed	MISC					Follow O&M Plan
69	9" x 9" Green Floor Tile Mastic			Library and Room 122 (not observed)	Assumed	MISC					Follow O&M Plan
7	12" x 12" Gray Floor Tile w/ Brown & White Streaks	1,000	SF	1st Floor Corridor, 2 Offices Across From 118, Main Office, 226,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Gray wall tile caulk			Girls & Boys Bathrooms, 106, 406, 408, 410, Locker Room	No ACBM	MISC					
71	12" x 12" Gray Floor Tile	860	SF	Locker Room, Rooms 104, 110, 414, 411	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12" x 12" Gray Floor Tile Mastic			Locker Room, Rooms 104, 110, 414, 411	No ACBM	MISC					
73	9" x 9" Green, Brown, and Tan Floor Tile			Room 104 (Under 12" x 12" Floor Tiles)	Chrysotile	MISC					Follow O&M Plan
74	9" x 9" Green, Brown, and Tan Floor Tile Mastic			Room 104 (Under 12" x 12" Floor Tiles)	Chrysotile	MISC					Follow O&M Plan
75	9" x 9" Brown w/White & Dark Brown Streaks Floor Tile Mastic	2,100	SF	Rooms 112, 308 & 312 (not observed 308)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12" x 12" White Floor Tile w/ Black Spots	1,200	SF	Room 122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	12" x 12" White Floor Tile w/ Black Spots Mastic			Room 122 (not observed)	Assumed	MISC					Follow O&M Plan
78	9" x 9" Brown w/White and Black Floor Tile			Room 322 (not observed)	Chrysotile	MISC					Follow O&M Plan
79	9" x 9" Brown w/Black and White Floor Tile Mastic			Room 322 (not observed)	Chrysotile	MISC					Follow O&M Plan
8	9" x 9" Orange Speckled Floor Tile	1,600	SF	Rooms 106, 108 & Basement Locker Room	Chrysotile	MISC	No	200	SF	6 ACBM with the potential for damage	Repair
80	Gray baseboard (cove base)			Throughout Facility	No ACBM	MISC					
81	Gray baseboard mastic			Throughout Facility	No ACBM	MISC					
82	White/green/red/gold linoleum adhesive			Rooms 215 and 221 (not observed 215, 221)	Assumed	MISC					Follow O&M Plan
83	1/2" Ceramic tile grout	500	SF	Locker Room & Small Amounts in Boy's & Girl's Bathrooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Cinder block mortar			Throughout Facility	No ACBM	MISC					
85	2' x 4' Lay-In Ceiling Panels			Rooms 102, Library, 122 and 104, 106	No ACBM	MISC					
86	2' x4' Lay In Ceiling Panels w/ Specks			Room 122, 325, 327, 323, 325, 321, 318, 314	No ACBM	MISC					
87	2' x 4' Lay In Ceiling Panels			Lunchroom, Teacher's Lunchroom, Library, and Men's Bathroom	No ACBM	MISC					
88	Beige curtain			Stage	No ACBM	MISC					

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
 Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
89	Red curtain			Stage	No ACBM	MISC					
9	9" x 9" Brown w/ White & Dark Brown Streaks Floor Tile	1,700	SF	Rooms 112, and 312	Chrysotile	MISC	No	2	SF	6 ACBM with the potential for damage	Remove
90	12" x 12" Brown Floor Tile w/ Dark Brown & White Streaks	2,830	SF	Rooms 406, 411, 425, and 426	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	12" x 12" Brown Floor Tile w/Dark Brown & White Streaks Mastic			Rooms 406, 411, 425, and 426	No ACBM	MISC					
92	Black baseboard (cove base)			Throughout Facility	No ACBM	MISC					
93	Black baseboard mastic			Throughout Facility	No ACBM	MISC					
94	Interior window caulk	1,000	LF	Throughout Facility	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
95	Window glazing			Throughout Facility	No ACBM	MISC					
96	Drywall			Basement and Room 108	No ACBM	MISC					
97	Glazed (finished) brick			Throughout Facility	No ACBM	MISC					
98	Glazed brick mortar			Throughout Facility	No ACBM	MISC					
99	Window glazing			West Wall of Building	No ACBM	MISC					
FT-001	9" x 9" Orange Floor Tile	700	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-002	12" x 12" White Floor Tile		SF	Rooms 122, 308	Assumed	MISC		8	SF		Follow O&M Plan
FTM-001	9" x 9" Orange Floor Tile Mastic	700	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-002	12" x 12" White Floor Tile Mastic			Rooms 122, 308	Assumed	MISC					Follow O&M Plan

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
 Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	12/27/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
11	
110	
111	
112	
113	
114	

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
115	
116	
117	
118	
119	
12	
120	
121	
124	
125	
126	
127	
128	
129	
13	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
14	
140	

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
 Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
141	
142	
143	
144	
145	
146	
147	
148	
149	
149M	
15	
150	
151	
152	
153	
154	
155	
156	
157	
158	
159	
16	
160	
161	
162	
163	
164	

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
165	
166	
167	
168	
169	
17	
170	
171	
172	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
 Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
34	
35	
36	
37	
38	
39	
4	
40	
41	
49	
5	
52	
53	
54	
54 A	
54 B	
54 C	
54 D	
55	
56	
57	
58	
59	
6	
60	
61	
62	

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
8	
80	
81	
82	
83	
84	
85	
86	
87	

Chicago Public Schools

School Al Raby High School
Address 3545 West Fulton Avenue

Unit 46471
 Chicago, IL, 60624

Building ID 7690
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
88	
89	
9	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
FT-001	
FT-002	
FTM-001	
FTM-002	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile - Abated**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/White Streaks - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Womens' 1st Floor Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/White Streaks - Abated**

MATERIAL LOCATION: **Womens' 1st Floor Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **Marker boards (chalk boards)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **Marker boards (chalk boards)**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Bulletin boards (poster board)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Bulletin boards (poster board)**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12" x 5" Glazed (Finished) Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girls and Boys Bathrooms and Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12" x 5" Glazed (Finished) Brick Mortar**
MATERIAL LOCATION: **Girls and Boys Bathrooms and Lunchroom**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Window caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Side of Building (406, 420, 226, Library)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Window caulk**
MATERIAL LOCATION: **West Side of Building (406, 420, 226, Library)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/White & Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Offices, 226, 411, 415, 416, and Room Between 411 & 415, 106**
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in Room 104, 413 - Now concrete floor 9' x 9' tiles not Observed in Room 226, 411- 2023 Damage in Room between 411 & 415, 106**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/White & Brown Streaks Mastic**
MATERIAL LOCATION: **Offices, 226, 411, 415, 416, and Room Between 411 & 415, 106**
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **Gasket material inside door (fire door gaskets)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium Doors**

MATERIAL QUANTITY: **10**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **Gasket material inside door (fire door gaskets)**
MATERIAL LOCATION: **Auditorium Doors**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 122**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Carpet mastic**
MATERIAL LOCATION: **Room 122**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Carpet mastic (green) - removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 218**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Carpet mastic (green) - removed**
MATERIAL LOCATION: **Room 218**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **1" Square white ceramic (tile grout)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Locker Rooms and Bathrooms**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **1" Square white ceramic (tile grout)**
MATERIAL LOCATION: **Locker Rooms and Bathrooms**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **Insulation inside firedoors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Entrances and Exits**

MATERIAL QUANTITY: **70**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **Insulation inside firedoors**
MATERIAL LOCATION: **Entrances and Exits**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 102, 118 (not observed 102)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile w/White Streaks**

MATERIAL LOCATION: **Rooms 102, 118 (not observed 102)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**
MATERIAL LOCATION: **Main Roof**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**

MATERIAL LOCATION: **Main Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**
MATERIAL LOCATION: **2nd Floor Roof**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**
MATERIAL LOCATION: **2nd Floor Roof**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**
MATERIAL LOCATION: **Gym Roof**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**
MATERIAL LOCATION: **Auditorium Roof**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Entire**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**
MATERIAL LOCATION: **Entire**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**
MATERIAL LOCATION: **Building Exterior**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **Exterior window grout - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **Exterior window grout - Non-AHERA**
MATERIAL LOCATION: **Exterior of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile w/ White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 102, 118 & 326 (not observed 326, 102)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile w/ White Streaks Mastic**
MATERIAL LOCATION: **Rooms 102, 118 & 326 (not observed 326, 102)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/ Green & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library (not observed)**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/ Green & White Streaks**

MATERIAL LOCATION: **Library (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **9" x 9" Bluish Green Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **9" x 9" Bluish Green Floor Tile w/White Streaks Mastic**
MATERIAL LOCATION: **Library - ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **1' x 2' Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher's Lunchroom**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **1' x 2' Black Floor Tile Mastic**

MATERIAL LOCATION: **Teacher's Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **Blue/red/beige carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **3328**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **Blue/red/beige carpet mastic**
MATERIAL LOCATION: **Library**
MATERIAL QUANTITY: **3328** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Black & Orange Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 221, 225, 226, and 308, 310, 322, 220, 216, 114 (patches)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in Room 226, damage in rooms 310, 225**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Black & Orange Streaks**
MATERIAL LOCATION: **Rooms 221, 225, 226, and 308, 310, 322, 220, 216, 114 (patches)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **18** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Black & Orange Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 221, 225, 226, and 308, 310, 322, 220, 216, 114 (patches),**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Black & Orange Streaks Mastic**
MATERIAL LOCATION: **Rooms 221, 225, 226, and 308, 310, 322, 220, 216, 114 (patches),**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **2" Black baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 221, 225, 418, and 420**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **2" Black baseboard**
MATERIAL LOCATION: **Rooms 221, 225, 418, and 420**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **2" Black baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 221, 225, 418, and 420**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **2" Black baseboard mastic**
MATERIAL LOCATION: **Rooms 221, 225, 418, and 420**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**
MATERIAL DESCRIPTION: **Purple carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **328 (Door Reads 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **129**
MATERIAL DESCRIPTION: **Purple carpet mastic**
MATERIAL LOCATION: **328 (Door Reads 324)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9" x 9" Bright Green Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9" x 9" Bright Green Floor Tile w/White Streaks**

MATERIAL LOCATION: **Library - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **Insulation Inside of Vault Door**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 411**
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **Insulation Inside of Vault Door**
MATERIAL LOCATION: **Room 411**
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 409, 418, 420, 426, 414, 411, 312 (patches)**

MATERIAL QUANTITY: **3300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 418 - 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks**
MATERIAL LOCATION: **Rooms 409, 418, 420, 426, 414, 411, 312 (patches)**
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 409, 418, 420, 426, 414, 411, 312 (patches)**

MATERIAL QUANTITY: **3300**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 418 - 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks Mastic**
MATERIAL LOCATION: **Rooms 409, 418, 420, 426, 414, 411, 312 (patches)**
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **White Linoleum w/Gray & Blue Specks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 414**

MATERIAL QUANTITY:


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **White Linoleum w/Gray & Blue Specks**
MATERIAL LOCATION: **Room 414**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **White Linoleum w/Gray & Blue Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 414**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **White Linoleum w/Gray & Blue Specks Mastic**
MATERIAL LOCATION: **Room 414**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **2' x 4' Lay-In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 414**
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **2' x 4' Lay-In Ceiling Panels**
MATERIAL LOCATION: **Room 414**
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd, 3rd & 4th Floor Corridors (not observed 2nd or 3rd)**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed on 2nd and 3rd floor**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile Mastic**
MATERIAL LOCATION: **2nd, 3rd & 4th Floor Corridors (not observed 2nd or 3rd)**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd, 3rd & 4th Floor Corridors (not observed 2nd and 3rd)**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile Mastic**
MATERIAL LOCATION: **2nd, 3rd & 4th Floor Corridors (not observed 2nd and 3rd)**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**
MATERIAL LOCATION: **Roof Exterior**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **139**

MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46471 BUIDLING ID: 7690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ron Brock
SCHOOL NAME: Al Raby High School INSPECTION DATE: 12/15/2022
ADDRESS: 3545 West Fulton Avenue IDPH LICENSE NO: 100-07134

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14
MATERIAL DESCRIPTION: 9" x 9" Green Floor Tile w/White Streaks
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Library and Room 122 - ABATED

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/White Streaks**

MATERIAL LOCATION: **Library and Room 122 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 102, 206, 110, 110C, 114**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 102, 206, 110, 110C, 114**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 102, 206, 110, 110C, 114**

MATERIAL QUANTITY: **700**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 102, 206, 110, 110C, 114**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **Window caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **Window caulk**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **Green carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **Green carpet adhesive**
MATERIAL LOCATION: **Library**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 122, 209, 221, 326 409, the Library & the Basement Locker Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rooms 326, 209, and 122**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 122, 209, 221, 326 409, the Library & the Basement Locker Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 122, 209, 221, 326 409, the Library & the Basement Locker Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in Rooms 326, 209, and 122**

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 122, 209, 221, 326 409, the Library & the Basement Locker Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **146**
MATERIAL DESCRIPTION: **9" x 9" Light Tan Floor Tile Patching**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **146**
MATERIAL DESCRIPTION: **9" x 9" Light Tan Floor Tile Patching**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147**
MATERIAL DESCRIPTION: **9" x 9" Light Tan Floor Tile Patching Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **20**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **147**
MATERIAL DESCRIPTION: **9" x 9" Light Tan Floor Tile Patching Mastic**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **148**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Hallways**
MATERIAL QUANTITY: **1462** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **148**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**
MATERIAL LOCATION: **2nd Floor Hallways**
MATERIAL QUANTITY: **1462** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Hallway**
MATERIAL QUANTITY: **1462** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **149**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
MATERIAL LOCATION: **2nd Floor Hallway**
MATERIAL QUANTITY: **1462** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149M**
MATERIAL DESCRIPTION: **12" x 12" Black & Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Hallway**
MATERIAL QUANTITY: **2925** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **149M**
MATERIAL DESCRIPTION: **12" x 12" Black & Brown Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Hallway**
MATERIAL QUANTITY: **2925** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46471 BUIDLING ID: 7690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ron Brock
SCHOOL NAME: Al Raby High School INSPECTION DATE: 12/15/2022
ADDRESS: 3545 West Fulton Avenue IDPH LICENSE NO: 100-07134

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15
MATERIAL DESCRIPTION: 9" x 9" Bluish Green Floor Tile w/White Streaks
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Library - ABATED

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9" x 9" Bluish Green Floor Tile w/White Streaks**

MATERIAL LOCATION: **Library - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **150**
MATERIAL DESCRIPTION: **White Ceramic Flooring and Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer Office and Bathroom**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **150**
MATERIAL DESCRIPTION: **White Ceramic Flooring and Grout**
MATERIAL LOCATION: **Engineer Office and Bathroom**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151**
MATERIAL DESCRIPTION: **White ceramic tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer Office & Bathroom**

MATERIAL QUANTITY: **200**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **151**
MATERIAL DESCRIPTION: **White ceramic tile mastic**
MATERIAL LOCATION: **Engineer Office & Bathroom**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152**
MATERIAL DESCRIPTION: **White & Blue Ceramic Floor Tile and Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor SE Boys Bathroom**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **152**
MATERIAL DESCRIPTION: **White & Blue Ceramic Floor Tile and Grout**
MATERIAL LOCATION: **1st Floor SE Boys Bathroom**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153**
MATERIAL DESCRIPTION: **White blue ceramic tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor SE Boys Bathrooms**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **153**
MATERIAL DESCRIPTION: **White blue ceramic tile mastic**
MATERIAL LOCATION: **1st Floor SE Boys Bathrooms**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **154**
MATERIAL DESCRIPTION: **Brown ceramic floor & grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3, 4, Boys and Girls Bathroom & 2nd Floor Girls Bathroom**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **154**
MATERIAL DESCRIPTION: **Brown ceramic floor & grout**
MATERIAL LOCATION: **3, 4, Boys and Girls Bathroom & 2nd Floor Girls Bathroom**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155**
MATERIAL DESCRIPTION: **Brown ceramic tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3, 4, Floor Boys & Girls Bathroom and 2 Floor Girls Bathroom**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **155**
MATERIAL DESCRIPTION: **Brown ceramic tile mastic**
MATERIAL LOCATION: **3, 4, Floor Boys & Girls Bathroom and 2 Floor Girls Bathroom**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **156**
MATERIAL DESCRIPTION: **Brown, gold, blue carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teachers Lunchroom, 222 library,**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **156**
MATERIAL DESCRIPTION: **Brown, gold, blue carpet mastic**
MATERIAL LOCATION: **Teachers Lunchroom, 222 library,**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **157**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Color Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 308**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 308**

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **157**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Color Floor Tile**
MATERIAL LOCATION: **Room 308**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **158**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige w/ Color Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 308**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **158**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige w/ Color Floor Tile**
MATERIAL LOCATION: **Room 308**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **159**
MATERIAL DESCRIPTION: **12" x 12" Coffee w/ Cream Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 330**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 330 cracked and buckling**

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **159**
MATERIAL DESCRIPTION: **12" x 12" Coffee w/ Cream Floor Tile**
MATERIAL LOCATION: **Room 330**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **White/green/red/gold linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 215 and 221**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **White/green/red/gold linoleum**

MATERIAL LOCATION: **Rooms 215 and 221**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **160**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Coffee w/ Cream Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 330**

MATERIAL QUANTITY: **500**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **160**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Coffee w/ Cream Floor Tile**
MATERIAL LOCATION: **Room 330**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **161**
MATERIAL DESCRIPTION: **12" x 12" Cream and Coffee Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 120-122**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **161**
MATERIAL DESCRIPTION: **12" x 12" Cream and Coffee Floor Tile**
MATERIAL LOCATION: **Rooms 120-122**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **162**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Cream and Coffee Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 120-122**

MATERIAL QUANTITY: **800**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **162**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Cream and Coffee Floor Tile**
MATERIAL LOCATION: **Rooms 120-122**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **163**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 324-326**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **163**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **Rooms 324-326**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **164**
MATERIAL DESCRIPTION: **Mastic Associated w/ Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 324-326**

MATERIAL QUANTITY: **800**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **164**
MATERIAL DESCRIPTION: **Mastic Associated w/ Linoleum**
MATERIAL LOCATION: **Rooms 324-326**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165**
MATERIAL DESCRIPTION: **12" x 12" Beige and Coffee Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 420, 422B (patches), 426, 425, 406A, 406, 322, 225, 220, 216, 102**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **900** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **165**
MATERIAL DESCRIPTION: **12" x 12" Beige and Coffee Floor Tile**
MATERIAL LOCATION: **Room 420, 422B (patches), 426, 425, 406A, 406, 322, 225, 220, 216, 102**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige and Coffee Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 420, 422B (patches), 426, 425, 406A, 406, 322, 225, 220, 216, 102**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage observed in 406**

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **166**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige and Coffee Floor Tile**
MATERIAL LOCATION: **Room 420, 422B (patches), 426, 425, 406A, 406, 322, 225, 220, 216, 102**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **14** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12" x 12" Charcoal Floor Tile w/White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 225 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12" x 12" Charcoal Floor Tile w/White Speckles**

MATERIAL LOCATION: **Room 225 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 212, 209**
MATERIAL QUANTITY: **1495** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Floor Tile**
MATERIAL LOCATION: **Room 212, 209**
MATERIAL QUANTITY: **1495** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Matrons Room & Room 208**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/White Streaks**
MATERIAL LOCATION: **Matrons Room & Room 208**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/White and Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 411, 414, 415, 416, 413, and 421 (not observed 414)**

MATERIAL QUANTITY: **2630** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 414**

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/White and Brown Streaks**
MATERIAL LOCATION: **Rooms 411, 414, 415, 416, 413, and 421 (not observed 414)**
MATERIAL QUANTITY: **2630** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Dark green linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym Office and 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Dark green linoleum**

MATERIAL LOCATION: **Gym Office and 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Brown cementitious floor sheeting**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Balcony and Assembly Hall**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Brown cementitious floor sheeting**
MATERIAL LOCATION: **Balcony and Assembly Hall**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Tan Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Tan Speckles**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9" x 9" Dark Orange Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office & Bathroom**

MATERIAL QUANTITY: **675**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9" x 9" Dark Orange Floor Tile**
MATERIAL LOCATION: **Engineer's Office & Bathroom**
MATERIAL QUANTITY: **675** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Tan w/White & Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104 (no access)**
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Tan w/White & Brown Streaks Floor Tile**
MATERIAL LOCATION: **Room 104 (no access)**
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile w/White and Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Assembly Hall**

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile w/White and Brown Streaks**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **1' x 2' Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher's Lunchroom (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **1' x 2' Black Floor Tile**
MATERIAL LOCATION: **Teacher's Lunchroom (not observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **1' x 1' White Wormed Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room, Serving Room and 218**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **1' x 1' White Wormed Ceiling Tile**

MATERIAL LOCATION: **Lunch Room, Serving Room and 218**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **2' x 2' Acoustical Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **2' x 2' Acoustical Ceiling Tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **White pegboard ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Dishwashing Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **White pegboard ceiling tile**

MATERIAL LOCATION: **Dishwashing Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/ White & Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 324, 422 & Storage, 326/330, 320, 208, 218 (not observed), 310 (patches)**

MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rooms 324, 326, and 330**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/ White & Brown Streaks**
MATERIAL LOCATION: **Rooms 324, 422 & Storage, 326/330, 320, 208, 218 (not observed), 310 (patches)**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **1' x 1' White Gouged Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room & Serving Room (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **1' x 1' White Gouged Ceiling Tile**

MATERIAL LOCATION: **Lunch Room & Serving Room (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **1' x 1' White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 122 & Serving Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **1' x 1' White Ceiling Tile**

MATERIAL LOCATION: **Room 122 & Serving Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Ceiling plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Ceiling plaster**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Plaster walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Damage in 425 with peeling paint observed in room 415 storage, 314, 313, 315**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Plaster walls**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Stucco plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall and Balcony**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Stucco plaster**

MATERIAL LOCATION: **Assembly Hall and Balcony**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Lab hoods**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 411, 414, 421, 422, and 422A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Lab hoods**

MATERIAL LOCATION: **Rooms 411, 414, 421, 422, and 422A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Transite desk tops (black)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 411, 415 (not observed 411)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Transite desk tops (black)**
MATERIAL LOCATION: **Rooms 411, 415 (not observed 411)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Black transite counter tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 411, 414, 415, 421 (not observed 411)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Black transite counter tops**
MATERIAL LOCATION: **Rooms 411, 414, 415, 421 (not observed 411)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Green transite desk tops**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 411, 414, 421 (not observed 411)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Green transite desk tops**
MATERIAL LOCATION: **Rooms 411, 414, 421 (not observed 411)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Possibly in Pipe Chases**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Aircell pipe insulation**

MATERIAL LOCATION: **Possibly in Pipe Chases**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd, 3rd & 4th Floor Corridors (not observed)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed on 2nd and 3rd floors**

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**
MATERIAL LOCATION: **2nd, 3rd & 4th Floor Corridors (not observed)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Aircell pipe insulation joints**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Possibly in Pipe Chases**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Aircell pipe insulation joints**

MATERIAL LOCATION: **Possibly in Pipe Chases**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Paperwrap on Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 322**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Paperwrap on Insulation**

MATERIAL LOCATION: **Room 322**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Insulation Beneath Shell of Incinerator**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Insulation Beneath Shell of Incinerator**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd, 3rd & 4th Floor Corridors (not observed 2nd and 3rd)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed on 2nd and 3rd floors - same 2019, 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile**
MATERIAL LOCATION: **2nd, 3rd & 4th Floor Corridors (not observed 2nd and 3rd)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Vibration Absorbers on Ducts**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Vibration Absorbers on Ducts**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Brown floor sheeting**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Brown floor sheeting**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor, Rooms 104, 226, 324, 414, 422, and Offices**
MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Floor tile mastic**
MATERIAL LOCATION: **1st Floor Corridor, Rooms 104, 226, 324, 414, 422, and Offices**
MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54 A**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/White & Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **324, 422 & Storage, 310 (patches)**

MATERIAL QUANTITY: **4800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 324**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **54 A**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/White & Brown Streaks Mastic**
MATERIAL LOCATION: **324, 422 & Storage, 310 (patches)**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54 B**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **54 B**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54 C**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/ White & Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **104**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **54 C**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/ White & Brown Streaks Mastic**
MATERIAL LOCATION: **104**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54 D**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Brown & White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor, 2 Offices Across From 118, Main Office, 226,**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in room 118**

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **54 D**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Brown & White Streaks Mastic**
MATERIAL LOCATION: **1st Floor Corridor, 2 Offices Across From 118, Main Office, 226,**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **White/orange/green/brown terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hallways, Stairwells, Stairs, Kitchen, Lunchroom Complex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **White/orange/green/brown terrazzo**

MATERIAL LOCATION: **Hallways, Stairwells, Stairs, Kitchen, Lunchroom Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Gray terrazzo stall panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Bathrooms and Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Gray terrazzo stall panels**

MATERIAL LOCATION: **Bathrooms and Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Gray/black/white terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Foyer**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Gray/black/white terrazzo**

MATERIAL LOCATION: **Foyer**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Gold/white terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Foyer**
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Gold/white terrazzo**
MATERIAL LOCATION: **Foyer**
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Gray/white terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Foyer**
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Gray/white terrazzo**
MATERIAL LOCATION: **Foyer**
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/ Brown and Orange Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Nurse's Room**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/ Brown and Orange Streaks**
MATERIAL LOCATION: **Nurse's Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Fireplace brick**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Foyer**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Fireplace brick**
MATERIAL LOCATION: **Foyer**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Fireplace brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Foyer**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Fireplace brick mortar**
MATERIAL LOCATION: **Foyer**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Gray wall tile caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girl's & Boy's Bathrooms, Library, Locker Rooms106, 318, 406, 408, 410**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Gray wall tile caulk**

MATERIAL LOCATION: **Girl's & Boy's Bathrooms, Library, Locker Rooms 106, 318, 406, 408, 410**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tilew/White & Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2000** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in the assembly hall and 1st floor storage**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile/White & Brown Streaks Mastic**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **9" x 9" Orange Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106, 108 & Basement Locker Room**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2400** DAMAGE UNITS: **SF**
COMMENTS: **Damage in basement**

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **9" x 9" Orange Speckled Floor Tile Mastic**
MATERIAL LOCATION: **Room 106, 108 & Basement Locker Room**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **260** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 212, 209**
MATERIAL QUANTITY: **1450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Floor Tile Mastic**
MATERIAL LOCATION: **Room 212, 209**
MATERIAL QUANTITY: **1450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **9" x 9" Black (w/White Streaks) Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Women's 1st Floor Bathroom**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **9" x 9" Black (w/White Streaks) Floor Tile Mastic**

MATERIAL LOCATION: **Women's 1st Floor Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **6 Sided ceramic tile grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Bathrooms and Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **6 Sided ceramic tile grout**

MATERIAL LOCATION: **Bathrooms and Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **9" x 9" Bright Green w/White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **9" x 9" Bright Green w/White Floor Tile Mastic**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Library and Room 122 (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**

MATERIAL LOCATION: **Library and Room 122 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Brown & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor, 2 Offices Across From 118, Main Office, 226,**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Brown & White Streaks**
MATERIAL LOCATION: **1st Floor Corridor, 2 Offices Across From 118, Main Office, 226,**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Gray wall tile caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girls & Boys Bathrooms, 106, 406, 408, 410, Locker Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Gray wall tile caulk**
MATERIAL LOCATION: **Girls & Boys Bathrooms, 106, 406, 408, 410, Locker Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Locker Room, Rooms 104, 110, 414, 411**

MATERIAL QUANTITY: **860**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 110**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
MATERIAL LOCATION: **Locker Room, Rooms 104, 110, 414, 411**
MATERIAL QUANTITY: **860** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Locker Room, Rooms 104, 110, 414, 411**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Locker Room, Rooms 104, 110, 414, 411**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46471 BUIDLING ID: 7690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ron Brock
SCHOOL NAME: Al Raby High School INSPECTION DATE: 12/15/2022
ADDRESS: 3545 West Fulton Avenue IDPH LICENSE NO: 100-07134

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 73
MATERIAL DESCRIPTION: 9" x 9" Green, Brown, and Tan Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Chrysotile FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 104 (Under 12" x 12" Floor Tiles)

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2022

Inspector's Signature:



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **9" x 9" Green, Brown, and Tan Floor Tile**
MATERIAL LOCATION: **Room 104 (Under 12" x 12" Floor Tiles)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **9" x 9" Green, Brown, and Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 104 (Under 12" x 12" Floor Tiles)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **9" x 9" Green, Brown, and Tan Floor Tile Mastic**
MATERIAL LOCATION: **Room 104 (Under 12" x 12" Floor Tiles)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **9" x 9" Brown w/White & Dark Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 112, 308 & 312 (not observed 308)**

MATERIAL QUANTITY: **2100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 308**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **9" x 9" Brown w/White & Dark Brown Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 112, 308 & 312 (not observed 308)**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Black Spots**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 122**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Black Spots**
MATERIAL LOCATION: **Room 122**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Black Spots Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 122 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Black Spots Mastic**

MATERIAL LOCATION: **Room 122 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **9" x 9" Brown w/White and Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 322 (not observed)**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **9" x 9" Brown w/White and Black Floor Tile**

MATERIAL LOCATION: **Room 322 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Black and White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 322 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Black and White Floor Tile Mastic**
MATERIAL LOCATION: **Room 322 (not observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **9" x 9" Orange Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**


RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 106, 108 & Basement Locker Room**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1600** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in the boiler room and room 106**

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **9" x 9" Orange Speckled Floor Tile**
MATERIAL LOCATION: **Rooms 106, 108 & Basement Locker Room**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Gray baseboard (cove base)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Gray baseboard (cove base)**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **Gray baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Gray baseboard mastic**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **White/green/red/gold linoleum adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 215 and 221 (not observed 215, 221)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **White/green/red/gold linoleum adhesive**
MATERIAL LOCATION: **Rooms 215 and 221 (not observed 215, 221)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **1/2" Ceramic tile grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Locker Room & Small Amounts in Boy's & Girl's Bathrooms**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **1/2" Ceramic tile grout**
MATERIAL LOCATION: **Locker Room & Small Amounts in Boy's & Girl's Bathrooms**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **Cinder block mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Cinder block mortar**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **2' x 4' Lay-In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 102, Library, 122 and 104, 106**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **2' x 4' Lay-In Ceiling Panels**
MATERIAL LOCATION: **Rooms 102, Library, 122 and 104, 106**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46471 BUILDING ID: 7690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ron Brock
SCHOOL NAME: Al Raby High School INSPECTION DATE: 12/15/2022
ADDRESS: 3545 West Fulton Avenue IDPH LICENSE NO: 100-07134

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 86
MATERIAL DESCRIPTION: 2' x4' Lay In Ceiling Panels w/ Specks
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 122, 325, 327, 323, 325, 321, 318, 314

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **2' x4' Lay In Ceiling Panels w/ Specks**

MATERIAL LOCATION: **Room 122, 325, 327, 323, 325, 321, 318, 314**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Teacher's Lunchroom, Library, and Men's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
MATERIAL LOCATION: **Lunchroom, Teacher's Lunchroom, Library, and Men's Bathroom**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Beige curtain**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Beige curtain**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **Red curtain**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **Red curtain**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **9" x 9" Brown w/ White & Dark Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 112, and 312**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in 112**

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **9" x 9" Brown w/ White & Dark Brown Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 112, and 312**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ Dark Brown & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 406, 411, 425, and 426**

MATERIAL QUANTITY: **2830**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ Dark Brown & White Streaks**
MATERIAL LOCATION: **Rooms 406, 411, 425, and 426**
MATERIAL QUANTITY: **2830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Dark Brown & White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 406, 411, 425, and 426**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Dark Brown & White Streaks Mastic**
MATERIAL LOCATION: **Rooms 406, 411, 425, and 426**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Black baseboard (cove base)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **Black baseboard (cove base)**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **Black baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **Black baseboard mastic**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **Interior window caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **Interior window caulk**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **Window glazing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **Window glazing**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement and Room 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Basement and Room 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **Glazed (finished) brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **Glazed (finished) brick**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **Glazed brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **Glazed brick mortar**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **Window glazing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Wall of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **Window glazing**

MATERIAL LOCATION: **West Wall of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-001**
MATERIAL DESCRIPTION: **9" x 9" Orange Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **700**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **FT-001**
MATERIAL DESCRIPTION: **9" x 9" Orange Floor Tile**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-002**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 122, 308**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **FT-002**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **Rooms 122, 308**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-001**
MATERIAL DESCRIPTION: **9" x 9" Orange Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **FTM-001**
MATERIAL DESCRIPTION: **9" x 9" Orange Floor Tile Mastic**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-002**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 122, 308**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/15/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUIDLING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **FTM-002**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 122, 308**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/27/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **171**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/ light brown Streaks Floor tiles**
MATERIAL LOCATION: **Room 414, 416 (patches), 411, 312 (patches)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **171**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/ light brown Streaks Floor tiles**
MATERIAL LOCATION: **Room 414, 416 (patches), 411, 312 (patches)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **167**

MATERIAL DESCRIPTION: **Tongue and groove wooden floor**

MATERIAL LOCATION: **Room 424, 410, 408, 306, 309, 311, 313, 314, 315, 318, 321, 325, 327, 215, 214, 211/211A, 210, gymnasium, auditorium stage.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **170**
MATERIAL DESCRIPTION: **Mastic associated with 12" x 12" Dark Brown w/ light brown Streaks Floor tiles**
MATERIAL LOCATION: **Rooms 414, 416 (patches), 411, 312 (patches)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **170**
MATERIAL DESCRIPTION: **Mastic associated with 12" x 12" Dark Brown w/ light brown Streaks Floor tiles**
MATERIAL LOCATION: **Rooms 414, 416 (patches), 411, 312 (patches)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **169**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White w/ brown specks Floor Tile**

MATERIAL LOCATION: **425, 426, 120**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **168**
MATERIAL DESCRIPTION: **12" x 12" White w/ brown specks Floor Tile**
MATERIAL LOCATION: **425, 426, 120**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **168**
MATERIAL DESCRIPTION: **12" x 12" White w/ brown specks Floor Tile**
MATERIAL LOCATION: **425, 426, 120**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/27/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ron Brock**
SCHOOL NAME: **Al Raby High School** INSPECTION DATE: **12/15/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **172**
MATERIAL DESCRIPTION: **Gray with light gray streaks Linoleum**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 12/15/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46471** BUILDING ID: **7690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Al Raby High School** REVIEW DATE: **12/27/2022**
ADDRESS: **3545 West Fulton Avenue** IDPH LICENSE NO: **100-07134**

HOMOGENEOUS AREA: **172**

MATERIAL DESCRIPTION: **Gray with light gray streaks Linoleum**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____




Date: 12/27/2022

APPENDIX B

Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otsafety.com

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Ron Brock

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/19/2022

Exam Date: 1/19/2022



Expiration Date: 1/19/2023

Certificate Number: BIR2201190225

Kathy DeSalvo, Director

Ronald Brock

Illinois Licensed Building Inspector, Air Sampling Professional, Asbestos Project Manager





OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER

3/28/2023

AIR SAMPLING PROFESSIONAL


Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid

training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed