

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0002
SCHOOL NAME: Austin High School
ADDRESS OF SCHOOL: 231 N Pine
CITY: Chicago, IL, 60644

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/11/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/24/2022 ENROLLMENT 191
IDPH INSPECTOR LICENSE NUMBER: 100-08904
IDPH LICENSED INSPECTOR NAME (Please Print): Douglas McCormick
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



10/12/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Austin High School

231 N Pine
Chicago, IL, 60644

Unit: 46621
Building ID: 1220

IDPH ID Number: 14-016-2990-0002

REPORT DATE:

Wednesday, October 12, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

10/12/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66511 Region: 03 IDPH ID: 14-016-2990-0002

School: Austin High School Building ID: 1220

Address: 231 N Pine

Chicago, IL, 60644

Building Contact: Ruiz, Luis

Contact Phone: 7737096415

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/24/2022

Review Date: 10/12/2022

Inspector: Douglas McCormick

Inspector IDPH License: 100-08904

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 12, 2022

RE: Austin High School, Unit 46621
231 N Pine
Chicago, IL, 60644

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Austin High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Austin High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Austin High School Unit: 66511 Region: 03
Address: 231 N Pine Chicago, IL, 60644
IDPH ID: 14-016-2990-0002 Building ID: 1220
Contact: Ruiz, Luis Phone: 7737096415

2. Description of Facility

Original Construction: 1930 Additional Construction:
Total Square Footage: 397258 No of Floors: 4
Current Occupancy: 191

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Douglas McCormick



Inspector IDPH license # 100-08904
Reinspection Date: 9/24/2022

Signature:
Date: 9/24/2022

6. Management Planner

Management Planner Name: Evan Christian



Management Planner IDPH license # 100-19466

Signature:
Date: 10/12/2022

7. Review Date: 10/12/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/12/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Austin High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1220:

| | |
|-----|------------------------------------|
| 116 | Black lab table |
| 117 | Wood flooring |
| 118 | Black science lab counter |
| 119 | Cabinet liner panels |
| 120 | Chalkboard adhesive |
| 121 | Drywall |
| 122 | Corkboard adhesive |
| 123 | 2' x 4' Ceiling Tile w/Holes |
| 124 | 1' x 1' Gray Fissured Ceiling Tile |

| | |
|-----|--|
| 125 | Green duct sealant |
| 126 | 9" x 9" Gray Floor Tile |
| 127 | 9" x 9" Gray Floor Tile Mastic |
| 128 | Skylight window glazing |
| 129 | 12" x 12" Pink Mottled Floor Tile |
| 130 | 12" x 12" Pink Mottled Floor Tile Mastic |
| 131 | Fire insulated door |
| 132 | Red capet mastic |
| 133 | Interior green house window glazing |
| 134 | Radiator cabinet liner |
| 135 | Brown speckled carpet |
| 136 | 1' x 1' Yellow Ceiling Tile Patch |
| 137 | Black w/White Flooring Sheet |
| 138 | Gray duct sealant |
| 139 | Fume hood |
| 140 | Vault door |
| 141 | 2' x 4' Smooth Speckled Ceiling Tile |
| 142 | Stage fire wall |
| 143 | Acoustical ceiling plaster |
| 144 | Gray carpet mastic |
| 145 | Gray sink sealant |
| 27 | 12" x 12" Light Blue w/Blue & White. Specks floor tile |
| 6 | 9" x 9" Red/Black Vinyl Floor Tile |

| | |
|--------|--|
| 7.7 | 12" x 12" Beige Speckle Vinyl Floor Tile |
| AA | Floor material Pinkish w/ White |
| FF | 2' x 4' laid in ceiling tile White |
| HA-103 | 1' x 1' White grooved Ceiling Tile |

B. The following new homogenous areas have been identified for Building 1220:

| | |
|-----|--|
| 116 | Black lab table |
| 117 | Wood flooring |
| 118 | Black science lab counter |
| 119 | Cabinet liner panels |
| 120 | Chalkboard adhesive |
| 121 | Drywall |
| 122 | Corkboard adhesive |
| 123 | 2' x 4' Ceiling Tile w/Holes |
| 124 | 1' x 1' Gray Fissured Ceiling Tile |
| 125 | Green duct sealant |
| 126 | 9" x 9" Gray Floor Tile |
| 127 | 9" x 9" Gray Floor Tile Mastic |
| 128 | Skylight window glazing |
| 129 | 12" x 12" Pink Mottled Floor Tile |
| 130 | 12" x 12" Pink Mottled Floor Tile Mastic |
| 131 | Fire insulated door |
| 132 | Red capet mastic |
| 133 | Interior green house window glazing |
| 134 | Radiator cabinet liner |
| 135 | Brown speckled carpet |
| 136 | 1' x 1' Yellow Ceiling Tile Patch |
| 137 | Black w/White Flooring Sheet |
| 138 | Gray duct sealant |

| | |
|-----|--------------------------------------|
| 139 | Fume hood |
| 140 | Vault door |
| 141 | 2' x 4' Smooth Speckled Ceiling Tile |
| 142 | Stage fire wall |
| 143 | Acoustical ceiling plaster |
| 144 | Gray carpet mastic |
| 145 | Gray sink sealant |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|-----|--|
| 110 | 1' x 1' Gray Fissured Ceiling Tile |
| 111 | 12" x 12" White w/ Blue Specks Floor Tile |
| 112 | Mastic Associated w/ 12" x 12" White w/ Blue Specks Floor Tile |
| 113 | Beige stone pattern sheet flooring |
| 114 | Mastic Associated w/ Beige Stone Pattern Sheet Flooring |
| 115 | Gray spray-on fireproofing |
| 116 | Black lab table |
| 117 | Wood flooring |
| 118 | Black science lab counter |
| 119 | Cabinet liner panels |
| 120 | Chalkboard adhesive |
| 121 | Drywall |
| 122 | Corkboard adhesive |
| 123 | 2' x 4' Ceiling Tile w/Holes |
| 124 | 1' x 1' Gray Fissured Ceiling Tile |
| 125 | Green duct sealant |
| 126 | 9" x 9" Gray Floor Tile |
| 127 | 9" x 9" Gray Floor Tile Mastic |
| 128 | Skylight window glazing |
| 129 | 12" x 12" Pink Mottled Floor Tile |
| 13 | Exterior brick - Non-AHERA |
| 130 | 12" x 12" Pink Mottled Floor Tile Mastic |
| 131 | Fire insulated door |
| 132 | Red capet mastic |
| 133 | Interior green house window glazing |
| 134 | Radiator cabinet liner |
| 135 | Brown speckled carpet |
| 136 | 1' x 1' Yellow Ceiling Tile Patch |
| 137 | Black w/White Flooring Sheet |
| 138 | Gray duct sealant |
| 139 | Fume hood |
| 140 | Vault door |
| 141 | 2' x 4' Smooth Speckled Ceiling Tile |
| 142 | Stage fire wall |
| 143 | Acoustical ceiling plaster |
| 144 | Gray carpet mastic |
| 145 | Gray sink sealant |
| 27 | 12" x 12" Light Blue w/Blue & White. Specks floor tile |
| 28 | 12" x 12" Light Blue w/Blue & White. Specks floor |

| | |
|---------|---|
| | tile mastic |
| 30 | 2' x 2' White Pin Hole Ceiling Tile |
| 31 | Black-gold carpet adhesive |
| 32 | Black-white-gray terazzo flooring |
| 33 | 12" x 12" White w/Blue-Brown Spec's Floor Tile |
| 34 | 12" x 12" White w/Blue-Brown Spec's Floor Tile Mastic |
| 35 | White-gray ceramic grout |
| 36 | White-gray ceramic adhesive |
| 37 | Green-black-white terrazzo |
| 3E | 9" x 9" Cream w/Off-White Streaks |
| 7 | 12" x 12" Light Red Speckle Vinyl Floor Tile |
| 7.1 | 12" x 12" Red Speckle Vinyl Floor Tile |
| 7.3 | 12" x 12" Gray Speckle Vinyl Floor Tile |
| 7.5 | 12" x 12" Off-White w/Beige Stripes Vinyl Floor Tile |
| 7.7 | 12" x 12" Beige Speckle Vinyl Floor Tile |
| 7.8 | 12" x 12" Black Vinyl Floor Tile |
| AA | Floor material Pinkish w/ White |
| BB | 12" x 12" White Floor Tile |
| CC | 12"x 12"red floor tile |
| DD | 12"x 12" black Floor Tile |
| EE | Mastic associate HA # BB,CC,DD |
| FF | 2' x 4' laid in ceiling tile White |
| GG | 12" x 12" White spline ceiling tile |
| HA-100 | Fire curtain |
| HA-101 | Woven electrical wire insulation |
| HA-102 | Electrical wire insulation for chandeliers |
| HA-103 | 1' x 1' White grooved Ceiling Tile |
| HA-104 | Glue for 1' x 1' White grooved Ceiling Tile |
| HA-105 | 12" x 12" Gray w/ White and Brown Specks Vinyl Floor Tile |
| HA-105m | Adhesive for 12" x 12"Gray w/ White and Brown Vinyl Floor Tile |
| HA-106 | Hard mud pipe fitting insulation |

The following areas were deemed to be inaccessible:

| | |
|------|---|
| 11 | 12" x 12" Red/Black Vinyl Floor Tile Mastic |
| 112 | Mastic Associated w/ 12" x 12" White w/ Blue Specks Floor Tile |
| 114 | Mastic Associated w/ Beige Stone Pattern Sheet Flooring |
| 12.2 | 12" x 12" Dark Beige Speckle Floor Tile Mastic |
| 12.3 | 12" x 12" Gray Speckle Vinyl Floor Tile Mastic |
| 12.6 | 12" x 12" White Vinyl Floor Tile Mastic |

| | |
|---------|---|
| 121 | Drywall |
| 122 | Corkboard adhesive |
| 123 | 2' x 4' Ceiling Tile w/Holes |
| 127 | 9" x 9" Gray Floor Tile Mastic |
| 128 | Skylight window glazing |
| 132 | Red capet mastic |
| 134 | Radiator cabinet liner |
| 136 | 1' x 1' Yellow Ceiling Tile Patch |
| 141 | 2' x 4' Smooth Speckled Ceiling Tile |
| 142 | Stage fire wall |
| 143 | Acoustical ceiling plaster |
| 144 | Gray carpet mastic |
| 28 | 12" x 12" Light Blue w/Blue & White. Specks floor tile mastic |
| 30 | 2' x 2' White Pin Hole Ceiling Tile |
| 31 | Black-gold carpet adhesive |
| 34 | 12" x 12" White w/Blue-Brown Spec's Floor Tile Mastic |
| 36 | White-gray ceramic adhesive |
| 7.2 | 12" x 12" Dark Beige Speckle Vinyl Floor Tile |
| 9 | Window panels |
| EE | Mastic associate HA # BB,CC,DD |
| FF | 2' x 4' laid in ceiling tile White |
| GG | 12" x 12" White spline ceiling tile |
| HA-104 | Glue for 1' x 1' White grooved Ceiling Tile |
| HA-105m | Adhesive for 12" x 12" Gray w/ White and Brown Vinyl Floor Tile |

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Douglas McCormick, IDPH License # 100-08904. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Austin High School Building 1220 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220

Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 11 | 12" x 12" Red/Black Vinyl Floor Tile Mastics | 20,000 | SF | Throughout 3rd, 4th, and 2nd Flr. Corridors, Auditorium, 219, 203, 200 | CHR | MISC | N | LOC | 25 | SF | No | ACBM with the potential for damage | 5 | LOW |
| 11.1 | 9" x 9" Beige w/Brown Strips Vinyl Floor Tile Mastics - Abated | | | Room 219, 318, 311, 431 | ABATED | MISC | | | | | | | | |
| 11.2 | 9" x 9" Red Vinyl Floor Tile Mastics | | | Room 320 | CHR | MISC | | | | | | | | |
| 11.3 | 9" x 9" Tan w/Brown Stripes Vinyl Floor Tile Mastics - Abated | | | Rooms 319, 321, and 313 | ABATED | MISC | | | | | | | | |
| 11.4 | 9" x 9" Light Green Vinyl Floor Tile Mastics - ABATED | | | Room 220 | ABATED | MISC | | | | | | | | |
| 11.5 | 9" x 9" Beige/Brown Vinyl Floor Tile Mastics | | | Room 335 | CHR | MISC | | | | | | | | |
| 110 | 1' x 1' Gray Fissured Ceiling Tile | 200 | SF | 431 | ASSUMED | MISC | Y | NONE | 0 | SF | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 111 | 12" x 12" White w/ Blue Specks Floor Tile | 4,500 | SF | Rooms 134, 134B, 137, 138, 431, 433, 335, 318, 320, 138, 137, | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 112 | Mastics Associated w/ 12" x 12" White w/ Blue Specks Floor Tile | 4,500 | SF | Rooms 134, 134B, 137, 138, 431, 433 | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 113 | Beige stone pattern sheet flooring | 800 | SF | Room 239 | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 114 | Mastics Associated w/ Beige Stone Pattern Sheet Flooring | 800 | SF | Room 239 | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 115 | Gray spray-on fireproofing | 10,000 | SF | Boiler Room, Attic Mechanical Spaces | ASSUMED | SURFACE | Y | NONE | 0 | SF | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 116 | Black lab table | 115 | EA | Rooms 419, 327, 313, 319 | ASSUMED | MISC | N | NONE | 0 | EA | Yes | ACBM with the potential for damage | | LOW |
| 117 | Wood flooring | 32,000 | SF | Rooms 439C, 407, 405, 401, 400, 404, 410, 412, 416, 417, 418, 420, 422, 325A, 331, 323, 357A, 307, 303, 305, 301A, 302B, 308, 312, 332, 326, 343, 345, 341, 216, GYM 214, Gym, Dance Room, 234, 232, 228, 236, 240, | ASSUMED | MISC | N | NONE | 0 | SF | Yes | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220

Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|---------------|-----------------------|
| | | | | 242, 233, 128, 134A, 134B, 136 | | | | | | | | | | |
| 118 | Black science lab counter | 280 | SF | Rooms 415, 427, 327, 319 | ASSUMED | MISC | N | NONE | 0 | SF | Yes | ACBM with the potential for damage | | LOW |
| 119 | Cabinet liner panels | 600 | SF | Rooms 411A, 313A | ASSUMED | MISC | N | NONE | 0 | SF | Yes | ACBM with the potential for damage | | LOW |
| 12 | 12" x 12" Light Red Speckle Vinyl Floor Tile Mastic | | | Rooms 101, 123, 106, 112, 1st Floor Corridor | NO_ACBM | MISC | | | | | | | | |
| 12.1 | 12" x 12" Red Speckle Vinyl Floor Tile Mastic | | | Room 101, Lunchroom | NO_ACBM | MISC | | | | | | | | |
| 12.2 | 12" x 12" Dark Beige Speckle Floor Tile Mastic | 1,200 | SF | Room 108 and 220 | CHR | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 12.3 | 12" x 12" Gray Speckle Vinyl Floor Tile Mastic | 750 | SF | Rooms 207,208 | CHR | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 12.4 | 12" x 12" Light Beige Speckle Vinyl Floor Tile Mastic | | | RM 206, 128 | NO_ACBM | MISC | | | | | | | | |
| 12.5 | 12" x 12" Off-White w/Beige Stripes Vinyl Floor Tile Mastic | | | Room 203, 327, 403, 3rd Fl Womens Toilet Room | NO_ACBM | MISC | | | | | | | | |
| 12.6 | 12" x 12" White Vinyl Floor Tile Mastic | 500 | SF | Men's and Women's Bathrooms Throughout School | CHR | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 12.7 | 12" x 12" Beige Speckled Vinyl Floor Tile Mastic - Abated | | | Room 220 | ABATED | MISC | | | | | | | | |
| 12.8 | 12" x 12" Black Vinyl Floor Tile Mastic - Abated | | | 4th Floor East Corridor | ABATED | MISC | | | | | | | | |
| 120 | Chalkboard adhesive | 400 | SF | Classrooms | ASSUMED | MISC | N | NONE | 0 | SF | Yes | ACBM with the potential for damage | | LOW |
| 121 | Drywall | 3,100 | SF | Rooms 402, 410, 331, 301A, 216, 239, 121, 116, Basement Electrical Room | ASSUMED | MISC | N | NONE | 0 | SF | Yes | ACBM with the potential for damage | | LOW |
| 122 | Corkboard adhesive | 15 | SF | Room 414 | ASSUMED | MISC | N | NONE | 0 | SF | Yes | ACBM with the potential for damage | | LOW |
| 123 | 2' x 4' Ceiling Tile w/Holes | 2,700 | SF | Rooms 416, 418, 431, 433, 429, 427, 331, 319, 302B, 229, 227, 137, 135, | ASSUMED | MISC | Y | DIST | 296 | SF | Yes | Damaged or significantly damaged friable misc. ACBM | 5 | LOW |
| 124 | 1' x 1' Gray Fissured Ceiling Tile | 1,400 | SF | Room 431 | ASSUMED | MISC | Y | NONE | 0 | SF | Yes | ACBM with the potential for damage | | LOW |
| 125 | Green duct sealant | 6 | LF | Attic Mechanical Spaces | ASSUMED | MISC | N | NONE | 0 | LF | Yes | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220

Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|---------------|-----------------------|
| 16 | Interior brick mortar | | | Interior of Building | NO_ACBM | MISC | | | | | | | | |
| 17 | Red brick material | | | 3rd Floor Janitors Closet | NO_ACBM | MISC | | | | | | | | |
| 18 | Red brick mortar | | | 3rd Floor Janitors Closet | NO_ACBM | MISC | | | | | | | | |
| 19 | Cinderblock material (brick) | | | Men's and Women's Bathrooms, Room 403, and Janitors Closet | NO_ACBM | MISC | | | | | | | | |
| 20 | Cinderblock mortar material | | | Men's and Women's Bathrooms, Room 403, and Janitors Closet | NO_ACBM | MISC | | | | | | | | |
| 21 | Chalkboard material | | | Room 305 | NO_ACBM | MISC | | | | | | | | |
| 22 | 4 Inch black mop guard | | | Men's and Women's Bathrooms Throughout School and Room 4 | NO_ACBM | MISC | | | | | | | | |
| 23 | 4 Inch black mop guard mastic | | | Men's and Women's Bathrooms Throughout School | NO_ACBM | MISC | | | | | | | | |
| 24 | Exterior window caulk | | | Exterior of Building | NO_ACBM | MISC | | | | | | | | |
| 25 | 12" x 12" Multi-Beige Floor Tile - Abated | | | Room 313 | ABATED | MISC | | | | | | | | |
| 26 | 12" x 12" Multi-Beige Floor Tile Mastic - Abated | | | Room 313 | ABATED | MISC | | | | | | | | |
| 27 | 12" x 12" Light Blue w/Blue & White. Specks floor tile | 1,700 | SF | Room 220, 403, 239 | ASSUMED | MISC | N | NONE | 0 | SF | Yes | ACBM with the potential for damage | | LOW |
| 28 | 12" x 12" Light Blue w/Blue & White. Specks floor tile mastic | 1,100 | SF | Room 220, 403 | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 29 | Smooth plaster | | | Throughout School, 422, 121B, 106, 114 | NO_ACBM | SURFACE | | | | | | | | |
| 30 | 2' x 2' White Pin Hole Ceiling Tile | 4,000 | SF | Lunch Room, 325A., 323 | ASSUMED | MISC | Y | LOC | 8 | SF | No | Damaged or significantly damaged friable misc. ACBM | 5 | LOW |
| 31 | Black-gold carpet adhesive | 7,000 | SF | Main Office, Rooms 201,202,300,300A, 320B,414B and Engineer Office, 316, 231, 114 | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 32 | Black-white-gray terazzo flooring | 20,000 | SF | 1st,2nd,3rd and 4th Floor Corridors, Stairwells, Landing, Kitchen, Kit. Office and Lunchroom | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220
 Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 33 | 12" x 12" White w/Blue-Brown Spec's Floor Tile | 2,000 | SF | Rooms 219,229,318,320 and 335, 433, 431 | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 34 | 12" x 12" White w/Blue-Brown Spec's Floor Tile Mastic | 2,000 | SF | Rooms 219,229,318,320 and 335 | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 35 | White-gray ceramic grout | 200 | SF | Engineer Office Bathroom | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 36 | White-gray ceramic adhesive | 200 | SF | Engineer Office Bathroom | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 37 | Green-black-white terrazzo | 3,200 | SF | 1st, 2nd, 3rd and 4th Boy's/Girl's Bathroom | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 3E | 9" x 9" Cream w/Off-White Streaks | | | 1st Floor Corridor Areas Across From Room 109 | ASSUMED | MISC | | | | | | | | |
| 6 | 9" x 9" Red/Black Vinyl Floor Tile | 38,000 | SF | Rooms 111, 119, 4th Floor Hallway, Auditorium | CHR | MISC | N | NONE | 0 | SF | Yes | ACBM with the potential for damage | | LOW |
| 6.1 | 9" x 9" Beige w/Brown Streaks Vinyl Floor Tile | 1,900 | SF | Room 219, 318, 311 | CHR | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 6.2 | 9" x 9" Red Vinyl Floor Tile | | | Room 320 | CHR | MISC | | | | | | | | |
| 6.3 | 9" x 9" Tan w/Brown Stripes Vinyl Floor Tile | 3,120 | SF | Rooms 319, 321, and 313 | CHR | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 6.4 | 9" x 9" Light Green Vinyl Floor Tile - ABATED | | | Room 220 | ABATED | MISC | | | | | | | | |
| 6.5 | 9" x 9" Beige and Brown Vinyl Floor Tile | 1,608 | SF | Room 335 | CHR | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 7 | 12" x 12" Light Red Speckle Vinyl Floor Tile | 19,400 | SF | Rooms 101, 123, 134, 106, 112, 1st Floor Hall | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 7.1 | 12" x 12" Red Speckle Vinyl Floor Tile | 900 | SF | Room 101 | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 7.2 | 12" x 12" Dark Beige Speckle Vinyl Floor Tile | 1,200 | SF | Rooms 108 and 220 | CHR | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 7.3 | 12" x 12" Gray Speckle Vinyl Floor Tile | 1,100 | SF | Rooms 207, 208 | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 7.4 | 12" x 12" Light Beige Speckle Vinyl Floor Tile | 1,050 | SF | Room 206,128 | CHR | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 7.5 | 12" x 12" Off-White w/Beige Stripes Vinyl Floor Tile | 2,425 | SF | Rooms 203, 327 and 403, 409, 4th Fl Womens Toilet Room, 3rd Floor Womens Toilet | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220

Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|---------------|-----------------------|
| | | | | Room, 2nd Fl Womens Toilet Room | | | | | | | | | | |
| 7.6 | 12" x 12" White Vinyl Floor Tile | 500 | SF | Men's and Women's Bathrooms Throughout School | CHR | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 7.7 | 12" x 12" Beige Speckle Vinyl Floor Tile | 5,000 | SF | Room 220,134,134 A,137,138,425 | ASSUMED | MISC | N | NONE | 0 | SF | Yes | ACBM with the potential for damage | | LOW |
| 7.8 | 12" x 12" Black Vinyl Floor Tile | 7,000 | SF | 4th Floor East Corridor, Room 203 | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| 8 | 1x6 wall tile | | | Library | NO_ACBM | MISC | | | | | | | | |
| 9 | Window panels | 1,000 | SF | Throughout Building | CHR | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| AA | Floor material Pinkish w/ White | 13,000 | SF | Rooms 101,107,133,211,21 5,313,319,321,327.4 11,415,419,421 | ASSUMED | MISC | N | LOC | 30 | SF | Yes | ACBM with the potential for damage | 5 | LOW |
| BB | 12" x 12" White Floor Tile | 37,000 | SF | 2nd,3th, 4th floor corridors | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| CC | 12"x 12" red floor tile | 1,000 | SF | All stairwell entrances on 2nd, 3rd, 4th floors | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| DD | 12"x 12" black Floor Tile | 1,000 | SF | All stairwell entrances on 2nd, 3rd, 4th floors | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| EE | Mastic associate HA # BB,CC,DD | 38,000 | SF | 2nd, 3rd, 4th floor corridors | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| FF | 2' x 4' laid in ceiling tile White | 45,000 | SF | Most classrooms, 421, 419, 407, 405, 403, 401, 400, 408, 410, 412, 308, 234, 228, 242, 243, 233, 240, 131, 128, 116, 134A, 134B, 136 | ASSUMED | MISC | Y | DIST | 62 | SF | Yes | Damaged or significantly damaged friable misc. ACBM | 5 | LOW |
| GG | 12" x 12" White spline ceiling tile | 5,000 | SF | Lunchroom | ASSUMED | MISC | Y | NONE | 0 | SF | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| HA-100 | Fire curtain | 400 | SF | Auditorium Stage | ASSUMED | MISC | N | NONE | 0 | SF | No | ACBM with the potential for damage | | LOW |
| HA-101 | Woven electrical wire insulation | | | Auditorium stage light fixtures | ASSUMED | MISC | | | | | | | | |
| HA-102 | Electrical wire insulation for chandeliers | | | Auditorium | ASSUMED | MISC | | | | | | | | |
| HA-103 | 1' x 1' White grooved Ceiling Tile | 16,900 | SF | GYM | ASSUMED | MISC | Y | DIST | 15 | SF | Yes | Damaged or significantly damaged | 5 | LOW |

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220

Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| |
|---|
| Reinspection Date 9/24/2022 |
| Inspector Name Douglas McCormick |
| 100-08904 5/15/2023 |
| Inspector's IDPH License Number / Expiration Date |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 11 | Damage in 219 |
| 11.1 | |
| 11.2 | Not observed 2022 |
| 11.3 | |
| 11.4 | |
| 11.5 | Not observed 2022 |
| 110 | |
| 111 | |
| 112 | |
| 113 | |
| 114 | |
| 115 | |
| 116 | |
| 117 | |
| 118 | |
| 119 | |
| 12 | |
| 12.1 | |
| 12.2 | |
| 12.3 | |
| 12.4 | |
| 12.5 | |
| 12.6 | |
| 12.7 | |

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220

Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---|
| 12.8 | |
| 120 | |
| 121 | |
| 122 | |
| 123 | Damaged in Room 431 and 343 |
| 124 | |
| 125 | |
| 126 | |
| 127 | |
| 128 | |
| 129 | |
| 13 | |
| 130 | |
| 131 | Damage in 3rd Floor Utility Closet by Boys Bathroom |
| 132 | |
| 133 | |
| 134 | |
| 135 | |
| 136 | |
| 137 | |
| 138 | |
| 139 | |
| 14 | |
| 140 | |
| 141 | |
| 142 | |
| 143 | |
| 144 | |
| 145 | |

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220

Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|--|
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 28 | |
| 29 | Damage found in Rooms 407, 431, 406, 213 |
| 30 | Damage in Room 323 |
| 31 | |
| 32 | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 3E | Not observed 2022 |
| 6 | |
| 6.1 | |
| 6.2 | Not observed 2022 |
| 6.3 | |
| 6.4 | Not observed 2022 |

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220

Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---|
| 6.5 | |
| 7 | |
| 7.1 | |
| 7.2 | |
| 7.3 | |
| 7.4 | |
| 7.5 | |
| 7.6 | |
| 7.7 | |
| 7.8 | |
| 8 | |
| 9 | |
| AA | Damage in 131 |
| BB | |
| CC | |
| DD | |
| EE | |
| FF | Damage in 131 Suite, Rooms, 401, 405-407 |
| GG | |
| HA-100 | |
| HA-101 | Not observed 2022 |
| HA-102 | Not observed 2022 |
| HA-103 | Missing 10 tiles and 15 damaged tiles in the gym area |
| HA-104 | |
| HA-105 | |
| HA-105m | |
| HA-106 | Not observed 2022 |
| HA-107 | Not observed 2022 |
| HA-108 | Not observed 2022 |

Chicago Public Schools

School Austin High School **Unit** 66511 **Building ID** 1220

Address 231 N Pine **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| HA-109 | |
| O | |

Table II

Management Planner's Review

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 11 | 12" x 12" Red/Black Vinyl Floor Tile Mastic | 20,000 | SF | Throughout 3rd, 4th, and 2nd Flr. Corridors, Auditorium, 219, 203, 200 | Chrysotile | MISC | No | 25 | SF | 6 ACBM with the potential for damage | Repair |
| 11.1 | 9" x 9" Beige w/Brown Strips Vinyl Floor Tile Mastic - Abated | | | Room 219, 318, 311, 431 | Abated | MISC | | | | | |
| 11.2 | 9" x 9" Red Vinyl Floor Tile Mastic | | | Room 320 | Chrysotile | MISC | | | | | Follow O&M Plan |
| 11.3 | 9" x 9" Tan w/Brown Stripes Vinyl Floor Tile Mastic - Abated | | | Rooms 319, 321, and 313 | Abated | MISC | | | | | |
| 11.4 | 9" x 9" Light Green Vinyl Floor Tile Mastic - ABATED | | | Room 220 | Abated | MISC | | | | | |
| 11.5 | 9" x 9" Beige/Brown Vinyl Floor Tile Mastic | | | Room 335 | Chrysotile | MISC | | | | | Follow O&M Plan |
| 110 | 1' x 1' Gray Fissured Ceiling Tile | 200 | SF | 431 | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 111 | 12" x 12" White w/ Blue Specks Floor Tile | 4,500 | SF | Rooms 134, 134B, 137, 138, 431, 433, 335, 318, 320, 138, 137, | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 112 | Mastic Associated w/ 12" x 12" White w/ Blue Specks Floor Tile | 4,500 | SF | Rooms 134, 134B, 137, 138, 431, 433 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 113 | Beige stone pattern sheet flooring | 800 | SF | Room 239 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 114 | Mastic Associated w/ Beige Stone Pattern Sheet Flooring | 800 | SF | Room 239 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 115 | Gray spray-on fireproofing | 10,000 | SF | Boiler Room, Attic Mechanical Spaces | Assumed | SURFACE | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 116 | Black lab table | 115 | EA | Rooms 419, 327, 313, 319 | Assumed | MISC | No | 0 | EA | 6 ACBM with the potential for damage | Follow O&M Plan |
| 117 | Wood flooring | 32,000 | SF | Rooms 439C, 407, 405, 401,400, 404, 410, 412, 416, 417, 418, 420, 422, 325A, 331, 323, 357A, 307, 303, 305, 301A, 302B, 308, 312, 332, 326, 343, 345, 341, 216, GYM 214, Gym, Dance Room, 234, 232, 228, 236, 240, 242, 233, 128, 134A, 134B, 136 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 118 | Black science lab counter | 280 | SF | Rooms 415, 427, 327, 319 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 119 | Cabinet liner panels | 600 | SF | Rooms 411A, 313A | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 12 | 12" x 12" Light Red Speckle Vinyl Floor Tile Mastic | | | Rooms 101, 123, 106, 112, 1st Floor Corridor | No ACBM | MISC | | | | | |
| 12.1 | 12" x 12" Red Speckle Vinyl Floor Tile Mastic | | | Room 101, Lunchroom | No ACBM | MISC | | | | | |
| 12.2 | 12" x 12" Dark Beige Speckle Floor Tile Mastic | 1,200 | SF | Room 108 and 220 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 12.3 | 12" x 12" Gray Speckle Vinyl Floor Tile Mastic | 750 | SF | Rooms 207,208 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|---|-----------------|
| 12.4 | 12" x 12" Light Beige Speckle Vinyl Floor Tile Mastic | | | RM 206, 128 | No ACBM | MISC | | | | | |
| 12.5 | 12" x 12" Off-White w/Beige Stripes Vinyl Floor Tile Mastic | | | Room 203, 327, 403, 3rd Fl Womens Toilet Room | No ACBM | MISC | | | | | |
| 12.6 | 12" x 12" White Vinyl Floor Tile Mastic | 500 | SF | Men's and Women's Bathrooms Throughout School | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 12.7 | 12" x 12" Beige Speckled Vinyl Floor Tile Mastic - Abated | | | Room 220 | Abated | MISC | | | | | |
| 12.8 | 12" x 12" Black Vinyl Floor Tile Mastic - Abated | | | 4th Floor East Corridor | Abated | MISC | | | | | |
| 120 | Chalkboard adhesive | 400 | SF | Classrooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 121 | Drywall | 3,100 | SF | Rooms 402, 410, 331, 301A, 216, 239, 121, 116, Basement Electrical Room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 122 | Corkboard adhesive | 15 | SF | Room 414 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 123 | 2' x 4' Ceiling Tile w/Holes | 2,700 | SF | Rooms 416, 418, 431, 433, 429, 427, 331, 319, 302B, 229, 227, 137, 135, | Assumed | MISC | Yes | 296 | SF | 4 Damaged or significantly damaged friable misc. ACBM | Remove |
| 124 | 1' x 1' Gray Fissured Ceiling Tile | 1,400 | SF | Room 431 | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 125 | Green duct sealant | 6 | LF | Attic Mechanical Spaces | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 126 | 9" x 9" Gray Floor Tile | 300 | SF | Room 439E | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 127 | 9" x 9" Gray Floor Tile Mastic | 300 | SF | Room 439E | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 128 | Skylight window glazing | 120 | LF | Rooms 325A, 323 | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 129 | 12" x 12" Pink Mottled Floor Tile | 1,500 | SF | Room 313 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 13 | Exterior brick - Non-AHERA | | | Exterior of Building | Assumed | MISC | | | | | Follow O&M Plan |
| 130 | 12" x 12" Pink Mottled Floor Tile Mastic | 1,500 | SF | Room 313 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 131 | Fire insulated door | 70 | SF | 3rd Fl Utility Closet By Boys Bathroom | Assumed | MISC | Yes | 10 | SF | 4 Damaged or significantly damaged friable misc. ACBM | Remove |
| 132 | Red capet mastic | 650 | SF | Room 249 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 133 | Interior green house window glazing | 200 | LF | Room 213 | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 134 | Radiator cabinet liner | 225 | SF | Room 203 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 135 | Brown speckled carpet | 1,350 | SF | Rooms 202, 201 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 136 | 1' x 1' Yellow Ceiling Tile Patch | 40 | SF | Gym | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 137 | Black w/White Flooring Sheet | 1,200 | SF | Gym Storage Room, Auditorium | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 138 | Gray duct sealant | 6 | LF | Room 210 Gym Storage | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 139 | Fume hood | 6 | SF | Room 239 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 14 | Exterior mortar - Non-AHERA | | | Exterior of Building | No ACBM | MISC | | | | | |
| 140 | Vault door | 13 | SF | Room 112 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|---|-----------------|
| 141 | 2' x 4' Smooth Speckled Ceiling Tile | 1,620 | SF | Room 121 Cafe | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 142 | Stage fire wall | 800 | SF | Auditorium | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 143 | Acoustical ceiling plaster | 1,000 | SF | Room 105 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 144 | Gray carpet mastic | 400 | SF | Room 103 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 145 | Gray sink sealant | 30 | LF | Room 131 Suite | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 15 | Interior brick material (masonry) | | | Interior of Building | No ACBM | MISC | | | | | |
| 16 | Interior brick mortar | | | Interior of Building | No ACBM | MISC | | | | | |
| 17 | Red brick material | | | 3rd Floor Janitors Closet | No ACBM | MISC | | | | | |
| 18 | Red brick mortar | | | 3rd Floor Janitors Closet | No ACBM | MISC | | | | | |
| 19 | Cinderblock material (brick) | | | Men's and Women's Bathrooms, Room 403, and Janitors Closet | No ACBM | MISC | | | | | |
| 20 | Cinderblock mortar material | | | Men's and Women's Bathrooms, Room 403, and Janitors Closet | No ACBM | MISC | | | | | |
| 21 | Chalkboard material | | | Room 305 | No ACBM | MISC | | | | | |
| 22 | 4 Inch black mop guard | | | Men's and Women's Bathrooms Throughout School and Room 4 | No ACBM | MISC | | | | | |
| 23 | 4 Inch black mop guard mastic | | | Men's and Women's Bathrooms Throughout School | No ACBM | MISC | | | | | |
| 24 | Exterior window caulk | | | Exterior of Building | No ACBM | MISC | | | | | |
| 25 | 12" x 12" Multi-Beige Floor Tile - Abated | | | Room 313 | Abated | MISC | | | | | |
| 26 | 12" x 12" Multi-Beige Floor Tile Mastic - Abated | | | Room 313 | Abated | MISC | | | | | |
| 27 | 12" x 12" Light Blue w/Blue & White. Specks floor tile | 1,700 | SF | Room 220, 403, 239 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 28 | 12" x 12" Light Blue w/Blue & White. Specks floor tile mastic | 1,100 | SF | Room 220, 403 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 29 | Smooth plaster | | | Throughout School, 422, 121B, 106, 114 | No ACBM | SURFACE | | | | | |
| 30 | 2' x 2' White Pin Hole Ceiling Tile | 4,000 | SF | Lunch Room, 325A,, 323 | Assumed | MISC | Yes | 8 | SF | 4 Damaged or significantly damaged friable misc. ACBM | Encapsulate |
| 31 | Black-gold carpet adhesive | 7,000 | SF | Main Office, Rooms 201,202,300,300A, 320B,414B and Engineer Office, 316, 231, 114 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 32 | Black-white-gray terazzo flooring | 20,000 | SF | 1st,2nd,3rd and 4th Floor Corridors, Stairwells, Landing, Kitchen, Kit. Office and Lunchroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 33 | 12" x 12" White w/Blue-Brown Spec's Floor Tile | 2,000 | SF | Rooms 219,229,318,320 and 335, 433, | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| | | | | 431 | | | | | | | |
| 34 | 12" x 12" White w/Blue-Brown Spec's Floor Tile Mastic | 2,000 | SF | Rooms 219,229,318,320 and 335 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 35 | White-gray ceramic grout | 200 | SF | Engineer Office Bathroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 36 | White-gray ceramic adhesive | 200 | SF | Engineer Office Bathroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 37 | Green-black-white terrazzo | 3,200 | SF | 1st, 2nd, 3rd and 4th Boy's/Girl's Bathroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 3E | 9" x 9" Cream w/Off-White Streaks | | | 1st Floor Corridor Areas Across From Room 109 | Assumed | MISC | | | | | Follow O&M Plan |
| 6 | 9" x 9" Red/Black Vinyl Floor Tile | 38,000 | SF | Rooms 111, 119, 4th Floor Hallway, Auditorium | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 6.1 | 9" x 9" Beige w/Brown Streaks Vinyl Floor Tile | 1,900 | SF | Room 219, 318, 311 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 6.2 | 9" x 9" Red Vinyl Floor Tile | | | Room 320 | Chrysotile | MISC | | | | | Follow O&M Plan |
| 6.3 | 9" x 9" Tan w/Brown Stripes Vinyl Floor Tile | 3,120 | SF | Rooms 319, 321, and 313 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 6.4 | 9" x 9" Light Green Vinyl Floor Tile - ABATED | | | Room 220 | Abated | MISC | | | | | |
| 6.5 | 9" x 9" Beige and Brown Vinyl Floor Tile | 1,608 | SF | Room 335 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7 | 12" x 12" Light Red Speckle Vinyl Floor Tile | 19,400 | SF | Rooms 101, 123, 134, 106, 112, 1st Floor Hall | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7.1 | 12" x 12" Red Speckle Vinyl Floor Tile | 900 | SF | Room 101 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7.2 | 12" x 12" Dark Beige Speckle Vinyl Floor Tile | 1,200 | SF | Rooms 108 and 220 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7.3 | 12" x 12" Gray Speckle Vinyl Floor Tile | 1,100 | SF | Rooms 207, 208 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7.4 | 12" x 12" Light Beige Speckle Vinyl Floor Tile | 1,050 | SF | Room 206,128 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7.5 | 12" x 12" Off-White w/Beige Stripes Vinyl Floor Tile | 2,425 | SF | Rooms 203, 327 and 403, 409, 4th Fl Womens Toilet Room, 3rd Floor Womens Toilet Room, 2nd Fl Womens Toilet Room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7.6 | 12" x 12" White Vinyl Floor Tile | 500 | SF | Men's and Women's Bathrooms Throughout School | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7.7 | 12" x 12" Beige Speckle Vinyl Floor Tile | 5,000 | SF | Room 220,134,134A,137,138,425 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7.8 | 12" x 12" Black Vinyl Floor Tile | 7,000 | SF | 4th Floor East Corridor, Room 203 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 8 | 1x6 wall tile | | | Library | No ACBM | MISC | | | | | |
| 9 | Window panels | 1,000 | SF | Throughout Building | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| AA | Floor material Pinkish w/ White | 13,000 | SF | Rooms 101,107,133,211,215,313,319,321,327, 411,415,419,421 | Assumed | MISC | No | 30 | SF | 6 ACBM with the potential for damage | Repair |
| BB | 12" x 12" White Floor Tile | 37,000 | SF | 2nd ,3th, 4th floor corridors | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|---------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|---|-----------------|
| CC | 12"x 12"red floor tile | 1,000 | SF | All stairwell entrances on 2nd, 3rd, 4th floors | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| DD | 12"x 12" black Floor Tile | 1,000 | SF | All stairwell entrances on 2nd, 3rd, 4th floors | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| EE | Mastic associate HA # BB,CC,DD | 38,000 | SF | 2nd, 3rd, 4th floor corridors | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| FF | 2' x 4' laid in ceiling tile White | 45,000 | SF | Most classrooms, 421, 419, 407, 405, 403, 401, 400, 408, 410, 412, 308, 234, 228, 242, 243, 233, 240, 131, 128, 116, 134A, 134B, 136 | Assumed | MISC | Yes | 62 | SF | 4 Damaged or significantly damaged friable misc. ACBM | Remove |
| GG | 12" x 12" White spline ceiling tile | 5,000 | SF | Lunchroom | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| HA-100 | Fire curtain | 400 | SF | Auditorium Stage | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-101 | Woven electrical wire insulation | | | Auditorium stage light fixtures | Assumed | MISC | | | | | Follow O&M Plan |
| HA-102 | Electrical wire insulation for chandeliers | | | Auditorium | Assumed | MISC | | | | | Follow O&M Plan |
| HA-103 | 1' x 1' White grooved Ceiling Tile | 16,900 | SF | GYM | Assumed | MISC | Yes | 15 | SF | 4 Damaged or significantly damaged friable misc. ACBM | Remove |
| HA-104 | Glue for 1' x 1' White grooved Ceiling Tile | 2,000 | SF | GYM | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-105 | 12" x 12" Gray w/ White and Brown Specks Vinyl Floor Tile | 2,000 | SF | Rooms 204 A, 204 B, 208 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-105m | Adhesive for 12" x 12"Gray w/ White and Brown Vinyl Floor Tile | 2,000 | SF | Rooms 204 A, 204B, 208 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-106 | Hard mud pipe fitting insulation | | | Boiler room and basement ""wax"" room | Assumed | TSI | | | | | Follow O&M Plan |
| HA-107 | Aircell pipe insulation | | | Garage | Chrysotile | TSI | | | | | Follow O&M Plan |
| HA-108 | Mudded fitting insulation in aircell pipe insulation | | | Garage | Chrysotile | TSI | | | | | Follow O&M Plan |
| HA-109 | Hard mudded fitting insulation on fiberglass pipe insulation | 1,000 | LF | Throughout the building | Chrysotile | TSI | Yes | 0 | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| O | Boiler insulation (interior) | | | Boiler Room | No ACBM | MISC | | | | | |

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|----------------|
| Review Date | 10/12/2022 |
| Manager Planner Name | Evan Christian |
| 100-19466 | 5/15/2023 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|---------------------|
| 11 | |
| 11.1 | |
| 11.2 | |
| 11.3 | |
| 11.4 | |
| 11.5 | |
| 110 | |
| 111 | |
| 112 | |
| 113 | |
| 114 | |

Chicago Public Schools

School Austin High School
Address 231 N Pine

Unit 66511
 Chicago, IL, 60644

Building ID 1220
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|----------------------------------|
| 115 | |
| 116 | |
| 117 | |
| 118 | |
| 119 | |
| 12 | |
| 12.1 | |
| 12.2 | |
| 12.3 | |
| 12.4 | |
| 12.5 | |
| 12.6 | |
| 12.7 | |
| 12.8 | |
| 120 | |
| 121 | |
| 122 | |
| 123 | Sample to Determine ACM Content |
| 124 | |
| 125 | |
| 126 | |
| 127 | |
| 128 | |
| 129 | |
| 13 | |
| 130 | |
| 131 | Sample to determine ACM content. |

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 132 | |
| 133 | |
| 134 | |
| 135 | |
| 136 | |
| 137 | |
| 138 | |
| 139 | |
| 14 | |
| 140 | |
| 141 | |
| 142 | |
| 143 | |
| 144 | |
| 145 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 27 | |
| 28 | |
| 29 | |
| 30 | |
| 31 | |
| 32 | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 3E | |
| 6 | |
| 6.1 | |
| 6.2 | |
| 6.3 | |
| 6.4 | |
| 6.5 | |
| 7 | |
| 7.1 | |
| 7.2 | |
| 7.3 | |
| 7.4 | |
| 7.5 | |
| 7.6 | |
| 7.7 | |
| 7.8 | |

Chicago Public Schools

School Austin High School
Address 231 N Pine

Unit 66511
 Chicago, IL, 60644

Building ID 1220
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|----------------------------------|
| 8 | |
| 9 | |
| AA | |
| BB | |
| CC | |
| DD | |
| EE | |
| FF | Sample to determine ACM content |
| GG | |
| HA-100 | |
| HA-101 | |
| HA-102 | |
| HA-103 | Sample to determine ACM content. |
| HA-104 | |
| HA-105 | |
| HA-105m | |
| HA-106 | |
| HA-107 | |
| HA-108 | |
| HA-109 | |
| O | |

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Red/Black Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 3rd, 4th, and 2nd Flr. Corridors, Auditorium, 219, 203, 200**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in 219**

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Red/Black Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Throughout 3rd, 4th, and 2nd Flr. Corridors, Auditorium, 219, 203, 200**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.1**
MATERIAL DESCRIPTION: **9" x 9" Beige w/Brown Strips Vinyl Floor Tile Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 219, 318, 311, 431**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **11.1**
MATERIAL DESCRIPTION: **9" x 9" Beige w/Brown Strips Vinyl Floor Tile Mastic - Abated**
MATERIAL LOCATION: **Room 219, 318, 311, 431**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.2**
MATERIAL DESCRIPTION: **9" x 9" Red Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 320**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **11.2**

MATERIAL DESCRIPTION: **9" x 9" Red Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 320**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.3**
MATERIAL DESCRIPTION: **9" x 9" Tan w/Brown Stripes Vinyl Floor Tile Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 319, 321, and 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **11.3**

MATERIAL DESCRIPTION: **9" x 9" Tan w/Brown Stripes Vinyl Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Rooms 319, 321, and 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.4**
MATERIAL DESCRIPTION: **9" x 9" Light Green Vinyl Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **11.4**

MATERIAL DESCRIPTION: **9" x 9" Light Green Vinyl Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.5**
MATERIAL DESCRIPTION: **9" x 9" Beige/Brown Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 335**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **11.5**

MATERIAL DESCRIPTION: **9" x 9" Beige/Brown Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 335**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **1' x 1' Gray Fissured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **431**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **1' x 1' Gray Fissured Ceiling Tile**
MATERIAL LOCATION: **431**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 134, 134B, 137, 138, 431, 433, 335, 318, 320, 138, 137,**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Specks Floor Tile**
MATERIAL LOCATION: **Rooms 134, 134B, 137, 138, 431, 433, 335, 318, 320, 138, 137,**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White w/ Blue Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 134, 134B, 137, 138, 431, 433**

MATERIAL QUANTITY: **4500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White w/ Blue Specks Floor Tile**
MATERIAL LOCATION: **Rooms 134, 134B, 137, 138, 431, 433**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **Beige stone pattern sheet flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 239**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **Beige stone pattern sheet flooring**
MATERIAL LOCATION: **Room 239**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **Mastic Associated w/ Beige Stone Pattern Sheet Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 239**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **Mastic Associated w/ Beige Stone Pattern Sheet Flooring**
MATERIAL LOCATION: **Room 239**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Gray spray-on fireproofing**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room, Attic Mechanical Spaces**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Gray spray-on fireproofing**
MATERIAL LOCATION: **Boiler Room, Attic Mechanical Spaces**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" Light Red Speckle Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 101, 123, 106, 112, 1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12" x 12" Light Red Speckle Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 101, 123, 106, 112, 1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.1**
MATERIAL DESCRIPTION: **12" x 12" Red Speckle Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101, Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **12.1**

MATERIAL DESCRIPTION: **12" x 12" Red Speckle Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 101, Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.2**
MATERIAL DESCRIPTION: **12" x 12" Dark Beige Speckle Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 108 and 220**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **12.2**
MATERIAL DESCRIPTION: **12" x 12" Dark Beige Speckle Floor Tile Mastic**
MATERIAL LOCATION: **Room 108 and 220**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.3**
MATERIAL DESCRIPTION: **12" x 12" Gray Speckle Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 207,208**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **12.3**
MATERIAL DESCRIPTION: **12" x 12" Gray Speckle Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 207,208**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.4**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Speckle Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **RM 206, 128**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **12.4**

MATERIAL DESCRIPTION: **12" x 12" Light Beige Speckle Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **RM 206, 128**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.5**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Beige Stripes Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 203, 327, 403, 3rd Fl Womens Toilet Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **12.5**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/Beige Stripes Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 203, 327, 403, 3rd Fl Womens Toilet Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.6**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **12.6**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.7**
MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Vinyl Floor Tile Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **12.7**

MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Vinyl Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.8**
MATERIAL DESCRIPTION: **12" x 12" Black Vinyl Floor Tile Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor East Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **12.8**

MATERIAL DESCRIPTION: **12" x 12" Black Vinyl Floor Tile Mastic - Abated**

MATERIAL LOCATION: **4th Floor East Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Exterior mortar - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Exterior mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Interior brick material (masonry)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Interior brick material (masonry)**

MATERIAL LOCATION: **Interior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Interior brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Interior brick mortar**

MATERIAL LOCATION: **Interior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Red brick material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Janitors Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Red brick material**

MATERIAL LOCATION: **3rd Floor Janitors Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Red brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Janitors Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Red brick mortar**

MATERIAL LOCATION: **3rd Floor Janitors Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Cinderblock material (brick)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Men's and Women's Bathrooms, Room 403, and Janitors Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Cinderblock material (brick)**

MATERIAL LOCATION: **Men's and Women's Bathrooms, Room 403, and Janitors Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Cinderblock mortar material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Men's and Women's Bathrooms, Room 403, and Janitors Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Cinderblock mortar material**

MATERIAL LOCATION: **Men's and Women's Bathrooms, Room 403, and Janitors Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Chalkboard material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 305**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Chalkboard material**

MATERIAL LOCATION: **Room 305**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **4 Inch black mop guard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School and Room 4**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **4 Inch black mop guard**

MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School and Room 4**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **4 Inch black mop guard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **4 Inch black mop guard mastic**

MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Exterior window caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Exterior window caulk**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12" x 12" Multi-Beige Floor Tile - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12" x 12" Multi-Beige Floor Tile - Abated**

MATERIAL LOCATION: **Room 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12" x 12" Multi-Beige Floor Tile Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12" x 12" Multi-Beige Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Room 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/Blue & White. Specks floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 220, 403, 239**

MATERIAL QUANTITY: **1700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/Blue & White. Specks floor tile**
MATERIAL LOCATION: **Room 220, 403, 239**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/Blue & White. Specks floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 220, 403**

MATERIAL QUANTITY: **1100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/Blue & White. Specks floor tile mastic**
MATERIAL LOCATION: **Room 220, 403**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Smooth plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School, 422, 121B, 106, 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Damage found in Rooms 407, 431, 406, 213**

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Smooth plaster**

MATERIAL LOCATION: **Throughout School, 422, 121B, 106, 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2' x 2' White Pin Hole Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunch Room, 325A,, 323**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 323**

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2' x 2' White Pin Hole Ceiling Tile**
MATERIAL LOCATION: **Lunch Room, 325A,, 323**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Black-gold carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Rooms 201,202,300,300A, 320B,414B and Engineer Office, 316, 231, 114**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Black-gold carpet adhesive**
MATERIAL LOCATION: **Main Office, Rooms 201,202,300,300A, 320B,414B and Engineer Office, 316, 231, 114**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Black-white-gray terazzo flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st,2nd,3rd and 4th Floor Corridors, Stairwells, Landing, Kitchen, Kit. Office and Lunchroom**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Black-white-gray terazzo flooring**

MATERIAL LOCATION: **1st,2nd,3rd and 4th Floor Corridors, Stairwells, Landing, Kitchen, Kit. Office and Lunchroom**

MATERIAL QUANTITY: **20000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue-Brown Spec's Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 219,229,318,320 and 335, 433, 431**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue-Brown Spec's Floor Tile**
MATERIAL LOCATION: **Rooms 219,229,318,320 and 335, 433, 431**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue-Brown Spec's Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 219,229,318,320 and 335**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12" x 12" White w/Blue-Brown Spec's Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 219,229,318,320 and 335**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **White-gray ceramic grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer Office Bathroom**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **White-gray ceramic grout**
MATERIAL LOCATION: **Engineer Office Bathroom**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **White-gray ceramic adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer Office Bathroom**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **White-gray ceramic adhesive**
MATERIAL LOCATION: **Engineer Office Bathroom**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Green-black-white terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd and 4th Boy's/Girl's Bathroom**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Green-black-white terrazzo**
MATERIAL LOCATION: **1st, 2nd, 3rd and 4th Boy's/Girl's Bathroom**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3E**
MATERIAL DESCRIPTION: **9" x 9" Cream w/Off-White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor Areas Across From Room 109**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **3E**

MATERIAL DESCRIPTION: **9" x 9" Cream w/Off-White Streaks**

MATERIAL LOCATION: **1st Floor Corridor Areas Across From Room 109**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9" x 9" Red/Black Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 111, 119, 4th Floor Hallway, Auditorium**

MATERIAL QUANTITY: **38000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9" x 9" Red/Black Vinyl Floor Tile**
MATERIAL LOCATION: **Rooms 111, 119, 4th Floor Hallway, Auditorium**
MATERIAL QUANTITY: **38000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.1**
MATERIAL DESCRIPTION: **9" x 9" Beige w/Brown Streaks Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 219, 318, 311**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **6.1**
MATERIAL DESCRIPTION: **9" x 9" Beige w/Brown Streaks Vinyl Floor Tile**
MATERIAL LOCATION: **Room 219, 318, 311**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.2**
MATERIAL DESCRIPTION: **9" x 9" Red Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 320**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **6.2**

MATERIAL DESCRIPTION: **9" x 9" Red Vinyl Floor Tile**

MATERIAL LOCATION: **Room 320**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.3**
MATERIAL DESCRIPTION: **9" x 9" Tan w/Brown Stripes Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 319, 321, and 313**

MATERIAL QUANTITY: **3120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **6.3**
MATERIAL DESCRIPTION: **9" x 9" Tan w/Brown Stripes Vinyl Floor Tile**
MATERIAL LOCATION: **Rooms 319, 321, and 313**
MATERIAL QUANTITY: **3120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.4**
MATERIAL DESCRIPTION: **9" x 9" Light Green Vinyl Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **6.4**

MATERIAL DESCRIPTION: **9" x 9" Light Green Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.5**
MATERIAL DESCRIPTION: **9" x 9" Beige and Brown Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 335**
MATERIAL QUANTITY: **1608** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **6.5**
MATERIAL DESCRIPTION: **9" x 9" Beige and Brown Vinyl Floor Tile**
MATERIAL LOCATION: **Room 335**
MATERIAL QUANTITY: **1608** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Light Red Speckle Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 101, 123, 134, 106, 112, 1st Floor Hall**

MATERIAL QUANTITY: **19400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Light Red Speckle Vinyl Floor Tile**
MATERIAL LOCATION: **Rooms 101, 123, 134, 106, 112, 1st Floor Hall**
MATERIAL QUANTITY: **19400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.1**
MATERIAL DESCRIPTION: **12" x 12" Red Speckle Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **7.1**
MATERIAL DESCRIPTION: **12" x 12" Red Speckle Vinyl Floor Tile**
MATERIAL LOCATION: **Room 101**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.2**
MATERIAL DESCRIPTION: **12" x 12" Dark Beige Speckle Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 108 and 220**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **7.2**
MATERIAL DESCRIPTION: **12" x 12" Dark Beige Speckle Vinyl Floor Tile**
MATERIAL LOCATION: **Rooms 108 and 220**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.3**
MATERIAL DESCRIPTION: **12" x 12" Gray Speckle Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 207, 208**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **7.3**
MATERIAL DESCRIPTION: **12" x 12" Gray Speckle Vinyl Floor Tile**
MATERIAL LOCATION: **Rooms 207, 208**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.4**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Speckle Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 206,128**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **7.4**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Speckle Vinyl Floor Tile**
MATERIAL LOCATION: **Room 206,128**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.5**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Beige Stripes Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 203, 327 and 403, 409, 4th FI Womens Toilet Room, 3rd Floor Womens Toilet Room, 2nd FI Womens Toilet Room**

MATERIAL QUANTITY: **2425** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **7.5**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Beige Stripes Vinyl Floor Tile**
MATERIAL LOCATION: **Rooms 203, 327 and 403, 409, 4th Fl Womens Toilet Room, 3rd Floor Womens Toilet Room, 2nd Fl Womens Toliet Room**
MATERIAL QUANTITY: **2425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.6**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **7.6**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile**
MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.7**
MATERIAL DESCRIPTION: **12" x 12" Beige Speckle Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 220,134,134A,137,138,425**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **7.7**
MATERIAL DESCRIPTION: **12" x 12" Beige Speckle Vinyl Floor Tile**
MATERIAL LOCATION: **Room 220,134,134A,137,138,425**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.8**
MATERIAL DESCRIPTION: **12" x 12" Black Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **4th Floor East Corridor, Room 203**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **7.8**
MATERIAL DESCRIPTION: **12" x 12" Black Vinyl Floor Tile**
MATERIAL LOCATION: **4th Floor East Corridor, Room 203**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **1x6 wall tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **1x6 wall tile**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Window panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Window panels**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **Floor material Pinkish w/ White**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 101,107,133,211,215,313,319,321,327,411,415,419,421**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **13000** DAMAGE UNITS: **SF**
COMMENTS: **Damage in 131**

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **Floor material Pinkish w/ White**
MATERIAL LOCATION: **Rooms 101,107,133,211,215,313,319,321,327,411,415,419,421**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd ,3th, 4th floor corridors**
MATERIAL QUANTITY: **37000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **BB**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **2nd ,3th, 4th floor corridors**
MATERIAL QUANTITY: **37000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CC**
MATERIAL DESCRIPTION: **12"x 12"red floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All stairwell entrances on 2nd, 3rd, 4th floors**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **CC**
MATERIAL DESCRIPTION: **12"x 12"red floor tile**
MATERIAL LOCATION: **All stairwell entrances on 2nd, 3rd, 4th floors**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DD**
MATERIAL DESCRIPTION: **12"x 12" black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All stairwell entrances on 2nd, 3rd, 4th floors**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **DD**
MATERIAL DESCRIPTION: **12"x 12" black Floor Tile**
MATERIAL LOCATION: **All stairwell entrances on 2nd, 3rd, 4th floors**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EE**
MATERIAL DESCRIPTION: **Mastic associate HA # BB,CC,DD**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd, 3rd, 4th floor corridors**
MATERIAL QUANTITY: **38000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **EE**
MATERIAL DESCRIPTION: **Mastic associate HA # BB,CC,DD**
MATERIAL LOCATION: **2nd, 3rd, 4th floor corridors**
MATERIAL QUANTITY: **38000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FF**
MATERIAL DESCRIPTION: **2' x 4' laid in ceiling tile White**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Most classrooms, 421, 419, 407, 405, 403, 401, 400, 408, 410, 412, 308, 234, 228, 242, 243, 233, 240, 131, 128, 116, 134A, 134B, 136**
MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in 131 Suite, Rooms, 401, 405-407**

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **FF**
MATERIAL DESCRIPTION: **2' x 4' laid in ceiling tile White**
MATERIAL LOCATION: **Most classrooms, 421, 419, 407, 405, 403, 401, 400, 408, 410, 412, 308, 234, 228, 242, 243, 233, 240, 131, 128, 116, 134A, 134B, 136**
MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **62** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **GG**
MATERIAL DESCRIPTION: **12" x 12" White spline ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **GG**
MATERIAL DESCRIPTION: **12" x 12" White spline ceiling tile**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **Fire curtain**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium Stage**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **Fire curtain**
MATERIAL LOCATION: **Auditorium Stage**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-101**
MATERIAL DESCRIPTION: **Woven electrical wire insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium stage light fixtures**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **HA-101**

MATERIAL DESCRIPTION: **Woven electrical wire insulation**

MATERIAL LOCATION: **Auditorium stage light fixtures**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-102**
MATERIAL DESCRIPTION: **Electrical wire insulation for chandeliers**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **HA-102**

MATERIAL DESCRIPTION: **Electrical wire insulation for chandeliers**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-103**
MATERIAL DESCRIPTION: **1' x 1' White grooved Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **GYM**
MATERIAL QUANTITY: **16900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **16900** DAMAGE UNITS: **SF**
COMMENTS: **Missing 10 tiles and 15 damaged tiles in the gym area**

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **HA-103**

MATERIAL DESCRIPTION: **1' x 1' White grooved Ceiling Tile**

MATERIAL LOCATION: **GYM**

MATERIAL QUANTITY: **16900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **15**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Sample to determine ACM content.

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-104**
MATERIAL DESCRIPTION: **Glue for 1' x 1' White grooved Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **GYM**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **HA-104**

MATERIAL DESCRIPTION: **Glue for 1' x 1' White grooved Ceiling Tile**

MATERIAL LOCATION: **GYM**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-105**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White and Brown Specks Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 204 A, 204 B, 208**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **HA-105**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White and Brown Specks Vinyl Floor Tile**
MATERIAL LOCATION: **Rooms 204 A, 204 B, 208**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-105m**
MATERIAL DESCRIPTION: **Adhesive for 12" x 12" Gray w/ White and Brown Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 204 A, 204B, 208**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **HA-105m**
MATERIAL DESCRIPTION: **Adhesive for 12" x 12" Gray w/ White and Brown Vinyl Floor Tile**
MATERIAL LOCATION: **Rooms 204 A, 204B, 208**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-106**
MATERIAL DESCRIPTION: **Hard mud pipe fitting insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler room and basement ""wax"" room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **HA-106**

MATERIAL DESCRIPTION: **Hard mud pipe fitting insulation**

MATERIAL LOCATION: **Boiler room and basement ""wax"" room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-107**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Garage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **HA-107**

MATERIAL DESCRIPTION: **Aircell pipe insulation**

MATERIAL LOCATION: **Garage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-108**
MATERIAL DESCRIPTION: **Mudded fitting insulation in aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Garage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **HA-108**

MATERIAL DESCRIPTION: **Mudded fitting insulation in aircell pipe insulation**

MATERIAL LOCATION: **Garage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-109**
MATERIAL DESCRIPTION: **Hard mudded fitting insulation on fiberglass pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout the building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **HA-109**
MATERIAL DESCRIPTION: **Hard mudded fitting insulation on fiberglass pipe insulation**
MATERIAL LOCATION: **Throughout the building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Boiler insulation (interior)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Boiler insulation (interior)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **129**
MATERIAL DESCRIPTION: **12" x 12" Pink Mottled Floor Tile**
MATERIAL LOCATION: **Room 313**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **1' x 1' Yellow Ceiling Tile Patch**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **136**

MATERIAL DESCRIPTION: **1' x 1' Yellow Ceiling Tile Patch**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **Radiator cabinet liner**
MATERIAL LOCATION: **Room 203**
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **134**

MATERIAL DESCRIPTION: **Radiator cabinet liner**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile**
MATERIAL LOCATION: **Room 439E**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile**
MATERIAL LOCATION: **Room 439E**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **127**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Room 439E**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **Black science lab counter**
MATERIAL LOCATION: **Rooms 415, 427, 327, 319**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **Black science lab counter**
MATERIAL LOCATION: **Rooms 415, 427, 327, 319**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **Acoustical ceiling plaster**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **143**

MATERIAL DESCRIPTION: **Acoustical ceiling plaster**

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **1' x 1' Gray Fissured Ceiling Tile**
MATERIAL LOCATION: **Room 431**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **1' x 1' Gray Fissured Ceiling Tile**
MATERIAL LOCATION: **Room 431**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Cabinet liner panels**
MATERIAL LOCATION: **Rooms 411A, 313A**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **119**

MATERIAL DESCRIPTION: **Cabinet liner panels**

MATERIAL LOCATION: **Rooms 411A, 313A**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **Chalkboard adhesive**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **120**

MATERIAL DESCRIPTION: **Chalkboard adhesive**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **Brown speckled carpet**
MATERIAL LOCATION: **Rooms 202, 201**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **Brown speckled carpet**
MATERIAL LOCATION: **Rooms 202, 201**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **Skylight window glazing**
MATERIAL LOCATION: **Rooms 325A, 323**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **128**

MATERIAL DESCRIPTION: **Skylight window glazing**

MATERIAL LOCATION: **Rooms 325A, 323**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **Gray carpet mastic**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Rooms 402, 410, 331, 301A, 216, 239, 121, 116, Basement Electrical Room**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**

ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Rooms 402, 410, 331, 301A, 216, 239, 121, 116, Basement Electrical Room**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **Vault door**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **13** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **140**

MATERIAL DESCRIPTION: **Vault door**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **13**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **Fire insulated door**
MATERIAL LOCATION: **3rd FI Utility Closet By Boys Bathroom**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **4 Damaged or significantly damaged friable misc. ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **10** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
Damage in 3rd Floor Utility Closet by Boys Bathroom

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **131**

MATERIAL DESCRIPTION: **Fire insulated door**

MATERIAL LOCATION: **3rd FI Utility Closet By Boys Bathroom**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content.

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Corkboard adhesive**
MATERIAL LOCATION: **Room 414**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **Green duct sealant**
MATERIAL LOCATION: **Attic Mechanical Spaces**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **139**

MATERIAL DESCRIPTION: **Fume hood**

MATERIAL LOCATION: **Room 239**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **139**

MATERIAL DESCRIPTION: **Fume hood**

MATERIAL LOCATION: **Room 239**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **133**

MATERIAL DESCRIPTION: **Interior green house window glazing**

MATERIAL LOCATION: **Room 213**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **132**

MATERIAL DESCRIPTION: **Red carpet mastic**

MATERIAL LOCATION: **Room 249**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **12" x 12" Pink Mottled Floor Tile Mastic**
MATERIAL LOCATION: **Room 313**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **130**

MATERIAL DESCRIPTION: **12" x 12" Pink Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Room 313**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **Wood flooring**

MATERIAL LOCATION: **Rooms 439C, 407, 405, 401,400, 404, 410, 412, 416, 417, 418, 420, 422, 325A, 331, 323, 357A, 307, 303, 305, 301A, 302B, 308, 312, 332, 326, 343, 345, 341, 216, GYM 214, Gym, Dance Room, 234, 232, 228, 236, 240, 242, 233, 128, 134A, 134B, 136**

MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**

ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **Wood flooring**

MATERIAL LOCATION: **Rooms 439C, 407, 405, 401,400, 404, 410, 412, 416, 417, 418, 420, 422, 325A, 331, 323, 357A, 307, 303, 305, 301A, 302B, 308, 312, 332, 326, 343, 345, 341, 216, GYM 214, Gym, Dance Room, 234, 232, 228, 236, 240, 242, 233, 128, 134A, 134B, 136**

MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **Gray sink sealant**
MATERIAL LOCATION: **Room 131 Suite**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **Gray sink sealant**
MATERIAL LOCATION: **Room 131 Suite**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **142**

MATERIAL DESCRIPTION: **Stage fire wall**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **Gray duct sealant**
MATERIAL LOCATION: **Room 210 Gym Storage**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **138**

MATERIAL DESCRIPTION: **Gray duct sealant**

MATERIAL LOCATION: **Room 210 Gym Storage**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **Black w/White Flooring Sheet**
MATERIAL LOCATION: **Gym Storage Room, Auditorium**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **137**

MATERIAL DESCRIPTION: **Black w/White Flooring Sheet**

MATERIAL LOCATION: **Gym Storage Room, Auditorium**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **Black lab table**
MATERIAL LOCATION: **Rooms 419, 327, 313, 319**
MATERIAL QUANTITY: **115** MATERIAL UNITS: **EA**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **EA**
COMMENTS:

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **Black lab table**
MATERIAL LOCATION: **Rooms 419, 327, 313, 319**
MATERIAL QUANTITY: **115** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile w/Holes**
MATERIAL LOCATION: **Rooms 416, 418, 431, 433, 429, 427, 331, 319, 302B, 229, 227, 137, 135,**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **4 Damaged or significantly damaged friable misc. ACBM**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **296** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damaged in Room 431 and 343

Inspector's Signature: _____



Date: 09/24/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile w/Holes**
MATERIAL LOCATION: **Rooms 416, 418, 431, 433, 429, 427, 331, 319, 302B, 229, 227, 137, 135,**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **296** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to Determine ACM Content

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **9/24/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **2' x 4' Smooth Speckled Ceiling Tile**
MATERIAL LOCATION: **Room 121 Cafe**
MATERIAL QUANTITY: **1620** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **09/24/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **10/12/2022**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **141**

MATERIAL DESCRIPTION: **2' x 4' Smooth Speckled Ceiling Tile**

MATERIAL LOCATION: **Room 121 Cafe**

MATERIAL QUANTITY: **1620** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

APPENDIX B

Inspector and Management Planner Licenses



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 08904

ISSUED

4/15/2022

EXPIRES

05/15/2023

DOUGLAS M McCORMICK
600 W VAN BUREN ST., STE 5
CHICAGO, IL 60607

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

4/4/2023

PROJECT MANAGER

4/5/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Doug McCormick

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 4/4/2022

Exam Date: 4/4/2022

Expiration Date: 4/4/2023

Certificate Number: BIR2204040955

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|-------------|--|
| MATERIAL | | |
| | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | | |
| | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | | |
| | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | | |
| | Loc | Localized |
| | Dist | Distributed |