

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0533
SCHOOL NAME: Jones Magnet High School
ADDRESS OF SCHOOL: 606 S. State
CITY: Chicago, IL, 60605

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/31/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/23/2022 ENROLLMENT 1925
IDPH INSPECTOR LICENSE NUMBER: 100-05020
IDPH LICENSED INSPECTOR NAME (Please Print): Devon Jackson
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

10/12/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Jones Magnet High School

606 S. State
Chicago, IL, 60605

Unit: 47021
Building ID: 1060

IDPH ID Number: 14-016-2990-0533

REPORT DATE:

Wednesday, October 12, 2022

Prepared for:

**Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

10/12/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 47021 Region: 03 IDPH ID: 14-016-2990-0533

School: Jones Magnet High School Building ID: 1060

Address: 606 S. State

Chicago, IL, 60605

Building Contact: Casasanto, Daniel

Contact Phone: 7737096175

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/23/2022

Review Date: 10/12/2022

Inspector: Devon Jackson

Inspector IDPH License: 100-05020

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 12, 2022

RE: Jones Magnet High School, Unit 47021
606 S. State
Chicago, IL, 60605

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Jones Magnet High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Jones Magnet High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Jones Magnet High School Unit: 47021 Region: 03
Address: 606 S. State Chicago, IL, 60605
IDPH ID: 14-016-2990-0533 Building ID: 1060
Contact: Casasanto, Daniel Phone: 7737096175

2. Description of Facility

Original Construction: 1968 Additional Construction: 1967,1968,2002
Total Square Footage: 24294 No of Floors: 2
Current Occupancy: 1925

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Devon Jackson


Inspector IDPH license # 100-05020
Reinspection Date: 9/23/2022

Signature: 
Date: 9/23/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature: 
Date: 10/12/2022

7. Review Date: 10/12/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/12/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Jones Magnet High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1060:

107	12" x 12" White w/ Blue Specks Floor Tile
108	12" x 12" Gray with Black Specks Floor Tile
109	12" x 12" White with Gray Specks Floor Tile
110	Mastic Associated with 12" x 12" White w/ Blue Specks, Gray with black Specks, White with Gray Specks Floor Tile
111	12" x 12" White w/ gray Specks Floor Tile
112	12" x 12" Gold w/ White Specks Floor Tile
113	12" x 12" Gold w/ White Specks Floor Tile
114	Mastic Associated with 12" x 12" White w/ gray Specks, Gold w/ White Specks, gray w/ White Specks Vinyl Floor Tile

115	2' x 2' Gray and Brown checkered carpet Mastic
116	12" x 12" White w/ gray Specks Vinyl Floor Tile
117	2' x 2' Rubber floor
118	12" x 12" White w/ gray Specks Vinyl Floor Tile Mastic
74	2' x 4' Lay-in Ceiling Panels
85	12" x 12" Blue Floor Tile
86	12" x 12" Blue Floor Tile Mastic
B	Elbows on Fiberglass Pipe Runs
D	Elbows on Fiberglass Pipe Runs
HA-100	1' x 1' grooved splined White Ceiling Tile

B. The following new homogenous areas have been identified for Building 1060:

107	12" x 12" White w/ Blue Specks Floor Tile
108	12" x 12" Gray with Black Specks Floor Tile
109	12" x 12" White with Gray Specks Floor Tile
110	Mastic Associated with 12" x 12" White w/ Blue Specks, Gray with black Specks, White with Gray Specks Floor Tile
111	12" x 12" White w/ gray Specks Floor Tile
112	12" x 12" Gold w/ White Specks Floor Tile
113	12" x 12" Gold w/ White Specks Floor Tile
114	Mastic Associated with 12" x 12" White w/ gray Specks, Gold w/ White Specks, gray w/ White Specks Vinyl Floor Tile
115	2' x 2' Gray and Brown checkered carpet Mastic
116	12" x 12" White w/ gray Specks Vinyl Floor Tile
117	2' x 2' Rubber floor
118	12" x 12" White w/ gray Specks Vinyl Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

102	12" x 12" Blue and White Floor Tile
102M	12" x 12" Blue & White Floor Tile Mastic
103	Terrazo floor
104	Ceramic Tile and Grout
104M	Ceramic tile mastic
105	12" x 12" White w/ Specks Floor Tile
105M	12" x 12" White w/Specks Floor Tile Mastic
106	Window expansion caulk
107	12" x 12" White w/ Blue Specks Floor Tile
108	12" x 12" Gray with Black Specks Floor Tile
109	12" x 12" White with Gray Specks Floor Tile
110	Mastic Associated with 12" x 12" White w/ Blue Specks, Gray with black Specks, White with Gray Specks Floor Tile
111	12" x 12" White w/ gray Specks Floor Tile
112	12" x 12" Gold w/ White Specks Floor Tile
113	12" x 12" Gold w/ White Specks Floor Tile
114	Mastic Associated with 12" x 12" White w/ gray Specks, Gold w/ White Specks, gray w/ White Specks Vinyl Floor Tile
115	2' x 2' Gray and Brown checkered carpet Mastic
116	12" x 12" White w/ gray Specks Vinyl Floor Tile
117	2' x 2' Rubber floor
118	12" x 12" White w/ gray Specks Vinyl Floor Tile Mastic
25	Insulation inside fire doors
26	Vibration damper
29	Linoleum
30	Linoleum mastic
31	12" x 12" Brown Floor Tile w/White & Brown Specks
32	12" x 12" Brown Floor Tile w/White & Brown Specks Mastic
33	Brown linoleum
34	Brown linoleum adhesive
35	Black Lab Counters and Sinks
36	Black lab tables
37	Fume hood interior materials
38	Gray Lab Counters and Sinks
39	Gray lab tables
40	12" x 12" White w/Brown Streaks Floor Tile
41	12" x 12" White w/Brown Streaks Floor Tile Mastic

42	12" x 12" Brown Mix Floor Tile
43	12" x 12" Brown Mix Floor Tile Mastic
44	12" x 12" Yellow Mix Floor Tile
45	12" x 12" Yellow Mix Floor Tile Mastic
46	12" x 12" Beige w/Brown Streaks Floor Tile
47	12" x 12" Beige w/Brown Streaks Floor Tile Mastic
48	12" x 12" White w/Medium Brown Specks Floor Tile
49	12" x 12" White w/Medium Brown Specks Floor Tile Mastic
50	12" x 12" Brown w/Specks Floor Tile
51	12" x 12" Brown w/Specks Floor Tile Mastic
52	12" x 12" Beige w/Gray Floor Tile
53	12" x 12" Beige w/Gray Floor Tile Mastic
54	12" x 12" Dark Gray w/Light Gray Floor Tile
55	12" x 12" Dark Gray w/Light Gray Floor Tile Mastic
56	12" x 12" White w/Gray Patches Floor Tile
57	12" x 12" White w/Gray Patches Floor Tile Mastic
58	4" Gray vinyl baseboard
59	4" Gray vinyl baseboard adhesive
5B	12" x 12" White Floor Tile
5E	12" x 12" White & Gray Floor Tile
60	4" Brown vinyl baseboard
61	4" Brown vinyl baseboard adhesive
62	4" Beige vinyl baseboard
63	4" Beige vinyl baseboard adhesive
64	4" Yellow vinyl baseboard
65	4" Yellow vinyl baseboard adhesive
66	4" Cream vinyl baseboard
67	4" Cream vinyl baseboard adhesive
68	4" Gray vinyl baseboard
69	4" Gray vinyl baseboard adhesive
70	Marker board adhesive
71	Poster board adhesive
72	Stair treads
73	Stair tread adhesive
74	2' x 4' Lay-in Ceiling Panels
75	Gray rubber flooring adhesive
76	Gray carpet adhesive
77	Brown/gray carpet adhesive
78	Drywall
79	Drywall compound
80	Chalk board adhesive
85	12" x 12" Blue Floor Tile
86	12" x 12" Blue Floor Tile Mastic
HA-100	1' x 1' grooved splined White Ceiling Tile
HA-101	Gray coating under the Kitchen sink

J

Tank insulation

The following areas were deemed to be inaccessible:

8D	12" x 12" Gray w/White Floor Tile Mastic
102M	12" x 12" Blue & White Floor Tile Mastic
103	Terrazo floor
104M	Ceramic tile mastic
105M	12" x 12" White w/Specks Floor Tile Mastic
25	Insulation inside fire doors
26	Vibration damper
30	Linoleum mastic
86	12" x 12" Blue Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Devon Jackson, IDPH License # 100-05020. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Jones Magnet High School Building 1060 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Jones Magnet High School Unit 47021 Building ID 1060

Address 606 S. State Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
34	Brown linoleum adhesive		SF	Classrooms 601 - 606, 605	ASSUMED	MISC				SF				
35	Black Lab Counters and Sinks	800	SF	Classrooms 603 - 606	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
36	Black lab tables	340	SF	Classrooms 604 - 606	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
37	Fume hood interior materials	120	SF	Classrooms 601A, 604A, 605A	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
38	Gray Lab Counters and Sinks	480	SF	Classrooms 601 - 602	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
39	Gray lab tables	260	SF	Classrooms 601 - 602	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
40	12" x 12" White w/Brown Streaks Floor Tile	26,750	SF	Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507 and 2, 3, 4, 5, 6, d, 400A, 301, 101, 103	ASSUMED	MISC	N	LOC	36	SF	No	ACBM with potential for significant damage	5	LOW
41	12" x 12" White w/Brown Streaks Floor Tile Mastic	26,750	SF	Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507, 1, 2, 3, 4, 5, 6, 301, 101, 103	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
42	12" x 12" Brown Mix Floor Tile	5,152	SF	Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507 and 1, 2, 3, 4, 5, 6	ASSUMED	MISC	N	DIST	20	SF	No	ACBM with the potential for damage	5	LOW
43	12" x 12" Brown Mix Floor Tile Mastic	5,152	SF	Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507, and 2, 3, 4, 5, 6	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
44	12" x 12" Yellow Mix Floor Tile	1,500	SF	Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
45	12" x 12" Yellow Mix Floor Tile Mastic	1,500	SF	Classrooms and Offices 201 - 202,	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Jones Magnet High School Unit 47021 Building ID 1060

Address 606 S. State Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				204 - 207, 302 - 303, 304 - 307, 401 - 403, 405 - 407, 501 - 507										
46	12" x 12" Beige w/Brown Streaks Floor Tile	16	SF	221 Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
47	12" x 12" Beige w/Brown Streaks Floor Tile Mastic	116	SF	221, 224, Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
48	12" x 12" White w/Medium Brown Specks Floor Tile	500	SF	Auditorium Exits by stairs, Cafe, Mgr. Off.	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
49	12" x 12" White w/Medium Brown Specks Floor Tile Mastic	500	SF	Auditorium Exits by stairs, Cafeteria/Foyer, Kitchen Corridor/Lower Stairs, Perf. Arts Stairway, Cafe, Mgr. Off.	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
50	12" x 12" Brown w/Specks Floor Tile	2,700	SF	Auditorium and Stage, Kitchen Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
51	12" x 12" Brown w/Specks Floor Tile Mastic	2,700	SF	Auditorium and Stage & Kitchen Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
52	12" x 12" Beige w/Gray Floor Tile	1,200	SF	Corridor to Perforooming Arts Wing	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
53	12" x 12" Beige w/Gray Floor Tile Mastic	600	SF	Corridor to Cafeteria, Stair Landings, Corridor to Perforooming Arts Wing	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
54	12" x 12" Dark Gray w/Light Gray Floor Tile	1,150	SF	Engineer's Office, 105I, 105J	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
55	12" x 12" Dark Gray w/Light Gray Floor Tile Mastic	1,150	SF	Engineer's Office, 105I, 105J	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
56	12" x 12" White w/Gray Patches Floor Tile	554	SF	As Patches in Cafeteria, Kitchen Storage and Elevators	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
57	12" x 12" White w/Gray Patches Floor Tile Mastic	554	SF	As Patches in Cafeteria, Kitchen Storage and Elevators	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
58	4" Gray vinyl baseboard	116	LF	Engineer's Office	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Jones Magnet High School Unit 47021 Building ID 1060

Address 606 S. State Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
59	4" Gray vinyl baseboard adhesive	116	LF	Engineer's Office	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
5A	12" x 12" Brown w/Beige Floor Tile	6,600	SF	PerfoRooming Arts Foyer, 221 & Office, 224, Lecture Hall & Stage, Theater,	CHR	MISC	N	DIST	33	SF	No	ACBM with the potential for damage	5	LOW
5B	12" x 12" White Floor Tile			Corridors Throughout	ASSUMED	MISC								
5E	12" x 12" White & Gray Floor Tile	990	SF	Classrooms 600	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
6	9" x 9" Tan Floor Tile			North Stair Landings	CHR	MISC								
60	4" Brown vinyl baseboard	68	LF	605A	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
61	4" Brown vinyl baseboard adhesive	68	LF	605A	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
62	4" Beige vinyl baseboard	950	LF	Office Area and Classrooms 600, 604, 604A	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
63	4" Beige vinyl baseboard adhesive	950	LF	Office Area and Classrooms 600, 604, 604A	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
64	4" Yellow vinyl baseboard	280	LF	Classrooms 601, 602	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
65	4" Yellow vinyl baseboard adhesive	280	LF	Classrooms 601, 602	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
66	4" Cream vinyl baseboard	4,100	LF	Library, Classrooms & Offices 200-207, 214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500-507, 1, 2, 3, 4, 5, 6, 301, 101, 103	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
67	4" Cream vinyl baseboard adhesive	4,100	LF	Library, Classrooms & Offices 200-207, 214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500-507, 1, 2, 3, 4, 5, 6, 301, 101, 103	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
68	4" Gray vinyl baseboard	400	LF	2nd-6th Floor Corridors, Classroom 404	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
69	4" Gray vinyl baseboard adhesive	400	LF	2nd-6th Floor Corridors,	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Jones Magnet High School Unit 47021 Building ID 1060
Address 606 S. State Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 9/23/2022
Inspector Name Devon Jackson
100-05020 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
8B	Not observed 2022
8D	
8E	
8F	Not observed 2022
9	Not observed 2022
1	
10	Not observed 2022
102	
102M	
103	
104	
104M	
105	
105M	
106	
107	
108	
109	
11	
110	
111	Damage in 304, 305, 308
112	Damage in 304, 305, 308
113	Damage in 304, 305, 308
114	Damage in 304, 305, 308

Chicago Public Schools

School Jones Magnet High School Unit 47021 Building ID 1060

Address 606 S. State Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
115	
116	
117	
118	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	Not observed 2022
32	Not observed 2022
33	Not observed 2022
34	Not observed 2022
35	
36	

Chicago Public Schools

School Jones Magnet High School Unit 47021 Building ID 1060

Address 606 S. State Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
37	
38	
39	
40	Damage found in Rooms 403,405,302,304,206,600,501,502,503, 400A, 103 4SF,
41	Not observed in 203,204,205 - May be Under Carpet
42	Damage found in Rooms 207, 504
43	
44	Not observed in Rooms 203-205, 302, 303
45	Not observed in Rooms 203-205, 302, 303
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
5A	Damage found in Rm. 224, Hall between Buildings, Lecture Hall
5B	Not observed 2022
5E	
6	Not observed 2022
60	
61	

Chicago Public Schools

School Jones Magnet High School Unit 47021 Building ID 1060

Address 606 S. State Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
85	2nd floor hall near room 224
86	
B	
D	
E	Not observed 2022
G	Not observed 2022
H	
HA-100	
HA-101	
I	

Chicago Public Schools

School Jones Magnet High School **Unit** 47021 **Building ID** 1060

Address 606 S. State **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
J	Not observed 2022

Table II

Management Planner's Review

Chicago Public Schools

School Jones Magnet High School

Unit 47021

Building ID 1060

Address 606 S. State

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
8B	12" x 12" White Floor Tile Mastic			1st Floor Corridor & Locker Room, 3rd & 5th Floors Lobby Areas, 304A & 504A (Alcove)	Chrysotile	MISC					Follow O&M Plan
8D	12" x 12" Gray w/White Floor Tile Mastic	500	SF	Classroom 504	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8E	12"x 12" White w/Gray Floor Tile Mastic	500	SF	Classrooms 600	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8F	12" x 12" Orange Floor Tile Mastic			Gym	Chrysotile	MISC					Follow O&M Plan
9	9" x 9" Tan Floor Tile Mastic			North Stair Landings	Chrysotile	MISC					Follow O&M Plan
1	Hard plaster			3rd Through 5th Floor Corridors	No ACBM	SURFACE					
10	9" x 9" White Floor Tile Mastic			Basement Corridor and Elevator Lobby	Chrysotile	MISC					Follow O&M Plan
102	12" x 12" Blue and White Floor Tile	6,400	SF	Kitchen Supply Room, Cafeteria, Stair Landing & Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102M	12" x 12" Blue & White Floor Tile Mastic	6,400	SF	Kitchen Supply Room, Cafeteria, Stairs, Entrance, Stair Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Terrazo floor	18,500	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	Ceramic Tile and Grout	3,072	SF	All Bathroom Walls and Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104M	Ceramic tile mastic	3,072	SF	All Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" White w/ Specks Floor Tile	108	SF	Kitchen Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105M	12" x 12" White w/Specks Floor Tile Mastic	108	SF	Kitchen Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	Window expansion caulk	15,000	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
107	12" x 12" White w/ Blue Specks Floor Tile	533	SF	Rooms 601, 602	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12" x 12" Gray with Black Specks Floor Tile	533	SF	Rooms 601, 602	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12" x 12" White with Gray Specks Floor Tile	533	SF	Rooms 601, 602	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	2' x 4' White (Wormy) Ceiling Tile			Rooms 600, 601, and 606, throughout 6th floor classrooms, 5th floor classrooms,	No ACBM	MISC					
110	Mastic Associated with 12" x 12" White w/ Blue Specks, Gray with black Specks, White with Gray Specks Floor Tile	1,600	SF	Rooms 601, 602	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	12" x 12" White w/ gray Specks Floor Tile	7,333	SF	Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Remove
112	12" x 12" Gold w/ White Specks Floor Tile	7,333	SF	Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Remove

Chicago Public Schools

School Jones Magnet High School

Unit 47021

Building ID 1060

Address 606 S. State

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
113	12" x 12" Gold w/ White Specks Floor Tile	7,333	SF	Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Remove
114	Mastic Associated with 12" x 12" White w/ gray Specks, Gold w/ White Specks, gray w/ White Specks Vinyl Floor Tile	22,000	SF	Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Remove
115	2' x 2' Gray and Brown checkered carpet Mastic	2,100	SF	Rooms 203/204/205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	12" x 12" White w/ gray Specks Vinyl Floor Tile	900	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	2' x 2' Rubber floor	1,000	SF	Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12" x 12" White w/ gray Specks Vinyl Floor Tile Mastic	900	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Brown baseboard			Throughout School	No ACBM	MISC					
13	Brown baseboard mastic			Throughout Building	No ACBM	MISC					
14	Black baseboard			Room 403 and 402	No ACBM	MISC					
15	Black baseboard mastic			Classrooms 402 & 403	No ACBM	MISC					
16	Carpet mastic			Faculty Lunchroom, Library Room (500), Rooms 604 & 606, 105A, Faculty lounge, 1st FL Corridor by offices, 105 throughout,	No ACBM	MISC					
17	Brown linoleum			Under Lockers on the 1st, 2nd, 3rd, 4th, 5th & 6th Floor & Locker Alcoves 504A & 604A	No ACBM	MISC					
18	Brown linoleum mastic			Under Lockers on the 1st, 2nd, 3rd, 4th, 5th & 6th Floor & Locker Alcoves 504A & 604A	No ACBM	MISC					
19	Drywall			Throughout School	No ACBM	MISC					
20	Exterior brick - Non-AHERA			Throughout Exterior of Building	No ACBM	MISC					
21	Exterior brick mortar - Non-AHERA			Exterior of Building	No ACBM	MISC					
22	Exterior joint compound			Exterior of School	No ACBM	MISC					
23	Roof flashing - Non-AHERA			Roof, 6th Floor	Chrysotile	MISC					Follow O&M Plan
24	Roof core - Non-AHERA			Roof Above Rooms 600-608	No ACBM	MISC					
25	Insulation inside fire doors	2,750	SF	Throughout School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Vibration damper	100	SF	7th Floor Mechanical Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Roof flashing - Non-AHERA			Above the 7th Floor	Chrysotile	MISC					Follow O&M Plan

Chicago Public Schools

School Jones Magnet High School

Unit 47021

Building ID 1060

Address 606 S. State

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
28	Roof core - Non-AHERA			Above the 7th Floor Mechanical Room	No ACBM	MISC					
29	Linoleum	4,500	SF	Rooms 601, 604, 603, 604A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Linoleum mastic	4,500	SF	Rooms 600, 601, 608, 604, 605, 604A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" x 12" Brown Floor Tile w/White & Brown Specks			Room 606	Assumed	MISC					Follow O&M Plan
32	12" x 12" Brown Floor Tile w/White & Brown Specks Mastic			Room 606	Assumed	MISC					Follow O&M Plan
33	Brown linoleum			Classrooms 601 - 606, 605	Assumed	MISC					Follow O&M Plan
34	Brown linoleum adhesive		SF	Classrooms 601 - 606, 605	Assumed	MISC			SF		Follow O&M Plan
35	Black Lab Counters and Sinks	800	SF	Classrooms 603 - 606	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Black lab tables	340	SF	Classrooms 604 - 606	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Fume hood interior materials	120	SF	Classrooms 601A, 604A, 605A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Gray Lab Counters and Sinks	480	SF	Classrooms 601 - 602	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Gray lab tables	260	SF	Classrooms 601 - 602	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12" x 12" White w/Brown Streaks Floor Tile	26,750	SF	Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507 and 2, 3, 4, 5, 6, d, 400A, 301, 101, 103	Assumed	MISC	No	36	SF	5 ACBM with potential for significant damage	Repair
41	12" x 12" White w/Brown Streaks Floor Tile Mastic	26,750	SF	Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507, 1, 2, 3, 4, 5, 6, 301, 101, 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" x 12" Brown Mix Floor Tile	5,152	SF	Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507 and 1, 2, 3, 4, 5, 6	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Repair
43	12" x 12" Brown Mix Floor Tile Mastic	5,152	SF	Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507, and 2, 3, 4, 5, 6	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12" x 12" Yellow Mix Floor Tile	1,500	SF	Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12" x 12" Yellow Mix Floor Tile Mastic	1,500	SF	Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12" x 12" Beige w/Brown Streaks Floor Tile	16	SF	221 Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12" x 12" Beige w/Brown Streaks Floor Tile Mastic	116	SF	221, 224, Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Jones Magnet High School

Unit 47021

Building ID 1060

Address 606 S. State

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
48	12" x 12" White w/Medium Brown Specks Floor Tile	500	SF	Auditorium Exits by stairs, Cafe, Mgr. Off.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12" x 12" White w/Medium Brown Specks Floor Tile Mastic	500	SF	Auditorium Exits by stairs, Cafeteria/Foyer, Kitchen Corridor/Lwer Stairs, Perf. Arts Stairway, Cafe, Mgr. Off.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12" x 12" Brown w/Specks Floor Tile	2,700	SF	Auditorium and Stage, Kitchen Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12" x 12" Brown w/Specks Floor Tile Mastic	2,700	SF	Auditorium and Stage & Kitchen Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12" x 12" Beige w/Gray Floor Tile	1,200	SF	Corridor to PerfoRooming Arts Wing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12" x 12" Beige w/Gray Floor Tile Mastic	600	SF	Corridor to Cafeteria, Stair Landings, Corridor to PerfoRooming Arts Wing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" Dark Gray w/Light Gray Floor Tile	1,150	SF	Engineer's Office, 105I, 105J	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" x 12" Dark Gray w/Light Gray Floor Tile Mastic	1,150	SF	Engineer's Office, 105I, 105J	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12" x 12" White w/Gray Patches Floor Tile	554	SF	As Patches in Cafeteria, Kitchen Storage and Elevators	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12" x 12" White w/Gray Patches Floor Tile Mastic	554	SF	As Patches in Cafeteria, Kitchen Storage and Elevators	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	4" Gray vinyl baseboard	116	LF	Engineer's Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
59	4" Gray vinyl baseboard adhesive	116	LF	Engineer's Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
5A	12" x 12" Brown w/Beige Floor Tile	6,600	SF	PerfoRooming Arts Foyer, 221 & Office, 224, Lecture Hall & Stage, Theater, Corridors Throughout	Chrysotile	MISC	No	33	SF	6 ACBM with the potential for damage	Repair
5B	12" x 12" White Floor Tile			Corridors Throughout	Assumed	MISC					Follow O&M Plan
5E	12" x 12" White & Gray Floor Tile	990	SF	Classrooms 600	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	9" x 9" Tan Floor Tile			North Stair Landings	Chrysotile	MISC					Follow O&M Plan
60	4" Brown vinyl baseboard	68	LF	605A	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
61	4" Brown vinyl baseboard adhesive	68	LF	605A	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
62	4" Beige vinyl baseboard	950	LF	Office Area and Classrooms 600, 604, 604A	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
63	4" Beige vinyl baseboard adhesive	950	LF	Office Area and Classrooms 600, 604, 604A	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
64	4" Yellow vinyl baseboard	280	LF	Classrooms 601, 602	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
65	4" Yellow vinyl baseboard adhesive	280	LF	Classrooms 601, 602	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
66	4" Cream vinyl baseboard	4,100	LF	Library, Classrooms & Offices 200-207, 214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500-507, 1, 2, 3, 4, 5, 6, 301, 101, 103	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
67	4" Cream vinyl baseboard adhesive	4,100	LF	Library, Classrooms & Offices 200-207,	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Jones Magnet High School

Unit 47021

Building ID 1060

Address 606 S. State

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500-507, 1, 2, 3, 4, 5, 6, 301, 101, 103							
68	4" Gray vinyl baseboard	400	LF	2nd-6th Floor Corridors, Classroom 404	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
69	4" Gray vinyl baseboard adhesive	400	LF	2nd-6th Floor Corridors, Classroom 404	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
70	Marker board adhesive	1,000	SF	Classrooms 201, 301, 304-308, 401-407, 501-507, 601, 602, 604-606	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Poster board adhesive	440	LF	Classrooms 201, 202, 204-207, 307, 308, 604, 605 and the 3rd and 6th Floor Corridors, 601, 602	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
72	Stair treads	630	SF	Rear Stairway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Stair tread adhesive	630	SF	Rear Stairway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	2' x 4' Lay-in Ceiling Panels	87,000	SF	1st - 6th Floor Classrooms, Library, Offices, Corridors	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
75	Gray rubber flooring adhesive	600	SF	Shipping/Receiving Dock	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	Gray carpet adhesive	1,144	SF	Classroom 404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Brown/gray carpet adhesive	7,000	SF	1st Floor Offices, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	Drywall	12,000	SF	1st - 6th Floor Classrooms, Library, Offices, Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	Drywall compound	12,000	SF	1st - 6th Floor Classrooms, Library, Offices, Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Chalk board adhesive	700	SF	Classrooms 201, 202, 204-207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12" x 12" Blue Floor Tile	15	SF	2nd floor hall between 2 buildings near room 221	Assumed	MISC	No	4	SF	6 ACBM with the potential for damage	Remove
86	12" x 12" Blue Floor Tile Mastic	15	SF	2nd floor hall between 2 buildings near room 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	Elbows on Fiberglass Pipe Runs	65	LF	7th Floor Mechanical Room	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Elbows on Fiberglass Pipe Runs	250	LF	Throughout School	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Breeching duct insulation			Boiler Room and Chiller Area	Chrysotile	TSI					Follow O&M Plan
G	Tank insulation (tar paper)			Boiler Room and Chiller Room	Chrysotile	TSI					Follow O&M Plan
H	Pipe insulation tar paper			Boiler Room	No ACBM	TSI					
HA-100	1' x 1' grooved splined White Ceiling Tile	2,000	SF	Two floors of the building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
HA-101	Gray coating under the Kitchen sink	5	SF	Kitchen and Office Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Jones Magnet High School

Unit 47021

Building ID 1060

Address 606 S. State

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
I	Boiler gasket insulation			Boiler Room	No ACBM	MISC					
J	Tank insulation			Mechanical Area by Kitchen	Assumed	MISC					Follow O&M Plan

Review Date	10/12/2022
Manager Planner Name	Evan Christian

HA Number	Management Comments
8B	
8D	

Chicago Public Schools

School Jones Magnet High School

Unit 47021

Building ID 1060

Address 606 S. State

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
8E	
8F	
9	
1	
10	
102	
102M	
103	
104	
104M	
105	
105M	
106	
107	
108	
109	
11	
110	
111	Sample to determine ACM content
112	Sample to determine ACM content
113	Sample to determine ACM content
114	Sample to determine ACM content
115	
116	
117	
118	
12	

Chicago Public Schools

School Jones Magnet High School
Address 606 S. State

Unit 47021
Chicago, IL, 60605

Building ID 1060
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	

Chicago Public Schools

School Jones Magnet High School
Address 606 S. State

Unit 47021
Chicago, IL, 60605

Building ID 1060
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
5A	
5B	
5E	
6	
60	
61	
62	

Chicago Public Schools

School Jones Magnet High School

Unit 47021

Building ID 1060

Address 606 S. State

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
85	Sample to determine ACM content
86	
B	
D	
E	
G	
H	
HA-100	
HA-101	

Chicago Public Schools

School Jones Magnet High School

Unit 47021

Building ID 1060

Address 606 S. State

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
I	
J	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8B**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor & Locker Room, 3rd & 5th Floors Lobby Areas, 304A & 504A (Alcove)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **8B**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor & Locker Room, 3rd & 5th Floors Lobby Areas, 304A & 504A (Alcove)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8D**
MATERIAL DESCRIPTION: **12" x 12" Gray w/White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classroom 504**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **8D**
MATERIAL DESCRIPTION: **12" x 12" Gray w/White Floor Tile Mastic**
MATERIAL LOCATION: **Classroom 504**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8E**
MATERIAL DESCRIPTION: **12"x 12" White w/Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 600**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **8E**
MATERIAL DESCRIPTION: **12"x 12" White w/Gray Floor Tile Mastic**
MATERIAL LOCATION: **Classrooms 600**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8F**
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **8F**
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile Mastic**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Stair Landings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic**
MATERIAL LOCATION: **North Stair Landings**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Hard plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Through 5th Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Hard plaster**

MATERIAL LOCATION: **3rd Through 5th Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Corridor and Elevator Lobby**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile Mastic**
MATERIAL LOCATION: **Basement Corridor and Elevator Lobby**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12" x 12" Blue and White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen Supply Room, Cafeteria, Stair Landing & Entrance**

MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12" x 12" Blue and White Floor Tile**
MATERIAL LOCATION: **Kitchen Supply Room, Cafeteria, Stair Landing & Entrance**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102M**
MATERIAL DESCRIPTION: **12" x 12" Blue & White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen Supply Room, Cafeteria, Stairs, Entrance, Stair Landing**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **102M**
MATERIAL DESCRIPTION: **12" x 12" Blue & White Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen Supply Room, Cafeteria, Stairs, Entrance, Stair Landing**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Terrazo floor**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **18500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Terrazo floor**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **18500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **Ceramic Tile and Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Bathroom Walls and Floors**
MATERIAL QUANTITY: **3072** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **Ceramic Tile and Grout**
MATERIAL LOCATION: **All Bathroom Walls and Floors**
MATERIAL QUANTITY: **3072** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104M**
MATERIAL DESCRIPTION: **Ceramic tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Bathrooms**
MATERIAL QUANTITY: **3072** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **104M**
MATERIAL DESCRIPTION: **Ceramic tile mastic**
MATERIAL LOCATION: **All Bathrooms**
MATERIAL QUANTITY: **3072** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" x 12" White w/ Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen Storage**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" x 12" White w/ Specks Floor Tile**
MATERIAL LOCATION: **Kitchen Storage**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105M**
MATERIAL DESCRIPTION: **12" x 12" White w/Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen Storage**

MATERIAL QUANTITY: **108**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **105M**
MATERIAL DESCRIPTION: **12" x 12" White w/Specks Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen Storage**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Window expansion caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Window expansion caulk**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **2' x 4' White (Wormy) Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 600, 601, and 606, throughout 6th floor classrooms, 5th floor classrooms,**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **2' x 4' White (Wormy) Ceiling Tile**
MATERIAL LOCATION: **Rooms 600, 601, and 606, throughout 6th floor classrooms, 5th floor classrooms,**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Brown baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Brown baseboard**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Brown baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Brown baseboard mastic**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Black baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 403 and 402**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Black baseboard**

MATERIAL LOCATION: **Room 403 and 402**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Black baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 402 & 403**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Black baseboard mastic**

MATERIAL LOCATION: **Classrooms 402 & 403**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Faculty Lunchroom, Library Room (500), Rooms 604 & 606, 105A, Faculty lounge, 1st FL Corridor by offices, 105 throughout,**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Carpet mastic**
MATERIAL LOCATION: **Faculty Lunchroom, Library Room (500), Rooms 604 & 606, 105A, Faculty lounge, 1st FL Corridor by offices, 105 throughout,**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Brown linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Under Lockers on the 1st, 2nd, 3rd, 4th, 5th & 6th Floor & Locker Alcoves 504A & 604A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Brown linoleum**
MATERIAL LOCATION: **Under Lockers on the 1st, 2nd, 3rd, 4th, 5th & 6th Floor & Locker Alcoves 504A & 604A**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Brown linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Under Lockers on the 1st, 2nd, 3rd, 4th, 5th & 6th Floor & Locker Alcoves 504A & 604A**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Brown linoleum mastic**
MATERIAL LOCATION: **Under Lockers on the 1st, 2nd, 3rd, 4th, 5th & 6th Floor & Locker Alcoves 504A & 604A**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**

MATERIAL LOCATION: **Throughout Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Exterior joint compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Exterior joint compound**

MATERIAL LOCATION: **Exterior of School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof, 6th Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**

MATERIAL LOCATION: **Roof, 6th Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Roof core - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof Above Rooms 600-608**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Roof core - Non-AHERA**

MATERIAL LOCATION: **Roof Above Rooms 600-608**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Insulation inside fire doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout School**
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Insulation inside fire doors**
MATERIAL LOCATION: **Throughout School**
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Vibration damper**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **7th Floor Mechanical Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Vibration damper**
MATERIAL LOCATION: **7th Floor Mechanical Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Above the 7th Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Roof flashing - Non-AHERA**

MATERIAL LOCATION: **Above the 7th Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Roof core - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Above the 7th Floor Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Roof core - Non-AHERA**

MATERIAL LOCATION: **Above the 7th Floor Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 601, 604, 603, 604A**

MATERIAL QUANTITY: **4500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **Rooms 601, 604, 603, 604A**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 600, 601, 608, 604, 605, 604A**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Linoleum mastic**
MATERIAL LOCATION: **Rooms 600, 601, 608, 604, 605, 604A**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/White & Brown Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 606**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/White & Brown Specks**
MATERIAL LOCATION: **Room 606**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/White & Brown Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 606**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/White & Brown Specks Mastic**
MATERIAL LOCATION: **Room 606**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Brown linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 601 - 606, 605**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Brown linoleum**

MATERIAL LOCATION: **Classrooms 601 - 606, 605**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Brown linoleum adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 601 - 606, 605**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Brown linoleum adhesive**
MATERIAL LOCATION: **Classrooms 601 - 606, 605**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Black Lab Counters and Sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 603 - 606**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Black Lab Counters and Sinks**
MATERIAL LOCATION: **Classrooms 603 - 606**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Black lab tables**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 604 - 606**
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Black lab tables**
MATERIAL LOCATION: **Classrooms 604 - 606**
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Fume hood interior materials**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms 601A, 604A, 605A**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Fume hood interior materials**
MATERIAL LOCATION: **Classrooms 601A, 604A, 605A**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Gray Lab Counters and Sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 601 - 602**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Gray Lab Counters and Sinks**
MATERIAL LOCATION: **Classrooms 601 - 602**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Gray lab tables**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 601 - 602**
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Gray lab tables**
MATERIAL LOCATION: **Classrooms 601 - 602**
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507 and 2, 3, 4, 5, 6,d, 400A, 301, 101, 103**
MATERIAL QUANTITY: **26750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage found in Rooms 403,405,302,304,206,600,501,502,503, 400A, 103 4SF,**

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Streaks Floor Tile**
MATERIAL LOCATION: **Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507 and 2, 3, 4, 5, 6,d, 400A, 301, 101, 103**
MATERIAL QUANTITY: **26750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **36** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507, 1,2, 3, 4, 5, 6 , 301, 101, 103**

MATERIAL QUANTITY: **26750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 203,204,205 - May be Under Carpet**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507, 1, 2, 3, 4, 5, 6, 301, 101, 103**
MATERIAL QUANTITY: **26750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507 and 1,2, 3, 4, 5, 6**
MATERIAL QUANTITY: **5152** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage found in Rooms 207, 504**

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile**
MATERIAL LOCATION: **Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507 and 1,2, 3, 4, 5, 6**
MATERIAL QUANTITY: **5152** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507, and 2, 3, 4, 5, 6**

MATERIAL QUANTITY: **5152**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile Mastic**
MATERIAL LOCATION: **Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507, and 2, 3, 4, 5, 6**
MATERIAL QUANTITY: **5152** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **12" x 12" Yellow Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rooms 203-205, 302, 303**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **12" x 12" Yellow Mix Floor Tile**
MATERIAL LOCATION: **Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" x 12" Yellow Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rooms 203-205, 302, 303**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" x 12" Yellow Mix Floor Tile Mastic**
MATERIAL LOCATION: **Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **221 Office**
MATERIAL QUANTITY: **16** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Streaks Floor Tile**
MATERIAL LOCATION: **221 Office**
MATERIAL QUANTITY: **16** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **221, 224, Office**
MATERIAL QUANTITY: **116** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Streaks Floor Tile Mastic**
MATERIAL LOCATION: **221, 224, Office**
MATERIAL QUANTITY: **116** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12" x 12" White w/Medium Brown Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium Exits by stairs, Cafe, Mgr. Off.**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12" x 12" White w/Medium Brown Specks Floor Tile**
MATERIAL LOCATION: **Auditorium Exits by stairs, Cafe.Mgr.Off.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12" x 12" White w/Medium Brown Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium Exits by stairs, Cafeteria/Foyer, Kitchen Corridor/Lwer Stairs, Perf. Arts Stairway, Cafe. Mgr. Off.**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12" x 12" White w/Medium Brown Specks Floor Tile Mastic**
MATERIAL LOCATION: **Auditorium Exits by stairs, Cafeteria/Foyer, Kitchen Corridor/Lwer Stairs, Perf. Arts Stairway, Cafe. Mgr. Off.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium and Stage, Kitchen Office**

MATERIAL QUANTITY: **2700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Specks Floor Tile**
MATERIAL LOCATION: **Auditorium and Stage, Kitchen Office**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium and Stage & Kitchen Office**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Specks Floor Tile Mastic**
MATERIAL LOCATION: **Auditorium and Stage & Kitchen Office**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor to PerfoRooming Arts Wing**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray Floor Tile**
MATERIAL LOCATION: **Corridor to PerfoRooming Arts Wing**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridor to Cafeteria, Stair Landings, Corridor to PerfoRooming Arts Wing**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray Floor Tile Mastic**
MATERIAL LOCATION: **Corridor to Cafeteria, Stair Landings, Corridor to PerfoRooming Arts Wing**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/Light Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, 105I, 105J**

MATERIAL QUANTITY: **1150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/Light Gray Floor Tile**
MATERIAL LOCATION: **Engineer's Office, 105I, 105J**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/Light Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, 105I, 105J**

MATERIAL QUANTITY: **1150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/Light Gray Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office, 105I, 105J**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Patches Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **As Patches in Cafeteria, Kitchen Storage and Elevators**

MATERIAL QUANTITY: **554** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Patches Floor Tile**
MATERIAL LOCATION: **As Patches in Cafeteria, Kitchen Storage and Elevators**
MATERIAL QUANTITY: **554** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Patches Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **As Patches in Cafeteria, Kitchen Storage and Elevators**

MATERIAL QUANTITY: **554** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Patches Floor Tile Mastic**
MATERIAL LOCATION: **As Patches in Cafeteria, Kitchen Storage and Elevators**
MATERIAL QUANTITY: **554** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **116** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **116** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **116** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **116** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **PerfoRooming Arts Foyer, 221 & Office, 224, Lecture Hall & Stage, Theater,**
MATERIAL QUANTITY: **6600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6600** DAMAGE UNITS: **SF**
COMMENTS: **Damage found in Rm. 224, Hall between Buildings, Lecture Hall**

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **5A**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Beige Floor Tile**
MATERIAL LOCATION: **PerfoRooming Arts Foyer, 221 & Office, 224, Lecture Hall & Stage, Theater,**
MATERIAL QUANTITY: **6600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **33** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5B**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridors Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **5B**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **Corridors Throughout**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5E**
MATERIAL DESCRIPTION: **12" x 12" White & Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 600**
MATERIAL QUANTITY: **990** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **5E**
MATERIAL DESCRIPTION: **12" x 12" White & Gray Floor Tile**
MATERIAL LOCATION: **Classrooms 600**
MATERIAL QUANTITY: **990** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Stair Landings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile**
MATERIAL LOCATION: **North Stair Landings**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **605A**
MATERIAL QUANTITY: **68** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
MATERIAL LOCATION: **605A**
MATERIAL QUANTITY: **68** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **605A**
MATERIAL QUANTITY: **68** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**
MATERIAL LOCATION: **605A**
MATERIAL QUANTITY: **68** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **4" Beige vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office Area and Classrooms 600, 604, 604A**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **4" Beige vinyl baseboard**
MATERIAL LOCATION: **Office Area and Classrooms 600, 604, 604A**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **4" Beige vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Office Area and Classrooms 600, 604, 604A**

MATERIAL QUANTITY: **950**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **4" Beige vinyl baseboard adhesive**
MATERIAL LOCATION: **Office Area and Classrooms 600, 604, 604A**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **4" Yellow vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 601, 602**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **4" Yellow vinyl baseboard**
MATERIAL LOCATION: **Classrooms 601, 602**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **4" Yellow vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 601, 602**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **4" Yellow vinyl baseboard adhesive**
MATERIAL LOCATION: **Classrooms 601, 602**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **4" Cream vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library, Classrooms & Offices 200-207, 214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500-507, 1, 2, 3, 4, 5 ,6, 301, 101, 103**

MATERIAL QUANTITY: **4100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **4" Cream vinyl baseboard**
MATERIAL LOCATION: **Library, Classrooms & Offices 200-207, 214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500-507, 1, 2, 3, 4, 5, 6, 301, 101, 103**
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **4" Cream vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library, Classrooms & Offices 200-207, 214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500-507, 1, 2, 3, 4, 5 ,6, 301, 101, 103**

MATERIAL QUANTITY: **4100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **4" Cream vinyl baseboard adhesive**
MATERIAL LOCATION: **Library, Classrooms & Offices 200-207, 214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500-507, 1, 2, 3, 4, 5, 6, 301, 101, 103**
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd-6th Floor Corridors, Classroom 404**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
MATERIAL LOCATION: **2nd-6th Floor Corridors, Classroom 404**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd-6th Floor Corridors, Classroom 404**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**
MATERIAL LOCATION: **2nd-6th Floor Corridors, Classroom 404**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Marker board adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 201, 301, 304-308, 401-407, 501-507, 601, 602, 604-606**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Marker board adhesive**
MATERIAL LOCATION: **Classrooms 201, 301, 304-308, 401-407, 501-507, 601, 602, 604-606**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Poster board adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms 201, 202, 204-207, 307, 308, 604, 605 and the 3rd and 6th Floor Corridors, 601, 602**

MATERIAL QUANTITY: **440**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Poster board adhesive**
MATERIAL LOCATION: **Classrooms 201, 202, 204-207, 307, 308, 604, 605 and the 3rd and 6th Floor Corridors, 601, 602**
MATERIAL QUANTITY: **440** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Stair treads**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rear Stairway**
MATERIAL QUANTITY: **630** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Stair treads**
MATERIAL LOCATION: **Rear Stairway**
MATERIAL QUANTITY: **630** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Stair tread adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rear Stairway**
MATERIAL QUANTITY: **630** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Stair tread adhesive**
MATERIAL LOCATION: **Rear Stairway**
MATERIAL QUANTITY: **630** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st - 6th Floor Classrooms, Library, Offices, Corridors**
MATERIAL QUANTITY: **87000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**
MATERIAL LOCATION: **1st - 6th Floor Classrooms, Library, Offices, Corridors**
MATERIAL QUANTITY: **87000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Gray rubber flooring adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Shipping/Receiving Dock**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Gray rubber flooring adhesive**
MATERIAL LOCATION: **Shipping/Receiving Dock**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **Gray carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classroom 404**
MATERIAL QUANTITY: **1144** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **Gray carpet adhesive**
MATERIAL LOCATION: **Classroom 404**
MATERIAL QUANTITY: **1144** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Brown/gray carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Offices, Library**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Brown/gray carpet adhesive**
MATERIAL LOCATION: **1st Floor Offices, Library**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st - 6th Floor Classrooms, Library, Offices, Corridors**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **1st - 6th Floor Classrooms, Library, Offices, Corridors**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **Drywall compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st - 6th Floor Classrooms, Library, Offices, Corridors**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **Drywall compound**
MATERIAL LOCATION: **1st - 6th Floor Classrooms, Library, Offices, Corridors**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Chalk board adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 201, 202, 204-207**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Chalk board adhesive**
MATERIAL LOCATION: **Classrooms 201, 202, 204-207**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd floor hall between 2 buildings near room 221**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**
COMMENTS: **2nd floor hall near room 224**

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **2nd floor hall between 2 buildings near room 221**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd floor hall between 2 buildings near room 221**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **2nd floor hall between 2 buildings near room 221**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Elbows on Fiberglass Pipe Runs**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **7th Floor Mechanical Room**

MATERIAL QUANTITY: **65**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Elbows on Fiberglass Pipe Runs**
MATERIAL LOCATION: **7th Floor Mechanical Room**
MATERIAL QUANTITY: **65** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Elbows on Fiberglass Pipe Runs**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout School**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Elbows on Fiberglass Pipe Runs**
MATERIAL LOCATION: **Throughout School**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Breeching duct insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room and Chiller Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Breeching duct insulation**

MATERIAL LOCATION: **Boiler Room and Chiller Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Tank insulation (tar paper)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room and Chiller Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Tank insulation (tar paper)**
MATERIAL LOCATION: **Boiler Room and Chiller Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Pipe insulation tar paper**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Pipe insulation tar paper**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **1' x 1' grooved splined White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Two floors of the building**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **1' x 1' grooved splined White Ceiling Tile**
MATERIAL LOCATION: **Two floors of the building**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-101**
MATERIAL DESCRIPTION: **Gray coating inder the Kitchen sink**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen and Office Area**

MATERIAL QUANTITY: **5**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **HA-101**
MATERIAL DESCRIPTION: **Gray coating inder the Kitchen sink**
MATERIAL LOCATION: **Kitchen and Office Area**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Boiler gasket insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Boiler gasket insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical Area by Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUIDLING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Tank insulation**

MATERIAL LOCATION: **Mechanical Area by Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **12" x 12" Gold w/ White Specks Floor Tile**

MATERIAL LOCATION: **Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217**

MATERIAL QUANTITY: **7333** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

COMMENTS:
Damage in 304, 305, 308

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12" x 12" Gold w/ White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217**
MATERIAL QUANTITY: **7333** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12" x 12" White w/ gray Specks Floor Tile**
MATERIAL LOCATION: **Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217**
MATERIAL QUANTITY: **7333** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **20** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in 304, 305, 308

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12" x 12" White w/ gray Specks Floor Tile**
MATERIAL LOCATION: **Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217**
MATERIAL QUANTITY: **7333** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **2' x 2' Rubber floor**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**

ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **2' x 2' Rubber floor**

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **Mastic Associated with 12" x 12" White w/ gray Specks, Gold w/ White Specks, gray w/ White Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217**

MATERIAL QUANTITY: **22000** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

COMMENTS:
Damage in 304, 305, 308

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **Mastic Associated with 12" x 12" White w/ gray Specks, Gold w/ White Specks, gray w/ White Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217**

MATERIAL QUANTITY: **22000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **Mastic Associated with 12" x 12" White w/ Blue Specks, Gray with black Specks, White with Gray Specks Floor Tile**

MATERIAL LOCATION: **Rooms 601, 602**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**

ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **Mastic Associated with 12" x 12" White w/ Blue Specks, Gray with black Specks, White with Gray Specks Floor Tile**

MATERIAL LOCATION: **Rooms 601, 602**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **12" x 12" White w/ gray Specks Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**

ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **118**

MATERIAL DESCRIPTION: **12" x 12" White w/ gray Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **2' x 2' Gray and Brown checkered carpet Mastic**
MATERIAL LOCATION: **Rooms 203/204/205**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **115**

MATERIAL DESCRIPTION: **2' x 2' Gray and Brown checkered carpet Mastic**

MATERIAL LOCATION: **Rooms 203/204/205**

MATERIAL QUANTITY: **2100**

MATERIAL UNITS:

SF

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12" x 12" White w/ gray Specks Vinyl Floor Tile**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**

ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **12" x 12" White w/ gray Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12" x 12" Gold w/ White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217**
MATERIAL QUANTITY: **7333** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **20** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in 304, 305, 308

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47021	BUILDING ID:	1060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jones Magnet High School	REVIEW DATE:	10/12/2022		
ADDRESS:	606 S. State	IDPH LICENSE NO:	100-05020		
HOMOGENEOUS AREA:	112				
MATERIAL DESCRIPTION:	12" x 12" Gold w/ White Specks Floor Tile				
MATERIAL LOCATION:	Rooms 501, 502, 503, 504, 505, 506, 507, 401, 402, 403, 405, 406, 407, 304, 305, 306, 307, 308, 200/201 203, 206, 207, 217				
MATERIAL QUANTITY:	7333	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	20	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content

Management Planner's Signature: _____



Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12" x 12" Gray with Black Specks Floor Tile**
MATERIAL LOCATION: **Rooms 601, 602**
MATERIAL QUANTITY: **533** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/23/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **12" x 12" Gray with Black Specks Floor Tile**

MATERIAL LOCATION: **Rooms 601, 602**

MATERIAL QUANTITY: **533**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12" x 12" White with Gray Specks Floor Tile**
MATERIAL LOCATION: **Rooms 601, 602**
MATERIAL QUANTITY: **533** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **12" x 12" White with Gray Specks Floor Tile**

MATERIAL LOCATION: **Rooms 601, 602**

MATERIAL QUANTITY: **533**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Jones Magnet High School** INSPECTION DATE: **9/23/2022**
ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Specks Floor Tile**
MATERIAL LOCATION: **Rooms 601, 602**
MATERIAL QUANTITY: **533** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/23/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47021** BUILDING ID: **1060**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Jones Magnet High School** REVIEW DATE: **10/12/2022**

ADDRESS: **606 S. State** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Specks Floor Tile**

MATERIAL LOCATION: **Rooms 601, 602**

MATERIAL QUANTITY: **533** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____




Date: **10/12/2022**

APPENDIX B

Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

Devon Jackson

has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/1/2022 - 3/3/2022

Exam Date: 3/3/2022




Expiration Date: 3/3/2023

Certificate Number: ABI2203030658

Kathy DeSalvo, Director

Devon Jackson

Illinois Licensed Building Inspector, Air Sampling Professional

 ILLINOIS DEPARTMENT OF PUBLIC HEALTH IDPH PROTECTING HEALTH. IMPROVING LIVES.	ASBESTOS PROFESSIONAL LICENSE	
ID NUMBER 100 - 05020	ISSUED 5/13/2022	EXPIRES 05/15/2023
DEVON A JACKSON 10657 SOUTH AVENUE D CHICAGO, IL 60617 Environmental Health		

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/3/2023
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	11/18/2022

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed