

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0029  
SCHOOL NAME: Marshall High School  
ADDRESS OF SCHOOL: 3250 W. Adams  
CITY: Chicago, IL, 60624

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/23/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** (Please type or print)

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 7/1/2022 ENROLLMENT 191  
IDPH INSPECTOR LICENSE NUMBER: 100-20411  
IDPH LICENSED INSPECTOR NAME (Please Print): Benyamen Maradkel  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



7/14/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Marshall High School**

3250 W. Adams  
Chicago, IL, 60624

Unit: 47041  
Building ID: 1470

IDPH ID Number: 14-016-2990-0029

**REPORT DATE:**

Thursday, July 14, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

07/14/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 47041            Region: 03            IDPH ID: 14-016-2990-0029

School: Marshall High School            Building ID: 1470

Address: 3250 W. Adams

Chicago, IL, 60624

Building Contact: Sell, David

Contact Phone: 7734260465

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/1/2022

Review Date: 07/14/2022

Inspector: Benyamen Maradkel

Inspector IDPH License: 100-20411

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: July 14, 2022

RE: Marshall High School, Unit 47041  
3250 W. Adams  
Chicago, IL, 60624

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Marshall High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Marshall High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Marshall High School Unit: 47041 Region: 03  
Address: 3250 W. Adams Chicago, IL, 60624  
IDPH ID: 14-016-2990-0029 Building ID: 1470  
Contact: Sell, David Phone: 7734260465

### 2. Description of Facility

Original Construction: 1916 Additional Construction: 1928  
Total Square Footage: 80659 No of Floors: 3  
Current Occupancy: 191

### 3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602


### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Benyamen Maradkel


Inspector IDPH license # 100-20411  
Reinspection Date: 7/1/2022

  
Signature:  
Date: 7/1/2022

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


  
Signature:  
Date: 07/14/2022

### 7. Review Date: 07/14/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 7/14/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Marshall High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1470:

105	12" x 12" White w/ Brown Specks Floor Tile
17	Insulation Inside of Vault Door
2	12" x 12" Dark Brown Floor Tile w/White & Blk Streaks
31	Aircell pipe insulation
33	Paperwrap pipe insulation
34	Hard Joint Compound on Paperwrap Pipe Insulation
35	Mag block pipe insulation
36	Mag block pipe joint insulation
37	Hard Joint Compound on Fiberglass Pipe Insulation

4	12" x 12" Black Floor Tile w/ Brown Streaks
54	12" x 12" Light Brown Floor Tile w/ Red & White Specks
61	Hard Joint Compound on Paperwrap Pipe Insulation
67	12" x 12" Light Brown Floor Tile w/ White & Red Streaks
78	12" x 12" Brown Floor Tile w/ White Streaks
82	Vault door liner
87	12" x 12" White Floor Tile w/ Gray Streaks
88	12" x 12" White Floor Tile w/ Gray Streaks Mastic
89	12" x 12" Gray Mix Floor Tile
9 M	Orange linoleum mastic
90	12" x 12" Gray Mix Floor Tile Mastic
91	12" x 12" White Floor Tile w/ Gray Streaks
92	12" x 12" White Floor Tile w/ Gray Streaks Mastic
95	2' x 4' White Ceiling Tile
98	Red stage curtain



B. The following new homogenous areas have been identified for Building 1470:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10 M	Brown linoleum mastic
100	Beige linoleum
101	Beige linoleum adhesive
102	Gray and Tan Terrazzo
103	Red 12" x 12" Floor Tile
104	Red 12" x 12" Floor Tile Mastic
105	12" x 12" White w/ Brown Specks Floor Tile
106	12" x 12" White w/ Brown Specks Floor Tile Mastic
107	12" x 12" Light Brown Floor Tile
108	12" x 12" Light Brown Floor Tile Mastic
109	Light blue linoleum
11	9" x 9" Green Floor Tile w/ White Specks
110	Light blue linoleum mastic
111	Textured gray linoleum
112	Textured gray linoleum mastic
113	12" x 12" Charcoal Floor Tile
114	12" x 12" Charcoal Floor Tile Mastic
115	12" x 12" Brown Mottled Floor Tile
116	12" x 12" Brown Mottled Floor Tile Mastic
17	Insulation Inside of Vault Door
18	Carpet mastic
18 A	Purple & white mix carpet mastic
18 B	Orange carpet mastic
18 C	Blue w/Brown Carpet w/Mastic
18 D	Blue carpet mastic
18 F	Lavender carpet mastic
18 G	Black and Green Carpet Mastic
18 H	Blue patterned carpet mastic
18 I	Blue mix carpet mastic
18 J	Gray carpet mastic
18 K	Brown mix carpet mastic
21	Roofing material - Non-AHERA
26	9" x 9" Light Green Floor Tile Mastic
4	12" x 12" Black Floor Tile w/ Brown Streaks
53	12" x 12" Dark Brown Floor Tile w/ White & Blk Spks
54	12" x 12" Light Brown Floor Tile w/ Red & White Specks
65	12" x 12" Olive Floor Tile w/ Brown & White Specks Mastic
66	12" x 12" White Floor Tile w/ Brown & Gray Streaks

67	12" x 12" Light Brown Floor Tile w/White & Red Streaks
7	12" x 12" Gray Floor Tile w/Brown & White Streaks
7M	12" x 12" Gray Floor Tile w/ Brown & White Streaks Mastic
8	12" x 12" Light Brown Floor Tile w/Red & White Streaks Mastic
82	Vault door liner
83	12" x 12" Gray Floor Tile w/ Brown Specks
84	12" x 12" Gray Floor Tile w/Brown Specks Mastic
85	12" x 12" Beige Mix Floor Tile
86	12" x 12" Beige Mix Floor Tile Mastic
87	12" x 12" White Floor Tile w/ Gray Streaks
88	12" x 12" White Floor Tile w/ Gray Streaks Mastic
89	12" x 12" Gray Mix Floor Tile
9 M	Orange linoleum mastic
90	12" x 12" Gray Mix Floor Tile Mastic
91	12" x 12" White Floor Tile w/Gray Streaks
92	12" x 12" White Floor Tile w/ Gray Streaks Mastic
93	12" x 12" Pink/Purple Speckled Floor Tile
94	12" x 12" Pink/Purple Speckled Floor Tile Mastic
95	2' x 4' White Ceiling Tile
96	4" Brown vinyl baseboard
97	4" Brown vinyl baseboard adhesive
98	Red stage curtain
99	Orange carpet adhesive
A	Blue linoleum flooring
A-1	Blue linoleum flooring-mastic
B	12" x 12" Vinyl Floor Tile Blue
B-1	12" x 12" Vinyl Floor Tile Blue-MASTIC

The following areas were deemed to be inaccessible:

101	Beige linoleum adhesive
104	Red 12" x 12" Floor Tile Mastic
106	12" x 12" White w/ Brown Specks Floor Tile Mastic
108	12" x 12" Light Brown Floor Tile Mastic
110	Light blue linoleum mastic
112	Textured gray linoleum mastic
114	12" x 12" Charcoal Floor Tile Mastic
116	12" x 12" Brown Mottled Floor Tile Mastic
17	Insulation Inside of Vault Door
18	Carpet mastic
18 A	Purple & white mix carpet mastic
18 C	Blue w/Brown Carpet w/Mastic

18 D	Blue carpet mastic
18 F	Lavender carpet mastic
18 G	Black and Green Carpet Mastic
18 K	Brown mix carpet mastic
23	9" x 9" Green Floor Tile w/ White Specks Mastic
2M	12" x 12" Dark Brown Floor Tile w/ White & Blk Streaks Mastic
79	12" x 12" Brown Floor Tile w/ White Streaks Mastic
8	12" x 12" Light Brown Floor Tile w/Red & White Streaks Mastic
82	Vault door liner
84	12" x 12" Gray Floor Tile w/Brown Specks Mastic
86	12" x 12" Beige Mix Floor Tile Mastic
88	12" x 12" White Floor Tile w/ Gray Streaks Mastic
9 M	Orange linoleum mastic
90	12" x 12" Gray Mix Floor Tile Mastic
92	12" x 12" White Floor Tile w/ Gray Streaks Mastic
A-1	Blue linoleum flooring-mastic
B-1	12" x 12" Vinyl Floor Tile Blue-MASTIC

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Benyamen Maradkel, IDPH License # 100-20411. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Marshall High School Building 1470 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470

Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
10	Dark brown linoleum			Room 125-1	NO_ACBM	MISC								
10 M	Brown linoleum mastic			Room 125-1	ASSUMED	MISC								
100	Beige linoleum	750	SF	Room 323	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
101	Beige linoleum adhesive	750	SF	Room 323	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
102	Gray and Tan Terrazzo	41,000	SF	Hallway borders, Lunchroom, Stairwells	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
103	Red 12" x 12" Floor Tile	2,700	SF	Room 124, Gym PE Storage, Auditorium	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
104	Red 12" x 12" Floor Tile Mastic	2,700	SF	Room 124, Gym PE Storage, Auditorium	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
105	12" x 12" White w/ Brown Specks Floor Tile	6,200	SF	Rooms 212, 214, 216, 325, 337, 341, 347, 353A	ASSUMED	MISC	N	LOC	4	SF	Yes	ACBM with the potential for damage	3	LOW
106	12" x 12" White w/ Brown Specks Floor Tile Mastic	6,200	SF	Rooms 212,214,216,325,337,341,347,353A	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
107	12" x 12" Light Brown Floor Tile	2,500	SF	2nd and 3rd Floor SW Hallways	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
108	12" x 12" Light Brown Floor Tile Mastic	2,500	SF	2nd and 3rd Floor SW Hallways	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
109	Light blue linoleum	2,750	SF	Rooms 151,312,316	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
11	9" x 9" Green Floor Tile w/ White Specks			Rooms 127 and 125	ASSUMED	MISC								
110	Light blue linoleum mastic	2,750	SF	Rooms 151,312,316	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
111	Textured gray linoleum	1,500	SF	Room 147	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
112	Textured gray linoleum mastic	1,500	SF	Room 147	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
113	12" x 12" Charcoal Floor Tile	150	SF	Gym Office(Small)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
114	12" x 12" Charcoal Floor Tile Mastic	150	SF	Gym Office(Small)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
115	12" x 12" Brown Mottled Floor Tile	700	SF	Auditorium Storage, Rooms 257,258,357,358,457,458, 321, gym office 235-2	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
116	12" x 12" Brown Mottled Floor Tile Mastic	700	SF	Auditorium Storage, Rooms 257,258,357,358,457,458, 321, gym office 235-2	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470

Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				7,458.gym office 235-2										
12	9" x 9" Red Floor Tile - ABATED			Room 151	ABATED	MISC								
12 M	9" x 9" Red Floor Tile Mastic - ABATED			151	ABATED	MISC								
13	2' x 4' Pitted Lay In Ceiling Panels			Throughout Corridors and Classrooms	NO_ACBM	MISC								
14	2' x 4' White Wormed Lay In Ceiling Panels			Lunchroom, 124, 2nd Floor Corridor, 247, 249, 354	NO_ACBM	MISC								
15	Exterior brick - Non-AHERA			Exterior of Building	NO_ACBM	MISC								
16	Exterior brick mortar - Non-AHERA			Exterior of Building	NO_ACBM	MISC								
17	Insulation Inside of Vault Door	24	SF	Rooms 125	ASSUMED	TSI	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
18	Carpet mastic	8,000	SF	Throughout Building	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
18 A	Purple & white mix carpet mastic	2,100	SF	Room 130, 229, 225, 227	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
18 B	Orange carpet mastic			Room 228	ASSUMED	MISC								
18 C	Blue w/Brown Carpet w/Mastic	700	SF	Room 237	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
18 D	Blue carpet mastic	1,000	SF	Room 137 and Assistant Principal's Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
18 E	Red carpet mastic			Rooms 124 and 127	NO_ACBM	MISC								
18 F	Lavender carpet mastic	700	SF	Room 125	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
18 G	Black and Green Carpet Mastic	700	SF	Principal's Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
18 H	Blue patterned carpet mastic			Room 126	ASSUMED	MISC								
18 I	Blue mix carpet mastic			Conference Room, auditorium	ASSUMED	MISC								
18 J	Gray carpet mastic			Room 136	ASSUMED	MISC								
18 K	Brown mix carpet mastic	100	SF	Infant Toddler Center	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
19	Black science lab tables	186	SF	Rooms 212, 214	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
2	12" x 12" Dark Brown Floor Tile w/White & Blk Streaks	400	SF	Rooms 210, 325, 344, 346, 347	CHR	MISC	N	LOC	10	SF	Yes	ACBM with the potential for damage	3	LOW
20	Gray boiler rope gaskets		LF	Boiler Interiors	CHR	TSI				LF				
21	Roofing material - Non-AHERA			Roof	ASSUMED	MISC								
23	9" x 9" Green Floor Tile w/ White Specks	1,100	SF	Room 127 Office	CHR	MISC	N	NONE	0	SF	No	ACBM with the		LOW



# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470

Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Mastic			Closet and Possibly Under the Carpet in Room 125 & Room 125 closet.								potential for damage		
24	Fire door lining			Door #9	INACCESSIBLE	TSI								
25	9" x 9" Tan Floor Tile w/ Brown & Beige Streaks Mastic			126 and 330 (Teacher's Lounge)	CHR	MISC								
26	9" x 9" Light Green Floor Tile Mastic			Rooms 127, Office Closet & Possibly Under the Carpet in 125 & Room 125 closet	ASSUMED	MISC								
27	Black table tops			Room 344, 327, and 323	NO_ACBM	MISC								
28	Gray exhaust hood lining			Room 327	NO_ACBM	MISC								
29	2' x 5' Thin Black Transite Table Tops - REMOVED			Room 323	ABATED	MISC								
2M	12" x 12" Dark Brown Floor Tile w/ White & Blk Streaks Mastic	769	SF	Rooms 210, 325, 341, 344, 346, 347	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
3	Black asphalt flooring			Stairways	NO_ACBM	MISC								
30	1.5' x 1.5' Gray Steam Table Boards			Open Basement Area	NO_ACBM	MISC								
31	Aircell pipe insulation	24	LF	Outside Gym, Possibly in inaccessible areas of the building	CHR	TSI	Y	LOC	3	LF	Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
32	Hard Joint Compound on Aircell Pipe Insulation			Possibly in Inaccessible Areas of the Building	AMO	TSI								
33	Paperwrap pipe insulation	210	LF	Possibly in inaccessible areas of the building	CHR	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
34	Hard Joint Compound on Paperwrap Pipe Insulation	150	LF	Throughout Basement	CHR	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
35	Mag block pipe insulation	5,000	LF	Engine Room, Air Tunnel 3 & 8	CHR	TSI	Y	DIST	10	LF	Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
36	Mag block pipe joint insulation	120	LF	Engine Room, Air Tunnel 3 & 8	CHR	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
37	Hard Joint Compound on Fiberglass Pipe	180	FITTING	Engine Room, Air	AMO	TSI	Y	NONE	0	FITTING	Yes	Any remaining friable		LOW

# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470

Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Insulation			Tunnels 3 & 8								ACBM or friable suspect ACBM		
38	Plaster walls			Throughout 1918 Building	NO_ACBM	SURFACE								
39	Plaster ceilings			Throughout 1918 Building	NO_ACBM	SURFACE								
4	12" x 12" Black Floor Tile w/ Brown Streaks	6,284	SF	Rooms 132, 134, 143,145, 230 (Women's Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Floor Bathroom	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
40	White boiler rope gasket			Boilers	NO_ACBM	MISC								
41	Gray transite counter tops - abated			Rooms 244, 246, 248, 344, 346, and 348	ABATED	MISC								
42	Mag type boiler gasket			Boiler Room	CHR	TSI								
43	Leather like boiler gaskets			Boiler Room	CHR	TSI								
44	Mineral wool boiler insulation			Boiler Room	NO_ACBM	TSI								
45	Water tank insulation - abated			Basement	ABATED	MISC								
46	Water tank insulation - abated			Basement	ABATED	MISC								
47	Aircell duct insulation		SF	Crawlspace 3	CHR	TSI				SF				
48	Brown vinyl stage curtain			Stage	NO_ACBM	MISC								
49	2' x 4' Brown Ceiling Panels			Corridor 9	NO_ACBM	MISC								
4M	12" x 12" Black Floor Tile w/ Brown Streaks Mastic			Rooms 132, 134, 143,145, 230 (Women's Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Flr RR	CHR	MISC								
5	9" x 9" Tan Floor Tile w/ Brown & Beige Streaks		SF	Rooms 126, 1st floor corridor	CHR	MISC				SF				
50	2' x 5' Black Transite Table Tops	5,000	SF	Rooms 244, 246, 248, 344, 346, 348, 321, 325, and 327	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
51	Gray transite table tops			Room 214	CHR	MISC								
52	2' x 4' White Pitted Ceiling Panels			Rooms 109, 110, 118, 310, 312, 314, and 320, 1st & 3rd Floor Corridors	NO_ACBM	MISC								
53	12" x 12" Dark Brown Floor Tile w/ White & Blk Spks	3,000	SF	Room 314, Engineer's Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470

Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
54	12" x 12" Light Brown Floor Tile w/Red & White Specks	65,000	SF	Corridors, Rooms 109, 220 and 320	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
55	Ceiling plaster			Throughout 1898 Building	NO_ACBM	SURFACE								
56	Plaster walls			Throughout 1898 Building	NO_ACBM	SURFACE								
57	Gypsum rock lath			Girl's Gyms and Balconies	NO_ACBM	MISC								
58	Aircell pipe insulation	120	LF	Gym 12	CHR	TSI	Y	NONE	0	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
59	Hard Joint Compound on Aircell Pipe Insulation	25	LF	Gym 12	CHR	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
6	Reddish brown linoleum			Rooms 223, 225, and 229	NO_ACBM	MISC								
60	Paperwrap pipe insulation	70	LF	Boiler Room	CHR	TSI	Y	NONE	0	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM		MODERATE
61	Hard Joint Compound on Paperwrap Pipe Insulation	25	LF	Boiler Room	CHR	TSI	Y	NONE	0	LF	Yes	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
62	Mag block pipe insulation			Boiler Room, Gym 12, Auditorium	CHR	TSI								
63	Mag block joint insulation			Boiler Room, Gym 12, Auditorium	CHR	TSI								
64	Hard Joint Compound on Fiberglass Pipe Insulation	15	LF	Boiler Room and throughout basement	CHR	TSI	Y	NONE	0	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM		MODERATE
65	12" x 12" Olive Floor Tile w/Brown & White Specks Mastic		SF	Room 130	ASSUMED	MISC				SF				
66	12" x 12" White Floor Tile w/ Brown & Gray Streaks		SF	Room 130	ASSUMED	MISC				SF				
67	12" x 12" Light Brown Floor Tile w/White & Red Streaks	2,504	SF	Room 147	ASSUMED	MISC	N	DIST	25	SF	Yes	ACBM with the potential for damage	5	LOW
68	1' x 1' White Wormed & Pitted Ceiling Tile			Room 144 and Boy's Gym, 227-229	NO_ACBM	MISC								
69	1' x 1' Beige Grooved Ceiling Tile			Girl's Gym, Room 333	NO_ACBM	MISC								
7	12" x 12" Gray Floor Tile w/Brown &		SF	Room 235	ASSUMED	MISC				SF				

# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470

Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	White Streaks													
70	2' x 4' White Wormed Lay In Ceiling Panels			Room 227 and Library	NO_ACBM	MISC								
71	1' x 1' White Pitted Ceiling Tile			Rooms 132, 134, 225, and 229, 2nd Floor Between Girl's & Boy's Gym	NO_ACBM	MISC								
72	2' x 4' White Pinhole Lay In Ceiling Panels			Room 140	NO_ACBM	MISC								
73	Orange fabric stage curtain			Stage	NO_ACBM	MISC								
74	4" Black vinyl baseboard			Throughout Building	NO_ACBM	MISC								
75	4" Black vinyl baseboard mastic			Throughout Building	NO_ACBM	MISC								
76	Tar paper under floor tile			Room 330	NO_ACBM	MISC								
77	Tar paper mastic under floor tile			Room 330	NO_ACBM	MISC								
78	12" x 12" Brown Floor Tile w/ White Streaks	400	SF	Room 341 Storage	CHR	MISC	N	LOC	100	SF	Yes	ACBM with potential for significant damage	5	LOW
79	12" x 12" Brown Floor Tile w/ White Streaks Mastic	400	SF	Room 341 Storage	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
7M	12" x 12" Gray Floor Tile w/ Brown & White Streaks Mastic			Room 235	ASSUMED	MISC								
8	12" x 12" Light Brown Floor Tile w/Red & White Streaks Mastic	65,000	SF	Corridors, Rooms 109, 220 and 320	ASSUMED	MISC	N	DIST	38	SF	No	ACBM with the potential for damage	5	LOW
80	9" x 9" Beige Floor Tile			Room 246	CHR	MISC								
81	9" x 9" Beige Floor Tile Mastic			Room 246	CHR	MISC								
82	Vault door liner	24	SF	Rooms 125	ASSUMED	TSI	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
83	12" x 12" Gray Floor Tile w/ Brown Specks	700	SF	Room 125	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
84	12" x 12" Gray Floor Tile w/Brown Specks Mastic	700	SF	Room 125	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
85	12" x 12" Beige Mix Floor Tile	900	SF	Room 130, 124 (office/closet), 127,132,134	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
86	12" x 12" Beige Mix Floor Tile Mastic	900	SF	Room 130, 124 (office/closet), 127,132,134	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
87	12" x 12" White Floor Tile w/ Gray Streaks	1,664	SF	Room 132 & 134 womens faculty restroom (254)	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
88	12" x 12" White Floor Tile w/ Gray Streaks Mastic	1,664	SF	Room 132 & 134, womens faculty restroom (254)	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW

# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470

Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
89	12" x 12" Gray Mix Floor Tile	1,500	SF	Room 143	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with the potential for damage	5	LOW
9	Orange linoleum			Room 101	NO_ACBM	MISC								
9 M	Orange linoleum mastic	500	SF	Room 101	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
90	12" x 12" Gray Mix Floor Tile Mastic	1,500	SF	Room 143	ASSUMED	MISC	N	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
91	12" x 12" White Floor Tile w/Gray Streaks	500	SF	Infant/Toddler Center	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
92	12" x 12" White Floor Tile w/ Gray Streaks Mastic	500	SF	Infant/Toddler Center	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
93	12" x 12" Pink/Purple Speckled Floor Tile			Classrooms 147 & 151	ASSUMED	MISC								
94	12" x 12" Pink/Purple Speckled Floor Tile Mastic			Classrooms 147 151	ASSUMED	MISC								
95	2' x 4' White Ceiling Tile	1,500	SF	Classrooms 147 & 151	ASSUMED	MISC	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
96	4" Brown vinyl baseboard		SF	Classrooms 147 & 151	ASSUMED	MISC				SF				
97	4" Brown vinyl baseboard adhesive		SF	Classrooms 147 & 151	ASSUMED	MISC				SF				
98	Red stage curtain	1,000	SF	Auditorium	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
99	Orange carpet adhesive			Auditorium and Room 228	ASSUMED	MISC								
A	Blue linoleum flooring	4,347	SF	ROOMS 147, 327, 344, 348, 314, 246 (PREP), 244	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
A-1	Blue linoleum flooring-mastic	4,347	SF	ROOMS 147, 327, 344, 348, 314, 246 (prep), 244	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
B	12" x 12" Vinyl Floor Tile Blue	1,200	SF	Rooms 354, 230 (teachers Lounge) & 330(Teachers Lounge), Mens 3rd Floor Bathroom, Room 246 Prep.	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
B-1	12" x 12" Vinyl Floor Tile Blue-MASTIC	1,200	SF	Rooms 354, 230 (teachers Lounge) & 330(Teachers Lounge), Mens 3rd Floor Bathroom,	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470  
Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates  
600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>7/1/2022</b>
Inspector Name <b><u>Benyamen Maradkel</u></b>
<b>100-20411</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
10	
10 M	Not Observed 2022
100	
101	
102	
103	Gym storage inaccessible
104	Gym storage inaccessible
105	Damage in Room 347 - 2022
106	
107	
108	
109	Not observed in Room 316
11	Not Observed 2022
110	Not observed in Room 316
111	
112	
113	
114	
115	
116	
12	
12 M	
13	
14	

# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470

Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
15	
16	
17	125 inaccessible due to abatement
18	
18 A	
18 B	Not observed 2022 - Could be present under wood floor
18 C	
18 D	Principals office inaccessible
18 E	
18 F	125 inaccessible due to abatement
18 G	Principals office inaccessible
18 H	Not observed 2022
18 I	Not Observed 2022
18 J	Not observed 2022 - Room inaccessible
18 K	
19	No tables in Room 343
2	Damage is located in Room 341, not observed in rooms 325, 344
20	Not observed 2022
21	
23	Not observed in Room 127, Room 125 inaccessible due to abatement
24	Not Observed 2022
25	Not observed 2022
26	Not Observed 2022
27	
28	
29	
2M	Not observed in Rooms 325, 341, 344
3	
30	



# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470

Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
31	Damaged outside gym 12
32	Not observed 2022
33	
34	
35	Damage in air tunnels
36	
37	
38	
39	
4	Not observed in Rooms 310, 244,246, 254, 132,134,143
40	
41	
42	Not VISIBLE 2022
43	Not VISIBLE 2022
44	
45	
46	
47	Not observed 2022 - Inaccessible
48	
49	
4M	Not visible 310, men 3rd Flr restroom 2022, 244, 246, 254, 132, 134,143
5	Not observed 2022
50	
51	Not observed 2022
52	
53	
54	
55	
56	

# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470

Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
57	
58	
59	
6	
60	
61	
62	
63	Not Observed 2022
64	
65	Not observed 2022
66	Not observed 2022
67	Not observed in Room 147, Damage is located in corridors 1, 2, and 3
68	
69	
7	Not observed - wood
70	
71	
72	
73	
74	
75	
76	
77	
78	Damage in Room 341 storage closet
79	
7M	Not observed 2022
8	Damaged outside room 318 and room 250
80	Not visible 2022
81	Not visible 2022

# Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470

Address 3250 W. Adams Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
82	125 inaccessible due to abatement
83	125 inaccessible due to abatement
84	125 inaccessible due to abatement
85	
86	
87	
88	
89	Damage in Room 143
9	
9 M	Inaccessible 2022
90	
91	
92	
93	Not Observed 2022
94	Not Observed 2022
95	
96	Not observed 2022
97	Not observed 2022
98	
99	Not Observed 2022
A	
A-1	
B	Not observed in Rooms 246, 354
B-1	

# Chicago Public Schools

**School** Marshall High School **Unit** 47041 **Building ID** 1470

**Address** 3250 W. Adams **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
10	Dark brown linoleum			Room 125-1	No ACBM	MISC					
10 M	Brown linoleum mastic			Room 125-1	Assumed	MISC					Follow O&M Plan
100	Beige linoleum	750	SF	Room 323	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	Beige linoleum adhesive	750	SF	Room 323	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	Gray and Tan Terrazzo	41,000	SF	Hallway borders, Lunchroom, Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Red 12" x 12" Floor Tile	2,700	SF	Room 124, Gym PE Storage, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	Red 12" x 12" Floor Tile Mastic	2,700	SF	Room 124, Gym PE Storage, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" White w/ Brown Specks Floor Tile	6,200	SF	Rooms 212, 214, 216, 325, 337, 341, 347, 353A	Assumed	MISC	No	4	SF	6 ACBM with the potential for damage	Repair
106	12" x 12" White w/ Brown Specks Floor Tile Mastic	6,200	SF	Rooms 212,214,216,325,337,341,347,353A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12" x 12" Light Brown Floor Tile	2,500	SF	2nd and 3rd Floor SW Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12" x 12" Light Brown Floor Tile Mastic	2,500	SF	2nd and 3rd Floor SW Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	Light blue linoleum	2,750	SF	Rooms 151,312,316	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	9" x 9" Green Floor Tile w/ White Specks			Rooms 127 and 125	Assumed	MISC					Follow O&M Plan
110	Light blue linoleum mastic	2,750	SF	Rooms 151,312,316	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	Textured gray linoleum	1,500	SF	Room 147	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	Textured gray linoleum mastic	1,500	SF	Room 147	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12" x 12" Charcoal Floor Tile	150	SF	Gym Office(Small)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12" x 12" Charcoal Floor Tile Mastic	150	SF	Gym Office(Small)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	12" x 12" Brown Mottled Floor Tile	700	SF	Auditorium Storage, Rooms 257,258,357,358,457,458, 321, gym office 235-2	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	12" x 12" Brown Mottled Floor Tile Mastic	700	SF	Auditorium Storage, Rooms 257,258,357,358,457,458.gym office 235-2	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9" x 9" Red Floor Tile - ABATED			Room 151	Abated	MISC					
12 M	9" x 9" Red Floor Tile Mastic - ABATED			151	Abated	MISC					
13	2' x 4' Pitted Lay In Ceiling Panels			Throughout Corridors and Classrooms	No ACBM	MISC					
14	2' x 4' White Wormed Lay In Ceiling Panels			Lunchroom, 124, 2nd Floor Corridor, 247, 249, 354	No ACBM	MISC					
15	Exterior brick - Non-AHERA			Exterior of Building	No ACBM	MISC					
16	Exterior brick mortar - Non-AHERA			Exterior of Building	No ACBM	MISC					

# Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
17	Insulation Inside of Vault Door	24	SF	Rooms 125	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
18	Carpet mastic	8,000	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18 A	Purple & white mix carpet mastic	2,100	SF	Room 130, 229, 225, 227	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18 B	Orange carpet mastic			Room 228	Assumed	MISC					Follow O&M Plan
18 C	Blue w/Brown Carpet w/Mastic	700	SF	Room 237	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18 D	Blue carpet mastic	1,000	SF	Room 137 and Assistant Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18 E	Red carpet mastic			Rooms 124 and 127	No ACBM	MISC					
18 F	Lavender carpet mastic	700	SF	Room 125	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18 G	Black and Green Carpet Mastic	700	SF	Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18 H	Blue patterned carpet mastic			Room 126	Assumed	MISC					Follow O&M Plan
18 I	Blue mix carpet mastic			Conference Room, auditorium	Assumed	MISC					Follow O&M Plan
18 J	Gray carpet mastic			Room 136	Assumed	MISC					Follow O&M Plan
18 K	Brown mix carpet mastic	100	SF	Infant Toddler Center	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Black science lab tables	186	SF	Rooms 212, 214	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2	12" x 12" Dark Brown Floor Tile w/White & Blk Streaks	400	SF	Rooms 210, 325, 344, 346, 347	Chrysotile	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
20	Gray boiler rope gaskets		LF	Boiler Interiors	Chrysotile	TSI			LF		Follow O&M Plan
21	Roofing material - Non-AHERA			Roof	Assumed	MISC					Follow O&M Plan
23	9" x 9" Green Floor Tile w/ White Specks Mastic	1,100	SF	Room 127 Office Closet and Possibly Under the Carpet in Room 125 & Room 125 closet.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Fire door lining			Door #9	Inaccessibl e	TSI					Follow O&M Plan
25	9" x 9" Tan Floor Tile w/ Brown & Beige Streaks Mastic			126 and 330 (Teacher's Lounge)	Chrysotile	MISC					Follow O&M Plan
26	9" x 9" Light Green Floor Tile Mastic			Rooms 127, Office Closet & Possibly Under the Carpet in 125 & Room 125 closet	Assumed	MISC					Follow O&M Plan
27	Black table tops			Room 344, 327, and 323	No ACBM	MISC					
28	Gray exhaust hood lining			Room 327	No ACBM	MISC					
29	2' x 5' Thin Black Transite Table Tops - REMOVED			Room 323	Abated	MISC					
2M	12" x 12" Dark Brown Floor Tile w/ White & Blk Streaks Mastic	769	SF	Rooms 210, 325, 341, 344, 346, 347	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
3	Black asphalt flooring			Stairways	No ACBM	MISC					
30	1.5' x 1.5' Gray Steam Table Boards			Open Basement Area	No ACBM	MISC					
31	Aircell pipe insulation	24	LF	Outside Gym, Possibly in inaccessible areas of the building	Chrysotile	TSI	Yes	3	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
32	Hard Joint Compound on Aircell Pipe Insulation			Possibly in Inaccessible Areas of the Building	Amosite	TSI					Follow O&M Plan
33	Paperwrap pipe insulation	210	LF	Possibly in inaccessible areas of the building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
34	Hard Joint Compound on Paperwrap Pipe Insulation	150	LF	Throughout Basement	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
35	Mag block pipe insulation	5,000	LF	Engine Room, Air Tunnel 3 & 8	Chrysotile	TSI	Yes	10	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Encapsulate
36	Mag block pipe joint insulation	120	LF	Engine Room, Air Tunnel 3 & 8	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
37	Hard Joint Compound on Fiberglass Pipe Insulation	180	FITTING	Engine Room, Air Tunnels 3 & 8	Amosite	TSI	Yes	0	FITTING	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
38	Plaster walls			Throughout 1918 Building	No ACBM	SURFACE					
39	Plaster ceilings			Throughout 1918 Building	No ACBM	SURFACE					
4	12" x 12" Black Floor Tile w/ Brown Streaks	6,284	SF	Rooms 132, 134, 143,145, 230 (Women's Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Floor Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	White boiler rope gasket			Boilers	No ACBM	MISC					
41	Gray transite counter tops - abated			Rooms 244, 246, 248, 344, 346, and 348	Abated	MISC					
42	Mag type boiler gasket			Boiler Room	Chrysotile	TSI					Follow O&M Plan
43	Leather like boiler gaskets			Boiler Room	Chrysotile	TSI					Follow O&M Plan
44	Mineral wool boiler insulation			Boiler Room	No ACBM	TSI					
45	Water tank insulation - abated			Basement	Abated	MISC					
46	Water tank insulation - abated			Basement	Abated	MISC					
47	Aircell duct insulation		SF	Crawlspace 3	Chrysotile	TSI			SF		Follow O&M Plan
48	Brown vinyl stage curtain			Stage	No ACBM	MISC					
49	2' x 4' Brown Ceiling Panels			Corridor 9	No ACBM	MISC					
4M	12" x 12" Black Floor Tile w/ Brown Streaks Mastic			Rooms 132, 134, 143,145, 230 (Women's Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Flr RR	Chrysotile	MISC					Follow O&M Plan



# Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
5	9" x 9" Tan Floor Tile w/ Brown & Beige Streaks		SF	Rooms 126, 1st floor corridor	Chrysotile	MISC			SF		Follow O&M Plan
50	2' x 5' Black Transite Table Tops	5,000	SF	Rooms 244, 246, 248, 344, 346, 348, 321, 325, and 327	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Gray transite table tops			Room 214	Chrysotile	MISC					Follow O&M Plan
52	2' x 4' White Pitted Ceiling Panels			Rooms 109, 110, 118, 310, 312, 314, and 320, 1st & 3rd Floor Corridors	No ACBM	MISC					
53	12" x 12" Dark Brown Floor Tile w/ White & Blk Spks	3,000	SF	Room 314, Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" Light Brown Floor Tile w/ Red & White Specks	65,000	SF	Corridors, Rooms 109, 220 and 320	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Ceiling plaster			Throughout 1898 Building	No ACBM	SURFACE					
56	Plaster walls			Throughout 1898 Building	No ACBM	SURFACE					
57	Gypsum rock lath			Girl's Gyms and Balconies	No ACBM	MISC					
58	Aircell pipe insulation	120	LF	Gym 12	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
59	Hard Joint Compound on Aircell Pipe Insulation	25	LF	Gym 12	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
6	Reddish brown linoleum			Rooms 223, 225, and 229	No ACBM	MISC					
60	Paperwrap pipe insulation	70	LF	Boiler Room	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
61	Hard Joint Compound on Paperwrap Pipe Insulation	25	LF	Boiler Room	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
62	Mag block pipe insulation			Boiler Room, Gym 12, Auditorium	Chrysotile	TSI					Follow O&M Plan
63	Mag block joint insulation			Boiler Room, Gym 12, Auditorium	Chrysotile	TSI					Follow O&M Plan
64	Hard Joint Compound on Fiberglass Pipe Insulation	15	LF	Boiler Room and throughout basement	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
65	12" x 12" Olive Floor Tile w/ Brown & White Specks Mastic		SF	Room 130	Assumed	MISC			SF		Follow O&M Plan
66	12" x 12" White Floor Tile w/ Brown & Gray Streaks		SF	Room 130	Assumed	MISC			SF		Follow O&M Plan
67	12" x 12" Light Brown Floor Tile w/ White & Red Streaks	2,504	SF	Room 147	Assumed	MISC	No	25	SF	6 ACBM with the potential for damage	Repair
68	1' x 1' White Wormed & Pitted Ceiling Tile			Room 144 and Boy's Gym, 227-229	No ACBM	MISC					
69	1' x 1' Beige Grooved Ceiling Tile			Girl's Gym, Room 333	No ACBM	MISC					
7	12" x 12" Gray Floor Tile w/ Brown & White Streaks		SF	Room 235	Assumed	MISC			SF		Follow O&M Plan
70	2' x 4' White Wormed Lay In Ceiling Panels			Room 227 and Library	No ACBM	MISC					
71	1' x 1' White Pitted Ceiling Tile			Rooms 132, 134, 225, and 229, 2nd	No ACBM	MISC					

# Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Floor Between Girl's & Boy's Gym							
72	2' x 4' White Pinhole Lay In Ceiling Panels			Room 140	No ACBM	MISC					
73	Orange fabric stage curtain			Stage	No ACBM	MISC					
74	4" Black vinyl baseboard			Throughout Building	No ACBM	MISC					
75	4" Black vinyl baseboard mastic			Throughout Building	No ACBM	MISC					
76	Tar paper under floor tile			Room 330	No ACBM	MISC					
77	Tar paper mastic under floor tile			Room 330	No ACBM	MISC					
78	12" x 12" Brown Floor Tile w/ White Streaks	400	SF	Room 341 Storage	Chrysotile	MISC	No	100	SF	5 ACBM with potential for significant damage	Repair
79	12" x 12" Brown Floor Tile w/ White Streaks Mastic	400	SF	Room 341 Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7M	12" x 12" Gray Floor Tile w/ Brown & White Streaks Mastic			Room 235	Assumed	MISC					Follow O&M Plan
8	12" x 12" Light Brown Floor Tile w/Red & White Streaks Mastic	65,000	SF	Corridors, Rooms 109, 220 and 320	Assumed	MISC	No	38	SF	6 ACBM with the potential for damage	Repair
80	9" x 9" Beige Floor Tile			Room 246	Chrysotile	MISC					Follow O&M Plan
81	9" x 9" Beige Floor Tile Mastic			Room 246	Chrysotile	MISC					Follow O&M Plan
82	Vault door liner	24	SF	Rooms 125	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
83	12" x 12" Gray Floor Tile w/ Brown Specks	700	SF	Room 125	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12" x 12" Gray Floor Tile w/Brown Specks Mastic	700	SF	Room 125	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12" x 12" Beige Mix Floor Tile	900	SF	Room 130, 124 (office/closet), 127,132,134	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" Beige Mix Floor Tile Mastic	900	SF	Room 130, 124 (office/closet), 127,132,134	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12" x 12" White Floor Tile w/ Gray Streaks	1,664	SF	Room 132 & 134 womens faculty restroom (254)	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
88	12" x 12" White Floor Tile w/ Gray Streaks Mastic	1,664	SF	Room 132 & 134, womens faculty restroom (254)	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
89	12" x 12" Gray Mix Floor Tile	1,500	SF	Room 143	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Repair
9	Orange linoleum			Room 101	No ACBM	MISC					
9 M	Orange linoleum mastic	500	SF	Room 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12" x 12" Gray Mix Floor Tile Mastic	1,500	SF	Room 143	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
91	12" x 12" White Floor Tile w/Gray Streaks	500	SF	Infant/Toddler Center	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12" x 12" White Floor Tile w/ Gray Streaks Mastic	500	SF	Infant/Toddler Center	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
93	12" x 12" Pink/Purple Speckled Floor Tile			Classrooms 147 & 151	Assumed	MISC					Follow O&M Plan
94	12" x 12" Pink/Purple Speckled Floor Tile Mastic			Classrooms 147 151	Assumed	MISC					Follow O&M Plan
95	2' x 4' White Ceiling Tile	1,500	SF	Classrooms 147 & 151	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
96	4" Brown vinyl baseboard		SF	Classrooms 147 & 151	Assumed	MISC			SF		Follow O&M Plan
97	4" Brown vinyl baseboard adhesive		SF	Classrooms 147 & 151	Assumed	MISC			SF		Follow O&M Plan
98	Red stage curtain	1,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	Orange carpet adhesive			Auditorium and Room 228	Assumed	MISC					Follow O&M Plan
A	Blue linoleum flooring	4,347	SF	ROOMS 147, 327, 344, 348, 314, 246 (PREP), 244	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-1	Blue linoleum flooring-mastic	4,347	SF	ROOMS 147, 327, 344, 348, 314, 246 (prep), 244	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	12" x 12" Vinyl Floor Tile Blue	1,200	SF	Rooms 354, 230(teachers Lounge) & 330(Teachers Lounge), Mens 3rd Floor Bathroom, Room 246 Prep.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B-1	12" x 12" Vinyl Floor Tile Blue-MASTIC	1,200	SF	Rooms 354, 230(teachers Lounge) & 330(Teachers Lounge), Mens 3rd Floor Bathroom, Room 246 Prep.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Marshall High School

**Unit** 47041

**Building ID** 1470

**Address** 3250 W. Adams

Chicago, IL, 60624

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	7/14/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
10	
10 M	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
11	
110	
111	
112	
113	
114	
115	
116	

# Chicago Public Schools

**School** Marshall High School  
**Address** 3250 W. Adams

**Unit** 47041  
 Chicago, IL, 60624

**Building ID** 1470  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
12	
12 M	
13	
14	
15	
16	
17	
18	
18 A	
18 B	
18 C	
18 D	
18 E	
18 F	
18 G	
18 H	
18 I	
18 J	
18 K	
19	
2	
20	
21	
23	
24	
25	
26	

# Chicago Public Schools

**School** Marshall High School  
**Address** 3250 W. Adams

**Unit** 47041  
Chicago, IL, 60624

**Building ID** 1470  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
27	
28	
29	
2M	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
4M	

# Chicago Public Schools

**School** Marshall High School  
**Address** 3250 W. Adams

**Unit** 47041  
Chicago, IL, 60624

**Building ID** 1470  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
5	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	

# Chicago Public Schools

**School** Marshall High School  
**Address** 3250 W. Adams

**Unit** 47041  
Chicago, IL, 60624

**Building ID** 1470  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
74	
75	
76	
77	
78	
79	
7M	
8	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
9	
9 M	
90	
91	
92	
93	
94	
95	
96	



# Chicago Public Schools

**School** Marshall High School  
**Address** 3250 W. Adams

**Unit** 47041  
Chicago, IL, 60624

**Building ID** 1470  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
97	
98	
99	
A	
A-1	
B	
B-1	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

Carnow, Conibear and Associates

*2022 AHERA REINSPECTION*

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Dark brown linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 125-1**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Dark brown linoleum**

MATERIAL LOCATION: **Room 125-1**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10 M**  
MATERIAL DESCRIPTION: **Brown linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 125-1**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **10 M**

MATERIAL DESCRIPTION: **Brown linoleum mastic**

MATERIAL LOCATION: **Room 125-1**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Beige linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 323**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Beige linoleum**  
MATERIAL LOCATION: **Room 323**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **Beige linoleum adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 323**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **Beige linoleum adhesive**  
MATERIAL LOCATION: **Room 323**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **Gray and Tan Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallway borders, Lunchroom, Stairwells**

MATERIAL QUANTITY: **41000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **Gray and Tan Terrazzo**  
MATERIAL LOCATION: **Hallway borders, Lunchroom, Stairwells**  
MATERIAL QUANTITY: **41000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Red 12" x 12" Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 124, Gym PE Storage, Auditorium**

MATERIAL QUANTITY: **2700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Gym storage inaccessible**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Red 12" x 12" Floor Tile**  
MATERIAL LOCATION: **Room 124, Gym PE Storage, Auditorium**  
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **Red 12" x 12" Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 124, Gym PE Storage, Auditorium**

MATERIAL QUANTITY: **2700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Gym storage inaccessible**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **Red 12" x 12" Floor Tile Mastic**  
MATERIAL LOCATION: **Room 124, Gym PE Storage, Auditorium**  
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 212, 214, 216, 325, 337, 341, 347, 353A**  
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **6200** DAMAGE UNITS: **SF**  
COMMENTS: **Damage in Room 347 - 2022**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile**  
MATERIAL LOCATION: **Rooms 212, 214, 216, 325, 337, 341, 347, 353A**  
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 212,214,216,325,337,341,347,353A**  
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 212,214,216,325,337,341,347,353A**  
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd and 3rd Floor SW Hallways**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**  
MATERIAL LOCATION: **2nd and 3rd Floor SW Hallways**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd and 3rd Floor SW Hallways**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**  
MATERIAL LOCATION: **2nd and 3rd Floor SW Hallways**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **Light blue linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 151,312,316**  
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not observed in Room 316**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **Light blue linoleum**  
MATERIAL LOCATION: **Rooms 151,312,316**  
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/ White Specks**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 127 and 125**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/ White Specks**

MATERIAL LOCATION: **Rooms 127 and 125**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Light blue linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 151,312,316**  
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not observed in Room 316**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Light blue linoleum mastic**  
MATERIAL LOCATION: **Rooms 151,312,316**  
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Textured gray linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 147**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Textured gray linoleum**  
MATERIAL LOCATION: **Room 147**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **Textured gray linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 147**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **Textured gray linoleum mastic**  
MATERIAL LOCATION: **Room 147**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12" x 12" Charcoal Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Office(Small)**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12" x 12" Charcoal Floor Tile**  
MATERIAL LOCATION: **Gym Office(Small)**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **12" x 12" Charcoal Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Office(Small)**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **12" x 12" Charcoal Floor Tile Mastic**  
MATERIAL LOCATION: **Gym Office(Small)**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **12" x 12" Brown Mottled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium Storage, Rooms 257,258,357,358,457,458, 321, gym office 235-2**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **12" x 12" Brown Mottled Floor Tile**  
MATERIAL LOCATION: **Auditorium Storage, Rooms 257,258,357,358,457,458, 321, gym office 235-2**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **12" x 12" Brown Mottled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium Storage, Rooms 257,258,357,358,457,458.gym office 235-2**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **12" x 12" Brown Mottled Floor Tile Mastic**  
MATERIAL LOCATION: **Auditorium Storage, Rooms 257,258,357,358,457,458.gym office 235-2**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 151**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile - ABATED**

MATERIAL LOCATION: **Room 151**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12 M**  
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **151**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **12 M**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **151**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **2' x 4' Pitted Lay In Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Corridors and Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **2' x 4' Pitted Lay In Ceiling Panels**

MATERIAL LOCATION: **Throughout Corridors and Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **2' x 4' White Wormed Lay In Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, 124, 2nd Floor Corridor, 247, 249, 354**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **2' x 4' White Wormed Lay In Ceiling Panels**

MATERIAL LOCATION: **Lunchroom, 124, 2nd Floor Corridor, 247, 249, 354**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Exterior brick - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Exterior brick mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Insulation Inside of Vault Door**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 125**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **125 inaccessible due to abatement**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Insulation Inside of Vault Door**

MATERIAL LOCATION: **Rooms 125**

MATERIAL QUANTITY: **24**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Carpet mastic**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47041**    BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School**    INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams**    IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 A**  
MATERIAL DESCRIPTION: **Purple & white mix carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 130, 229, 225, 227**  
MATERIAL QUANTITY: **2100**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18 A**  
MATERIAL DESCRIPTION: **Purple & white mix carpet mastic**  
MATERIAL LOCATION: **Room 130, 229, 225, 227**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 B**  
MATERIAL DESCRIPTION: **Orange carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 228**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022 - Could be present under wood floor**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18 B**

MATERIAL DESCRIPTION: **Orange carpet mastic**

MATERIAL LOCATION: **Room 228**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 C**  
MATERIAL DESCRIPTION: **Blue w/Brown Carpet w/Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 237**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18 C**

MATERIAL DESCRIPTION: **Blue w/Brown Carpet w/Mastic**

MATERIAL LOCATION: **Room 237**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 D**  
MATERIAL DESCRIPTION: **Blue carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 137 and Assistant Principal's Office**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Principals office inaccessible**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18 D**  
MATERIAL DESCRIPTION: **Blue carpet mastic**  
MATERIAL LOCATION: **Room 137 and Assistant Principal's Office**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 E**  
MATERIAL DESCRIPTION: **Red carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 124 and 127**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18 E**

MATERIAL DESCRIPTION: **Red carpet mastic**

MATERIAL LOCATION: **Rooms 124 and 127**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 F**  
MATERIAL DESCRIPTION: **Lavender carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 125**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **125 inaccessible due to abatement**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18 F**  
MATERIAL DESCRIPTION: **Lavender carpet mastic**  
MATERIAL LOCATION: **Room 125**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 G**  
MATERIAL DESCRIPTION: **Black and Green Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Principals office inaccessible**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18 G**

MATERIAL DESCRIPTION: **Black and Green Carpet Mastic**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 H**  
MATERIAL DESCRIPTION: **Blue patterned carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 126**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18 H**

MATERIAL DESCRIPTION: **Blue patterned carpet mastic**

MATERIAL LOCATION: **Room 126**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 I**  
MATERIAL DESCRIPTION: **Blue mix carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Conference Room, auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18 I**  
MATERIAL DESCRIPTION: **Blue mix carpet mastic**  
MATERIAL LOCATION: **Conference Room, auditorium**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 J**  
MATERIAL DESCRIPTION: **Gray carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022 - Room inaccessible**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18 J**

MATERIAL DESCRIPTION: **Gray carpet mastic**

MATERIAL LOCATION: **Room 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 K**  
MATERIAL DESCRIPTION: **Brown mix carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Infant Toddler Center**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18 K**  
MATERIAL DESCRIPTION: **Brown mix carpet mastic**  
MATERIAL LOCATION: **Infant Toddler Center**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Black science lab tables**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 212, 214**  
MATERIAL QUANTITY: **186** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **No tables in Room 343**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Black science lab tables**  
MATERIAL LOCATION: **Rooms 212, 214**  
MATERIAL QUANTITY: **186** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile w/White & Blk Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 210, 325, 344, 346, 347**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **400** DAMAGE UNITS: **SF**  
COMMENTS: **Damage is located in Room 341, not observed in rooms 325, 344**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile w/White & Blk Streaks**  
MATERIAL LOCATION: **Rooms 210, 325, 344, 346, 347**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Gray boiler rope gaskets**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Interiors**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Gray boiler rope gaskets**

MATERIAL LOCATION: **Boiler Interiors**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Roofing material - Non-AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/ White Specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 127 Office Closet and Possibly Under the Carpet in Room 125 & Room 125 closet.**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 127, Room 125 inaccessible due to abatement**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/ White Specks Mastic**  
MATERIAL LOCATION: **Room 127 Office Closet and Possibly Under the Carpet in Room 125 & Room 125 closet.**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Fire door lining**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Inaccessible** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Door #9**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Fire door lining**

MATERIAL LOCATION: **Door #9**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/ Brown & Beige Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **126 and 330 (Teacher's Lounge)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/ Brown & Beige Streaks Mastic**

MATERIAL LOCATION: **126 and 330 (Teacher's Lounge)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **9" x 9" Light Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 127, Office Closet & Possibly Under the Carpet in 125 & Room 125 closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **9" x 9" Light Green Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 127, Office Closet & Possibly Under the Carpet in 125 & Room 125 closet**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Black table tops**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 344, 327, and 323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Black table tops**

MATERIAL LOCATION: **Room 344, 327, and 323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Gray exhaust hood lining**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 327**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Gray exhaust hood lining**

MATERIAL LOCATION: **Room 327**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **2' x 5' Thin Black Transite Table Tops - REMOVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **2' x 5' Thin Black Transite Table Tops - REMOVED**

MATERIAL LOCATION: **Room 323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2M**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile w/ White & Blk Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 210, 325, 341, 344, 346, 347**

MATERIAL QUANTITY: **769**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rooms 325, 341, 344**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **2M**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile w/ White & Blk Streaks Mastic**  
MATERIAL LOCATION: **Rooms 210, 325, 341, 344, 346, 347**  
MATERIAL QUANTITY: **769** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**  
MATERIAL DESCRIPTION: **Black asphalt flooring**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stairways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Black asphalt flooring**

MATERIAL LOCATION: **Stairways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **1.5' x 1.5' Gray Steam Table Boards**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Open Basement Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **1.5' x 1.5' Gray Steam Table Boards**

MATERIAL LOCATION: **Open Basement Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Outside Gym, Possibly in inaccessible areas of the building**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **24** DAMAGE UNITS: **LF**  
COMMENTS: **Damaged outside gym 12**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
MATERIAL LOCATION: **Outside Gym, Possibly in inaccessible areas of the building**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **3** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Amosite** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Possibly in Inaccessible Areas of the Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**

MATERIAL LOCATION: **Possibly in Inaccessible Areas of the Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Possibly in inaccessible areas of the building**  
MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**  
MATERIAL LOCATION: **Possibly in inaccessible areas of the building**  
MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Basement**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Hard Joint Compound on Paperwrap Pipe Insulation**

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Mag block pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engine Room, Air Tunnel 3 & 8**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS: **Damage in air tunnels**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Mag block pipe insulation**  
MATERIAL LOCATION: **Engine Room, Air Tunnel 3 & 8**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Mag block pipe joint insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engine Room, Air Tunnel 3 & 8**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Mag block pipe joint insulation**

MATERIAL LOCATION: **Engine Room, Air Tunnel 3 & 8**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engine Room, Air Tunnels 3 & 8**  
MATERIAL QUANTITY: **180** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Engine Room, Air Tunnels 3 & 8**

MATERIAL QUANTITY: **180**

MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Plaster walls**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Plaster walls**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Plaster ceilings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Plaster ceilings**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/ Brown Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 132, 134, 143,145, 230 (Women's Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Floor Bathroom**

MATERIAL QUANTITY: **6284**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rooms 310, 244,246, 254, 132,134,143**

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **4**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/ Brown Streaks**  
MATERIAL LOCATION: **Rooms 132, 134, 143,145, 230 (Women's Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Floor Bathroom**  
MATERIAL QUANTITY: **6284** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **White boiler rope gasket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boilers**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **White boiler rope gasket**

MATERIAL LOCATION: **Boilers**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Gray transite counter tops - abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 244, 246, 248, 344, 346, and 348**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Gray transite counter tops - abated**

MATERIAL LOCATION: **Rooms 244, 246, 248, 344, 346, and 348**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Mag type boiler gasket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not VISIBLE 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Mag type boiler gasket**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Leather like boiler gaskets**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not VISIBLE 2022**

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Leather like boiler gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Mineral wool boiler insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Mineral wool boiler insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Water tank insulation - abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Water tank insulation - abated**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Water tank insulation - abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Water tank insulation - abated**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Aircell duct insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Crawlspace 3**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022 - Inaccessible**

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Aircell duct insulation**

MATERIAL LOCATION: **Crawlspace 3**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Brown vinyl stage curtain**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Brown vinyl stage curtain**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **2' x 4' Brown Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridor 9**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **2' x 4' Brown Ceiling Panels**

MATERIAL LOCATION: **Corridor 9**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4M**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/ Brown Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 132, 134, 143,145, 230 (Women's Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Flr RR**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not visible 310, men 3rd Flr restroom 2022, 244, 246, 254, 132, 134,143**

Inspector's Signature: 

Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **4M**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/ Brown Streaks Mastic**  
MATERIAL LOCATION: **Rooms 132, 134, 143,145, 230 (Women's Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Flr RR**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/ Brown & Beige Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage  
Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 126, 1st floor corridor**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/ Brown & Beige Streaks**

MATERIAL LOCATION: **Rooms 126, 1st floor corridor**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **2' x 5' Black Transite Table Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 244, 246, 248, 344, 346, 348, 321, 325, and 327**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **2' x 5' Black Transite Table Tops**  
MATERIAL LOCATION: **Rooms 244, 246, 248, 344, 346, 348, 321, 325, and 327**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Gray transite table tops**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 214**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Gray transite table tops**

MATERIAL LOCATION: **Room 214**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **2' x 4' White Pitted Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 109, 110, 118, 310, 312, 314, and 320, 1st & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **2' x 4' White Pitted Ceiling Panels**

MATERIAL LOCATION: **Rooms 109, 110, 118, 310, 312, 314, and 320, 1st & 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile w/ White & Blk Spks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 314, Engineer's Office**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile w/ White & Blk Spks**  
MATERIAL LOCATION: **Room 314, Engineer's Office**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Red & White Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridors, Rooms 109, 220 and 320**

MATERIAL QUANTITY: **65000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Red & White Specks**  
MATERIAL LOCATION: **Corridors, Rooms 109, 220 and 320**  
MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Ceiling plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1898 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Ceiling plaster**

MATERIAL LOCATION: **Throughout 1898 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Plaster walls**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1898 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Plaster walls**

MATERIAL LOCATION: **Throughout 1898 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Gypsum rock lath**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girl's Gyms and Balconies**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Gypsum rock lath**

MATERIAL LOCATION: **Girl's Gyms and Balconies**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym 12**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Aircell pipe insulation**

MATERIAL LOCATION: **Gym 12**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym 12**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**

MATERIAL LOCATION: **Gym 12**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**  
MATERIAL DESCRIPTION: **Reddish brown linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 223, 225, and 229**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Reddish brown linoleum**

MATERIAL LOCATION: **Rooms 223, 225, and 229**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **70**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Paperwrap pipe insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **70**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Hard Joint Compound on Paperwrap Pipe Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Mag block pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room, Gym 12, Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Mag block pipe insulation**

MATERIAL LOCATION: **Boiler Room, Gym 12, Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **Mag block joint insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room, Gym 12, Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Mag block joint insulation**

MATERIAL LOCATION: **Boiler Room, Gym 12, Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage Deterioration**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boiler Room and throughout basement**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

---



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room and throughout basement**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12" x12" Olive Floor Tile w/Brown & White Specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x12" Olive Floor Tile w/Brown & White Specks Mastic**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Brown & Gray Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Brown & Gray Streaks**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/White & Red Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 147**  
MATERIAL QUANTITY: **2504** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2504** DAMAGE UNITS: **SF**  
COMMENTS: **Not observed in Room 147, Damage is located in corridors 1, 2, and 3**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/White & Red Streaks**  
MATERIAL LOCATION: **Room 147**  
MATERIAL QUANTITY: **2504** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **1' x 1' White Wormed & Pitted Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 144 and Boy's Gym, 227-229**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **1' x 1' White Wormed & Pitted Ceiling Tile**

MATERIAL LOCATION: **Room 144 and Boy's Gym, 227-229**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **1' x 1' Beige Grooved Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girl's Gym, Room 333**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **1' x 1' Beige Grooved Ceiling Tile**

MATERIAL LOCATION: **Girl's Gym, Room 333**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Brown & White Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 235**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed - wood**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Brown & White Streaks**

MATERIAL LOCATION: **Room 235**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **2' x 4' White Wormed Lay In Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 227 and Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **2' x 4' White Wormed Lay In Ceiling Panels**

MATERIAL LOCATION: **Room 227 and Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **1' x 1' White Pitted Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 132, 134, 225, and 229, 2nd Floor Between Girl's & Boy's Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **1' x 1' White Pitted Ceiling Tile**

MATERIAL LOCATION: **Rooms 132, 134, 225, and 229, 2nd Floor Between Girl's & Boy's Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **2' x 4' White Pinhole Lay In Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 140**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **2' x 4' White Pinhole Lay In Ceiling Panels**

MATERIAL LOCATION: **Room 140**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **Orange fabric stage curtain**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Stage**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Orange fabric stage curtain**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **4" Black vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **4" Black vinyl baseboard**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **4" Black vinyl baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **4" Black vinyl baseboard mastic**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **Tar paper under floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 330**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Tar paper under floor tile**

MATERIAL LOCATION: **Room 330**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Tar paper mastic under floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 330**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Tar paper mastic under floor tile**

MATERIAL LOCATION: **Room 330**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ White Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage  
Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 341 Storage**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS: **Damage in Room 341 storage closet**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ White Streaks**

MATERIAL LOCATION: **Room 341 Storage**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **100**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ White Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 341 Storage**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ White Streaks Mastic**  
MATERIAL LOCATION: **Room 341 Storage**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7M**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Brown & White Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 235**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **7M**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Brown & White Streaks Mastic**

MATERIAL LOCATION: **Room 235**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Red & White Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridors, Rooms 109, 220 and 320**  
MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damaged outside room 318 and room 250**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/Red & White Streaks Mastic**  
MATERIAL LOCATION: **Corridors, Rooms 109, 220 and 320**  
MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **38** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 246**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not visible 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**

MATERIAL LOCATION: **Room 246**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 246**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not visible 2022**

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 246**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **Vault door liner**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 125**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **125 inaccessible due to abatement**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **Vault door liner**

MATERIAL LOCATION: **Rooms 125**

MATERIAL QUANTITY: **24**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Brown Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 125**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **125 inaccessible due to abatement**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Brown Specks**  
MATERIAL LOCATION: **Room 125**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Brown Specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 125**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **125 inaccessible due to abatement**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Brown Specks Mastic**  
MATERIAL LOCATION: **Room 125**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 130, 124 (office/closet), 127,132,134**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**  
MATERIAL LOCATION: **Room 130, 124 (office/closet), 127,132,134**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 130, 124 (office/closet),127,132,134**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**  
MATERIAL LOCATION: **Room 130, 124 (office/closet),127,132,134**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 132 & 134 womens faculty restroom (254)**

MATERIAL QUANTITY: **1664**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Streaks**  
MATERIAL LOCATION: **Room 132 & 134 womens faculty restroom (254)**  
MATERIAL QUANTITY: **1664** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 132 & 134, womens faculty restroom (254)**

MATERIAL QUANTITY: **1664**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Streaks Mastic**  
MATERIAL LOCATION: **Room 132 & 134, womens faculty restroom (254)**  
MATERIAL QUANTITY: **1664** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 143**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1500** DAMAGE UNITS: **SF**  
COMMENTS: **Damage in Room 143**

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**  
MATERIAL LOCATION: **Room 143**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **Orange linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Orange linoleum**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9 M**  
MATERIAL DESCRIPTION: **Orange linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 101**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Inaccessible 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **9 M**  
MATERIAL DESCRIPTION: **Orange linoleum mastic**  
MATERIAL LOCATION: **Room 101**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 143**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic**  
MATERIAL LOCATION: **Room 143**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Infant/Toddler Center**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks**

MATERIAL LOCATION: **Infant/Toddler Center**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Infant/Toddler Center**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Streaks Mastic**

MATERIAL LOCATION: **Infant/Toddler Center**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **12" x 12" Pink/Purple Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 147 & 151**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12" x 12" Pink/Purple Speckled Floor Tile**

MATERIAL LOCATION: **Classrooms 147 & 151**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **12" x 12" Pink/Purple Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 147 151**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **12" x 12" Pink/Purple Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms 147 151**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **2' x 4' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms 147 & 151**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **2' x 4' White Ceiling Tile**  
MATERIAL LOCATION: **Classrooms 147 & 151**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 147 & 151**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**

MATERIAL LOCATION: **Classrooms 147 & 151**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 147 & 151**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**

MATERIAL LOCATION: **Classrooms 147 & 151**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **Red stage curtain**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **Red stage curtain**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **Orange carpet adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium and Room 228**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **Orange carpet adhesive**

MATERIAL LOCATION: **Auditorium and Room 228**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Blue linoleum flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ROOMS 147, 327, 344, 348, 314, 246 (PREP), 244**  
MATERIAL QUANTITY: **4347** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Blue linoleum flooring**  
MATERIAL LOCATION: **ROOMS 147, 327, 344, 348, 314, 246 (PREP), 244**  
MATERIAL QUANTITY: **4347** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-1**  
MATERIAL DESCRIPTION: **Blue linoleum flooring-mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ROOMS 147, 327, 344, 348, 314, 246 (prep), 244**  
MATERIAL QUANTITY: **4347** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/01/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **A-1**  
MATERIAL DESCRIPTION: **Blue linoleum flooring-mastic**  
MATERIAL LOCATION: **ROOMS 147, 327, 344, 348, 314, 246 (prep), 244**  
MATERIAL QUANTITY: **4347** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile Blue**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 354, 230(teachers Lounge) & 330(Teachers Lounge), Mens 3rd Floor Bathroom, Room 246 Prep.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rooms 246, 354**

Inspector's Signature:



Date: **07/01/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile Blue**  
MATERIAL LOCATION: **Rooms 354, 230(teachers Lounge) & 330(Teachers Lounge), Mens 3rd Floor Bathroom, Room 246 Prep.**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Marshall High School** INSPECTION DATE: **7/1/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B-1**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile Blue-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 354, 230(teachers Lounge) & 330(Teachers Lounge), Mens 3rd Floor Bathroom, Room 246 Prep.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/01/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/14/2022**  
ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **B-1**  
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile Blue-MASTIC**  
MATERIAL LOCATION: **Rooms 354, 230(teachers Lounge) & 330(Teachers Lounge), Mens 3rd Floor Bathroom, Room 246 Prep.**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

*2022 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---

# Benyamen Maradkel

Illinois Licensed Building Inspector



**ASBESTOS  
PROFESSIONAL  
LICENSE**

**ID NUMBER**  
**100 - 20411**

**ISSUED**  
**3/17/2022**

**EXPIRES**  
**05/15/2023**

**BENYAMEN C MARADKEL**  
**706 W HACKBERRY DR**  
**ARLINGTON HEIGHTS, IL 6000**  
Environmental Health



**ENDORSEMENTS**

INSPECTOR

**EXPIRES**

5/9/2023

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Benyamen Maradkel**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090703

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519

  
Kathy DeSalvo, Director



# ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

**100 - 19466**

ISSUED

**4/22/2022**

EXPIRES

**05/15/2023**

**EVAN I CHRISTIAN**  
**1119 N HOYNE AVE, APT 1**  
**CHICAGO, IL 60622**

Environmental Health



## ENDORSEMENTS

## TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER

3/28/2023

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**

This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.





OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed