

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0037
SCHOOL NAME: Senn Academy
ADDRESS OF SCHOOL: 5900 N. Glenwood
CITY: Chicago, IL, 60660

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **10/10/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/10/2022 ENROLLMENT 1500
IDPH INSPECTOR LICENSE NUMBER: 100-20616
IDPH LICENSED INSPECTOR NAME (Please Print): Antonio Munoz IV
IDPH MP LICENSE NUMBER: 100-04019
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



10/3/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Senn Academy

5900 N. Glenwood
Chicago, IL, 60660

Unit: 47061
Building ID: 1540

IDPH ID Number: 14-016-2990-0037

REPORT DATE:

Monday, October 03, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Specialty Consulting, Inc.

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

10/03/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 47061 Region: 01 IDPH ID: 14-016-2990-0037

School: Senn Academy Building ID: 1540

Address: 5900 N. Glenwood

Chicago, IL, 60660

Building Contact: Montanez, Raymond

Contact Phone: 7737096752

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/10/2022

Review Date: 10/03/2022

Inspector: Antonio Munoz IV

Inspector IDPH License: 100-20616

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Arturo Saenz
100-04019

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 03, 2022

RE: Senn Academy, Unit 47061
5900 N. Glenwood
Chicago, IL, 60660

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Senn Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Senn Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Senn Academy
Address: 5900 N. Glenwood
IDPH ID: 14-016-2990-0037
Contact: Montanez, Raymond

Unit: 47061
Chicago, IL, 60660
Building ID: 1540
Phone: 7737096752

Region: 01

2. Description of Facility

Original Construction: 1930
Total Square Footage: 37798
Current Occupancy: 1500

Additional Construction: 1913,1930
No of Floors: 3

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant


MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575

Fax: (312) 319-7580

5. Inspector

Inspector Name: Antonio Munoz IV


Inspector IDPH license # 100-20616
Reinspection Date: 9/10/2022

Signature: 
Date: 9/10/2022

6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019

Signature: 
Date: 10/03/2022

7. Review Date: 10/03/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/3/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Senn Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1540:

B. The following new homogenous areas have been identified for Building 1540:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

- 104 12" x 12" Light Green w/ White Streaks VFT (Not Observed)
- 105 12" x 12" Light Green w/ White Streaks VFT Mastic (Not Observed)
- 106 12" x 12" Beige w/ Dark & White Streaks VFT
- 127 12" x 12" White w/Beige Streaks VFT - Not Observed
- 127 A 12" x 12" White w/Beige Streaks VFT Mastic
- 128 12" x 12" White w/Blue Streaks VFT
- 128 A 12" x 12" White w/Blue Streaks VFT Mastic
- 133 Lt Blue Speckled Linoleum- NOT OBSERVED
- 134 Lt Blue Speckled Linoleum Mastic- NOT OBSERVED
- 135 12" x 12" White w/ Gold Specks VFT (Not Observed)
- 136 12" x 12" White w/ Gold Specks VFT Mastic (Not Observed)
- 137 2' x 4' White Pin-Hole Ceiling Tile
- 138 12" x 12" White w/ Beige VFT
- 139 12" x 12" White w/ Beige VFT Mastic
- 140 12" x 12" Light Gray VFT
- 141 12" x 12" Light Gray VFT Mastic
- 142 12" x 12" Light Blue VFT
- 143 12" x 12" Light Blue VFT Mastic
- 144 12" x 12" Green VFT (Not Observed)
- 145 12" x 12" Green VFT Mastic (Not Observed)
- 146 12" x 12" White VFT (Not Observed)
- 147 12" x 12" White VFT Mastic (Not Observed)
- 148 Linoleum, Gray w/Gray Streaks
- 148M Linoleum, Gray w/Gray Streaks Mastic
- 149 Linoleum, Blue Solid
- 149M Linoleum, Blue Solid Mastic
- 150 12" x 12" VFT- NOT OBSERVED
- 150M 12" x 12" VFT Mastic - NOT OBSERVED
- 151 12" x 12" Solid Gray VFT
- 151M 12" x 12" Solid Gray VFT Mastic
- 152 12" x 12" Tan w/Brown Speckles VFT (Not Observed)
- 152M 12" x 12" Tan w/Brown Speckles VFT Mastic (Not Observed)
- 153 12" x 12" White w/ Tan Speckles VFT (Not Observed)

153M	12" x 12" White w/ Tan Speckles VFT Mastic (Not Observed)
154M	Gold, Blue Carpet Mastic
155	Linoleum, White w/Gray Streaks
155M	Linoleum, White w/Gray Streaks Mastic
156	12" x 12" Light Gray w/ Gray and White Specks VFT
156A	12" x 12" Light Gray w/ Gray and White Specks VFT MASTIC
157	2' x 4' Smooth Ceiling Tile
158	1' x 1' Ceiling Tile w/ Grooves
159	1' x 1' Ceiling Tile w/ Grooves above HA 161
160	2' x 4' Ceiling Tile w/ Grooves
161	2' x 4' Ceiling Tile w/ Grooves
162	2' x 4' Ceiling Tile - pinhole
163	2' x 4' Ceiling Tile - pinholes
164	12" x 12" Tan w/ light brown specks VFT
164A	12" x 12" Tan w/ light brown specks VFT MASTIC
165	9" x 9" Brown w/ yellow design VFT (Not Observed)
165A	9" x 9" Brown w/ yellow design VFT MASTIC (Not Observed)
166	12" x 12" Light Blue w/ blue specks VFT (Not Observed)
166A	12" x 12" Light Blue w/ blue specks VFT MASTIC (Not Observed)
167	12" x 12" White w/light blue, gray and yellow specks VFT (Not Observed)
167A	12" x 12" White w/ light blue, gray and yellow specks VFT MASTIC (Not Observed)
168	Black Lab Table Tops
169	Black Lab Counter Tops
170	Blue Linoleum with MASTIC
171	12" x 12" Gray w/ tan streaks VFT w/ MASTIC
172	Decorative Plaster
173	Terrazzo
174	Terrazzo
175	12" x 12" Blue Speckled VFT (Not Observed)
176	12" x 12" Blue Speckled VFT Mastic (Not Observed)
177	12" x 12" Light Blue w/ Specks VFT (Not Observed)
178	12" x 12" Light Blue w/ Specks VFT Mastic (Not Observed)
179	12" x 12" Gray w/ Streaks VFT (Not Observed)
180	12" x 12" Gray w/ Streaks VFT Mastic (Not Observed)
181	Gray Linoleum w/ Granite Pattern

182	Gray Linoleum w/ Granite Pattern Mastic
183	Gray Linoleum
184	Gray Linoleum Mastic
185	12" x 12" Red w/ Streaks VFT
186	12" x 12" Red w/ Streaks VFT Mastic
187	12" x 12" Yellow w/Streaks VFT
188	12" x 12" Yellow w/Streaks VFT Mastic
189	12" x 12" Green w/ Streaks VFT
190	12" x 12" Green w/ Streaks VFT Mastic
191	12" x 12" Dark Gray Linoleum w/ Granite Pattern (Not Observed)
192	12" x 12" Dark Gray Linoleum w/ Granite Pattern Mastic (Not Observed)
193	12" x 12" Pink w/ Maroon Specks VFT
194	12" x 12" Pink w/ Maroon Specks VFT Mastic
195	12" x 12" Maroon w/ Pink Specks VFT
196	12" x 12" Maroon w/ Pink Specks VFT Mastic
197	12" x 12" Beige w/ Beige Specs VFT
198	12" x 12" Beige w/ Beige Specs VFT Mastic
199	20" x 20" Off White w/ Specks VFT
200	20" x 20" Off White w/ Specks VFT Mastic
201	20" x 20" Beige w/ Specks VFT
202	20" x 20" Beige w/ Specks VFT Mastic
203	20" x 20" Brown w/ Specks VFT
204	20" x 20" Brown w/ Specks VFT Mastic
205	Linoleum Gray w/ Granite Pattern
206	Linoleum Gray w/ Granite Pattern Mastic
207	Linoleum Gray w/ Black Spots
208	Linoleum Gray w/ Black Spots Mastic
209	12" x 12" Light Gray w/ Specks VFT
210	12" x 12" Light Gray w/ Specks VFT Mastic
211	12" x 12" Dark Gray w/ Specks VFT
212	12" x 12" Dark Gray w/ Specks VFT Mastic
213	12" x 12" White w/ Red, Blue & Yellow Specks VFT
214	12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic
215	12" x 12" Light Gray w/ Specks VFT
216	12" x 12" Light Gray w/ Specks VFT Mastic
217	12" x 12" Dark Gray w/ Specks VFT
218	12" x 12" Dark Gray w/ Specks VFT Mastic
25	Insulation in Vault Door
64	12" x 12" Light Brown w/ White Streaks VFT (Not Observed)
65	12" x 12" Light Brown w/ White Streaks VFT Mastic (Not Observed)
80	12" x 12" White w/ Brown Speckles VFT (Not Observed)

81	12" x 12" White w/ Brown Speckles VFT Mastic
86	12" x 12" Brown w/ Light Brown Speckles VFT (Not observed)
88	Brown Linoleum
89	Green Linoleum (Not Observed)
AA	12" x 12" Green Floor Tile - NOT OBSERVED
BB	Mastic associated with HA AA - NOT OBSERVED
CC	Lab Counter Tops
DD	Lab Tables
EE	Lab Fume Hoods

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Antonio Munoz IV, IDPH License # 100-20616. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	8/16/2019
	8/16/2019
	12/30/2019
	1/20/2020
	7/21/2021

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Senn Academy Building 1540 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Boiler Lagging (ABATED 2010)			Boiler # 1 - 1931 Bldg.	ABATED	TSI								
02	Boiler Lagging (ABATED 2010)			Boiler # 2 - 1931 Bldg.	ABATED	TSI								
03	Boiler Lagging (ABATED 2010)			Boiler # 3 - 1931 Bldg.	ABATED	TSI								
04	Boiler Lagging (ABATED 2010)			Boiler # 4 - 1931 Bldg.	ABATED	TSI								
05	Boiler Gasket (ABATED 2010)			Boiler # 1 - 1931 Bldg.	ABATED	MISC								
06	Boiler Gasket (ABATED 2010)			Boiler # 2 - 1931 Bldg.	ABATED	MISC								
09	MJP on Fiberglass Pipe Insulation	600	FITTING	Throughout (See Hatching Maps) - 1912 Bldg.	CHR	TSI	Y	LOC	2		No	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
10	MJP on Fiberglass Pipe Insulation	425	FITTING	ROTC Room, Boiler & Pump Rooms, Main Tunnel, 2nd & 3rd Floor South Janitors Closet Chase, 2nd Floor Boys Toilet (N), 3rd Floor Unisex Toilet; 1st Floor Janitor's Closet; Under Sinks in Rooms 310, 352, and 366; BookRoom Between Room 315 and 317; Mens Room Next to Room 322 - 1931 Bldg.	CHR	TSI	Y	LOC	1		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
100	9" x 9" Red w/ White Streaks VFT- NOT OBSERVED	300	SF	115 Kitchen - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1000	12" x 12" Orange/Brown VFT- NOT OBSERVED	24	SF	Room 180 wooden stage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1001	12" x 12" Orange/Brown VFT Black Mastic - NOT OBSERVED	24	SF	Room 180 wooden stage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	9" x 9" Red w/ White Streaks VFT Mastic- NOT OBSERVED	300	SF	115 Kitchen - 1912 Bldg.	CHR	MISC	N	DIST	16		No	ACBM with the potential for damage	3	LOW
102	9" x 9" Gray w/ White Streaks VFT (Not Observed)	800	SF	Rooms 117A - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	9" x 9" Gray w/ White Streaks VFT Mastic (Not Observed)	800	SF	Rooms 117A - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
104	12" x 12" Light Green w/ White Streaks VFT (Not Observed)	350	SF	Room 123A - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	12" x 12" Light Green w/ White Streaks VFT Mastic (Not Observed)	350	SF	Room 123A - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12" x 12" Beige w/ Dark & White Streaks VFT	6,100	SF	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	12" x 12" Beige w/ Dark & White Streaks VFT Mastic	6,100	SF	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	9" x 9" Lt. Brown w/ Dark Red Streaks VFT	455	SF	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.	CHR	MISC	N	DIST	48		No	ACBM with the potential for damage	3	LOW
109	9" x 9" Lt. Brown w/ Dark Red Streaks VFT Mastic	455	SF	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	9" x 9" Green w/ White Streaks VFT	300	SF	Teacher Lunchroom/Lounge - 1912 Bldg.	CHR	MISC	N	LOC	3		No	ACBM with the potential for damage	3	LOW
111	9" x 9" Green w/ White Streaks VFT Mastic	300	SF	Teacher Lunchroom/Lounge - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
112	12" x 12" Lt. Brown w/ Gray Speckles VFT (Not Observed)	80	SF	153 Vest., 120 Vest. - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	12" x 12" Lt. Brown w/ Gray Speckles VFT Mastic (Not Observed)	80	SF	153 Vest., 120 Vest. - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	12" x 12" Beige w/ Brown Streaks VFT - NOT OBSERVED	1,400	SF	Rooms 166, & 162 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	12" x 12" Beige w/ Brown Streaks VFT Mastic - NOT OBSERVED	1,400	SF	Rooms 166, & 162 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	12" x 12" Blue-Gray w/ White Streaks VFT	500	SF	Room 373, 375 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	12" x 12" Blue-Gray w/ White Streaks VFT Mastic	500	SF	Room 373, 375 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	12" x 12" Dk Gray w/ Beige Streaks VFT - NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
119	12" x 12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
120	12" x 12" Lt Gray w/ White Speckles VFT- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
121	12" x 12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
122	12" x 12" Brown VFT- NOT OBSERVED		SF	Stage - 1912 Bldg.	CHR	MISC	N	NONE	0		No			LOW
123	12" x 12" Brown VFT Mastic- NOT OBSERVED	0	SF	Stage - 1912 Bldg.	CHR	MISC	N	NONE	0		No			LOW
124	2' x 2' Black Border VFT (Abated)			115 Kitchen - 1912 Bldg.	ABATED	MISC								
125	2' x 2' Black Border VFT Mastic- Abated			115 Kitchen - 1912 Bldg.	ABATED	MISC								
126	2' x 2' Ceiling Tile- NOT OBSERVED	1,700	SF	Room 425, & 326 - 1912 Bldg.	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
127	12" x 12" White w/Beige Streaks VFT - Not Observed	1,000	SF	Room 377A, 178, 180	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
127 A	12" x 12" White w/Beige Streaks VFT Mastic	1,000	SF	Room 377A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
128	12" x 12" White w/Blue Streaks VFT	880	SF	Room 351	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
128 A	12" x 12" White w/Blue Streaks VFT Mastic	880	SF	Room 351	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	MJP on Paperwrap Pipe Insulation	370	FITTING	1st Floor South JC, 2nd Floor Janitor's Closet, 238 Chase, 188, Autoshop - 1931 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
133	Lt Blue Speckled Linoleum- NOT OBSERVED	800	SF	Rooms 356, 326 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	Lt Blue Speckled Linoleum Mastic- NOT OBSERVED	800	SF	Rooms 356, 326 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
135	12" x 12" White w/ Gold Specks VFT (Not Observed)	1,000	SF	Rooms 174, 176, & 180 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
136	12" x 12" White w/ Gold Specks VFT Mastic (Not Observed)	1,000	SF	Rooms 174, 176, & 180 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
137	2' x 4' White Pin-Hole Ceiling Tile	1,000	SF	Room 356 - 1912 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
138	12" x 12" White w/ Beige VFT	2,000	SF	310 & Office, 302, 108, 110 - 1931 Bldg.	ASSUMED	MISC	N	LOC	100		No	ACBM with the potential for damage	3	LOW
139	12" x 12" White w/ Beige VFT Mastic	2,000	SF	310 & Office, 302, 108, 110 - 1931 Bldg.	ASSUMED	MISC	N	LOC	100		No	ACBM with the potential for damage	3	LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
14	Paperwrap Pipe Insulation	300	LF	ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
140	12" x 12" Light Gray VFT	800	SF	Room 210, & Engineer's Office - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
141	12" x 12" Light Gray VFT Mastic	800	SF	210, & Engineer's Office - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142	12" x 12" Light Blue VFT	900	SF	Room 210, 195A & Engineer's Office - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143	12" x 12" Light Blue VFT Mastic	900	SF	Room 210, 195A & Engineer's Office - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
144	12" x 12" Green VFT (Not Observed)	300	SF	1st Floor Hall (N&S) - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
145	12" x 12" Green VFT Mastic (Not Observed)	300	SF	1st Floor Hall (N&S) - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
146	12" x 12" White VFT (Not Observed)	1,000	SF	1st Floor Hall (N&S) - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
147	12" x 12" White VFT Mastic (Not Observed)	1,000	SF	1st Floor Hall (N&S) - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
148	Linoleum, Gray w/Gray Streaks	4,500	SF	Rooms 350, 352, 356 Vault, 306 and 310	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
148M	Linoleum, Gray w/Gray Streaks Mastic	4,500	SF	Rooms 350, 352, 356 Vault, 306 and 310	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
149	Linoleum, Blue Solid	2,000	SF	Rooms 100, 106, and 106 Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
149M	Linoleum, Blue Solid Mastic	2,000	SF	Rooms 100, 106, and 106 Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
150	12" x 12" VFT- NOT OBSERVED	200	SF	3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
150M	12" x 12" VFT Mastic - NOT OBSERVED	200	SF	3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Walls - NOT OBSERVED										
151	12" x 12" Solid Gray VFT	800	SF	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
151M	12" x 12" Solid Gray VFT Mastic	800	SF	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
152	12" x 12" Tan w/Brown Speckles VFT (Not Observed)	800	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
152M	12" x 12" Tan w/Brown Speckles VFT Mastic (Not Observed)	800	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
153	12" x 12" White w/ Tan Speckles VFT (Not Observed)	200	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
153M	12" x 12" White w/ Tan Speckles VFT Mastic (Not Observed)	200	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
154M	Gold, Blue Carpet Mastic	1,000	SF	Rooms 379, 375, 326, 315, and 272 (not observed), Room 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
155	Linoleum, White w/Gray Streaks	750	SF	Room 352	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
155M	Linoleum, White w/Gray Streaks Mastic	750	SF	Room 352	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
156	12" x 12" Light Gray w/ Gray and White Specks VFT	600	SF	Room 377, 377B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
156A	12" x 12" Light Gray w/ Gray and White Specks VFT MASTIC	600	SF	Room 377, 377B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
157	2' x 4' Smooth Ceiling Tile	700	SF	Room 351	ASSUMED	MISC	Y	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
158	1' x 1' Ceiling Tile w/ Grooves	2,600	SF	Room 320, 425 - 1911 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
159	1' x 1' Ceiling Tile w/ Grooves above HA 161	1,000	SF	Rooms 108, 148, 149, 146	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
160	2' x 4' Ceiling Tile w/ Grooves	22,000	SF	South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet - 1930 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
161	2' x 4' Ceiling Tile w/ Grooves	45,000	SF	Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335, 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166 - 1911	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
162	2' x 4' Ceiling Tile - pinhole	13,000	SF	Bldg. 1st Floor Hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352, 364, 366 - 1911 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
163	2' x 4' Ceiling Tile - pinholes	4,500	SF	Corridor from pump room- room 184, kitchen, cafeteria - 1930 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
164	12" x 12" Tan w/ light brown specks VFT	1,600	SF	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
164A	12" x 12" Tan w/ light brown specks VFT MASTIC	1,600	SF	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
165	9" x 9" Brown w/ yellow design VFT (Not Observed)	100	SF	Room 123 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
165A	9" x 9" Brown w/ yellow design VFT MASTIC (Not Observed)	100	SF	Room 123 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
166	12" x 12" Light Blue w/ blue specks VFT (Not Observed)	500	SF	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
166A	12" x 12" Light Blue w/ blue specks VFT MASTIC (Not Observed)	500	SF	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
167	12" x 12" White w/light blue, gray and yellow specks VFT (Not Observed)	7,000	SF	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
167A	12" x 12" White w/ light blue, gray and yellow specks VFT MASTIC (Not	7,000	SF	2nd, 3rd Floor main center corridor,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Observed)			Health Center (144), 162, 166 - 1912 Bldg.										
168	Black Lab Table Tops	700	SF	Rooms 358, 364, 367	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
169	Black Lab Counter Tops	300	SF	Rooms 358, 364, 367	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
170	Blue Linoleum with MASTIC	2,300	SF	Rooms 358, 364, 366	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
171	12" x 12" Gray w/ tan streaks VFT w/ MASTIC	400	SF	Room 170	ASSUMED	MISC	N	NONE			No	ACBM with potential for significant damage		LOW
172	Decorative Plaster	1,200	SF	Assembly hall, vestibule leading to assembly hall	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
173	Terrazzo	2,000	SF	Stairwells, 1st fl. corridor west of pump room - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
174	Terrazzo	1,000	SF	1st Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
175	12" x 12" Blue Speckled VFT (Not Observed)	1,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
176	12" x 12" Blue Speckled VFT Mastic (Not Observed)	1,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
177	12" x 12" Light Blue w/ Specks VFT (Not Observed)	8,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
178	12" x 12" Light Blue w/ Specks VFT Mastic (Not Observed)	8,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
179	12" x 12" Gray w/ Streaks VFT (Not Observed)	900	SF	Room 221	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
180	12" x 12" Gray w/ Streaks VFT Mastic (Not Observed)	900	SF	Room 221	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
181	Gray Linoleum w/ Granite Pattern	1,200	SF	Room 100, 108, 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
182	Gray Linoleum w/ Granite Pattern Mastic	1,200	SF	Room 100, 108, 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
183	Gray Linoleum	2,400	SF	Rooms 105, 105A, 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
184	Gray Linoleum Mastic	2,400	SF	Rooms 105, 105A, 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
185	12" x 12" Red w/ Streaks VFT	400	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
186	12" x 12" Red w/ Streaks VFT Mastic	400	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
187	12" x 12" Yellow w/Streaks VFT	400	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
188	12" x 12" Yellow w/Streaks VFT Mastic	400	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
189	12" x 12" Green w/ Streaks VFT	200	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
190	12" x 12" Green w/ Streaks VFT Mastic	200	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
191	12" x 12" Dark Gray Linoleum w/ Granite Pattern (Not Observed)	2,000	SF	Main Office (131-134)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
192	12" x 12" Dark Gray Linoleum w/ Granite Pattern Mastic (Not Observed)	2,000	SF	Main Office (131-134)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
193	12" x 12" Pink w/ Maroon Specks VFT	1,200	SF	Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
194	12" x 12" Pink w/ Maroon Specks VFT Mastic	1,200	SF	Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
195	12" x 12" Maroon w/ Pink Specks VFT	200	SF	Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
196	12" x 12" Maroon w/ Pink Specks VFT Mastic	200	SF	Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
197	12" x 12" Beige w/ Beige Specs VFT	2,500	SF	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
198	12" x 12" Beige w/ Beige Specs VFT Mastic	2,500	SF	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
199	20" x 20" Off White w/ Specks VFT	3,335	SF	Rooms 339, 326, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117, 352 Vault, 3rd Floor West Toilets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Mudded Joint Packing on Aircell Pipe Insulation	603	FITTING	Mixing Room, 219, 319, Auditorium Crawlspace, Room 120A - 1912 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
200	20" x 20" Off White w/ Specks VFT Mastic	2,800	SF	Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
201	20" x 20" Beige w/ Specks VFT	5,000	SF	Room 225A, Library, 276, 278, 280, 326, 123A thru 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
202	20" x 20" Beige w/ Specks VFT Mastic	5,000	SF	Room 225A, Library, 276, 278, 280, 326, 123A thru 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
203	20" x 20" Brown w/ Specks VFT	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117, 326	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
204	20" x 20" Brown w/ Specks VFT Mastic	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
205	Linoleum Gray w/ Granite Pattern	2,500	SF	Main Office and Associated Offices (131-134)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
206	Linoleum Gray w/ Granite Pattern Mastic	2,500	SF	Main Office and Associated Offices (131-134)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
207	Linoleum Gray w/ Black Spots	2,300	SF	Rooms 151, 155	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
208	Linoleum Gray w/ Black Spots Mastic	2,500	SF	Rooms 151, 155	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
209	12" x 12" Light Gray w/ Specks VFT	20,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
210	12" x 12" Light Gray w/ Specks VFT Mastic	2,500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
211	12" x 12" Dark Gray w/ Specks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
212	12" x 12" Dark Gray w/ Specks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
213	12" x 12" White w/ Red, Blue & Yellow Specks VFT	2,500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
214	12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic	2,500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
215	12" x 12" Light Gray w/ Specks VFT	10,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
216	12" x 12" Light Gray w/ Specks VFT Mastic	10,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
217	12" x 12" Dark Gray w/ Specks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
218	12" x 12" Dark Gray w/ Specks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Insulation in Vault Door	28	SF	Office - 1912 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
26	Mudded Joint Packing on Aircell Insulation	300	FITTING	Room 238 Chase, Autoshop, Autoshop Tool Room - 1931 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
27	Aircell Pipe Insulation	1,000	LF	Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autoshop & Autoshop Tool Room, Kitchen Storage - 1931 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
30	Aircell Pipe Insulation	2,600	LF	Rooms 219, 319, 356, & Auditorium Crawlspace - 1912 Bldg.	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
33	Paperwrap Pipe Insulation	400	LF	Auditorium Crawlspace - 1912 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
34	MJP E/F/V on Paperwrap Pipe Insulation	50	FITTING	Auditorium Crawlspace - 1912 Bldg.	CHR	TSI	Y	DIST	7		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
39	Hard Coat Plaster			Throughout - 1912 Bldg.	NO_ACBM						No			
40	Hard Coat Plaster			Throughout - 1931 Bldg.	NO_ACBM						No			
55	12" x 12" Tan w/Speckles VFT	5,000	SF	3rd Floor Corridor	CHR	MISC	N	DIST	50		No	ACBM with the	3	LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.										
72	9" x 9" Orange w/White VFT Streaks (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.	ABATED	MISC								
73	9" x 9" Orange w/White Streaks VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.	ABATED	MISC								
76	9" x 9" Maroon w/ White Streaks VFT (Abated)			2nd Floor Hall (S) - 1931 Bldg.	ABATED	MISC								
77	9" x 9" Maroon w/ White Streaks VFT Mastic (Abated)			2nd Floor Hall (S) - 1931 Bldg.	ABATED	MISC								
78	9" x 9" Black w/ Faint White Streaks VFT (Abated)			2nd & 3rd Floor Halls (N&S) - 1931 Bldg.	ABATED	MISC								
79	9" x 9" Black w/ Faint White Streaks VFT Mastic (Abated)			2nd & 3rd Floor Halls (N&S) - 1931 Bldg.	ABATED	MISC								
80	12" x 12" White w/ Brown Speckles VFT (Not Observed)	1,200	SF	Room 341 & 213 - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	12" x 12" White w/ Brown Speckles VFT Mastic	1,200	SF	Room 341 & 213 - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	12" x 12" Brown w/ Light Brown Speckles VFT (Not observed)	600	SF	Room 239 - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	12" x 12" Brown w/ Light Brown Speckles VFT Mastic (Not Observed)	600	SF	Room 239 - 1931 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	Brown Linoleum	250	SF	238 North Storage - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	Green Linoleum (Not Observed)	5,500	SF	Main Gym, Office & Locker - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	12" x 12" Peach w/ Speckles VFT- NOT OBSERVED	700	SF	Rooms 352, 379, 350 Storage - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	12" x 12" Peach w/ Speckles VFT Mastic - NOT OBSERVED	700	SF	Rooms 352, 379, 350 Storage - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92	12" x 12" Light Brown w/ Dark Speckles VFT	700	SF	Room 355, 373, 375 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
93	12" x 12" Light Brown w/ Dark Speckles VFT Mastic	700	SF	Room 355, 373, 375 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
94	12" x 12" Beige w/ Dark Speckles VFT (Not Observed)	2,000	SF	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.										
95	12" x 12" Beige w/ Dark Speckles VFT Mastic (Not Observed)	2,000	SF	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
96	12" x 12" Dark Brown w/White & Dark Streaks VFT- NOT OBSERVED	1,900	SF	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
97	12" x 12" Dark Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED	1,900	SF	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
98	12" x 12" Black w/ White Speckles VFT- NOT OBSERVED	250	SF	3rd Floor Corridor (N) - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99	12" x 12" Black w/ White Speckles VFT Mastic- NOT OBSERVED	250	SF	3rd Floor Corridor (N) - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AA	12" x 12" Green Floor Tile - NOT OBSERVED		SF	3rd floor, side corridor, East to West navy areas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BB	Mastic associated with HA AA - NOT OBSERVED		SF	3rd floor, side corridor, East to West navy areas - NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No			LOW
CC	Lab Counter Tops	3,500	SF	Classrooms 100, 106, 108, 110, 302, 310, 350	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
DD	Lab Tables	2,600	SF	Classrooms 110, 302, 310, 350	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
EE	Lab Fume Hoods	750	SF	Classrooms 100, 106, 350	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 9/10/2022
Inspector Name Antonio Munoz IV
100-20616 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
09	Damage noted drawing, 2nd floor west teacher's toilet has 2 damaged
10	Damage noted on drawing, 1 damaged in 3rd floor west toilets
100	
1000	
1001	
101	Damage noted on drawing
102	
103	
104	
105	
106	
107	
108	Damage noted on drawing, 35 sf missing
109	
110	Damage noted on drawing
111	
112	
113	

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
114	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
127 A	
128	
128 A	
13	
133	
134	
135	
136	
137	
138	Damage noted on drawing, 100 sf damage in room 302
139	Damage noted on drawing, 100 sf damage in room 302
14	
140	
141	
142	

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
143	
144	
145	
146	
147	
148	Not observed in rooms 352 or 356 vault
148M	
149	
149M	
150	
150M	
151	
151M	
152	
152M	
153	
153M	
154M	
155	Not Observed
155M	
156	
156A	
157	
158	
159	
160	
161	
162	
163	

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
164	
164A	
165	
165A	
166	
166A	
167	
167A	
168	
169	
170	
171	
172	
173	
174	
175	
176	
177	
178	
179	
180	
181	
182	
183	
184	
185	
186	
187	
188	

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
189	
190	
191	
192	
193	
194	
195	
196	
197	
198	
199	Change noted on drawing, Added 35 sf to 352 Vault, Added 500 sf to 3rd floor west toilets
20	
200	
201	
202	
203	Added 326
204	
205	
206	
207	
208	
209	
210	
211	
212	
213	
214	
215	

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
216	
217	
218	
25	
26	
27	
30	
33	
34	Damage noted on drawing, 2 split end and 1 physical damage in fan room #2, 4 damaged in 3rd floor west girl's toilet
39	
40	
55	Damage noted on drawing, 50 sf damage in room 233
56	
57	
60	
61	
62	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
76	

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
77	
78	
79	
80	
81	
86	
87	
88	
89	Observed Office
90	
91	
92	373 & 375 Not Observed
93	373 & 375 Not Observed
94	
95	
96	
97	
98	
99	
AA	
BB	
CC	
DD	
EE	

Chicago Public Schools

School Senn Academy **Unit** 47061 **Building ID** 1540

Address 5900 N. Glenwood **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Boiler Lagging (ABATED 2010)			Boiler # 1 - 1931 Bldg.	Abated	TSI					
02	Boiler Lagging (ABATED 2010)			Boiler # 2 - 1931 Bldg.	Abated	TSI					
03	Boiler Lagging (ABATED 2010)			Boiler # 3 - 1931 Bldg.	Abated	TSI					
04	Boiler Lagging (ABATED 2010)			Boiler # 4 - 1931 Bldg.	Abated	TSI					
05	Boiler Gasket (ABATED 2010)			Boiler # 1 - 1931 Bldg.	Abated	MISC					
06	Boiler Gasket (ABATED 2010)			Boiler # 2 - 1931 Bldg.	Abated	MISC					
09	MJP on Fiberglass Pipe Insulation	600	FITTING	Throughout (See Hatching Maps) - 1912 Bldg.	Chrysotile	TSI	Yes	2	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
10	MJP on Fiberglass Pipe Insulation	425	FITTING	ROTC Room, Boiler & Pump Rooms, Main Tunnel, 2nd & 3rd Floor South Janitors Closet Chase, 2nd Floor Boys Toilet (N), 3rd Floor Unisex Toilet; 1st Floor Janitor's Closet; Under Sinks in Rooms 310, 352, and 366; BookRoom Between Room 315 and 317; Mens Room Next to Room 322 - 1931 Bldg.	Chrysotile	TSI	Yes	1	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
100	9" x 9" Red w/ White Streaks VFT- NOT OBSERVED	300	SF	115 Kitchen - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1000	12" x 12" Orange/Brown VFT- NOT OBSERVED	24	SF	Room 180 wooden stage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1001	12" x 12" Orange/Brown VFT Black Mastic - NOT OBSERVED	24	SF	Room 180 wooden stage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	9" x 9" Red w/ White Streaks VFT Mastic- NOT OBSERVED	300	SF	115 Kitchen - 1912 Bldg.	Chrysotile	MISC	No	16	SF	6 ACBM with the potential for damage	Remove
102	9" x 9" Gray w/ White Streaks VFT (Not Observed)	800	SF	Rooms 117A - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	9" x 9" Gray w/ White Streaks VFT Mastic (Not Observed)	800	SF	Rooms 117A - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12" x 12" Light Green w/ White Streaks VFT (Not Observed)	350	SF	Room 123A - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" Light Green w/ White Streaks VFT Mastic (Not Observed)	350	SF	Room 123A - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12" x 12" Beige w/ Dark & White Streaks VFT	6,100	SF	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12" x 12" Beige w/ Dark & White Streaks VFT Mastic	6,100	SF	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
108	9" x 9" Lt. Brown w/ Dark Red Streaks VFT	455	SF	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.	Chrysotile	MISC	No	48	SF	6 ACBM with the potential for damage	Remove
109	9" x 9" Lt. Brown w/ Dark Red Streaks VFT Mastic	455	SF	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	9" x 9" Green w/ White Streaks VFT	300	SF	Teacher Lunchroom/Lounge - 1912 Bldg.	Chrysotile	MISC	No	3	SF	6 ACBM with the potential for damage	Remove
111	9" x 9" Green w/ White Streaks VFT Mastic	300	SF	Teacher Lunchroom/Lounge - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12" x 12" Lt. Brown w/ Gray Speckles VFT (Not Observed)	80	SF	153 Vest., 120 Vest. - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12" x 12" Lt. Brown w/ Gray Speckles VFT Mastic (Not Observed)	80	SF	153 Vest., 120 Vest. - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12" x 12" Beige w/ Brown Streaks VFT- NOT OBSERVED	1,400	SF	Rooms 166, & 162 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	12" x 12" Beige w/ Brown Streaks VFT Mastic - NOT OBSERVED	1,400	SF	Rooms 166, & 162 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	12" x 12" Blue-Gray w/ White Streaks VFT	500	SF	Room 373, 375 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12" x 12" Blue-Gray w/ White Streaks VFT Mastic	500	SF	Room 373, 375 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12" x 12" Dk Gray w/ Beige Streaks VFT- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	12" x 12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	12" x 12" Lt Gray w/ White Speckles VFT- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12" x 12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	12" x 12" Brown VFT- NOT OBSERVED		SF	Stage - 1912 Bldg.	Chrysotile	MISC	No	0	SF		
123	12" x 12" Brown VFT Mastic- NOT OBSERVED	0	SF	Stage - 1912 Bldg.	Chrysotile	MISC	No	0	SF		
124	2' x 2' Black Border VFT (Abated)			115 Kitchen - 1912 Bldg.	Abated	MISC					
125	2' x 2' Black Border VFT Mastic- Abated			115 Kitchen - 1912 Bldg.	Abated	MISC					
126	2' x 2' Ceiling Tile- NOT OBSERVED	1,700	SF	Room 425, & 326 - 1912 Bldg.	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127	12" x 12" White w/Beige Streaks VFT - Not Observed	1,000	SF	Room 377A, 178, 180	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127 A	12" x 12" White w/Beige Streaks VFT Mastic	1,000	SF	Room 377A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
128	12" x 12" White w/Blue Streaks VFT	880	SF	Room 351	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
128 A	12" x 12" White w/Blue Streaks VFT Mastic	880	SF	Room 351	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	MJP on Paperwrap Pipe Insulation	370	FITTING	1st Floor South JC, 2nd Floor Janitor's Closet, 238 Chase, 188, Autoshop - 1931 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
133	Lt Blue Speckled Linoleum- NOT OBSERVED	800	SF	Rooms 356, 326 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	Lt Blue Speckled Linoleum Mastic- NOT OBSERVED	800	SF	Rooms 356, 326 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	12" x 12" White w/ Gold Specks VFT (Not Observed)	1,000	SF	Rooms 174, 176, & 180 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	12" x 12" White w/ Gold Specks VFT Mastic (Not Observed)	1,000	SF	Rooms 174, 176, & 180 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	2' x 4' White Pin-Hole Ceiling Tile	1,000	SF	Room 356 - 1912 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	12" x 12" White w/ Beige VFT	2,000	SF	310 & Office, 302, 108, 110 - 1931 Bldg.	Assumed	MISC	No	100	SF	6 ACBM with the potential for damage	Remove
139	12" x 12" White w/ Beige VFT Mastic	2,000	SF	310 & Office, 302, 108, 110 - 1931 Bldg.	Assumed	MISC	No	100	SF	6 ACBM with the potential for damage	Remove
14	Paperwrap Pipe Insulation	300	LF	ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
140	12" x 12" Light Gray VFT	800	SF	Room 210, & Engineer's Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
141	12" x 12" Light Gray VFT Mastic	800	SF	210, & Engineer's Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142	12" x 12" Light Blue VFT	900	SF	Room 210, 195A & Engineer's Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143	12" x 12" Light Blue VFT Mastic	900	SF	Room 210, 195A & Engineer's Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	12" x 12" Green VFT (Not Observed)	300	SF	1st Floor Hall (N&S) - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	12" x 12" Green VFT Mastic (Not Observed)	300	SF	1st Floor Hall (N&S) - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
146	12" x 12" White VFT (Not Observed)	1,000	SF	1st Floor Hall (N&S) - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
147	12" x 12" White VFT Mastic (Not Observed)	1,000	SF	1st Floor Hall (N&S) - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148	Linoleum, Gray w/Gray Streaks	4,500	SF	Rooms 350, 352, 356 Vault, 306 and 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148M	Linoleum, Gray w/Gray Streaks Mastic	4,500	SF	Rooms 350, 352, 356 Vault, 306 and 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149	Linoleum, Blue Solid	2,000	SF	Rooms 100, 106, and 106 Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149M	Linoleum, Blue Solid Mastic	2,000	SF	Rooms 100, 106, and 106 Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
150	12" x 12" VFT- NOT OBSERVED	200	SF	3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
150M	12" x 12" VFT Mastic - NOT OBSERVED	200	SF	3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151	12" x 12" Solid Gray VFT	800	SF	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151M	12" x 12" Solid Gray VFT Mastic	800	SF	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152	12" x 12" Tan w/Brown Speckles VFT (Not Observed)	800	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152M	12" x 12" Tan w/Brown Speckles VFT Mastic (Not Observed)	800	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153	12" x 12" White w/ Tan Speckles VFT (Not Observed)	200	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153M	12" x 12" White w/ Tan Speckles VFT Mastic (Not Observed)	200	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
154M	Gold, Blue Carpet Mastic	1,000	SF	Rooms 379, 375, 326, 315, and 272 (not observed), Room 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155	Linoleum, White w/Gray Streaks	750	SF	Room 352	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155M	Linoleum, White w/Gray Streaks Mastic	750	SF	Room 352	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
156	12" x 12" Light Gray w/ Gray and White Specks VFT	600	SF	Room 377, 377B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
156A	12" x 12" Light Gray w/ Gray and White Specks VFT MASTIC	600	SF	Room 377, 377B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
157	2' x 4' Smooth Ceiling Tile	700	SF	Room 351	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
158	1' x 1' Ceiling Tile w/ Grooves	2,600	SF	Room 320, 425 - 1911 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159	1' x 1' Ceiling Tile w/ Grooves above HA 161	1,000	SF	Rooms 108, 148, 149, 146	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
160	2' x 4' Ceiling Tile w/ Grooves	22,000	SF	South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet - 1930 Bldg.							
161	2' x 4' Ceiling Tile w/ Grooves	45,000	SF	Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335. 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166 - 1911 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
162	2' x 4' Ceiling Tile - pinhole	13,000	SF	1st Floor Hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352, 364, 366 - 1911 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
163	2' x 4' Ceiling Tile - pinholes	4,500	SF	Corridor from pump room- room 184, kitchen, cafeteria - 1930 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
164	12" x 12" Tan w/ light brown specks VFT	1,600	SF	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
164A	12" x 12" Tan w/ light brown specks VFT MASTIC	1,600	SF	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
165	9" x 9" Brown w/ yellow design VFT (Not Observed)	100	SF	Room 123 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
165A	9" x 9" Brown w/ yellow design VFT MASTIC (Not Observed)	100	SF	Room 123 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
166	12" x 12" Light Blue w/ blue specks VFT (Not Observed)	500	SF	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
166A	12" x 12" Light Blue w/ blue specks VFT MASTIC (Not Observed)	500	SF	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
167	12" x 12" White w/light blue, gray and yellow specks VFT (Not Observed)	7,000	SF	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
167A	12" x 12" White w/ light blue, gray and yellow specks VFT MASTIC (Not Observed)	7,000	SF	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
168	Black Lab Table Tops	700	SF	Rooms 358, 364, 367	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
169	Black Lab Counter Tops	300	SF	Rooms 358, 364, 367	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
170	Blue Linoleum with MASTIC	2,300	SF	Rooms 358, 364, 366	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
171	12" x 12" Gray w/ tan streaks VFT w/ MASTIC	400	SF	Room 170	Assumed	MISC	No		SF	5 ACBM with potential for significant damage	Remove
172	Decorative Plaster	1,200	SF	Assembly hall, vestibule leading to assembly hall	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
173	Terrazzo	2,000	SF	Stairwells, 1st fl. corridor west of pump room - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
174	Terrazzo	1,000	SF	1st Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
175	12" x 12" Blue Speckled VFT (Not Observed)	1,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
176	12" x 12" Blue Speckled VFT Mastic (Not Observed)	1,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
177	12" x 12" Light Blue w/ Specks VFT (Not Observed)	8,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
178	12" x 12" Light Blue w/ Specks VFT Mastic (Not Observed)	8,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
179	12" x 12" Gray w/ Streaks VFT (Not Observed)	900	SF	Room 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
180	12" x 12" Gray w/ Streaks VFT Mastic (Not Observed)	900	SF	Room 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
181	Gray Linoleum w/ Granite Pattern	1,200	SF	Room 100, 108, 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
182	Gray Linoleum w/ Granite Pattern Mastic	1,200	SF	Room 100, 108, 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
183	Gray Linoleum	2,400	SF	Rooms 105, 105A, 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
184	Gray Linoleum Mastic	2,400	SF	Rooms 105, 105A, 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
185	12" x 12" Red w/ Streaks VFT	400	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
186	12" x 12" Red w/ Streaks VFT Mastic	400	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
187	12" x 12" Yellow w/Streaks VFT	400	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
188	12" x 12" Yellow w/Streaks VFT Mastic	400	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
189	12" x 12" Green w/ Streaks VFT	200	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
190	12" x 12" Green w/ Streaks VFT Mastic	200	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
191	12" x 12" Dark Gray Linoleum w/ Granite Pattern (Not Observed)	2,000	SF	Main Office (131-134)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
192	12" x 12" Dark Gray Linoleum w/ Granite Pattern Mastic (Not Observed)	2,000	SF	Main Office (131-134)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
193	12" x 12" Pink w/ Maroon Specks VFT	1,200	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
194	12" x 12" Pink w/ Maroon Specks VFT Mastic	1,200	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
195	12" x 12" Maroon w/ Pink Specks VFT	200	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
196	12" x 12" Maroon w/ Pink Specks VFT Mastic	200	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
197	12" x 12" Beige w/ Beige Specs VFT	2,500	SF	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
198	12" x 12" Beige w/ Beige Specs VFT Mastic	2,500	SF	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
199	20" x 20" Off White w/ Specks VFT	3,335	SF	Rooms 339, 326, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117, 352 Vault, 3rd Floor West Toilets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Mudded Joint Packing on Aircell Pipe Insulation	603	FITTING	Mixing Room, 219, 319, Auditorium Crawlspace, Room 120A - 1912 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
200	20" x 20" Off White w/ Specks VFT Mastic	2,800	SF	Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
201	20" x 20" Beige w/ Specks VFT	5,000	SF	Room 225A, Library, 276, 278, 280, 326, 123A thru 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
202	20" x 20" Beige w/ Specks VFT Mastic	5,000	SF	Room 225A, Library, 276, 278, 280, 326, 123A thru 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
203	20" x 20" Brown w/ Specks VFT	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117, 326	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
204	20" x 20" Brown w/ Specks VFT Mastic	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
205	Linoleum Gray w/ Granite Pattern	2,500	SF	Main Office and Associated Offices (131-134)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
206	Linoleum Gray w/ Granite Pattern Mastic	2,500	SF	Main Office and Associated Offices (131-134)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
207	Linoleum Gray w/ Black Spots	2,300	SF	Rooms 151, 155	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
208	Linoleum Gray w/ Black Spots Mastic	2,500	SF	Rooms 151, 155	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
209	12" x 12" Light Gray w/ Specks VFT	20,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
210	12" x 12" Light Gray w/ Specks VFT Mastic	2,500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
211	12" x 12" Dark Gray w/ Specks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
212	12" x 12" Dark Gray w/ Specks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
213	12" x 12" White w/ Red, Blue & Yellow Specks VFT	2,500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
214	12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic	2,500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
215	12" x 12" Light Gray w/ Specks VFT	10,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
216	12" x 12" Light Gray w/ Specks VFT Mastic	10,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
217	12" x 12" Dark Gray w/ Specks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
218	12" x 12" Dark Gray w/ Specks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Insulation in Vault Door	28	SF	Office - 1912 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Mudded Joint Packing on Aircell Insulation	300	FITTING	Room 238 Chase, Autoshop, Autoshop Tool Room - 1931 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
27	Aircell Pipe Insulation	1,000	LF	Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autoshop & Autoshop Tool Room, Kitchen Storage - 1931 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
30	Aircell Pipe Insulation	2,600	LF	Rooms 219, 319, 356, & Auditorium Crawlspace - 1912 Bldg.	Chrysotile	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
33	Paperwrap Pipe Insulation	400	LF	Auditorium Crawlspace - 1912 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
34	MJP E/F/V on Paperwrap Pipe Insulation	50	FITTING	Auditorium Crawlspace - 1912 Bldg.	Chrysotile	TSI	Yes	7	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
39	Hard Coat Plaster			Throughout - 1912 Bldg.	No ACBM						
40	Hard Coat Plaster			Throughout - 1931 Bldg.	No ACBM						
55	12" x 12" Tan w/Speckles VFT	5,000	SF	3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.	Chrysotile	MISC	No	50	SF	6 ACBM with the potential for damage	Remove

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
56	9" x 9" Brown w/Streaks VFT Mastic	500	SF	Room 356	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12" x 12" Tan w/Speckles VFT Mastic	5,000	SF	3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	9" x 9" Maroon VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC					
61	9" x 9" Maroon VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC					
62	9" x 9" Brown w/Streaks VFT NOT OBSERVED	500	SF	Room 356 - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12" x 12" Light Brown w/ White Streaks VFT (Not Observed)	200	SF	Rooms 100, 106, & 106 Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12" x 12" Light Brown w/ White Streaks VFT Mastic (Not Observed)	200	SF	Rooms 100, 106, & 106 Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	9" x 9" Black VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC					
67	9" x 9" Black VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC					
68	9" x 9" Black w/Large White Streaks VFT (Abated)			3rd Floor Hall (S&N) - 1931 Bldg.	Abated	MISC					
69	9" x 9" Black w/Large White Streaks VFT Mastic (Abated)			3rd Floor Hall (S&N) - 1931 Bldg.	Abated	MISC					
70	9" x 9" Brown w/Large White Streaks VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC					
71	9" x 9" Brown w/Large White Streaks VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC					
72	9" x 9" Orange w/White VFT Streaks (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.	Abated	MISC					
73	9" x 9" Orange w/White Streaks VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.	Abated	MISC					
76	9" x 9" Maroon w/ White Streaks VFT (Abated)			2nd Floor Hall (S) - 1931 Bldg.	Abated	MISC					
77	9" x 9" Maroon w/ White Streaks VFT Mastic (Abated)			2nd Floor Hall (S) - 1931 Bldg.	Abated	MISC					
78	9" x 9" Black w/ Faint White Streaks VFT (Abated)			2nd & 3rd Floor Halls (N&S) - 1931 Bldg.	Abated	MISC					
79	9" x 9" Black w/ Faint White Streaks VFT Mastic (Abated)			2nd & 3rd Floor Halls (N&S) - 1931 Bldg.	Abated	MISC					
80	12" x 12" White w/ Brown Speckles VFT (Not Observed)	1,200	SF	Room 341 & 213 - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
81	12" x 12" White w/ Brown Speckles VFT Mastic	1,200	SF	Room 341 & 213 - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" Brown w/ Light Brown Speckles VFT (Not observed)	600	SF	Room 239 - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12" x 12" Brown w/ Light Brown Speckles VFT Mastic (Not Observed)	600	SF	Room 239 - 1931 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Brown Linoleum	250	SF	238 North Storage - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	Green Linoleum (Not Observed)	5,500	SF	Main Gym, Office & Locker - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12" x 12" Peach w/ Speckles VFT- NOT OBSERVED	700	SF	Rooms 352, 379, 350 Storage - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	12" x 12" Peach w/ Speckles VFT Mastic - NOT OBSERVED	700	SF	Rooms 352, 379, 350 Storage - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12" x 12" Light Brown w/ Dark Speckles VFT	700	SF	Room 355, 373, 375 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93	12" x 12" Light Brown w/ Dark Speckles VFT Mastic	700	SF	Room 355, 373, 375 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12" x 12" Beige w/ Dark Speckles VFT (Not Observed)	2,000	SF	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
95	12" x 12" Beige w/ Dark Speckles VFT Mastic (Not Observed)	2,000	SF	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	12" x 12" Dark Brown w/White & Dark Streaks VFT- NOT OBSERVED	1,900	SF	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	12" x 12" Dark Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED	1,900	SF	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	12" x 12" Black w/ White Speckles VFT- NOT OBSERVED	250	SF	3rd Floor Corridor (N) - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	12" x 12" Black w/ White Speckles VFT Mastic- NOT OBSERVED	250	SF	3rd Floor Corridor (N) - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AA	12" x 12" Green Floor Tile - NOT OBSERVED		SF	3rd floor, side corridor, East to West navy areas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BB	Mastic associated with HA AA - NOT OBSERVED		SF	3rd floor, side corridor, East to West navy areas - NOT OBSERVED	Assumed	MISC	No	0	SF		
CC	Lab Counter Tops	3,500	SF	Classrooms 100, 106, 108, 110, 302, 310, 350	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
DD	Lab Tables	2,600	SF	Classrooms 110, 302, 310, 350	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
EE	Lab Fume Hoods	750	SF	Classrooms 100, 106, 350	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
 Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

Review Date	10/3/2022
Manager Planner Name	Arturo Saenz
100-04019	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
09	repair damaged ACM asap
10	repair damaged ACM asap
100	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
 Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
1000	
1001	
101	remove damaged ACM ASAP
102	
103	
104	
105	
106	
107	
108	remove damaged ACM ASAP
109	
110	remove damaged ACM ASAP
111	
112	
113	
114	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
 Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
126	
127	
127 A	
128	
128 A	
13	
133	
134	
135	
136	
137	
138	sample material, remove damaged ACM ASAP
139	sample material, remove damaged ACM ASAP
14	
140	
141	
142	
143	
144	
145	
146	
147	
148	
148M	
149	
149M	
150	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
 Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
150M	
151	
151M	
152	
152M	
153	
153M	
154M	
155	
155M	
156	
156A	
157	
158	
159	
160	
161	
162	
163	
164	
164A	
165	
165A	
166	
166A	
167	
167A	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
168	
169	
170	
171	sample material, remove damaged ACM ASAP
172	
173	
174	
175	
176	
177	
178	
179	
180	
181	
182	
183	
184	
185	
186	
187	
188	
189	
190	
191	
192	
193	
194	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
195	
196	
197	
198	
199	
20	
200	
201	
202	
203	
204	
205	
206	
207	
208	
209	
210	
211	
212	
213	
214	
215	
216	
217	
218	
25	
26	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
 Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
27	
30	
33	
34	repair damaged ACM asap
39	
40	
55	remove damaged ACM ASAP
56	
57	
60	
61	
62	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
76	
77	
78	
79	
80	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
81	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
AA	
BB	
CC	
DD	
EE	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 1 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 1 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 2 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 2 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 3 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 3 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 4 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 4 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Boiler Gasket (ABATED 2010)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 1 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Boiler Gasket (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 1 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Boiler Gasket (ABATED 2010)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 2 - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Boiler Gasket (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 2 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1912 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS: **Damage noted drawing, 2nd floor west teacher's toilet has 2 damaged**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1912 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

repair damaged ACM asap

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **ROTC Room, Boiler & Pump Rooms, Main Tunnel, 2nd & 3rd Floor South Janitors Closet Chase, 2nd Floor Boys Toilet (N), 3rd Floor Unisex Toilet; 1st Floor Janitor's Closet; Under Sinks in Rooms 310, 352, and 366; BookRoom Between Room 315 and 317; Mens Room Next to Room 322 - 1931 Bldg.**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**
COMMENTS: **Damage noted on drawing, 1 damaged in 3rd floor west toilets**

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **ROTC Room, Boiler & Pump Rooms, Main Tunnel, 2nd & 3rd Floor South Janitors Closet Chase, 2nd Floor Boys Toilet (N), 3rd Floor Unisex Toilet; 1st Floor Janitor's Closet; Under Sinks in Rooms 310, 352, and 366; BookRoom Between Room 315 and 317; Mens Room Next to Room 322 - 1931 Bldg.**

MATERIAL QUANTITY: **425** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **1** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

repair damaged ACM asap

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **9" x 9" Red w/ White Streaks VFT- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **115 Kitchen - 1912 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **9" x 9" Red w/ White Streaks VFT- NOT OBSERVED**
MATERIAL LOCATION: **115 Kitchen - 1912 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1000**
MATERIAL DESCRIPTION: **12" x 12" Orange/Brown VFT- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 180 wooden stage**
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **1000**
MATERIAL DESCRIPTION: **12" x 12" Orange/Brown VFT- NOT OBSERVED**
MATERIAL LOCATION: **Room 180 wooden stage**
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1001**
MATERIAL DESCRIPTION: **12" x 12" Orange/Brown VFT Black Mastic - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 180 wooden stage**
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **1001**
MATERIAL DESCRIPTION: **12" x 12" Orange/Brown VFT Black Mastic - NOT OBSERVED**
MATERIAL LOCATION: **Room 180 wooden stage**
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **9" x 9" Red w/ White Streaks VFT Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **115 Kitchen - 1912 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage noted on drawing**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **9" x 9" Red w/ White Streaks VFT Mastic- NOT OBSERVED**
MATERIAL LOCATION: **115 Kitchen - 1912 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **16** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

remove damaged ACM ASAP

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **9" x 9" Gray w/ White Streaks VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 117A - 1912 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **9" x 9" Gray w/ White Streaks VFT (Not Observed)**
MATERIAL LOCATION: **Rooms 117A - 1912 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **9" x 9" Gray w/ White Streaks VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 117A - 1912 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **9" x 9" Gray w/ White Streaks VFT Mastic (Not Observed)**
MATERIAL LOCATION: **Rooms 117A - 1912 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ White Streaks VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 123A - 1912 Bldg.**

MATERIAL QUANTITY: **350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ White Streaks VFT (Not Observed)**
MATERIAL LOCATION: **Room 123A - 1912 Bldg.**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ White Streaks VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 123A - 1912 Bldg.**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ White Streaks VFT Mastic (Not Observed)**
MATERIAL LOCATION: **Room 123A - 1912 Bldg.**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.**

MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark & White Streaks VFT**
MATERIAL LOCATION: **Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.**
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark & White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.**

MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark & White Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.**
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **9" x 9" Lt. Brown w/ Dark Red Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.**
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage noted on drawing, 35 sf missing**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **9" x 9" Lt. Brown w/ Dark Red Streaks VFT**
MATERIAL LOCATION: **Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.**
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **48** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

remove damaged ACM ASAP

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **9" x 9" Lt. Brown w/ Dark Red Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.**
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **9" x 9" Lt. Brown w/ Dark Red Streaks VFT Mastic**
MATERIAL LOCATION: **Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.**
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **9" x 9" Green w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage noted on drawing**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **9" x 9" Green w/ White Streaks VFT**
MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

remove damaged ACM ASAP

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **9" x 9" Green w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **9" x 9" Green w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12" x 12" Lt. Brown w/ Gray Speckles VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **153 Vest., 120 Vest. - 1912 Bldg.**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12" x 12" Lt. Brown w/ Gray Speckles VFT (Not Observed)**
MATERIAL LOCATION: **153 Vest., 120 Vest. - 1912 Bldg.**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12" x 12" Lt. Brown w/ Gray Speckles VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **153 Vest., 120 Vest. - 1912 Bldg.**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12" x 12" Lt. Brown w/ Gray Speckles VFT Mastic (Not Observed)**
MATERIAL LOCATION: **153 Vest., 120 Vest. - 1912 Bldg.**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Streaks VFT- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 166, & 162 - 1912 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Streaks VFT- NOT OBSERVED**
MATERIAL LOCATION: **Rooms 166, & 162 - 1912 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Streaks VFT Mastic - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 166, & 162 - 1912 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Streaks VFT Mastic - NOT OBSERVED**
MATERIAL LOCATION: **Rooms 166, & 162 - 1912 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12" x 12" Blue-Gray w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 373, 375 - 1912 Bldg.**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12" x 12" Blue-Gray w/ White Streaks VFT**
MATERIAL LOCATION: **Room 373, 375 - 1912 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12" x 12" Blue-Gray w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 373, 375 - 1912 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12" x 12" Blue-Gray w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 373, 375 - 1912 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **12" x 12" Dk Gray w/ Beige Streaks VFT- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **12" x 12" Dk Gray w/ Beige Streaks VFT- NOT OBSERVED**
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **12" x 12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912 Bldg.**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **12" x 12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED**
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **12" x 12" Lt Gray w/ White Speckles VFT- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **12" x 12" Lt Gray w/ White Speckles VFT- NOT OBSERVED**
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **12" x 12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **12" x 12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED**
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **12" x 12" Brown VFT- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stage - 1912 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **12" x 12" Brown VFT- NOT OBSERVED**
MATERIAL LOCATION: **Stage - 1912 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **12" x 12" Brown VFT Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stage - 1912 Bldg.**

MATERIAL QUANTITY: **0**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **12" x 12" Brown VFT Mastic- NOT OBSERVED**
MATERIAL LOCATION: **Stage - 1912 Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **2' x 2' Black Border VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **115 Kitchen - 1912 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **2' x 2' Black Border VFT (Abated)**
MATERIAL LOCATION: **115 Kitchen - 1912 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **2' x 2' Black Border VFT Mastic- Abated**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **115 Kitchen - 1912 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **2' x 2' Black Border VFT Mastic- Abated**
MATERIAL LOCATION: **115 Kitchen - 1912 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 425, & 326 - 1912 Bldg.**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile- NOT OBSERVED**
MATERIAL LOCATION: **Room 425, & 326 - 1912 Bldg.**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **12" x 12" White w/Beige Streaks VFT - Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 377A, 178, 180**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **12" x 12" White w/Beige Streaks VFT - Not Observed**
MATERIAL LOCATION: **Room 377A, 178, 180**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127 A**
MATERIAL DESCRIPTION: **12" x 12" White w/Beige Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 377A**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **127 A**
MATERIAL DESCRIPTION: **12" x 12" White w/Beige Streaks VFT Mastic**
MATERIAL LOCATION: **Room 377A**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 351**
MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Streaks VFT**
MATERIAL LOCATION: **Room 351**
MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128 A**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 351**
MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **128 A**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Streaks VFT Mastic**
MATERIAL LOCATION: **Room 351**
MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **MJP on Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor South JC, 2nd Floor Janitor's Closet, 238 Chase, 188, Autoshop - 1931 Bldg.**
MATERIAL QUANTITY: **370** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **MJP on Paperwrap Pipe Insulation**
MATERIAL LOCATION: **1st Floor South JC, 2nd Floor Janitor's Closet, 238 Chase, 188, Autoshop - 1931 Bldg.**
MATERIAL QUANTITY: **370** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **Lt Blue Speckled Linoleum- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 356, 326 - 1912 Bldg.**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **Lt Blue Speckled Linoleum- NOT OBSERVED**
MATERIAL LOCATION: **Rooms 356, 326 - 1912 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **Lt Blue Speckled Linoleum Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 356, 326 - 1912 Bldg.**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **Lt Blue Speckled Linoleum Mastic- NOT OBSERVED**
MATERIAL LOCATION: **Rooms 356, 326 - 1912 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **12" x 12" White w/ Gold Specks VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 174, 176, & 180 - 1912 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **12" x 12" White w/ Gold Specks VFT (Not Observed)**
MATERIAL LOCATION: **Rooms 174, 176, & 180 - 1912 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **12" x 12" White w/ Gold Specks VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 174, 176, & 180 - 1912 Bldg.**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **12" x 12" White w/ Gold Specks VFT Mastic (Not Observed)**
MATERIAL LOCATION: **Rooms 174, 176, & 180 - 1912 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **2' x 4' White Pin-Hole Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 356 - 1912 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **2' x 4' White Pin-Hole Ceiling Tile**
MATERIAL LOCATION: **Room 356 - 1912 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **310 & Office, 302, 108, 110 - 1931 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage noted on drawing, 100 sf damage in room 302**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige VFT**
MATERIAL LOCATION: **310 & Office, 302, 108, 110 - 1931 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

sample material, remove damaged ACM ASAP

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **310 & Office, 302, 108, 110 - 1931 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage noted on drawing, 100 sf damage in room 302**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige VFT Mastic**
MATERIAL LOCATION: **310 & Office, 302, 108, 110 - 1931 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

sample material, remove damaged ACM ASAP

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
MATERIAL LOCATION: **ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **12" x 12" Light Gray VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 210, & Engineer's Office - 1931 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **12" x 12" Light Gray VFT**
MATERIAL LOCATION: **Room 210, & Engineer's Office - 1931 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **12" x 12" Light Gray VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **210, & Engineer's Office - 1931 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **12" x 12" Light Gray VFT Mastic**
MATERIAL LOCATION: **210, & Engineer's Office - 1931 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **12" x 12" Light Blue VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 210, 195A & Engineer's Office - 1931 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **12" x 12" Light Blue VFT**
MATERIAL LOCATION: **Room 210, 195A & Engineer's Office - 1931 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **12" x 12" Light Blue VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 210, 195A & Engineer's Office - 1931 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **12" x 12" Light Blue VFT Mastic**
MATERIAL LOCATION: **Room 210, 195A & Engineer's Office - 1931 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **12" x 12" Green VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **12" x 12" Green VFT (Not Observed)**
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **12" x 12" Green VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **12" x 12" Green VFT Mastic (Not Observed)**
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **146**
MATERIAL DESCRIPTION: **12" x 12" White VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **146**
MATERIAL DESCRIPTION: **12" x 12" White VFT (Not Observed)**
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147**
MATERIAL DESCRIPTION: **12" x 12" White VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **147**
MATERIAL DESCRIPTION: **12" x 12" White VFT Mastic (Not Observed)**
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **148**
MATERIAL DESCRIPTION: **Linoleum, Gray w/Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 350, 352, 356 Vault, 306 and 310**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in rooms 352 or 356 vault**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **148**
MATERIAL DESCRIPTION: **Linoleum, Gray w/Gray Streaks**
MATERIAL LOCATION: **Rooms 350, 352, 356 Vault, 306 and 310**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **148M**
MATERIAL DESCRIPTION: **Linoleum, Gray w/Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 350, 352, 356 Vault, 306 and 310**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **148M**
MATERIAL DESCRIPTION: **Linoleum, Gray w/Gray Streaks Mastic**
MATERIAL LOCATION: **Rooms 350, 352, 356 Vault, 306 and 310**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149**
MATERIAL DESCRIPTION: **Linoleum, Blue Solid**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 100, 106, and 106 Office**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **149**
MATERIAL DESCRIPTION: **Linoleum, Blue Solid**
MATERIAL LOCATION: **Rooms 100, 106, and 106 Office**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149M**
MATERIAL DESCRIPTION: **Linoleum, Blue Solid Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 100, 106, and 106 Office**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **149M**
MATERIAL DESCRIPTION: **Linoleum, Blue Solid Mastic**
MATERIAL LOCATION: **Rooms 100, 106, and 106 Office**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **150**
MATERIAL DESCRIPTION: **12" x 12" VFT- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **150**
MATERIAL DESCRIPTION: **12" x 12" VFT- NOT OBSERVED**
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **150M**
MATERIAL DESCRIPTION: **12" x 12" VFT Mastic - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **150M**
MATERIAL DESCRIPTION: **12" x 12" VFT Mastic - NOT OBSERVED**
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151**
MATERIAL DESCRIPTION: **12" x 12" Solid Gray VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **151**
MATERIAL DESCRIPTION: **12" x 12" Solid Gray VFT**
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151M**
MATERIAL DESCRIPTION: **12" x 12" Solid Gray VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **151M**
MATERIAL DESCRIPTION: **12" x 12" Solid Gray VFT Mastic**
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152**
MATERIAL DESCRIPTION: **12" x 12" Tan w/Brown Speckles VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **152**
MATERIAL DESCRIPTION: **12" x 12" Tan w/Brown Speckles VFT (Not Observed)**
MATERIAL LOCATION: **3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152M**
MATERIAL DESCRIPTION: **12" x 12" Tan w/Brown Speckles VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **152M**
MATERIAL DESCRIPTION: **12" x 12" Tan w/Brown Speckles VFT Mastic (Not Observed)**
MATERIAL LOCATION: **3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153**
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Speckles VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **153**
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Speckles VFT (Not Observed)**
MATERIAL LOCATION: **3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153M**
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Speckles VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **153M**
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Speckles VFT Mastic (Not Observed)**
MATERIAL LOCATION: **3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **154M**
MATERIAL DESCRIPTION: **Gold, Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 379, 375, 326, 315, and 272 (not observed), Room 225**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **154M**
MATERIAL DESCRIPTION: **Gold, Blue Carpet Mastic**
MATERIAL LOCATION: **Rooms 379, 375, 326, 315, and 272 (not observed), Room 225**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155**
MATERIAL DESCRIPTION: **Linoleum, White w/Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 352**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not Observed**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **155**
MATERIAL DESCRIPTION: **Linoleum, White w/Gray Streaks**
MATERIAL LOCATION: **Room 352**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155M**
MATERIAL DESCRIPTION: **Linoleum, White w/Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 352**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **155M**
MATERIAL DESCRIPTION: **Linoleum, White w/Gray Streaks Mastic**
MATERIAL LOCATION: **Room 352**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **156**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Gray and White Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 377, 377B**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **156**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Gray and White Specks VFT**
MATERIAL LOCATION: **Room 377, 377B**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **156A**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Gray and White Specks VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 377, 377B**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **156A**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Gray and White Specks VFT MASTIC**
MATERIAL LOCATION: **Room 377, 377B**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **157**
MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 351**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **157**
MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**
MATERIAL LOCATION: **Room 351**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **158**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile w/ Grooves**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 320, 425 - 1911 Bldg.**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **158**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile w/ Grooves**
MATERIAL LOCATION: **Room 320, 425 - 1911 Bldg.**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **159**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile w/ Grooves above HA 161**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 108, 148, 149, 146**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **159**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile w/ Grooves above HA 161**
MATERIAL LOCATION: **Rooms 108, 148, 149, 146**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **160**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile w/ Grooves**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet - 1930 Bldg.**

MATERIAL QUANTITY: **22000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **160**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile w/ Grooves**

MATERIAL LOCATION: **South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet - 1930 Bldg.**

MATERIAL QUANTITY: **22000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **161**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile w/ Grooves**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335. 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166 - 1911 Bldg.**

MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **161**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile w/ Grooves**

MATERIAL LOCATION: **Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335. 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166 - 1911 Bldg.**

MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **162**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile - pinhole**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352, 364, 366 - 1911 Bldg.**

MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **162**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile - pinhole**
MATERIAL LOCATION: **1st Floor Hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352, 364, 366 - 1911 Bldg.**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **163**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile - pinholes**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridor from pump room- room 184, kitchen, cafeteria - 1930 Bldg.**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **163**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile - pinholes**
MATERIAL LOCATION: **Corridor from pump room- room 184, kitchen, cafeteria - 1930 Bldg.**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **164**
MATERIAL DESCRIPTION: **12" x 12" Tan w/ light brown specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **164**
MATERIAL DESCRIPTION: **12" x 12" Tan w/ light brown specks VFT**
MATERIAL LOCATION: **Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **164A**
MATERIAL DESCRIPTION: **12" x 12" Tan w/ light brown specks VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **164A**
MATERIAL DESCRIPTION: **12" x 12" Tan w/ light brown specks VFT MASTIC**
MATERIAL LOCATION: **Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165**
MATERIAL DESCRIPTION: **9" x 9" Brown w/ yellow design VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 123 - 1912 Bldg.**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **165**
MATERIAL DESCRIPTION: **9" x 9" Brown w/ yellow design VFT (Not Observed)**
MATERIAL LOCATION: **Room 123 - 1912 Bldg.**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165A**
MATERIAL DESCRIPTION: **9" x 9" Brown w/ yellow design VFT MASTIC (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 123 - 1912 Bldg.**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **165A**
MATERIAL DESCRIPTION: **9" x 9" Brown w/ yellow design VFT MASTIC (Not Observed)**
MATERIAL LOCATION: **Room 123 - 1912 Bldg.**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ blue specks VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **166**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ blue specks VFT (Not Observed)**
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166A**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ blue specks VFT MASTIC (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **166A**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ blue specks VFT MASTIC (Not Observed)**
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **167**
MATERIAL DESCRIPTION: **12" x 12" White w/light blue, gray and yellow specks VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **167**
MATERIAL DESCRIPTION: **12" x 12" White w/light blue, gray and yellow specks VFT (Not Observed)**
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **167A**
MATERIAL DESCRIPTION: **12" x 12" White w/ light blue, gray and yellow specks VFT MASTIC (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **167A**
MATERIAL DESCRIPTION: **12" x 12" White w/ light blue, gray and yellow specks VFT MASTIC (Not Observed)**
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **168**
MATERIAL DESCRIPTION: **Black Lab Table Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 358, 364, 367**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **168**
MATERIAL DESCRIPTION: **Black Lab Table Tops**
MATERIAL LOCATION: **Rooms 358, 364, 367**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **169**
MATERIAL DESCRIPTION: **Black Lab Counter Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 358, 364, 367**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **169**
MATERIAL DESCRIPTION: **Black Lab Counter Tops**
MATERIAL LOCATION: **Rooms 358, 364, 367**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **170**
MATERIAL DESCRIPTION: **Blue Linoleum with MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 358, 364, 366**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **170**
MATERIAL DESCRIPTION: **Blue Linoleum with MASTIC**
MATERIAL LOCATION: **Rooms 358, 364, 366**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **171**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ tan streaks VFT w/ MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 170**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **171**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ tan streaks VFT w/ MASTIC**
MATERIAL LOCATION: **Room 170**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

sample material, remove damaged ACM ASAP

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **172**
MATERIAL DESCRIPTION: **Decorative Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly hall, vestibule leading to assembly hall**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **172**
MATERIAL DESCRIPTION: **Decorative Plaster**
MATERIAL LOCATION: **Assembly hall, vestibule leading to assembly hall**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **173**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairwells, 1st fl. corridor west of pump room - 1931 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **173**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Stairwells, 1st fl. corridor west of pump room - 1931 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **174**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **174**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **1st Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **175**
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **175**
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled VFT (Not Observed)**
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **176**
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **176**
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled VFT Mastic (Not Observed)**
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **177**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ Specks VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **177**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ Specks VFT (Not Observed)**
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **178**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ Specks VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **178**
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ Specks VFT Mastic (Not Observed)**
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **179**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Streaks VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 221**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **179**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Streaks VFT (Not Observed)**
MATERIAL LOCATION: **Room 221**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **180**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Streaks VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 221**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **180**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Streaks VFT Mastic (Not Observed)**
MATERIAL LOCATION: **Room 221**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **181**
MATERIAL DESCRIPTION: **Gray Linoleum w/ Granite Pattern**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100, 108, 106**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **181**
MATERIAL DESCRIPTION: **Gray Linoleum w/ Granite Pattern**
MATERIAL LOCATION: **Room 100, 108, 106**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **182**
MATERIAL DESCRIPTION: **Gray Linoleum w/ Granite Pattern Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100, 108, 106**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **182**
MATERIAL DESCRIPTION: **Gray Linoleum w/ Granite Pattern Mastic**
MATERIAL LOCATION: **Room 100, 108, 106**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **183**
MATERIAL DESCRIPTION: **Gray Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 105, 105A, 110**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **183**
MATERIAL DESCRIPTION: **Gray Linoleum**
MATERIAL LOCATION: **Rooms 105, 105A, 110**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **184**
MATERIAL DESCRIPTION: **Gray Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 105, 105A, 110**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **184**
MATERIAL DESCRIPTION: **Gray Linoleum Mastic**
MATERIAL LOCATION: **Rooms 105, 105A, 110**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **185**
MATERIAL DESCRIPTION: **12" x 12" Red w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **185**
MATERIAL DESCRIPTION: **12" x 12" Red w/ Streaks VFT**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **186**
MATERIAL DESCRIPTION: **12" x 12" Red w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **186**
MATERIAL DESCRIPTION: **12" x 12" Red w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **187**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **187**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/Streaks VFT**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **188**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **188**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/Streaks VFT Mastic**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **189**
MATERIAL DESCRIPTION: **12" x 12" Green w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **189**
MATERIAL DESCRIPTION: **12" x 12" Green w/ Streaks VFT**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **190**
MATERIAL DESCRIPTION: **12" x 12" Green w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **190**
MATERIAL DESCRIPTION: **12" x 12" Green w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Health Center (144)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **191**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray ILnoleum w/ Granite Pattern (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office (131-134)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **191**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray ILnoleum w/ Granite Pattern (Not Observed)**
MATERIAL LOCATION: **Main Office (131-134)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **192**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Linoleum w/ Granite Pattern Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office (131-134)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **192**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Linoleum w/ Granite Pattern Mastic (Not Observed)**
MATERIAL LOCATION: **Main Office (131-134)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **193**
MATERIAL DESCRIPTION: **12" x 12" Pink w/ Maroon Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 115**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **193**
MATERIAL DESCRIPTION: **12" x 12" Pink w/ Maroon Specks VFT**
MATERIAL LOCATION: **Room 115**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **194**
MATERIAL DESCRIPTION: **12" x 12" Pink w/ Maroon Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 115**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **194**
MATERIAL DESCRIPTION: **12" x 12" Pink w/ Maroon Specks VFT Mastic**
MATERIAL LOCATION: **Room 115**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **195**
MATERIAL DESCRIPTION: **12" x 12" Maroon w/ Pink Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 115**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **195**
MATERIAL DESCRIPTION: **12" x 12" Maroon w/ Pink Specks VFT**
MATERIAL LOCATION: **Room 115**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **196**
MATERIAL DESCRIPTION: **12" x 12" Maroon w/ Pink Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 115**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **196**
MATERIAL DESCRIPTION: **12" x 12" Maroon w/ Pink Specks VFT Mastic**
MATERIAL LOCATION: **Room 115**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **197**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Beige Specs VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **197**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Beige Specs VFT**
MATERIAL LOCATION: **Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **198**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Beige Specs VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **198**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Beige Specs VFT Mastic**
MATERIAL LOCATION: **Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **199**
MATERIAL DESCRIPTION: **20" x 20" Off White w/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 339, 326, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117, 352 Vault, 3rd Floor West Toilets**

MATERIAL QUANTITY: **3335** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Change noted on drawing, Added 35 sf to 352 Vault, Added 500 sf to 3rd floor west toilets**

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **199**
MATERIAL DESCRIPTION: **20" x 20" Off White w/ Specks VFT**
MATERIAL LOCATION: **Rooms 339, 326, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117, 352 Vault, 3rd Floor West Toilets**
MATERIAL QUANTITY: **3335** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mixing Room, 219, 319, Auditorium Crawlspace, Room 120A - 1912 Bldg.**
MATERIAL QUANTITY: **603** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Pipe Insulation**
MATERIAL LOCATION: **Mixing Room, 219, 319, Auditorium Crawlspace, Room 120A - 1912 Bldg.**
MATERIAL QUANTITY: **603** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **200**
MATERIAL DESCRIPTION: **20" x 20" Off White w/ Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **200**
MATERIAL DESCRIPTION: **20" x 20" Off White w/ Specks VFT Mastic**
MATERIAL LOCATION: **Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **201**
MATERIAL DESCRIPTION: **20" x 20" Beige w/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 225A, Library, 276, 278, 280, 326, 123A thru 117**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **201**
MATERIAL DESCRIPTION: **20" x 20" Beige w/ Specks VFT**
MATERIAL LOCATION: **Room 225A, Library, 276, 278, 280, 326, 123A thru 117**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **202**
MATERIAL DESCRIPTION: **20" x 20" Beige w/ Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 225A, Library, 276, 278, 280, 326, 123A thru 117**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **202**
MATERIAL DESCRIPTION: **20" x 20" Beige w/ Specks VFT Mastic**
MATERIAL LOCATION: **Room 225A, Library, 276, 278, 280, 326, 123A thru 117**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **203**
MATERIAL DESCRIPTION: **20" x 20" Brown w/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 225A, Library, 276, 278, 280, 123A thru 117, 326**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Added 326**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **203**
MATERIAL DESCRIPTION: **20" x 20" Brown w/ Specks VFT**
MATERIAL LOCATION: **Room 225A, Library, 276, 278, 280, 123A thru 117, 326**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **204**
MATERIAL DESCRIPTION: **20" x 20" Brown w/ Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 225A, Library, 276, 278, 280, 123A thru 117**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **204**
MATERIAL DESCRIPTION: **20" x 20" Brown w/ Specks VFT Mastic**
MATERIAL LOCATION: **Room 225A, Library, 276, 278, 280, 123A thru 117**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **205**
MATERIAL DESCRIPTION: **Linoleum Gray w/ Granite Pattern**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office and Associated Offices (131-134)**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **205**
MATERIAL DESCRIPTION: **Linoleum Gray w/ Granite Pattern**
MATERIAL LOCATION: **Main Office and Associated Offices (131-134)**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **206**
MATERIAL DESCRIPTION: **Linoleum Gray w/ Granite Pattern Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office and Associated Offices (131-134)**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **206**
MATERIAL DESCRIPTION: **Linoleum Gray w/ Granite Pattern Mastic**
MATERIAL LOCATION: **Main Office and Associated Offices (131-134)**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **207**
MATERIAL DESCRIPTION: **Linoleum Gray w/ Black Spots**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 151, 155**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **207**
MATERIAL DESCRIPTION: **Linoleum Gray w/ Black Spots**
MATERIAL LOCATION: **Rooms 151, 155**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **208**
MATERIAL DESCRIPTION: **Linoleum Gray w/ Black Spots Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 151, 155**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **208**
MATERIAL DESCRIPTION: **Linoleum Gray w/ Black Spots Mastic**
MATERIAL LOCATION: **Rooms 151, 155**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **209**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**

MATERIAL QUANTITY: **20000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **209**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Specks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **210**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **210**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **211**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **211**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Specks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **212**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **212**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **213**
MATERIAL DESCRIPTION: **12" x 12" White w/ Red, Blue & Yellow Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **213**
MATERIAL DESCRIPTION: **12" x 12" White w/ Red, Blue & Yellow Specks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **214**
MATERIAL DESCRIPTION: **12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **214**
MATERIAL DESCRIPTION: **12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **215**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1931 Bldg.**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **215**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Specks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1931 Bldg.**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **216**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1931 Bldg.**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **216**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1931 Bldg.**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **217**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1931 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **217**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Specks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1931 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **218**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1931 Bldg.**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **218**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1931 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Insulation in Vault Door**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office - 1912 Bldg.**
MATERIAL QUANTITY: **28** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Insulation in Vault Door**

MATERIAL LOCATION: **Office - 1912 Bldg.**

MATERIAL QUANTITY: **28**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 238 Chase, Autoshop, Autoshop Tool Room - 1931 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Insulation**
MATERIAL LOCATION: **Room 238 Chase, Autoshop, Autoshop Tool Room - 1931 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autoshop & Autoshop Tool Room, Kitchen Storage - 1931 Bldg.**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autosshop & Autosshop Tool Room, Kitchen Storage - 1931 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 219, 319, 356, & Auditorium Crawlspace - 1912 Bldg.**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Rooms 219, 319, 356, & Auditorium Crawlspace - 1912 Bldg.**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium Crawlspace - 1912 Bldg.**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
MATERIAL LOCATION: **Auditorium Crawlspace - 1912 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium Crawlspace - 1912 Bldg.**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**
COMMENTS: **Damage noted on drawing, 2 split end and 1 physical damage in fan room #2, 4 damaged in 3rd floor west girl's toilet**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**
MATERIAL LOCATION: **Auditorium Crawlspace - 1912 Bldg.**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **7** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

repair damaged ACM asap

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1912 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout - 1912 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Tan w/Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage noted on drawing, 50 sf damage in room 233**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Tan w/Speckles VFT**
MATERIAL LOCATION: **3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

remove damaged ACM ASAP

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 356**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Streaks VFT Mastic**
MATERIAL LOCATION: **Room 356**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" Tan w/Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" Tan w/Speckles VFT Mastic**
MATERIAL LOCATION: **3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **9" x 9" Maroon VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **9" x 9" Maroon VFT (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **9" x 9" Maroon VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **9" x 9" Maroon VFT Mastic (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Streaks VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 356 - NOT OBSERVED**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Streaks VFT NOT OBSERVED**
MATERIAL LOCATION: **Room 356 - NOT OBSERVED**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Streaks VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 100, 106, & 106 Office - 1931 Bldg.**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Streaks VFT (Not Observed)**
MATERIAL LOCATION: **Rooms 100, 106, & 106 Office - 1931 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Streaks VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 100, 106, & 106 Office - 1931 Bldg.**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Streaks VFT Mastic (Not Observed)**
MATERIAL LOCATION: **Rooms 100, 106, & 106 Office - 1931 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **9" x 9" Black VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **9" x 9" Black VFT (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **9" x 9" Black VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **9" x 9" Black VFT Mastic (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **9" x 9" Black w/Large White Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Hall (S&N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **9" x 9" Black w/Large White Streaks VFT (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **9" x 9" Black w/Large White Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Hall (S&N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **9" x 9" Black w/Large White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Large White Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **9" x 9" Brown w/Large White Streaks VFT (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Large White Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **9" x 9" Brown w/Large White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **9" x 9" Orange w/White VFT Streaks (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **9" x 9" Orange w/White VFT Streaks (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **9" x 9" Orange w/White Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **9" x 9" Orange w/White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **9" x 9" Maroon w/ White Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **9" x 9" Maroon w/ White Streaks VFT (Abated)**

MATERIAL LOCATION: **2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022** _____

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **9" x 9" Maroon w/ White Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **9" x 9" Maroon w/ White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **9" x 9" Black w/ Faint White Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd & 3rd Floor Halls (N&S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **9" x 9" Black w/ Faint White Streaks VFT (Abated)**

MATERIAL LOCATION: **2nd & 3rd Floor Halls (N&S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022** _____

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **9" x 9" Black w/ Faint White Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd & 3rd Floor Halls (N&S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **9" x 9" Black w/ Faint White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **2nd & 3rd Floor Halls (N&S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Speckles VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 341 & 213 - 1931 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Speckles VFT (Not Observed)**
MATERIAL LOCATION: **Room 341 & 213 - 1931 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 341 & 213 - 1931 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Speckles VFT Mastic**
MATERIAL LOCATION: **Room 341 & 213 - 1931 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Light Brown Speckles VFT (Not observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 239 - 1931 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Light Brown Speckles VFT (Not observed)**
MATERIAL LOCATION: **Room 239 - 1931 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Light Brown Speckles VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 239 - 1931 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Light Brown Speckles VFT Mastic (Not Observed)**
MATERIAL LOCATION: **Room 239 - 1931 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Brown Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **238 North Storage - 1931 Bldg.**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Brown Linoleum**
MATERIAL LOCATION: **238 North Storage - 1931 Bldg.**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **Green Linoleum (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Gym, Office & Locker - 1931 Bldg.**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Observed Office**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **Green Linoleum (Not Observed)**
MATERIAL LOCATION: **Main Gym, Office & Locker - 1931 Bldg.**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **12" x 12" Peach w/ Speckles VFT- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 352, 379, 350 Storage - 1912 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **12" x 12" Peach w/ Speckles VFT- NOT OBSERVED**
MATERIAL LOCATION: **Rooms 352, 379, 350 Storage - 1912 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **12" x 12" Peach w/ Speckles VFT Mastic - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 352, 379, 350 Storage - 1912 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **12" x 12" Peach w/ Speckles VFT Mastic - NOT OBSERVED**
MATERIAL LOCATION: **Rooms 352, 379, 350 Storage - 1912 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 355, 373, 375 - 1912 Bldg.**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **373 & 375 Not Observed**

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Speckles VFT**
MATERIAL LOCATION: **Room 355, 373, 375 - 1912 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 355, 373, 375 - 1912 Bldg.**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **373 & 375 Not Observed**

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Speckles VFT Mastic**
MATERIAL LOCATION: **Room 355, 373, 375 - 1912 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Speckles VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Speckles VFT (Not Observed)**
MATERIAL LOCATION: **3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Speckles VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Speckles VFT Mastic (Not Observed)**
MATERIAL LOCATION: **3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/White & Dark Streaks VFT- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/White & Dark Streaks VFT- NOT OBSERVED**
MATERIAL LOCATION: **3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.**

MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED**
MATERIAL LOCATION: **3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **12" x 12" Black w/ White Speckles VFT- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Corridor (N) - 1912 Bldg.**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **12" x 12" Black w/ White Speckles VFT- NOT OBSERVED**
MATERIAL LOCATION: **3rd Floor Corridor (N) - 1912 Bldg.**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **12" x 12" Black w/ White Speckles VFT Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridor (N) - 1912 Bldg.**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **12" x 12" Black w/ White Speckles VFT Mastic- NOT OBSERVED**
MATERIAL LOCATION: **3rd Floor Corridor (N) - 1912 Bldg.**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd floor, side corridor, East to West navy areas**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile - NOT OBSERVED**
MATERIAL LOCATION: **3rd floor, side corridor, East to West navy areas**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB**
MATERIAL DESCRIPTION: **Mastic associated with HA AA - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd floor, side corridor, East to West navy areas - NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **BB**
MATERIAL DESCRIPTION: **Mastic associated with HA AA - NOT OBSERVED**
MATERIAL LOCATION: **3rd floor, side corridor, East to West navy areas - NOT OBSERVED**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CC**
MATERIAL DESCRIPTION: **Lab Counter Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 100, 106, 108, 110, 302, 310, 350**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **CC**
MATERIAL DESCRIPTION: **Lab Counter Tops**
MATERIAL LOCATION: **Classrooms 100, 106, 108, 110, 302, 310, 350**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DD**
MATERIAL DESCRIPTION: **Lab Tables**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 110, 302, 310, 350**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/10/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **DD**
MATERIAL DESCRIPTION: **Lab Tables**
MATERIAL LOCATION: **Classrooms 110, 302, 310, 350**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Antonio Munoz IV**
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **9/10/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EE**
MATERIAL DESCRIPTION: **Lab Fume Hoods**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 100, 106, 350**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/10/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/3/2022**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-20616**

HOMOGENEOUS AREA: **EE**
MATERIAL DESCRIPTION: **Lab Fume Hoods**
MATERIAL LOCATION: **Classrooms 100, 106, 350**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/03/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ANTONIO MUNOZ IV
has completed the ASBESTOS INSPECTOR'S INITIAL course and successfully passed the
examination on 03/30/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

03/28/2022-03/30/2022

Course Dates:

03/30/2023

Expires:

2203BI03

Certificate Number:

A handwritten signature in black ink, appearing to read "N Peneff".

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

ANTONIO MUNOZ IV
3211 S HAMILTON
CHICAGO, IL 60608

4/21/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 20616

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 20616	ISSUED 4/21/2022	INSPECTOR	3/30/2023
ANTONIO MUNOZ IV 3211 S HAMILTON CHICAGO, IL 60608 Environmental Health	EXPIRES 05/15/2023	PROJECT MANAGER	1/22/2023
		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES
Nationally Accredited by PHAB



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562

A handwritten signature in cursive script that reads 'Kathy DeSalvo'.

Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583

A handwritten signature in cursive script that reads 'Kathy DeSalvo'.

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois

ARTURO SAENZ
 2942 W VAN BUREN ST
 CHICAGO, IL 60612

2/28/2022



**ASBESTOS
 PROFESSIONAL
 LICENSE**

ID NUMBER
 100 - 04019

ISSUED
 2/28/2022

EXPIRES
 05/15/2023

ARTURO SAENZ
 2942 W VAN BUREN ST
 CHICAGO, IL 60612



Environmental Health

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

<p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p>	<p>TC EXPIRES</p>
<p>ID NUMBER 100 - 04019</p>	<p>ISSUED 2/28/2022</p>	<p>EXPIRES 05/15/2023</p>	<p>INSPECTOR</p>	<p>11/1/2022</p>
<p>ARTURO SAENZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health</p>			<p>MANAGEMENT PLANNER</p>	<p>11/1/2022</p>
			<p>AIR SAMPLING PROFESSIONAL</p>	
			<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
 EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES

Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed